

# Post-Production Service Pack for ProLiant version G7 Component

---

[BIOS - System ROM](#)

[Driver - Network](#)

[Driver - Storage](#)

[Driver - Storage Controller](#)

[Driver - Storage Fibre Channel and Fibre Channel Over Ethernet](#)

[Driver - Storage Tape](#)

[Driver - System Management](#)

[Driver - Video](#)

[Firmware - Blade Infrastructure](#)

[Firmware - Lights-Out Management](#)

[Firmware - Network](#)

[Firmware - SAS Storage Disk](#)

[Firmware - SATA Storage Disk](#)

[Firmware - Storage Controller](#)

[Firmware - Storage Fibre Channel](#)

[Firmware - Storage Tape](#)

[Software - Lights-Out Management](#)

[Software - Network](#)

[Software - Storage Controller](#)

[Software - Storage Fibre Channel](#)

[Software - Storage Fibre Channel HBA](#)

[Software - System Management](#)

## BIOS - System ROM

[Top](#)

Online ROM Flash Component for Linux - HP ProLiant BL2x220c G7 (I29) Servers

Version: 2015.08.16 **(Recommended)**

Filename: RPMS/i386/hp-firmware-system-i29-2015.08.16-1.1.i386.rpm

### **Important Note!**

**Important Notes:**

None

**Deliverable Name:**

HP ProLiant BL2x220c G7 System ROM - I29

**Release Version:**

08/16/2015

**Last Recommended or Critical Revision:**

08/16/2015

**Previous Revision:**

07/02/2013

**Firmware Dependencies:**

None

**Enhancements/New Features:**

None

**Problems Fixed:**

While HP ProLiant servers using impacted Intel processors are not vulnerable to the specific attack announced publicly at the Blackhat USA 2015 security conference, this BIOS update includes updated microcodes from Intel which prevent the possibility of exploiting the processor vulnerability that make the attack possible. This Intel processor vulnerability is NOT unique to HP ProLiant servers.

**Known Issues:**

None

**Fixes****Important Notes:**

None

**Firmware Dependencies:**

None

**Problems Fixed:**

While HP ProLiant servers using impacted Intel processors are not vulnerable to the specific attack announced publicly at the Blackhat USA 2015 security conference, this BIOS update includes updated microcodes from Intel which prevent the possibility of exploiting the processor vulnerability that make the attack possible. This Intel processor vulnerability is NOT unique to HP ProLiant servers.

**Known Issues:**

None

---

Online ROM Flash Component for Linux - HP ProLiant BL460c G7 (I27) Servers

Version: 2015.08.16 **(Recommended)**

Filename: RPMS/i386/hp-firmware-system-i27-2015.08.16-1.1.i386.rpm

**Important Note!****Important Notes:**

None

**Deliverable Name:**

HP ProLiant BL460c G7 System ROM - I27

**Release Version:**

08/16/2015

**Last Recommended or Critical Revision:**

08/16/2015

**Previous Revision:**

07/02/2013

**Firmware Dependencies:**

None

**Enhancements/New Features:**

None

**Problems Fixed:**

While HP ProLiant servers using impacted Intel processors are not vulnerable to the specific attack announced publicly at the Blackhat USA 2015 security conference, this BIOS update includes updated microcodes from Intel which prevent the possibility of exploiting the processor vulnerability that make the attack possible. This Intel processor vulnerability is NOT unique to HP ProLiant servers.

**Known Issues:**

None

**Fixes**

**Important Notes:**

None

**Firmware Dependencies:**

None

**Problems Fixed:**

While HP ProLiant servers using impacted Intel processors are not vulnerable to the specific attack announced publicly at the Blackhat USA 2015 security conference, this BIOS update includes updated microcodes from Intel which prevent the possibility of exploiting the processor vulnerability that make the attack possible. This Intel processor vulnerability is NOT unique to HP ProLiant servers.

**Known Issues:**

None

---

Online ROM Flash Component for Linux - HP ProLiant BL465c G7 (A19) Servers

Version: 2014.02.02 (C) **(Optional)**

Filename: RPMS/i386/hp-firmware-system-a19-2014.02.02-3.i386.rpm

**Important Note!**

**Important Notes:**

Ver. 2014.02.02 (C) contains a documentation update only and is functionally equivalent to ver. 2014.02.02. It is not necessary to upgrade with

Revision C if a previous component Revision was used to upgrade the system ROM to version 2014.02.02.

**Deliverable Name:**

HP ProLiant BL465c G7 System ROM - A19

**Release Date:**

02/02/2014

**Last Recommended or Critical Revision:**

12/08/2012

**Previous Revision:**

12/08/2012

**Firmware Dependencies:**

None

**Enhancements/New Features:**

None

**Problems Fixed:**

Resolved a very rare condition where the system could become unresponsive or unexpectedly reset when running with AMD Opteron 6100 or 6200 processors.

**Known Issues:**

None

**Fixes**

**Important Notes:**

Ver. 2014.02.02 (C) contains a documentation update only and is functionally equivalent to ver. 2014.02.02. It is not necessary to upgrade with Revision C if a previous component Revision was used to upgrade the system ROM to version 2014.02.02.

**Firmware Dependencies:**

None

**Problems Fixed:**

Resolved a very rare condition where the system could become unresponsive or unexpectedly reset when running with AMD Opteron 6100 or 6200 processors.

**Known Issues:**

None

---

### **Important Note!**

**Important Notes:**

None

**Deliverable Name:**

HP ProLiant BL490c G7 System ROM - I28

**Release Version:**

08/16/2015

**Last Recommended or Critical Revision:**

08/16/2015

**Previous Revision:**

07/02/2013

**Firmware Dependencies:**

None

**Enhancements/New Features:**

None

**Problems Fixed:**

While HP ProLiant servers using impacted Intel processors are not vulnerable to the specific attack announced publicly at the Blackhat USA 2015 security conference, this BIOS update includes updated microcodes from Intel which prevent the possibility of exploiting the processor vulnerability that make the attack possible. This Intel processor vulnerability is NOT unique to HP ProLiant servers.

**Known Issues:**

None

### **Fixes**

**Important Notes:**

None

**Firmware Dependencies:**

None

**Problems Fixed:**

While HP ProLiant servers using impacted Intel processors are not vulnerable to the specific attack announced publicly at the Blackhat USA 2015 security conference, this BIOS update includes updated microcodes from Intel which prevent the possibility of exploiting the processor vulnerability that make the attack possible. This Intel processor vulnerability is NOT unique to HP ProLiant servers.

**Known Issues:**

None

---

Online ROM Flash Component for Linux - HP ProLiant BL680c G7/BL620c G7 (I25) Servers

Version: 2015.08.16 **(Recommended)**

Filename: RPMS/i386/hp-firmware-system-i25-2015.08.16-1.1.i386.rpm

**Important Note!****Important Notes:**

None

**Deliverable Name:**

HP ProLiant BL680c G7/BL620c G7 System ROM - I25

**Release Version:**

08/16/2015

**Last Recommended or Critical Revision:**

08/16/2015

**Previous Revision:**

07/01/2013

**Firmware Dependencies:**

None

**Enhancements/New Features:**

None

**Problems Fixed:**

While HP ProLiant servers using impacted Intel processors are not vulnerable to the specific attack announced publicly at the Blackhat USA 2015 security conference, this BIOS update includes updated microcodes from Intel which prevent the possibility of exploiting the processor vulnerability that make the attack possible. This Intel processor vulnerability is NOT unique to HP ProLiant servers.

**Known Issues:**

None

**Fixes****Important Notes:**

None

**Firmware Dependencies:**

None

**Problems Fixed:**

While HP ProLiant servers using impacted Intel processors are not vulnerable to the specific attack announced publicly at the Blackhat USA 2015 security conference, this BIOS update includes updated microcodes from Intel which prevent the possibility of exploiting the processor vulnerability that make the attack possible. This Intel processor vulnerability is NOT unique to HP ProLiant servers.

**Known Issues:**

None

---

Online ROM Flash Component for Linux - HP ProLiant BL685c G7 (A20) Servers

Version: 2016.03.07 **(Recommended)**

Filename: RPMS/i386/hp-firmware-system-a20-2016.03.07-1.1.i386.rpm

**Important Note!****Important Notes:**

None

**Deliverable Name:**

HP ProLiant BL685c G7 System ROM

**Release Version:**

03/07/2016

**Last Recommended or Critical Revision:**

03/07/2016

**Previous Revision:**

09/03/2014

**Firmware Dependencies:**

None

**Enhancements/New Features:**

None

**Problems Fixed:**

Addressed an issue with AMD Opteron 6300 series processors in which the processor may experience unpredictable system behavior in virtualized environments due to an issue with the revision of the AMD microcode included in the 09/03/2014 revision of the System ROM. Only the 09/03/2014 revision of the System ROM is impacted by this issue. This revision of the System ROM contains an updated version of AMD's microcode that addresses this issue. This issue is NOT unique to HPE ProLiant servers and could impact any system utilizing affected processors with the affected AMD microcode. Due to the potential severity of the issue addressed in this revision of the System ROM, it is highly recommended that the System ROM be upgraded for impacted systems.

**Known Issues:**

None

## Fixes

### Important Notes:

None

### Firmware Dependencies:

None

### Problems Fixed:

Addressed an issue with AMD Opteron 6300 series processors in which the processor may experience unpredictable system behavior in virtualized environments due to an issue with the revision of the AMD microcode included in the 09/03/2014 revision of the System ROM. Only the 09/03/2014 revision of the System ROM is impacted by this issue. This revision of the System ROM contains an updated version of AMD's microcode that addresses this issue. This issue is NOT unique to HPE ProLiant servers and could impact any system utilizing affected processors with the affected AMD microcode. Due to the potential severity of the issue addressed in this revision of the System ROM, it is highly recommended that the System ROM be upgraded for impacted systems.

### Known Issues:

None

---

Online ROM Flash Component for Linux - HP ProLiant DL360 G7 (P68) Servers

Version: 2015.08.16 **(Recommended)**

Filename: RPMS/i386/hp-firmware-system-p68-2015.08.16-1.1.i386.rpm

## Important Note!

### Important Notes:

None

### Deliverable Name:

HP ProLiant DL360 G7 System ROM - P68

### Release Version:

08/16/2015

### Last Recommended or Critical Revision:

08/16/2015

### Previous Revision:

07/02/2013

### Firmware Dependencies:

None

### Enhancements/New Features:

None

### Problems Fixed:



While HP ProLiant servers using impacted Intel processors are not vulnerable to the specific attack announced publicly at the Blackhat USA 2015 security conference, this BIOS update includes updated microcodes from Intel which prevent the possibility of exploiting the processor vulnerability that make the attack possible. This Intel processor vulnerability is NOT unique to HP ProLiant servers.

**Known Issues:**

None

**Fixes**

**Important Notes:**

None

**Firmware Dependencies:**

None

**Problems Fixed:**

While HP ProLiant servers using impacted Intel processors are not vulnerable to the specific attack announced publicly at the Blackhat USA 2015 security conference, this BIOS update includes updated microcodes from Intel which prevent the possibility of exploiting the processor vulnerability that make the attack possible. This Intel processor vulnerability is NOT unique to HP ProLiant servers.

**Known Issues:**

None

---

Online ROM Flash Component for Linux - HP ProLiant DL380 G7 (P67) Servers

Version: 2015.08.16 **(Recommended)**

Filename: RPMS/i386/hp-firmware-system-p67-2015.08.16-1.1.i386.rpm

**Important Note!**

**Important Notes:**

None

**Deliverable Name:**

HP ProLiant DL380 G7 System ROM - P67

**Release Version:**

08/16/2015

**Last Recommended or Critical Revision:**

08/16/2015

**Previous Revision:**

07/02/2013

**Firmware Dependencies:**

None

**Enhancements/New Features:**

None

**Problems Fixed:**

While HP ProLiant servers using impacted Intel processors are not vulnerable to the specific attack announced publicly at the Blackhat USA 2015 security conference, this BIOS update includes updated microcodes from Intel which prevent the possibility of exploiting the processor vulnerability that make the attack possible. This Intel processor vulnerability is NOT unique to HP ProLiant servers.

**Known Issues:**

None

**Fixes****Important Notes:**

None

**Firmware Dependencies:**

None

**Problems Fixed:**

While HP ProLiant servers using impacted Intel processors are not vulnerable to the specific attack announced publicly at the Blackhat USA 2015 security conference, this BIOS update includes updated microcodes from Intel which prevent the possibility of exploiting the processor vulnerability that make the attack possible. This Intel processor vulnerability is NOT unique to HP ProLiant servers.

**Known Issues:**

None

---

Online ROM Flash Component for Linux - HP ProLiant DL385 G7 (A18) Servers

Version: 2014.02.02 (B) **(Optional)**

Filename: RPMS/i386/hp-firmware-system-a18-2014.02.02-2.1.i386.rpm

**Important Note!****Important Notes:**

Ver. 2014.02.02 (B) contains updates to the component packaging and is functionally equivalent to ver. 2014.02.02. It is not necessary to upgrade with Revision B if a previous component Revision was used to upgrade the system ROM to version 2014.02.02.

**Deliverable Name:**

HP ProLiant DL385 G7 System ROM - A18

**Release Version:**

02/02/2014

**Last Recommended or Critical Revision:**

12/08/2012

**Previous Revision:**

12/08/2012

**Firmware Dependencies:**

None

**Enhancements/New Features:**

None

**Problems Fixed:**

Resolved a very rare condition where the system could become unresponsive or unexpectedly reset when running with AMD Opteron 6100 or 6200 processors.

**Known Issues:**

None

**Prerequisites**

The "HPE ProLiant iLO 3/4 Channel Interface Driver" (CHIF) for Linux which is integrated into the standard Linux kernel.

**Fixes**

**Important Notes:**

Ver. 2014.02.02 (B) contains updates to the component packaging and is functionally equivalent to ver. 2014.02.02. It is not necessary to upgrade with Revision B if a previous component Revision was used to upgrade the system ROM to version 2014.02.02.

**Firmware Dependencies:**

None

**Problems Fixed:**

Resolved a very rare condition where the system could become unresponsive or unexpectedly reset when running with AMD Opteron 6100 or 6200 processors.

**Known Issues:**

None

---

Online ROM Flash Component for Linux - HP ProLiant DL580 G7 (P65) Servers

Version: 2015.08.16 **(Recommended)**

Filename: RPMS/i386/hp-firmware-system-p65-2015.08.16-1.1.i386.rpm

**Important Note!**

**Important Notes:**

None

**Deliverable Name:**

HP ProLiant DL580 G7 System ROM - P65

**Release Version:**

08/16/2015

**Last Recommended or Critical Revision:**

08/16/2015

**Previous Revision:**

10/01/2013

**Firmware Dependencies:**

None

**Enhancements/New Features:**

None

**Problems Fixed:**

While HP ProLiant servers using impacted Intel processors are not vulnerable to the specific attack announced publicly at the Blackhat USA 2015 security conference, this BIOS update includes updated microcodes from Intel which prevent the possibility of exploiting the processor vulnerability that make the attack possible. This Intel processor vulnerability is NOT unique to HP ProLiant servers.

**Known Issues:**

None

**Fixes****Important Notes:**

None

**Firmware Dependencies:**

None

**Problems Fixed:**

While HP ProLiant servers using impacted Intel processors are not vulnerable to the specific attack announced publicly at the Blackhat USA 2015 security conference, this BIOS update includes updated microcodes from Intel which prevent the possibility of exploiting the processor vulnerability that make the attack possible. This Intel processor vulnerability is NOT unique to HP ProLiant servers.

**Known Issues:**

None

---

Online ROM Flash Component for Linux - HP ProLiant DL585 G7 (A16) Servers

Version: 2016.03.07 **(Recommended)**

Filename: RPMS/i386/hp-firmware-system-a16-2016.03.07-1.1.i386.rpm

**Important Note!****Important Notes:**

None

**Deliverable Name:**

HP ProLiant DL585 G7 System ROM

**Release Version:**

03/07/2016

**Last Recommended or Critical Revision:**

03/07/2016

**Previous Revision:**

09/03/2014

**Firmware Dependencies:**

None

**Enhancements/New Features:**

None

**Problems Fixed:**

Addressed an issue with AMD Opteron 6300 series processors in which the processor may experience unpredictable system behavior in virtualized environments due to an issue with the revision of the AMD microcode included in the 09/03/2014 revision of the System ROM. Only the 09/03/2014 revision of the System ROM is impacted by this issue. This revision of the System ROM contains an updated version of AMD's microcode that addresses this issue. This issue is NOT unique to HPE ProLiant servers and could impact any system utilizing affected processors with the affected AMD microcode. Due to the potential severity of the issue addressed in this revision of the System ROM, it is highly recommended that the System ROM be upgraded for impacted systems.

**Known Issues:**

None

**Fixes**

**Important Notes:**

None

**Firmware Dependencies:**

None

**Problems Fixed:**

Addressed an issue with AMD Opteron 6300 series processors in which the processor may experience unpredictable system behavior in virtualized environments due to an issue with the revision of the AMD microcode included in the 09/03/2014 revision of the System ROM. Only the 09/03/2014 revision of the System ROM is impacted by this issue. This revision of the System ROM contains an updated version of AMD's microcode that addresses this issue. This issue is NOT unique to HPE ProLiant servers and could impact any system utilizing affected processors with the affected AMD microcode. Due to the potential severity of the issue addressed in this revision of the System ROM, it is highly recommended that the System ROM be upgraded for impacted systems.

**Known Issues:**

None

---

Online ROM Flash Component for Linux - HP ProLiant DL980 G7 (P66) Servers

Version: 2015.08.16 **(Recommended)**

Filename: RPMS/i386/hp-firmware-system-p66-2015.08.16-1.1.i386.rpm

### **Important Note!**

#### **Important Notes:**

None

#### **Deliverable Name:**

HP ProLiant DL980 G7 System ROM - P66

#### **Release Version:**

08/16/2015

#### **Last Recommended or Critical Revision:**

08/16/2015

#### **Previous Revision:**

08/15/2014

#### **Firmware Dependencies:**

None

#### **Enhancements/New Features:**

None

#### **Problems Fixed:**

While HP ProLiant servers using impacted Intel processors are not vulnerable to the specific attack announced publicly at the Blackhat USA 2015 security conference, this BIOS update includes updated microcodes from Intel which prevent the possibility of exploiting the processor vulnerability that make the attack possible. This Intel processor vulnerability is NOT unique to HP ProLiant servers.

#### **Known Issues:**

None

### **Fixes**

#### **Important Notes:**

None

#### **Firmware Dependencies:**

None

#### **Problems Fixed:**

While HP ProLiant servers using impacted Intel processors are not vulnerable to the specific attack announced publicly at the Blackhat USA 2015 security conference, this BIOS update includes updated microcodes from Intel which prevent the possibility of exploiting the processor vulnerability that make the attack possible. This Intel processor vulnerability is NOT unique to HP ProLiant servers.

**Known Issues:**

None

---

Online ROM Flash Component for Linux - HP ProLiant ML110 G7/DL120 G7 (J01) Servers

Version: 2013.07.01 (B) **(Critical)**

Filename: RPMS/i386/hp-firmware-system-j01-2013.07.01-2.1.i386.rpm

**Important Note!**

**Important Notes:**

Ver. 2013.07.01 (B) contains updates to the component packaging and is functionally equivalent to ver. 2013.07.01. It is not necessary to upgrade with Revision B if a previous component Revision was used to upgrade the system ROM to version 2013.07.01.

**Deliverable Name:**

HP ProLiant ML110 G7 and DL120 G7 System ROM - J01

**Release Version:**

07/01/2013

**Last Recommended or Critical Revision:**

07/01/2013

**Previous Revision:**

12/04/2012

**Firmware Dependencies:**

None

**Enhancements/New Features:**

None

**Problems Fixed:**

Addressed a processor issue under which a rare and complex sequence of internal processor microarchitecture events that occur in specific operating environments could cause a server system to experience unexpected page faults, general protection faults, or machine check exceptions or other unpredictable system behavior. While all processors supported by this server have this issue, to be affected by this issue the server must be operating in a virtualized environment, have Intel Hyperthreading enabled, have a hypervisor that enables Intel VT FlexPriority and Extended Page Tables, and have a guest OS utilizing 32-bit PAE Paging Mode. This issue is not unique to HP ProLiant servers and could impact any system utilizing affected processors operating with the conditions listed above. This revision of the System ROM contains an updated version of Intel's microcode that addresses this issue. Due to the potential severity of the issue addressed in this revision of the System ROM, this System ROM upgrade is considered a critical fix.

**Known Issues:**

None

## **Prerequisites**

The "HPE ProLiant iLO 3/4 Channel Interface Driver" (CHIF) for Linux which is integrated into the standard Linux kernel.

## **Fixes**

### **Important Notes:**

Ver. 2013.07.01 (B) contains updates to the component packaging and is functionally equivalent to ver. 2013.07.01. It is not necessary to upgrade with Revision B if a previous component Revision was used to upgrade the system ROM to version 2013.07.01.

### **Firmware Dependencies:**

None

### **Problems Fixed:**

Addressed a processor issue under which a rare and complex sequence of internal processor microarchitecture events that occur in specific operating environments could cause a server system to experience unexpected page faults, general protection faults, or machine check exceptions or other unpredictable system behavior. While all processors supported by this server have this issue, to be affected by this issue the server must be operating in a virtualized environment, have Intel Hyperthreading enabled, have a hypervisor that enables Intel VT FlexPriority and Extended Page Tables, and have a guest OS utilizing 32-bit PAE Paging Mode. This issue is not unique to HP ProLiant servers and could impact any system utilizing affected processors operating with the conditions listed above. This revision of the System ROM contains an updated version of Intel's microcode that addresses this issue. Due to the potential severity of the issue addressed in this revision of the System ROM, this System ROM upgrade is considered a critical fix.

### **Known Issues:**

None

---

Online ROM Flash Component for Linux - HP ProLiant SL335s G7 (A24) Servers

Version: 2012.12.08 (C) **(Recommended)**

Filename: RPMS/i386/hp-firmware-system-a24-2012.12.08-3.i386.rpm

## **Important Note!**

### **Important Notes:**

Ver. 2012.12.08 (C) contains a documentation update only and is functionally equivalent to ver. 2012.12.08. It is not necessary to upgrade with Revision C if a previous component Revision was used to upgrade the system ROM to version 2012.12.08.

### **Deliverable Name:**

HP ProLiant SL335s G7 System ROM - A24

### **Release Date:**

12/08/2012

### **Last Recommended or Critical Revision:**

12/08/2012

### **Previous Revision:**



09/01/2012

**Firmware Dependencies:**

None

**Enhancements/New Features:**

Optimized the memory settings to improve the reliability of the memory system.

Added the latest product names of optional expansion cards and updated language translations (for non-English modes) in the ROM-Based Setup Utility (RBSU).

**Problems Fixed:**

Resolved an issue that could result in a server reset or the inability to boot. Servers should be updated to this revision of the system ROM to minimize the potential for a system reset or the inability to boot.

Resolved an issue where industry standard tools, operating systems, and HP utilities may report less Level 3 (L3) cache than expected.

Resolved a rare issue where the system and IML may indicate an uncorrectable reset when upgrading to the 09/01/2012 system ROM.

**Known Issues:**

None

**Fixes**

**Important Notes:**

Ver. 2012.12.08 (C) contains a documentation update only and is functionally equivalent to ver. 2012.12.08. It is not necessary to upgrade with Revision C if a previous component Revision was used to upgrade the system ROM to version 2012.12.08.

**Firmware Dependencies:**

None

**Problems Fixed:**

Resolved an issue that could result in a server reset or the inability to boot. Servers should be updated to this revision of the system ROM to minimize the potential for a system reset or the inability to boot.

Resolved an issue where industry standard tools, operating systems, and HP utilities may report less Level 3 (L3) cache than expected.

Resolved a rare issue where the system and IML may indicate an uncorrectable reset when upgrading to the 09/01/2012 system ROM.

**Known Issues:**

None

**Enhancements**

Optimized the memory settings to improve the reliability of the memory system.

Added the latest product names of optional expansion cards and updated language translations (for non-English modes) in the ROM-Based Setup Utility (RBSU).

---

### **Important Note!**

**Important Notes:**

None

**Deliverable Name:**

HP ProLiant SL390s G7 System ROM - P69

**Release Date:**

08/16/2015

**Last Recommended or Critical Revision:**

08/16/2015

**Previous Revision:**

07/02/2013

**Firmware Dependencies:**

None

**Enhancements/New Features:**

None

**Problems Fixed:**

While HP ProLiant servers using impacted Intel processors are not vulnerable to the specific attack announced publicly at the Blackhat USA 2015 security conference, this BIOS update includes updated microcodes from Intel which prevent the possibility of exploiting the processor vulnerability that make the attack possible. This Intel processor vulnerability is NOT unique to HP ProLiant servers.

**Known Issues:**

None

### **Fixes**

**Important Notes:**

None

**Firmware Dependencies:**

None

**Problems Fixed:**

While HP ProLiant servers using impacted Intel processors are not vulnerable to the specific attack announced publicly at the Blackhat USA 2015 security conference, this BIOS update includes updated microcodes from Intel which prevent the possibility of exploiting the processor vulnerability that make the attack possible. This Intel processor vulnerability is NOT unique to HP ProLiant servers.

**Known Issues:**

None

---

Online ROM Flash Component for Linux - HP ProLiant SL4545 G7 (A31) Servers

Version: 2013.11.02 (B) **(Optional)**

Filename: RPMS/i386/hp-firmware-system-a31-2013.11.02-2.1.i386.rpm

**Important Note!****Important Notes:**

Ver. 2013.11.02 (B) contains updates to the component packaging and is functionally equivalent to ver. 2013.11.02. It is not necessary to upgrade with Revision B if a previous component Revision was used to upgrade the system ROM to version 2013.11.02.

**Deliverable Name:**

HP ProLiant SL4545 G7 System ROM - A31

**Release Version:**

11/02/2013

**Last Recommended or Critical Revision:**

12/08/2012

**Previous Revision:**

06/05/2013

**Firmware Dependencies:**

None

**Enhancements/New Features:**

Added the latest product names of optional expansion cards in the ROM-Based Setup Utility (RBSU).

**Problems Fixed:**

None

**Known Issues:**

None

**Prerequisites**

The "HPE ProLiant iLO 3/4 Channel Interface Driver" (CHIF) for Linux which is integrated into the standard Linux kernel.

**Enhancements****Important Notes:**

Ver. 2013.11.02 (B) contains updates to the component packaging and is functionally equivalent to ver. 2013.11.02. It is not necessary to upgrade with Revision B if a previous component Revision was used to upgrade the system ROM to version 2013.11.02.

**Firmware Dependencies:**

None

**Enhancements/New Features:**

Added the latest product names of optional expansion cards in the ROM-Based Setup Utility (RBSU).

**Known Issues:**

None

---

Online ROM Flash Component for VMware ESXi - HP ProLiant BL460c G7 (I27) Servers

Version: 2015.08.16 **(Recommended)**

Filename: CPO28127.zip

**Important Note!****Important Notes:**

None

**Deliverable Name:**

HP ProLiant BL460c G7 System ROM - I27

**Release Version:**

08/16/2015

**Last Recommended or Critical Revision:**

08/16/2015

**Previous Revision:**

07/02/2013

**Firmware Dependencies:**

None

**Enhancements/New Features:**

None

**Problems Fixed:**

While HP ProLiant servers using impacted Intel processors are not vulnerable to the specific attack announced publicly at the Blackhat USA 2015 security conference, this BIOS update includes updated microcodes from Intel which prevent the possibility of exploiting the processor vulnerability that make the attack possible. This Intel processor vulnerability is NOT unique to HP ProLiant servers.

**Known Issues:**

None

**Fixes**

**Important Notes:**

None

**Firmware Dependencies:**

None

**Problems Fixed:**

While HP ProLiant servers using impacted Intel processors are not vulnerable to the specific attack announced publicly at the Blackhat USA 2015 security conference, this BIOS update includes updated microcodes from Intel which prevent the possibility of exploiting the processor vulnerability that make the attack possible. This Intel processor vulnerability is NOT unique to HP ProLiant servers.

**Known Issues:**

None

---

Online ROM Flash Component for VMware ESXi - HP ProLiant BL465c G7 (A19) Servers

Version: 2014.02.02 (C) **(Optional)**

Filename: CP026050.zip

**Important Note!****Important Notes:**

Ver. 2014.02.02 (C) contains updates to the component packaging and is functionally equivalent to ver. 2014.02.02. It is not necessary to upgrade with Revision C if a previous component Revision was used to upgrade the system ROM to version 2014.02.02.

**Deliverable Name:**

HP ProLiant BL465c G7 System ROM - A19

**Release Date:**

02/02/2014

**Last Recommended or Critical Revision:**

12/08/2012

**Previous Revision:**

12/08/2012

**Firmware Dependencies:**

None

**Enhancements/New Features:**

None

**Problems Fixed:**

Resolved a very rare condition where the system could become unresponsive or unexpectedly reset when running with AMD Opteron 6100 or 6200 processors.

**Known Issues:**

None

**Fixes****Important Notes:**

Ver. 2014.02.02 (C) contains updates to the component packaging and is functionally equivalent to ver. 2014.02.02. It is not necessary to upgrade with Revision C if a previous component Revision was used to upgrade the system ROM to version 2014.02.02.

**Firmware Dependencies:**

None

**Problems Fixed:**

Resolved a very rare condition where the system could become unresponsive or unexpectedly reset when running with AMD Opteron 6100 or 6200 processors.

**Known Issues:**

None

---

Online ROM Flash Component for VMware ESXi - HP ProLiant BL490c G7 (I28) Servers

Version: 2015.08.16 **(Recommended)**

Filename: CP028138.zip

**Important Note!****Important Notes:**

None

**Deliverable Name:**

HP ProLiant BL490c G7 System ROM - I28

**Release Version:**

08/16/2015

**Last Recommended or Critical Revision:**

08/16/2015

**Previous Revision:**

07/02/2013

**Firmware Dependencies:**

None

**Enhancements/New Features:**

None

**Problems Fixed:**

While HP ProLiant servers using impacted Intel processors are not vulnerable to the specific attack announced publicly at the Blackhat USA 2015 security conference, this BIOS update includes updated microcodes from Intel which prevent the possibility of exploiting the processor vulnerability that make the attack possible. This Intel processor vulnerability is NOT unique to HP ProLiant servers.

**Known Issues:**

None

**Fixes**

**Important Notes:**

None

**Firmware Dependencies:**

None

**Problems Fixed:**

While HP ProLiant servers using impacted Intel processors are not vulnerable to the specific attack announced publicly at the Blackhat USA 2015 security conference, this BIOS update includes updated microcodes from Intel which prevent the possibility of exploiting the processor vulnerability that make the attack possible. This Intel processor vulnerability is NOT unique to HP ProLiant servers.

**Known Issues:**

None

---

Online ROM Flash Component for VMware ESXi - HP ProLiant BL680c G7/BL620c G7 (I25) Servers

Version: 2015.08.16 **(Recommended)**

Filename: CP028112.zip

**Important Note!**

**Important Notes:**

None

**Deliverable Name:**

HP ProLiant BL680c G7/BL620c G7 System ROM - I25

**Release Version:**

08/16/2015

**Last Recommended or Critical Revision:**

08/16/2015

**Previous Revision:**

07/01/2013

**Firmware Dependencies:**

None

**Enhancements/New Features:**

None

**Problems Fixed:**

While HP ProLiant servers using impacted Intel processors are not vulnerable to the specific attack announced publicly at the Blackhat USA 2015 security conference, this BIOS update includes updated microcodes from Intel which prevent the possibility of exploiting the processor vulnerability that make the attack possible. This Intel processor vulnerability is NOT unique to HP ProLiant servers.

**Known Issues:**

None

**Fixes****Important Notes:**

None

**Firmware Dependencies:**

None

**Problems Fixed:**

While HP ProLiant servers using impacted Intel processors are not vulnerable to the specific attack announced publicly at the Blackhat USA 2015 security conference, this BIOS update includes updated microcodes from Intel which prevent the possibility of exploiting the processor vulnerability that make the attack possible. This Intel processor vulnerability is NOT unique to HP ProLiant servers.

**Known Issues:**

None

---

Online ROM Flash Component for VMware ESXi - HP ProLiant BL685c G7 (A20) Servers

Version: 2016.03.07 **(Recommended)**

Filename: CPO29832.zip

**Important Note!****Important Notes:**

None

**Deliverable Name:**

HP ProLiant BL685c G7 System ROM

**Release Version:**

03/07/2016

**Last Recommended or Critical Revision:**



03/07/2016

**Previous Revision:**

09/03/2014

**Firmware Dependencies:**

None

**Enhancements/New Features:**

None

**Problems Fixed:**

Addressed an issue with AMD Opteron 6300 series processors in which the processor may experience unpredictable system behavior in virtualized environments due to an issue with the revision of the AMD microcode included in the 09/03/2014 revision of the System ROM. Only the 09/03/2014 revision of the System ROM is impacted by this issue. This revision of the System ROM contains an updated version of AMD's microcode that addresses this issue. This issue is NOT unique to HPE ProLiant servers and could impact any system utilizing affected processors with the affected AMD microcode. Due to the potential severity of the issue addressed in this revision of the System ROM, it is highly recommended that the System ROM be upgraded for impacted systems.

**Known Issues:**

None

**Fixes**

**Important Notes:**

None

**Firmware Dependencies:**

None

**Problems Fixed:**

Addressed an issue with AMD Opteron 6300 series processors in which the processor may experience unpredictable system behavior in virtualized environments due to an issue with the revision of the AMD microcode included in the 09/03/2014 revision of the System ROM. Only the 09/03/2014 revision of the System ROM is impacted by this issue. This revision of the System ROM contains an updated version of AMD's microcode that addresses this issue. This issue is NOT unique to HPE ProLiant servers and could impact any system utilizing affected processors with the affected AMD microcode. Due to the potential severity of the issue addressed in this revision of the System ROM, it is highly recommended that the System ROM be upgraded for impacted systems.

**Known Issues:**

None

---

Online ROM Flash Component for VMware ESXi - HP ProLiant DL360 G7 (P68) Servers

Version: 2015.08.16 **(Recommended)**

Filename: CPO28091.zip

**Important Note!**

**Important Notes:**

None

**Deliverable Name:**

HP ProLiant DL360 G7 System ROM - P68

**Release Version:**

08/16/2015

**Last Recommended or Critical Revision:**

08/16/2015

**Previous Revision:**

07/02/2013

**Firmware Dependencies:**

None

**Enhancements/New Features:**

None

**Problems Fixed:**

While HP ProLiant servers using impacted Intel processors are not vulnerable to the specific attack announced publicly at the Blackhat USA 2015 security conference, this BIOS update includes updated microcodes from Intel which prevent the possibility of exploiting the processor vulnerability that make the attack possible. This Intel processor vulnerability is NOT unique to HP ProLiant servers.

**Known Issues:**

None

**Fixes**

**Important Notes:**

None

**Firmware Dependencies:**

None

**Problems Fixed:**

While HP ProLiant servers using impacted Intel processors are not vulnerable to the specific attack announced publicly at the Blackhat USA 2015 security conference, this BIOS update includes updated microcodes from Intel which prevent the possibility of exploiting the processor vulnerability that make the attack possible. This Intel processor vulnerability is NOT unique to HP ProLiant servers.

**Known Issues:**

None

**Important Note!**

**Important Notes:**

None

**Deliverable Name:**

HP ProLiant DL380 G7 System ROM - P67

**Release Version:**

08/16/2015

**Last Recommended or Critical Revision:**

08/16/2015

**Previous Revision:**

07/02/2013

**Firmware Dependencies:**

None

**Enhancements/New Features:**

None

**Problems Fixed:**

While HP ProLiant servers using impacted Intel processors are not vulnerable to the specific attack announced publicly at the Blackhat USA 2015 security conference, this BIOS update includes updated microcodes from Intel which prevent the possibility of exploiting the processor vulnerability that make the attack possible. This Intel processor vulnerability is NOT unique to HP ProLiant servers.

**Known Issues:**

None

**Fixes**

**Important Notes:**

None

**Firmware Dependencies:**

None

**Problems Fixed:**

While HP ProLiant servers using impacted Intel processors are not vulnerable to the specific attack announced publicly at the Blackhat USA 2015 security conference, this BIOS update includes updated microcodes from Intel which prevent the possibility of exploiting the processor vulnerability that make the attack possible. This Intel processor vulnerability is NOT unique to HP ProLiant servers.

**Known Issues:**

None

---

Online ROM Flash Component for VMware ESXi - HP ProLiant DL385 G7 (A18) Servers

Version: 2014.02.02 (E) **(Optional)**

Filename: CPO26045.zip

### **Important Note!**

#### **Important Notes:**

Ver. 2014.02.02 (E) contains updates to the component packaging and is functionally equivalent to ver. 2014.02.02. It is not necessary to upgrade with Revision E if a previous component Revision was used to upgrade the system ROM to version 2014.02.02.

#### **Deliverable Name:**

HP ProLiant DL385 G7 System ROM - A18

#### **Release Date:**

02/02/2014

#### **Last Recommended or Critical Revision:**

12/08/2012

#### **Previous Revision:**

12/08/2012

#### **Firmware Dependencies:**

None

#### **Enhancements/New Features:**

None

#### **Problems Fixed:**

Resolved a very rare condition where the system could become unresponsive or unexpectedly reset when running with AMD Opteron 6100 or 6200 processors.

#### **Known Issues:**

None

### **Fixes**

#### **Important Notes:**

Ver. 2014.02.02 (E) contains updates to the component packaging and is functionally equivalent to ver. 2014.02.02. It is not necessary to upgrade with Revision E if a previous component Revision was used to upgrade the system ROM to version 2014.02.02.

#### **Firmware Dependencies:**

None

**Problems Fixed:**

Resolved a very rare condition where the system could become unresponsive or unexpectedly reset when running with AMD Opteron 6100 or 6200 processors.

**Known Issues:**

None

---

Online ROM Flash Component for VMware ESXi - HP ProLiant DL580 G7 (P65) Servers

Version: 2015.08.16 **(Recommended)**

Filename: CP028087.zip

**Important Note!****Important Notes:**

None

**Deliverable Name:**

HP ProLiant DL580 G7 System ROM - P65

**Release Version:**

08/16/2015

**Last Recommended or Critical Revision:**

08/16/2015

**Previous Revision:**

10/01/2013

**Firmware Dependencies:**

None

**Enhancements/New Features:**

None

**Problems Fixed:**

While HP ProLiant servers using impacted Intel processors are not vulnerable to the specific attack announced publicly at the Blackhat USA 2015 security conference, this BIOS update includes updated microcodes from Intel which prevent the possibility of exploiting the processor vulnerability that make the attack possible. This Intel processor vulnerability is NOT unique to HP ProLiant servers.

**Known Issues:**

None

**Fixes****Important Notes:**

None

**Firmware Dependencies:**

None

**Problems Fixed:**

While HP ProLiant servers using impacted Intel processors are not vulnerable to the specific attack announced publicly at the Blackhat USA 2015 security conference, this BIOS update includes updated microcodes from Intel which prevent the possibility of exploiting the processor vulnerability that make the attack possible. This Intel processor vulnerability is NOT unique to HP ProLiant servers.

**Known Issues:**

None

---

Online ROM Flash Component for VMware ESXi - HP ProLiant DL585 G7 (A16) Servers

Version: 2016.03.07 **(Recommended)**

Filename: CPO29828.zip

**Important Note!****Important Notes:**

None

**Deliverable Name:**

HP ProLiant DL585 G7 System ROM

**Release Version:**

03/07/2016

**Last Recommended or Critical Revision:**

03/07/2016

**Previous Revision:**

09/03/2014

**Firmware Dependencies:**

None

**Enhancements/New Features:**

None

**Problems Fixed:**

Addressed an issue with AMD Opteron 6300 series processors in which the processor may experience unpredictable system behavior in virtualized environments due to an issue with the revision of the AMD microcode included in the 09/03/2014 revision of the System ROM. Only the 09/03/2014 revision of the System ROM is impacted by this issue. This revision of the System ROM contains an updated version of AMD's microcode that addresses this issue. This issue is NOT unique to HPE ProLiant servers and could impact any system utilizing affected processors with the affected AMD microcode. Due to the potential severity of the issue addressed in this revision of the System ROM, it is highly recommended that the System ROM be upgraded for impacted systems.

**Known Issues:**

None

## **Fixes**

### **Important Notes:**

None

### **Firmware Dependencies:**

None

### **Problems Fixed:**

Addressed an issue with AMD Opteron 6300 series processors in which the processor may experience unpredictable system behavior in virtualized environments due to an issue with the revision of the AMD microcode included in the 09/03/2014 revision of the System ROM. Only the 09/03/2014 revision of the System ROM is impacted by this issue. This revision of the System ROM contains an updated version of AMD's microcode that addresses this issue. This issue is NOT unique to HPE ProLiant servers and could impact any system utilizing affected processors with the affected AMD microcode. Due to the potential severity of the issue addressed in this revision of the System ROM, it is highly recommended that the System ROM be upgraded for impacted systems.

### **Known Issues:**

None

---

Online ROM Flash Component for VMware ESXi - HP ProLiant DL980 G7 (P66) Servers

Version: 2015.08.16 **(Recommended)**

Filename: CP028148.zip

## **Important Note!**

### **Important Notes:**

None

### **Deliverable Name:**

HP ProLiant DL980 G7 System ROM - P66

### **Release Version:**

08/16/2015

### **Last Recommended or Critical Revision:**

08/16/2015

### **Previous Revision:**

08/15/2014

### **Firmware Dependencies:**

None

### **Enhancements/New Features:**

None

**Problems Fixed:**

While HP ProLiant servers using impacted Intel processors are not vulnerable to the specific attack announced publicly at the Blackhat USA 2015 security conference, this BIOS update includes updated microcodes from Intel which prevent the possibility of exploiting the processor vulnerability that make the attack possible. This Intel processor vulnerability is NOT unique to HP ProLiant servers.

**Known Issues:**

None

**Fixes**

**Important Notes:**

None

**Firmware Dependencies:**

None

**Problems Fixed:**

While HP ProLiant servers using impacted Intel processors are not vulnerable to the specific attack announced publicly at the Blackhat USA 2015 security conference, this BIOS update includes updated microcodes from Intel which prevent the possibility of exploiting the processor vulnerability that make the attack possible. This Intel processor vulnerability is NOT unique to HP ProLiant servers.

**Known Issues:**

None

---

Online ROM Flash Component for VMware ESXi - HP ProLiant SL4545 G7 (A31) Servers

Version: 2013.11.02 (B) **(Optional)**

Filename: CP024186.scexe

**Important Note!**

**Important Notes:**

Version 2013.11.02 (B) contains an update to the flash driver and replaces version 2013.11.02. The actual firmware contained within version 2013.11.02 (B) did not change as compared to version 2013.11.02 and therefore it is not necessary to upgrade if version 2013.11.02 has already been installed.

**Deliverable Name:**

HP ProLiant SL4545 G7 System ROM - A31

**Release Date:**

11/02/2013

**Last Recommended or Critical Revision:**

12/08/2012

**Previous Revision:**



06/05/2013

**Firmware Dependencies:**

None

**Enhancements/New Features:**

Added the latest product names of optional expansion cards in the ROM-Based Setup Utility (RBSU).

**Problems Fixed:**

None

**Known Issues:**

None

**Enhancements**

**Important Notes:**

Version 2013.11.02 (B) contains an update to the flash driver and replaces version 2013.11.02. The actual firmware contained within version 2013.11.02 (B) did not change as compared to version 2013.11.02 and therefore it is not necessary to upgrade if version 2013.11.02 has already been installed.

**Firmware Dependencies:**

None

**Enhancements/New Features:**

Added the latest product names of optional expansion cards in the ROM-Based Setup Utility (RBSU).

**Known Issues:**

None

---

Online ROM Flash Component for Windows - HP ProLiant BL2x220c G7 (I29) Servers

Version: 2015.08.16 **(Recommended)**

Filename: cp028113.exe

**Important Note!**

**Important Notes:**

None

**Deliverable Name:**

HP ProLiant BL2x220c G7 System ROM - I29

**Release Version:**

08/16/2015

**Last Recommended or Critical Revision:**

08/16/2015

**Previous Revision:**

07/02/2013

**Firmware Dependencies:**

None

**Enhancements/New Features:**

None

**Problems Fixed:**

While HP ProLiant servers using impacted Intel processors are not vulnerable to the specific attack announced publicly at the Blackhat USA 2015 security conference, this BIOS update includes updated microcodes from Intel which prevent the possibility of exploiting the processor vulnerability that make the attack possible. This Intel processor vulnerability is NOT unique to HP ProLiant servers.

**Known Issues:**

None

**Fixes**

**Important Notes:**

None

**Firmware Dependencies:**

None

**Problems Fixed:**

While HP ProLiant servers using impacted Intel processors are not vulnerable to the specific attack announced publicly at the Blackhat USA 2015 security conference, this BIOS update includes updated microcodes from Intel which prevent the possibility of exploiting the processor vulnerability that make the attack possible. This Intel processor vulnerability is NOT unique to HP ProLiant servers.

**Known Issues:**

None

---

Online ROM Flash Component for Windows - HP ProLiant BL460c G7 (I27) Servers

Version: 2015.08.16 **(Recommended)**

Filename: cp028124.exe

**Important Note!**

**Important Notes:**

None

**Deliverable Name:**

HP ProLiant BL460c G7 System ROM - I27

**Release Version:**

08/16/2015

**Last Recommended or Critical Revision:**

08/16/2015

**Previous Revision:**

07/02/2013

**Firmware Dependencies:**

None

**Enhancements/New Features:**

None

**Problems Fixed:**

While HP ProLiant servers using impacted Intel processors are not vulnerable to the specific attack announced publicly at the Blackhat USA 2015 security conference, this BIOS update includes updated microcodes from Intel which prevent the possibility of exploiting the processor vulnerability that make the attack possible. This Intel processor vulnerability is NOT unique to HP ProLiant servers.

**Known Issues:**

None

**Fixes****Important Notes:**

None

**Firmware Dependencies:**

None

**Problems Fixed:**

While HP ProLiant servers using impacted Intel processors are not vulnerable to the specific attack announced publicly at the Blackhat USA 2015 security conference, this BIOS update includes updated microcodes from Intel which prevent the possibility of exploiting the processor vulnerability that make the attack possible. This Intel processor vulnerability is NOT unique to HP ProLiant servers.

**Known Issues:**

None

---

Online ROM Flash Component for Windows - HP ProLiant BL465c G7 (A19) Servers

Version: 2014.02.02 (B) **(Optional)**

Filename: cp023998.exe

**Important Note!****Important Notes:**

Component packaging has been updated; no impact to product's functionality.

**Deliverable Name:**

HP ProLiant BL465c G7 System ROM - A19

**Release Date:**

02/02/2014

**Last Recommended or Critical Revision:**

12/08/2012

**Previous Revision:**

12/08/2012

**Firmware Dependencies:**

None

**Enhancements/New Features:**

None

**Problems Fixed:**

Resolved a very rare condition where the system could become unresponsive or unexpectedly reset when running with AMD Opteron 6100 or 6200 processors.

**Known Issues:**

None

**Fixes**

**Important Notes:**

Component packaging has been updated; no impact to product's functionality.

**Firmware Dependencies:**

None

**Problems Fixed:**

Resolved a very rare condition where the system could become unresponsive or unexpectedly reset when running with AMD Opteron 6100 or 6200 processors.

**Known Issues:**

None

---

### **Important Note!**

**Important Notes:**

None

**Deliverable Name:**

HP ProLiant BL490c G7 System ROM - I28

**Release Version:**

08/16/2015

**Last Recommended or Critical Revision:**

08/16/2015

**Previous Revision:**

07/02/2013

**Firmware Dependencies:**

None

**Enhancements/New Features:**

None

**Problems Fixed:**

While HP ProLiant servers using impacted Intel processors are not vulnerable to the specific attack announced publicly at the Blackhat USA 2015 security conference, this BIOS update includes updated microcodes from Intel which prevent the possibility of exploiting the processor vulnerability that make the attack possible. This Intel processor vulnerability is NOT unique to HP ProLiant servers.

**Known Issues:**

None

### **Fixes**

**Important Notes:**

None

**Firmware Dependencies:**

None

**Problems Fixed:**

While HP ProLiant servers using impacted Intel processors are not vulnerable to the specific attack announced publicly at the Blackhat USA 2015 security conference, this BIOS update includes updated microcodes from Intel which prevent the possibility of exploiting the processor vulnerability that make the attack possible. This Intel processor vulnerability is NOT unique to HP ProLiant servers.

**Known Issues:**

None

---

Online ROM Flash Component for Windows - HP ProLiant BL680c G7/BL620c G7 (I25) Servers

Version: 2015.08.16 **(Recommended)**

Filename: cp028109.exe

**Important Note!****Important Notes:**

None

**Deliverable Name:**

HP ProLiant BL680c G7/BL620c G7 System ROM - I25

**Release Version:**

08/16/2015

**Last Recommended or Critical Revision:**

08/16/2015

**Previous Revision:**

07/01/2013

**Firmware Dependencies:**

None

**Enhancements/New Features:**

None

**Problems Fixed:**

While HP ProLiant servers using impacted Intel processors are not vulnerable to the specific attack announced publicly at the Blackhat USA 2015 security conference, this BIOS update includes updated microcodes from Intel which prevent the possibility of exploiting the processor vulnerability that make the attack possible. This Intel processor vulnerability is NOT unique to HP ProLiant servers.

**Known Issues:**

None

**Fixes****Important Notes:**

None

**Firmware Dependencies:**

None

**Problems Fixed:**

While HP ProLiant servers using impacted Intel processors are not vulnerable to the specific attack announced publicly at the Blackhat USA 2015 security conference, this BIOS update includes updated microcodes from Intel which prevent the possibility of exploiting the processor vulnerability that make the attack possible. This Intel processor vulnerability is NOT unique to HP ProLiant servers.

**Known Issues:**

None

---

Online ROM Flash Component for Windows - HP ProLiant BL685c G7 (A20) Servers

Version: 2016.03.07 **(Recommended)**

Filename: cp029829.exe

**Important Note!****Important Notes:**

None

**Deliverable Name:**

HP ProLiant BL685c G7 System ROM

**Release Version:**

03/07/2016

**Last Recommended or Critical Revision:**

03/07/2016

**Previous Revision:**

09/03/2014

**Firmware Dependencies:**

None

**Enhancements/New Features:**

None

**Problems Fixed:**

Addressed an issue with AMD Opteron 6300 series processors in which the processor may experience unpredictable system behavior in virtualized environments due to an issue with the revision of the AMD microcode included in the 09/03/2014 revision of the System ROM. Only the 09/03/2014 revision of the System ROM is impacted by this issue. This revision of the System ROM contains an updated version of AMD's microcode that addresses this issue. This issue is NOT unique to HPE ProLiant servers and could impact any system utilizing affected processors with the affected AMD microcode. Due to the potential severity of the issue addressed in this revision of the System ROM, it is highly recommended that the System ROM be upgraded for impacted systems.

**Known Issues:**

None

## Fixes

### Important Notes:

None

### Firmware Dependencies:

None

### Problems Fixed:

Addressed an issue with AMD Opteron 6300 series processors in which the processor may experience unpredictable system behavior in virtualized environments due to an issue with the revision of the AMD microcode included in the 09/03/2014 revision of the System ROM. Only the 09/03/2014 revision of the System ROM is impacted by this issue. This revision of the System ROM contains an updated version of AMD's microcode that addresses this issue. This issue is NOT unique to HPE ProLiant servers and could impact any system utilizing affected processors with the affected AMD microcode. Due to the potential severity of the issue addressed in this revision of the System ROM, it is highly recommended that the System ROM be upgraded for impacted systems.

### Known Issues:

None

---

Online ROM Flash Component for Windows - HP ProLiant DL360 G7 (P68) Servers

Version: 2015.08.16 **(Recommended)**

Filename: cp028088.exe

## Important Note!

### Important Notes:

None

### Deliverable Name:

HP ProLiant DL360 G7 System ROM - P68

### Release Version:

08/16/2015

### Last Recommended or Critical Revision:

08/16/2015

### Previous Revision:

07/02/2013

### Firmware Dependencies:

None

### Enhancements/New Features:

None

### Problems Fixed:



While HP ProLiant servers using impacted Intel processors are not vulnerable to the specific attack announced publicly at the Blackhat USA 2015 security conference, this BIOS update includes updated microcodes from Intel which prevent the possibility of exploiting the processor vulnerability that make the attack possible. This Intel processor vulnerability is NOT unique to HP ProLiant servers.

**Known Issues:**

None

**Fixes**

**Important Notes:**

None

**Firmware Dependencies:**

None

**Problems Fixed:**

While HP ProLiant servers using impacted Intel processors are not vulnerable to the specific attack announced publicly at the Blackhat USA 2015 security conference, this BIOS update includes updated microcodes from Intel which prevent the possibility of exploiting the processor vulnerability that make the attack possible. This Intel processor vulnerability is NOT unique to HP ProLiant servers.

**Known Issues:**

None

---

Online ROM Flash Component for Windows - HP ProLiant DL380 G7 (P67) Servers

Version: 2015.08.16 **(Recommended)**

Filename: cp028139.exe

**Important Note!**

**Important Notes:**

None

**Deliverable Name:**

HP ProLiant DL380 G7 System ROM - P67

**Release Version:**

08/16/2015

**Last Recommended or Critical Revision:**

08/16/2015

**Previous Revision:**

07/02/2013

**Firmware Dependencies:**

None

**Enhancements/New Features:**

None

**Problems Fixed:**

While HP ProLiant servers using impacted Intel processors are not vulnerable to the specific attack announced publicly at the Blackhat USA 2015 security conference, this BIOS update includes updated microcodes from Intel which prevent the possibility of exploiting the processor vulnerability that make the attack possible. This Intel processor vulnerability is NOT unique to HP ProLiant servers.

**Known Issues:**

None

**Fixes****Important Notes:**

None

**Firmware Dependencies:**

None

**Problems Fixed:**

While HP ProLiant servers using impacted Intel processors are not vulnerable to the specific attack announced publicly at the Blackhat USA 2015 security conference, this BIOS update includes updated microcodes from Intel which prevent the possibility of exploiting the processor vulnerability that make the attack possible. This Intel processor vulnerability is NOT unique to HP ProLiant servers.

**Known Issues:**

None

---

Online ROM Flash Component for Windows - HP ProLiant DL385 G7 (A18) Servers

Version: 2014.02.02 (B) **(Optional)**

Filename: cp023997.exe

**Important Note!****Important Notes:**

Component packaging has been updated; no impact to product's functionality.

**Deliverable Name:**

HP ProLiant DL385 G7 System ROM - A18

**Release Date:**

02/02/2014

**Last Recommended or Critical Revision:**

12/08/2012

**Previous Revision:**

12/08/2012

**Firmware Dependencies:**

None

**Enhancements/New Features:**

None

**Problems Fixed:**

Resolved a very rare condition where the system could become unresponsive or unexpectedly reset when running with AMD Opteron 6100 or 6200 processors.

**Known Issues:**

None

**Fixes**

**Important Notes:**

Component packaging has been updated; no impact to product's functionality.

**Firmware Dependencies:**

None

**Problems Fixed:**

Resolved a very rare condition where the system could become unresponsive or unexpectedly reset when running with AMD Opteron 6100 or 6200 processors.

**Known Issues:**

None

---

Online ROM Flash Component for Windows - HP ProLiant DL580 G7 (P65) Servers

Version: 2015.08.16 **(Recommended)**

Filename: cp028084.exe

**Important Note!**

**Important Notes:**

None

**Deliverable Name:**

HP ProLiant DL580 G7 System ROM - P65

**Release Version:**

08/16/2015

**Last Recommended or Critical Revision:**

08/16/2015

**Previous Revision:**

10/01/2013

**Firmware Dependencies:**

None

**Enhancements/New Features:**

None

**Problems Fixed:**

While HP ProLiant servers using impacted Intel processors are not vulnerable to the specific attack announced publicly at the Blackhat USA 2015 security conference, this BIOS update includes updated microcodes from Intel which prevent the possibility of exploiting the processor vulnerability that make the attack possible. This Intel processor vulnerability is NOT unique to HP ProLiant servers.

**Known Issues:**

None

**Fixes**

**Important Notes:**

None

**Firmware Dependencies:**

None

**Problems Fixed:**

While HP ProLiant servers using impacted Intel processors are not vulnerable to the specific attack announced publicly at the Blackhat USA 2015 security conference, this BIOS update includes updated microcodes from Intel which prevent the possibility of exploiting the processor vulnerability that make the attack possible. This Intel processor vulnerability is NOT unique to HP ProLiant servers.

**Known Issues:**

None

---

Online ROM Flash Component for Windows - HP ProLiant DL585 G7 (A16) Servers

Version: 2016.03.07 **(Recommended)**

Filename: cp029825.exe

**Important Note!**

**Important Notes:**

None

**Deliverable Name:**

HP ProLiant DL585 G7 System ROM

**Release Version:**

03/07/2016

**Last Recommended or Critical Revision:**

03/07/2016

**Previous Revision:**

09/03/2014

**Firmware Dependencies:**

None

**Enhancements/New Features:**

None

**Problems Fixed:**

Addressed an issue with AMD Opteron 6300 series processors in which the processor may experience unpredictable system behavior in virtualized environments due to an issue with the revision of the AMD microcode included in the 09/03/2014 revision of the System ROM. Only the 09/03/2014 revision of the System ROM is impacted by this issue. This revision of the System ROM contains an updated version of AMD's microcode that addresses this issue. This issue is NOT unique to HPE ProLiant servers and could impact any system utilizing affected processors with the affected AMD microcode. Due to the potential severity of the issue addressed in this revision of the System ROM, it is highly recommended that the System ROM be upgraded for impacted systems.

**Known Issues:**

None

**Fixes****Important Notes:**

None

**Firmware Dependencies:**

None

**Problems Fixed:**

Addressed an issue with AMD Opteron 6300 series processors in which the processor may experience unpredictable system behavior in virtualized environments due to an issue with the revision of the AMD microcode included in the 09/03/2014 revision of the System ROM. Only the 09/03/2014 revision of the System ROM is impacted by this issue. This revision of the System ROM contains an updated version of AMD's microcode that addresses this issue. This issue is NOT unique to HPE ProLiant servers and could impact any system utilizing affected processors with the affected AMD microcode. Due to the potential severity of the issue addressed in this revision of the System ROM, it is highly recommended that the System ROM be upgraded for impacted systems.

**Known Issues:**

None

### **Important Note!**

**Important Notes:**

None

**Deliverable Name:**

HP ProLiant DL980 G7 System ROM - P66

**Release Version:**

08/16/2015

**Last Recommended or Critical Revision:**

08/16/2015

**Previous Revision:**

08/15/2014

**Firmware Dependencies:**

None

**Enhancements/New Features:**

None

**Problems Fixed:**

While HP ProLiant servers using impacted Intel processors are not vulnerable to the specific attack announced publicly at the Blackhat USA 2015 security conference, this BIOS update includes updated microcodes from Intel which prevent the possibility of exploiting the processor vulnerability that make the attack possible. This Intel processor vulnerability is NOT unique to HP ProLiant servers.

**Known Issues:**

None

### **Fixes**

**Important Notes:**

None

**Firmware Dependencies:**

None

**Problems Fixed:**

While HP ProLiant servers using impacted Intel processors are not vulnerable to the specific attack announced publicly at the Blackhat USA 2015 security conference, this BIOS update includes updated microcodes from Intel which prevent the possibility of exploiting the processor vulnerability that make the attack possible. This Intel processor vulnerability is NOT unique to HP ProLiant servers.

**Known Issues:**

None

---

Online ROM Flash Component for Windows - HP ProLiant ML110 G7/DL120 G7 (J01) Servers

Version: 2013.07.01 (B) **(Critical)**

Filename: cp024022.exe

### **Important Note!**

#### **Important Notes:**

Component packaging has been updated; no impact to product's functionality.

#### **Deliverable Name:**

HP ProLiant ML110 G7 and DL120 G7 System ROM - J01

#### **Release Date:**

07/01/2013

#### **Last Recommended or Critical Revision:**

07/01/2013

#### **Previous Revision:**

12/04/2012

#### **Firmware Dependencies:**

None

#### **Enhancements/New Features:**

None

#### **Problems Fixed:**

Addressed a processor issue under which a rare and complex sequence of internal processor microarchitecture events that occur in specific operating environments could cause a server system to experience unexpected page faults, general protection faults, or machine check exceptions or other unpredictable system behavior. While all processors supported by this server have this issue, to be affected by this issue the server must be operating in a virtualized environment, have Intel Hyperthreading enabled, have a hypervisor that enables Intel VT FlexPriority and Extended Page Tables, and have a guest OS utilizing 32-bit PAE Paging Mode. This issue is not unique to HP ProLiant servers and could impact any system utilizing affected processors operating with the conditions listed above. This revision of the System ROM contains an updated version of Intel's microcode that addresses this issue. Due to the potential severity of the issue addressed in this revision of the System ROM, this System ROM upgrade is considered a critical fix.

#### **Known Issues:**

None

### **Fixes**

#### **Important Notes:**

Component packaging has been updated; no impact to product's functionality.

**Firmware Dependencies:**

None

**Problems Fixed:**

Addressed a processor issue under which a rare and complex sequence of internal processor microarchitecture events that occur in specific operating environments could cause a server system to experience unexpected page faults, general protection faults, or machine check exceptions or other unpredictable system behavior. While all processors supported by this server have this issue, to be affected by this issue the server must be operating in a virtualized environment, have Intel Hyperthreading enabled, have a hypervisor that enables Intel VT FlexPriority and Extended Page Tables, and have a guest OS utilizing 32-bit PAE Paging Mode. This issue is not unique to HP ProLiant servers and could impact any system utilizing affected processors operating with the conditions listed above. This revision of the System ROM contains an updated version of Intel's microcode that addresses this issue. Due to the potential severity of the issue addressed in this revision of the System ROM, this System ROM upgrade is considered a critical fix.

**Known Issues:**

None

---

Online ROM Flash Component for Windows - HP ProLiant SL335s G7 (A24) Servers

Version: 2012.12.08 (B) **(Recommended)**

Filename: cp024000.exe

**Important Note!****Important Notes:**

Component packaging has been updated; no impact to product's functionality.

**Deliverable Name:**

HP ProLiant SL335s G7 System ROM - A24

**Release Date:**

12/08/2012

**Last Recommended or Critical Revision:**

12/08/2012

**Previous Revision:**

09/01/2012

**Firmware Dependencies:**

None

**Enhancements/New Features:**

Optimized the memory settings to improve the reliability of the memory system.

Added the latest product names of optional expansion cards and updated language translations (for non-English modes) in the ROM-Based Setup Utility (RBSU).

**Problems Fixed:**



Resolved an issue that could result in a server reset or the inability to boot. Servers should be updated to this revision of the system ROM to minimize the potential for a system reset or the inability to boot.

Resolved an issue where industry standard tools, operating systems, and HP utilities may report less Level 3 (L3) cache than expected.

Resolved a rare issue where the system and IML may indicate an uncorrectable reset when upgrading to the 09/01/2012 system ROM.

**Known Issues:**

None

**Fixes**

**Important Notes:**

Component packaging has been updated; no impact to product's functionality.

**Firmware Dependencies:**

None

**Problems Fixed:**

Resolved an issue that could result in a server reset or the inability to boot. Servers should be updated to this revision of the system ROM to minimize the potential for a system reset or the inability to boot.

Resolved an issue where industry standard tools, operating systems, and HP utilities may report less Level 3 (L3) cache than expected.

Resolved a rare issue where the system and IML may indicate an uncorrectable reset when upgrading to the 09/01/2012 system ROM.

**Known Issues:**

None

**Enhancements**

Optimized the memory settings to improve the reliability of the memory system.

Added the latest product names of optional expansion cards and updated language translations (for non-English modes) in the ROM-Based Setup Utility (RBSU).

---

Online ROM Flash Component for Windows - HP ProLiant SL390s G7 (P69) Servers

Version: 2015.08.16 **(Recommended)**

Filename: cp028116.exe

**Important Note!**

**Important Notes:**

None

**Deliverable Name:**

HP ProLiant SL390s G7 System ROM - P69

**Release Date:**

08/16/2015

**Last Recommended or Critical Revision:**

08/16/2015

**Previous Revision:**

07/02/2013

**Firmware Dependencies:**

None

**Enhancements/New Features:**

None

**Problems Fixed:**

While HP ProLiant servers using impacted Intel processors are not vulnerable to the specific attack announced publicly at the Blackhat USA 2015 security conference, this BIOS update includes updated microcodes from Intel which prevent the possibility of exploiting the processor vulnerability that make the attack possible. This Intel processor vulnerability is NOT unique to HP ProLiant servers.

**Known Issues:**

None

**Fixes****Important Notes:**

None

**Firmware Dependencies:**

None

**Problems Fixed:**

While HP ProLiant servers using impacted Intel processors are not vulnerable to the specific attack announced publicly at the Blackhat USA 2015 security conference, this BIOS update includes updated microcodes from Intel which prevent the possibility of exploiting the processor vulnerability that make the attack possible. This Intel processor vulnerability is NOT unique to HP ProLiant servers.

**Known Issues:**

None

---

Online ROM Flash Component for Windows - HP ProLiant SL4545 G7 (A31) Servers

Version: 2013.11.02 (B) **(Optional)**

Filename: cp024001.exe

**Important Note!****Important Notes:**

Component packaging has been updated; no impact to product's functionality.

**Deliverable Name:**

HP ProLiant SL4545 G7 System ROM - A31

**Release Date:**

11/02/2013

**Last Recommended or Critical Revision:**

12/08/2012

**Previous Revision:**

06/05/2013

**Firmware Dependencies:**

None

**Enhancements/New Features:**

Added the latest product names of optional expansion cards in the ROM-Based Setup Utility (RBSU).

**Problems Fixed:**

None

**Known Issues:**

None

**Enhancements**

**Important Notes:**

Component packaging has been updated; no impact to product's functionality.

**Firmware Dependencies:**

None

**Enhancements/New Features:**

Added the latest product names of optional expansion cards in the ROM-Based Setup Utility (RBSU).

**Known Issues:**

None

---

**Driver - Network**

HP Broadcom 1Gb Multifunction Drivers for Windows Server 2008

Version: 7.8.50.0 (D) **(Optional)**

Filename: cp023429.exe

[Top](#)

### **Important Note!**

HP recommends the firmware provided in *HP Broadcom Online Firmware Upgrade Utility for Windows Server 2008*, version 4.0.1.11 or later for use with these drivers.

### **Fixes**

These drivers address an issue that prevents the iSCSI driver from being installed when booting from a storage area network (SAN).

These drivers correct the "SpeedDuplex" advanced property options for several devices.

### **Supported Devices and Features**

This driver supports the following network adapters:

- HP NC373F PCI Express Multifunction Gigabit Server Adapter
- HP NC373T PCI Express Multifunction Gigabit Server Adapter
- HP NC382i Integrated Dual Port Multifunction Gigabit Server Adapter
- HP NC382m Dual Port 1GbE Multifunction BL-c Adapter
- HP NC382T PCI Express Dual Port Gigabit Server Adapter

---

HP Broadcom 1Gb Multifunction Drivers for Windows Server x64 Editions

Version: 7.8.50.0 (E) **(Optional)**

Filename: cp023430.exe

### **Important Note!**

HP recommends the firmware provided in *HP Broadcom Online Firmware Upgrade Utility for Windows Server x64 Editions*, version 4.0.1.11 or later for use with these drivers.

### **Fixes**

These drivers address an issue that prevents the iSCSI driver from being installed when booting from a storage area network (SAN).

These drivers correct the "SpeedDuplex" advanced property options for several devices.

### **Supported Devices and Features**

This driver supports the following network adapters:

- HP NC373F PCI Express Multifunction Gigabit Server Adapter
- HP NC373T PCI Express Multifunction Gigabit Server Adapter
- HP NC382i Integrated Dual Port Multifunction Gigabit Server Adapter
- HP NC382m Dual Port 1GbE Multifunction BL-c Adapter
- HP NC382T PCI Express Dual Port Gigabit Server Adapter

---

HP Broadcom tg3 Ethernet Drivers for VMware vSphere 5.5

Version: 2015.10.01 **(Optional)**

Filename: cp026888.zip

### **Important Note!**

HP recommends the firmware provided in *HP Broadcom NX1 Online Firmware Upgrade Utility for VMware*, version 1.8.6, for use with this driver.

This component is intended to be used by HP applications. It is a zip file that contains the same driver deliverable available from the vmware.com and the HP vibsdepot.hp.com webpages, plus an HP specific CPOxxxxx.xml file.

### **Fixes**

TBD

### **Enhancements**

This driver now supports the HP Ethernet 1Gb 2-port 332i Adapter (22E8).

### **Supported Devices and Features**

These drivers support the following network adapters:

- HP Ethernet 1Gb 2-port 330i Adapter
- HP Ethernet 1Gb 4-port 331FLR Adapter
- HP Ethernet 1Gb 4-port 331i Adapter
- HP Ethernet 1Gb 4-port 331i-SPI Adapter
- HP Ethernet 1Gb 4-port 331T Adapter
- HP Ethernet 1Gb 2-port 332i Adapter
- HP Ethernet 1Gb 2-port 332T Adapter

---

HP Broadcom tg3 Ethernet Drivers for VMware vSphere 6.0

Version: 2015.10.01 **(Optional)**

Filename: cp026889.zip

### **Important Note!**

HP recommends the firmware provided in *HP Broadcom NX1 Online Firmware Upgrade Utility for VMware*, version 1.8.6, for use with this driver.

This component is intended to be used by HP applications. It is a zip file that contains the same driver deliverable available from the vmware.com and the HP vibsdepot.hp.com webpages, plus an HP specific CPOxxxxx.xml file.

### **Enhancements**

This driver now supports the HP Ethernet 1Gb 2-port 332i Adapter (22E8).

### **Supported Devices and Features**

These drivers support the following network adapters:

- HP Ethernet 1Gb 2-port 330i Adapter
- HP Ethernet 1Gb 4-port 331FLR Adapter
- HP Ethernet 1Gb 4-port 331i Adapter

- HP Ethernet 1Gb 4-port 331i-SPI Adapter
- HP Ethernet 1Gb 4-port 331T Adapter
- HP Ethernet 1Gb 2-port 332i Adapter
- HP Ethernet 1Gb 2-port 332T Adapter

---

HP Intel E1R Driver for Windows Server 2008

Version: 12.7.29.0 (C) **(Optional)**

Filename: cp019461.exe

### **Fixes**

This driver addresses an issue where a “link down” message is recorded in the Windows system event log during every system boot regardless of the actual state of the link.

### **Enhancements**

This driver now supports the following network adapters:

- HP Ethernet 1Gb 2-port 363i Adapter
- HP Ethernet 1Gb 1-port 364i Adapter
- HP Ethernet 1Gb 2-port 367i Adapter

### **Supported Devices and Features**

This driver supports the following HP Intel E1R network adapters:

- HP NC365T PCI Express Quad Port Gigabit Server Adapter
- HP Ethernet 1Gb 2-port 361i Adapter
- HP Ethernet 1Gb 2-port 361FLB Adapter
- HP Ethernet 1Gb 2-port 361T Adapter
- HP Ethernet 1Gb 2-port 363i Adapter
- HP Ethernet 1Gb 1-port 364i Adapter
- HP Ethernet 1Gb 4-port 366FLR Adapter
- HP Ethernet 1Gb 4-port 366i Adapter
- HP Ethernet 1Gb 4-port 366M Adapter
- HP Ethernet 1Gb 2-port 367i Adapter

---

HP Intel E1R Driver for Windows Server 2008 x64 Editions

Version: 12.7.29.0 (C) **(Optional)**

Filename: cp019462.exe

### **Fixes**

This driver addresses an issue where a “link down” message is recorded in the Windows system event log during every system boot regardless of the actual state of the link.

### **Enhancements**

This driver now supports the following network adapters:

- HP Ethernet 1Gb 2-port 363i Adapter
- HP Ethernet 1Gb 1-port 364i Adapter
- HP Ethernet 1Gb 2-port 367i Adapter

## **Supported Devices and Features**

This driver supports the following HP Intel E1R network adapters:

- HP NC365T PCI Express Quad Port Gigabit Server Adapter
- HP Ethernet 1Gb 2-port 361i Adapter
- HP Ethernet 1Gb 2-port 361FLB Adapter
- HP Ethernet 1Gb 2-port 361T Adapter
- HP Ethernet 1Gb 2-port 363i Adapter
- HP Ethernet 1Gb 2-port 364i Adapter
- HP Ethernet 1Gb 4-port 366FLR Adapter
- HP Ethernet 1Gb 4-port 366i Adapter
- HP Ethernet 1Gb 4-port 366M Adapter
- Hp Ethernet 1Gb 2-port 367i Adapter

---

HP Intel ixn/ixt Drivers for Windows Server 2008

Version: 3.5.22.0 (D) **(Optional)**

Filename: cp019449.exe

### **Fixes**

This driver addresses an issue where a “link down” message is recorded in the Windows system event log during every system boot regardless of the actual state of the link.

### **Enhancements**

This component now supports the HP Ethernet 10Gb 2-port 562i Adapter.

## **Supported Devices and Features**

This component supports the following HP Intel ixn network adapters:

- HP Ethernet 10Gb 2-port 560FLB Adapter
- HP Ethernet 10Gb 2-port 560FLR-SFP+ Adapter
- HP Ethernet 10Gb 2-port 560M Adapter
- HP Ethernet 10Gb 2-port 560SFP+ Adapter

This component supports the following HP Intel ixt network adapters:

- HP Ethernet 10Gb 2-port 561FLR-T Adapter
- HP Ethernet 10Gb 2-port 561T Adapter
- HP Ethernet 10Gb 2-port 562i Adapter

---

HP Intel ixn/ixt Drivers for Windows Server 2008 x64 Editions

Version: 3.5.22.0 (D) **(Optional)**

Filename: cp019450.exe

### **Fixes**

This driver addresses an issue where a “link down” message is recorded in the Windows system event log during every system boot regardless of the actual state of the link.

## **Enhancements**

This component now supports the HP Ethernet 10Gb 2-port 562i Adapter.

## **Supported Devices and Features**

This component supports the following HP Intel ixn network adapters:

- HP Ethernet 10Gb 2-port 560FLB Adapter
- HP Ethernet 10Gb 2-port 560FLR-SFP+ Adapter
- HP Ethernet 10Gb 2-port 560SFP+ Adapter
- HP Ethernet 10Gb 2-port 560M Adapter

This component supports the following HP Intel ixt network adapters:

- HP Ethernet 10Gb 2-port 561FLR-T Adapter
- HP Ethernet 10Gb 2-port 561T Adapter
- HP Ethernet 10Gb 2-port 562i Adapter

---

HP Mellanox CX3 Driver for Windows Server 2008 R2

Version: 4.95.10777.0 **(Optional)**

Filename: cp026814.exe

## **Fixes**

This driver corrects an issue which results in a Windows Stop Error (BSOD) after a receive buffer size change in Virtual Machine Queue (VMQ) mode.

This driver corrects an issue with the Powershell setting of RDMA over Converged Ethernet (RoCE) mode when the machine has more than one Mellanox device installed.

This driver corrects an issue with the reporting of Network Virtualization using Generic Routing Encapsulation (NVGRE) capabilities to the operating system.

## **Enhancements**

Explicit Congestion Notification (ECN) is now configurable via PowerShell.

This driver supports a new mode that ignores Frame Check Sequence (FCS) warnings and allows the Ethernet packets to be received by the NIC.

## **Supported Devices and Features**

This driver supports the following HP Mellanox CX3 network adapters:

- HP Ethernet 10G 2-port 546FLR-SFP+ Adapter
- HP Ethernet 10G 2-port 546SFP+ Adapter
- HP InfiniBand FDR/Ethernet 10Gb/40Gb 2-port 544+QSFP Adapter
- HP InfiniBand FDR/Ethernet 10Gb/40Gb 2-port 544+FLR-QSFP Adapter
- HP InfiniBand FDR/Ethernet 10Gb/40Gb 2-port 544+M Adapter
- HP InfiniBand QDR/Ethernet 10Gb 2-port 544+FLR-QSFP Adapter
- HP InfiniBand QDR/Ethernet 10Gb 2-port 544+M Adapter
- HP InfiniBand QDR/EN 10Gb Dual Port 544FLR-QSFP Adapter
- HP InfiniBand FDR/EN 10/40Gb Dual Port 544QSFP Adapter
- HP InfiniBand FDR/EN 10/40Gb Dual Port 544FLR-QSFP Adapter



- HP InfiniBand FDR/EN 10/40Gb Dual Port 544M Adapter
- HP InfiniBand QDR/EN 10Gb Dual Port 544M Adapter
- HP Infiniband QDR/Ethernet 10Gb 2P 544i Adapter

---

HP NC-Series Intel E1E Driver for Windows Server 2008

Version: 9.15.17.0 **(Optional)**

Filename: cp017186.exe

### **Fixes**

This driver addresses an issue where checksum offload computations were performed even when checksum offload was disabled.

### **Supported Devices and Features**

This driver supports the following HP NC-Series Intel network adapters:

- HP NC110T PCI Express Single Port Gigabit Server Adapter
- HP NC360m Dual Port Gigabit Ethernet BL-c Adapter
- HP NC360T PCI Express Dual Port Gigabit Server Adapter
- HP NC364m Quad Port Gigabit Ethernet BL-c Adapter
- HP NC364T PCI Express Quad Port Gigabit Server Adapter

---

HP NC-Series Intel E1E Driver for Windows Server 2008 R2

Version: 9.15.17.0 (B) **(Optional)**

Filename: cp018229.exe

### **Enhancements**

This driver now supports Windows Server 2012.

### **Supported Devices and Features**

This driver supports the following HP NC-Series Intel network adapters:

- HP NC110T PCI Express Single Port Gigabit Server Adapter
- HP NC360m Dual Port Gigabit Ethernet BL-c Adapter
- HP NC360T PCI Express Dual Port Gigabit Server Adapter
- HP NC364m Quad Port Gigabit Ethernet BL-c Adapter
- HP NC364T PCI Express Quad Port Gigabit Server Adapter

---

HP NC-Series Intel E1E Driver for Windows Server 2008 x64 Editions

Version: 9.15.17.0 **(Optional)**

Filename: cp017187.exe

### **Fixes**

This driver addresses an issue where checksum offload computations were performed even when checksum offload was disabled.

### **Supported Devices and Features**

This driver supports the following HP NC-Series Intel network adapters:

- HP NC110T PCI Express Single Port Gigabit Server Adapter
- HP NC360m Dual Port Gigabit Ethernet BL-c Adapter
- HP NC360T PCI Express Dual Port Gigabit Server Adapter
- HP NC364m Quad Port Gigabit Ethernet BL-c Adapter
- HP NC364T PCI Express Quad Port Gigabit Server Adapter

---

HP NC-Series Intel E1Q Driver for Windows Server 2008

Version: 12.7.29.0 (B) **(Optional)**

Filename: cp021179.exe

### **Fixes**

This component addresses an issue which can result in installed adapters remaining in a disabled state when they should be enabled after installation is complete.

### **Supported Devices and Features**

This driver supports the following HP NC-Series Intel E1Q network adapters:

- HP NC112T PCI Express Gigabit Server Adapter
- HP NC112i 1-port Ethernet Server Adapter
- HP NC362i Integrated Dual Port Gigabit Server Adapter
- HP NC362i Integrated Dual Port BL-c Gigabit Server Adapter

---

HP NC-Series Intel E1Q Driver for Windows Server 2008 R2

Version: 12.7.27.0 (B) **(Optional)**

Filename: cp021181.exe

### **Fixes**

This component addresses an issue which can result in installed adapters remaining in a disabled state when they should be enabled after installation is complete.

### **Supported Devices and Features**

This driver supports the following HP NC-Series Intel E1Q network adapters:

- HP NC112T PCI Express Gigabit Server Adapter
- HP NC112i 1-port Ethernet Server Adapter
- HP NC362i Integrated Dual Port Gigabit Server Adapter
- HP NC362i Integrated Dual Port BL-c Gigabit Server Adapter

---

HP NC-Series Intel E1Q Driver for Windows Server 2008 x64 Editions

Version: 12.7.29.0 (B) **(Optional)**

Filename: cp021180.exe

### **Fixes**

This component addresses an issue which can result in installed adapters remaining in a disabled state when they should be enabled after

installation is complete.

### **Supported Devices and Features**

This driver supports the following HP NC-Series Intel E1Q network adapters:

- HP NC112T PCI Express Gigabit Server Adapter
- HP NC112i 1-port Ethernet Server Adapter
- HP NC362i Integrated Dual Port Gigabit Server Adapter
- HP NC362i Integrated Dual Port BL-c Gigabit Server Adapter

---

HP NC-Series Intel E1Q Driver for Windows Server 2012

Version: 12.7.27.0 (B) **(Optional)**

Filename: cp021182.exe

### **Fixes**

This component addresses an issue which can result in installed adapters remaining in a disabled state when they should be enabled after installation is complete.

### **Supported Devices and Features**

This driver supports the following HP NC-Series Intel E1Q network adapters:

- HP NC112T PCI Express Gigabit Server Adapter
- HP NC112i 1-port Ethernet Server Adapter
- HP NC362i Integrated Dual Port Gigabit Server Adapter
- HP NC362i Integrated Dual Port BL-c Gigabit Server Adapter

---

HP Network Configuration Utility for Windows Server 2008

Version: 10.90.0.0 (B) **(Optional)**

Filename: cp023337.exe

### **Important Note!**

**Attention Gen9 customers:** This utility does not support Gen9 ProLiant platform NICs. See Customer Notice *HP Network Configuration Utility (NCU) - HP NCU Does Not Support Ethernet / FlexFabric Adapters designed for HP ProLiant Gen9 Servers* for more information:

<http://h20564.www2.hp.com/portal/site/hpsc/public/kb/docDisplay?docId=c04539182>.

### **Fixes**

This component addresses an issue which results in extremely long installation times on systems with a large number of virtual miniports.

---

HP QLogic nx\_nic Drivers for SUSE Linux Enterprise Server 11 i586

Version: 4.0.596.1-5 **(Optional)**

Filename: hp-nx\_nic-docs-1.0.0-4.noarch.rpm; hp-nx\_nic-tools-4.0.596.1-4.noarch.rpm; hpqlgc-nx\_nic-kmp-default-4.0.596.1\_3.0.101\_63-5.sles11sp4.i586.rpm; hpqlgc-nx\_nic-kmp-default-4.0.596.1\_3.0.76\_011-2.sles11sp3.i586.rpm; hpqlgc-nx\_nic-kmp-pae-4.0.596.1\_3.0.101\_63-5.sles11sp4.i586.rpm; hpqlgc-nx\_nic-kmp-pae-4.0.596.1\_3.0.76\_011-2.sles11sp3.i586.rpm; hpqlgc-nx\_nic-kmp-xen-4.0.596.1\_3.0.101\_63-5.sles11sp4.i586.rpm; hpqlgc-nx\_nic-kmp-xen-4.0.596.1\_3.0.76\_011-2.sles11sp3.i586.rpm; README

## **Important Note!**

HP recommends the firmware provided in *HP QLogic P3 Online Firmware Upgrade Utility for Linux x86*, version 5.6.10, for use with these drivers.

## **Enhancements**

This product now supports SUSE LINUX Enterprise Server 11 SP4.

## **Supported Devices and Features**

This software supports the following network adapters:

- HP NC375i Integrated Quad Port Multifunction Gigabit Server Adapter

---

HP QLogic nx\_nic Drivers for SUSE Linux Enterprise Server 11 x86\_64

Version: 4.0.596.1-5 **(Optional)**

Filename: hp-nx\_nic-docs-1.0.0-4.noarch.rpm; hp-nx\_nic-tools-4.0.596.1-4.noarch.rpm; hpqlgc-nx\_nic-kmp-default-4.0.596.1\_3.0.101\_63-5.sles11sp4.x86\_64.rpm; hpqlgc-nx\_nic-kmp-default-4.0.596.1\_3.0.76\_0.11-2.sles11sp3.x86\_64.rpm; hpqlgc-nx\_nic-kmp-xen-4.0.596.1\_3.0.101\_63-5.sles11sp4.x86\_64.rpm; hpqlgc-nx\_nic-kmp-xen-4.0.596.1\_3.0.76\_0.11-2.sles11sp3.x86\_64.rpm; README

## **Important Note!**

HP recommends the firmware provided in *HP QLogic P3 Online Firmware Upgrade Utility for Linux x86\_84*, version 5.6.10, for use with these drivers.

## **Enhancements**

This product now supports SUSE LINUX Enterprise Server 11 SP4.

## **Supported Devices and Features**

This software supports the following network adapters:

- HP NC375i Integrated Quad Port Multifunction Gigabit Server Adapter

---

HP QLogic P3 Drivers for VMware vSphere 5.5

Version: 2015.10.01 **(Optional)**

Filename: cp026078.zip

## **Important Note!**

This component is intended to be used by HP applications. It is a zip file that contains the same driver deliverable available from the vmware.com and the HP vibsdepot.hp.com webpages, plus an HP specific CPOxxxx.xml file.

## **Fixes**

This driver corrects a Page Fault that occurs when the driver loads the NIC's firmware.

## **Supported Devices and Features**

These drivers support the following QLogic P3 network adapters:

- HP NC375i Integrated Quad Port Multifunction Gigabit Server Adapter

---

HP QLogic P3 Drivers for VMware vSphere 6.0

Version: 2015.10.01 **(Optional)**

Filename: cp027056.zip

## **Important Note!**

This component is intended to be used by HP applications. It is a zip file that contains the same driver deliverable available from the vmware.com and the HP vibsdepot.hp.com webpages, plus an HP specific CPOxxxx.xml file.

## **Enhancements**

Initial release.

## **Supported Devices and Features**

These drivers support the following QLogic P3 network adapters:

- HP NC375i Integrated Quad Port Multifunction Gigabit Server Adapter

---

HP QLogic P3P Drivers for VMware vSphere 6.0

Version: 2015.10.01 **(Optional)**

Filename: cp027058.zip

## **Important Note!**

HP recommends the firmware provided in HP QLogic P3P Online Firmware Upgrade Utility for VMware, version 2.5.5, for use with this driver.

This component is intended to be used by HP applications. It is a zip file that contains the same driver deliverable available from the vmware.com and the HP vibsdepot.hp.com webpages, plus an HP specific CPOxxxx.xml file.

## **Enhancements**

Initial release.

## **Supported Devices and Features**

These drivers support the following HP P3P network adapters:

- HP NC523SFP 10Gb 2-port Flex-10 Ethernet Server Adapter
- HP FlexFabric 10Gb 2-port 526FLR-SFP+ Adapter
- HP CN1000Q Dual Port Converged Network Adapter

---

HP QLogic P3P iSCSI Driver for Windows Server 2008

Version: 2.1.6.10 **(Optional)**

Filename: cp021538.exe

### **Important Note!**

HP recommends the firmware provided in the *HP QLogic P3P Online Firmware Upgrade Utility for Windows Server 2008*, version 4.0.0.19 or later for use with this driver.

### **Fixes**

This driver corrects an issue which can result in an adapter reset when enabling or disabling a Virtual Local Area Network (VLAN).

This driver corrects an issue which can result in an adapter reset while assigning a static IP address.

### **Supported Devices and Features**

This driver supports the following HP P3P network adapters:

- HP CN1000Q Dual Port Converged Network Adapter
- HP FlexFabric 10Gb 2-port 526FLR-SFP+ Adapter

---

HP QLogic P3P iSCSI Driver for Windows Server 2008 x64 Editions

Version: 2.1.6.10 **(Optional)**

Filename: cp021539.exe

### **Important Note!**

HP recommends the firmware provided in the *HP QLogic P3P Online Firmware Upgrade Utility for Windows Server x64 Editions*, version 4.0.0.19 or later for use with this driver.

### **Fixes**

This driver corrects an issue which can result in an adapter reset when enabling or disabling a Virtual Local Area Network (VLAN).

This driver corrects an issue which can result in an adapter reset while assigning a static IP address.

### **Supported Devices and Features**

This driver supports the following HP P3P network adapters:

- HP CN1000Q Dual Port Converged Network Adapter
- HP FlexFabric 10Gb 2-port 526FLR-SFP+ Adapter

---

HP QLogic P3P iSCSI Driver for Windows Server 2012 and Windows Server 2012 R2

Version: 2.1.6.10 **(Optional)**

Filename: cp021540.exe

### **Important Note!**

HP recommends the firmware provided in the *HP QLogic P3P Online Firmware Upgrade Utility for Windows Server x64 Editions*, version

4.0.0.19 or later for use with this driver.

### **Fixes**

This driver corrects an issue which can result in an adapter reset when enabling or disabling a Virtual Local Area Network (VLAN).

This driver corrects an issue which can result in an adapter reset while assigning a static IP address.

### **Supported Devices and Features**

This driver supports the following HP P3P network adapters:

- HP CN1000Q Dual Port Converged Network Adapter
- HP FlexFabric 10Gb 2-port 526FLR-SFP+ Adapter

---

HPE Broadcom 1Gb Driver for Windows Server 2008

Version: 17.4.0.0 **(Optional)**

Filename: cp029526.exe

### **Important Note!**

HPE recommends the firmware provided in *HPE Broadcom NX1 Online Firmware Upgrade Utility for Windows Server 2008*, version 5.0.0.22 or later, for use with this driver.

### **Fixes**

This driver addresses an issue where the driver causes a Windows Stop Error (BSOD) with code 0000001E.

### **Supported Devices and Features**

This driver supports the following network adapters:

- HP Ethernet 1Gb 2-port 330i Adapter (182D)
- HP Ethernet 1Gb 4-port 331i Adapter (3372)
- HP Ethernet 1Gb 4-port 331i-SPI Adapter
- HP Ethernet 1Gb 4-port 331FLR Adapter
- HP Ethernet 1Gb 4-port 331T Adapter
- HP Ethernet 1Gb 2-port 332i Adapter
- HP Ethernet 1Gb 2-port 332T Adapter

---

HPE Broadcom 1Gb Driver for Windows Server x64 Editions

Version: 17.4.0.0 (B) **(Optional)**

Filename: cp030252.exe

### **Important Note!**

HPE recommends the firmware provided in *HPE Broadcom NX1 Online Firmware Upgrade Utility for Windows Server x64 Editions*, version 5.0.0.24 or later, for use with this driver.

## **Fixes**

This driver addresses a Windows Stop Error (BSOD) with stop code:0x7F.

## **Enhancements**

This product now supports Windows Server 2016.

## **Supported Devices and Features**

This driver supports the following network adapters:

- HP Ethernet 1Gb 2-port 330i Adapter (182D)
- HP Ethernet 1Gb 2-port 330i Adapter (22BD)
- HP Ethernet 1Gb 4-port 331i Adapter (3372)
- HP Ethernet 1Gb 4-port 331i Adapter (22BE)
- HP Ethernet 1Gb 4-port 331i-SPI Adapter
- HP Ethernet 1Gb 4-port 331FLR Adapter
- HP Ethernet 1Gb 4-port 331T Adapter
- HP Ethernet 1Gb 2-port 332i Adapter (2133)
- HP Ethernet 1Gb 2-port 332i Adapter (22E8)
- HP Ethernet 1Gb 2-port 332T Adapter

---

HPE Broadcom tg3 Ethernet Drivers for Red Hat Enterprise Linux 6 i686

Version: 3.1370-5 **(Optional)**

Filename: kmod-tg3-3.1370-1.rhel6u7.i686.rpm; kmod-tg3-3.1370-5.rhel6u8.i686.rpm; README

## **Important Note!**

HPE recommends the firmware provided in *HPE NX1 Broadcom Online Firmware Upgrade Utility for Linux x86*, version 2.17.5 or later, for use with these drivers.

## **Enhancements**

This product now supports Red Hat Enterprise Linux 6 Update 8.

## **Supported Devices and Features**

These drivers support the following network adapters:

- HP Ethernet 1Gb 2-port 330i Adapter (182D)
- HP Ethernet 1Gb 4-port 331i Adapter (3372)
- HP Ethernet 1Gb 4-port 331i-SPI Adapter
- HP Ethernet 1Gb 4-port 331FLR Adapter
- HP Ethernet 1Gb 4-port 331T Adapter
- HP Ethernet 1Gb 2-port 332i Adapter
- HP Ethernet 1Gb 2-port 332T Adapter

---

HPE Broadcom tg3 Ethernet Drivers for Red Hat Enterprise Linux 6 x86\_64

Version: 3.1370-5 **(Optional)**



Filename: kmod-tg3-3.137o-1.rhel6u7.x86\_64.rpm; kmod-tg3-3.137o-5.rhel6u8.x86\_64.rpm; README

### **Important Note!**

HPE recommends the firmware provided in *HPE Intel Online Firmware Upgrade Utility for Linux x86\_64*, version 2.17.5 or later, for use with these drivers.

### **Enhancements**

This product now supports Red Hat Enterprise Linux 6 Update 8.

### **Supported Devices and Features**

These drivers support the following network adapters:

- HP Ethernet 1Gb 2-port 330i Adapter (182D)
- HP Ethernet 1Gb 2-port 330i Adapter (22BD)
- HP Ethernet 1Gb 4-port 331i Adapter (3372)
- HP Ethernet 1Gb 4-port 331i Adapter (22BE)
- HP Ethernet 1Gb 4-port 331i-SPI Adapter
- HP Ethernet 1Gb 4-port 331FLR Adapter
- HP Ethernet 1Gb 4-port 331T Adapter
- HP Ethernet 1Gb 2-port 332i Adapter (2133)
- HP Ethernet 1Gb 2-port 332i Adapter (22E8)
- HP Ethernet 1Gb 2-port 332T Adapter

---

HPE Broadcom tg3 Ethernet Drivers for Red Hat Enterprise Linux 7 x86\_64

Version: 3.137o-1 (**Optional**)

Filename: kmod-tg3-3.137o-1.rhel7u1.x86\_64.rpm; kmod-tg3-3.137o-1.rhel7u2.x86\_64.rpm; README

### **Important Note!**

HPE recommends the firmware provided in *HPE NX1 Broadcom Online Firmware Upgrade Utility for Linux x86\_64*, version 2.17.6 or later, for use with these drivers.

### **Fixes**

This product addresses an issue where driver syslog entries show the module name "pcieport" instead of "tg3."

This product addresses an issue where TCP Segmentation Offloading (TSO) and checksum offloading are not performed correctly when the frame has been VLAN encapsulated.

### **Supported Devices and Features**

These drivers support the following network adapters:

- HP Ethernet 1Gb 2-port 330i Adapter (182D)
- HP Ethernet 1Gb 2-port 330i Adapter (22BD)
- HP Ethernet 1Gb 4-port 331i Adapter (3372)
- HP Ethernet 1Gb 4-port 331i Adapter (22BE)
- HP Ethernet 1Gb 4-port 331i-SPI Adapter
- HP Ethernet 1Gb 4-port 331FLR Adapter

- HP Ethernet 1Gb 4-port 331T Adapter
- HP Ethernet 1Gb 2-port 332i Adapter (2133)
- HP Ethernet 1Gb 2-port 332i Adapter (22E8)
- HP Ethernet 1Gb 2-port 332T Adapter

---

HPE Broadcom tg3 Ethernet Drivers for SUSE Linux Enterprise Server 11 i586

Version: 3.137o-1 **(Optional)**

Filename: README; tg3-kmp-default-3.137o\_3.0.101\_63-1.sles11sp4.i586.rpm; tg3-kmp-default-3.137o\_3.0.76\_0.11-1.sles11sp3.i586.rpm; tg3-kmp-pae-3.137o\_3.0.101\_63-1.sles11sp4.i586.rpm; tg3-kmp-pae-3.137o\_3.0.76\_0.11-1.sles11sp3.i586.rpm; tg3-kmp-xen-3.137o\_3.0.101\_63-1.sles11sp4.i586.rpm; tg3-kmp-xen-3.137o\_3.0.76\_0.11-1.sles11sp3.i586.rpm

### **Important Note!**

HPE recommends the firmware provided in *HPE NX1 Broadcom Online Firmware Upgrade Utility for Linux x86*, version 2.17.6 or later, for use with these drivers.

### **Fixes**

This product addresses an issue where driver syslog entries show the module name "pcieport" instead of "tg3."

This product addresses an issue where TCP Segmentation Offloading (TSO) and checksum offloading are not performed correctly when the frame has been VLAN encapsulated.

### **Supported Devices and Features**

These drivers support the following network adapters:

- HP Ethernet 1Gb 2-port 330i Adapter (182D)
- HP Ethernet 1Gb 4-port 331i Adapter (3372)
- HP Ethernet 1Gb 4-port 331i-SPI Adapter
- HP Ethernet 1Gb 4-port 331FLR Adapter
- HP Ethernet 1Gb 4-port 331T Adapter
- HP Ethernet 1Gb 2-port 332i Adapter
- HP Ethernet 1Gb 2-port 332T Adapter

---

HPE Broadcom tg3 Ethernet Drivers for SUSE Linux Enterprise Server 11 x86\_64

Version: 3.137o-1 **(Optional)**

Filename: README; tg3-kmp-default-3.137o\_3.0.101\_63-1.sles11sp4.x86\_64.rpm; tg3-kmp-default-3.137o\_3.0.76\_0.11-1.sles11sp3.x86\_64.rpm; tg3-kmp-xen-3.137o\_3.0.101\_63-1.sles11sp4.x86\_64.rpm; tg3-kmp-xen-3.137o\_3.0.76\_0.11-1.sles11sp3.x86\_64.rpm

### **Important Note!**

HPE recommends the firmware provided in *HPE NX1 Broadcom Online Firmware Upgrade Utility for Linux x86\_64*, version 2.17.6 or later, for use with these drivers.

### **Fixes**

This product addresses an issue where driver syslog entries show the module name "pcieport" instead of "tg3."

This product addresses an issue where TCP Segmentation Offloading (TSO) and checksum offloading are not performed correctly when the frame has been VLAN encapsulated.

## **Supported Devices and Features**

These drivers support the following network adapters:

- HP Ethernet 1Gb 2-port 330i Adapter (182D)
- HP Ethernet 1Gb 2-port 330i Adapter (22BD)
- HP Ethernet 1Gb 4-port 331i Adapter (3372)
- HP Ethernet 1Gb 4-port 331i Adapter (22BE)
- HP Ethernet 1Gb 4-port 331i-SPI Adapter
- HP Ethernet 1Gb 4-port 331FLR Adapter
- HP Ethernet 1Gb 4-port 331T Adapter
- HP Ethernet 1Gb 2-port 332i Adapter (2133)
- HP Ethernet 1Gb 2-port 332i Adapter (22E8)
- HP Ethernet 1Gb 2-port 332T Adapter

---

HPE Broadcom tg3 Ethernet Drivers for SUSE Linux Enterprise Server 12 x86\_64

Version: 3.137o-1 **(Optional)**

Filename: README; tg3-kmp-default-3.137o\_k3.12.28\_4-1.sles12sp0.x86\_64.rpm; tg3-kmp-default-3.137o\_k3.12.49\_11-1.sles12sp1.x86\_64.rpm; tg3-kmp-xen-3.137o\_k3.12.28\_4-1.sles12sp0.x86\_64.rpm; tg3-kmp-xen-3.137o\_k3.12.49\_11-1.sles12sp1.x86\_64.rpm

### **Important Note!**

HPE recommends the firmware provided in *HPE NX1 Broadcom Online Firmware Upgrade Utility for Linux x86\_64*, version 2.17.6 or later, for use with these drivers.

### **Fixes**

This product addresses an issue where driver syslog entries show the module name "pcieport" instead of "tg3."

This product addresses an issue where TCP Segmentation Offloading (TSO) and checksum offloading are not performed correctly when the frame has been VLAN encapsulated.

## **Supported Devices and Features**

These drivers support the following network adapters:

- HP Ethernet 1Gb 2-port 330i Adapter (182D)
- HP Ethernet 1Gb 2-port 330i Adapter (22BD)
- HP Ethernet 1Gb 4-port 331i Adapter (3372)
- HP Ethernet 1Gb 4-port 331i Adapter (22BE)
- HP Ethernet 1Gb 4-port 331i-SPI Adapter
- HP Ethernet 1Gb 4-port 331FLR Adapter
- HP Ethernet 1Gb 4-port 331T Adapter
- HP Ethernet 1Gb 2-port 332i Adapter (2133)
- HP Ethernet 1Gb 2-port 332i Adapter (22E8)
- HP Ethernet 1Gb 2-port 332T Adapter

---

HPE Emulex 10/20 GbE Driver for Windows Server 2008

Version: 11.1.145.30 (B) **(Optional)**

Filename: cp032093.exe

### **Important Note!**

HPE recommends the firmware provided in *HPE Firmware Flash for Emulex Converged Network Adapters - Windows (x86)*, version 2016.10.01 or later for use with this driver.

### **Fixes**

This component no longer recognizes the HP NC551i Dual Port FlexFabric 10Gb Adapter, which is now consistent with the driver that the component contains.

### **Supported Devices and Features**

This driver supports the following network adapters:

- HP NC552SFP 10Gb 2-port Ethernet Server Adapter
- HP NC553i 10Gb 2-port FlexFabric Converged Network Adapter
- HP Flex-10 10Gb 2-port 552M Adapter
- HP FlexFabric 10Gb 2-port 554FLB Adapter
- HP FlexFabric 10Gb 2-port 554FLR-SFP+ Adapter
- HP FlexFabric 10Gb 2-port 554M Adapter

---

HPE Emulex 10/20 GbE Driver for Windows Server 2008 R2

Version: 11.1.145.30 (B) **(Optional)**

Filename: cp032105.exe

### **Important Note!**

HPE recommends the firmware provided in *HPE Firmware Flash for Emulex Converged Network Adapters - Windows (x64)*, version 2016.10.01 or later for use with this driver.

### **Fixes**

This component no longer recognizes the HP NC551i Dual Port FlexFabric 10Gb Adapter, which is now consistent with the driver that the component contains.

### **Supported Devices and Features**

This driver supports the following network adapters:

- HP NC553i 10Gb 2-port FlexFabric Converged Network Adapter
- HP Flex-10 10Gb 2-port 552M Adapter
- HP FlexFabric 10Gb 2-port 554FLB Adapter
- HP FlexFabric 10Gb 2-port 554FLR-SFP+ Adapter
- HP FlexFabric 10Gb 2-port 554M Adapter
- HP FlexFabric 10Gb 2-port 556FLR-SFP+ Adapter
- HPE FlexFabric 10Gb 2-port 556FLR-T Adapter
- HP Ethernet 10Gb 2-port 557SFP+ Adapter
- HP FlexFabric 20Gb 2-port 650FLB Adapter
- HP FlexFabric 20Gb 2-port 650M Adapter
- HP StoreFabric CN1200E Dual Port Converged Network Adapter

HPE Emulex 10/20 GbE Driver for Windows Server 2008 x64 Editions

Version: 11.1.145.30 (B) **(Optional)**

Filename: cp032094.exe

### **Important Note!**

HPE recommends the firmware provided in *HPE Firmware Flash for Emulex Converged Network Adapters - Windows (x64)*, version 2016.10.01 or later for use with this driver.

### **Fixes**

This component no longer recognizes the HP NC551i Dual Port FlexFabric 10Gb Adapter, which is now consistent with the driver that the component contains.

### **Supported Devices and Features**

This driver supports the following network adapters:

- HP NC553i 10Gb 2-port FlexFabric Converged Network Adapter
- HP Flex-10 10Gb 2-port 552M Adapter
- HP FlexFabric 10Gb 2-port 554FLB Adapter
- HP FlexFabric 10Gb 2-port 554FLR-SFP+ Adapter
- HP FlexFabric 10Gb 2-port 554M Adapter
- HP FlexFabric 10Gb 2-port 556FLR-SFP+ Adapter
- HP Ethernet 10Gb 2-port 557SFP+ Adapter
- HP FlexFabric 20Gb 2-port 650FLB Adapter
- HP FlexFabric 20Gb 2-port 650M Adapter
- HP StoreFabric CN1200E Dual Port Converged Network Adapter

---

HPE Emulex 10/20 GbE Driver for Windows Server 2012

Version: 11.1.145.30 (B) **(Optional)**

Filename: cp032106.exe

### **Important Note!**

HPE recommends the firmware provided in *HPE Firmware Flash for Emulex Converged Network Adapters - Windows (x64)*, version 2016.10.01 or later for use with this driver.

### **Fixes**

This component no longer recognizes the HP NC551i Dual Port FlexFabric 10Gb Adapter, which is now consistent with the driver that the component contains.

### **Supported Devices and Features**

This driver supports the following network adapters:

- HP NC552SFP 10Gb 2-port Ethernet Server Adapter

- HP NC553i 10Gb 2-port FlexFabric Converged Network Adapter
- HP Flex-10 10Gb 2-port 552M Adapter
- HP FlexFabric 10Gb 2-port 554FLB Adapter
- HP FlexFabric 10Gb 2-port 554FLR-SFP+ Adapter
- HP FlexFabric 10Gb 2-port 554M Adapter
- HP FlexFabric 10Gb 2-port 556FLR-SFP+ Adapter
- HPE FlexFabric 10Gb 2-port 556FLR-T Adapter
- HP Ethernet 10Gb 2-port 557SFP+ Adapter
- HP FlexFabric 20Gb 2-port 650FLB Adapter
- HP FlexFabric 20Gb 2-port 650M Adapter
- HP StoreFabric CN1200E Dual Port Converged Network Adapter
- HPE StoreFabric CN1200E-T Adapter

---

HPE Emulex 10/20 GbE Driver for Windows Server 2012 R2

Version: 10.7.110.16 **(Optional)**

Filename: cp027194.exe

### **Important Note!**

HPE recommends the firmware provided in *HPE Firmware Online Flash for Emulex Fibre Channel Host Bus Adapters - Windows 2008/2012/2012 R2 x64*, version 2016.02.01, for use with this driver.

### **Fixes**

This driver addresses an issue that results in Event ID 67 appearing in the Windows System Event Log in systems with an HP FlexFabric 20Gb 2-port 650FLB Adapter installed.

### **Enhancements**

This product now supports the following network adapters:

- HPE FlexFabric 10Gb 2-port 556FLR-T Adapter
- HPE StoreFabric CN1200E-T Adapter

### **Supported Devices and Features**

This driver supports the following network adapters:

- HP NC551i Dual Port FlexFabric 10Gb Network Adapter
- HP NC552SFP 10Gb 2-port Ethernet Server Adapter
- HP NC553i 10Gb 2-port FlexFabric Converged Network Adapter
- HP Flex-10 10Gb 2-port 552M Adapter
- HP FlexFabric 10Gb 2-port 554FLB Adapter
- HP FlexFabric 10Gb 2-port 554FLR-SFP+ Adapter
- HP FlexFabric 10Gb 2-port 554M Adapter
- HP FlexFabric 10Gb 2-port 556FLR-SFP+ Adapter
- HPE FlexFabric 10Gb 2-port 556FLR-T Adapter
- HP Ethernet 10Gb 2-port 557SFP+ Adapter
- HP FlexFabric 20Gb 2-port 650FLB Adapter
- HP FlexFabric 20Gb 2-port 650M Adapter
- HP CN1100E Dual Port Converged Network Adapter
- HP StoreFabric CN1200E Dual Port Converged Network Adapter

- HPE StoreFabric CN1200E-T Adapter

---

HPE Emulex 10/20 GbE Driver for Windows Server 2016

Version: 11.1.196.4 (B) **(Optional)**

Filename: cp032095.exe

### **Important Note!**

HPE recommends the firmware provided in *HPE Firmware Flash for Emulex Converged Network Adapters for Windows Server 2016 (x64)*, version 2016.10.01 or later for use with this driver.

### **Fixes**

This component no longer recognizes the HP NC551i Dual Port FlexFabric 10Gb Adapter, which is now consistent with the driver that the component contains.

### **Supported Devices and Features**

This driver supports the following network adapters:

- HP CN1100E Dual Port Converged Network Adapter
- HP NC552SFP 10Gb 2-port Ethernet Server Adapter
- HP NC553i 10Gb 2-port FlexFabric Converged Network Adapter
- HP Flex-10 10Gb 2-port 552M Adapter
- HP FlexFabric 10Gb 2-port 554FLB Adapter
- HP FlexFabric 10Gb 2-port 554FLR-SFP+ Adapter
- HP FlexFabric 10Gb 2-port 554M Adapter
- HP FlexFabric 10Gb 2-port 556FLR-SFP+ Adapter
- HPE FlexFabric 10Gb 2-port 556FLR-T Adapter
- HP Ethernet 10Gb 2-port 557SFP+ Adapter
- HP FlexFabric 20Gb 2-port 650FLB Adapter
- HP FlexFabric 20Gb 2-port 650M Adapter
- HP StoreFabric CN1200E Dual Port Converged Network Adapter
- HPE StoreFabric CN1200E-T Adapter

---

HPE Emulex 10/20 GbE Drivers for Red Hat Enterprise Linux 6 i686

Version: 11.1.183.21-1 **(Optional)**

Filename: kmod-be2net-11.1.145.27-1.rhel6u7.i686.rpm; kmod-be2net-11.1.183.21-1.rhel6u8.i686.rpm; README

### **Important Note!**

HPE recommends the firmware provided in *HPE Firmware Flash for Emulex Converged Network Adapters - Linux (x86)*, version 2016.08.02 or later for use with these drivers.

### **Fixes**

This driver provides a recovery mechanism that addresses unhandled exceptions on the supported devices.

### **Enhancements**

This product now supports Red Hat Enterprise Linux 6 Update 8.

### **Supported Devices and Features**

This driver supports the following network adapters:

- HP NC553i 10Gb 2-port FlexFabric Converged Network Adapter
- HP Flex-10 10Gb 2-port 552M Adapter
- HP FlexFabric 10Gb 2-port 554FLB Adapter
- HP FlexFabric 10Gb 2-port 554FLR-SFP+ Adapter
- HP FlexFabric 10Gb 2-port 554M Adapter

---

HPE Emulex 10/20 GbE Drivers for Red Hat Enterprise Linux 6 x86\_64

Version: 11.1.183.21-1 **(Optional)**

Filename: kmod-be2net-11.1.145.27-1.rhel6u7.x86\_64.rpm; kmod-be2net-11.1.183.21-1.rhel6u8.x86\_64.rpm; README

### **Important Note!**

HPE recommends the firmware provided in *HPE Firmware Flash for Emulex Converged Network Adapters - Linux (x64)*, version 2016.08.02 for use with these drivers.

### **Fixes**

This driver provides a recovery mechanism that addresses unhandled exceptions on the supported devices.

### **Enhancements**

This product now supports Red Hat Enterprise Linux 6 Update 8.

### **Supported Devices and Features**

This driver supports the following network adapters:

- HP NC553i 10Gb 2-port FlexFabric Converged Network Adapter
- HP Flex-10 10Gb 2-port 552M Adapter
- HP FlexFabric 10Gb 2-port 554FLB Adapter
- HP FlexFabric 10Gb 2-port 554FLR-SFP+ Adapter
- HP FlexFabric 10Gb 2-port 554M Adapter
- HP FlexFabric 10Gb 2-port 556FLR-SFP+ Adapter
- HPE FlexFabric 10Gb 2-port 556FLR-T Adapter
- HP Ethernet 10Gb 2-port 557SFP+ Adapter
- HP FlexFabric 20Gb 2-port 650FLB Adapter
- HP FlexFabric 20Gb 2-port 650M Adapter
- HP StoreFabric CN1200E Dual Port Converged Network Adapter
- HPE StoreFabric CN1200E-T Adapter

---

HPE Emulex 10/20 GbE Drivers for Red Hat Enterprise Linux 7 x86\_64

Version: 11.1.145.27-1 **(Optional)**

Filename: kmod-be2net-11.1.145.27-1.rhel7u1.x86\_64.rpm; kmod-be2net-11.1.145.27-1.rhel7u2.x86\_64.rpm; README



### **Important Note!**

HPE recommends the firmware provided in *HPE Firmware Flash for Emulex Converged Network Adapters - Linux (x64)*, version 2016.08.02 for use with these drivers.

### **Fixes**

This driver provides a recovery mechanism that addresses unhandled exceptions on the supported devices.

### **Supported Devices and Features**

This driver supports the following network adapters:

- HP NC553i 10Gb 2-port FlexFabric Converged Network Adapter
- HP Flex-10 10Gb 2-port 552M Adapter
- HP FlexFabric 10Gb 2-port 554FLB Adapter
- HP FlexFabric 10Gb 2-port 554FLR-SFP+ Adapter
- HP FlexFabric 10Gb 2-port 554M Adapter
- HP FlexFabric 10Gb 2-port 556FLR-SFP+ Adapter
- HPE FlexFabric 10Gb 2-port 556FLR-T Adapter
- HP Ethernet 10Gb 2-port 557SFP+ Adapter
- HP FlexFabric 20Gb 2-port 650FLB Adapter
- HP FlexFabric 20Gb 2-port 650M Adapter
- HP StoreFabric CN1200E Dual Port Converged Network Adapter
- HPE StoreFabric CN1200E-T Adapter

---

HPE Emulex 10/20 GbE Drivers for SUSE Linux Enterprise Server 11 i586

Version: 11.1.145.27-1 **(Optional)**

Filename: be2net-kmp-default-11.1.145.27\_3.0.101\_63-1.sles11sp4.i386.rpm; be2net-kmp-default-11.1.145.27\_3.0.76\_0.11-1.sles11sp3.i386.rpm; be2net-kmp-pae-11.1.145.27\_3.0.101\_63-1.sles11sp4.i386.rpm; be2net-kmp-pae-11.1.145.27\_3.0.76\_0.11-1.sles11sp3.i386.rpm; be2net-kmp-xen-11.1.145.27\_3.0.101\_63-1.sles11sp4.i386.rpm; be2net-kmp-xen-11.1.145.27\_3.0.76\_0.11-1.sles11sp3.i386.rpm; README

### **Important Note!**

HPE recommends the firmware provided in *HPE Firmware Flash for Emulex Converged Network Adapters - Linux (x86)*, version 2016.08.02 or later for use with these drivers.

### **Fixes**

This driver provides a recovery mechanism that addresses unhandled exceptions on the supported devices.

### **Supported Devices and Features**

This driver supports the following network adapters:

- HP NC553i 10Gb 2-port FlexFabric Converged Network Adapter
- HP Flex-10 10Gb 2-port 552M Adapter
- HP FlexFabric 10Gb 2-port 554FLB Adapter
- HP FlexFabric 10Gb 2-port 554FLR-SFP+ Adapter
- HP FlexFabric 10Gb 2-port 554M Adapter

---

HPE Emulex 10/20 GbE Drivers for SUSE Linux Enterprise Server 11 x86\_64

Version: 11.1.145.27-1 (**Optional**)

Filename: be2net-kmp-default-11.1.145.27\_3.0.101\_63-1.sles11sp4.x86\_64.rpm; be2net-kmp-default-11.1.145.27\_3.0.76\_0.11-1.sles11sp3.x86\_64.rpm; be2net-kmp-xen-11.1.145.27\_3.0.101\_63-1.sles11sp4.x86\_64.rpm; be2net-kmp-xen-11.1.145.27\_3.0.76\_0.11-1.sles11sp3.x86\_64.rpm; README

### **Important Note!**

HPE recommends the firmware provided in *HPE Firmware Flash for Emulex Converged Network Adapters - Linux (x64)*, version 2016.08.02 for use with these drivers.

### **Fixes**

This driver provides a recovery mechanism that addresses unhandled exceptions on the supported devices.

### **Supported Devices and Features**

This driver supports the following network adapters:

- HP NC553i 10Gb 2-port FlexFabric Converged Network Adapter
- HP Flex-10 10Gb 2-port 552M Adapter
- HP FlexFabric 10Gb 2-port 554FLB Adapter
- HP FlexFabric 10Gb 2-port 554FLR-SFP+ Adapter
- HP FlexFabric 10Gb 2-port 554M Adapter
- HP FlexFabric 10Gb 2-port 556FLR-SFP+ Adapter
- HPE FlexFabric 10Gb 2-port 556FLR-T Adapter
- HP Ethernet 10Gb 2-port 557SFP+ Adapter
- HP FlexFabric 20Gb 2-port 650FLB Adapter
- HP FlexFabric 20Gb 2-port 650M Adapter
- HP StoreFabric CN1200E Dual Port Converged Network Adapter
- HPE StoreFabric CN1200E-T Adapter

---

HPE Emulex 10/20 GbE Drivers for SUSE Linux Enterprise Server 12 x86\_64

Version: 11.1.145.27-1 (**Optional**)

Filename: be2net-kmp-default-11.1.145.27\_k3.12.28\_4-1.sles12sp0.x86\_64.rpm; be2net-kmp-default-11.1.145.27\_k3.12.49\_11-1.sles12sp1.x86\_64.rpm; be2net-kmp-xen-11.1.145.27\_k3.12.28\_4-1.sles12sp0.x86\_64.rpm; be2net-kmp-xen-11.1.145.27\_k3.12.49\_11-1.sles12sp1.x86\_64.rpm; README

### **Important Note!**

HPE recommends the firmware provided in *HPE Firmware Flash for Emulex Converged Network Adapters - Linux (x64)*, version 2016.08.02 for use with these drivers.

### **Fixes**

This driver provides a recovery mechanism that addresses unhandled exceptions on the supported devices.

### **Supported Devices and Features**

This driver supports the following network adapters:

- HP NC553i 10Gb 2-port FlexFabric Converged Network Adapter
- HP Flex-10 10Gb 2-port 552M Adapter
- HP FlexFabric 10Gb 2-port 554FLB Adapter
- HP FlexFabric 10Gb 2-port 554FLR-SFP+ Adapter
- HP FlexFabric 10Gb 2-port 554M Adapter
- HP FlexFabric 10Gb 2-port 556FLR-SFP+ Adapter
- HPE FlexFabric 10Gb 2-port 556FLR-T Adapter
- HP Ethernet 10Gb 2-port 557SFP+ Adapter
- HP FlexFabric 20Gb 2-port 650FLB Adapter
- HP FlexFabric 20Gb 2-port 650M Adapter
- HP StoreFabric CN1200E Dual Port Converged Network Adapter
- HPE StoreFabric CN1200E-T Adapter

---

HPE Emulex 10/20 GbE iSCSI Driver for Windows Server 2008

Version: 11.1.185.0 (B) **(Optional)**

Filename: cp032096.exe

### **Important Note!**

HPE recommends the firmware provided in *HPE Firmware Flash for Emulex Converged Network Adapters - Windows (x86)*, version 2016.10.01 or later for use with this driver.

### **Fixes**

This component no longer recognizes the HP NC551i Dual Port FlexFabric 10Gb Adapter, which is now consistent with the driver that the component contains.

### **Supported Devices and Features**

This driver supports the following network adapters:

- HP NC553i 10Gb 2-port FlexFabric Converged Network Adapter
- HP FlexFabric 10Gb 2-port 554FLB Adapter
- HP FlexFabric 10Gb 2-port 554FLR-SFP+ Adapter
- HP FlexFabric 10Gb 2-port 554M Adapter

---

HPE Emulex 10/20 GbE iSCSI Driver for Windows Server 2008 R2

Version: 11.1.185.0 (B) **(Optional)**

Filename: cp032098.exe

### **Important Note!**

HPE recommends the firmware provided in *HPE Firmware Flash for Emulex Converged Network Adapters - Windows (x64)*, version 2016.10.01 or later for use with this driver.

### **Fixes**

This component no longer recognizes the HP NC551i Dual Port FlexFabric 10Gb Adapter, which is now consistent with the driver that the component contains.

## **Supported Devices and Features**

This driver supports the following network adapters:

- HP NC553i 10Gb 2-port FlexFabric Converged Network Adapter
- HP FlexFabric 10Gb 2-port 554FLB Adapter
- HP FlexFabric 10Gb 2-port 554FLR-SFP+ Adapter
- HP FlexFabric 10Gb 2-port 554M Adapter
- HP FlexFabric 10Gb 2-port 556FLR-SFP+ Adapter
- HPE FlexFabric 10Gb 2-port 556FLR-T Adapter
- HP FlexFabric 20Gb 2-port 650FLB Adapter
- HP FlexFabric 20Gb 2-port 650M Adapter
- HP StoreFabric CN1200E Dual Port Converged Network Adapter
- HPE StoreFabric CN1200E-T Adapter

---

HPE Emulex 10/20 GbE iSCSI Driver for Windows Server 2008 x64 Editions

Version: 11.1.185.0 (B) **(Optional)**

Filename: cp032097.exe

### **Important Note!**

HPE recommends the firmware provided in *HPE Firmware Flash for Emulex Converged Network Adapters - Windows (x64)*, version 2016.10.01 or later for use with this driver.

### **Fixes**

This component no longer recognizes the HP NC551i Dual Port FlexFabric 10Gb Adapter, which is now consistent with the driver that the component contains.

## **Supported Devices and Features**

This driver supports the following network adapters:

- HP NC553i 10Gb 2-port FlexFabric Converged Network Adapter
- HP FlexFabric 10Gb 2-port 554FLB Adapter
- HP FlexFabric 10Gb 2-port 554FLR-SFP+ Adapter
- HP FlexFabric 10Gb 2-port 554M Adapter
- HP FlexFabric 10Gb 2-port 556FLR-SFP+ Adapter
- HPE FlexFabric 10Gb 2-port 556FLR-T Adapter
- HP FlexFabric 20Gb 2-port 650FLB Adapter
- HP FlexFabric 20Gb 2-port 650M Adapter
- HP StoreFabric CN1200E Dual Port Converged Network Adapter

---

HPE Emulex 10/20 GbE iSCSI Driver for Windows Server 2012

Version: 11.1.185.0 (B) **(Optional)**

Filename: cp032099.exe

### **Important Note!**

HPE recommends the firmware provided in *HPE Firmware Flash for Emulex Converged Network Adapters - Windows (x64)*, version 2016.10.01

or later for use with this driver.

## **Fixes**

This component no longer recognizes the HP NC551i Dual Port FlexFabric 10Gb Adapter, which is now consistent with the driver that the component contains.

## **Supported Devices and Features**

This driver supports the following network adapters:

- HP NC553i 10Gb 2-port FlexFabric Converged Network Adapter
- HP FlexFabric 10Gb 2-port 554FLB Adapter
- HP FlexFabric 10Gb 2-port 554FLR-SFP+ Adapter
- HP FlexFabric 10Gb 2-port 554M Adapter
- HP FlexFabric 10Gb 2-port 556FLR-SFP+ Adapter
- HPE FlexFabric 10Gb 2-port 556FLR-T Adapter
- HP FlexFabric 20Gb 2-port 650FLB Adapter
- HP FlexFabric 20Gb 2-port 650M Adapter
- HP StoreFabric CN1200E Dual Port Converged Network Adapter
- HPE StoreFabric CN1200E-T Adapter

---

HPE Emulex 10/20 GbE iSCSI Driver for Windows Server 2012 R2

Version: 11.1.185.0 (B) **(Optional)**

Filename: cp032100.exe

## **Important Note!**

HPE recommends the firmware provided in *HPE Firmware Flash for Emulex Converged Network Adapters - Windows (x64)*, version 2016.10.01 or later for use with this driver.

## **Fixes**

This component no longer recognizes the HP NC551i Dual Port FlexFabric 10Gb Adapter, which is now consistent with the driver that the component contains.

## **Supported Devices and Features**

This driver supports the following network adapters:

- HP NC553i 10Gb 2-port FlexFabric Converged Network Adapter
- HP FlexFabric 10Gb 2-port 554FLB Adapter
- HP FlexFabric 10Gb 2-port 554FLR-SFP+ Adapter
- HP FlexFabric 10Gb 2-port 554M Adapter
- HP FlexFabric 10Gb 2-port 556FLR-SFP+ Adapter
- HPE FlexFabric 10Gb 2-port 556FLR-T Adapter
- HP FlexFabric 20Gb 2-port 650FLB Adapter
- HP FlexFabric 20Gb 2-port 650M Adapter
- HP StoreFabric CN1200E Dual Port Converged Network Adapter
- HPE StoreFabric CN1200E-T Adapter

---

HPE Emulex 10/20 GbE iSCSI Driver for Windows Server 2016

Version: 11.1.185.0 **(Optional)**

Filename: cp029151.exe

### **Important Note!**

HPE recommends the firmware provided in *HPE Firmware Flash for Emulex Converged Network Adapters for Windows Server 2016 (x64)*, version 2016.10.01 or later for use with this driver.

### **Enhancements**

Initial release.

### **Supported Devices and Features**

This driver supports the following network adapters:

- HP CN1100E Dual Port Converged Network Adapter
- HP NC553i 10Gb 2-port FlexFabric Converged Network Adapter
- HP FlexFabric 10Gb 2-port 554FLB Adapter
- HP FlexFabric 10Gb 2-port 554FLR-SFP+ Adapter
- HP FlexFabric 10Gb 2-port 554M Adapter
- HP FlexFabric 10Gb 2-port 556FLR-SFP+ Adapter
- HPE FlexFabric 10Gb 2-port 556FLR-T Adapter
- HP FlexFabric 20Gb 2-port 650FLB Adapter
- HP FlexFabric 20Gb 2-port 650M Adapter
- HP StoreFabric CN1200E Dual Port Converged Network Adapter
- HPE StoreFabric CN1200E-T Adapter

---

HPE Emulex 10/20 GbE iSCSI Drivers for Red Hat Enterprise Linux 6 i686

Version: 11.1.183.21-1 **(Optional)**

Filename: kmod-be2iscsi-11.1.145.26-1.rhel6u7.i686.rpm; kmod-be2iscsi-11.1.183.21-1.rhel6u8.i686.rpm; README

### **Important Note!**

HPE recommends the firmware provided in *HPE Firmware Flash for Emulex Converged Network Adapters - Linux (x86)*, version 2016.08.02 or later for use with these drivers.

### **Fixes**

This driver provides a recovery mechanism that addresses unhandled exceptions on the supported devices.

### **Enhancements**

This product now supports Red Hat Enterprise Linux 6 Update 8.

### **Supported Devices and Features**

This driver supports the following network adapters:

HP NC553i 10Gb 2-port FlexFabric Converged Network Adapter

- HP FlexFabric 10Gb 2-port 554FLB Adapter
- HP FlexFabric 10Gb 2-port 554FLR-SFP+ Adapter
- HP FlexFabric 10Gb 2-port 554M Adapter

---

HPE Emulex 10/20 GbE iSCSI Drivers for Red Hat Enterprise Linux 6 x86\_64

Version: 11.1.183.21-1 **(Optional)**

Filename: kmod-be2iscsi-11.1.145.26-1.rhel6u7.x86\_64.rpm; kmod-be2iscsi-11.1.183.21-1.rhel6u8.x86\_64.rpm; README

### **Important Note!**

HPE recommends the firmware provided in *HPE Firmware Flash for Emulex Converged Network Adapters - Linux (x64)*, version 2016.08.02 for use with these drivers.

### **Fixes**

This driver provides a recovery mechanism that addresses unhandled exceptions on the supported devices.

### **Enhancements**

This product now supports Red Hat Enterprise Linux 6 Update 8.

### **Supported Devices and Features**

This driver supports the following network adapters:

- HP NC553i 10Gb 2-port FlexFabric Converged Network Adapter
- HP FlexFabric 10Gb 2-port 554FLB Adapter
- HP FlexFabric 10Gb 2-port 554FLR-SFP+ Adapter
- HP FlexFabric 10Gb 2-port 554M Adapter
- HP FlexFabric 10Gb 2-port 556FLR-SFP+ Adapter
- HPE FlexFabric 10Gb 2-port 556FLR-T Adapter
- HP FlexFabric 20Gb 2-port 650FLB Adapter
- HP FlexFabric 20Gb 2-port 650M Adapter
- HP StoreFabric CN1200E Dual Port Converged Network Adapter
- HPE StoreFabric CN1200E-T Adapter

---

HPE Emulex 10/20 GbE iSCSI Drivers for Red Hat Enterprise Linux 7 x86\_64

Version: 11.1.145.26-1 **(Optional)**

Filename: kmod-be2iscsi-11.1.145.26-1.rhel7u1.x86\_64.rpm; kmod-be2iscsi-11.1.145.26-1.rhel7u2.x86\_64.rpm; README

### **Important Note!**

HPE recommends the firmware provided in *HPE Firmware Flash for Emulex Converged Network Adapters - Linux (x64)*, version 2016.08.02 for use with these drivers.

### **Fixes**

This driver provides a recovery mechanism that addresses unhandled exceptions on the supported devices.

## **Supported Devices and Features**

This driver supports the following network adapters:

- HP NC553i 10Gb 2-port FlexFabric Converged Network Adapter
- HP FlexFabric 10Gb 2-port 554FLB Adapter
- HP FlexFabric 10Gb 2-port 554FLR-SFP+ Adapter
- HP FlexFabric 10Gb 2-port 554M Adapter
- HP FlexFabric 10Gb 2-port 556FLR-SFP+ Adapter
- HPE FlexFabric 10Gb 2-port 556FLR-T Adapter
- HP FlexFabric 20Gb 2-port 650FLB Adapter
- HP FlexFabric 20Gb 2-port 650M Adapter
- HP StoreFabric CN1200E Dual Port Converged Network Adapter
- HPE StoreFabric CN1200E-T Adapter

---

HPE Emulex 10/20 GbE iSCSI Drivers for SUSE Linux Enterprise Server 11 i586

Version: 11.1.145.26-1 **(Optional)**

Filename: be2iscsi-kmp-default-11.1.145.26\_3.0.101\_63-1.sles11sp4.i386.rpm; be2iscsi-kmp-default-11.1.145.26\_3.0.76\_0.11-1.sles11sp3.i386.rpm; be2iscsi-kmp-pae-11.1.145.26\_3.0.101\_63-1.sles11sp4.i386.rpm; be2iscsi-kmp-pae-11.1.145.26\_3.0.76\_0.11-1.sles11sp3.i386.rpm; be2iscsi-kmp-xen-11.1.145.26\_3.0.101\_63-1.sles11sp4.i386.rpm; be2iscsi-kmp-xen-11.1.145.26\_3.0.76\_0.11-1.sles11sp3.i386.rpm; README

### **Important Note!**

HPE recommends the firmware provided in *HPE Firmware Flash for Emulex Converged Network Adapters - Linux (x86)*, version 2016.08.02 or later for use with these drivers.

### **Fixes**

This driver provides a recovery mechanism that addresses unhandled exceptions on the supported devices.

## **Supported Devices and Features**

This driver supports the following network adapters:

- HP NC553i 10Gb 2-port FlexFabric Converged Network Adapter
- HP FlexFabric 10Gb 2-port 554FLB Adapter
- HP FlexFabric 10Gb 2-port 554FLR-SFP+ Adapter
- HP FlexFabric 10Gb 2-port 554M Adapter

---

HPE Emulex 10/20 GbE iSCSI Drivers for SUSE Linux Enterprise Server 11 x86\_64

Version: 11.1.145.26-1 **(Optional)**

Filename: be2iscsi-kmp-default-11.1.145.26\_3.0.101\_63-1.sles11sp4.x86\_64.rpm; be2iscsi-kmp-default-11.1.145.26\_3.0.76\_0.11-1.sles11sp3.x86\_64.rpm; be2iscsi-kmp-xen-11.1.145.26\_3.0.101\_63-1.sles11sp4.x86\_64.rpm; be2iscsi-kmp-xen-11.1.145.26\_3.0.76\_0.11-1.sles11sp3.x86\_64.rpm; README

### **Important Note!**

HPE recommends the firmware provided in *HPE Firmware Flash for Emulex Converged Network Adapters - Linux (x64)*, version 2016.08.02 for use with these drivers.



## **Fixes**

This driver provides a recovery mechanism that addresses unhandled exceptions on the supported devices.

## **Supported Devices and Features**

This driver supports the following network adapters:

- HP NC553i 10Gb 2-port FlexFabric Converged Network Adapter
- HP FlexFabric 10Gb 2-port 554FLB Adapter
- HP FlexFabric 10Gb 2-port 554FLR-SFP+ Adapter
- HP FlexFabric 10Gb 2-port 554M Adapter
- HP FlexFabric 10Gb 2-port 556FLR-SFP+ Adapter
- HPE FlexFabric 10Gb 2-port 556FLR-T Adapter
- HP FlexFabric 20Gb 2-port 650FLB Adapter
- HP FlexFabric 20Gb 2-port 650M Adapter
- HP StoreFabric CN1200E Dual Port Converged Network Adapter
- HPE StoreFabric CN1200E-T Adapter

---

HPE Emulex 10/20 GbE iSCSI Drivers for SUSE Linux Enterprise Server 12 x86\_64

Version: 11.1.145.26-1 (**Optional**)

Filename: be2iscsi-kmp-default-11.1.145.26\_k3.12.28\_4-1.sles12sp0.x86\_64.rpm; be2iscsi-kmp-default-11.1.145.26\_k3.12.49\_11-1.sles12sp1.x86\_64.rpm; be2iscsi-kmp-xen-11.1.145.26\_k3.12.28\_4-1.sles12sp0.x86\_64.rpm; be2iscsi-kmp-xen-11.1.145.26\_k3.12.49\_11-1.sles12sp1.x86\_64.rpm; README

## **Important Note!**

HPE recommends the firmware provided in *HPE Firmware Flash for Emulex Converged Network Adapters - Linux (x64)*, version 2016.08.02 for use with these drivers.

## **Fixes**

This driver provides a recovery mechanism that addresses unhandled exceptions on the supported devices.

## **Supported Devices and Features**

This driver supports the following network adapters:

- HP NC553i 10Gb 2-port FlexFabric Converged Network Adapter
  - HP FlexFabric 10Gb 2-port 554FLB Adapter
  - HP FlexFabric 10Gb 2-port 554FLR-SFP+ Adapter
  - HP FlexFabric 10Gb 2-port 554M Adapter
  - HP FlexFabric 10Gb 2-port 556FLR-SFP+ Adapter
  - HPE FlexFabric 10Gb 2-port 556FLR-T Adapter
  - HP FlexFabric 20Gb 2-port 650FLB Adapter
  - HP FlexFabric 20Gb 2-port 650M Adapter
  - HP StoreFabric CN1200E Dual Port Converged Network Adapter
  - HPE StoreFabric CN1200E-T Adapter
-

HPE Emulex 10/20 GbE iSCSI Drivers for VMware vSphere 5.5

Version: 2016.10.07 **(Optional)**

Filename: cp029504.zip

### **Important Note!**

This component is intended to be used by HPE applications. It is a zip file that contains the same driver deliverable available from the vmware.com and the HPE vibsdepot.hp.com webpages, plus an HPE specific CP0xxxxx.xml file.

HPE recommends the firmware provided in *HPE Firmware Flash for Emulex Fibre Channel Host Bus and Converged Network Adapters for VMware vSphere 5.5 and 6.0*, version 2016.10.01 or later, for use with this driver.

### **Fixes**

This driver provides a recovery mechanism that addresses unhandled exceptions on the supported devices.

### **Supported Devices and Features**

These drivers support the following network adapters:

- HP NC553i 10Gb 2-port FlexFabric Converged Network Adapter
- HP FlexFabric 10Gb 2-port 554FLB Adapter
- HP FlexFabric 10Gb 2-port 554FLR-SFP+ Adapter
- HP FlexFabric 10Gb 2-port 554M Adapter
- HP FlexFabric 10Gb 2-port 556FLR-SFP+ Adapter
- HPE FlexFabric 10Gb 2-port 556FLR-T Adapter
- HP FlexFabric 20Gb 2-port 650FLB Adapter
- HP FlexFabric 20Gb 2-port 650M Adapter
- HP CN1100E Dual Port Converged Network Adapter
- HP StoreFabric CN1200E Dual Port Converged Network Adapter
- HPE StoreFabric CN1200E-T Adapter

---

HPE Emulex 10/20 GbE iSCSI Drivers for VMware vSphere 6.0

Version: 2016.10.07 **(Optional)**

Filename: cp029505.zip

### **Important Note!**

This component is intended to be used by HPE applications. It is a zip file that contains the same driver deliverable available from the vmware.com and the HPE vibsdepot.hp.com webpages, plus an HPE specific CP0xxxxx.xml file.

HPE recommends the firmware provided in *HPE Firmware Flash for Emulex Fibre Channel Host Bus and Converged Network Adapters for VMware vSphere 5.5 and 6.0*, version 2016.10.01 or later, for use with this driver.

### **Fixes**

This driver provides a recovery mechanism that addresses unhandled exceptions on the supported devices.

### **Supported Devices and Features**

These drivers support the following network adapters:

- HP NC553i 10Gb 2-port FlexFabric Converged Network Adapter
- HP FlexFabric 10Gb 2-port 554FLB Adapter
- HP FlexFabric 10Gb 2-port 554FLR-SFP+ Adapter
- HP FlexFabric 10Gb 2-port 554M Adapter
- HP FlexFabric 10Gb 2-port 556FLR-SFP+ Adapter
- HPE FlexFabric 10Gb 2-port 556FLR-T Adapter
- HP FlexFabric 20Gb 2-port 650FLB Adapter
- HP FlexFabric 20Gb 2-port 650M Adapter
- HP CN1100E Dual Port Converged Network Adapter
- HP StoreFabric CN1200E Dual Port Converged Network Adapter
- HPE StoreFabric CN1200E-T Adapter

---

HPE Emulex 10GbE Drivers for VMware vSphere 5.5

Version: 2016.10.07 **(Optional)**

Filename: cp029507.zip

### **Important Note!**

This component is intended to be used by HPE applications. It is a zip file that contains the same driver deliverable available from the vmware.com and the HPE vib depot.hp.com webpages, plus an HPE specific CPOxxxx.xml file.

HPE recommends the firmware provided in *HPE Firmware Flash for Emulex Fibre Channel Host Bus and Converged Network Adapters for VMware vSphere 5.5 and 6.0*, version 2016.10.01 or later, for use with this driver.

### **Fixes**

This driver provides a recovery mechanism that addresses unhandled exceptions on the supported devices.

### **Supported Devices and Features**

This driver supports the following network adapters:

- HP NC552SFP 10Gb 2-port Ethernet Server Adapter
- HP NC553i 10Gb 2-port FlexFabric Converged Network Adapter
- HP Flex-10 10Gb 2-port 552M Adapter
- HP FlexFabric 10Gb 2-port 554FLB Adapter
- HP FlexFabric 10Gb 2-port 554FLR-SFP+ Adapter
- HP FlexFabric 10Gb 2-port 554M Adapter
- HP FlexFabric 10Gb 2-port 556FLR-SFP+ Adapter
- HPE FlexFabric 10Gb 2-port 556FLR-T Adapter
- HP Ethernet 10Gb 2-port 557SFP+ Adapter
- HP FlexFabric 20Gb 2-port 650FLB Adapter
- HP FlexFabric 20Gb 2-port 650M Adapter
- HP CN1100E Dual Port Converged Network Adapter
- HP StoreFabric CN1200E Dual Port Converged Network Adapter
- HPE StoreFabric CN1200E-T Adapter

---

HPE Emulex 10GbE Drivers for VMware vSphere 6.0

Version: 2016.10.07 **(Optional)**

Filename: cp029508.zip

## **Important Note!**

This component is intended to be used by HPE applications. It is a zip file that contains the same driver deliverable available from the vmware.com and the HPE vibsddepot.hp.com webpages, plus an HPE specific CPOxxxxx.xml file.

HPE recommends the firmware provided in *HPE Firmware Flash for Emulex Fibre Channel Host Bus and Converged Network Adapters for VMware vSphere 5.5 and 6.0*, version 2016.10.01 or later, for use with this driver.

## **Fixes**

This driver provides a recovery mechanism that addresses unhandled exceptions on the supported devices.

## **Supported Devices and Features**

This driver supports the following network adapters:

- HP NC552SFP 10Gb 2-port Ethernet Server Adapter
- HP NC553i 10Gb 2-port FlexFabric Converged Network Adapter
- HP Flex-10 10Gb 2-port 552M Adapter
- HP FlexFabric 10Gb 2-port 554FLB Adapter
- HP FlexFabric 10Gb 2-port 554FLR-SFP+ Adapter
- HP FlexFabric 10Gb 2-port 554M Adapter
- HP FlexFabric 10Gb 2-port 556FLR-SFP+ Adapter
- HPE FlexFabric 10Gb 2-port 556FLR-T Adapter
- HP Ethernet 10Gb 2-port 557SFP+ Adapter
- HP FlexFabric 20Gb 2-port 650FLB Adapter
- HP FlexFabric 20Gb 2-port 650M Adapter
- HP CN1100E Dual Port Converged Network Adapter
- HP StoreFabric CN1200E Dual Port Converged Network Adapter
- HPE StoreFabric CN1200E-T Adapter

---

HPE Intel e1000e Drivers for Red Hat Enterprise Linux 6 i686

Version: 3.3.4-1 **(Optional)**

Filename: kmod-hp-e1000e-3.2.7.2-12.rhel6u7.i686.rpm; kmod-hp-e1000e-3.3.4-1.rhel6u8.i686.rpm; README

## **Enhancements**

This product now supports Red Hat Enterprise Linux 6 Update 8.

## **Supported Devices and Features**

These drivers support the following network adapters:

- HP NC112i 1-port Ethernet Server Adapter

---

HPE Intel e1000e Drivers for Red Hat Enterprise Linux 6 x86\_64

Version: 3.3.4-1 **(Optional)**

Filename: kmod-hp-e1000e-3.2.7.2-12.rhel6u7.x86\_64.rpm; kmod-hp-e1000e-3.3.4-1.rhel6u8.x86\_64.rpm; README

## **Enhancements**

This product now supports Red Hat Enterprise Linux 6 Update 8.

### **Supported Devices and Features**

These drivers support the following network adapters:

- HP NC112i 1-port Ethernet Server Adapter

---

HPE Intel e1000e Drivers for Red Hat Enterprise Linux 7 x86\_64

Version: 3.2.7.2-12 **(Optional)**

Filename: kmod-hp-e1000e-3.2.7.2-12.rhel7u1.x86\_64.rpm; kmod-hp-e1000e-3.2.7.2-12.rhel7u2.x86\_64.rpm; README

### **Fixes**

The RPM header for this product now shows the correct source RPM URL.

### **Supported Devices and Features**

These drivers support the following network adapters:

- HP NC112i 1-port Ethernet Server Adapter

---

HPE Intel e1000e Drivers for SUSE Linux Enterprise Server 11 i586

Version: 3.2.7.2-12 **(Optional)**

Filename: hp-e1000e-kmp-default-3.2.7.2\_3.0.101\_63-12.sles11sp4.i586.rpm; hp-e1000e-kmp-default-3.2.7.2\_3.0.76\_011-12.sles11sp3.i586.rpm; hp-e1000e-kmp-pae-3.2.7.2\_3.0.101\_63-12.sles11sp4.i586.rpm; hp-e1000e-kmp-pae-3.2.7.2\_3.0.76\_011-12.sles11sp3.i586.rpm; hp-e1000e-kmp-xen-3.2.7.2\_3.0.101\_63-12.sles11sp4.i586.rpm; hp-e1000e-kmp-xen-3.2.7.2\_3.0.76\_011-12.sles11sp3.i586.rpm; README

### **Fixes**

The RPM header for this product now shows the correct source RPM URL.

### **Supported Devices and Features**

These drivers support the following network adapters:

- HP NC112i 1-port Ethernet Server Adapter

---

HPE Intel e1000e Drivers for SUSE Linux Enterprise Server 11 x86\_64

Version: 3.2.7.2-12 **(Optional)**

Filename: hp-e1000e-kmp-default-3.2.7.2\_3.0.101\_63-12.sles11sp4.x86\_64.rpm; hp-e1000e-kmp-default-3.2.7.2\_3.0.76\_011-12.sles11sp3.x86\_64.rpm; hp-e1000e-kmp-xen-3.2.7.2\_3.0.101\_63-12.sles11sp4.x86\_64.rpm; hp-e1000e-kmp-xen-3.2.7.2\_3.0.76\_011-12.sles11sp3.x86\_64.rpm; README

### **Fixes**

The RPM header for this product now shows the correct source RPM URL.

### **Supported Devices and Features**

These drivers support the following network adapters:

- HP NC112i 1-port Ethernet Server Adapter

---

HPE Intel e1000e Drivers for SUSE Linux Enterprise Server 12 x86\_64

Version: 3.2.7.2-12 **(Optional)**

Filename: hp-e1000e-kmp-default-3.2.7.2\_k3.12.28\_4-12.sles12sp0.x86\_64.rpm; hp-e1000e-kmp-default-3.2.7.2\_k3.12.49\_11-12.sles12sp1.x86\_64.rpm; hp-e1000e-kmp-xen-3.2.7.2\_k3.12.28\_4-12.sles12sp0.x86\_64.rpm; hp-e1000e-kmp-xen-3.2.7.2\_k3.12.49\_11-12.sles12sp1.x86\_64.rpm; README

### **Fixes**

The RPM header for this product now shows the correct source RPM URL.

### **Supported Devices and Features**

These drivers support the following network adapters:

- HP NC112i 1-port Ethernet Server Adapter

---

HPE Intel E1R Driver for Windows Server 2008 R2

Version: 12.14.7.0 **(Optional)**

Filename: cp027785.exe

### **Important Note!**

HPE recommends the firmware provided in *HPE Intel Online Firmware Upgrade Utility for Windows Server x64 Editions*, version 5.0.0.7, for use with this driver.

### **Fixes**

This driver addresses an issue where Virtual Machine Queue (VMQ) feature was incorrectly disabled.

### **Supported Devices and Features**

This driver supports the following HPE Intel E1R network adapters:

- HP NC365T PCI Express Quad Port Gigabit Server Adapter
  - HP Ethernet 1Gb 2-port 361i Adapter
  - HP Ethernet 1Gb 2-port 361FLB Adapter
  - HP Ethernet 1Gb 2-port 361T Adapter
  - HP Ethernet 1Gb 2-port 363i Adapter
  - HP Ethernet 1Gb 1-port 364i Adapter
  - HP Ethernet 1Gb 4-port 366i Adapter
  - HP Ethernet 1Gb 4-port 366FLR Adapter
  - HP Ethernet 1Gb 4-port 366M Adapter
  - HP Ethernet 1Gb 4-port 366T Adapter
  - HP Ethernet 1Gb 2-port 367i Adapter
-

HPE Intel E1R Driver for Windows Server 2012

Version: 12.14.8.0 **(Optional)**

Filename: cp028837.exe

### **Important Note!**

HPE recommends the firmware provided in *HPE Intel Online Firmware Upgrade Utility for Windows Server x64 Editions*, version 5.0.0.25 or later, for use with this driver.

### **Fixes**

This driver addresses an issue that results in the failure of a Powershell command that contains an adapter name.

### **Supported Devices and Features**

This driver supports the following HPE Intel E1R network adapters:

- HP Ethernet 1Gb 2-port 361i Adapter
- HP Ethernet 1Gb 2-port 361FLB Adapter
- HP Ethernet 1Gb 2-port 361T Adapter
- HP Ethernet 1Gb 2-port 363i Adapter
- HP Ethernet 1Gb 1-port 364i Adapter
- HP Ethernet 1Gb 4-port 366i Adapter
- HP Ethernet 1Gb 4-port 366FLR Adapter
- HP Ethernet 1Gb 4-port 366M Adapter
- HP Ethernet 1Gb 4-port 366T Adapter
- HP Ethernet 1Gb 2-port 367i Adapter

---

HPE Intel E1R Driver for Windows Server 2012 R2

Version: 12.14.8.0 **(Optional)**

Filename: cp028838.exe

### **Important Note!**

HPE recommends the firmware provided in *HPE Intel Online Firmware Upgrade Utility for Windows Server x64 Editions*, version 5.0.0.25 or later, for use with this driver.

### **Fixes**

This driver addresses an issue that results in the failure of a Powershell command that contains an adapter name.

### **Enhancements**

This product now supports the HPE Ethernet 1Gb 4-port 366i Communication Board.

### **Supported Devices and Features**

This driver supports the following HPE Intel E1R network adapters:

- HP Ethernet 1Gb 2-port 361i Adapter
- HP Ethernet 1Gb 2-port 361FLB Adapter

- HP Ethernet 1Gb 2-port 361T Adapter
- HP Ethernet 1Gb 2-port 363i Adapter
- HP Ethernet 1Gb 1-port 364i Adapter
- HP Ethernet 1Gb 4-port 366i Adapter
- HPE Ethernet 1Gb 4-port 366i Communication Board
- HP Ethernet 1Gb 4-port 366FLR Adapter
- HP Ethernet 1Gb 4-port 366M Adapter
- HP Ethernet 1Gb 4-port 366T Adapter
- HP Ethernet 1Gb 2-port 367i Adapter

---

HPE Intel E1R Driver for Windows Server 2016

Version: 12.15.184.0 **(Optional)**

Filename: cp029676.exe

### **Important Note!**

HPE recommends the firmware provided in *HPE Intel Online Firmware Upgrade Utility for Windows Server x64 Editions*, version 5.0.0.25 or later, for use with this driver.

### **Enhancements**

Initial release.

### **Supported Devices and Features**

This driver supports the following HPE Intel E1R network adapters:

- HP Ethernet 1Gb 2-port 361i Adapter
- HP Ethernet 1Gb 2-port 361FLB Adapter
- HP Ethernet 1Gb 2-port 361T Adapter
- HP Ethernet 1Gb 2-port 363i Adapter
- HP Ethernet 1Gb 1-port 364i Adapter
- HP Ethernet 1Gb 4-port 366i Adapter
- HPE Ethernet 1Gb 4-port 366i Communication Board
- HP Ethernet 1Gb 4-port 366FLR Adapter
- HP Ethernet 1Gb 4-port 366M Adapter
- HP Ethernet 1Gb 4-port 366T Adapter
- HP Ethernet 1Gb 2-port 367i Adapter

---

HPE Intel i40e Drivers for Red Hat Enterprise Linux 7 x86\_64

Version: 1.3.46-13 **(Optional)**

Filename: kmod-hp-i40e-1.3.46-13.rhel7u1.x86\_64.rpm; kmod-hp-i40e-1.3.46-13.rhel7u2.x86\_64.rpm; README

### **Important Note!**

HPE recommends the firmware provided in *HPE Intel Online Firmware Upgrade Utility for Linux x86\_64*, version 1.11.11, for use with these drivers.

### **Enhancements**



This product now supports the HPE Ethernet 10Gb 2-port 563i Adapter.

### **Supported Devices and Features**

This product supports the following network adapters:

- HPE Ethernet 10Gb 2-port 562FLR-SFP+ Adapter
- HPE Ethernet 10Gb 2-port 562SFP+ Adapter
- HPE Ethernet 10Gb 2-port 563i Adapter

---

HPE Intel i40e Drivers for SUSE Linux Enterprise Server 11 x86\_64

Version: 1.3.46-13 **(Optional)**

Filename: hp-i40e-kmp-default-1.3.46\_3.0.101\_63-13.sles11sp4.x86\_64.rpm; hp-i40e-kmp-default-1.3.46\_3.0.76\_011-13.sles11sp3.x86\_64.rpm; hp-i40e-kmp-xen-1.3.46\_3.0.101\_63-13.sles11sp4.x86\_64.rpm; hp-i40e-kmp-xen-1.3.46\_3.0.76\_011-13.sles11sp3.x86\_64.rpm; README

### **Important Note!**

HPE recommends the firmware provided in *HPE Intel Online Firmware Upgrade Utility for Linux x86\_64*, version 1.11.11, for use with these drivers.

### **Enhancements**

This product now supports the HPE Ethernet 10Gb 2-port 563i Adapter.

### **Supported Devices and Features**

This product supports the following network adapters:

- HPE Ethernet 10Gb 2-port 562FLR-SFP+ Adapter
- HPE Ethernet 10Gb 2-port 562SFP+ Adapter
- HPE Ethernet 10Gb 2-port 563i Adapter

---

HPE Intel i40e Drivers for SUSE Linux Enterprise Server 12 x86\_64

Version: 1.3.46-13 **(Optional)**

Filename: hp-i40e-kmp-default-1.3.46\_k3.12.28\_4-13.sles12sp0.x86\_64.rpm; hp-i40e-kmp-default-1.3.46\_k3.12.49\_11-13.sles12sp1.x86\_64.rpm; hp-i40e-kmp-xen-1.3.46\_k3.12.28\_4-13.sles12sp0.x86\_64.rpm; hp-i40e-kmp-xen-1.3.46\_k3.12.49\_11-13.sles12sp1.x86\_64.rpm; README

### **Important Note!**

HPE recommends the firmware provided in *HPE Intel Online Firmware Upgrade Utility for Linux x86\_64*, version 1.11.11, for use with these drivers.

### **Enhancements**

This product now supports the HPE Ethernet 10Gb 2-port 563i Adapter.

### **Supported Devices and Features**

This product supports the following network adapters:

- HPE Ethernet 10Gb 2-port 562FLR-SFP+ Adapter
- HPE Ethernet 10Gb 2-port 562SFP+ Adapter
- HPE Ethernet 10Gb 2-port 563i Adapter

---

HPE Intel i40e Drivers for VMware vSphere 5.5/6.0

Version: 2016.03.29 **(Optional)**

Filename: cp027503.zip

### **Important Note!**

This component is intended to be used by HPE applications. It is a zip file that contains the same driver deliverable available from the vmware.com and the HPE vibstdepot.hpe.com webpages, plus an HPE specific CPOxxxxx.xml file.

HPE recommends the firmware provided in *HPE Intel Online Firmware Upgrade Utility for VMware*, version 3.0.8, for use with this driver.

### **Fixes**

This driver addresses a purple diagnostic screen (PSOD) that occurs due to a Tx hang.

This driver addresses an issue where the device flow control behavior does not match the hardware Flow Control setting.

### **Supported Devices and Features**

This product supports the following network adapters:

- HPE Ethernet 10Gb 2-port 562FLR-SFP+ Adapter
- HPE Ethernet 10Gb 2-port 562SFP+ Adapter

---

HPE Intel i40ea Driver for Windows Server 2008 R2

Version: 1.2.130.0 (C) **(Optional)**

Filename: cp029054.exe

### **Important Note!**

HPE recommends the firmware provided in *HPE Intel Online Firmware Upgrade Utility for Windows Server x64 Editions*, version 5.0.0.25 or later, for use with this driver.

### **Fixes**

This product addresses an issue where a shared network port that is ILO enabled loses connectivity while booting with a mounted image.

This product addresses an issue where a yellow bang appears when the user chooses to create a virtual machine using an existing virtual hard disk.

### **Supported Devices and Features**

This product supports the following network adapters:

- HPE Ethernet 10Gb 2-port 562FLR-SFP+ Adapter
- HPE Ethernet 10Gb 2-port 562SFP+ Adapter

---

HPE Intel i40ea Driver for Windows Server 2012

Version: 1.2.133.0 (B) **(Optional)**

Filename: cp029055.exe

### **Important Note!**

HPE recommends the firmware provided in *HPE Intel Online Firmware Upgrade Utility for Windows Server x64 Editions*, version 5.0.0.25 or later, for use with this driver.

### **Fixes**

This product addresses an issue where a shared network port that is ILO enabled loses connectivity while booting with a mounted image.

This product addresses an issue where a yellow bang appears when the user chooses to create a virtual machine using an existing virtual hard disk.

### **Supported Devices and Features**

This product supports the following network adapters:

- HPE Ethernet 10Gb 2-port 562FLR-SFP+ Adapter
- HPE Ethernet 10Gb 2-port 562SFP+ Adapter

---

HPE Intel i40ea Driver for Windows Server 2012 R2

Version: 1.2.133.0 (C) **(Optional)**

Filename: cp029056.exe

### **Important Note!**

HPE recommends the firmware provided in *HPE Intel Online Firmware Upgrade Utility for Windows Server x64 Editions*, version 5.0.0.25 or later, for use with this driver.

### **Fixes**

This product addresses an issue where a shared network port that is ILO enabled loses connectivity while booting with a mounted image.

This product addresses an issue where a yellow bang appears when the user chooses to create a virtual machine using an existing virtual hard disk.

### **Supported Devices and Features**

This product supports the following network adapters:

- HPE Ethernet 10Gb 2-port 562FLR-SFP+ Adapter
- HPE Ethernet 10Gb 2-port 562SFP+ Adapter

---

HPE Intel i40evf Drivers for Red Hat Enterprise Linux 7 x86\_64

Version: 1.3.33.2-12 **(Optional)**

Filename: kmod-hp-i40evf-1.3.33.2-12.rhel7u1.x86\_64.rpm; kmod-hp-i40evf-1.3.33.2-12.rhel7u2.x86\_64.rpm; README

### **Important Note!**

HPE recommends the firmware provided in *HPE Intel Online Firmware Upgrade Utility for Linux x86\_64*, version 1.11.11, for use with these drivers.

### **Fixes**

The RPM header for this product now shows the correct source RPM URL.

### **Supported Devices and Features**

This product supports the following HPE network adapters:

- HPE Ethernet 10Gb 2-port 562FLR-SFP+ Adapter
- HPE Ethernet 10Gb 2-port 562SFP+ Adapter

---

HPE Intel i40evf Drivers for SUSE Linux Enterprise Server 11 x86\_64

Version: 1.3.33.2-12 **(Optional)**

Filename: hp-i40evf-kmp-default-1.3.33.2\_3.0.101\_63-12.sles11sp4.x86\_64.rpm; hp-i40evf-kmp-default-1.3.33.2\_3.0.76\_011-12.sles11sp3.x86\_64.rpm; hp-i40evf-kmp-xen-1.3.33.2\_3.0.101\_63-12.sles11sp4.x86\_64.rpm; hp-i40evf-kmp-xen-1.3.33.2\_3.0.76\_011-12.sles11sp3.x86\_64.rpm; README

### **Important Note!**

HPE recommends the firmware provided in *HPE Intel Online Firmware Upgrade Utility for Linux x86\_64*, version 1.11.11, for use with these drivers.

### **Fixes**

The RPM header for this product now shows the correct source RPM URL.

### **Supported Devices and Features**

This product supports the following HPE network adapters:

- HPE Ethernet 10Gb 2-port 562FLR-SFP+ Adapter
- HPE Ethernet 10Gb 2-port 562SFP+ Adapter

---

HPE Intel i40evf Drivers for SUSE Linux Enterprise Server 12 x86\_64

Version: 1.3.33.2-12 **(Optional)**

Filename: hp-i40evf-kmp-default-1.3.33.2\_k3.12.28\_4-12.sles12sp0.x86\_64.rpm; hp-i40evf-kmp-default-1.3.33.2\_k3.12.49\_11-12.sles12sp1.x86\_64.rpm; hp-i40evf-kmp-xen-1.3.33.2\_k3.12.28\_4-12.sles12sp0.x86\_64.rpm; hp-i40evf-kmp-xen-1.3.33.2\_k3.12.49\_11-12.sles12sp1.x86\_64.rpm; README

### **Important Note!**

HPE recommends the firmware provided in *HPE Intel Online Firmware Upgrade Utility for Linux x86\_64*, version 1.11.11, for use with these drivers.

## **Fixes**

The RPM header for this product now shows the correct source RPM URL.

## **Supported Devices and Features**

This product supports the following HPE network adapters:

- HPE Ethernet 10Gb 2-port 562FLR-SFP+ Adapter
- HPE Ethernet 10Gb 2-port 562SFP+ Adapter

---

HPE Intel igb Drivers for Red Hat Enterprise Linux 6 i686

Version: 5.3.5.3-1 (B) **(Optional)**

Filename: kmod-hp-igb-5.3.5.3-1.rhel6u7.i686.rpm; kmod-hp-igb-5.3.5.3-1.rhel6u8.i686.rpm; README

## **Important Note!**

HPE recommends the firmware provided in *HPE Intel Online Firmware Upgrade Utility for Linux x86*, version 1.11.11 or later, for use with these drivers.

## **Fixes**

This product addresses an issue where the offload property cannot be disabled.

## **Enhancements**

This product now supports Red Hat Enterprise Linux 6 Update 8.

## **Supported Devices and Features**

These drivers support the following Intel network adapters:

- HP Ethernet 1Gb 2-port 361i Adapter
- HP Ethernet 1Gb 2-port 361FLB Adapter
- HP Ethernet 1Gb 2-port 361T Adapter
- HP NC362i Integrated Dual Port Gigabit Server Adapter
- HP NC362i Integrated Dual Port BL-c Gigabit Server Adapter
- HP Ethernet 1Gb 2-port 363i Adapter
- HP Ethernet 1Gb 1-port 364i Adapter
- HP NC365T 4-port Ethernet Server Adapter
- HP Ethernet 1Gb 4-port 366FLR Adapter
- HP Ethernet 1Gb 4-port 366i Adapter
- HP Ethernet 1Gb 4-port 366M Adapter
- HP Ethernet 1Gb 2-port 367i Adapter

---

HPE Intel igb Drivers for Red Hat Enterprise Linux 6 x86\_64

Version: 5.3.5.3-1 (B) **(Optional)**

Filename: kmod-hp-igb-5.3.5.3-1.rhel6u7.x86\_64.rpm; kmod-hp-igb-5.3.5.3-1.rhel6u8.x86\_64.rpm; README

## **Important Note!**

HPE recommends the firmware provided in *HPE Intel Online Firmware Upgrade Utility for Linux x86\_64*, version 1.11.11, for use with these drivers.

### **Fixes**

This product addresses an issue where the offload property cannot be disabled.

### **Enhancements**

This product now supports Red Hat Enterprise Linux 6 Update 8.

This product now supports the HPE Ethernet 1Gb 4-port 366i Communication Board.

### **Supported Devices and Features**

These drivers support the following Intel network adapters:

- HP Ethernet 1Gb 2-port 361i Adapter
- HP Ethernet 1Gb 2-port 361FLB Adapter
- HP Ethernet 1Gb 2-port 361T Adapter
- HP NC362i Integrated Dual Port Gigabit Server Adapter
- HP NC362i Integrated Dual Port BL-c Gigabit Server Adapter
- HP Ethernet 1Gb 2-port 363i Adapter
- HP Ethernet 1Gb 1-port 364i Adapter
- HP NC365T 4-port Ethernet Server Adapter
- HP Ethernet 1Gb 4-port 366FLR Adapter
- HP Ethernet 1Gb 4-port 366i Adapter
- HPE Ethernet 1Gb 4-port 366i Communication Board
- HP Ethernet 1Gb 4-port 366M Adapter
- HP Ethernet 1Gb 4-port 366T Adapter
- HP Ethernet 1Gb 2-port 367i Adapter

---

HPE Intel igb Drivers for Red Hat Enterprise Linux 7 x86\_64

Version: 5.3.5.3-1 **(Optional)**

Filename: kmod-hp-igb-5.3.5.3-1.rhel7u1.x86\_64.rpm; kmod-hp-igb-5.3.5.3-1.rhel7u2.x86\_64.rpm; README

### **Important Note!**

HPE recommends the firmware provided in *HPE Intel Online Firmware Upgrade Utility for Linux x86\_64*, version 1.11.11, for use with these drivers.

### **Fixes**

This product addresses an issue where the offload property cannot be disabled.

### **Enhancements**

This product now supports the HPE Ethernet 1Gb 4-port 366i Communication Board.

### **Supported Devices and Features**

These drivers support the following Intel network adapters:

- HP Ethernet 1Gb 2-port 361i Adapter
- HP Ethernet 1Gb 2-port 361FLB Adapter
- HP Ethernet 1Gb 2-port 361T Adapter
- HP NC362i Integrated Dual Port Gigabit Server Adapter
- HP NC362i Integrated Dual Port BL-c Gigabit Server Adapter
- HP Ethernet 1Gb 2-port 363i Adapter
- HP Ethernet 1Gb 1-port 364i Adapter
- HP NC365T 4-port Ethernet Server Adapter
- HP Ethernet 1Gb 4-port 366FLR Adapter
- HP Ethernet 1Gb 4-port 366i Adapter
- HPE Ethernet 1Gb 4-port 366i Communication Board
- HP Ethernet 1Gb 4-port 366M Adapter
- HP Ethernet 1Gb 4-port 366T Adapter
- HP Ethernet 1Gb 2-port 367i Adapter

---

HPE Intel igb Drivers for SUSE Linux Enterprise Server 11 i586

Version: 5.3.5.3-1 **(Optional)**

Filename: hp-igb-kmp-default-5.3.5.3\_3.0.101\_63-1.sles11sp4.i586.rpm; hp-igb-kmp-default-5.3.5.3\_3.0.76\_011-1.sles11sp3.i586.rpm; hp-igb-kmp-pae-5.3.5.3\_3.0.101\_63-1.sles11sp4.i586.rpm; hp-igb-kmp-pae-5.3.5.3\_3.0.76\_011-1.sles11sp3.i586.rpm; hp-igb-kmp-xen-5.3.5.3\_3.0.101\_63-1.sles11sp4.i586.rpm; hp-igb-kmp-xen-5.3.5.3\_3.0.76\_011-1.sles11sp3.i586.rpm; README

### **Important Note!**

HPE recommends the firmware provided in *HPE Intel Online Firmware Upgrade Utility for Linux x86*, version 1.11.11 or later, for use with these drivers.

### **Fixes**

This product addresses an issue where the offload property cannot be disabled.

### **Supported Devices and Features**

These drivers support the following Intel network adapters:

- HP Ethernet 1Gb 2-port 361i Adapter
- HP Ethernet 1Gb 2-port 361FLB Adapter
- HP Ethernet 1Gb 2-port 361T Adapter
- HP NC362i Integrated Dual Port Gigabit Server Adapter
- HP NC362i Integrated Dual Port BL-c Gigabit Server Adapter
- HP Ethernet 1Gb 2-port 363i Adapter
- HP Ethernet 1Gb 1-port 364i Adapter
- HP NC365T 4-port Ethernet Server Adapter
- HP Ethernet 1Gb 4-port 366FLR Adapter
- HP Ethernet 1Gb 4-port 366i Adapter
- HP Ethernet 1Gb 4-port 366M Adapter
- HP Ethernet 1Gb 2-port 367i Adapter

---

HPE Intel igb Drivers for SUSE Linux Enterprise Server 11 x86\_64

Version: 5.3.5.3-1 **(Optional)**

Filename: hp-igb-kmp-default-5.3.5.3\_3.0.101\_63-1.sles11sp4.x86\_64.rpm; hp-igb-kmp-default-5.3.5.3\_3.0.76\_011-1.sles11sp3.x86\_64.rpm; hp-igb-kmp-xen-5.3.5.3\_3.0.101\_63-1.sles11sp4.x86\_64.rpm; hp-igb-kmp-xen-5.3.5.3\_3.0.76\_011-1.sles11sp3.x86\_64.rpm; README

### **Important Note!**

HPE recommends the firmware provided in *HPE Intel Online Firmware Upgrade Utility for Linux x86\_64*, version 1.11.11, for use with these drivers.

### **Fixes**

This product addresses an issue where the offload property cannot be disabled.

### **Supported Devices and Features**

These drivers support the following Intel network adapters:

- HP Ethernet 1Gb 2-port 361i Adapter
- HP Ethernet 1Gb 2-port 361FLB Adapter
- HP Ethernet 1Gb 2-port 361T Adapter
- HP NC362i Integrated Dual Port Gigabit Server Adapter
- HP NC362i Integrated Dual Port BL-c Gigabit Server Adapter
- HP Ethernet 1Gb 2-port 363i Adapter
- HP Ethernet 1Gb 1-port 364i Adapter
- HP NC365T 4-port Ethernet Server Adapter
- HP Ethernet 1Gb 4-port 366FLR Adapter
- HP Ethernet 1Gb 4-port 366i Adapter
- HP Ethernet 1Gb 4-port 366M Adapter
- HP Ethernet 1Gb 4-port 366T Adapter
- HP Ethernet 1Gb 2-port 367i Adapter

---

HPE Intel igb Drivers for SUSE Linux Enterprise Server 12 x86\_64

Version: 5.3.5.3-1 **(Optional)**

Filename: hp-igb-kmp-default-5.3.5.3\_k3.12.28\_4-1.sles12sp0.x86\_64.rpm; hp-igb-kmp-default-5.3.5.3\_k3.12.49\_11-1.sles12sp1.x86\_64.rpm; hp-igb-kmp-xen-5.3.5.3\_k3.12.28\_4-1.sles12sp0.x86\_64.rpm; hp-igb-kmp-xen-5.3.5.3\_k3.12.49\_11-1.sles12sp1.x86\_64.rpm; README

### **Important Note!**

HPE recommends the firmware provided in *HPE Intel Online Firmware Upgrade Utility for Linux x86\_64*, version 1.11.11, for use with these drivers.

### **Fixes**

This product addresses an issue where the offload property cannot be disabled.

### **Supported Devices and Features**

These drivers support the following Intel network adapters:

- HP Ethernet 1Gb 2-port 361i Adapter
- HP Ethernet 1Gb 2-port 361FLB Adapter
- HP Ethernet 1Gb 2-port 361T Adapter



- HP NC362i Integrated Dual Port Gigabit Server Adapter
- HP NC362i Integrated Dual Port BL-c Gigabit Server Adapter
- HP Ethernet 1Gb 2-port 363i Adapter
- HP Ethernet 1Gb 1-port 364i Adapter
- HP NC365T 4-port Ethernet Server Adapter
- HP Ethernet 1Gb 4-port 366FLR Adapter
- HP Ethernet 1Gb 4-port 366i Adapter
- HP Ethernet 1Gb 4-port 366M Adapter
- HP Ethernet 1Gb 4-port 366T Adapter
- HP Ethernet 1Gb 2-port 367i Adapter

---

HPE Intel igb Drivers for VMware vSphere 5.5/6.0

Version: 2016.10.07 **(Optional)**

Filename: cp029473.zip

### **Important Note!**

This component is intended to be used by HPE applications. It is a zip file that contains the same driver deliverable available from the vmware.com and the HPE vibsdepot.hpe.com webpages, plus an HPE specific CPOxxxx.xml file.

HPE recommends the firmware provided in *HPE Intel Online Firmware Upgrade Utility for VMware*, version 3.1.9 or later, for use with this driver.

### **Fixes**

This product resolves an issue where an excessive number of error messages is logged.

### **Enhancements**

This product now supports the HPE Ethernet 1Gb 4-port 366i Communication Board.

### **Supported Devices and Features**

These drivers support the following network adapters:

- HP Ethernet 1Gb 2-port 361i Adapter
- HP Ethernet 1Gb 2-port 361FLB Adapter
- HP Ethernet 1Gb 2-port 361T Adapter
- HP NC362i Integrated Dual Port Gigabit Server Adapter
- HP NC362i Integrated Dual Port BL-c Gigabit Server Adapter
- HP Ethernet 1Gb 2-port 363i Adapter
- HP Ethernet 1Gb 1-port 364i Adapter
- HP NC365T 4-port Ethernet Server Adapter
- HP Ethernet 1Gb 4-port 366FLR Adapter
- HP Ethernet 1Gb 4-port 366i Adapter
- HPE Ethernet 1Gb 4-port 366i Communication Board
- HP Ethernet 1Gb 4-port 366M Adapter
- HP Ethernet 1Gb 4-port 366T Adapter
- HP Ethernet 1Gb 2-port 367i Adapter

---

HPE Intel ixgbe Drivers for Red Hat Enterprise Linux 6 i686

Version: 4.4.6-1 **(Optional)**

Filename: kmod-hp-ixgbe-4.3.13-2.rhel6u7.i686.rpm; kmod-hp-ixgbe-4.4.6-1.rhel6u8.i686.rpm; README

### **Important Note!**

HPE recommends the firmware provided in *HPE Intel Online Firmware Upgrade Utility for Linux x86*, version 1.11.11 or later, for use with these drivers.

### **Fixes**

This product addresses an issue where the first virtual function (VF) receives a copy of physical function's (PF) traffic.

### **Enhancements**

This product now supports Red Hat Enterprise Linux 6 Update 8.

This product now provides multicast promiscuous mode support for trusted virtual functions.

### **Supported Devices and Features**

These drivers support the following network adapters:

- HP Ethernet 10Gb 2-port 560FLB Adapter
- HP Ethernet 10Gb 2-port 560FLR-SFP+ Adapter
- HP Ethernet 10Gb 2-port 560M Adapter
- HP Ethernet 10Gb 2-port 560SFP+ Adapter
- HP Ethernet 10Gb 2-port 561FLR-T Adapter
- HP Ethernet 10Gb 2-port 561T Adapter
- HP Ethernet 10Gb 2-port 562i Adapter

---

HPE Intel ixgbe Drivers for Red Hat Enterprise Linux 6 x86\_64

Version: 4.4.6-1 **(Optional)**

Filename: kmod-hp-ixgbe-4.3.13-2.rhel6u7.x86\_64.rpm; kmod-hp-ixgbe-4.4.6-1.rhel6u8.x86\_64.rpm; README

### **Important Note!**

HPE recommends the firmware provided in *HPE Intel Online Firmware Upgrade Utility for Linux x86\_64*, version 1.11.11, for use with these drivers.

### **Fixes**

This product addresses an issue where the first virtual function (VF) receives a copy of physical function's (PF) traffic.

### **Enhancements**

This product now supports Red Hat Enterprise Linux 6 Update 8.

This product now provides multicast promiscuous mode support for trusted virtual functions.

### **Supported Devices and Features**

These drivers support the following network adapters:

- HP Ethernet 10Gb 2-port 560FLB Adapter
- HP Ethernet 10Gb 2-port 560FLR-SFP+ Adapter
- HP Ethernet 10Gb 2-port 560M Adapter
- HP Ethernet 10Gb 2-port 560SFP+ Adapter
- HP Ethernet 10Gb 2-port 561FLR-T Adapter
- HP Ethernet 10Gb 2-port 561T Adapter
- HP Ethernet 10Gb 2-port 562i Adapter

---

HPE Intel ixgbe Drivers for Red Hat Enterprise Linux 7 x86\_64

Version: 4.3.13-2 **(Optional)**

Filename: kmod-hp-ixgbe-4.3.13-2.rhel7u1.x86\_64.rpm; kmod-hp-ixgbe-4.3.13-2.rhel7u2.x86\_64.rpm; README

### **Important Note!**

HPE recommends the firmware provided in *HPE Intel Online Firmware Upgrade Utility for Linux x86\_64*, version 1.11.11, for use with these drivers.

### **Fixes**

This product addresses an issue where the first virtual function (VF) receives a copy of physical function's (PF) traffic.

### **Enhancements**

This product now provides multicast promiscuous mode support for trusted virtual functions.

### **Supported Devices and Features**

These drivers support the following network adapters:

- HP Ethernet 10Gb 2-port 560FLB Adapter
- HP Ethernet 10Gb 2-port 560FLR-SFP+ Adapter
- HP Ethernet 10Gb 2-port 560M Adapter
- HP Ethernet 10Gb 2-port 560SFP+ Adapter
- HP Ethernet 10Gb 2-port 561FLR-T Adapter
- HP Ethernet 10Gb 2-port 561T Adapter
- HP Ethernet 10Gb 2-port 562i Adapter

---

HPE Intel ixgbe Drivers for SUSE Linux Enterprise Server 11 i586

Version: 4.3.13-2 **(Optional)**

Filename: hp-ixgbe-kmp-default-4.3.13\_3.0.101\_63-2.sles11sp4.i586.rpm; hp-ixgbe-kmp-default-4.3.13\_3.0.76\_0.11-2.sles11sp3.i586.rpm; hp-ixgbe-kmp-pae-4.3.13\_3.0.101\_63-2.sles11sp4.i586.rpm; hp-ixgbe-kmp-pae-4.3.13\_3.0.76\_0.11-2.sles11sp3.i586.rpm; hp-ixgbe-kmp-xen-4.3.13\_3.0.101\_63-2.sles11sp4.i586.rpm; hp-ixgbe-kmp-xen-4.3.13\_3.0.76\_0.11-2.sles11sp3.i586.rpm; README

### **Important Note!**

HPE recommends the firmware provided in *HPE Intel Online Firmware Upgrade Utility for Linux x86*, version 1.11.11 or later, for use with these drivers.

## **Fixes**

This product addresses an issue where the first virtual function (VF) receives a copy of physical function's (PF) traffic.

## **Enhancements**

This product now provides multicast promiscuous mode support for trusted virtual functions.

## **Supported Devices and Features**

These drivers support the following network adapters:

- HP Ethernet 10Gb 2-port 560FLB Adapter
- HP Ethernet 10Gb 2-port 560FLR-SFP+ Adapter
- HP Ethernet 10Gb 2-port 560M Adapter
- HP Ethernet 10Gb 2-port 560SFP+ Adapter
- HP Ethernet 10Gb 2-port 561FLR-T Adapter
- HP Ethernet 10Gb 2-port 561T Adapter
- HP Ethernet 10Gb 2-port 562i Adapter

---

HPE Intel ixgbe Drivers for SUSE Linux Enterprise Server 11 x86\_64

Version: 4.3.13-2 **(Optional)**

Filename: hp-ixgbe-kmp-default-4.3.13\_3.0.101\_63-2.sles11sp4.x86\_64.rpm; hp-ixgbe-kmp-default-4.3.13\_3.0.76\_0.11-2.sles11sp3.x86\_64.rpm; hp-ixgbe-kmp-xen-4.3.13\_3.0.101\_63-2.sles11sp4.x86\_64.rpm; hp-ixgbe-kmp-xen-4.3.13\_3.0.76\_0.11-2.sles11sp3.x86\_64.rpm; README

## **Important Note!**

HPE recommends the firmware provided in *HPE Intel Online Firmware Upgrade Utility for Linux x86\_64*, version 1.11.11, for use with these drivers.

## **Fixes**

This product addresses an issue where the first virtual function (VF) receives a copy of physical function's (PF) traffic.

## **Enhancements**

This product now provides multicast promiscuous mode support for trusted virtual functions.

## **Supported Devices and Features**

These drivers support the following network adapters:

- HP Ethernet 10Gb 2-port 560FLB Adapter
  - HP Ethernet 10Gb 2-port 560FLR-SFP+ Adapter
  - HP Ethernet 10Gb 2-port 560M Adapter
  - HP Ethernet 10Gb 2-port 560SFP+ Adapter
  - HP Ethernet 10Gb 2-port 561FLR-T Adapter
  - HP Ethernet 10Gb 2-port 561T Adapter
  - HP Ethernet 10Gb 2-port 562i Adapter
-

HPE Intel ixgbe Drivers for SUSE Linux Enterprise Server 12 x86\_64

Version: 4.3.13-2 **(Optional)**

Filename: hp-ixgbe-kmp-default-4.3.13\_k3.12.28\_4-2.sles12sp0.x86\_64.rpm; hp-ixgbe-kmp-default-4.3.13\_k3.12.49\_11-2.sles12sp1.x86\_64.rpm; hp-ixgbe-kmp-xen-4.3.13\_k3.12.28\_4-2.sles12sp0.x86\_64.rpm; hp-ixgbe-kmp-xen-4.3.13\_k3.12.49\_11-2.sles12sp1.x86\_64.rpm; README

### **Important Note!**

HPE recommends the firmware provided in *HPE Intel Online Firmware Upgrade Utility for Linux x86\_64*, version 1.11.11, for use with these drivers.

### **Fixes**

This product addresses an issue where the first virtual function (VF) receives a copy of physical function's (PF) traffic.

### **Enhancements**

This product now provides multicast promiscuous mode support for trusted virtual functions.

### **Supported Devices and Features**

These drivers support the following network adapters:

- HP Ethernet 10Gb 2-port 560FLB Adapter
- HP Ethernet 10Gb 2-port 560FLR-SFP+ Adapter
- HP Ethernet 10Gb 2-port 560M Adapter
- HP Ethernet 10Gb 2-port 560SFP+ Adapter
- HP Ethernet 10Gb 2-port 561FLR-T Adapter
- HP Ethernet 10Gb 2-port 561T Adapter
- HP Ethernet 10Gb 2-port 562i Adapter

---

HPE Intel ixgbe Drivers for VMware vSphere 6.0

Version: 2016.10.07 **(Optional)**

Filename: cp029476.zip

### **Important Note!**

This component is intended to be used by HPE applications. It is a zip file that contains the same driver deliverable available from the vmware.com and the HPE vibspot.hpe.com webpages, plus an HPE specific CPOxxxx.xml file.

HPE recommends the firmware provided in *HPE Intel Online Firmware Upgrade Utility for VMware*, version 3.1.9 or later, for use with this driver.

### **Fixes**

This product resolves an issue where an excessive number of error messages is logged.

### **Supported Devices and Features**

These drivers support the following network adapters:

- HP Ethernet 10Gb 2-port 560FLB Adapter
- HP Ethernet 10Gb 2-port 560FLR-SFP+ Adapter

- HP Ethernet 10Gb 2-port 560M Adapter
- HP Ethernet 10Gb 2-port 560SFP+ Adapter
- HP Ethernet 10Gb 2-port 561FLR-T Adapter
- HP Ethernet 10Gb 2-port 561T Adapter
- HP Ethernet 10Gb 2-port 562i Adapter

---

HPE Intel ixgbevf Drivers for Red Hat Enterprise Linux 6 i686

Version: 3.2.2-1 **(Optional)**

Filename: kmod-hp-ixgbevf-3.1.2-2.rhel6u7.i686.rpm; kmod-hp-ixgbevf-3.2.2-1.rhel6u8.i686.rpm; README

### **Important Note!**

HPE recommends the firmware provided in *HPE Intel Online Firmware Upgrade Utility for Linux x86*, version 1.11.11 or later, for use with these drivers.

### **Fixes**

This product addresses an issue where the first virtual function (VF) receives a copy of physical function's (PF) traffic.

### **Enhancements**

This product now supports Red Hat Enterprise Linux 6 Update 8.

This product now provides multicast promiscuous mode support for trusted virtual functions.

### **Supported Devices and Features**

These drivers support the following network adapters:

- HP Ethernet 10Gb 2-port 560FLB Adapter
- HP Ethernet 10Gb 2-port 560FLR-SFP+ Adapter
- HP Ethernet 10Gb 2-port 560M Adapter
- HP Ethernet 10Gb 2-port 560SFP+ Adapter
- HP Ethernet 10Gb 2-port 561FLR-T Adapter
- HP Ethernet 10Gb 2-port 561T Adapter
- HP Ethernet 10Gb 2-port 562i Adapter

---

HPE Intel ixgbevf Drivers for Red Hat Enterprise Linux 6 x86\_64

Version: 3.2.2-1 **(Optional)**

Filename: kmod-hp-ixgbevf-3.1.2-2.rhel6u7.x86\_64.rpm; kmod-hp-ixgbevf-3.2.2-1.rhel6u8.x86\_64.rpm; README

### **Important Note!**

HPE recommends the firmware provided in *HPE Intel Online Firmware Upgrade Utility for Linux x86\_64*, version 1.11.11, for use with these drivers.

### **Fixes**

This product addresses an issue where the first virtual function (VF) receives a copy of physical function's (PF) traffic.

## **Enhancements**

This product now supports Red Hat Enterprise Linux 6 Update 8.

This product now provides multicast promiscuous mode support for trusted virtual functions.

## **Supported Devices and Features**

These drivers support the following network adapters:

- HP Ethernet 10Gb 2-port 560FLB Adapter
- HP Ethernet 10Gb 2-port 560FLR-SFP+ Adapter
- HP Ethernet 10Gb 2-port 560M Adapter
- HP Ethernet 10Gb 2-port 560SFP+ Adapter
- HP Ethernet 10Gb 2-port 561FLR-T Adapter
- HP Ethernet 10Gb 2-port 561T Adapter
- HP Ethernet 10Gb 2-port 562i Adapter

---

HPE Intel ixgbevf Drivers for Red Hat Enterprise Linux 7 x86\_64

Version: 3.1.2-2 **(Optional)**

Filename: kmod-hp-ixgbevf-3.1.2-2.rhel7u1.x86\_64.rpm; kmod-hp-ixgbevf-3.1.2-2.rhel7u2.x86\_64.rpm; README

## **Important Note!**

HPE recommends the firmware provided in *HPE Intel Online Firmware Upgrade Utility for Linux x86\_64*, version 1.11.11, for use with these drivers.

## **Fixes**

This product addresses an issue where the first virtual function (VF) receives a copy of physical function's (PF) traffic.

## **Enhancements**

This product now provides multicast promiscuous mode support for trusted virtual functions.

## **Supported Devices and Features**

These drivers support the following network adapters:

- HP Ethernet 10Gb 2-port 560FLB Adapter
- HP Ethernet 10Gb 2-port 560FLR-SFP+ Adapter
- HP Ethernet 10Gb 2-port 560M Adapter
- HP Ethernet 10Gb 2-port 560SFP+ Adapter
- HP Ethernet 10Gb 2-port 561FLR-T Adapter
- HP Ethernet 10Gb 2-port 561T Adapter
- HP Ethernet 10Gb 2-port 562i Adapter

---

HPE Intel ixgbevf Drivers for SUSE Linux Enterprise Server 11 i586

Version: 3.1.2-2 **(Optional)**

Filename: hp-ixgbevf-kmp-default-3.1.2\_3.0.101\_63-2.sles11sp4.i586.rpm; hp-ixgbevf-kmp-default-3.1.2\_3.0.76\_0.11-2.sles11sp3.i586.rpm; hp-ixgbevf-kmp-pae-3.1.2\_3.0.101\_63-2.sles11sp4.i586.rpm; hp-ixgbevf-kmp-pae-3.1.2\_3.0.76\_0.11-2.sles11sp3.i586.rpm; hp-ixgbevf-kmp-xen-3.1.2\_3.0.101\_63-2.sles11sp4.i586.rpm; hp-ixgbevf-kmp-xen-3.1.2\_3.0.76\_0.11-2.sles11sp3.i586.rpm; README

### **Important Note!**

HPE recommends the firmware provided in *HPE Intel Online Firmware Upgrade Utility for Linux x86*, version 1.11.11 or later, for use with these drivers.

### **Fixes**

This product addresses an issue where the first virtual function (VF) receives a copy of physical function's (PF) traffic.

### **Enhancements**

This product now provides multicast promiscuous mode support for trusted virtual functions.

### **Supported Devices and Features**

These drivers support the following network adapters:

- HP Ethernet 10Gb 2-port 560FLB Adapter
- HP Ethernet 10Gb 2-port 560FLR-SFP+ Adapter
- HP Ethernet 10Gb 2-port 560M Adapter
- HP Ethernet 10Gb 2-port 560SFP+ Adapter
- HP Ethernet 10Gb 2-port 561FLR-T Adapter
- HP Ethernet 10Gb 2-port 561T Adapter
- HP Ethernet 10Gb 2-port 562i Adapter

---

HPE Intel ixgbevf Drivers for SUSE Linux Enterprise Server 11 x86\_64

Version: 3.1.2-2 **(Optional)**

Filename: hp-ixgbevf-kmp-default-3.1.2\_3.0.101\_63-2.sles11sp4.x86\_64.rpm; hp-ixgbevf-kmp-default-3.1.2\_3.0.76\_0.11-2.sles11sp3.x86\_64.rpm; hp-ixgbevf-kmp-xen-3.1.2\_3.0.101\_63-2.sles11sp4.x86\_64.rpm; hp-ixgbevf-kmp-xen-3.1.2\_3.0.76\_0.11-2.sles11sp3.x86\_64.rpm; README

### **Important Note!**

HPE recommends the firmware provided in *HPE Intel Online Firmware Upgrade Utility for Linux x86\_64*, version 1.11.11, for use with these drivers.

### **Fixes**

This product addresses an issue where the first virtual function (VF) receives a copy of physical function's (PF) traffic.

### **Enhancements**

This product now provides multicast promiscuous mode support for trusted virtual functions.

### **Supported Devices and Features**

These drivers support the following network adapters:



- HP Ethernet 10Gb 2-port 560FLB Adapter
- HP Ethernet 10Gb 2-port 560FLR-SFP+ Adapter
- HP Ethernet 10Gb 2-port 560M Adapter
- HP Ethernet 10Gb 2-port 560SFP+ Adapter
- HP Ethernet 10Gb 2-port 561FLR-T Adapter
- HP Ethernet 10Gb 2-port 561T Adapter
- HP Ethernet 10Gb 2-port 562i Adapter

---

HPE Intel ixgbevf Drivers for SUSE Linux Enterprise Server 12 x86\_64

Version: 3.1.2-2 **(Optional)**

Filename: hp-ixgbevf-kmp-default-3.1.2\_k3.12.28\_4-2.sles12sp0.x86\_64.rpm; hp-ixgbevf-kmp-default-3.1.2\_k3.12.49\_11-2.sles12sp1.x86\_64.rpm; hp-ixgbevf-kmp-xen-3.1.2\_k3.12.28\_4-2.sles12sp0.x86\_64.rpm; hp-ixgbevf-kmp-xen-3.1.2\_k3.12.49\_11-2.sles12sp1.x86\_64.rpm; README

### **Important Note!**

HPE recommends the firmware provided in *HPE Intel Online Firmware Upgrade Utility for Linux x86\_64*, version 1.11.11, for use with these drivers.

### **Fixes**

This product addresses an issue where the first virtual function (VF) receives a copy of physical function's (PF) traffic.

### **Enhancements**

This product now provides multicast promiscuous mode support for trusted virtual functions.

### **Supported Devices and Features**

These drivers support the following network adapters:

- HP Ethernet 10Gb 2-port 560FLB Adapter
- HP Ethernet 10Gb 2-port 560FLR-SFP+ Adapter
- HP Ethernet 10Gb 2-port 560M Adapter
- HP Ethernet 10Gb 2-port 560SFP+ Adapter
- HP Ethernet 10Gb 2-port 561FLR-T Adapter
- HP Ethernet 10Gb 2-port 561T Adapter
- HP Ethernet 10Gb 2-port 562i Adapter

---

HPE Intel ixn/ixt Drivers for Windows Server 2008 R2

Version: 3.9.58.9101 (C) **(Optional)**

Filename: cp029058.exe

### **Important Note!**

HPE recommends the firmware provided in *HPE Intel Online Firmware Upgrade Utility for Windows Server x64 Editions*, version 5.0.0.25 or later, for use with this driver.

### **Fixes**

This product corrects an issue which results in the component selecting an incorrect driver for installation.

The \*NumaNodeID keyword has been changed to type \*dword"(as per Microsoft documentation) to correctly support more than 8 NUMA nodes.

### **Supported Devices and Features**

This component supports the following HP Intel ixn network adapters:

- HP Ethernet 10Gb 2-port 560FLB Adapter
- HP Ethernet 10Gb 2-port 560FLR-SFP+ Adapter
- HP Ethernet 10Gb 2-port 560M Adapter
- HP Ethernet 10Gb 2-port 560SFP+ Adapter

This component supports the following HP Intel ixt network adapters:

- HP Ethernet 10Gb 2-port 561FLR-T Adapter
- HP Ethernet 10Gb 2-port 561T Adapter
- HP Ethernet 10Gb 2-port 562i Adapter

---

HPE Intel ixn/ixt Drivers for Windows Server 2012

Version: 3.9.58.9101 (C) **(Optional)**

Filename: cp029059.exe

### **Important Note!**

HPE recommends the firmware provided in *HPE Intel Online Firmware Upgrade Utility for Windows Server x64 Editions*, version 5.0.0.25 or later, for use with this driver.

### **Fixes**

This product corrects an issue which results in the component selecting an incorrect driver for installation.

The \*NumaNodeID keyword has been changed to type \*dword"(as per Microsoft documentation) to correctly support more than 8 NUMA nodes.

### **Supported Devices and Features**

This component supports the following HP Intel ixn network adapters:

- HP Ethernet 10Gb 2-port 560FLB Adapter
- HP Ethernet 10Gb 2-port 560FLR-SFP+ Adapter
- HP Ethernet 10Gb 2-port 560SFP+ Adapter
- HP Ethernet 10Gb 2-port 560M Adapter

This component supports the following HP Intel ixt network adapters:

- HP Ethernet 10Gb 2-port 561FLR-T Adapter
- HP Ethernet 10Gb 2-port 561T Adapter
- HP Ethernet 10Gb 2-port 562i Adapter

---

HPE Intel ixn/ixt Drivers for Windows Server 2012 R2

Version: 3.9.58.9101 (C) **(Optional)**

Filename: cp029060.exe

### **Important Note!**

HPE recommends the firmware provided in *HPE Intel Online Firmware Upgrade Utility for Windows Server x64 Editions*, version 5.0.0.25 or later,

for use with this driver.

## **Fixes**

This product corrects an issue which results in the component selecting an incorrect driver for installation.

The \*NumaNodeID keyword has been changed to type \*dword"(as per Microsoft documentation) to correctly support more than 8 NUMA nodes.

## **Supported Devices and Features**

This component supports the following HP Intel ixn network adapters:

- HP Ethernet 10Gb 2-port 560FLB Adapter
- HP Ethernet 10Gb 2-port 560FLR-SFP+ Adapter
- HP Ethernet 10Gb 2-port 560SFP+ Adapter
- HP Ethernet 10Gb 2-port 560M Adapter

This component supports the following HP Intel ixt network adapters:

- HP Ethernet 10Gb 2-port 561FLR-T Adapter
- HP Ethernet 10Gb 2-port 561T Adapter
- HP Ethernet 10Gb 2-port 562i Adapter

---

HPE Intel ixn/ixt Drivers for Windows Server 2016

Version: 4.0.217.0 **(Optional)**

Filename: cp029677.exe

## **Important Note!**

HPE recommends the firmware provided in *HPE Intel Online Firmware Upgrade Utility for Windows Server x64 Editions*, version 5.0.0.25 or later, for use with this driver.

## **Enhancements**

Initial release.

## **Supported Devices and Features**

This component supports the following HP Intel ixn network adapters:

- HP Ethernet 10Gb 2-port 560FLB Adapter
- HP Ethernet 10Gb 2-port 560FLR-SFP+ Adapter
- HP Ethernet 10Gb 2-port 560SFP+ Adapter
- HP Ethernet 10Gb 2-port 560M Adapter

This component supports the following HP Intel ixt network adapters:

- HP Ethernet 10Gb 2-port 561FLR-T Adapter
- HP Ethernet 10Gb 2-port 561T Adapter
- HP Ethernet 10Gb 2-port 562i Adapter

---

HPE Mellanox RoCE (RDMA over Converged Ethernet) Driver for Red Hat Enterprise Linux 6 Update 6 (x86\_64)

Version: 3.2 (A) **(Recommended)**

Filename: kmod-mlnx-ofa\_kernel-3.2-OFED.3.2.2.0.0.1.g378ff02.rhel6u6.x86\_64.rpm; mlnx-ofa\_kernel-3.2-OFED.3.2.2.0.0.1.g378ff02.5.rhel6u6.x86\_64.rpm

## **Fixes**

### **Fixes in version 3.2 (A):**

- The RoCE user-space library RPM "mlnx-ofa\_kernel" failed to install when OS distribution RPMs in "infiniband support" group were already installed.
- The RoCE driver upgrade didnt work properly when a previous version of MLNX-EN driver was already installed. This resulted in Mellanox Ethernet ports not coming up.

### **Fixes in version 3.2:**

- Set closest NUMA node as the default for Receive Side Scaling.
- ARP request packets destined for a proxy VXLAN interface were not handled correctly when GRO was enabled.

## **Enhancements**

### **HPE Mellanox RoCE driver version 3.2 contains the following changes and new features:**

- FCS scattering for Raw Packet Queue Pairs and Work Queues.
- Indication of L4 packet type on the receive side completions.
- Support CVLAN insertion for Work Queues

## **Supported Devices and Features**

SUPPORTED KERNELS:

The kernels of Red Hat Enterprise Linux 6U6 (x86\_64) supported by this binary rpm are:  
2.6.32-504.el6 - (x86\_64) and future update kernels.

---

HPE Mellanox RoCE (RDMA over Converged Ethernet) Driver for Red Hat Enterprise Linux 6 Update 7 (x86\_64)

Version: 3.2 (A) **(Recommended)**

Filename: kmod-mlnx-ofa\_kernel-3.2-OFED.3.2.2.0.0.1.g378ff02.rhel6u7.x86\_64.rpm; mlnx-ofa\_kernel-3.2-OFED.3.2.2.0.0.1.g378ff02.5.rhel6u7.x86\_64.rpm

## **Fixes**

### **Fixes in version 3.2 (A):**

- The RoCE user-space library RPM "mlnx-ofa\_kernel" failed to install when OS distribution RPMs in "infiniband support" group were already installed.
- The RoCE driver upgrade didnt work properly when a previous version of MLNX-EN driver was already installed. This resulted in Mellanox Ethernet ports not coming up.

### **Fixes in version 3.2:**

- Set closest NUMA node as the default for Receive Side Scaling.
- ARP request packets destined for a proxy VXLAN interface were not handled correctly when GRO was enabled.

## **Enhancements**

### **HPE Mellanox RoCE driver version 3.2 contains the following changes and new features:**

- FCS scattering for Raw Packet Queue Pairs and Work Queues.
- Indication of L4 packet type on the receive side completions.
- Support CVLAN insertion for Work Queues

## **Supported Devices and Features**

SUPPORTED KERNELS:

The kernels of Red Hat Enterprise Linux 6U6 (x86\_64) supported by this binary rpm are:  
2.6.32-573.el6 - (x86\_64) and future update kernels.

---

HPE Mellanox RoCE (RDMA over Converged Ethernet) Driver for Red Hat Enterprise Linux 7 Update 1 (x86\_64)

Version: 3.2 (A) **(Recommended)**

Filename: kmod-mlnx-ofa\_kernel-3.2-OFED.3.2.2.0.0.1.g378ff02.rhel7u1.x86\_64.rpm; mlnx-ofa\_kernel-3.2-OFED.3.2.2.0.0.1.g378ff02.5.rhel7u1.x86\_64.rpm

## **Fixes**

### **Fixes in version 3.2 (A):**

- The RoCE user-space library RPM "mlnx-ofa\_kernel" failed to install when OS distribution RPMs in "infiniband support" group were already installed.
- The RoCE driver upgrade didnt work properly when a previous version of MLNX-EN driver was already installed. This resulted in Mellanox Ethernet ports not coming up.

### **Fixes in version 3.2:**

- Set closest NUMA node as the default for Receive Side Scaling.
- ARP request packets destined for a proxy VXLAN interface were not handled correctly when GRO was enabled.

## **Enhancements**

### **HPE Mellanox RoCE driver version 3.2 contains the following changes and new features:**

- FCS scattering for Raw Packet Queue Pairs and Work Queues.
- Indication of L4 packet type on the receive side completions.
- Support CVLAN insertion for Work Queues

## **Supported Devices and Features**

SUPPORTED KERNELS:

The kernels of Red Hat Enterprise Linux 7 Update 1 (x86\_64) supported by this binary rpm are:  
3.10.0-229.el7 - (x86\_64) and future update kernels.

---

HPE Mellanox RoCE (RDMA over Converged Ethernet) Driver for Red Hat Enterprise Linux 7 Update 2 (x86\_64)

Version: 3.2 (A) **(Recommended)**

Filename: kmod-mlnx-ofa\_kernel-3.2-OFED.3.2.2.0.0.1.g378ff02.rhel7u2.x86\_64.rpm; mlnx-ofa\_kernel-3.2-OFED.3.2.2.0.0.1.g378ff02.5.rhel7u2.x86\_64.rpm

## **Fixes**

### **Fixes in version 3.2 (A):**

- The RoCE user-space library RPM "mlnx-ofa\_kernel" failed to install when OS distribution RPMs in "infiniband support" group were already installed.
- The RoCE driver upgrade didnt work properly when a previous version of MLNX-EN driver was already installed. This resulted in Mellanox Ethernet ports not coming up.

#### **Fixes in version 3.2:**

- Set closest NUMA node as the default for Receive Side Scaling.
- ARP request packets destined for a proxy VXLAN interface were not handled correctly when GRO was enabled.

#### **Enhancements**

##### **HPE Mellanox RoCE driver version 3.2 contains the following changes and new features:**

- FCS scattering for Raw Packet Queue Pairs and Work Queues.
- Indication of L4 packet type on the receive side completions.
- Support CVLAN insertion for Work Queues

#### **Supported Devices and Features**

SUPPORTED KERNELS:

The kernels of Red Hat Enterprise Linux 7 Update 2 (x86\_64) supported by this binary rpm are:  
3.10.0-327.el7 - (x86\_64) and future update kernels.

---

HPE Mellanox RoCE (RDMA over Converged Ethernet) Driver for SUSE LINUX Enterprise Server 11 SP3 AMD64/EM64T)

Version: 3.2 (A) **(Recommended)**

Filename: mlnx-ofa\_kernel-3.2-OFED.3.2.2.0.0.1.g378ff02.5.sles11sp3.x86\_64.rpm; mlnx-ofa\_kernel-kmp-default-3.2\_3.0.76\_0.11-OFED.3.2.2.0.0.1.g378ff02.sles11sp3.x86\_64.rpm; mlnx-ofa\_kernel-kmp-xen-3.2\_3.0.76\_0.11-OFED.3.2.2.0.0.1.g378ff02.sles11sp3.x86\_64.rpm

#### **Fixes**

##### **Fixes in version 3.2 (A):**

- The RoCE user-space library RPM "mlnx-ofa\_kernel" failed to install when OS distribution RPMs in "infiniband support" group were already installed.
- The RoCE driver upgrade didnt work properly when a previous version of MLNX-EN driver was already installed. This resulted in Mellanox Ethernet ports not coming up.

#### **Fixes in version 3.2:**

- Set closest NUMA node as the default for Receive Side Scaling.
- ARP request packets destined for a proxy VXLAN interface were not handled correctly when GRO was enabled.

#### **Enhancements**

##### **HPE Mellanox RoCE driver version 3.2 contains the following changes and new features:**

- FCS scattering for Raw Packet Queue Pairs and Work Queues.
- Indication of L4 packet type on the receive side completions.
- Support CVLAN insertion for Work Queues

#### **Supported Devices and Features**

#### SUPPORTED KERNELS:

The kernels of SUSE LINUX Enterprise Server SP3 (AMD64/EM64T) supported by this binary rpm are:

3.0.76-0.11-default - (AMD64/EM64T) and future update kernels.

3.0.76-0.11-xen - (AMD64/EM64T) and future update kernels.

---

HPE Mellanox RoCE (RDMA over Converged Ethernet) Driver for SUSE LINUX Enterprise Server 11 SP4 AMD64/EM64T)

Version: 3.2 (A) **(Recommended)**

Filename: mlnx-ofa\_kernel-3.2-OFED.3.2.2.0.0.1.g378ff02.5.sles11sp4.x86\_64.rpm; mlnx-ofa\_kernel-kmp-default-3.2\_3.0.101\_63-

OFED.3.2.2.0.0.1.g378ff02.sles11sp4.x86\_64.rpm; mlnx-ofa\_kernel-kmp-xen-3.2\_3.0.101\_63-OFED.3.2.2.0.0.1.g378ff02.sles11sp4.x86\_64.rpm

#### **Fixes**

##### **Fixes in version 3.2 (A):**

- The RoCE user-space library RPM "mlnx-ofa\_kernel" failed to install when OS distribution RPMs in "infiniband support" group were already installed.
- The RoCE driver upgrade didnt work properly when a previous version of MLNX-EN driver was already installed. This resulted in Mellanox Ethernet ports not coming up.

##### **Fixes in version 3.2:**

- Set closest NUMA node as the default for Receive Side Scaling.
- ARP request packets destined for a proxy VXLAN interface were not handled correctly when GRO was enabled.

#### **Enhancements**

##### **HPE Mellanox RoCE driver version 3.2 contains the following changes and new features:**

- FCS scattering for Raw Packet Queue Pairs and Work Queues.
- Indication of L4 packet type on the receive side completions.
- Support CVLAN insertion for Work Queues

#### **Supported Devices and Features**

#### SUPPORTED KERNELS:

The kernels of SUSE LINUX Enterprise Server SP3 (AMD64/EM64T) supported by this binary rpm are:

3.0.101-63-default - (AMD64/EM64T) and future update kernels.

3.0.101-63-xen - (AMD64/EM64T) and future update kernels.

---

HPE Mellanox RoCE (RDMA over Converged Ethernet) Driver for SUSE LINUX Enterprise Server 12 (AMD64/EM64T)

Version: 3.2 (A) **(Recommended)**

Filename: mlnx-ofa\_kernel-3.2-OFED.3.2.2.0.0.1.g378ff02.5.sles12sp0.x86\_64.rpm; mlnx-ofa\_kernel-kmp-default-3.2\_k3.12.28\_4-

OFED.3.2.2.0.0.1.g378ff02.sles12sp0.x86\_64.rpm; mlnx-ofa\_kernel-kmp-xen-3.2\_k3.12.28\_4-OFED.3.2.2.0.0.1.g378ff02.sles12sp0.x86\_64.rpm

#### **Fixes**

##### **Fixes in version 3.2 (A):**

- The RoCE user-space library RPM "mlnx-ofa\_kernel" failed to install when OS distribution RPMs in "infiniband support" group were already installed.

The RoCE driver upgrade didnt work properly when a previous version of MLNX-EN driver was already installed. This resulted in Mellanox Ethernet ports not coming up.

#### **Fixes in version 3.2:**

- Set closest NUMA node as the default for Receive Side Scaling.
- ARP request packets destined for a proxy VXLAN interface were not handled correctly when GRO was enabled.

#### **Enhancements**

##### **HPE Mellanox RoCE driver version 3.2 contains the following changes and new features:**

- FCS scattering for Raw Packet Queue Pairs and Work Queues.
- Indication of L4 packet type on the receive side completions.
- Support CVLAN insertion for Work Queues

#### **Supported Devices and Features**

SUPPORTED KERNELS:

The kernels of SUSE LINUX Enterprise Server 12 (AMD64/EM64T) supported by this binary rpm are:

3.12.28-4-default - (AMD64/EM64T) and future update kernels.

3.12.28-4-xen - (AMD64/EM64T) and future update kernels.

---

HPE Mellanox RoCE (RDMA over Converged Ethernet) Driver for SUSE LINUX Enterprise Server 12 SP1 (AMD64/EM64T)

Version: 3.2 (A) **(Recommended)**

Filename: mlnx-ofa\_kernel-3.2-OFED.3.2.2.0.0.1.g378ff02.5.sles12sp1.x86\_64.rpm; mlnx-ofa\_kernel-kmp-default-3.2\_k3.12.49\_11-OFED.3.2.2.0.0.1.g378ff02.sles12sp1.x86\_64.rpm; mlnx-ofa\_kernel-kmp-xen-3.2\_k3.12.49\_11-OFED.3.2.2.0.0.1.g378ff02.sles12sp1.x86\_64.rpm

#### **Fixes**

##### **Fixes in version 3.2 (A):**

- The RoCE user-space library RPM "mlnx-ofa\_kernel" failed to install when OS distribution RPMs in "infiniband support" group were already installed.
- The RoCE driver upgrade didnt work properly when a previous version of MLNX-EN driver was already installed. This resulted in Mellanox Ethernet ports not coming up.

##### **Fixes in version 3.2:**

- Set closest NUMA node as the default for Receive Side Scaling.
- ARP request packets destined for a proxy VXLAN interface were not handled correctly when GRO was enabled.

#### **Enhancements**

##### **HPE Mellanox RoCE driver version 3.2 contains the following changes and new features:**

- FCS scattering for Raw Packet Queue Pairs and Work Queues.
- Indication of L4 packet type on the receive side completions.
- Support CVLAN insertion for Work Queues

#### **Supported Devices and Features**



#### SUPPORTED KERNELS:

The kernels of SUSE LINUX Enterprise Server 12 SP1 (AMD64/EM64T) supported by this binary rpm are:

3.12.49-11-default - (AMD64/EM64T) and future update kernels.

3.12.49-11-xen - (AMD64/EM64T) and future update kernels.

---

HPE Network Configuration Utility for Windows Server 2008 R2

Version: 11.50.0.0 **(Optional)**

Filename: cp028184.exe

#### **Enhancements**

This product now supports the following network adapters:

- HP FlexFabric 10Gb 2-port 556FLR-SFP+ Adapter
- HPE FlexFabric 10Gb 2-port 556FLR-T Adapter
- HP Ethernet 10Gb 2-port 557SFP+ Adapter
- HP FlexFabric 20Gb 2-port 650FLB Adapter
- HP FlexFabric 20Gb 2-port 650M Adapter
- HP StoreFabric CN1200E Dual Port Converged Network Adapter
- HPE StoreFabric CN1200E-T Adapter

---

HPE Network Configuration Utility for Windows Server 2008 x64 Editions

Version: 11.50.0.0 **(Optional)**

Filename: cp028183.exe

#### **Enhancements**

This product now supports the following network adapters:

- HP FlexFabric 10Gb 2-port 556FLR-SFP+ Adapter
- HPE FlexFabric 10Gb 2-port 556FLR-T Adapter
- HP Ethernet 10Gb 2-port 557SFP+ Adapter
- HP FlexFabric 20Gb 2-port 650FLB Adapter
- HP FlexFabric 20Gb 2-port 650M Adapter
- HP StoreFabric CN1200E Dual Port Converged Network Adapter

---

HPE QLogic iSCSI Drivers for Red Hat Enterprise Linux 6 i686

Version: 5.04.01.12.00.00-3 **(Optional)**

Filename: hp-qlgc-docs-1.1.1-1.noarch.rpm; hp-qlgc-utils-1.3.0-1.noarch.rpm; kmod-hpqlgc-qla4xxx-5.04.01.12.00.00\_k0-3.rhel6u6.i686.rpm; kmod-hpqlgc-qla4xxx-5.04.01.12.00.00\_k0-3.rhel6u7.i686.rpm; README

#### **Important Note!**

HPE recommends the firmware provided in *HP QLogic P3P Online Firmware Upgrade Utility for Linux x86*, version 1.9.7, for use with these drivers.

#### **Enhancements**

A signature has been added to the kernel module (qla4xxx.ko) contained in this product.

## **Supported Devices and Features**

This software supports the following network adapters:

- HP FlexFabric 10Gb 2-port 526FLR-SFP+ Adapter
- HP CN1000Q Dual Port Converged Network Adapter

---

HPE QLogic iSCSI Drivers for Red Hat Enterprise Linux 6 x86\_64

Version: 5.04.01.12.00.00-3 **(Optional)**

Filename: hp-qlgc-docs-1.1.1-1.noarch.rpm; hp-qlgc-utils-1.3.0-1.noarch.rpm; kmod-hpqlgc-qla4xxx-5.04.01.12.00.00\_k0-3.rhel6u6.x86\_64.rpm; kmod-hpqlgc-qla4xxx-5.04.01.12.00.00\_k0-3.rhel6u7.x86\_64.rpm; README

### **Important Note!**

HPE recommends the firmware provided in *HP QLogic P3P Online Firmware Upgrade Utility for Linux x86\_64*, version 1.9.7, for use with these drivers.

### **Enhancements**

A signature has been added to the kernel module (qla4xxx.ko) contained in this product.

## **Supported Devices and Features**

This software supports the following network adapters:

- HP FlexFabric 10Gb 2-port 526FLR-SFP+ Adapter
- HP CN1000Q Dual Port Converged Network Adapter

---

HPE QLogic iSCSI Drivers for Red Hat Enterprise Linux 7 x86\_64

Version: 5.04.01.12.00.00-3 **(Optional)**

Filename: hp-qlgc-docs-1.1.1-1.noarch.rpm; hp-qlgc-utils-1.3.0-1.noarch.rpm; kmod-hpqlgc-qla4xxx-5.04.01.12.00.00\_k0-3.rhel7u1.x86\_64.rpm; kmod-hpqlgc-qla4xxx-5.04.01.12.00.00\_k0-3.rhel7u2.x86\_64.rpm; README

### **Important Note!**

HPE recommends the firmware provided in *HP QLogic P3P Online Firmware Upgrade Utility for Linux x86\_64*, version 1.9.7, for use with these drivers.

### **Enhancements**

A signature has been added to the kernel module (qla4xxx.ko) contained in this product.

## **Supported Devices and Features**

This software supports the following network adapters:

- HP FlexFabric 10Gb 2-port 526FLR-SFP+ Adapter
- HP CN1000Q Dual Port Converged Network Adapter

---

HPE QLogic iSCSI Drivers for SUSE Linux Enterprise Server 11 i586

Version: 5.04.01.12.00.00-5 **(Optional)**

Filename: hp-qlgc-docs-1.1.1-1.noarch.rpm; hp-qlgc-utils-1.3.0-1.noarch.rpm; hpqlgc-qla4xxx-kmp-default-5.04.01.12.00.00\_k0\_3.0.101\_63-5.sles11sp4.i586.rpm; hpqlgc-qla4xxx-kmp-default-5.04.01.12.00.00\_k0\_3.0.76\_0.11-5.sles11sp3.i586.rpm; hpqlgc-qla4xxx-kmp-pae-5.04.01.12.00.00\_k0\_3.0.101\_63-5.sles11sp4.i586.rpm; hpqlgc-qla4xxx-kmp-pae-5.04.01.12.00.00\_k0\_3.0.76\_0.11-5.sles11sp3.i586.rpm; hpqlgc-qla4xxx-kmp-xen-5.04.01.12.00.00\_k0\_3.0.101\_63-5.sles11sp4.i586.rpm; hpqlgc-qla4xxx-kmp-xen-5.04.01.12.00.00\_k0\_3.0.76\_0.11-5.sles11sp3.i586.rpm; README

### **Important Note!**

HPE recommends the firmware provided in *HP QLogic P3P Online Firmware Upgrade Utility for Linux x86*, version 1.9.7, for use with these drivers.

### **Enhancements**

A signature has been added to the kernel module (qla4xxx.ko) contained in this product.

### **Supported Devices and Features**

This software supports the following network adapters:

- HP FlexFabric 10Gb 2-port 526FLR-SFP+ Adapter
- HP CN1000Q Dual Port Converged Network Adapter

---

HPE QLogic iSCSI Drivers for SUSE Linux Enterprise Server 11 x86\_64

Version: 5.04.01.12.00.00-5 **(Optional)**

Filename: hp-qlgc-docs-1.1.1-1.noarch.rpm; hp-qlgc-utils-1.3.0-1.noarch.rpm; hpqlgc-qla4xxx-kmp-default-5.04.01.12.00.00\_k0\_3.0.101\_63-5.sles11sp4.x86\_64.rpm; hpqlgc-qla4xxx-kmp-default-5.04.01.12.00.00\_k0\_3.0.76\_0.11-5.sles11sp3.x86\_64.rpm; hpqlgc-qla4xxx-kmp-xen-5.04.01.12.00.00\_k0\_3.0.101\_63-5.sles11sp4.x86\_64.rpm; hpqlgc-qla4xxx-kmp-xen-5.04.01.12.00.00\_k0\_3.0.76\_0.11-5.sles11sp3.x86\_64.rpm; README

### **Important Note!**

HPE recommends the firmware provided in *HP QLogic P3P Online Firmware Upgrade Utility for Linux x86\_64*, version 1.9.7, for use with these drivers.

### **Enhancements**

A signature has been added to the kernel module (qla4xxx.ko) contained in this product.

### **Supported Devices and Features**

This software supports the following network adapters:

- HP FlexFabric 10Gb 2-port 526FLR-SFP+ Adapter
- HP CN1000Q Dual Port Converged Network Adapter

---

HPE QLogic iSCSI Drivers for SUSE Linux Enterprise Server 12 x86\_64

Version: 5.04.01.12.00.00-5 **(Optional)**

Filename: hp-qlgc-docs-1.1.1-1.noarch.rpm; hp-qlgc-utils-1.3.0-1.noarch.rpm; hpqlgc-qla4xxx-kmp-default-5.04.01.12.00.00\_k0\_k3.12.28\_4-5.sles12sp0.x86\_64.rpm; hpqlgc-qla4xxx-kmp-default-5.04.01.12.00.00\_k0\_k3.12.49\_11-5.sles12sp1.x86\_64.rpm; hpqlgc-qla4xxx-kmp-xen-5.04.01.12.00.00\_k0\_k3.12.28\_4-5.sles12sp0.x86\_64.rpm; hpqlgc-qla4xxx-kmp-xen-5.04.01.12.00.00\_k0\_k3.12.49\_11-5.sles12sp1.x86\_64.rpm; README

### **Important Note!**

HPE recommends the firmware provided in *HP QLogic P3P Online Firmware Upgrade Utility for Linux x86\_64*, version 1.9.7, for use with these drivers.

### **Enhancements**

A signature has been added to the kernel module (qla4xxx.ko) contained in this product.

### **Supported Devices and Features**

This software supports the following network adapters:

- HP FlexFabric 10Gb 2-port 526FLR-SFP+ Adapter
- HP CN1000Q Dual Port Converged Network Adapter

---

HPE QLogic nx\_nic Drivers for Red Hat Enterprise Linux 6 i686

Version: 4.0.596.1-6 (B) **(Optional)**

Filename: hp-nx\_nic-docs-1.0.0-4.noarch.rpm; hp-nx\_nic-tools-4.0.596.1-4.noarch.rpm; kmod-hpqlgc-nx\_nic-4.0.596.1-4.rhel6u6.i686.rpm; kmod-hpqlgc-nx\_nic-4.0.596.1-6.rhel6u7.i686.rpm; README

### **Important Note!**

HP recommends the firmware provided in *HP QLogic P3 Online Firmware Upgrade Utility for Linux x86*, version 5.6.10, for use with these drivers.

### **Enhancements**

This product is now HPE signed.

### **Supported Devices and Features**

This software supports the following network adapters:

- HP NC375i Integrated Quad Port Multifunction Gigabit Server Adapter

---

HPE QLogic nx\_nic Drivers for Red Hat Enterprise Linux 6 x86\_64

Version: 4.0.596.1-6 (B) **(Optional)**

Filename: hp-nx\_nic-docs-1.0.0-4.noarch.rpm; hp-nx\_nic-tools-4.0.596.1-4.noarch.rpm; kmod-hpqlgc-nx\_nic-4.0.596.1-4.rhel6u6.x86\_64.rpm; kmod-hpqlgc-nx\_nic-4.0.596.1-6.rhel6u7.x86\_64.rpm; README

### **Important Note!**

HP recommends the firmware provided in *HP QLogic P3 Online Firmware Upgrade Utility for Linux x86\_64*, version 5.6.10, for use with these drivers.

## **Enhancements**

This product is now HPE signed.

## **Supported Devices and Features**

This software supports the following network adapters:

- HP NC375i Integrated Quad Port Multifunction Gigabit Server Adapter

---

HPE QLogic nx\_nic Drivers for Red Hat Enterprise Linux 7 x86\_64

Version: 4.0.596.1-2 (B) **(Optional)**

Filename: hp-nx\_nic-docs-1.0.0-4.noarch.rpm; hp-nx\_nic-tools-4.0.596.1-4.noarch.rpm; kmod-hpqlgc-nx\_nic-4.0.596.1-2.rhel7u1.x86\_64.rpm; kmod-hpqlgc-nx\_nic-4.0.596.1-2.rhel7u2.x86\_64.rpm; README

## **Important Note!**

HPE recommends the firmware provided in *HP QLogic P3 Online Firmware Upgrade Utility for Linux x86\_84*, version 5.6.7, for use with these drivers.

## **Enhancements**

This driver now supports Red Hat Enterprise Linux 7 Update 2.

## **Supported Devices and Features**

This software supports the following network adapters:

- HP NC375i Integrated Quad Port Multifunction Gigabit Server Adapter

---

HPE QLogic nx\_nic Drivers for SUSE Linux Enterprise Server 12 x86\_64

Version: 4.0.596.1-2 **(Optional)**

Filename: hp-nx\_nic-docs-1.0.0-4.noarch.rpm; hp-nx\_nic-tools-4.0.596.1-4.noarch.rpm; hpqlgc-nx\_nic-kmp-default-4.0.596.1\_k3.12.28\_4-4.sles12sp0.x86\_64.rpm; hpqlgc-nx\_nic-kmp-default-4.0.596.1\_k3.12.49\_11-2.sles12sp1.x86\_64.rpm; hpqlgc-nx\_nic-kmp-xen-4.0.596.1\_k3.12.28\_4-4.sles12sp0.x86\_64.rpm; hpqlgc-nx\_nic-kmp-xen-4.0.596.1\_k3.12.49\_11-2.sles12sp1.x86\_64.rpm; README

## **Important Note!**

HPE recommends the firmware provided in *HP QLogic P3 Online Firmware Upgrade Utility for Linux x86\_84*, version 5.6.7, for use with these drivers.

## **Enhancements**

This driver now supports SUSE Linux Enterprise Server 12 SP1.

## **Supported Devices and Features**

This software supports the following network adapters:

- HP NC375i Integrated Quad Port Multifunction Gigabit Server Adapter

---

HPE QLogic NX2 1/10/20 GbE Multifunction Drivers for Red Hat Enterprise Linux 6 i686

Version: 7.14.07-1 **(Optional)**

Filename: kmod-netxtreme2-7.14.07-1.rhel6u7.i686.rpm; kmod-netxtreme2-7.14.07-1.rhel6u8.i686.rpm; README

### **Important Note!**

HPE recommends the firmware provided in *HPE QLogic NX2 Online Firmware Upgrade Utility for Linux x86*, version 2.18.44 or later, for use with these drivers.

### **Fixes**

This product corrects received cyclic redundancy check (RX CRC) errors that occur for 1Gb jumbo frames.

This product addresses an error that occurs when transmitting packets tagged with two VLANs.

This product addresses an issue where offloading is unexpectedly disabled when VXLAN is enabled for both IPv4 and IPv6.

This product addresses an issue where RSS for a VXLAN packet fails.

### **Enhancements**

This product now supports Red Hat Enterprise Linux 6 Update 8.

### **Supported Devices and Features**

These drivers support the following network adapters:

- HP NC382i Integrated Dual Port Multifunction Gigabit Server Adapter
- HP Ethernet 10Gb 2-port 530FLR-SFP+ Adapter
- HP Ethernet 10Gb 2-port 530FLB Adapter
- HP Ethernet 10Gb 2-port 530M Adapter
- HP Ethernet 10Gb 2-port 530SFP+ Adapter
- HP Ethernet 10Gb 2-port 530T Adapter
- HP NC532i Dual Port 10GbE Multifunction BL-c Adapter
- HP NC532m Dual Port 10GbE Multifunction BL-c Adapter
- HP Ethernet 10Gb 2-port 533FLR-T Adapter
- HP FlexFabric 10Gb 2-port 534FLB Adapter
- HP FlexFabric 10Gb 2-port 534FLR-SFP+ Adapter
- HP FlexFabric 10Gb 2-port 534M Adapter
- HP FlexFabric 20Gb 2-port 630FLB Adapter
- HP FlexFabric 20Gb 2-port 630M Adapter
- HP StoreFabric CN1100R Dual Port Converged Network Adapter

---

HPE QLogic NX2 1/10/20 GbE Multifunction Drivers for Red Hat Enterprise Linux 6 x86\_64

Version: 7.14.07-1 **(Optional)**

Filename: kmod-netxtreme2-7.14.07-1.rhel6u7.x86\_64.rpm; kmod-netxtreme2-7.14.07-1.rhel6u8.x86\_64.rpm; README

### **Important Note!**

HPE recommends the firmware provided in *HPE QLogic NX2 Online Firmware Upgrade Utility for Linux x86\_64*, version 2.18.44 or later, for use with these drivers.

## **Enhancements**

This product now supports Red Hat Enterprise Linux 6 Update 8.

This product now supports the following network adapters:

- HPE Synergy 3820C 10/20Gb Converged Network Adapter
- HPE Synergy 10Gb 2-port 2820C Converged Network Adapter

## **Supported Devices and Features**

These drivers support the following network adapters:

- HP NC382i Integrated Dual Port Multifunction Gigabit Server Adapter
- HP Ethernet 10Gb 2-port 530FLR-SFP+ Adapter
- HP Ethernet 10Gb 2-port 530FLB Adapter
- HP Ethernet 10Gb 2-port 530M Adapter
- HP Ethernet 10Gb 2-port 530SFP+ Adapter
- HP Ethernet 10Gb 2-port 530T Adapter
- HP NC532i Dual Port 10GbE Multifunction BL-c Adapter
- HP NC532m Dual Port 10GbE Multifunction BL-c Adapter
- HP Ethernet 10Gb 2-port 533FLR-T Adapter
- HP FlexFabric 10Gb 2-port 534FLB Adapter
- HP FlexFabric 10Gb 2-port 534FLR-SFP+ Adapter
- HP FlexFabric 10Gb 2-port 534M Adapter
- HP FlexFabric 10Gb 2-port 536FLB Adapter
- HPE FlexFabric 10Gb 4-port 536FLR-T Adapter
- HP FlexFabric 20Gb 2-port 630FLB Adapter
- HP FlexFabric 20Gb 2-port 630M Adapter
- HP StoreFabric CN1100R Dual Port Converged Network Adapter
- HPE StoreFabric CN1100R-T Converged Network Adapter
- HPE Synergy 10Gb 2820C Ethernet Adapter
- HPE Synergy 3820C 10/20Gb Converged Network Adapter

---

HPE QLogic NX2 1/10/20 GbE Multifunction Drivers for Red Hat Enterprise Linux 7 x86\_64

Version: 7.14.07-1 **(Optional)**

Filename: kmod-netxtreme2-7.14.07-1.rhel7u1.x86\_64.rpm; kmod-netxtreme2-7.14.07-1.rhel7u2.x86\_64.rpm; README

## **Important Note!**

HPE recommends the firmware provided in *HPE QLogic NX2 Online Firmware Upgrade Utility for Linux x86\_64*, version 2.18.44 or later, for use with these drivers.

## **Enhancements**

This product now supports the following network adapters:

- HPE Synergy 3820C 10/20Gb Converged Network Adapter
- HPE Synergy 10Gb 2-port 2820C Converged Network Adapter

## **Supported Devices and Features**

These drivers support the following network adapters:

- HP NC382i Integrated Dual Port Multifunction Gigabit Server Adapter
- HP Ethernet 10Gb 2-port 530FLR-SFP+ Adapter
- HP Ethernet 10Gb 2-port 530FLB Adapter
- HP Ethernet 10Gb 2-port 530M Adapter
- HP Ethernet 10Gb 2-port 530SFP+ Adapter
- HP Ethernet 10Gb 2-port 530T Adapter
- HP NC532i Dual Port 10GbE Multifunction BL-c Adapter
- HP NC532m Dual Port 10GbE Multifunction BL-c Adapter
- HP Ethernet 10Gb 2-port 533FLR-T Adapter
- HP FlexFabric 10Gb 2-port 534FLB Adapter
- HP FlexFabric 10Gb 2-port 534FLR-SFP+ Adapter
- HP FlexFabric 10Gb 2-port 534M Adapter
- HP FlexFabric 10Gb 2-port 536FLB Adapter
- HPE FlexFabric 10Gb 4-port 536FLR-T Adapter
- HP FlexFabric 20Gb 2-port 630FLB Adapter
- HP FlexFabric 20Gb 2-port 630M Adapter
- HP StoreFabric CN1100R Dual Port Converged Network Adapter
- HPE StoreFabric CN1100R-T Converged Network Adapter
- HPE Synergy 10Gb 2820C Ethernet Adapter
- HPE Synergy 3820C 10/20Gb Converged Network Adapter

---

HPE QLogic NX2 1/10/20 GbE Multifunction Drivers for SUSE Linux Enterprise Server 11 i586

Version: 7.14.07-1 (**Optional**)

Filename: netxtreme2-kmp-default-7.14.07\_3.0.101\_63-1.sles11sp4.i586.rpm; netxtreme2-kmp-default-7.14.07\_3.0.76\_0.11-1.sles11sp3.i586.rpm; netxtreme2-kmp-pae-7.14.07\_3.0.101\_63-1.sles11sp4.i586.rpm; netxtreme2-kmp-pae-7.14.07\_3.0.76\_0.11-1.sles11sp3.i586.rpm; netxtreme2-kmp-xen-7.14.07\_3.0.101\_63-1.sles11sp4.i586.rpm; netxtreme2-kmp-xen-7.14.07\_3.0.76\_0.11-1.sles11sp3.i586.rpm; README

### **Important Note!**

HPE recommends the firmware provided in *HPE QLogic NX2 Online Firmware Upgrade Utility for Linux x86*, version 2.18.44 or later, for use with these drivers.

### **Fixes**

This product corrects received cyclic redundancy check (RX CRC) errors that occur for 1Gb jumbo frames.

This product addresses an error that occurs when transmitting packets tagged with two VLANs.

This product addresses an issue where offloading is unexpectedly disabled when VXLAN is enabled for both IPv4 and IPv6.

This product addresses an issue where RSS for a VXLAN packet fails.

## **Supported Devices and Features**

These drivers support the following network adapters:

- HP NC382i Integrated Dual Port Multifunction Gigabit Server Adapter
- HP Ethernet 10Gb 2-port 530FLR-SFP+ Adapter



- HP Ethernet 10Gb 2-port 530FLB Adapter
- HP Ethernet 10Gb 2-port 530M Adapter
- HP Ethernet 10Gb 2-port 530SFP+ Adapter
- HP Ethernet 10Gb 2-port 530T Adapter
- HP NC532i Dual Port 10GbE Multifunction BL-c Adapter
- HP NC532m Dual Port 10GbE Multifunction BL-c Adapter
- HP Ethernet 10Gb 2-port 533FLR-T Adapter
- HP FlexFabric 10Gb 2-port 534FLB Adapter
- HP FlexFabric 10Gb 2-port 534FLR-SFP+ Adapter
- HP FlexFabric 10Gb 2-port 534M Adapter
- HP FlexFabric 20Gb 2-port 630FLB Adapter
- HP FlexFabric 20Gb 2-port 630M Adapter
- HP StoreFabric CN1100R Dual Port Converged Network Adapter

---

HPE QLogic NX2 1/10/20 GbE Multifunction Drivers for SUSE Linux Enterprise Server 11 x86\_64

Version: 7.14.07-1 **(Optional)**

Filename: netxtreme2-kmp-default-7.14.07\_3.0.101\_63-1.sles11sp4.x86\_64.rpm; netxtreme2-kmp-default-7.14.07\_3.0.76\_0.11-1.sles11sp3.x86\_64.rpm; netxtreme2-kmp-xen-7.14.07\_3.0.101\_63-1.sles11sp4.x86\_64.rpm; netxtreme2-kmp-xen-7.14.07\_3.0.76\_0.11-1.sles11sp3.x86\_64.rpm; README

### **Important Note!**

HPE recommends the firmware provided in *HPE QLogic NX2 Online Firmware Upgrade Utility for Linux x86\_64*, version 2.18.44 or later, for use with these drivers.

### **Enhancements**

This product now supports the following network adapters:

- HPE Synergy 3820C 10/20Gb Converged Network Adapter
- HPE Synergy 10Gb 2-port 2820C Converged Network Adapter

### **Supported Devices and Features**

These drivers support the following network adapters:

- HP NC382i Integrated Dual Port Multifunction Gigabit Server Adapter
- HP Ethernet 10Gb 2-port 530FLR-SFP+ Adapter
- HP Ethernet 10Gb 2-port 530FLB Adapter
- HP Ethernet 10Gb 2-port 530M Adapter
- HP Ethernet 10Gb 2-port 530SFP+ Adapter
- HP Ethernet 10Gb 2-port 530T Adapter
- HP NC532i Dual Port 10GbE Multifunction BL-c Adapter
- HP NC532m Dual Port 10GbE Multifunction BL-c Adapter
- HP Ethernet 10Gb 2-port 533FLR-T Adapter
- HP FlexFabric 10Gb 2-port 534FLB Adapter
- HP FlexFabric 10Gb 2-port 534FLR-SFP+ Adapter
- HP FlexFabric 10Gb 2-port 534M Adapter
- HP FlexFabric 10Gb 2-port 536FLB Adapter
- HPE FlexFabric 10Gb 4-port 536FLR-T Adapter
- HP FlexFabric 20Gb 2-port 630FLB Adapter
- HP FlexFabric 20Gb 2-port 630M Adapter

- HP StoreFabric CN1100R Dual Port Converged Network Adapter
- HPE StoreFabric CN1100R-T Converged Network Adapter
- HPE Synergy 10Gb 2820C Ethernet Adapter
- HPE Synergy 3820C 10/20Gb Converged Network Adapter

---

HPE QLogic NX2 1/10/20 GbE Multifunction Drivers for SUSE Linux Enterprise Server 12 x86\_64

Version: 7.14.07-1 **(Optional)**

Filename: netxtreme2-kmp-default-7.14.07\_k3.12.28\_4-1.sles12sp0.x86\_64.rpm; netxtreme2-kmp-default-7.14.07\_k3.12.49\_11-1.sles12sp1.x86\_64.rpm; netxtreme2-kmp-xen-7.14.07\_k3.12.28\_4-1.sles12sp0.x86\_64.rpm; netxtreme2-kmp-xen-7.14.07\_k3.12.49\_11-1.sles12sp1.x86\_64.rpm; README

### **Important Note!**

HPE recommends the firmware provided in *HPE QLogic NX2 Online Firmware Upgrade Utility for Linux x86\_64*, version 2.18.44 or later, for use with these drivers.

### **Enhancements**

This product now supports the following network adapters:

- HPE Synergy 3820C 10/20Gb Converged Network Adapter
- HPE Synergy 10Gb 2-port 2820C Converged Network Adapter

### **Supported Devices and Features**

These drivers support the following network adapters:

- HP NC382i Integrated Dual Port Multifunction Gigabit Server Adapter
- HP Ethernet 10Gb 2-port 530FLR-SFP+ Adapter
- HP Ethernet 10Gb 2-port 530FLB Adapter
- HP Ethernet 10Gb 2-port 530M Adapter
- HP Ethernet 10Gb 2-port 530SFP+ Adapter
- HP Ethernet 10Gb 2-port 530T Adapter
- HP NC532i Dual Port 10GbE Multifunction BL-c Adapter
- HP NC532m Dual Port 10GbE Multifunction BL-c Adapter
- HP Ethernet 10Gb 2-port 533FLR-T Adapter
- HP FlexFabric 10Gb 2-port 534FLB Adapter
- HP FlexFabric 10Gb 2-port 534FLR-SFP+ Adapter
- HP FlexFabric 10Gb 2-port 534M Adapter
- HP FlexFabric 10Gb 2-port 536FLB Adapter
- HPE FlexFabric 10Gb 4-port 536FLR-T Adapter
- HP FlexFabric 20Gb 2-port 630FLB Adapter
- HP FlexFabric 20Gb 2-port 630M Adapter
- HP StoreFabric CN1100R Dual Port Converged Network Adapter
- HPE StoreFabric CN1100R-T Converged Network Adapter
- HPE Synergy 10Gb 2820C Ethernet Adapter
- HPE Synergy 3820C 10/20Gb Converged Network Adapter

---

HPE QLogic NX2 1/10/20 GbE Multifunction Drivers for VMware vSphere 5.5

Version: 2016.10.07 **(Optional)**

Filename: cp028027.zip

### **Important Note!**

This component is intended to be used by HPE applications. It is a zip file that contains the same driver deliverable available from the vmware.com and the HPE vibsdepot.hp.com webpages, plus an HPE specific CP0xxxxx.xml file.

HPE recommends the firmware provided in *HPE QLogic NX2 Online Firmware Upgrade Utility for VMware*, version 1.12.43 or later, for use with this driver.

### **Enhancements**

This product now supports the following network adapters:

- HPE Synergy 3820C 10/20Gb Converged Network Adapter
- HPE Synergy 10Gb 2-port 2820C Converged Network Adapter

### **Supported Devices and Features**

These drivers support the following network adapters:

- HP NC382i Integrated Dual Port Multifunction Gigabit Server Adapter
- HP Ethernet 10Gb 2-port 530FLR-SFP+ Adapter
- HP Ethernet 10Gb 2-port 530FLB Adapter
- HP Ethernet 10Gb 2-port 530M Adapter
- HP Ethernet 10Gb 2-port 530SFP+ Adapter
- HP Ethernet 10Gb 2-port 530T Adapter
- HP NC532i Dual Port 10GbE Multifunction BL-c Adapter
- HP NC532m Dual Port 10GbE Multifunction BL-c Adapter
- HP Ethernet 10Gb 2-port 533FLR-T Adapter
- HP FlexFabric 10Gb 2-port 534FLB Adapter
- HP FlexFabric 10Gb 2-port 534FLR-SFP+ Adapter
- HP FlexFabric 10Gb 2-port 534M Adapter
- HP FlexFabric 10Gb 2-port 536FLB Adapter
- HPE FlexFabric 10Gb 4-port 536FLR-T Adapter
- HP FlexFabric 20Gb 2-port 630FLB Adapter
- HP FlexFabric 20Gb 2-port 630M Adapter
- HP FlexFabric 20Gb 2-port 631M Adapter
- HP StoreFabric CN1100R Dual Port Converged Network Adapter
- HPE StoreFabric CN1100R-T Dual Port Converged Network Adapter
- HPE Synergy 10Gb 2-port 2820C Converged Network Adapter
- HPE Synergy 3820C 10/20Gb Converged Network Adapter

---

HPE QLogic NX2 1/10/20 GbE Multifunction Drivers for VMware vSphere 6.0

Version: 2016.10.07 **(Optional)**

Filename: cp028028.zip

### **Important Note!**

This component is intended to be used by HPE applications. It is a zip file that contains the same driver deliverable available from the vmware.com and the HPE vibsdepot.hp.com webpages, plus an HPE specific CP0xxxxx.xml file.

HPE recommends the firmware provided in *HPE QLogic NX2 Online Firmware Upgrade Utility for VMware*, version 1.12.43 or later, for use with this driver.

## **Enhancements**

This product now supports the following network adapters:

- HPE Synergy 3820C 10/20Gb Converged Network Adapter
- HPE Synergy 10Gb 2-port 2820C Converged Network Adapter

## **Supported Devices and Features**

These drivers support the following network adapters:

- HP NC382i Integrated Dual Port Multifunction Gigabit Server Adapter
- HP Ethernet 10Gb 2-port 530FLR-SFP+ Adapter
- HP Ethernet 10Gb 2-port 530FLB Adapter
- HP Ethernet 10Gb 2-port 530M Adapter
- HP Ethernet 10Gb 2-port 530SFP+ Adapter
- HP Ethernet 10Gb 2-port 530T Adapter
- HP NC532i Dual Port 10GbE Multifunction BL-c Adapter
- HP NC532m Dual Port 10GbE Multifunction BL-c Adapter
- HP Ethernet 10Gb 2-port 533FLR-T Adapter
- HP FlexFabric 10Gb 2-port 534FLB Adapter
- HP FlexFabric 10Gb 2-port 534FLR-SFP+ Adapter
- HP FlexFabric 10Gb 2-port 534M Adapter
- HP FlexFabric 10Gb 2-port 536FLB Adapter
- HP FlexFabric 20Gb 2-port 630FLB Adapter
- HP FlexFabric 20Gb 2-port 630M Adapter
- HP FlexFabric 20Gb 2-port 631M Adapter
- HP StoreFabric CN1100R Dual Port Converged Network Adapter
- HPE StoreFabric CN1100R-T Dual Port Converged Network Adapter
- HPE Synergy 10Gb 2820C Ethernet Adapter
- HPE Synergy 3820C 10/20Gb Converged Network Adapter

---

HPE QLogic NX2 10/20GbE Multifunction Drivers for Windows Server 2008

Version: 7.13.104.0 **(Optional)**

Filename: cp030841.exe

## **Important Note!**

HPE recommends the firmware provided in *HPE QLogic NX2 Online Firmware Upgrade Utility for Windows Server 2008*, version 5.0.0.24 or later, for use with these drivers.

## **Fixes**

This product addresses an issue which results in a system crash when trying to power on virtual machines with the maximum number of VMQs configured.

This product addresses an issue which results in a system hang after configuration of VMQ adapters.

This product addresses an issue where a system crash occurs on a Virtual Machine after rebooting to recover a failing virtual function device.

## **Supported Devices and Features**

This driver supports the following network adapters:

- HP NC532i Dual Port 10GbE Multifunction BL-c Adapter
- HP NC532m Dual Port 10GbE Multifunction BL-c Adapter
- HP Flex-10 10Gb 2-port 530FLB Adapter
- HP Ethernet 10Gb 2-port 530FLR-SFP+ Adapter
- HP Flex-10 10Gb 2-port 530M Adapter
- HP Ethernet 10Gb 2-port 530SFP+ Adapter
- HP Ethernet 10Gb 2-port 530T Adapter
- HP Ethernet 10Gb 2-port 533FLR-T Adapter
- HP FlexFabric 10Gb 2-port 534FLB Adapter
- HP FlexFabric 10Gb 2-port 534FLR-SFP+ Adapter
- HP FlexFabric 10Gb 2-port 534M Adapter
- HP FlexFabric 20Gb 2-port 630FLB Adapter
- HP FlexFabric 20Gb 2-port 630M Adapter
- HP StoreFabric CN1100R Dual Port Converged Network Adapter

---

HPE QLogic NX2 10/20GbE Multifunction Drivers for Windows Server x64 Editions

Version: 7.13.104.0 (**Optional**)

Filename: cp030253.exe

### **Important Note!**

HP recommends the firmware provided in *HPE QLogic NX2 Online Firmware Upgrade Utility for Windows Server x64 Editions*, version 5.0.0.24 or later, for use with these drivers.

### **Enhancements**

This product now supports Windows Server 2016.

This product now supports the following network adapters:

- HPE Synergy 3820C 10/20Gb Converged Network Adapter
- HPE Synergy 10Gb 2-port 2820C Converged Network Adapter

### **Supported Devices and Features**

This driver supports the following network adapters:

- HP Flex-10 10Gb 2-port 530FLB Adapter
- HP Ethernet 10Gb 2-port 530FLR-SFP+ Adapter
- HP Flex-10 10Gb 2-port 530M Adapter
- HP Ethernet 10Gb 2-port 530SFP+ Adapter
- HP Ethernet 10Gb 2-port 530T Adapter
- HP NC532i Dual Port 10GbE Multifunction BL-c Adapter
- HP NC532m Dual Port 10GbE Multifunction BL-c Adapter
- HP Ethernet 10Gb 2-port 533FLR-T Adapter
- HP FlexFabric 10Gb 2-port 534FLB Adapter
- HP FlexFabric 10Gb 2-port 534FLR-SFP+ Adapter
- HP FlexFabric 10Gb 2-port 534M Adapter
- HP FlexFabric 10Gb 2-port 536FLB Adapter
- HPE FlexFabric 10Gb 4-port 536FLR-T Adapter

- HP FlexFabric 20Gb 2-port 630FLB Adapter
- HP FlexFabric 20Gb 2-port 630M Adapter
- HP StoreFabric CN1100R Dual Port Converged Network Adapter
- HPE StoreFabric CN1100R-T Converged Network Adapter
- HPE Synergy 10Gb 2820C Ethernet Adapter
- HPE Synergy 3820C 10/20Gb Converged Network Adapter

---

HPE QLogic NX2 Linux iSCSI Offload IO Daemon for Red Hat Enterprise Linux 6 Update 7 i686

Version: 2.11.4.0-2 (B) **(Optional)**

Filename: iscsiui0-2.11.4.0-2.rhel6u7.i686.rpm

### **Enhancements**

This product is now HPE signed.

### **Supported Devices and Features**

This product supports the following network adapters:

- HP NC382i Integrated Dual Port Multifunction Gigabit Server Adapter
- HP Flex-10 10Gb 2-port 530FLB Adapter
- HP Ethernet 10Gb 2-port 530FLR-SFP+ Adapter
- HP Flex-10 10Gb 2-port 530M Adapter
- HP Ethernet 10Gb 2-port 530SFP+ Adapter
- HP Ethernet 10Gb 2-port 530T Adapter
- HP NC532m Dual Port 10GbE Multifunction BL-c Adapter
- HP FlexFabric 10Gb 2-port 533FLR-T Adapter
- HP FlexFabric 10Gb 2-port 534FLB Adapter
- HP FlexFabric 10Gb 2-port 534FLR-SFP+ Adapter
- HP FlexFabric 10Gb 2-port 534M Adapter
- HP FlexFabric 20Gb 2-port 630FLB Adapter
- HP FlexFabric 20Gb 2-port 630M Adapter
- HP StoreFabric CN1100R Dual Port Converged Network Adapter

---

HPE QLogic NX2 Linux iSCSI Offload IO Daemon for Red Hat Enterprise Linux 6 Update 7 x86\_64

Version: 2.11.4.0-2 (C) **(Optional)**

Filename: iscsiui0-2.11.4.0-2.rhel6u7.x86\_64.rpm

### **Enhancements**

This product now supports the following network adapters:

- HPE FlexFabric 10Gb 4-port 536FLR-T Adapter
- HPE Synergy 10Gb 2-port 2820C Converged Network Adapter
- HPE Synergy 3820C 10/20Gb Converged Network Adapter

### **Supported Devices and Features**

This product supports the following network adapters:

- HP NC382i Integrated Dual Port Multifunction Gigabit Server Adapter

- HP Flex-10 10Gb 2-port 530FLB Adapter
- HP Ethernet 10Gb 2-port 530FLR-SFP+ Adapter
- HP Flex-10 10Gb 2-port 530M Adapter
- HP Ethernet 10Gb 2-port 530SFP+ Adapter
- HP Ethernet 10Gb 2-port 530T Adapter
- HP NC532m Dual Port 10GbE Multifunction BL-c Adapter
- HP FlexFabric 10Gb 2-port 533FLR-T Adapter
- HP FlexFabric 10Gb 2-port 534FLB Adapter
- HP FlexFabric 10Gb 2-port 534FLR-SFP+ Adapter
- HP FlexFabric 10Gb 2-port 534M Adapter
- HP FlexFabric 10Gb 2-port 536FLB Adapter
- HPE FlexFabric 10Gb 4-port 536FLR-T Adapter
- HP FlexFabric 20Gb 2-port 630FLB Adapter
- HP FlexFabric 20Gb 2-port 630M Adapter
- HP StoreFabric CN1100R Dual Port Converged Network Adapter
- HPE StoreFabric CN1100R-T Converged Network Adapter
- HPE Synergy 10Gb 2-port 2820C Converged Network Adapter
- HPE Synergy 3820C 10/20Gb Converged Network Adapter

---

HPE QLogic NX2 Linux iSCSI Offload IO Daemon for Red Hat Enterprise Linux 6 Update 8 i686

Version: 2.11.4.1-1 **(Optional)**

Filename: iscsiui0-2.11.4.1-1.rhel6u8.i686.rpm

### **Enhancements**

Initial release.

### **Supported Devices and Features**

This product supports the following network adapters:

- HP NC382i Integrated Dual Port Multifunction Gigabit Server Adapter
- HP Flex-10 10Gb 2-port 530FLB Adapter
- HP Ethernet 10Gb 2-port 530FLR-SFP+ Adapter
- HP Flex-10 10Gb 2-port 530M Adapter
- HP Ethernet 10Gb 2-port 530SFP+ Adapter
- HP Ethernet 10Gb 2-port 530T Adapter
- HP NC532m Dual Port 10GbE Multifunction BL-c Adapter
- HP FlexFabric 10Gb 2-port 533FLR-T Adapter
- HP FlexFabric 10Gb 2-port 534FLB Adapter
- HP FlexFabric 10Gb 2-port 534FLR-SFP+ Adapter
- HP FlexFabric 10Gb 2-port 534M Adapter
- HP FlexFabric 20Gb 2-port 630FLB Adapter
- HP FlexFabric 20Gb 2-port 630M Adapter
- HP StoreFabric CN1100R Dual Port Converged Network Adapter

---

HPE QLogic NX2 Linux iSCSI Offload IO Daemon for Red Hat Enterprise Linux 6 Update 8 x86\_64

Version: 2.11.4.1-1 (B) **(Optional)**

Filename: iscsiui0-2.11.4.1-1.rhel6u8.x86\_64.rpm

### **Enhancements**

This product now supports the following network adapters:

- HPE FlexFabric 10Gb 4-port 536FLR-T Adapter
- HPE Synergy 10Gb 2-port 2820C Converged Network Adapter
- HPE Synergy 3820C 10/20Gb Converged Network Adapter

### **Supported Devices and Features**

This product supports the following network adapters:

- HP NC382i Integrated Dual Port Multifunction Gigabit Server Adapter
- HP Flex-10 10Gb 2-port 530FLB Adapter
- HP Ethernet 10Gb 2-port 530FLR-SFP+ Adapter
- HP Flex-10 10Gb 2-port 530M Adapter
- HP Ethernet 10Gb 2-port 530SFP+ Adapter
- HP Ethernet 10Gb 2-port 530T Adapter
- HP NC532m Dual Port 10GbE Multifunction BL-c Adapter
- HP FlexFabric 10Gb 2-port 533FLR-T Adapter
- HP FlexFabric 10Gb 2-port 534FLB Adapter
- HP FlexFabric 10Gb 2-port 534FLR-SFP+ Adapter
- HP FlexFabric 10Gb 2-port 534M Adapter
- HP FlexFabric 10Gb 2-port 536FLB Adapter
- HPE FlexFabric 10Gb 4-port 536FLR-T Adapter
- HP FlexFabric 20Gb 2-port 630FLB Adapter
- HP FlexFabric 20Gb 2-port 630M Adapter
- HP StoreFabric CN1100R Dual Port Converged Network Adapter
- HPE StoreFabric CN1100R-T Converged Network Adapter
- HPE Synergy 10Gb 2-port 2820C Converged Network Adapter
- HPE Synergy 3820C 10/20Gb Converged Network Adapter

---

HPE QLogic NX2 Linux iSCSI Offload IO Daemon for Red Hat Enterprise Linux 7 Update 1 x86\_64

Version: 2.11.4.0-2 (C) **(Optional)**

Filename: iscsiui0-2.11.4.0-2.rhel7u1.x86\_64.rpm

### **Enhancements**

This product now supports the following network adapters:

- HPE FlexFabric 10Gb 4-port 536FLR-T Adapter
- HPE Synergy 10Gb 2-port 2820C Converged Network Adapter
- HPE Synergy 3820C 10/20Gb Converged Network Adapter

### **Supported Devices and Features**

This product supports the following network adapters:

- HP NC382i Integrated Dual Port Multifunction Gigabit Server Adapter
- HP Flex-10 10Gb 2-port 530FLB Adapter
- HP Ethernet 10Gb 2-port 530FLR-SFP+ Adapter
- HP Flex-10 10Gb 2-port 530M Adapter
- HP Ethernet 10Gb 2-port 530SFP+ Adapter
- HP Ethernet 10Gb 2-port 530T Adapter



- HP NC532m Dual Port 10GbE Multifunction BL-c Adapter
- HP FlexFabric 10Gb 2-port 533FLR-T Adapter
- HP FlexFabric 10Gb 2-port 534FLB Adapter
- HP FlexFabric 10Gb 2-port 534FLR-SFP+ Adapter
- HP FlexFabric 10Gb 2-port 534M Adapter
- HP FlexFabric 10Gb 2-port 536FLB Adapter
- HPE FlexFabric 10Gb 4-port 536FLR-T Adapter
- HP FlexFabric 20Gb 2-port 630FLB Adapter
- HP FlexFabric 20Gb 2-port 630M Adapter
- HP StoreFabric CN1100R Dual Port Converged Network Adapter
- HPE StoreFabric CN1100R-T Converged Network Adapter
- HPE Synergy 10Gb 2-port 2820C Converged Network Adapter
- HPE Synergy 3820C 10/20Gb Converged Network Adapter

---

HPE QLogic NX2 Linux iSCSI Offload IO Daemon for Red Hat Enterprise Linux 7 Update 2 x86\_64

Version: 2.11.4.0-2 (C) **(Optional)**

Filename: iscsiui0-2.11.4.0-2.rhel7u2.x86\_64.rpm

### **Enhancements**

This product now supports the following network adapters:

- HPE FlexFabric 10Gb 4-port 536FLR-T Adapter
- HPE Synergy 10Gb 2-port 2820C Converged Network Adapter
- HPE Synergy 3820C 10/20Gb Converged Network Adapter

### **Supported Devices and Features**

This product supports the following network adapters:

- HP NC382i Integrated Dual Port Multifunction Gigabit Server Adapter
- HP Flex-10 10Gb 2-port 530FLB Adapter
- HP Ethernet 10Gb 2-port 530FLR-SFP+ Adapter
- HP Flex-10 10Gb 2-port 530M Adapter
- HP Ethernet 10Gb 2-port 530SFP+ Adapter
- HP Ethernet 10Gb 2-port 530T Adapter
- HP NC532m Dual Port 10GbE Multifunction BL-c Adapter
- HP FlexFabric 10Gb 2-port 533FLR-T Adapter
- HP FlexFabric 10Gb 2-port 534FLB Adapter
- HP FlexFabric 10Gb 2-port 534FLR-SFP+ Adapter
- HP FlexFabric 10Gb 2-port 534M Adapter
- HP FlexFabric 10Gb 2-port 536FLB Adapter
- HPE FlexFabric 10Gb 4-port 536FLR-T Adapter
- HP FlexFabric 20Gb 2-port 630FLB Adapter
- HP FlexFabric 20Gb 2-port 630M Adapter
- HP StoreFabric CN1100R Dual Port Converged Network Adapter
- HPE StoreFabric CN1100R-T Converged Network Adapter
- HPE Synergy 10Gb 2-port 2820C Converged Network Adapter
- HPE Synergy 3820C 10/20Gb Converged Network Adapter

Version: 2.11.4.0-2 (B) **(Optional)**

Filename: iscsiui0-2.11.4.0-2.sles11sp3.i586.rpm

## **Enhancements**

This product is now HPE signed.

## **Supported Devices and Features**

This product supports the following network adapters:

- HP NC382i Integrated Dual Port Multifunction Gigabit Server Adapter
- HP Flex-10 10Gb 2-port 530FLB Adapter
- HP Ethernet 10Gb 2-port 530FLR-SFP+ Adapter
- HP Flex-10 10Gb 2-port 530M Adapter
- HP Ethernet 10Gb 2-port 530SFP+ Adapter
- HP Ethernet 10Gb 2-port 530T Adapter
- HP NC532m Dual Port 10GbE Multifunction BL-c Adapter
- HP FlexFabric 10Gb 2-port 533FLR-T Adapter
- HP FlexFabric 10Gb 2-port 534FLB Adapter
- HP FlexFabric 10Gb 2-port 534FLR-SFP+ Adapter
- HP FlexFabric 10Gb 2-port 534M Adapter
- HP FlexFabric 20Gb 2-port 630FLB Adapter
- HP FlexFabric 20Gb 2-port 630M Adapter
- HP StoreFabric CN1100R Dual Port Converged Network Adapter

---

HPE QLogic NX2 Linux iSCSI Offload IO Daemon for SUSE Linux Enterprise Server 11 SP3 x86\_64

Version: 2.11.4.0-2 (C) **(Optional)**

Filename: iscsiui0-2.11.4.0-2.sles11sp3.x86\_64.rpm

## **Enhancements**

This product now supports the following network adapters:

- HPE FlexFabric 10Gb 4-port 536FLR-T Adapter
- HPE Synergy 10Gb 2-port 2820C Converged Network Adapter
- HPE Synergy 3820C 10/20Gb Converged Network Adapter

## **Supported Devices and Features**

This product supports the following network adapters:

- HP NC382i Integrated Dual Port Multifunction Gigabit Server Adapter
- HP Flex-10 10Gb 2-port 530FLB Adapter
- HP Ethernet 10Gb 2-port 530FLR-SFP+ Adapter
- HP Flex-10 10Gb 2-port 530M Adapter
- HP Ethernet 10Gb 2-port 530SFP+ Adapter
- HP Ethernet 10Gb 2-port 530T Adapter
- HP NC532m Dual Port 10GbE Multifunction BL-c Adapter
- HP FlexFabric 10Gb 2-port 533FLR-T Adapter
- HP FlexFabric 10Gb 2-port 534FLB Adapter
- HP FlexFabric 10Gb 2-port 534FLR-SFP+ Adapter
- HP FlexFabric 10Gb 2-port 534M Adapter

- HP FlexFabric 10Gb 2-port 536FLB Adapter
- HPE FlexFabric 10Gb 4-port 536FLR-T Adapter
- HP FlexFabric 20Gb 2-port 630FLB Adapter
- HP FlexFabric 20Gb 2-port 630M Adapter
- HP StoreFabric CN1100R Dual Port Converged Network Adapter
- HPE StoreFabric CN1100R-T Converged Network Adapter
- HPE Synergy 10Gb 2-port 2820C Converged Network Adapter
- HPE Synergy 3820C 10/20Gb Converged Network Adapter

---

HPE QLogic NX2 Linux iSCSI Offload IO Daemon for SUSE Linux Enterprise Server 11 SP4 i586

Version: 2.11.4.0-2 (B) **(Optional)**

Filename: iscsiui0-2.11.4.0-2.sles11sp4.i586.rpm

### **Enhancements**

This product is now HPE signed.

### **Supported Devices and Features**

This product supports the following network adapters:

- HP NC382i Integrated Dual Port Multifunction Gigabit Server Adapter
- HP Flex-10 10Gb 2-port 530FLB Adapter
- HP Ethernet 10Gb 2-port 530FLR-SFP+ Adapter
- HP Flex-10 10Gb 2-port 530M Adapter
- HP Ethernet 10Gb 2-port 530SFP+ Adapter
- HP Ethernet 10Gb 2-port 530T Adapter
- HP NC532m Dual Port 10GbE Multifunction BL-c Adapter
- HP FlexFabric 10Gb 2-port 533FLR-T Adapter
- HP FlexFabric 10Gb 2-port 534FLB Adapter
- HP FlexFabric 10Gb 2-port 534FLR-SFP+ Adapter
- HP FlexFabric 10Gb 2-port 534M Adapter
- HP FlexFabric 20Gb 2-port 630FLB Adapter
- HP FlexFabric 20Gb 2-port 630M Adapter
- HP StoreFabric CN1100R Dual Port Converged Network Adapter

---

HPE QLogic NX2 Linux iSCSI Offload IO Daemon for SUSE Linux Enterprise Server 11 SP4 x86\_64

Version: 2.11.4.0-2 (C) **(Optional)**

Filename: iscsiui0-2.11.4.0-2.sles11sp4.x86\_64.rpm

### **Enhancements**

This product now supports the following network adapters:

- HPE FlexFabric 10Gb 4-port 536FLR-T Adapter
- HPE Synergy 10Gb 2-port 2820C Converged Network Adapter
- HPE Synergy 3820C 10/20Gb Converged Network Adapter

### **Supported Devices and Features**

This product supports the following network adapters:

- HP NC382i Integrated Dual Port Multifunction Gigabit Server Adapter
- HP Flex-10 10Gb 2-port 530FLB Adapter
- HP Ethernet 10Gb 2-port 530FLR-SFP+ Adapter
- HP Flex-10 10Gb 2-port 530M Adapter
- HP Ethernet 10Gb 2-port 530SFP+ Adapter
- HP Ethernet 10Gb 2-port 530T Adapter
- HP NC532m Dual Port 10GbE Multifunction BL-c Adapter
- HP FlexFabric 10Gb 2-port 533FLR-T Adapter
- HP FlexFabric 10Gb 2-port 534FLB Adapter
- HP FlexFabric 10Gb 2-port 534FLR-SFP+ Adapter
- HP FlexFabric 10Gb 2-port 534M Adapter
- HP FlexFabric 10Gb 2-port 536FLB Adapter
- HPE FlexFabric 10Gb 4-port 536FLR-T Adapter
- HP FlexFabric 20Gb 2-port 630FLB Adapter
- HP FlexFabric 20Gb 2-port 630M Adapter
- HP StoreFabric CN1100R Dual Port Converged Network Adapter
- HPE StoreFabric CN1100R-T Converged Network Adapter
- HPE Synergy 10Gb 2-port 2820C Converged Network Adapter
- HPE Synergy 3820C 10/20Gb Converged Network Adapter

---

HPE QLogic NX2 Linux iSCSI Offload IO Daemon for SUSE Linux Enterprise Server 12 SP1 x86\_64

Version: 2.11.4.0-2 (C) **(Optional)**

Filename: iscsiui0-2.11.4.0-2.sles12sp1.x86\_64.rpm

### **Enhancements**

This product now supports the following network adapters:

- HPE FlexFabric 10Gb 4-port 536FLR-T Adapter
- HPE Synergy 10Gb 2-port 2820C Converged Network Adapter
- HPE Synergy 3820C 10/20Gb Converged Network Adapter

### **Supported Devices and Features**

This product supports the following network adapters:

- HP NC382i Integrated Dual Port Multifunction Gigabit Server Adapter
- HP Flex-10 10Gb 2-port 530FLB Adapter
- HP Ethernet 10Gb 2-port 530FLR-SFP+ Adapter
- HP Flex-10 10Gb 2-port 530M Adapter
- HP Ethernet 10Gb 2-port 530SFP+ Adapter
- HP Ethernet 10Gb 2-port 530T Adapter
- HP NC532m Dual Port 10GbE Multifunction BL-c Adapter
- HP FlexFabric 10Gb 2-port 533FLR-T Adapter
- HP FlexFabric 10Gb 2-port 534FLB Adapter
- HP FlexFabric 10Gb 2-port 534FLR-SFP+ Adapter
- HP FlexFabric 10Gb 2-port 534M Adapter
- HP FlexFabric 10Gb 2-port 536FLB Adapter
- HPE FlexFabric 10Gb 4-port 536FLR-T Adapter
- HP FlexFabric 20Gb 2-port 630FLB Adapter
- HP FlexFabric 20Gb 2-port 630M Adapter
- HP StoreFabric CN1100R Dual Port Converged Network Adapter

- HP StoreFabric CN1100R-T Converged Network Adapter
- HPE Synergy 10Gb 2-port 2820C Converged Network Adapter
- HPE Synergy 3820C 10/20Gb Converged Network Adapter

---

HPE QLogic NX2 Linux iSCSI Offload IO Daemon for SUSE Linux Enterprise Server 12 x86\_64

Version: 2.11.4.0-2 (C) **(Optional)**

Filename: iscsiui0-2.11.4.0-2.sles12sp0x86\_64.rpm

### **Enhancements**

This product now supports the following network adapters:

- HPE FlexFabric 10Gb 4-port 536FLR-T Adapter
- HPE Synergy 10Gb 2-port 2820C Converged Network Adapter
- HPE Synergy 3820C 10/20Gb Converged Network Adapter

### **Supported Devices and Features**

This product supports the following network adapters:

- HP NC382i Integrated Dual Port Multifunction Gigabit Server Adapter
- HP Flex-10 10Gb 2-port 530FLB Adapter
- HP Ethernet 10Gb 2-port 530FLR-SFP+ Adapter
- HP Flex-10 10Gb 2-port 530M Adapter
- HP Ethernet 10Gb 2-port 530SFP+ Adapter
- HP Ethernet 10Gb 2-port 530T Adapter
- HP NC532m Dual Port 10GbE Multifunction BL-c Adapter
- HP FlexFabric 10Gb 2-port 533FLR-T Adapter
- HP FlexFabric 10Gb 2-port 534FLB Adapter
- HP FlexFabric 10Gb 2-port 534FLR-SFP+ Adapter
- HP FlexFabric 10Gb 2-port 534M Adapter
- HP FlexFabric 10Gb 2-port 536FLB Adapter
- HPE FlexFabric 10Gb 4-port 536FLR-T Adapter
- HP FlexFabric 20Gb 2-port 630FLB Adapter
- HP FlexFabric 20Gb 2-port 630M Adapter
- HP StoreFabric CN1100R Dual Port Converged Network Adapter
- HPE StoreFabric CN1100R-T Converged Network Adapter
- HPE Synergy 10Gb 2-port 2820C Converged Network Adapter
- HPE Synergy 3820C 10/20Gb Converged Network Adapter

---

HPE QLogic P3P iSCSI Drivers for VMware vSphere 5.5

Version: 2016.03.29 **(Optional)**

Filename: cp028004.zip

### **Important Note!**

This component is intended to be used by HPE applications. It is a zip file that contains the same driver deliverable available from the vmware.com and the HPE vibspot.hpe.com webpages, plus an HPE specific CPOxxxx.xml file.

HPE recommends the firmware provided in *HPE QLogic P3P Online Firmware Upgrade Utility for VMware*, version 2.5.5, for use with this driver.

## **Fixes**

This driver addresses a "Lost Heartbeat" purple diagnostic screen (PSOD) seen during the collection of a minidump.

## **Supported Devices and Features**

These drivers support the following network adapters:

- HP FlexFabric 10Gb 2-port 526FLR-SFP+ Adapter
- HP CN1000Q Dual Port Converged Network Adapter

---

HPE QLogic P3P iSCSI Drivers for VMware vSphere 6.0

Version: 2016.03.29 **(Optional)**

Filename: cp028005.zip

## **Important Note!**

This component is intended to be used by HPE applications. It is a zip file that contains the same driver deliverable available from the vmware.com and the HPE vibsdepot.hpe.com webpages, plus an HPE specific CPOxxxxx.xml file.

HPE recommends the firmware provided in *HPE QLogic P3P Online Firmware Upgrade Utility for VMware*, version 2.5.5, for use with this driver.

## **Fixes**

This driver addresses a "Lost Heartbeat" purple diagnostic screen (PSOD) seen during the collection of a minidump.

## **Supported Devices and Features**

These drivers support the following HP P3P network adapters:

- HP FlexFabric 10Gb 2-port 526FLR-SFP+ Adapter
- HP CN1000Q Dual Port Converged Network Adapter

---

HPE QLogic P3P Multifunction Driver for Windows Server 2008

Version: 5.3.32.1130 **(Optional)**

Filename: cp028932.exe

## **Important Note!**

HPE recommends the firmware provided in the following firmware products, as applicable, for use with this driver:

- *HP QLogic P3 Online Firmware Upgrade Utility for Windows Server 2008*, version 4.0.0.19 or later
- *HP QLogic P3P Online Firmware Upgrade Utility for Windows Server 2008*, version 4.0.0.19(B) or later

## **Fixes**

This product addresses an issue where the Virtual Memory Queue (VMQ) causes 100% CPU usage on a single core.

## **Supported Devices and Features**

This driver supports the following network adapters:

- HP NC375i Integrated Quad Port Multifunction Gigabit Server Adapter
- HP NC523SFP 10Gb 2-port Flex-10 Server Adapter
- HP FlexFabric 10Gb 2-port 526FLR-SFP+ Adapter
- HP CN1000Q Dual Port Converged Network Adapter

---

HPE QLogic P3P Multifunction Driver for Windows Server 2008 R2

Version: 5.3.32.1130 **(Optional)**

Filename: cp028934.exe

### **Important Note!**

HPE recommends the firmware provided in the following firmware products, as applicable, for use with this driver:

- *HP QLogic P3 Online Firmware Upgrade Utility for Windows Server x64 Editions*, version 4.0.0.19 or later
- *HP QLogic P3P Online Firmware Upgrade Utility for Windows Server x64 Editions*, version 4.0.0.19(C) or later

### **Fixes**

This product addresses an issue where the Virtual Memory Queue (VMQ) causes 100% CPU usage on a single core.

### **Supported Devices and Features**

This driver supports the following network adapters:

- HP NC375i Integrated Quad Port Multifunction Gigabit Server Adapter
- HP NC523SFP 10Gb 2-port Flex-10 Server Adapter
- HP FlexFabric 10Gb 2-port 526FLR-SFP+ Adapter
- HP CN1000Q Dual Port Converged Network Adapter

---

HPE QLogic P3P Multifunction Driver for Windows Server 2008 x64 Editions

Version: 5.3.32.1130 **(Optional)**

Filename: cp028933.exe

### **Important Note!**

HPE recommends the firmware provided in the following firmware products, as applicable, for use with this driver:

- *HP QLogic P3 Online Firmware Upgrade Utility for Windows Server x64 Editions*, version 4.0.0.19 or later
- *HP QLogic P3P Online Firmware Upgrade Utility for Windows Server x64 Editions*, version 4.0.0.19(C) or later

### **Fixes**

This product addresses an issue where the Virtual Memory Queue (VMQ) causes 100% CPU usage on a single core.

### **Supported Devices and Features**

This driver supports the following network adapters:

- HP NC375i Integrated Quad Port Multifunction Gigabit Server Adapter

- HP NC523SFP 10Gb 2-port Flex-10 Server Adapter
- HP FlexFabric 10Gb 2-port 526FLR-SFP+ Adapter
- HP CN1000Q Dual Port Converged Network Adapter

---

HPE QLogic P3P Multifunction Driver for Windows Server 2012

Version: 5.3.32.1130 **(Optional)**

Filename: cp028935.exe

### **Important Note!**

HPE recommends the firmware provided in the following firmware products, as applicable, for use with this driver:

- *HP QLogic P3 Online Firmware Upgrade Utility for Windows Server x64 Editions*, version 4.0.0.19 or later
- *HP QLogic P3P Online Firmware Upgrade Utility for Windows Server x64 Editions*, version 4.0.0.19(C) or later

### **Fixes**

This product addresses an issue where the Virtual Memory Queue (VMQ) causes 100% CPU usage on a single core.

### **Supported Devices and Features**

This driver supports the following network adapters:

- HP NC375i Integrated Quad Port Multifunction Gigabit Server Adapter
- HP NC523SFP 10Gb 2-port Flex-10 Server Adapter
- HP FlexFabric 10Gb 2-port 526FLR-SFP+ Adapter
- HP CN1000Q Dual Port Converged Network Adapter

---

HPE QLogic P3P Multifunction Driver for Windows Server 2012 R2

Version: 5.3.32.1130 **(Optional)**

Filename: cp028936.exe

### **Important Note!**

HPE recommends the firmware provided in the following firmware products, as applicable, for use with this driver:

- *HP QLogic P3 Online Firmware Upgrade Utility for Windows Server x64 Editions*, version 4.0.0.19 or later
- *HP QLogic P3P Online Firmware Upgrade Utility for Windows Server x64 Editions*, version 4.0.0.19(C) or later

### **Fixes**

This product addresses an issue where the Virtual Memory Queue (VMQ) causes 100% CPU usage on a single core.

### **Supported Devices and Features**

This driver supports the following network adapters:

- HP NC375i Integrated Quad Port Multifunction Gigabit Server Adapter
- HP NC523SFP 10Gb 2-port Flex-10 Server Adapter
- HP FlexFabric 10Gb 2-port 526FLR-SFP+ Adapter
- HP CN1000Q Dual Port Converged Network Adapter



---

HPE QLogic qlcnic Drivers for Red Hat Enterprise Linux 6 i686

Version: 5.3.63-3 **(Optional)**

Filename: hp-qlgc-docs-1.1.1-1.noarch.rpm; hp-qlgc-utils-1.3.0-1.noarch.rpm; kmod-hpqlgc-qlcnic-5.3.63-3.rhel6u6.i686.rpm; kmod-hpqlgc-qlcnic-5.3.63-3.rhel6u7.i686.rpm; README

### **Important Note!**

HPE recommends the firmware provided in *HP QLogic P3P Online Firmware Upgrade Utility for Linux x86*, version 1.9.7 or later, for use with these drivers.

### **Fixes**

This product addresses memory allocation failures seen while copying a firmware image.

This product addresses network connectivity issues seen when using a large number of multicast groups.

### **Enhancements**

This product now provides support for an extended minidump feature.

### **Supported Devices and Features**

These drivers support the following network adapters:

- HP NC523SFP 10Gb 2-port Flex-10 Ethernet Server Adapter
- HP FlexFabric 10Gb 2-port 526FLR-SFP+ Adapter
- HP CN1000Q Dual Port Converged Network Adapter

---

HPE QLogic qlcnic Drivers for Red Hat Enterprise Linux 6 x86\_64

Version: 5.3.63-3 **(Optional)**

Filename: hp-qlgc-docs-1.1.1-1.noarch.rpm; hp-qlgc-utils-1.3.0-1.noarch.rpm; kmod-hpqlgc-qlcnic-5.3.63-3.rhel6u6.x86\_64.rpm; kmod-hpqlgc-qlcnic-5.3.63-3.rhel6u7.x86\_64.rpm; README

### **Important Note!**

HPE recommends the firmware provided in *HP QLogic P3P Online Firmware Upgrade Utility for Linux x86\_64*, version 1.9.7 or later, for use with these drivers.

### **Fixes**

This product addresses memory allocation failures seen while copying a firmware image.

This product addresses network connectivity issues seen when using a large number of multicast groups.

### **Enhancements**

This product now provides support for an extended minidump feature.

## **Supported Devices and Features**

These drivers support the following network adapters:

- HP NC523SFP 10Gb 2-port Flex-10 Ethernet Server Adapter
- HP FlexFabric 10Gb 2-port 526FLR-SFP+ Adapter
- HP CN1000Q Dual Port Converged Network Adapter

---

HPE QLogic qlcnic Drivers for Red Hat Enterprise Linux 7 x86\_64

Version: 5.3.63-3 **(Optional)**

Filename: hp-qlgc-docs-1.1.1-1.noarch.rpm; hp-qlgc-utils-1.3.0-1.noarch.rpm; kmod-hpqlgc-qlcnic-5.3.63-3.rhel7u1.x86\_64.rpm; kmod-hpqlgc-qlcnic-5.3.63-3.rhel7u2.x86\_64.rpm; README

### **Important Note!**

HPE recommends the firmware provided in *HP QLogic P3P Online Firmware Upgrade Utility for Linux x86\_64*, version 1.9.7 or later, for use with these drivers.

### **Fixes**

This product addresses memory allocation failures seen while copying a firmware image.

This product addresses network connectivity issues seen when using a large number of multicast groups.

### **Enhancements**

This product now provides support for an extended minidump feature.

## **Supported Devices and Features**

These drivers support the following network adapters:

- HP NC523SFP 10Gb 2-port Flex-10 Ethernet Server Adapter
- HP FlexFabric 10Gb 2-port 526FLR-SFP+ Adapter
- HP CN1000Q Dual Port Converged Network Adapter

---

HPE QLogic qlcnic Drivers for SUSE Linux Enterprise Server 11 i586

Version: 5.3.63-3 **(Optional)**

Filename: hp-qlgc-docs-1.1.1-1.noarch.rpm; hp-qlgc-utils-1.3.0-1.noarch.rpm; hpqlgc-qlcnic-kmp-default-5.3.63\_3.0.101\_63-5.sles11sp4.i586.rpm; hpqlgc-qlcnic-kmp-default-5.3.63\_3.0.76\_0.11-5.sles11sp3.i586.rpm; hpqlgc-qlcnic-kmp-pae-5.3.63\_3.0.101\_63-5.sles11sp4.i586.rpm; hpqlgc-qlcnic-kmp-pae-5.3.63\_3.0.76\_0.11-5.sles11sp3.i586.rpm; hpqlgc-qlcnic-kmp-xen-5.3.63\_3.0.101\_63-5.sles11sp4.i586.rpm; hpqlgc-qlcnic-kmp-xen-5.3.63\_3.0.76\_0.11-5.sles11sp3.i586.rpm; README

### **Important Note!**

HPE recommends the firmware provided in *HP QLogic P3P Online Firmware Upgrade Utility for Linux x86*, version 1.9.7 or later, for use with these drivers.

### **Fixes**

This product addresses memory allocation failures seen while copying a firmware image.

This product addresses network connectivity issues seen when using a large number of multicast groups.

## **Enhancements**

This product now provides support for an extended minidump feature.

## **Supported Devices and Features**

These drivers support the following network adapters:

- HP NC523SFP 10Gb 2-port Flex-10 Ethernet Server Adapter
- HP FlexFabric 10Gb 2-port 526FLR-SFP+ Adapter
- HP CN1000Q Dual Port Converged Network Adapter

---

HPE QLogic qlcnic Drivers for SUSE Linux Enterprise Server 11 x86\_64

Version: 5.3.63-3 **(Optional)**

Filename: hp-qlgc-docs-1.1.1-1.noarch.rpm; hp-qlgc-utils-1.3.0-1.noarch.rpm; hpqlgc-qlcnic-kmp-default-5.3.63\_3.0.101\_63-5.sles11sp4.x86\_64.rpm; hpqlgc-qlcnic-kmp-default-5.3.63\_3.0.76\_0.11-5.sles11sp3.x86\_64.rpm; hpqlgc-qlcnic-kmp-xen-5.3.63\_3.0.101\_63-5.sles11sp4.x86\_64.rpm; hpqlgc-qlcnic-kmp-xen-5.3.63\_3.0.76\_0.11-5.sles11sp3.x86\_64.rpm; README

## **Important Note!**

HPE recommends the firmware provided in *HP QLogic P3P Online Firmware Upgrade Utility for Linux x86\_64*, version 1.9.7 or later, for use with these drivers.

## **Fixes**

This product addresses memory allocation failures seen while copying a firmware image.

This product addresses network connectivity issues seen when using a large number of multicast groups.

## **Enhancements**

This product now provides support for an extended minidump feature.

## **Supported Devices and Features**

These drivers support the following network adapters:

- HP NC523SFP 10Gb 2-port Flex-10 Ethernet Server Adapter
- HP FlexFabric 10Gb 2-port 526FLR-SFP+ Adapter
- HP CN1000Q Dual Port Converged Network Adapter

---

HPE QLogic qlcnic Drivers for SUSE Linux Enterprise Server 12 x86\_64

Version: 5.3.63-3 **(Optional)**

Filename: hp-qlgc-docs-1.1.1-1.noarch.rpm; hp-qlgc-utils-1.3.0-1.noarch.rpm; hpqlgc-qlcnic-kmp-default-5.3.63\_k3.12.28\_4-5.sles12sp0.x86\_64.rpm; hpqlgc-qlcnic-kmp-default-5.3.63\_k3.12.49\_11-5.sles12sp1.x86\_64.rpm; hpqlgc-qlcnic-kmp-xen-5.3.63\_k3.12.28\_4-5.sles12sp0.x86\_64.rpm; hpqlgc-qlcnic-kmp-xen-5.3.63\_k3.12.49\_11-5.sles12sp1.x86\_64.rpm; README

## **Important Note!**

HPE recommends the firmware provided in *HP QLogic P3P Online Firmware Upgrade Utility for Linux x86\_64*, version 1.9.7 or later, for use with these drivers.

## **Fixes**

This product addresses memory allocation failures seen while copying a firmware image.

This product addresses network connectivity issues seen when using a large number of multicast groups.

## **Enhancements**

This product now provides support for an extended minidump feature.

## **Supported Devices and Features**

These drivers support the following network adapters:

- HP NC523SFP 10Gb 2-port Flex-10 Ethernet Server Adapter
- HP FlexFabric 10Gb 2-port 526FLR-SFP+ Adapter
- HP CN1000Q Dual Port Converged Network Adapter

---

Mellanox InfiniBand and Ethernet Driver for SuSE Linux Enterprise Server 12

Version: 3.3-1.0.4.0 (**Recommended**)

Filename: MLNX\_OFED\_LINUX-3.3-1.0.4.0-sles12sp0-x86\_64.tar.gz

## **Important Note!**

**If using secure boot mode operation, use signed Mellanox OFED driver which is distributed via the HP Software Delivery Repository:**

[http://downloads.linux.hp.com/SDR/downloads/MLNX\\_OFED/](http://downloads.linux.hp.com/SDR/downloads/MLNX_OFED/)

**It is recommended to follow instructions from "Performance\_Tuning\_Guide\_for\_Mellanox\_Network\_Adapters.pdf" , if using MLNX\_EN (Ethernet driver) from this OFED version. The performance tuning guide helps you to setup the parameters that improves the performance of Mellanox VPI cards in Ethernet mode. "Performance\_Tuning\_Guide\_for\_Mellanox\_Network\_Adapters.pdf" is bundled with the driver.**

For a list of known issues with this release, refer Chapter 3 of "Mellanox OFED Release notes" bundled with the driver download.

## **Fixes**

### **Fixes in version 3.3-1.0.4.0:**

- Fixed the issue where as a result of the `ndo_set_mac_address` support in IPoIB, a memory corruption issue was exposed in the bonding driver over IPoIB interface. This memory corruption issue could have caused unpredictable behavior, such as ports becoming dysfunctional in RedHat, kernel panicking in Ubuntu devices, and other behaviors.

### **Fixes in version 3.3-1.0.0.0:**

- IB Core
  - Fixed a potential security breach in the InfiniBand stack that was caused due to wrong reliance on the write system call.

RoCE

- Fixed the issue where the InfiniBand error counters found under `/sys/class/infiniband/<mlx5_dev>/ports/<port>` did not function properly in

ConnectX-4 adapter cards.

- Installation
  - Fixed the issue where `dapl` package was missing in `MLNX_OFED` for Ubuntu PPC64LE.
- TX Queue Counter
  - Changed TX queue counter format to: `xq_[tc]*[ring/channel]`.
- RDMA Sniffer
  - Fixed RDMA sniffer functionality issues.
- IPoIB
  - Fixed IPoIB Connected Mode in ConnectX-3 functionality issues.
  - Fixed the issue where in order to change the IPoIB mode (connected/datagram), the interface had to be taken down (via `ifconfig ibX down` or `ifdown ibX`). Now, the mode can be changed regardless of the interface's state ("up" or "down").
- `mlx4_en`
  - Added DCB PFC support through CEE netlink commands to prevent Priority Flow Control mode functionality issues on the host side.
- SR-IOV
  - Fixed an issue which added error messages to the `dmesg` when a VF used `ethtool` facilities.
  - Fixed an issue which caused any traffic from PF to any VF on the same port to drop when the physical link was down.

For additional information on fixes, please refer to the "Release Notes" document included with the driver download.

## **Enhancements**

**MLNX OFED v3.3-1.0.0.0 contains the following changes and new features:**

**For ConnectX-4/ConnectX-4 Lx :**

- **Added support for the following features/changes on ConnectX-4/ConnectX-4 Lx:**
  - **VF MAC Address Anti-Spoofing** : Also known as MAC spoof-check, the VF MAC Address Anti-Spoofing prevents malicious VFs from faking their MAC addresses.
  - **VF All-multi Mode** : Added support for the VF to enter all-multi RX mode, meaning that in addition to the traffic originally targeted to the VF, it will receive all the multicast traffic sent from/to the other functions on the same physical port.  
  
Note: Only privileged/trusted VFs can enter the all-multi RX mode.
  - **VF Promiscuous Mode** : Added support for the VF to enter promiscuous RX mode, meaning that in addition to the traffic originally targeted to the VF, it will receive the unmatched traffic and all the multicast traffic that reaches the physical port. The unmatched traffic is any traffic's DMAC that does not match any of the VFs' or PFs' MAC addresses.  
  
Note: Only privileged/trusted VFs can enter the promiscuous RX mode.
  - **Privileged VF** : Added support for determining privileged/trusted VFs so security sensitive features can be enabled for these VFs, such as entering promiscuous and all-multi RX modes.
  - **DCBX** : Added support for standard DCBX CEE API.
  - **Per Priority Counters** : Exposed performance counters per priority.
  - **IB Error Counters** : Exposed IB sysfs error counters for `mlx5` driver.
  - **Accelerated Receive Flow Steering (aRFS)** : Boosts the speed of RFS by adding hardware assistance. RFS is an in-kernel-logic responsible for load balancing between CPUs by attaching flows to CPUs that are used by flow's owner applications.
  - **Packet Pacing for UDP/TCP** : Performs rate limit per UDP/TCP connection.

**For ConnectX-3/ConnectX-3 Pro/ConnectX-4/ConnectX-4 Lx :**

- **Added support for the following features/changes on ConnectX-3/ConnectX-3 Pro/ConnectX-4/ConnectX-4 Lx :**
  - **MAD Congestion Control** : Added an SA MAD congestion control mechanism that is configurable using sysfs entries.
  - **Physical Memory Allocation** : Added support for Physical Address Memory Region (PA-MR) which allows managing physical memory used for posting send and receive requests.
  - **IB Router** : Added the ability to send traffic between two or more subnets.
  - **PeerDirect Async** : Mellanox PeerDirect Async™ sub-system gives peer hardware devices, such as GPU cards, and dedicated AS accelerators the ability to take control over HCA in critical path offloading CPU.
  - **Physical MR** : Allows the user to use physical addresses instead of virtual addresses in critical path. Thus enhances performance since there is no need in addresses translation.
  - **OFED Scripts** : Renamed the UP name that appears in mlnx\_perf report to "TC", as the mlnx\_perf script counts the packets and calculates the bandwidth on rings that belong to the same Traffic Class (TC).
  - **RoCE v1 (Layer 2) Compatibility** : Added the option to connect between nodes running MLNX\_OFED and nodes running RoCE with Layer 2 GID format.

For additional information on the new features, please refer to the MLNX\_OFED User Manual and Release Notes bundled with the software.

## **Supported Devices and Features**

### **Supported Host Channel Adapters Firmware Versions:**

HCA	Recommended Firmware Rev.	Additional Firmware Rev. Supported
Connect-IB®	10.14.2036	10.14.1100
ConnectX®-4 Lx	14.14.2036	14.14.1100
ConnectX®-4	12.14.2036	12.14.1100
ConnectX®-3 Pro	2.36.5000	2.35.5100
ConnectX®-3	2.36.5000	2.35.5100
ConnectX®-2	2.9.1000	2.9.1000

---

net-mlx4\_en driver component for VMware 5.5

Version: 2015.05.02 **(Recommended)**

Filename: cp025935.zip

### **Important Note!**

This component is intended to be used by HP applications. It is a zip that contains the same driver deliverable available from the HP vibspot.hp.com webpage, plus an HP specific CPXXXX.xml file.

### **Fixes**

Initial version

---

net-mst kernel module driver component for VMware 5.5

Version: 2016.01.19 **(Recommended)**

Filename: cp029081.zip

### **Important Note!**

This component is intended to be used by HP applications. It is a zip that contains the same driver deliverable available from the HP

vibsdepot.hp.com webpage, plus an HP specific CPXXXX.xml file.

### **Fixes**

Initial version of 4.2.0.16 for Snap6

### **Enhancements**

MST Version 4.2.0.16

---

net-mst kernel module driver component for VMware 6.0

Version: 2016.01.19 **(Recommended)**

Filename: cp029082.zip

### **Important Note!**

This component is intended to be used by HP applications. It is a zip that contains the same driver deliverable available from the HP vibsdepot.hp.com webpage, plus an HP specific CPXXXX.xml file.

### **Fixes**

Initial version of 4.2.0.16 for Snap6

### **Enhancements**

MST Version 4.2.0.16

---

nmlx4\_en driver component for VMware 6.0

Version: 2015.10.29 **(Recommended)**

Filename: cp028535.zip

### **Important Note!**

#### **Known Issues in 3.2.0.7:**

- When the port is DOWN, the management interface port type field (nmlx\_en\_MgmtIFPortType) indicates one of the port types supported by the device, in the following order: TP, FIBER, DA, NONE. If the cable supports several types, the first type in the list mentioned above will be printed.
- When the port is UP, the management interface port type field (nmlx-\_en\_MgmtIFPortType) indicates which one of all possible supported types is currently connected.
- Management interface port type field (nmlx\_en\_MgmtIFPortType) reports SFP-to-RJ45 cable as FIBER.
- Management interface auto negotiation field (nmlx\_en\_MgmtIFAutoNegMode) is equivalent to "esxcli network nic get -n vmnicX" field "Pause Autonegotiate".

### **Fixes**

#### **Fixes in 3.2.0.7:**

- Management interface port type field (nmlx-\_en\_MgmtIFPortType) reported incorrect value.

---

VMware ESX 5.5 MST Drivers Offline Bundle for Mellanox Adapters

Version: 4.3.0.29 **(Recommended)**

Filename: MLNX-NET-MST-ESX-5.5.0-4.3.0.29.zip

### **Fixes**

Initial version of 4.3.0.29

---

VMware ESX 6.0 MST Drivers Offline Bundle for Mellanox Adapters

Version: 4.3.0.29 **(Recommended)**

Filename: MLNX-NMST-ESX-6.0.0-4.3.0.29.zip

### **Fixes**

Initial version of VM60 nmst 4.3.0.29

---

## **Driver - Storage**

[Top](#)

HP ProLiant Smart Array Embedded SATA RAID Controller Driver for Microsoft Windows Server 2012 and Microsoft Windows Server 2012 R2

Version: 6.18.4.64 (A) **(Optional)**

Filename: cp022401.exe

### **Enhancements**

Added support for Microsoft Windows Server 2012 R2

---

HP ProLiant Smart Array Embedded SATA RAID Controller Driver for Windows 2003/2008 x64 Editions

Version: 6.18.0.64 (B) **(Optional)**

Filename: cp020545.exe

### **Important Note!**

If the target controller was successfully updated to version 6.18.0.64(A) of this driver, then it is not necessary to update to version 6.18.0.64(B)

### **Enhancements**

Support added for Microsoft Windows Small Business Server 2011 Standard and Essentials

---

HP ProLiant Smart Array Embedded SATA RAID Controller Driver for Windows Server 2003/2008

Version: 6.18.0.32 (A) **(Optional)**

Filename: cp018782.exe

### **Important Note!**

If the target controller was successfully updated to version 6.18.0.32, then it is not necessary to update to version 6.18.0.32(A )



## **Fixes**

- Corrects an issue where HP B110i would try to resume the rebuild progress if the drive was replaced while the server was offline.
  - To improve rebuild time, ensure that drive write cache is enabled during rebuild and disabled when rebuild completes.
- 

## **Driver - Storage Controller**

[Top](#)

\*REMOVED\* HPE ProLiant Smart Array HPCISSs3 Controller Driver for 64-bit Microsoft Windows Server 2012/2016 Editions

Version: 100.18.2.64 **(Recommended)**

Filename: cp032118.exe

## **Fixes**

**REMOVED:** The HPCISSs3.sys version 100.18.2.64 driver is no longer available for download from HPE.com. When version 100.18.2.64 of the HPE ProLiant Smart Array HPCISSs3 Controller Driver is running on a system with Microsoft Windows Server 2012, 2012 R2, or 2016, a blue screen error may occur. Refer to HPE Customer Advisory for more details. [http://h20564.www2.hp.com/hpsc/doc/public/display?docId=emr\\_na-a00020203en\\_us](http://h20564.www2.hp.com/hpsc/doc/public/display?docId=emr_na-a00020203en_us)

Click the "Obtain software" link to access the download web page for the replacement HPCISSs3.sys version 100.20.0.64 driver.

Fixes the following issue:

Resolved an issue where Microsoft Windows may become unresponsive when the operating system issues a reset to certain 6TB or 8TB drives configured in a dual domain configuration and when connected to a Gen9 Smart Array controller in HBA mode.

Drive models affected:

- MB6000JEQUV
- MB8000JEQVA
- MB4000JEQNL
- MB6000JEQNN

---

HP H2xx SAS/SATA Host Bus Adapter Driver for Microsoft Windows Server 2008 x86 Editions

Version: 2.68.64.0 **(Optional)**

Filename: cp021866.exe

## **Enhancements**

Updated for Version Control across all LSI\_sas2 Windows Drivers.

---

HP H2xx SAS/SATA Host Bus Adapter Driver for 64-bit Microsoft Windows Server 2016 Editions

Version: 2.68.64.2 **(Optional)**

Filename: cp029941.exe

## **Enhancements**

Added support for:

- Microsoft Windows Server 2016 - Server Core and Server with a Desktop.
-

HP H2xx SAS/SATA Host Bus Adapter Driver for Microsoft Windows Server 2008 R2 Editions

Version: 2.68.64.0 **(Optional)**

Filename: cp021871.exe

### **Enhancements**

Updated for Version Control across all LSI\_sas2 Windows Drivers.

---

HP H2xx SAS/SATA Host Bus Adapter Driver for Microsoft Windows Server 2008 x64 Editions

Version: 2.68.64.0 **(Optional)**

Filename: cp021868.exe

### **Enhancements**

Updated for Version Control across all LSI\_sas2 Windows Drivers.

---

HP H2xx SAS/SATA Host Bus Adapter Driver for Microsoft Windows Server 2012 R2 x64 Editions

Version: 2.68.64.1 **(Optional)**

Filename: cp023630.exe

### **Enhancements**

- Added support for Windows 8.1 and Windows Server 2012R2 to the build scripts.
  - Add build support for new Windows Event Logging
  - Add support for automatic selection of the default driver build parameters file during the build
- 

HP H2xx SAS/SATA Host Bus Adapter Driver for Microsoft Windows Server 2012 x64 Editions

Version: 2.68.64.0 **(Optional)**

Filename: cp021873.exe

### **Enhancements**

Updated for Version Control across all LSI\_sas2 Windows Drivers.

---

HP H2xx SAS/SATA Host Bus Adapter Driver for Red Hat Enterprise Linux 6 (AMD64/EM64T)

Version: 15.10.04.00-10 **(Recommended)**

Filename: kmod-mpt2sas-15.10.02.00-8.rhel6u0.x86\_64.rpm; kmod-mpt2sas-15.10.02.00-8.rhel6u1.x86\_64.rpm; kmod-mpt2sas-15.10.02.00-8.rhel6u2.x86\_64.rpm; kmod-mpt2sas-15.10.02.00-8.rhel6u3.x86\_64.rpm; kmod-mpt2sas-15.10.02.00-8.rhel6u4.x86\_64.rpm; kmod-mpt2sas-15.10.02.00-8.rhel6u5.x86\_64.rpm; kmod-mpt2sas-15.10.04.00-10.rhel6u8.x86\_64.rpm; kmod-mpt2sas-15.10.04.00-3.rhel6u6.x86\_64.rpm; kmod-mpt2sas-15.10.04.00-6.rhel6u7.x86\_64.rpm

### **Enhancements**

Added support for Red Hat Enterprise Linux 6 Update 8.

### **Supported Devices and Features**

#### SUPPORTED KERNELS:

The kernels of Red Hat Enterprise Linux 6 (AMD64/EM64T) supported by this binary rpm are:

- 2.6.32-131.el6 - Red Hat Enterprise Linux 6 Update 1 (AMD64/EM64T) and future errata kernels for update 1.
- 2.6.32-220.el6 - Red Hat Enterprise Linux 6 Update 2 (AMD64/EM64T) and future errata kernels for update 2.
- 2.6.32-279.el6 - Red Hat Enterprise Linux 6 Update 3 (AMD64/EM64T) and future errata kernels for update 3.
- 2.6.32-358.el6 - Red Hat Enterprise Linux 6 Update 4 (AMD64/EM64T) and future errata kernels for update 4.
- 2.6.32-431.el6 - Red Hat Enterprise Linux 6 Update 5 (AMD64/EM64T) and future errata kernels for update 5.
- 2.6.32-504.el6 - Red Hat Enterprise Linux 6 Update 6 (AMD64/EM64T) and future errata kernels for update 6.
- 2.6.32-573.el6 - Red Hat Enterprise Linux 6 Update 7 (AMD64/EM64T) and future errata kernels for update 7.
- 2.6.32-642.el6 - Red Hat Enterprise Linux 6 Update 8 (AMD64/EM64T) and future errata kernels for update 8.

---

HP H2xx SAS/SATA Host Bus Adapter Driver for Red Hat Enterprise Linux 6 (x86)

Version: 15.10.04.00-10 **(Recommended)**

Filename: kmod-mpt2sas-15.10.02.00-7.rhel6u0.i686.rpm; kmod-mpt2sas-15.10.02.00-8.rhel6u1.i686.rpm; kmod-mpt2sas-15.10.02.00-8.rhel6u2.i686.rpm; kmod-mpt2sas-15.10.02.00-8.rhel6u3.i686.rpm; kmod-mpt2sas-15.10.02.00-8.rhel6u4.i686.rpm; kmod-mpt2sas-15.10.02.00-8.rhel6u5.i686.rpm; kmod-mpt2sas-15.10.04.00-10.rhel6u8.i686.rpm; kmod-mpt2sas-15.10.04.00-3.rhel6u6.i686.rpm; kmod-mpt2sas-15.10.04.00-6.rhel6u7.i686.rpm

#### **Enhancements**

Added support for Red Hat Enterprise Linux 6 Update 8.

#### **Supported Devices and Features**

#### SUPPORTED KERNELS:

The kernels of Red Hat Enterprise Linux 6 (x86) supported by this binary rpm are:

- 2.6.32-131.el6 - Red Hat Enterprise Linux 6 Update 1(x86) and future errata kernels for update 1.
- 2.6.32-220.el6 - Red Hat Enterprise Linux 6 Update 2(x86) and future errata kernels for update 2.
- 2.6.32-279.el6 - Red Hat Enterprise Linux 6 Update 3(x86) and future errata kernels for update 3.
- 2.6.32-358.el6 - Red Hat Enterprise Linux 6 Update 4(x86) and future errata kernels for update 4.
- 2.6.32-431.el6 - Red Hat Enterprise Linux 6 Update 5(x86) and future errata kernels for update 5.
- 2.6.32-504.el6 - Red Hat Enterprise Linux 6 Update 6(x86) and future errata kernels for update 6.
- 2.6.32-573.el6 - Red Hat Enterprise Linux 6 Update 7(x86) and future errata kernels for update 7.
- 2.6.32-642.el6 - Red Hat Enterprise Linux 6 Update 8(x86) and future errata kernels for update 8.

---

HP H2xx SAS/SATA Host Bus Adapter Driver for SUSE LINUX Enterprise Server 11 (AMD64/EM64T)

Version: 15.10.04.00-5 (A) **(Recommended)**

Filename: lsi-mpt2sas-kmp-default-15.10.02.00-6.sles11sp1.x86\_64.rpm; lsi-mpt2sas-kmp-default-15.10.02.00-6.sles11sp2.x86\_64.rpm; lsi-mpt2sas-kmp-default-15.10.02.00-6.sles11sp3.x86\_64.rpm; lsi-mpt2sas-kmp-default-15.10.04.00-5.sles11sp4.x86\_64.rpm; lsi-mpt2sas-kmp-xen-15.10.02.00-6.sles11sp1.x86\_64.rpm; lsi-mpt2sas-kmp-xen-15.10.02.00-6.sles11sp2.x86\_64.rpm; lsi-mpt2sas-kmp-xen-15.10.02.00-6.sles11sp3.x86\_64.rpm; lsi-mpt2sas-kmp-xen-15.10.04.00-5.sles11sp4.x86\_64.rpm

#### **Enhancements**

Added HPE digital signatures to RPM packages and included kernel objects. No functional changes were made to the driver.

If driver version 15.10.04.00-5 is installed on the target system, then it is not necessary to update to driver version 15.10.04.00-5(A).

## **Supported Devices and Features**

### SUPPORTED KERNELS:

The kernels of SUSE LINUX Enterprise Server 11 (AMD64/EM64T) supported by this driver diskette are:

2.6.32.12-0.7 - SUSE LINUX Enterprise Server 11 SP 1 (AMD64/EM64T) plus future errata.

3.0.13-0.27.1 - SUSE LINUX Enterprise Server 11 SP 2 (AMD64/EM64T) plus future errata.

3.0.76-0.11.1 - SUSE LINUX Enterprise Server 11 SP 3 (AMD64/EM64T) plus future errata.

3.0.101-63-default - SUSE LINUX Enterprise Server 11 SP 4 (AMD64/EM64T) plus future errata.

---

HP H2xx SAS/SATA Host Bus Adapter Driver for SUSE LINUX Enterprise Server 11 (x86)

Version: 15.10.04.00-5 (A) **(Recommended)**

Filename: lsi-mpt2sas-kmp-default-15.10.02.00-6.sles11sp1.i586.rpm; lsi-mpt2sas-kmp-default-15.10.02.00-6.sles11sp2.i586.rpm; lsi-mpt2sas-kmp-default-15.10.02.00-6.sles11sp3.i686.rpm; lsi-mpt2sas-kmp-default-15.10.04.00-5.sles11sp4.i686.rpm; lsi-mpt2sas-kmp-pae-15.10.02.00-6.sles11sp1.i586.rpm; lsi-mpt2sas-kmp-pae-15.10.02.00-6.sles11sp2.i586.rpm; lsi-mpt2sas-kmp-pae-15.10.02.00-6.sles11sp3.i686.rpm; lsi-mpt2sas-kmp-pae-15.10.04.00-5.sles11sp4.i686.rpm; lsi-mpt2sas-kmp-xen-15.10.02.00-6.sles11sp1.i586.rpm; lsi-mpt2sas-kmp-xen-15.10.02.00-6.sles11sp2.i586.rpm; lsi-mpt2sas-kmp-xen-15.10.02.00-6.sles11sp3.i686.rpm; lsi-mpt2sas-kmp-xen-15.10.04.00-5.sles11sp4.i686.rpm

## **Enhancements**

Added HPE digital signatures to RPM packages and included kernel objects. No functional changes were made to the driver.

If driver version 15.10.04.00-5 is installed on the target system, then it is not necessary to update to driver version 15.10.04.00-6(A).

## **Supported Devices and Features**

### SUPPORTED KERNELS:

The kernels of SUSE LINUX Enterprise Server 11 (x86) supported by this driver diskette are:

2.6.32.12-0.7 - SUSE LINUX Enterprise Server 11 SP 1 (x86) plus future errata.

3.0.13-0.27.1 - SUSE LINUX Enterprise Server 11 SP 2 (x86) plus future errata.

3.0.76-0.11.1 - SUSE LINUX Enterprise Server 11 SP 3 (x86) plus future errata.

3.0.101-63-default - SUSE LINUX Enterprise Server 11 SP 4 (x86) and future errata kernels for SP 4.

---

HP H2xx SAS/SATA Host Bus Adapter Driver for SUSE LINUX Enterprise Server 12 (AMD64/EM64T)

Version: 15.10.04.00-7 (A) **(Recommended)**

Filename: lsi-mpt2sas-kmp-default-15.10.04.00-3.sles12sp0.x86\_64.rpm; lsi-mpt2sas-kmp-default-15.10.04.00-7.sles12sp1.x86\_64.rpm; lsi-mpt2sas-kmp-xen-15.10.04.00-3.sles12sp0.x86\_64.rpm; lsi-mpt2sas-kmp-xen-15.10.04.00-7.sles12sp1.x86\_64.rpm

## **Enhancements**

Added HPE digital signatures to RPM packages and included kernel objects. No functional changes were made to the driver.

If driver version 15.10.04.00-7 is installed on the target system, then it is not necessary to update to driver version 15.10.04.00-7(A).

## **Supported Devices and Features**

SUPPORTED KERNELS:

The kernels of SUSE LINUX Enterprise Server 12 (AMD64/EM64T) supported by this binary rpm are:

3.12.28-4 - SUSE LINUX Enterprise Server 12 (AMD64/EM64T) and future update kernels.

3.12.49-11.1- SUSE LINUX Enterprise Server 12 (AMD64/EM64T) SP1 plus future errata.

---

HP ProLiant Smart Array Controller (AMD64/EM64T) Driver for SUSE LINUX Enterprise Server 12 (AMD64/EM64T)

Version: 3.4.16-145 **(Recommended)**

Filename: hpsa-kmp-default-3.4.16-145.sles12sp0.x86\_64.rpm; hpsa-kmp-default-3.4.16-145.sles12sp1.x86\_64.rpm; hpsa-kmp-xen-3.4.16-145.sles12sp0.x86\_64.rpm; hpsa-kmp-xen-3.4.16-145.sles12sp1.x86\_64.rpm

**Enhancements**

When a controller lock-up occurs, the controller now generates an NMI, which results in more diagnostic information in the AHS logs to better identify the cause of the lock-up.

**Supported Devices and Features**

SUPPORTED KERNELS:

The kernels of SUSE LINUX Enterprise Server 12 (AMD64/EM64T) supported by this binary rpm are:

3.12.28-4 - SUSE LINUX Enterprise Server 12 (AMD64/EM64T) and future update kernels.

3.12.49-11.1- SUSE LINUX Enterprise Server 12 (AMD64/EM64T) SP1 plus future errata.

---

HP ProLiant Smart Array SAS/SATA Controller Driver for Windows Server 2008

Version: 6.28.0.32 **(Optional)**

Filename: cp020622.exe

**Enhancements**

Minor performance enhancements

---

HP ProLiant Smart Array SAS/SATA Controller Driver for Windows Server 2008 x64 Edition

Version: 6.28.0.64 (C) **(Optional)**

Filename: cp028066.exe

**Enhancements**

Added support for HP ProLiant WS460c Gen8 Graphics Server Blade.

---

HP ProLiant Smart Array SAS/SATA Controller Driver for Windows Server 2012 x64 Edition

Version: 6.28.0.64 (C) **(Recommended)**

Filename: cp028045.exe

**Enhancements**

Added support for HPE ProLiant WS460c Gen9 Graphics Server Blade.

---

HP Smart Array B110i SATA RAID Controller Driver for Red Hat Enterprise Linux 6 (AMD64/EM64T)

Version: 1.2.6-18 (A) **(Recommended)**

Filename: kmod-hpahcisr-1.2.6-18.rhel6u1.x86\_64.rpm; kmod-hpahcisr-1.2.6-18.rhel6u2.x86\_64.rpm; kmod-hpahcisr-1.2.6-18.rhel6u3.x86\_64.rpm; kmod-hpahcisr-1.2.6-18.rhel6u4.x86\_64.rpm; kmod-hpahcisr-1.2.6-18.rhel6u5.x86\_64.rpm; kmod-hpahcisr-1.2.6-18.rhel6u6.x86\_64.rpm

### **Enhancements**

RPMs are now signed. No other changes were made to the driver

### **Supported Devices and Features**

SUPPORTED KERNELS:

The kernels of Red Hat Enterprise Linux 6 (AMD64/EM64T) supported by this binary rpm are:

- 2.6.32-131.el6 - Red Hat Enterprise Linux 6 Update 1(AMD64/EM64T) and future errata kernels for update 1.
- 2.6.32-220.el6 - Red Hat Enterprise Linux 6 Update 2(AMD64/EM64T) and future errata kernels for update 2.
- 2.6.32-279.el6 - Red Hat Enterprise Linux 6 Update 3(AMD64/EM64T) and future errata kernels for update 3.
- 2.6.32-358.el6 - Red Hat Enterprise Linux 6 Update 4(AMD64/EM64T) and future errata kernels for update 4.
- 2.6.32-431.el6 - Red Hat Enterprise Linux 6 Update 5(AMD64/EM64T) and future errata kernels for update 5.
- 2.6.32-504.el6 - Red Hat Enterprise Linux 6 Update 6(AMD64/EM64T) and future errata kernels for update 6.

---

HP Smart Array B110i SATA RAID Controller Driver for Red Hat Enterprise Linux 6 (x86)

Version: 1.2.6-18 (A) **(Recommended)**

Filename: kmod-hpahcisr-1.2.6-18.rhel6u1.i686.rpm; kmod-hpahcisr-1.2.6-18.rhel6u2.i686.rpm; kmod-hpahcisr-1.2.6-18.rhel6u3.i686.rpm; kmod-hpahcisr-1.2.6-18.rhel6u4.i686.rpm; kmod-hpahcisr-1.2.6-18.rhel6u5.i686.rpm; kmod-hpahcisr-1.2.6-18.rhel6u6.i686.rpm

### **Enhancements**

RPMs are now signed. No other changes were made to the driver

### **Supported Devices and Features**

SUPPORTED KERNELS:

The kernels of Red Hat Enterprise Linux 6 (x86) supported by this binary rpm are:

- 2.6.32-131.el6 - Red Hat Enterprise Linux 6 Update 1(x86) and future errata kernels for update 1.
- 2.6.32-220.el6 - Red Hat Enterprise Linux 6 Update 2(x86) and future errata kernels for update 2.
- 2.6.32-279.el6 - Red Hat Enterprise Linux 6 Update 3(x86) and future errata kernels for update 3.
- 2.6.32-358.el6 - Red Hat Enterprise Linux 6 Update 4(x86) and future errata kernels for update 4.
- 2.6.32-431.el6 - Red Hat Enterprise Linux 6 Update 5(x86) and future errata kernels for update 5.
- 2.6.32-504.el6 - Red Hat Enterprise Linux 6 Update 6(x86) and future errata kernels for update 6.

---

HP Smart Array B110i SATA RAID Controller Driver for SUSE LINUX Enterprise Server 11 (AMD64/EM64T)

Version: 1.2.6-17 (A) **(Recommended)**

Filename: hpahcisr-kmp-default-1.2.6-17.sles11sp1.x86\_64.rpm; hpahcisr-kmp-default-1.2.6-17.sles11sp2.x86\_64.rpm; hpahcisr-kmp-default-1.2.6-17.sles11sp3.x86\_64.rpm

### **Enhancements**

RPMs are now signed. No other changes were made to the driver

## **Supported Devices and Features**

### SUPPORTED KERNELS:

The kernels of SUSE LINUX Enterprise Server 11 (AMD64/EM64T) supported by this binary rpm are:

2.6.32.12-0.7 - SUSE LINUX Enterprise Server 11 SP 1 (AMD64/EM64T) and future errata kernels for SP 1.

3.0.13-0.27.1 - SUSE LINUX Enterprise Server 11 SP 2 (AMD64/EM64T) and future errata kernels for SP 2.

3.0.76-0.11.1 - SUSE LINUX Enterprise Server 11 SP 3 (AMD64/EM64T) and future errata kernels for SP 3.

---

HP Smart Array B110i SATA RAID Controller Driver for SUSE LINUX Enterprise Server 11 (x86)

Version: 1.2.6-17 (A) **(Recommended)**

Filename: hpahcisr-kmp-default-1.2.6-17.sles11sp1.i586.rpm; hpahcisr-kmp-default-1.2.6-17.sles11sp2.i586.rpm; hpahcisr-kmp-default-1.2.6-17.sles11sp3.i586.rpm; hpahcisr-kmp-pae-1.2.6-17.sles11sp1.i586.rpm; hpahcisr-kmp-pae-1.2.6-17.sles11sp2.i586.rpm; hpahcisr-kmp-pae-1.2.6-17.sles11sp3.i586.rpm

## **Enhancements**

RPMs are now signed. No other changes were made to the driver

## **Supported Devices and Features**

### SUPPORTED KERNELS:

The kernels of SUSE LINUX Enterprise Server 11 (x86) supported by this binary rpm are:

2.6.32.12-0.7 - SUSE LINUX Enterprise Server 11 SP 1 (x86) and future errata kernels for SP 1.

3.0.13-0.27.1 - SUSE LINUX Enterprise Server 11 SP 2 (x86) and future errata kernels for SP 2.

3.0.76-0.11.1 - SUSE LINUX Enterprise Server 11 SP 3 (x86) and future errata kernels for SP 3.

---

HPE H2xx SAS/SATA Host Bus Adapter Driver for Red Hat Enterprise Linux 7 (64-bit)

Version: 15.10.06.00-5 **(Recommended)**

Filename: kmod-mpt2sas-15.10.05.00-3.rhel7u3.x86\_64.rpm; kmod-mpt2sas-15.10.06.00-5.rhel7u4.x86\_64.rpm

## **Enhancements**

Added support for Red Hat Enterprise LINUX 7 Update 4.

## **Supported Devices and Features**

### SUPPORTED KERNELS:

The kernels of Red Hat Enterprise Linux 7 (64-bit) supported by this binary rpm are:

3.10.0-514.el7- Red Hat Enterprise Linux 7 Update 3 (64-bit) and future errata kernels for update 3.

3.10.0-693.el7- Red Hat Enterprise Linux 7 Update 4 (64-bit) and future errata kernels for update 4.

**Note:** This driver component supports Gen9 servers only with H221 controllers and the controller does not support connection to D2600, D2700, and D6000 Disk Enclosures with Gen9 servers.

---

HPE H2xx SAS/SATA Host Bus Adapter Driver for SUSE LINUX Enterprise Server 12 (64-bit)

Version: 15.10.06.00-6 **(Recommended)**

Filename: lsi-mpt2sas-kmp-default-15.10.06.00-2.sles12sp2.x86\_64.rpm; lsi-mpt2sas-kmp-default-15.10.06.00-6.sles12sp3.x86\_64.rpm

## **Enhancements**

Added support for SUSE LINUX Enterprise Server 12 SP2 and SP3.

## **Supported Devices and Features**

SUPPORTED KERNELS:

The kernels of SUSE LINUX Enterprise Server 12 (64-bit) supported by this binary rpm are:

4.4.21-69-default - SUSE LINUX Enterprise Server 12 (64-bit) SP2 plus future errata.

4.4.73-5.1 -SUSE LINUX Enterprise Server 12 (64-bit) SP3 plus future errata.

**Note:** This driver component supports Gen9 servers only with H221 controllers and the controller does not support connection to D2600, D2700, and D6000 Disk Enclosures with Gen9 servers.

---

HPE ProLiant Smart Array Controller (32-bit) Driver for Red Hat Enterprise Linux 6 (32-bit)

Version: 3.4.20-100 **(Recommended)**

Filename: kmod-hpsa-3.4.20-100.rhel6u8.i686.rpm; kmod-hpsa-3.4.20-100.rhel6u9.i686.rpm

## **Fixes**

Fixed the below:

In a multipath configuration with heavy IO running, the controller might not switch all traffic to the active path when one path fails.

## **Supported Devices and Features**

SUPPORTED KERNELS:

The kernels of Red Hat Enterprise Linux 6 (x86) supported by this binary rpm are:

2.6.32-642.el6 - Red Hat Enterprise Linux 6 Update 8(x86) and future errata kernels for update 8.

2.6.32-696.el6 - Red Hat Enterprise Linux 6 Update 9(x86) and future errata kernels for update 9.

---

HPE ProLiant Smart Array Controller (64-bit) Driver for Red Hat Enterprise Linux 7 (64-bit)

Version: 3.4.20-113 **(Recommended)**

Filename: kmod-hpsa-3.4.20-113.rhel7u3.x86\_64.rpm; kmod-hpsa-3.4.20-113.rhel7u4.x86\_64.rpm

## **Fixes**

Fixed the below:

In a multipath configuration with heavy IO running, the controller might not switch all traffic to the active path when one path fails.

SmartPath might not be enabled in some situations.

## **Enhancements**

Added support for Red Hat Enterprise LINUX 7 Update 3.

Added support for Smart Array Controller P830 and P830i



## **Supported Devices and Features**

### SUPPORTED KERNELS:

The kernels of Red Hat Enterprise Linux 7 (64-bit) supported by this binary rpm are:

3.10.0-514.el7 - Red Hat Enterprise Linux 7 Update 3 (64-bit) and future errata kernels for update 3.

3.10.0-693.el7 - Red Hat Enterprise Linux 7 Update 4 (64-bit) and future errata kernels for update 4.

---

HPE ProLiant Smart Array Controller (AMD64/EM64T) Driver for Red Hat Enterprise Linux 6 (AMD64/EM64T)

Version: 3.4.18-108 **(Recommended)**

Filename: kmod-hpsa-3.4.18-108.rhel6u5.x86\_64.rpm; kmod-hpsa-3.4.18-108.rhel6u6.x86\_64.rpm; kmod-hpsa-3.4.18-108.rhel6u7.x86\_64.rpm; kmod-hpsa-3.4.18-108.rhel6u8.x86\_64.rpm; kmod-hpsa-3.4.18-108.rhel6u9.x86\_64.rpm

### **Fixes**

- In rare cases, the OS would offline drives.

### **Enhancements**

- Added support for Red Hat Enterprise Linux 6 Update 9.
- Multiple performance improvements.

## **Supported Devices and Features**

### SUPPORTED KERNELS:

The kernels of Red Hat Enterprise Linux 6 (AMD64/EM64T) supported by this driver diskette are:

2.6.32-431.el6 - Red Hat Enterprise Linux 6 Update 5(AMD64/EM64T) and future errata kernels for update 5.

2.6.32-504.el6 - Red Hat Enterprise Linux 6 Update 6(AMD64/EM64T) and future errata kernels for update 6.

2.6.32-573.el6 - Red Hat Enterprise Linux 6 Update 7(AMD64/EM64T) and future errata kernels for update 7.

2.6.32-642.el6 - Red Hat Enterprise Linux 6 Update 8(AMD64/EM64T) and future errata kernels for update 8.

2.6.32-696.el6 - Red Hat Enterprise Linux 6 Update 9(AMD64/EM64T) and future errata kernels for update 9.

---

HPE ProLiant Smart Array Controller (AMD64/EM64T) Driver for SUSE LINUX Enterprise Server 11 (AMD64/EM64T)

Version: 3.4.18-105 **(Recommended)**

Filename: hpsa-kmp-default-3.4.18-105.sles11sp1.x86\_64.rpm; hpsa-kmp-default-3.4.18-105.sles11sp2.x86\_64.rpm; hpsa-kmp-default-3.4.18-105.sles11sp3.x86\_64.rpm; hpsa-kmp-default-3.4.18-105.sles11sp4.x86\_64.rpm; hpsa-kmp-xen-3.4.18-105.sles11sp1.x86\_64.rpm; hpsa-kmp-xen-3.4.18-105.sles11sp2.x86\_64.rpm; hpsa-kmp-xen-3.4.18-105.sles11sp3.x86\_64.rpm; hpsa-kmp-xen-3.4.18-105.sles11sp4.x86\_64.rpm

### **Fixes**

- In rare cases, the OS would offline drives.

### **Enhancements**

- Multiple performance improvements.

## **Supported Devices and Features**

The kernels of SUSE LINUX Enterprise Server 11 (AMD64/EM64T) supported by this driver diskette are:  
2.6.32.12-0.7 - SUSE LINUX Enterprise Server 11 SP 1 (AMD64/EM64T) and future errata kernels for SP 1.  
3.0.13-0.27.1 - SUSE LINUX Enterprise Server 11 SP 2 (AMD64/EM64T) and future errata kernels for SP 2.  
3.0.76-0.11.1 - SUSE LINUX Enterprise Server 11 SP 3 (AMD64/EM64T) and future errata kernels for SP 3.  
3.0.101-63-default - SUSE LINUX Enterprise Server 11 SP 4 (AMD64/EM64T) and future errata kernels for SP 4.

---

HPE ProLiant Smart Array Controller Driver for VMware vSphere 5.5 (Bundle file)

Version: 5.5.0.124-1 (**Recommended**)

Filename: hpsa-5.5.0.124-4683595.zip

### **Fixes**

Below is fixed in the hpsa driver version 5.5.0.124-1

On HPE ProLiant servers, reinserting and reactivating a previously hot-removed RAID 0 disk may cause the volume to fail to return to an online or ready state in VMware vSphere 5.5. The HPE Smart Array (HPSA) driver prevents the unplugged volume's offline state from being recognized by driver and when the volume is physically reinserted and reactivated with the Smart Storage Administrator (SSA) utility, the volume status remains as offline in a VMware vSAN environment.

### **Supported Devices and Features**

Following is the list of Controllers supported by version 5.5.0.124-1 driver:

HP Smart Array P230i Controller  
HP Smart Array P240nr Controller  
HP Smart Array P244br Controller  
HP Smart Array P246br Controller  
HP Smart Array P430 Controller  
HP Smart Array P431 Controller  
HP Smart Array P440 Controller  
HP Smart Array P440ar Controller  
HP Smart Array P441 Controller  
HP Smart Array P542D Controller  
HP Smart Array P731m Controller  
HP Smart Array P741m Controller  
HP Smart Array P812 Controller  
HP Smart Array P822 Controller  
HP Smart Array P830 Controller  
HP Smart Array P830i Controller  
HP Smart Array P840 Controller  
HP Smart Array P840ar Controller  
HP Smart Array P841 Controller  
HP Smart HBA H240  
HP Smart HBA H240ar  
HP Smart HBA H240nr Controller  
HP Smart HBA H241  
HP Smart HBA H244br  
Smart Array P212  
Smart Array P220i  
Smart Array P222  
Smart Array P410  
Smart Array P410i  
Smart Array P411

Smart Array P420  
Smart Array P420i  
Smart Array P421  
Smart Array P700m  
Smart Array P711m  
Smart Array P712m  
Smart Array P721m

---

HPE ProLiant Smart Array Controller Driver for VMware vSphere 5.5 (Driver Component).

Version: 2016.11.18 **(Recommended)**

Filename: cp031417.zip

### **Important Note!**

This component is intended to be used by HPE applications. It is a zip that contains the same driver deliverable available from the vmware.com and the HPE <http://vibsdepot.hpe.com/> webpages, plus an HPE specific CPXXXX.xml file.

### **Fixes**

Below is fixed in the hpsa driver version 5.5.0.124-1

On HPE ProLiant servers, reinserting and reactivating a previously hot-removed RAID 0 disk may cause the volume to fail to return to an online or ready state in VMware vSphere 5.5. The HPE Smart Array (HPSA) driver prevents the unplugged volume's offline state from being recognized by driver and when the volume is physically reinserted and reactivated with the Smart Storage Administrator (SSA) utility, the volume status remains as offline in a VMware vSAN environment.

### **Supported Devices and Features**

Following is the list of Controllers supported by version 2016.10.21 of the Driver Component:

HP Smart Array P230i Controller  
HP Smart Array P240nr Controller  
HP Smart Array P244br Controller  
HP Smart Array P246br Controller  
HP Smart Array P430 Controller  
HP Smart Array P431 Controller  
HP Smart Array P440 Controller  
HP Smart Array P440ar Controller  
HP Smart Array P441 Controller  
HP Smart Array P542D Controller  
HP Smart Array P731m Controller  
HP Smart Array P741m Controller  
HP Smart Array P812 Controller  
HP Smart Array P822 Controller  
HP Smart Array P830 Controller  
HP Smart Array P830i Controller  
HP Smart Array P840 Controller  
HP Smart Array P840ar Controller  
HP Smart Array P841 Controller  
HP Smart HBA H240

HP Smart HBA H240ar  
HP Smart HBA H240nr Controller  
HP Smart HBA H241  
HP Smart HBA H244br  
Smart Array P212  
Smart Array P220i  
Smart Array P222  
Smart Array P410  
Smart Array P410i  
Smart Array P411  
Smart Array P420  
Smart Array P420i  
Smart Array P421  
Smart Array P700m  
Smart Array P711m  
Smart Array P712m  
Smart Array P721m

---

HPE ProLiant Smart Array Controller Driver for VMware vSphere 6.0 (Bundle file)

Version: 6.0.0.124-1 **(Recommended)**

Filename: hpsa-6.0.0.124-4683364.zip

### **Fixes**

Below is fixed in the hpsa driver version 6.0.0.124-1

On HPE ProLiant servers, reinserting and reactivating a previously hot-removed RAID 0 disk may cause the volume to fail to return to an online or ready state in VMware vSphere 6.0. The HPE Smart Array (HPSA) driver prevents the unplugged volume's offline state from being recognized by driver and when the volume is physically reinserted and reactivated with the Smart Storage Administrator (SSA) utility, the volume status remains as offline in a VMware vSAN environment.

### **Supported Devices and Features**

Following is the list of Controllers supported by version 6.0.0.124-1 driver:

HP Smart Array P230i Controller  
HP Smart Array P240nr Controller  
HP Smart Array P244br Controller  
HP Smart Array P246br Controller  
HP Smart Array P430 Controller  
HP Smart Array P431 Controller  
HP Smart Array P440 Controller  
HP Smart Array P440ar Controller  
HP Smart Array P441 Controller  
HP Smart Array P542D Controller  
HP Smart Array P731m Controller  
HP Smart Array P741m Controller  
HP Smart Array P812 Controller  
HP Smart Array P822 Controller  
HP Smart Array P830 Controller  
HP Smart Array P830i Controller

HP Smart Array P840 Controller  
HP Smart Array P840ar Controller  
HP Smart Array P841 Controller  
HP Smart HBA H240  
HP Smart HBA H240ar  
HP Smart HBA H240nr Controller  
HP Smart HBA H241  
HP Smart HBA H244br  
Smart Array P212  
Smart Array P220i  
Smart Array P222  
Smart Array P410  
Smart Array P410i  
Smart Array P411  
Smart Array P420  
Smart Array P420i  
Smart Array P421  
Smart Array P700m  
Smart Array P711m  
Smart Array P712m  
Smart Array P721m

---

HPE ProLiant Smart Array Controller Driver for VMware vSphere 6.0 (Driver Component).

Version: 2016.11.18 **(Recommended)**

Filename: cp031418.zip

### **Important Note!**

This component is intended to be used by HPE applications. It is a zip that contains the same driver deliverable available from the vmware.com and the HPE <http://vibsdepot.hpe.com/> webpages, plus an HPE specific CPXXXX.xml file.

### **Fixes**

Below is fixed in the hpsa driver version 6.0.0.124-1

On HPE ProLiant servers, reinserting and reactivating a previously hot-removed RAID 0 disk may cause the volume to fail to return to an online or ready state in VMware vSphere 6.0. The HPE Smart Array (HPSA) driver prevents the unplugged volume's offline state from being recognized by driver and when the volume is physically reinserted and reactivated with the Smart Storage Administrator (SSA) utility, the volume status remains as offline in a VMware vSAN environment.

### **Supported Devices and Features**

Following is the list of Controllers supported by version 2016.10.21 of the Driver Component:

HP Smart Array P230i Controller  
HP Smart Array P240nr Controller  
HP Smart Array P244br Controller  
HP Smart Array P246br Controller  
HP Smart Array P430 Controller  
HP Smart Array P431 Controller

HP Smart Array P440 Controller  
HP Smart Array P440ar Controller  
HP Smart Array P441 Controller  
HP Smart Array P542D Controller  
HP Smart Array P731m Controller  
HP Smart Array P741m Controller  
HP Smart Array P812 Controller  
HP Smart Array P822 Controller  
HP Smart Array P830 Controller  
HP Smart Array P830i Controller  
HP Smart Array P840 Controller  
HP Smart Array P840ar Controller  
HP Smart Array P841 Controller  
HP Smart HBA H240  
HP Smart HBA H240ar  
HP Smart HBA H240nr Controller  
HP Smart HBA H241  
HP Smart HBA H244br  
Smart Array P212  
Smart Array P220i  
Smart Array P222  
Smart Array P410  
Smart Array P410i  
Smart Array P411  
Smart Array P420  
Smart Array P420i  
Smart Array P421  
Smart Array P700m  
Smart Array P711m  
Smart Array P712m  
Smart Array P721m

---

HPE ProLiant Smart Array HPCISS3 Controller Driver for Windows Server 2008 x64 Edition

Version: 6.12.0.64 (A) **(Recommended)**

Filename: cp030674.exe

### **Enhancements**

Added support for:

HPE Smart HBA H240nr Controller.

HPE Smart Array P240nr Controller.

HPE Smart Array P542D Controller.

---

### **Driver - Storage Fibre Channel and Fibre Channel Over Ethernet**

[Top](#)

HP Storage Fibre Channel Over Ethernet Adapter Kit for the QLogic Storport Driver for Windows Server 2012 and 2012 R2

Version: 9.1.13.10 **(Recommended)**

Filename: cp025684.exe

### **Important Note!**

Release Notes:

[HP StorageWorks QLogic Adapters Release Notes](#)

### **Fixes**

- Fixed condition to account for tape retry delay time when SCSI status busy and queue full without other status bits.

### **Enhancements**

Updated to driver version 9.1.13.10

### **Supported Devices and Features**

This driver supports the following HP adapters:

- HP CN1000Q Dual Port Converged Network Adapter
- HP FlexFabric 10Gb 2-port 526FLR-SFP+ Adapter

---

HP Storage Fibre Channel Over Ethernet Adapter Kit for the x64 QLogic Storport Driver

Version: 9.1.13.10 **(Recommended)**

Filename: cp025685.exe

### **Important Note!**

Release Notes:

[HP StorageWorks QLogic Adapters Release Notes](#)

### **Fixes**

- Fixed condition to account for tape retry delay time when SCSI status busy and queue full without other status bits.

### **Enhancements**

9.1.13.10 version

### **Supported Devices and Features**

This driver supports the following HP adapters:

- HP CN1000Q Dual Port Converged Network Adapter
- HP FlexFabric 10Gb 2-port 526FLR-SFP+ Adapter

---

HP Storage Fibre Channel Over Ethernet Adapter Kit for the x86 QLogic Storport Driver

Version: 9.1.13.10 **(Recommended)**

Filename: cp025686.exe

### **Important Note!**

Release Notes:

[HP StorageWorks QLogic Adapters Release Notes](#)

### **Fixes**

- Fixed condition to account for tape retry delay time when SCSI status busy and queue full without other status bits.

### **Enhancements**

Updated the Smart Component to contain driver version 9.1.13.10

### **Supported Devices and Features**

This driver supports the following HP adapters:

- HP CN1000Q Dual Port Converged Network Adapter
- HP FlexFabric 10Gb 2-port 526FLR-SFP+ Adapter

---

HP Storage QLogic BR-series Storport Fibre Channel Host Bus Adapter Driver for Microsoft Windows Server 2012

Version: 3.2.5.0 **(Recommended)**

Filename: cp025313.exe

### **Important Note!**

Release Notes:

[HP StorageWorks Brocade Fibre Channel Host Bus Adapters Release Notes](#)

To keep drivers and boot code synchronized, be sure to update your adapter with the latest boot image from [www.hp.com](http://www.hp.com) before you install or update adapter driver packages.



### **Enhancements**

Updated driver version to 3.2.5.0. This driver will identify 8Gb HBA/mezzanine cards as "QLogic" or "QLogic BR-series" in product description displays.

### **Supported Devices and Features**

This driver supports the following HP adapters:

- HP 81B PCIe 8Gb Fibre Channel Single Port Host Bus Adapter
- HP 82B PCIe 8Gb Fibre Channel Dual Port Host Bus Adapter
- Brocade 804 8Gb Fibre Channel HBA for c-Class BladeSystem

---

HP Storage QLogic BR-series Storport Fibre Channel Host Bus Adapter Driver for Microsoft Windows Server 2012 R2

Version: 3.2.5.0 **(Recommended)**

Filename: cp025052.exe

### **Important Note!**



Release Notes:

[HP StorageWorks Brocade Fibre Channel Host Bus Adapters Release Notes](#)

To keep drivers and boot code synchronized, be sure to update your adapter with the latest boot image from [www.hp.com](http://www.hp.com) before you install or update adapter driver packages.



### **Enhancements**

Updated driver version to 3.2.5.0. This driver will identify 8Gb HBA/mezzanine cards as "QLogic" or "QLogic BR-series" in product description displays.

### **Supported Devices and Features**

This driver supports the following HP adapters:

- HP 81B PCIe 8Gb Fibre Channel Single Port Host Bus Adapter
- HP 82B PCIe 8Gb Fibre Channel Dual Port Host Bus Adapter
- Brocade 804 8Gb Fibre Channel HBA for c-Class BladeSystem

---

HP Storage x64 QLogic BR-series Storport Fibre Channel Host Bus Adapter Driver for Microsoft Windows Server 2008 R2

Version: 3.2.5.0 **(Recommended)**

Filename: cp025314.exe

### **Important Note!**

Release Notes:

[HP StorageWorks Brocade Fibre Channel Host Bus Adapters Release Notes](#)

To keep drivers and boot code synchronized, be sure to update your adapter with the latest boot image from [www.hp.com](http://www.hp.com) before you install or update adapter driver packages.

### **Enhancements**

Updated driver version to 3.2.5.0. This driver will identify 8Gb HBA/mezzanine cards as "QLogic" or "QLogic BR-series" in product description displays.

### **Supported Devices and Features**

This driver supports the following HP adapters:

- HP 81B PCIe 8Gb Fibre Channel Single Port Host Bus Adapter
  - HP 82B PCIe 8Gb Fibre Channel Dual Port Host Bus Adapter
  - Brocade 804 8Gb Fibre Channel HBA for c-Class BladeSystem
-

HPE Storage Fibre Channel Adapter Kit for the QLogic Storport Driver for Windows Server 2012 and 2012 R2

Version: 9.1.17.25 **(Recommended)**

Filename: cp031889.exe

### **Important Note!**

Release Notes:

[HPE StoreFabric QLogic Adapters Release Notes](#)

### **Fixes**

The driver update is a workaround to address unexpected path loss behavior during Brocade switch FOS upgrades

### **Enhancements**

updated to driver version 9.1.17.25

### **Supported Devices and Features**

This driver supports the following adapters:

- HP FC1142SR 4Gb PCIe Host Bus Adapter
- HP FC1242SR 4Gb PCIe DC Host Bus Adapter
- HP 81Q PCIe Fibre Channel Host Bus Adapter
- HP 82Q 8Gb Dual Port PCIe Fibre Channel Host Bus Adapter
- QLogic QMH2562 8Gb Fibre Channel Host Bus Adapter for c-Class BladeSystem
- QLogic QMH2462 4Gb Fibre Channel Host Bus Adapter for c-Class BladeSystem
- HP QMH2572 8Gb Fibre Channel Host Bus Adapter for c-Class BladeSystem
- HP QMH2672 16Gb Fibre Channel Host Bus Adapter for c-Class BladeSystem
- HP StoreFabric SN1000Q 16GB 2-port PCIe Fibre Channel Host Bus Adapter
- HP StoreFabric SN1000Q 16GB 1-port PCIe Fibre Channel Host Bus Adapter
- HPE StoreFabric SN1100Q 16GB 2-port PCIe Fibre Channel Host Bus Adapter
- HPE StoreFabric SN1100Q 16GB 1-port PCIe Fibre Channel Host Bus Adapter
- HPE StoreFabric 84Q 4P 8Gb Fibre Channel HBA
- HPE Synergy 3830C 16G Fibre Channel Host Bus Adapter

---

HPE Storage Fibre Channel Adapter Kit for the QLogic Storport Driver for Windows Server 2016

Version: 9.2.2.20 **(Recommended)**

Filename: cp029979.exe

### **Important Note!**

Release Notes:

[HPE StoreFabric QLogic Adapters Release Notes](#)

### **Enhancements**

Initial driver version 9.2.2.20

## **Supported Devices and Features**

This driver supports the following adapters:

- HP 81Q PCIe Fibre Channel Host Bus Adapter
- HP 82Q 8Gb Dual Port PCIe Fibre Channel Host Bus Adapter
- QLogic QMH2562 8Gb Fibre Channel Host Bus Adapter for c-Class BladeSystem
- HP QMH2572 8Gb Fibre Channel Host Bus Adapter for c-Class BladeSystem
- HP QMH2672 16Gb Fibre Channel Host Bus Adapter for c-Class BladeSystem
- HP StoreFabric SN1000Q 16GB 2-port PCIe Fibre Channel Host Bus Adapter
- HP StoreFabric SN1000Q 16GB 1-port PCIe Fibre Channel Host Bus Adapter
- HPE StoreFabric SN1100Q 16GB 2-port PCIe Fibre Channel Host Bus Adapter
- HPE StoreFabric SN1100Q 16GB 1-port PCIe Fibre Channel Host Bus Adapter
- HPE StoreFabric 84Q 4P 8Gb Fibre Channel HBA
- HPE Synergy 3830C 16G Fibre Channel Host Bus Adapter

---

HPE Storage Fibre Channel Adapter Kit for the x64 Emulex Storport Driver

Version: 11.1.145.16 (C) **(Recommended)**

Filename: cp031671.exe

### **Important Note!**

Release Notes:

[HPE StoreFabric Emulex Adapters Release Notes](#)

### **Prerequisites**

Please consult SPOCK for a list of supported configurations available at the following link:

<http://www.hpe.com/storage/spock/>

### **Enhancements**

This driver, version 11.1.145.16, adds support for the following devices:

- HPE StoreFabric SN1200E 16Gb 2P FC HBA
- HPE StoreFabric SN1200E 16Gb 1P FC HBA
- HPE StoreFabric SN1600E 32Gb 2p FC HBA
- HPE StoreFabric SN1600E 32Gb 1p FC HBA

The raw driver files can be obtained by extracting the Smart Component and then extracting the Emulex installer. Use this command:

```
elxdvrv-fcoe-version.exe /q2 extract=2
```

The extracted files are located:

```
C:\Users\Administrator\Documents\Emulex\Drivers\FCoE-version
```

Each kit folder has subsequent architecture folders with subsequent OS folders. For example,

```
C:\Users\Administrator\Documents\Emulex\Drivers\FCoE-version\x64\win2008
```

## **Supported Devices and Features**

- HP 82E 8Gb Dual Port PCIe Fibre Channel Host Bus Adapter
- HP 81E 8Gb Single Port PCIe Fibre Channel Host Bus Adapter
- HP SN1000E 16Gb Dual Port Fibre Channel Host Bus Adapter
- HP SN1000E 16Gb Single Port Fibre Channel Host Bus Adapter
- HP LPe1205A 8Gb Fibre Channel Host Bus Adapter for BladeSystem c-Class
- Emulex LPe1205 8Gb Fibre Channel Host Bus Adapter for c-Class BladeSystem
- HP SN1100E 16Gb Dual Port Fibre Channel Host Bus Adapter
- HP SN1100E 16Gb Single Port Fibre Channel Host Bus Adapter
- HP Fibre Channel 16Gb LPe1605 Mezz Adapter
- HP StoreFabric 84E 4-Port Fibre Channel Host Bus Adapter
- HPE Synergy 3530C 16Gb Fibre Channel Host Bus Adapter
- HPE StoreFabric SN1100E 4P 16Gb FC HBA
- HPE StoreFabric SN1200E 16Gb 2P FC HBA
- HPE StoreFabric SN1200E 16Gb 1P FC HBA
- HPE StoreFabric SN1600E 32Gb 2p FC HBA
- HPE StoreFabric SN1600E 32Gb 1p FC HBA

---

HP Storage Fibre Channel Adapter Kit for the x64 QLogic Storport Driver

Version: 9.1.17.25 **(Recommended)**

Filename: cp031888.exe

### **Important Note!**

Release Notes:

[HPE StoreFabric QLogic Adapters Release Notes](#)

### **Fixes**

The driver update is a workaround to address unexpected path loss behavior during Brocade switch FOS upgrades

### **Enhancements**

Updated to driver version 9.1.17.25.

## **Supported Devices and Features**

This driver supports the following adapters:

- HP FC1142SR 4Gb PCIe Host Bus Adapter
- HP FC1242SR 4Gb PCIe DC Host Bus Adapter
- HP 81Q PCIe Fibre Channel Host Bus Adapter
- HP 82Q 8Gb Dual Port PCIe Fibre Channel Host Bus Adapter
- QLogic QMH2562 8Gb Fibre Channel Host Bus Adapter for c-Class BladeSystem
- QLogic QMH2462 4Gb Fibre Channel Host Bus Adapter for c-Class BladeSystem
- HP QMH2572 8Gb Fibre Channel Host Bus Adapter for c-Class BladeSystem
- HP QMH2672 16Gb Fibre Channel Host Bus Adapter for c-Class BladeSystem
- HP StoreFabric SN1000Q 16GB 2-port PCIe Fibre Channel Host Bus Adapter

- HP StoreFabric SN1000Q 16GB 1-port PCIe Fibre Channel Host Bus Adapter
- HPE StoreFabric SN1100Q 16GB 2-port PCIe Fibre Channel Host Bus Adapter
- HPE StoreFabric SN1100Q 16GB 1-port PCIe Fibre Channel Host Bus Adapter
- HPE StoreFabric 84Q 4P 8Gb Fibre Channel HBA
- HPE Synergy 3830C 16G Fibre Channel Host Bus Adapter

---

HPE Storage Fibre Channel Adapter Kit for the x86 Emulex Storport Driver

Version: 11.1.145.16 **(Recommended)**

Filename: cp029980.exe

### **Important Note!**

Release Notes:

[HPE StoreFabric Emulex Adapters Release Notes](#)

### **Enhancements**

Updated to driver version 11.1.145.16

- Added automatic recovery from errors that previously required a system reboot
- Added SmartSAN 2.0 support

Removed the raw driver file folder. The raw driver files can be obtained by extracting the Smart Component and then extracting the Emulex installer. Use this command:

```
elxdvrv-fcoe-version.exe /q2 extract=2
```

The extracted files are located:

```
C:\Users\Administrator\Documents\Emulex\Drivers\FCoE-version
```

Each kit folder has subsequent architecture folders with subsequent OS folders. For example,

```
C:\Users\Administrator\Documents\Emulex\Drivers\FCoE-version\x64\win2008
```

### **Supported Devices and Features**

- HP 82E 8Gb Dual Port PCIe Fibre Channel Host Bus Adapter
- HP 81E 8Gb Single Port PCIe Fibre Channel Host Bus Adapter
- HP SN1000E 16Gb Dual Port Fibre Channel Host Bus Adapter
- HP SN1000E 16Gb Single Port Fibre Channel Host Bus Adapter
- HP LPe1205A 8Gb Fibre Channel Host Bus Adapter for BladeSystem c-Class
- Emulex LPe1205 8Gb Fibre Channel Host Bus Adapter for c-Class BladeSystem
- HP SN1100E 16Gb Dual Port Fibre Channel Host Bus Adapter
- HP SN1100E 16Gb Single Port Fibre Channel Host Bus Adapter
- HP Fibre Channel 16Gb LPe1605 Mezz Adapter
- HP StoreFabric 84E 4-Port Fibre Channel Host Bus Adapter

---

HPE Storage Fibre Channel Adapter Kit for the x86 QLogic Storport Driver

Version: 9.1.17.25 **(Recommended)**

Filename: cp031887.exe

### **Important Note!**

Release Notes:

[HPE StoreFabric QLogic Adapters Release Notes](#)

### **Fixes**

The driver update is a workaround to address unexpected path loss behavior during Brocade switch FOS upgrades

### **Enhancements**

Updated to Driver version 9.1.17.25

### **Supported Devices and Features**

This driver supports the following HP adapters:

- HP FC1142SR 4Gb PCIe Host Bus Adapter
- HP FC1242SR 4Gb PCIe DC Host Bus Adapter
- HP 81Q PCIe Fibre Channel Host Bus Adapter
- HP 82Q 8Gb Dual Port PCIe Fibre Channel Host Bus Adapter
- QLogic QMH2562 8Gb Fibre Channel Host Bus Adapter for c-Class BladeSystem
- QLogic QMH2462 4Gb Fibre Channel Host Bus Adapter for c-Class BladeSystem
- HP QMH2572 8Gb Fibre Channel Host Bus Adapter for c-Class BladeSystem
- HP QMH2672 16Gb FC HBA for c-Class BladeSystem
- HP StoreFabric SN1000Q 16GB 2-port PCIe Fibre Channel Host Bus Adapter
- HP StoreFabric SN1000Q 16GB 1-port PCIe Fibre Channel Host Bus Adapter

---

HPE Storage Fibre Channel Over Ethernet Adapter Kit for the x64 Emulex Storport Driver

Version: 11.1.145.16 **(Recommended)**

Filename: cp029983.exe

### **Important Note!**

Release Notes:

[HPE StoreFabric Emulex Adapters Release Notes](#)

### **Enhancements**

Updated to driver version 11.1.145.16

- Added support for Windows Server 2016
- Added automatic recovery from errors that previously required a system reboot
- Added SmartSAN 2.0 support

Removed the raw driver file folder. The raw driver files can be obtained by extracting the Smart Component and then extracting the Emulex installer. Use this command:

```
elxdrv-fcoe-version.exe /q2 extract=2
```

The extracted files are located:

```
C:\Users\Administrator\Documents\Emulex\Drivers\FCoE-version
```

Each kit folder has subsequent architecture folders with subsequent OS folders. For example,

```
C:\Users\Administrator\Documents\Emulex\Drivers\FCoE-version\x64\win2008
```

## **Supported Devices and Features**

This driver supports the following HP adapters:

- HP NC553i 10Gb 2-port FlexFabric Converged Network Adapter
- HP StorageWorks CN1100E Dual Port Converged Network Adapter
- HP FlexFabric 10Gb 2-port 554FLB Adapter
- HP FlexFabric 10Gb 2-port 554FLR-SFP+ Adapter
- HP FlexFabric 10Gb 2-port 554M Adapter
- HP FlexFabric 20Gb 2-port 650FLB Adapter
- HP FlexFabric 20Gb 2-port 650M Adapter
- HP FlexFabric 10Gb 2-port 556FLR-SFP+ Adapter
- HP StoreFabric CN1200E Dual Port Converged Network Adapter
- HPE StoreFabric CN1200E-T Adapter
- HPE FlexFabric 10Gb 2-port 556FLR-T Adapter

---

HPE Storage Fibre Channel Over Ethernet Adapter Kit for the x86 Emulex Storport Driver

Version: 11.1.145.16 **(Recommended)**

Filename: cp029982.exe

## **Important Note!**

Release Notes:

[HPE Storefabric Emulex Adapters Release Notes](#)

## **Enhancements**

Updated to driver version 11.1.145.16

- Added automatic recovery from errors that previously required a system reboot
- Added SmartSAN 2.0 support

Removed the raw driver file folder. The raw driver files can be obtained by extracting the Smart Component and then extracting the Emulex installer. Use this command:

```
elxdrv-fcoe-version.exe /q2 extract=2
```

The extracted files are located:

```
C:\Users\Administrator\Documents\Emulex\Drivers\FCoE-version
```

Each kit folder has subsequent architecture folders with subsequent OS folders. For example,

C:\Users\Administrator\Documents\Emulex\Drivers\FCoE-version\x64\win2008

## **Supported Devices and Features**

This driver supports the following HP adapters:

- HP NC553i 10Gb 2-port FlexFabric Converged Network Adapter
- HP StorageWorks CN1100E Dual Port Converged Network Adapter
- HP FlexFabric 10Gb 2-port 554FLB Adapter
- HP FlexFabric 10Gb 2-port 554FLR-SFP+ Adapter
- HP FlexFabric 10Gb 2-port 554M Adapter

---

Red Hat Enterprise Linux 6 Server (x86-64) FCoE/FC Driver Kit for HPE Emulex CNAs, HBAs and mezzanine HBAs and CNAs

Version: 11.1.183.21 (C) **(Recommended)**

Filename: kmod-elx-lpfc-11.1.183.21-1.rhel6u6.x86\_64.rpm; kmod-elx-lpfc-11.1.183.21-1.rhel6u7.x86\_64.rpm; kmod-elx-lpfc-11.1.183.21-1.rhel6u8.x86\_64.rpm

## **Important Note!**

Release Notes:

[HPE StoreFabric Emulex Adapters Release Notes](#)

## **Prerequisites**

Please consult SPOCK for a list of supported configurations available at the following link:

<http://www.hpe.com/storage/spock/>

## **Enhancements**

This driver, version 11.1.183.21, adds support for the following devices:

- HPE StoreFabric SN1200E 16Gb 2P FC HBA
- HPE StoreFabric SN1200E 16Gb 1P FC HBA
- HPE StoreFabric SN1600E 32Gb 2p FC HBA
- HPE StoreFabric SN1600E 32Gb 1p FC HBA

## **Supported Devices and Features**

- 
- HP NC553i 10Gb 2-port FlexFabric Converged Network Adapter
- HP SN1000E 16Gb Dual Port Fibre Channel Host Bus Adapter
- HP SN1000E 16Gb Single Port Fibre Channel Host Bus Adapter
- HP 82E 8Gb Dual Port PCIe Fibre Channel Host Bus Adapter
- HP 81E 8Gb Single Port PCIe Fibre Channel Host Bus Adapter
- HP CN1100E Dual Port Converged Network Adapter
- HP FlexFabric 10Gb 2-port 554M Adapter
- HP FlexFabric 10Gb 2-port 554FLR-SFP+ Adapter



- HP FlexFabric 10Gb 2-port 554FLB Adapter
- HP LPe1205A 8Gb Fibre Channel Host Bus Adapter for BladeSystem c-Class
- Emulex LPe1205 8Gb Fibre Channel Host Bus Adapter for c-Class BladeSystem
- HP SN1100E 16Gb Dual Port Fibre Channel Host Bus Adapter
- HP SN1100E 16Gb Single Port Fibre Channel Host Bus Adapter
- HP LPe1605 16Gb Fibre Channel Host Bus Adapter for BladeSystem c-Class
- HP FlexFabric 20Gb 2-port 650FLB Adapter
- HP FlexFabric 20Gb 2-port 650M Adapter
- HP FlexFabric 10Gb 2-port 556FLR-SFP+ Adapter
- HP StoreFabric CN1200E Dual Port Converged Network Adapter
- HPE FlexFabric 10Gb 2-port 556FLR-T Adapter
- HPE StoreFabric CN1200E-T 10GBASE-T Converged Network Adapter
- HP StoreFabric 84E 4-Port Fibre Channel Host Bus Adapter
- HPE Synergy 3530C 16Gb Fibre Channel Host Bus Adapter
- HPE StoreFabric SN1100E 4P 16Gb FC HBA
- HPE StoreFabric SN1200E 16Gb 2P FC HBA
- HPE StoreFabric SN1200E 16Gb 1P FC HBA
- HPE StoreFabric SN1600E 32Gb 2p FC HBA
- HPE StoreFabric SN1600E 32Gb 1p FC HBA

---

Red Hat Enterprise Linux 6 Server (x86-64) FCoE/FC Driver Kit for HPE Qlogic CNAs, HBAs and mezzanine HBAs

Version: 8.07.00.34.06.0-k1 (b) **(Recommended)**

Filename: kmod-qlgc-qla2xxx-8.07.00.34.06.0\_k1-1.rhel6u9.x86\_64.rpm; kmod-qlgc-qla2xxx-8.07.00.34.06.0\_k1-2.rhel6u7.x86\_64.rpm; kmod-qlgc-qla2xxx-8.07.00.34.06.0\_k1-2.rhel6u8.x86\_64.rpm

### **Important Note!**

Release Notes

[HPE StoreFabric QLogic Adapters Release Notes](#)

Note: The rpm base-name for the QLogic driver has been changed to "qlgc". Upgrades from the earlier "hpqlgc" driver are supported.

### **Enhancements**

Initial support for Red Hat Enterprise Linux 6 update 9

driver version 8.07.00.34.06.0-k1

### **Supported Devices and Features**

This driver supports the following HP adapters:

- HP FC1142SR 4Gb PCIe Host Bus Adapter
- HP FC1242SR 4Gb PCIe DC Host Bus Adapter
- HP 81Q PCIe Fibre Channel Host Bus Adapter
- HP 82Q 8Gb Dual Port PCIe Fibre Channel Host Bus Adapter

- o QLogic QMH2562 8Gb Fibre Channel Host Bus Adapter for c-Class BladeSystem
- o QLogic QMH2462 4Gb Fibre Channel Host Bus Adapter for c-Class BladeSystem
- o HP QMH2572 8Gb Fibre Channel Host Bus Adapter for c-Class BladeSystem
- o HP StoreFabric SN1000Q 16Gb PCIe Fibre Channel Host Bus Adapter
- o HP QMH2672 16Gb FC HBA for c-Class BladeSystem
- o HP FlexFabric 10Gb 2-port 526FLR-SFP+ Adapter
- o HP CN1000Q Dual Port Converged Network Adapter
- o HP StoreFabric SN1000Q 16GB 2-port PCIe Fibre Channel Host Bus Adapter
- o HP StoreFabric SN1000Q 16GB 1-port PCIe Fibre Channel Host Bus Adapter
- o HPE StoreFabric 84Q 4P 8Gb Fibre Channel HBA
- o HPE StoreFabric SN1100Q 16Gb 2P FC HBA
- o HPE StoreFabric SN1100Q 16Gb 1P FC HBA
- o HPE Synergy 3830C 16G Fibre Channel Host Bus Adapter

---

Red Hat Enterprise Linux 7 Server FCoE/FC Driver Kit for HPE Emulex CNAs, HBAs and mezzanine HBAs and CNAs

Version: 11.1.183.21 (C) **(Recommended)**

Filename: kmod-elx-lpfc-11.1.183.21-1.rhel7u1.x86\_64.rpm; kmod-elx-lpfc-11.1.183.21-1.rhel7u2.x86\_64.rpm

### **Important Note!**

Release Notes:

[HPE StoreFabric Emulex Adapters Release Notes](#)

### **Prerequisites**

Please consult SPOCK for a list of supported configurations available at the following link:

<http://www.hpe.com/storage/spock/>

### **Enhancements**

This driver, version 11.1.183.21, adds support for the following devices:

- o HPE StoreFabric SN1200E 16Gb 2P FC HBA
- o HPE StoreFabric SN1200E 16Gb 1P FC HBA
- o HPE StoreFabric SN1600E 32Gb 2p FC HBA
- o HPE StoreFabric SN1600E 32Gb 1p FC HBA

### **Supported Devices and Features**

- o HP NC553i 10Gb 2-port FlexFabric Converged Network Adapter
- o HP SN1000E 16Gb Dual Port Fibre Channel Host Bus Adapter
- o HP SN1000E 16Gb Single Port Fibre Channel Host Bus Adapter
- o HP 82E 8Gb Dual Port PCIe Fibre Channel Host Bus Adapter
- o HP 81E 8Gb Single Port PCIe Fibre Channel Host Bus Adapter
- o HP CN1100E Dual Port Converged Network Adapter
- o HP FlexFabric 10Gb 2-port 554M Adapter
- o HP FlexFabric 10Gb 2-port 554FLR-SFP+ Adapter
- o HP FlexFabric 10Gb 2-port 554FLB Adapter
- o HP LPe1205A 8Gb Fibre Channel Host Bus Adapter for BladeSystem c-Class
- o Emulex LPe1205 8Gb Fibre Channel Host Bus Adapter for c-Class BladeSystem

- HP SN1100E 16Gb Dual Port Fibre Channel Host Bus Adapter
- HP SN1100E 16Gb Single Port Fibre Channel Host Bus Adapter
- HP LPe1605 16Gb Fibre Channel Host Bus Adapter for BladeSystem c-Class
- HP FlexFabric 20Gb 2-port 650FLB Adapter
- HP FlexFabric 20Gb 2-port 650M Adapter
- HP FlexFabric 10Gb 2-port 556FLR-SFP+ Adapter
- HP StoreFabric CN1200E Dual Port Converged Network Adapter
- HPE FlexFabric 10Gb 2-port 556FLR-T Adapter
- HPE StoreFabric CN1200E-T 10GBASE-T Converged Network Adapter
- HP StoreFabric 84E 4-Port Fibre Channel Host Bus Adapter
- HPE Synergy 3530C 16Gb Fibre Channel Host Bus Adapter
- HPE StoreFabric SN1100E 4P 16Gb FC HBA
- HPE StoreFabric SN1200E 16Gb 2P FC HBA
- HPE StoreFabric SN1200E 16Gb 1P FC HBA
- HPE StoreFabric SN1600E 32Gb 2p FC HBA
- HPE StoreFabric SN1600E 32Gb 1p FC HBA

---

Red Hat Enterprise Linux 7 Server FCoE/FC Driver Kit for HPE QLogic CNAs, HBAs and mezzanine HBAs and CNAs

Version: 8.07.00.34.07.0-k1 (b) **(Recommended)**

Filename: kmod-qlgc-qla2xxx-8.07.00.34.07.0\_k1-1.rhel7u3.x86\_64.rpm; kmod-qlgc-qla2xxx-8.07.00.34.07.0\_k1-3.rhel7u1.x86\_64.rpm; kmod-qlgc-qla2xxx-8.07.00.34.07.0\_k1-3.rhel7u2.x86\_64.rpm

### **Important Note!**

Release Notes:

[HPE StoreFabric QLogic Adapters Release Notes](#)

Note: The rpm base-name for the QLogic driver has been changed to "qlgc". Upgrades from the earlier "hpqlgc" driver are supported.

### **Prerequisites**

Please consult SPOCK for a list of supported configurations available at the following link:

<http://www.hpe.com/storage/spock/>

### **Fixes**

This driver version resolves the following:

- corrected issue where scsi status was getting overwritten.
- set relogin flag when failed to queue login requests.
- set echo test mailbox command option bit15 correctly.
- corrected FDMI vendor port state value.
- corrected warnings reported by static checker.
- race condition in handling rport deletion during recovery.

## **Enhancements**

Driver version 8.07.00.34.07.0-k1

Added support for Red Hat Enterprise Linux 7 Server update 3.

Added support for Private link statistics counters.

Added support for the following devices:

- HPE StoreFabric 84Q 4P 8Gb Fibre Channel HBA
- HPE StoreFabric SN1100Q 16Gb 2P FC HBA
- HPE StoreFabric SN1100Q 16Gb 1P FC HBA
- HPE Synergy 3830C 16G Fibre Channel Host Bus Adapter

## **Supported Devices and Features**

This driver supports the following adapters:

- HP 81Q PCIe Fibre Channel Host Bus Adapter
- HP 82Q 8Gb Dual Port PCIe Fibre Channel Host Bus Adapter
- QLogic QMH2562 8Gb Fibre Channel Host Bus Adapter for c-Class BladeSystem
- HP QMH2572 8Gb Fibre Channel Host Bus Adapter for c-Class BladeSystem
- HP StoreFabric SN1000Q 16Gb PCIe Fibre Channel Host Bus Adapter
- HP QMH2672 16Gb FC HBA for c-Class BladeSystem
- HP FlexFabric 10Gb 2-port 526FLR-SFP+ Adapter
- HP CN1000Q Dual Port Converged Network Adapter
- HP StoreFabric SN1000Q 16GB 2-port PCIe Fibre Channel Host Bus Adapter
- HP StoreFabric SN1000Q 16GB 1-port PCIe Fibre Channel Host Bus Adapter
- HPE StoreFabric 84Q 4P 8Gb Fibre Channel HBA
- HPE StoreFabric SN1100Q 16Gb 2P FC HBA
- HPE StoreFabric SN1100Q 16Gb 1P FC HBA
- HPE Synergy 3830C 16G Fibre Channel Host Bus Adapter

---

SUSE Linux Enterprise Server 11 (AMD64/EM64T) FCoE/FC Driver Kit for HPE Emulex CNAs, HBAs and mezzanine HBAs and CNAs

Version: 11.1.183.21 (C) **(Recommended)**

Filename: elx-lpfc-kmp-default-11.1.183.21\_3.0.101\_63-1.sles11sp4.x86\_64.rpm; elx-lpfc-kmp-default-11.1.183.21\_3.0.76\_0.11-1.sles11sp3.x86\_64.rpm; elx-lpfc-kmp-trace-11.1.183.21\_3.0.101\_63-1.sles11sp4.x86\_64.rpm; elx-lpfc-kmp-trace-11.1.183.21\_3.0.76\_0.11-1.sles11sp3.x86\_64.rpm; elx-lpfc-kmp-xen-11.1.183.21\_3.0.101\_63-1.sles11sp4.x86\_64.rpm; elx-lpfc-kmp-xen-11.1.183.21\_3.0.76\_0.11-1.sles11sp3.x86\_64.rpm

## **Important Note!**

Release Notes:

[HPE StoreFabric Emulex Adapters Release Notes](#)

## **Prerequisites**

Please consult SPOCK for a list of supported configurations available at the following link:

<http://www.hpe.com/storage/spock/>

## **Enhancements**

This driver, version 11.1.183.21, adds support for the following devices:

- HPE StoreFabric SN1200E 16Gb 2P FC HBA
- HPE StoreFabric SN1200E 16Gb 1P FC HBA
- HPE StoreFabric SN1600E 32Gb 2p FC HBA
- HPE StoreFabric SN1600E 32Gb 1p FC HBA

## **Supported Devices and Features**

- HP NC553i 10Gb 2-port FlexFabric Converged Network Adapter
- HP SN1000E 16Gb Dual Port Fibre Channel Host Bus Adapter
- HP SN1000E 16Gb Single Port Fibre Channel Host Bus Adapter
- HP 82E 8Gb Dual Port PCIe Fibre Channel Host Bus Adapter
- HP 81E 8Gb Single Port PCIe Fibre Channel Host Bus Adapter
- HP CN1100E Dual Port Converged Network Adapter
- HP FlexFabric 10Gb 2-port 554M Adapter
- HP FlexFabric 10Gb 2-port 554FLR-SFP+ Adapter
- HP FlexFabric 10Gb 2-port 554FLB Adapter
- HP LPe1205A 8Gb Fibre Channel Host Bus Adapter for BladeSystem c-Class
- Emulex LPe1205 8Gb Fibre Channel Host Bus Adapter for c-Class BladeSystem
- HP SN1100E 16Gb Dual Port Fibre Channel Host Bus Adapter
- HP SN1100E 16Gb Single Port Fibre Channel Host Bus Adapter
- HP LPe1605 16Gb Fibre Channel Host Bus Adapter for BladeSystem c-Class
- HP FlexFabric 20Gb 2-port 650FLB Adapter
- HP FlexFabric 20Gb 2-port 650M Adapter
- HP FlexFabric 10Gb 2-port 556FLR-SFP+ Adapter
- HP StoreFabric CN1200E Dual Port Converged Network Adapter
- HPE FlexFabric 10Gb 2-port 556FLR-T Adapter
- HPE StoreFabric CN1200E-T 10GBASE-T Converged Network Adapter
- HP StoreFabric 84E 4-Port Fibre Channel Host Bus Adapter
- HPE Synergy 3530C 16Gb Fibre Channel Host Bus Adapter
- HPE StoreFabric SN1100E 4P 16Gb FC HBA
- HPE StoreFabric SN1200E 16Gb 2P FC HBA
- HPE StoreFabric SN1200E 16Gb 1P FC HBA
- HPE StoreFabric SN1600E 32Gb 2p FC HBA
- HPE StoreFabric SN1600E 32Gb 1p FC HBA

---

SUSE Linux Enterprise Server 11 (AMD64/EM64T) FCoE/FC Driver Kit for HPE Qlogic CNAs, HBAs and mezzanine HBAs

Version: 8.07.00.34.11.3-k (b) **(Recommended)**

Filename: qlgc-qla2xxx-kmp-default-8.07.00.34.11.3\_k\_3.0.101\_63-3.sles11sp4.x86\_64.rpm; qlgc-qla2xxx-kmp-default-8.07.00.34.11.3\_k\_3.0.76\_0.11-3.sles11sp3.x86\_64.rpm; qlgc-qla2xxx-kmp-xen-8.07.00.34.11.3\_k\_3.0.101\_63-3.sles11sp4.x86\_64.rpm; qlgc-qla2xxx-kmp-xen-8.07.00.34.11.3\_k\_3.0.76\_0.11-3.sles11sp3.x86\_64.rpm

## **Important Note!**

Release Notes

[HPE StoreFabric QLogic Adapters Release Notes](#)

Note: The rpm base-name for the QLogic driver has been changed to "qlgc". Upgrades from the earlier "hpqlgc" driver are supported.

## **Fixes**

This driver version resolves the following:

- corrected issue where scsi status was getting overwritten.
- set relogin flag when failed to queue login requests.
- set echo test mailbox command option bit15 correctly.
- corrected FDMI vendor port state value.
- corrected warnings reported by static checker.
- race condition in handling rport deletion during recovery.

## **Enhancements**

Updated driver version 8.07.00.34.11.3-k

Added support for Private link statistics counters.

Added support for the following devices:

- HPE StoreFabric 84Q 4P 8Gb Fibre Channel HBA
- HPE StoreFabric SN1100Q 16Gb 2P FC HBA
- HPE StoreFabric SN1100Q 16Gb 1P FC HBA
- HPE Synergy 3830C 16G Fibre Channel Host Bus Adapter

## **Supported Devices and Features**

This driver supports the following HP adapters:

- HP FC1142SR 4Gb PCIe Host Bus Adapter
- HP FC1242SR 4Gb PCIe DC Host Bus Adapter
- HP 81Q PCIe Fibre Channel Host Bus Adapter
- HP 82Q 8Gb Dual Port PCIe Fibre Channel Host Bus Adapter
- QLogic QMH2562 8Gb Fibre Channel Host Bus Adapter for c-Class BladeSystem
- QLogic QMH2462 4Gb Fibre Channel Host Bus Adapter for c-Class BladeSystem
- HP QMH2572 8Gb Fibre Channel Host Bus Adapter for c-Class BladeSystem
- HP StoreFabric SN1000Q 16Gb PCIe Fibre Channel Host Bus Adapter
- HP QMH2672 16Gb FC HBA for c-Class BladeSystem
- HP FlexFabric 10Gb 2-port 526FLR-SFP+ Adapter
- HP CN1000Q Dual Port Converged Network Adapter
- HP StoreFabric SN1000Q 16GB 2-port PCIe Fibre Channel Host Bus Adapter
- HP StoreFabric SN1000Q 16GB 1-port PCIe Fibre Channel Host Bus Adapter
- HPE StoreFabric 84Q 4P 8Gb Fibre Channel HBA
- HPE StoreFabric SN1100Q 16Gb 2P FC HBA
- HPE StoreFabric SN1100Q 16Gb 1P FC HBA
- HPE Synergy 3830C 16G Fibre Channel Host Bus Adapter

Version: 11.1.183.21 **(Recommended)**

Filename: elx-lpfc-kmp-default-11.1.183.21\_3.0.101\_63-1.sles11sp4.i586.rpm; elx-lpfc-kmp-default-11.1.183.21\_3.0.76\_0.11-1.sles11sp3.i586.rpm; elx-lpfc-kmp-pae-11.1.183.21\_3.0.101\_63-1.sles11sp4.i586.rpm; elx-lpfc-kmp-pae-11.1.183.21\_3.0.76\_0.11-1.sles11sp3.i586.rpm; elx-lpfc-kmp-trace-11.1.183.21\_3.0.101\_63-1.sles11sp4.i586.rpm; elx-lpfc-kmp-trace-11.1.183.21\_3.0.76\_0.11-1.sles11sp3.i586.rpm; elx-lpfc-kmp-xen-11.1.183.21\_3.0.101\_63-1.sles11sp4.i586.rpm; elx-lpfc-kmp-xen-11.1.183.21\_3.0.76\_0.11-1.sles11sp3.i586.rpm

### **Important Note!**

Release Notes:

[HPE StoreFabric Emulex Adapters Release Notes](#)

### **Enhancements**

Updated driver to version 11.1.183.21

- Added automatic recovery from errors that previously required a system reboot

### **Supported Devices and Features**

- HP NC553i 10Gb 2-port FlexFabric Converged Network Adapter
- HP SN1000E 16Gb Dual Port Fibre Channel Host Bus Adapter
- HP SN1000E 16Gb Single Port Fibre Channel Host Bus Adapter
- HP 82E 8Gb Dual Port PCIe Fibre Channel Host Bus Adapter
- HP 81E 8Gb Single Port PCIe Fibre Channel Host Bus Adapter
- HP CN1100E Dual Port Converged Network Adapter
- HP FlexFabric 10Gb 2-port 554M Adapter
- HP FlexFabric 10Gb 2-port 554FLR-SFP+ Adapter
- HP FlexFabric 10Gb 2-port 554FLB Adapter
- HP LPe1205A 8Gb Fibre Channel Host Bus Adapter for BladeSystem c-Class
- Emulex LPe1205 8Gb Fibre Channel Host Bus Adapter for c-Class BladeSystem
- HP SN1100E 16Gb Dual Port Fibre Channel Host Bus Adapter
- HP SN1100E 16Gb Single Port Fibre Channel Host Bus Adapter
- HP Fibre Channel 16Gb LPe1605 Mezz
- HP StoreFabric 84E 4-port Fibre Channel Host Bus Adapter

---

SUSE Linux Enterprise Server 11 (x86) FCoE/FC Driver Kit for HPE Qlogic CNAs, HBAs and mezzanine HBAs

Version: 8.07.00.34.11.3-k **(Recommended)**

Filename: qlgc-qla2xxx-kmp-default-8.07.00.34.11.3\_k\_3.0.101\_63-3.sles11sp4.i586.rpm; qlgc-qla2xxx-kmp-pae-8.07.00.34.11.3\_k\_3.0.101\_63-3.sles11sp4.i586.rpm; qlgc-qla2xxx-kmp-pae-8.07.00.34.11.3\_k\_3.0.76\_0.11-3.sles11sp3.i586.rpm; qlgc-qla2xxx-kmp-xen-8.07.00.34.11.3\_k\_3.0.101\_63-3.sles11sp4.i586.rpm; qlgc-qla2xxx-kmp-xen-8.07.00.34.11.3\_k\_3.0.76\_0.11-3.sles11sp3.i586.rpm

### **Important Note!**

Release Notes

[HPE StoreFabric QLogic Adapter Release Notes](#)

Note: The rpm base-name for the QLogic driver has been changed to "qlgc". Upgrades from the earlier "hpqlgc" driver are supported.

## **Fixes**

This driver version resolves the following:

- corrected issue where scsi status was getting overwritten.
- set relogin flag when failed to queue login requests.
- set echo test mailbox command option bit15 correctly.
- corrected FDMI vendor port state value.
- corrected warnings reported by static checker.
- race condition in handling rport deletion during recovery.

## **Enhancements**

Updated to version 8.07.00.34.11.3-k

Added support for Private link statistics counters.

## **Supported Devices and Features**

This driver supports the following HP adapters:

- HP FC1142SR 4Gb PCIe Host Bus Adapter
- HP FC1242SR 4Gb PCIe DC Host Bus Adapter
- HP 81Q PCIe Fibre Channel Host Bus Adapter
- HP 82Q 8Gb Dual Port PCIe Fibre Channel Host Bus Adapter
- QLogic QMH2562 8Gb Fibre Channel Host Bus Adapter for c-Class BladeSystem
- QLogic QMH2462 4Gb Fibre Channel Host Bus Adapter for c-Class BladeSystem
- HP QMH2572 8Gb Fibre Channel Host Bus Adapter for c-Class BladeSystem
- HP StoreFabric SN1000Q 16Gb PCIe Fibre Channel Host Bus Adapter
- HP QMH2672 16Gb FC HBA for c-Class BladeSystem
- HP FlexFabric 10Gb 2-port 526FLR-SFP+ Adapter
- HP CN1000Q Dual Port Converged Network Adapter
- HP StoreFabric SN1000Q 16GB 2-port PCIe Fibre Channel Host Bus Adapter
- HP StoreFabric SN1000Q 16GB 1-port PCIe Fibre Channel Host Bus Adapter

---

SUSE Linux Enterprise Server 12 FCoE/FC Driver Kit for HPE Emulex CNAs, HBAs and mezzanine HBAs and CNAs

Version: 11.1.183.21 **(Recommended)**

Filename: elx-lpfc-kmp-default-11.1.183.21\_3.12.28\_4-1.sles12sp0.x86\_64.rpm; elx-lpfc-kmp-default-11.1.183.21\_3.12.49\_11-1.sles12sp1.x86\_64.rpm;  
elx-lpfc-kmp-xen-11.1.183.21\_3.12.28\_4-1.sles12sp0.x86\_64.rpm; elx-lpfc-kmp-xen-11.1.183.21\_3.12.49\_11-1.sles12sp1.x86\_64.rpm

## **Important Note!**

Release Notes:

[HPE StoreFabric Emulex Adapters Release Notes](#)

## **Enhancements**

Updated driver to version 11.1.183.21



- Added automatic recovery from errors that previously required a system reboot
- Added SmartSAN 2.0 support
- Added support for Red Hat Enterprise Linux 6 update 8

### **Supported Devices and Features**

- HP NC553i 10Gb 2-port FlexFabric Converged Network Adapter
- HP SN1000E 16Gb Dual Port Fibre Channel Host Bus Adapter
- HP SN1000E 16Gb Single Port Fibre Channel Host Bus Adapter
- HP 82E 8Gb Dual Port PCIe Fibre Channel Host Bus Adapter
- HP 81E 8Gb Single Port PCIe Fibre Channel Host Bus Adapter
- HP CN1100E Dual Port Converged Network Adapter
- HP FlexFabric 10Gb 2-port 554M Adapter
- HP FlexFabric 10Gb 2-port 554FLR-SFP+ Adapter
- HP FlexFabric 10Gb 2-port 554FLB Adapter
- HP LPe1205A 8Gb Fibre Channel Host Bus Adapter for BladeSystem c-Class
- Emulex LPe1205 8Gb Fibre Channel Host Bus Adapter for c-Class BladeSystem
- HP SN1100E 16Gb Dual Port Fibre Channel Host Bus Adapter
- HP SN1100E 16Gb Single Port Fibre Channel Host Bus Adapter
- HP LPe1605 16Gb Fibre Channel Host Bus Adapter for BladeSystem c-Class
- HP FlexFabric 20Gb 2-port 650FLB Adapter
- HP FlexFabric 20Gb 2-port 650M Adapter
- HP FlexFabric 10Gb 2-port 556FLR-SFP+ Adapter
- HP StoreFabric CN1200E Dual Port Converged Network Adapter
- HPE FlexFabric 10Gb 2-port 556FLR-T Adapter
- HPE StoreFabric CN1200E-T 10GBASE-T Converged Network Adapter
- HP StoreFabric 84E 4-Port Fibre Channel Host Bus Adapter
- HPE Synergy 3530C 16Gb Fibre Channel Host Bus Adapter
- HPE StoreFabric SN1100E 4P 16Gb FC HBA

---

SUSE Linux Enterprise Server 12 FCoE/FC Driver Kit for HPE Emulex CNAs, HBAs and mezzanine HBAs and CNAs

Version: 11.1.183.21 (C) **(Recommended)**

Filename: elx-lpfc-kmp-default-11.1.183.21\_3.12.28\_4-1.sles12sp0.x86\_64.rpm; elx-lpfc-kmp-default-11.1.183.21\_3.12.49\_11-1.sles12sp1.x86\_64.rpm; elx-lpfc-kmp-xen-11.1.183.21\_3.12.28\_4-1.sles12sp0.x86\_64.rpm; elx-lpfc-kmp-xen-11.1.183.21\_3.12.49\_11-1.sles12sp1.x86\_64.rpm

### **Important Note!**

Release Notes:

[HPE StoreFabric Emulex Adapters Release Notes](#)

### **Prerequisites**

Please consult SPOCK for a list of supported configurations available at the following link:

<http://www.hpe.com/storage/spock/>

### **Enhancements**

This driver, version 11.1.183.21, adds support for the following devices:

- o HPE StoreFabric SN1200E 16Gb 2P FC HBA
- o HPE StoreFabric SN1200E 16Gb 1P FC HBA
- o HPE StoreFabric SN1600E 32Gb 2p FC HBA
- o HPE StoreFabric SN1600E 32Gb 1p FC HBA

## **Supported Devices and Features**

- o HP NC553i 10Gb 2-port FlexFabric Converged Network Adapter
- o HP SN1000E 16Gb Dual Port Fibre Channel Host Bus Adapter
- o HP SN1000E 16Gb Single Port Fibre Channel Host Bus Adapter
- o HP 82E 8Gb Dual Port PCIe Fibre Channel Host Bus Adapter
- o HP 81E 8Gb Single Port PCIe Fibre Channel Host Bus Adapter
- o HP CN1100E Dual Port Converged Network Adapter
- o HP FlexFabric 10Gb 2-port 554M Adapter
- o HP FlexFabric 10Gb 2-port 554FLR-SFP+ Adapter
- o HP FlexFabric 10Gb 2-port 554FLB Adapter
- o HP LPe1205A 8Gb Fibre Channel Host Bus Adapter for BladeSystem c-Class
- o Emulex LPe1205 8Gb Fibre Channel Host Bus Adapter for c-Class BladeSystem
- o HP SN1100E 16Gb Dual Port Fibre Channel Host Bus Adapter
- o HP SN1100E 16Gb Single Port Fibre Channel Host Bus Adapter
- o HP LPe1605 16Gb Fibre Channel Host Bus Adapter for BladeSystem c-Class
- o HP FlexFabric 20Gb 2-port 650FLB Adapter
- o HP FlexFabric 20Gb 2-port 650M Adapter
- o HP FlexFabric 10Gb 2-port 556FLR-SFP+ Adapter
- o HP StoreFabric CN1200E Dual Port Converged Network Adapter
- o HPE FlexFabric 10Gb 2-port 556FLR-T Adapter
- o HPE StoreFabric CN1200E-T 10GBASE-T Converged Network Adapter
- o HP StoreFabric 84E 4-Port Fibre Channel Host Bus Adapter
- o HPE Synergy 3530C 16Gb Fibre Channel Host Bus Adapter
- o HPE StoreFabric SN1100E 4P 16Gb FC HBA
- o HPE StoreFabric SN1200E 16Gb 2P FC HBA
- o HPE StoreFabric SN1200E 16Gb 1P FC HBA
- o HPE StoreFabric SN1600E 32Gb 2p FC HBA
- o HPE StoreFabric SN1600E 32Gb 1p FC HBA

---

SUSE Linux Enterprise Server 12 FCoE/FC Driver Kit for HPE QLogic CNAs, HBAs and mezzanine HBAs and CNAs

Version: 8.07.00.34.12.0-k1 (b) **(Recommended)**

Filename: qlgc-qla2xxx-kmp-default-8.07.00.34.12.0\_k1\_k3.12.28\_4-3.sles12sp0.x86\_64.rpm; qlgc-qla2xxx-kmp-default-8.07.00.34.12.0\_k1\_k3.12.49\_11-3.sles12sp1.x86\_64.rpm; qlgc-qla2xxx-kmp-xen-8.07.00.34.12.0\_k1\_k3.12.28\_4-3.sles12sp0.x86\_64.rpm; qlgc-qla2xxx-kmp-xen-8.07.00.34.12.0\_k1\_k3.12.49\_11-3.sles12sp1.x86\_64.rpm

### **Important Note!**

Release Notes:

[HPE StoreFabric QLogic Adapters Release Notes](#)

Note: The rpm base-name for the QLogic driver has been changed to "qlgc". Upgrades from the earlier "hpqlgc" driver are supported.

## **Fixes**

This driver version resolves the following:

- corrected issue where scsi status was getting overwritten.
- set relogin flag when failed to queue login requests.
- set echo test mailbox command option bit15 correctly.
- corrected FDMI vendor port state value.
- corrected warnings reported by static checker.
- race condition in handling rport deletion during recovery.

## **Enhancements**

Updated to version 8.07.00.34.12.0-k1

Added support for Private link statistics counters.

Added support for the following devices:

- HPE StoreFabric 84Q 4P 8Gb Fibre Channel HBA
- HPE StoreFabric SN1100Q 16Gb 2P FC HBA
- HPE StoreFabric SN1100Q 16Gb 1P FC HBA
- HPE Synergy 3830C 16G Fibre Channel Host Bus Adapter

## **Supported Devices and Features**

This driver supports the following HP adapters:

- HP 81Q PCIe Fibre Channel Host Bus Adapter
- HP 82Q 8Gb Dual Port PCIe Fibre Channel Host Bus Adapter
- QLogic QMH2562 8Gb Fibre Channel Host Bus Adapter for c-Class BladeSystem
- HP QMH2572 8Gb Fibre Channel Host Bus Adapter for c-Class BladeSystem
- HP StoreFabric SN1000Q 16Gb PCIe Fibre Channel Host Bus Adapter
- HP QMH2672 16Gb FC HBA for c-Class BladeSystem
- HP FlexFabric 10Gb 2-port 526FLR-SFP+ Adapter
- HP CN1000Q Dual Port Converged Network Adapter
- HP StoreFabric SN1000Q 16GB 2-port PCIe Fibre Channel Host Bus Adapter
- HP StoreFabric SN1000Q 16GB 1-port PCIe Fibre Channel Host Bus Adapter
- HPE StoreFabric 84Q 4P 8Gb Fibre Channel HBA
- HPE StoreFabric SN1100Q 16Gb 2P FC HBA
- HPE StoreFabric SN1100Q 16Gb 1P FC HBA
- HPE Synergy 3830C 16G Fibre Channel Host Bus Adapter

---

SUSE Linux Enterprise Server 12 FCoE/FC Driver Kit for HPE QLogic CNAs, HBAs and mezzanine HBAs and CNAs

Version: 8.07.00.34.12.0-k1 (c) **(Recommended)**

Filename: qlgc-qla2xxx-kmp-default-8.07.00.34.12.0\_k1\_k3.12.28\_4-3.sles12sp0x86\_64.rpm; qlgc-qla2xxx-kmp-default-8.07.00.34.12.0\_k1\_k3.12.49\_11-3.sles12sp1x86\_64.rpm; qlgc-qla2xxx-kmp-default-8.07.00.34.12.2\_k1\_k4.4.21\_69-1.sles12sp2x86\_64.rpm; qlgc-qla2xxx-kmp-xen-8.07.00.34.12.0\_k1\_k3.12.28\_4-3.sles12sp0x86\_64.rpm; qlgc-qla2xxx-kmp-xen-8.07.00.34.12.0\_k1\_k3.12.49\_11-3.sles12sp1x86\_64.rpm

## **Important Note!**

Release Notes:

[HPE StoreFabric QLogic Adapters Release Notes](#)

Note: The rpm base-name for the QLogic driver has been changed to "qlgc". Upgrades from the earlier "hpqlgc" driver are supported.

## **Prerequisites**

Please consult SPOCK for a list of supported configurations available at the following link:

<http://www.hpe.com/storage/spock/>

## **Fixes**

This driver version resolves the following:

- corrected issue where scsi status was getting overwritten.
- set relogin flag when failed to queue login requests.
- set echo test mailbox command option bit15 correctly.
- corrected FDMI vendor port state value.
- corrected warnings reported by static checker.
- race condition in handling rport deletion during recovery.

## **Enhancements**

Driver version 8.07.00.34.12.0-k1

Added support for SUSE Linux Enterprise Server 12 SP2

Added support for Private link statistics counters.

Added support for the following devices:

- HPE StoreFabric 84Q 4P 8Gb Fibre Channel HBA
- HPE StoreFabric SN1100Q 16Gb 2P FC HBA
- HPE StoreFabric SN1100Q 16Gb 1P FC HBA
- HPE Synergy 3830C 16G Fibre Channel Host Bus Adapter

## **Supported Devices and Features**

This driver supports the following HP adapters:

- HP 81Q PCIe Fibre Channel Host Bus Adapter
- HP 82Q 8Gb Dual Port PCIe Fibre Channel Host Bus Adapter
- QLogic QMH2562 8Gb Fibre Channel Host Bus Adapter for c-Class BladeSystem
- HP QMH2572 8Gb Fibre Channel Host Bus Adapter for c-Class BladeSystem

- HP StoreFabric SN1000Q 16Gb PCIe Fibre Channel Host Bus Adapter
- HP QMH2672 16Gb FC HBA for c-Class BladeSystem
- HP FlexFabric 10Gb 2-port 526FLR-SFP+ Adapter
- HP CN1000Q Dual Port Converged Network Adapter
- HP StoreFabric SN1000Q 16GB 2-port PCIe Fibre Channel Host Bus Adapter
- HP StoreFabric SN1000Q 16GB 1-port PCIe Fibre Channel Host Bus Adapter
- HPE StoreFabric 84Q 4P 8Gb Fibre Channel HBA
- HPE StoreFabric SN1100Q 16Gb 2P FC HBA
- HPE StoreFabric SN1100Q 16Gb 1P FC HBA
- HPE Synergy 3830C 16G Fibre Channel Host Bus Adapter

## Driver - Storage Tape

[Top](#)

HPE StoreEver Tape Drivers for Microsoft Windows

Version: 4.2.0.0 **(Recommended)**

Filename: cp030019.exe

### Enhancements

- New LTO Tape Drive driver version 1.0.9.1
  - Added support for Microsoft Windows Server 2016 x64
- New MSL Library and 1/8 G2 autoloader driver version 3.0.0.4
  - Added support for Microsoft Windows Server 2016 x64
- New ESL G3 Tape Library driver version 7.5.8.3
  - Added support for Microsoft Windows Server 2016 x64
- Use previous versions of this driver installer if older drivers are required.
- See table below for operating system support and driver versions
  - **bold** - new driver versions
  - \* - not supported

	Microsoft Windows Client Operating Systems				
Driver Description (HP and HPE branded products are supported)	7 x86	7 x64	8 x64	8.1 x64	10 x64
LTO Tape Drive - (LTO-7 drives require version 1.0.9.1)	1.0.9.1	1.0.9.1	1.0.9.1	1.0.9.1	1.0.9.1
MSL6480 Tape Library for 1/8 G2 Tape Autoloader					
MSL2024 Tape Library	3.0.0.0	3.0.0.0	3.0.0.0	3.0.0.3	3.0.0.4
MSL4048 Tape Library					
MSL8096 Tape Library					
DAT Tape Drive	1.7.1.0	1.7.1.0	1.7.1.0	1.7.2.0	*
USB Mass Storage Controller - (DAT 72 & 160 only)	6.07.2010	6.07.2010	7.00.2012	8.00.2014	*

	Microsoft Windows Server Operating Systems			
Driver Description (HP and HPE branded products are supported)	Server	Server	Server	Server

	2008 R2 x64	2012 x64	2012 R2 x64	2016 x64
LTO Tape Drive - (LTO-7 drives require version 1.0.9.1)	1.0.9.1	1.0.9.1	1.0.9.1	<b>1.0.9.1</b>
MSL6480 Tape Library for 1/8 G2 Tape Autoloader MSL2024 Tape Library MSL4048 Tape Library MSL8096 Tape Library	3.0.0.0	3.0.0.0	3.0.0.3	<b>3.0.0.4</b>
ESL G3 Tape Library	7.5.7.1	7.5.8.1	7.5.8.2	<b>7.5.8.3</b>
ESL E Tape Library	1.5.1.0	1.5.1.1	*	*
DAT Tape Drive	1.7.1.0	1.7.1.0	1.7.2.0	*
USB Mass Storage Controller - (DAT 72 & 160 only)	6.07.2010	7.00.2012	8.00.2014	*

---

### Driver - System Management

[Top](#)

Combined Chipset Identifier for Windows Server 2008

Version: 8.2.0.0 (B) **(Optional)**

Filename: cp029650.exe

#### **Important Note!**

Version 8.1.0.0 of this component is the final version to support installation under Windows Server 2003.

#### **Enhancements**

The component executable is now digitally signed with both SHA-1 and SHA-256 signatures.

---

Combined Chipset Identifier for Windows Server 2008 x64 Edition

Version: 8.2.0.0 (B) **(Optional)**

Filename: cp029651.exe

#### **Important Note!**

Version 8.1.0.0 of this component is the final version to support installation under Windows Server 2003 x64 Edition.

#### **Enhancements**

The component executable is now digitally signed with both SHA-1 and SHA-256 signatures.

---

iLO 3/4 Channel Interface Driver for Windows Server 2008 to Server 2012 R2

Version: 3.30.0.0 **(Optional)**

Filename: cp029394.exe

#### **Important Note!**

The Channel Interface Driver was separated into its own component when the ProLiant Support Pack version 9.00 was released. Previously, the driver was a part of the *iLO 3 Management Controller Driver Package* component.

## **Fixes**

Ensure that work items created by the driver are properly terminated if the driver has been restarted.

---

iLO 3/4 Channel Interface Driver for Windows Server 2008 X86

Version: 3.30.0.0 **(Optional)**

Filename: cp029393.exe

## **Important Note!**

The Channel Interface Driver was separated into its own component when the ProLiant Support Pack version 9.00 was released. Previously, the driver was a part of the *iLO 3 Management Controller Driver Package* component.

## **Fixes**

Ensure that work items created by the driver are properly terminated if the driver has been restarted.

## **Enhancements**

The component executable is now digitally signed with both SHA-1 and SHA-256 signatures.

---

iLO 3/4 Management Controller Driver Package for Windows Server 2008 to Server 2012 R2

Version: 3.30.0.0 **(Optional)**

Filename: cp029429.exe

## **Prerequisites**

The *iLO 3/4 Channel Interface Driver for Windows Server 2008 to Server 2012 R2* (version 3.4.0.0 or later) must be installed prior to this component. The Channel Interface Driver was previously included within this component, but is now installed separately.

## **Enhancements**

The support provided by the ProLiant System Shutdown service has been merged into the ProLiant Monitor service. The ProLiant System Shutdown service will no longer appear as a separate item in the list of services on the system.

---

iLO 3/4 Management Controller Driver Package for Windows Server 2008 X86

Version: 3.30.0.0 **(Optional)**

Filename: cp029428.exe

## **Prerequisites**

The *iLO 3/4 Channel Interface Driver for Windows Server 2008 X86* (version 3.4.0.0 or later) must be installed prior to this component. The Channel Interface Driver was previously included within this component, but is now installed separately.

## **Enhancements**

The support provided by the ProLiant System Shutdown service has been merged into the ProLiant Monitor service. The ProLiant System Shutdown service will no longer appear as a separate item in the list of services on the system.

---

**Driver - Video**[Top](#)

ATI ES1000 Video Controller Driver for Windows Server 2008

Version: 6.14.10.6748 (B) **(Optional)**

Filename: cp029668.exe

**Enhancements**

The component executable is now digitally signed with both SHA-1 and SHA-256 signatures.

---

ATI ES1000 Video Controller Driver for Windows Server 2008 x64 Editions

Version: 6.14.10.6748 (B) **(Optional)**

Filename: cp029669.exe

**Enhancements**

The component executable is now digitally signed with both SHA-1 and SHA-256 signatures.

---

Matrox G200eH Video Controller Driver for Windows Server 2008 X64

Version: 6.12.1.1030 (C) **(Optional)**

Filename: cp029671.exe

**Enhancements**

The component executable is now digitally signed with both SHA-1 and SHA-256 signatures.

---

Matrox G200eH Video Controller Driver for Windows Server 2008 X86

Version: 6.12.1.1030 (C) **(Optional)**

Filename: cp029670.exe

**Enhancements**

The component executable is now digitally signed with both SHA-1 and SHA-256 signatures.

---

Matrox G200eH Video Controller Driver for Windows Server 2012 and Server 2012 R2

Version: 9.15.1.143 **(Optional)**

Filename: cp029672.exe

**Fixes**

The Windows bug check display is now visible through the iLO Remote Console on systems that were booted in UEFI mode but do not have a monitor connected.

**Enhancements**

Updated component installer to only support Windows Server 2012 and Server 2012 R2.



---

## Firmware - Blade Infrastructure

[Top](#)

HPE BladeSystem c-Class Virtual Connect Firmware, Ethernet plus 8Gb 20-port and 8/16Gb 24-port FC Edition Component for Windows

Version: 4.60 **(Recommended)**

Filename: cp031272.exe

### **Prerequisites**

The 4.60 version of HPE Virtual Connect Release Notes contains the prerequisites and can also be found in the following URL: <http://www.hpe.com/info/vc/manuals>

### **Fixes**

The latest list of issues resolved can be found in the HPE Virtual Connect Release Notes that can be found in the following URL: <http://www.hpe.com/info/vc/manuals>

### **Enhancements**

The latest list of enhancements can be found in the HPE Virtual Connect Release Notes that can be found in the following URL: <http://www.hpe.com/info/vc/manuals>

### **Supported Devices and Features**

HPE Flex-10 10Gb Virtual Connect Ethernet Module for c-Class BladeSystem

HPE Virtual Connect FlexFabric 10Gb/24-port Module for c-Class BladeSystem

HPE Virtual Connect 8Gb 24-port Fibre Channel Module for c-Class BladeSystem

HPE Virtual Connect 8Gb 20-port Fibre Channel Module for c-Class BladeSystem

HPE Virtual Connect Flex-10/10D Module for c-Class BladeSystem

HPE Virtual Connect FlexFabric-20/40 F8 Module for HP BladeSystem c-Class

HPE Virtual Connect 16Gb 24-port Fibre Channel Module for c-Class BladeSystem

---

HPE BladeSystem c-Class Virtual Connect Firmware, Ethernet plus 8Gb 20-port and 8/16Gb 24-port FC Edition Component for Linux

Version: 4.60 **(Recommended)**

Filename: RPMS/i386/firmware-vceth-4.60-1.1.i386.rpm

### **Prerequisites**

The 4.60 version of HPE Virtual Connect Release Notes contains the prerequisites and can be found in the following URL: <http://www.hpe.com/info/vc/manuals>

### **Fixes**

The latest list of issues resolved can be found in the HPE Virtual Connect Release Notes that can be found in the following URL: <http://www.hpe.com/info/vc/manuals>

## **Enhancements**

The latest list of enhancements can be found in the HPE Virtual Connect Release Notes that can be found in the following URL:  
<http://www.hpe.com/info/vc/manuals>

## **Supported Devices and Features**

HPE Flex-10 10Gb Virtual Connect Ethernet Module for c-Class BladeSystem

HPE Virtual Connect FlexFabric 10Gb/24-port Module for c-Class BladeSystem

HPE Virtual Connect 8Gb 24-port Fibre Channel Module for c-Class BladeSystem

HPE Virtual Connect 8Gb 20-port Fibre Channel Module for c-Class BladeSystem

HPE Virtual Connect Flex-10/10D Module for c-Class BladeSystem

HPE Virtual Connect FlexFabric-20/40 F8 Module for HP BladeSystem c-Class

HPE Virtual Connect 16Gb 24-port Fibre Channel Module for c-Class BladeSystem

---

Online HP 6Gb SAS BL Switch Firmware Smart Component for Linux (x86/x64)

Version: 4.2.2.0 **(Recommended)**

Filename: RPMS/i586/hp-firmware-solex6gb-solex-4.2.2.0-1.1.i586.rpm

## **Fixes**

- Firmware was changed to make it more robust and resilient to handle possible unresponsiveness due to a potential deadlock between multiple processes. If deadlock was to occur, it might cause an inability to establish an SSH session with the switch.

## **Enhancements**

- Made changes to firmware to capture more debug information.

---

Online HPE 6Gb SAS BL Switch Firmware Smart Component for Windows (x86/x64)

Version: 4.2.2.0 (B) **(Recommended)**

Filename: cp030778.exe

## **Fixes**

- Firmware was changed to make it more robust and resilient to handle possible unresponsiveness due to a potential deadlock between multiple processes. If deadlock was to occur, it might cause an inability to establish an SSH session with the switch.

## **Enhancements**

- Made changes to firmware to capture more debug information.
- Added support for the Microsoft® Windows Server® 2016 OS.

---

Online HPE BladeSystem c-Class Onboard Administrator Firmware Component for Linux

## **Important Note!**

Update to this firmware version if any documented fixes or enhanced functionality provided by this version would be useful to your system.

### **Important Notes**

#### o **Firmware Upgrade**

- Starting OA 4.50 release, a standardized code signing and validation mechanism has been introduced to enhance the firmware image authenticity.
- For customers using Firmware ROM image to upgrade OA:
  - For OAs with firmware version less than 3.50, first update to OA 3.50 and then continue updating to OA 4.50 or above.
- For customers using Smart Components to upgrade OA:
  - OA firmware update mechanisms which rely on HPE Smart Components (example: EFM), will not be affected by this change. The Smart Component will automatically perform the intermediate upgrade to OA 3.50 before performing the OA 4.50 or above upgrade.

#### o **EFM**

- The OA only supports SPP ISO images that are less than 4 GB in size, whether hosted directly via the Enclosure DVD feature or an attached USB key, or mounted remotely via a specified URL. If an ISO image exceeds 4 GB, the CLI SHOW FIRMWARE MANAGEMENT command displays ISO URL Status as "Invalid URL."
  - If an SPP ISO image exceeds 4 GB, it is necessary to create a custom ISO image that excludes components unnecessary to the OA EFM blade firmware update process. At a minimum, the custom ISO must contain the firmware components for HPE ProLiant BL servers. (When using HP SUM to create the custom ISO image, select Firmware as the Component Type, and select HPE ProLiant BL Series as the Server Type.) For information about creating a custom ISO image compatible for OA EFM functionality, see the *HPE BladeSystem Onboard Administrator User Guide*. More HP SUM information can be found via HPE Smart Update Manager online help or at <http://www.hp.com/go/hpsum/documentation>.

#### o **FIPS**

- OA 3.71 is in active evaluation for FIPS as referenced in the 140-2 In Process list located at <http://csrc.nist.gov/groups/STM/cmvp/documents/140-1/140InProcess.pdf>.

#### o **IPv6**

- When the Enable DHCPv6 or Enable SLAAC enclosure IPv6 settings are disabled on the Onboard Administrator, the respective DHCPv6 or SLAAC addresses of the iLOs in the enclosure are retained until these addresses expire automatically based on their respective configurations. A manual reset of the iLO releases these addresses immediately

## **Prerequisites**

The Onboard Administrator Smart Component contains 32-bit executable binaries. As a result, the client operating system upon which the OA Smart Component is installed and executed must either have native support for 32-bit executables or must have the 32-bit compatibility libraries installed.

## **Fixes**

### **General**

- o Addressed an issue where EFM was reporting success while firmware update of iLO 4 failed.
- o Fixed an issue where OA might lose its IP address after OA firmware upgrade when ENCLOSURE\_IP\_MODE was enabled .
- o Fixed an issue where all iLOs were reset after making EBIPA changes to an empty bay. Now only the specific iLOs are reset.
- o Resolved an issue where iLOs became inaccessible after OA failover occurs with iLOs configured in EBIPA for IPv6. This occurs when an external router in the management network is configured to send Router Advertisements.
- o Corrected the type mismatch of OID cpqRackCommonEnclosureManagerLocation which could cause failures in the SNMP clients. The definition is changed from STRING to INTEGER.

- Resolved an issue where information on only the last server NIC port of a multiport adaptor was shown on GUI and CLI. Now details of all the server NIC ports are displayed.
- Resolved an issue of time synchronization between active and standby OA when date and time settings were changed from “Manual” to “NTP”.
- Resolved EFM discovery/update failure when the server power policy in the EFM configuration is set to “must be off”.
- Security**

The following security vulnerabilities were fixed:

- CVE-2016-2108 – Addressed a vulnerability in ASN.1 implementation in OpenSSL that can cause Denial Of Service via any field in crafted serialized data
- CVE-2015-8605 - UDP payload length not properly checked. Addressed a vulnerability where a badly formed packet with an invalid IPv4 UDP length field can cause a DHCP server, client, or relay program to terminate abnormally.
- CVE-2012-3954 - Fixed a memory leak issue in DHCPv6 daemon that could result in out of memory condition in OA.
- CVE-2016-0797 and CVE-2016-0799 - Addressed a vulnerability in OpenSSL that could enable security attacks by passing large amount of untrusted data to certain functions in OpenSSL.
- CVE-2015-8605 - Addressed a vulnerability in IPv4 stack that can be exploited to cause a Denial Of Service via an invalid length field in a UDP IPv4 packet.
- CVE-2015-3196 - Addressed a vulnerability in OpenSSL that results in Denial Of Service by remote servers via a crafted ServerKeyExchange message.
- CVE-2015-3195 - Addressed a vulnerability in OpenSSL that can be exploited to obtain sensitive information from process memory by triggering a decoding failure in a PKCS#7 or CMS application.
- CVE-2015-6564 - Addressed a vulnerability in OpenSSH that might allow local users to gain privileges by leveraging control of the sshd uid to send an unexpectedly early MONITOR\_REQ\_PAM\_FREE\_CTX request.
- CVE-2015-6563 - Addressed a vulnerability in OpenSSH that allows local users to conduct impersonation attacks by leveraging any SSH login access in conjunction with control of the sshd uid.
- CVE-2015-5621 - Addressed a vulnerability in Net-SNMP that causes a Denial Of Service and possibly allows execution of arbitrary code via a crafted packet.
- CVE-2015-5364 and CVE-2015-5366 - Addressed a vulnerability in UDP stack that can be exploited in UDP flood scenario to cause Denial Of Service in the OA.

## **Enhancements**

Onboard Administrator 4.60 provides support for the following enhancements:

- Hardware Additions**
  - None.
- Features Additions and Changes**
  - General**
    - GUI, CLI, Smart components, help files, URLs, Product Names rebranded to align with HPE branding guidelines.
    - Enhanced information reporting of Gen9 servers booted in UEFI mode.
    - Support the configuration of SNMP trap agent address when non-default VLAN is enabled on OA.
    - Enhanced syslog to show the flooding information when VLAN configured nodes flood the management network.
  - Remote Support**
    - Modified to connect to the HPE remote support URL.
  - EFM**
    - Enhanced error handling mechanism in EFM for servers in UEFI boot mode.
    - Enhanced EFM to display detailed name for smart array controllers.
    - EFM enhanced to identify more devices in the EFM report.
    - Enhanced the status reporting of EFM operations to align with HPSUM return codes

## **Important Note!**

Update to this firmware version if any documented fixes or enhanced functionality provided by this version would be useful to your system.

### **Important Notes**

#### o **Firmware Upgrade**

- Starting OA 4.50 release, a standardized code signing and validation mechanism has been introduced to enhance the firmware image authenticity.
- For customers using Firmware ROM image to upgrade OA:
  - For OAs with firmware version less than 3.50, first update to OA 3.50 and then continue updating to OA 4.50 or above.
- For customers using Smart Components to upgrade OA:
  - OA firmware update mechanisms which rely on HPE Smart Components (example: EFM), will not be affected by this change. The Smart Component will automatically perform the intermediate upgrade to OA 3.50 before performing the OA 4.50 or above upgrade.

#### o **EFM**

- The OA only supports SPP ISO images that are less than 4 GB in size, whether hosted directly via the Enclosure DVD feature or an attached USB key, or mounted remotely via a specified URL. If an ISO image exceeds 4 GB, the CLI SHOW FIRMWARE MANAGEMENT command displays ISO URL Status as "Invalid URL."
  - If an SPP ISO image exceeds 4 GB, it is necessary to create a custom ISO image that excludes components unnecessary to the OA EFM blade firmware update process. At a minimum, the custom ISO must contain the firmware components for HPE ProLiant BL servers. (When using HP SUM to create the custom ISO image, select Firmware as the Component Type, and select HPE ProLiant BL Series as the Server Type.) For information about creating a custom ISO image compatible for OA EFM functionality, see the *HPE BladeSystem Onboard Administrator User Guide*. More HP SUM information can be found via HPE Smart Update Manager online help or at <http://www.hp.com/go/hpsum/documentation>.

#### o **FIPS**

- OA 3.71 is in active evaluation for FIPS as referenced in the 140-2 In Process list located at <http://csrc.nist.gov/groups/STM/cmvp/documents/140-1/140InProcess.pdf>.

#### o **IPv6**

- When the Enable DHCPv6 or Enable SLAAC enclosure IPv6 settings are disabled on the Onboard Administrator, the respective DHCPv6 or SLAAC addresses of the iLOs in the enclosure are retained until these addresses expire automatically based on their respective configurations. A manual reset of the iLO releases these addresses immediately.

## **Prerequisites**

The Onboard Administrator Smart Component contains 32-bit executable binaries. As a result, the client operating system upon which the OA Smart Component is installed and executed must either have native support for 32-bit executables or must have the 32-bit compatibility libraries installed.

## **Fixes**

### **General**

- Addressed an issue where EFM was reporting success while firmware update of iLO 4 failed.
- Fixed an issue where OA might lose its IP address after OA firmware upgrade when ENCLOSURE\_IP\_MODE was enabled .
- Fixed an issue where all iLOs were reset after making EBIPA changes to an empty bay. Now only the specific iLOs are reset.
- Resolved an issue where iLOs became inaccessible after OA failover occurs with iLOs configured in EBIPA for IPv6. This occurs when an external router in the management network is configured to send Router Advertisements.
- Corrected the type mismatch of OID cpqRackCommonEnclosureManagerLocation which could cause failures in the SNMP clients. The

definition is changed from STRING to INTEGER.

- Resolved an issue where information on only the last server NIC port of a multiport adaptor was shown on GUI and CLI. Now details of all the server NIC ports are displayed.
- Resolved an issue of time synchronization between active and standby OA when date and time settings were changed from “Manual” to “NTP”.
- Resolved EFM discovery/update failure when the server power policy in the EFM configuration is set to “must be off”.

The following security vulnerabilities were fixed:

- **Security**

- CVE-2016-2108 – Addressed a vulnerability in ASN.1 implementation in OpenSSL that can cause Denial Of Service via any field in crafted serialized data
- CVE-2015-8605 - UDP payload length not properly checked. Addressed a vulnerability where a badly formed packet with an invalid IPv4 UDP length field can cause a DHCP server, client, or relay program to terminate abnormally.
- CVE-2012-3954 - Fixed a memory leak issue in DHCPv6 daemon that could result in out of memory condition in OA.
- CVE-2016-0797 and CVE-2016-0799 - Addressed a vulnerability in OpenSSL that could enable security attacks by passing large amount of untrusted data to certain functions in OpenSSL.
- CVE-2015-8605 - Addressed a vulnerability in IPv4 stack that can be exploited to cause a Denial Of Service via an invalid length field in a UDP IPv4 packet.
- CVE-2015-3196 - Addressed a vulnerability in OpenSSL that results in Denial Of Service by remote servers via a crafted ServerKeyExchange message.
- CVE-2015-3195 - Addressed a vulnerability in OpenSSL that can be exploited to obtain sensitive information from process memory by triggering a decoding failure in a PKCS#7 or CMS application.
- CVE-2015-6564 - Addressed a vulnerability in OpenSSH that might allow local users to gain privileges by leveraging control of the sshd uid to send an unexpectedly early MONITOR\_REQ\_PAM\_FREE\_CTX request.
- CVE-2015-6563 - Addressed a vulnerability in OpenSSH that allows local users to conduct impersonation attacks by leveraging any SSH login access in conjunction with control of the sshd uid.
- CVE-2015-5621 - Addressed a vulnerability in Net-SNMP that causes a Denial Of Service and possibly allows execution of arbitrary code via a crafted packet.
- CVE-2015-5364 and CVE-2015-5366 - Addressed a vulnerability in UDP stack that can be exploited in UDP flood scenario to cause Denial Of Service in the OA.

## **Enhancements**

Onboard Administrator 4.60 provides support for the following enhancements:

- **Hardware Additions**

- None.

- **Features Additions and Changes**

- **General**

- GUI, CLI, Smart components, help files, URLs, Product Names rebranded to align with HPE branding guidelines.
- Enhanced information reporting of Gen9 servers booted in UEFI mode.
- Support the configuration of SNMP trap agent address when non-default VLAN is enabled on OA.
- Enhanced syslog to show the flooding information when VLAN configured nodes flood the management network.

- **Remote Support**

- Modified to connect to the HPE remote support URL.

- **EFM**

- Enhanced error handling mechanism in EFM for servers in UEFI boot mode.
  - Enhanced EFM to display detailed name for smart array controllers .
  - EFM enhanced to identify more devices in the EFM report.
  - Enhanced the status reporting of EFM operations to align with HPSUM return codes.
-

Firmware CD Supplemental Update / Online ROM Flash Component for Linux - HP Integrated Lights-Out 3

Version: 1.88 **(Optional)**

Filename: CP029099.scexe

### **Important Note!**

KNOWN ISSUES:

- Authentication may work intermittently if you have a large number of Active Directory groups.

### **Prerequisites**

Customers running a version of iLO 3 previous to v1.20 must upgrade v1.20 before upgrading to this version. iLO 3 v1.20 may be obtained from the following locations:

Linux: <https://downloads.hpe.com/pub/softlib2/software1/sc-linux-fw-ilo/p1255562964/v64722/CP014002.scexe>

Windows: <https://downloads.hpe.com/pub/softlib2/software1/sc-windows-fw-ilo/p901462262/v64721/cp014001.exe>

Win64: <https://downloads.hpe.com/pub/softlib2/software1/sc-windows-fw-ilo/p1728391553/v64720/cp014000.exe>

### **Fixes**

The following issues are resolved in this version:

- Addressed Security Bulletins HPSBHF03440 and HPSBHF03441.
- Removed the iLO 3 short-name from the SAN field in the Certificate Signing Request.
- Changed the IPMI master write read completion code to avoid retries by the open IPMI driver.
- Changed the IPMI close session request to utilize the session handle, if present.
- Fixed the IPMI channel privilege level setting.
- Fixed an issue that allowed authenticated iLO web interface users to use browser debug tools to set their own password below the configured minimum password length.
- Fixed an issue that prevents users from using the CLI to set a password that contains the "\" character.
- Disabled TLSv1.0 when the FIPS mode or Enforce AES/3DES Encryption options are enabled.
- Added X-Frame-Options to the HTTP header as a countermeasure for Clickjacking.
- Fixed an issue in which the IPMI Set SOL Configuration parameters return an error completion code when the configuration change was successful
- Fixed IPMI OEM commands for setting and getting the serial number and product ID.
- Fixed an intermittent loss of OA communications after an iLO firmware update on a blade server.

### **Enhancements**

iLO 3 v1.88 includes the following enhancements:

- Added support for AES-CTR ciphers and HMAC-SHA2-256 to the SSH server.
- Disabled the CBC ciphers in the SSH server when iLO 3 is in FIPS mode or when the Enforce AES/3DES Encryption option is enabled.
- Certificate Signing Requests now use the SHA256 algorithm for the signature.
- The Java IRC now includes two alternatives: A Java Web Start console and a Java applet-based console. The Java Web Start option works in newer browsers that do not allow the applet version to run. On systems with OpenJDK, you must use the Java applet-based console with a browser (such as Firefox) that supports a Java plug-in.

Version: 1.88 **(Optional)**

Filename: CP029098.zip

## **Important Note!**

KNOWN ISSUES:

- Authentication may work intermittently if you have a large number of Active Directory groups.

## **Prerequisites**

Customers running a version of iLO 3 previous to v1.20 must upgrade v1.20 before upgrading to this version. iLO 3 v1.20 may be obtained from the following locations:

Linux: <https://downloads.hpe.com/pub/softlib2/software1/sc-linux-fw-ilo/p1255562964/v64722/CP014002.scexe>

Windows: <https://downloads.hpe.com/pub/softlib2/software1/sc-windows-fw-ilo/p901462262/v64721/cp014001.exe>

Win64: <https://downloads.hpe.com/pub/softlib2/software1/sc-windows-fw-ilo/p1728391553/v64720/cp014000.exe>

## **Fixes**

The following issues are resolved in this version:

- Addressed Security Bulletins HPSBHF03440 and HPSBHF03441.
- Removed the iLO 3 short-name from the SAN field in the Certificate Signing Request.
- Changed the IPMI master write read completion code to avoid retries by the open IPMI driver.
- Changed the IPMI close session request to utilize the session handle, if present.
- Fixed the IPMI channel privilege level setting.
- Fixed an issue that allowed authenticated iLO web interface users to use browser debug tools to set their own password below the configured minimum password length.
- Fixed an issue that prevents users from using the CLI to set a password that contains the "\" character.
- Disabled TLSv1.0 when the FIPS mode or Enforce AES/3DES Encryption options are enabled.
- Added X-Frame-Options to the HTTP header as a countermeasure for Clickjacking.
- Fixed an issue in which the IPMI Set SOL Configuration parameters return an error completion code when the configuration change was successful
- Fixed IPMI OEM commands for setting and getting the serial number and product ID.
- Fixed an intermittent loss of OA communications after an iLO firmware update on a blade server.

## **Enhancements**

iLO 3 v1.88 includes the following enhancements:

- Added support for AES-CTR ciphers and HMAC-SHA2-256 to the SSH server.
- Disabled the CBC ciphers in the SSH server when iLO 3 is in FIPS mode or when the Enforce AES/3DES Encryption option is enabled.
- Certificate Signing Requests now use the SHA256 algorithm for the signature.
- The Java IRC now includes two alternatives: A Java Web Start console and a Java applet-based console. The Java Web Start option works in newer browsers that do not allow the applet version to run. On systems with OpenJDK, you must use the Java applet-based console with a browser (such as Firefox) that supports a Java plug-in.

---

Online ROM Flash Component for Windows - HP Integrated Lights-Out 3

Version: 1.88 **(Optional)**

Filename: cp029100.exe



## **Important Note!**

KNOWN ISSUES:

- Authentication may work intermittently if you have a large number of Active Directory groups.

## **Prerequisites**

Customers running a version of iLO 3 previous to v1.20 must upgrade v1.20 before upgrading to this version. iLO 3 v1.20 may be obtained from the following locations:

Linux: <https://downloads.hpe.com/pub/softlib2/software1/sc-linux-fw-ilo/p1255562964/v64722/CP014002.scexe>

Windows: <https://downloads.hpe.com/pub/softlib2/software1/sc-windows-fw-ilo/p901462262/v64721/cp014001.exe>

Win64: <https://downloads.hpe.com/pub/softlib2/software1/sc-windows-fw-ilo/p1728391553/v64720/cp014000.exe>

## **Fixes**

The following issues are resolved in this version:

- Addressed Security Bulletins HPSBHF03440 and HPSBHF03441.
- Removed the iLO 3 short-name from the SAN field in the Certificate Signing Request.
- Changed the IPMI master write read completion code to avoid retries by the open IPMI driver.
- Changed the IPMI close session request to utilize the session handle, if present.
- Fixed the IPMI channel privilege level setting.
- Fixed an issue that allowed authenticated iLO web interface users to use browser debug tools to set their own password below the configured minimum password length.
- Fixed an issue that prevents users from using the CLI to set a password that contains the "\*" character.
- Disabled TLSv1.0 when the FIPS mode or Enforce AES/3DES Encryption options are enabled.
- Added X-Frame-Options to the HTTP header as a countermeasure for Clickjacking.
- Fixed an issue in which the IPMI Set SOL Configuration parameters return an error completion code when the configuration change was successful
- Fixed IPMI OEM commands for setting and getting the serial number and product ID.
- Fixed an intermittent loss of OA communications after an iLO firmware update on a blade server.

## **Enhancements**

iLO 3 v1.88 includes the following enhancements:

- Added support for AES-CTR ciphers and HMAC-SHA2-256 to the SSH server.
- Disabled the CBC ciphers in the SSH server when iLO 3 is in FIPS mode or when the Enforce AES/3DES Encryption option is enabled.
- Certificate Signing Requests now use the SHA256 algorithm for the signature.
- The Java IRC now includes two alternatives: A Java Web Start console and a Java applet-based console. The Java Web Start option works in newer browsers that do not allow the applet version to run. On systems with OpenJDK, you must use the Java applet-based console with a browser (such as Firefox) that supports a Java plug-in.

---

## **Firmware - Network**

HP QLogic P3 Online Firmware Upgrade Utility for Windows Server x64 Editions

Version: 4.0.0.21 **(Optional)**

Filename: cp025867.exe

[Top](#)

## **Prerequisites**

This package requires the appropriate driver version for your network adapter be installed before firmware can be updated. This package requires one of the following, as appropriate for your platform:

- HP QLogic P3P Multifunction Driver for Windows Server 2008 x64 Editions, version 5.3.26.605 or later
- HP QLogic P3P Multifunction Driver for Windows Server 2008 R2, version 5.3.26.605 or later
- HP QLogic P3P Multifunction Driver for Windows Server 2012, version 5.3.26.605 or later
- HP QLogic P3P Multifunction Driver for Windows Server 2012 R2, version 5.3.26.605 or later

## **Enhancements**

This product contains an updated help file and component installer.

## **Supported Devices and Features**

This software supports the following HP QLogic P3 network adapters:

- HP NC375i Integrated Quad Port Multifunction Gigabit Server Adapter

---

HP QLogic P3 Online Firmware Upgrade Utility for Linux x86

Version: 5.6.10 **(Optional)**

Filename: hp-firmware-nic-netxen-5.6.10-1.1.i386.rpm

## **Important Note!**

HP recommends *HP QLogic nx\_nic Drivers*, versions 4.0.596.1-5, for use with this firmware.

## **Prerequisites**

This package requires an HP QLogic nx\_nic Drivers RPM for the appropriate platform be installed before firmware can be updated.

This package version can be used to upgrade adapters with firmware versioned 4.0.230 and later.

This package can be used with the HP Smart Update Manager (HPSUM) version 7.0.0.0 or later. Earlier versions of HPSUM cannot install this package correctly.

## **Enhancements**

This product now supports Red Hat Enterprise Linux 6 Update 7.

This product now supports SUSE LINUX Enterprise Server 11 SP4.

## **Supported Devices and Features**

This software supports the following HP QLogic P3 network adapters:

- HP NC375i Integrated Quad Port Multifunction Gigabit Server Adapter

---

HP QLogic P3 Online Firmware Upgrade Utility for Linux x86\_64

Version: 5.6.10 **(Optional)**

Filename: hp-firmware-nic-netxen-5.6.10-1.1.x86\_64.rpm

### **Important Note!**

HP recommends the following drivers, as appropriate, for use with this firmware:

- HP QLogic nx\_nic Drivers for Red Hat Enterprise Linux 6 x86\_64, version 4.0.596.1-5
- HP QLogic nx\_nic Drivers for Red Hat Enterprise Linux 7 x86\_64, version 4.0.596.1-2
- HP QLogic nx\_nic Drivers for SUSE Linux Enterprise Server 11 x86\_64, version 4.0.596.1-5
- HP QLogic nx\_nic Drivers for SUSE Linux Enterprise Server 12 x86\_64, version 4.0.596.1-4

### **Prerequisites**

This package requires an HP QLogic nx\_nic Drivers RPM for the appropriate platform be installed before firmware can be updated.

This package version can be used to upgrade adapters with firmware versioned 4.0.230 and later.

This package can be used with the HP Smart Update Manager (HPSUM) version 7.0.0.0 or later. Earlier versions of HPSUM cannot install this package correctly.

### **Enhancements**

This product now supports Red Hat Enterprise Linux 6 Update 7.

This product now supports SUSE LINUX Enterprise Server 11 SP4.

### **Supported Devices and Features**

This software supports the following HP QLogic P3 network adapters:

- HP NC375i Integrated Quad Port Multifunction Gigabit Server Adapter

---

HP QLogic P3 Online Firmware Upgrade Utility for Windows Server 2008

Version: 4.0.0.21 **(Optional)**

Filename: cp025866.exe

### **Prerequisites**

This package requires HP QLogic P3P Multifunction Driver for Windows Server 2008, version 5.3.26.605 or later, be installed before firmware can be updated.

### **Enhancements**

This product contains an updated help file and component installer.

### **Supported Devices and Features**

This software supports the following HP QLogic P3 network adapter:

- HP NC375i Integrated Quad Port Multifunction Gigabit Server Adapter

---

HP QLogic P3P Online Firmware Upgrade Utility for Linux x86

Version: 1.9.7 **(Optional)**

Filename: hp-firmware-nic-qlogic-p3p-1.9.7-1.1.i386.rpm

### **Important Note!**

HP recommends *HP QLogic qlcnic Drivers*, versions 5.3.62.1-4, for use with this firmware.

### **Prerequisites**

This package can be used with the *HP Smart Update Manager (HPSUM)* version 7.0.0.0 or later. Earlier versions of HPSUM cannot install this package correctly.

This package requires *HP QLogic qlcnic Drivers RPM* for the appropriate platform be installed before firmware can be updated.

### **Fixes**

This product addresses an issue that results in the Fibre Channel Ping command (fcping) taking more than 3ms for each ping.

### **Enhancements**

This product now supports Red Hat Enterprise Linux 6 Update 7.

This product now supports SUSE LINUX Enterprise Server 11 SP4.

### **Supported Devices and Features**

This package supports the following network adapters:

- HP CN1000Q Dual Port Converged Network Adapter
- HP NC523SFP 10Gb 2-port Ethernet Server Adapter
- HP FlexFabric 10Gb 2-port 526FLR-SFP+ Adapter

---

HP QLogic P3P Online Firmware Upgrade Utility for Linux x86\_64

Version: 1.9.7 **(Optional)**

Filename: hp-firmware-nic-qlogic-p3p-nic-1.9.7-1.1.x86\_64.rpm

### **Important Note!**

HP recommends the following drivers, as appropriate, for use with this firmware:

- HP QLogic qlcnic Drivers for Red Hat Enterprise Linux 6 x86\_64, version 5.3.62.1-4
- HP QLogic qlcnic Drivers for Red Hat Enterprise Linux 7 x86\_64, version 5.3.62.1-1
- HP QLogic qlcnic Drivers for Red Hat Enterprise Linux 11 x86\_64, version 5.3.62.1-4
- HP QLogic qlcnic Drivers for Red Hat Enterprise Linux 12 x86\_64, version 5.3.62.1-1

### **Prerequisites**

This package can be used with the *HP Smart Update Manager (HPSUM)* version 7.0.0.0 or later. Earlier versions of HPSUM cannot install this package correctly.

This package requires *HP QLogic qlcnic Drivers RPM* for the appropriate platform be installed before firmware can be updated.

### **Fixes**

This product addresses an issue that results in the Fibre Channel Ping command (fcping) taking more than 3ms for each ping.

### **Enhancements**

This product now supports Red Hat Enterprise Linux 6 Update 7.

This product now supports SUSE LINUX Enterprise Server 11 SP4.

### **Supported Devices and Features**

This package supports the following network adapters:

- HP CN1000Q Dual Port Converged Network Adapter
- HP NC523SFP 10Gb 2-port Ethernet Server Adapter
- HP FlexFabric 10Gb 2-port 526FLR-SFP+ Adapter

---

HP QLogic P3P Online Firmware Upgrade Utility for VMware

Version: 2.5.5 **(Optional)**

Filename: CP026998.txt; CP026998.zip

### **Important Note!**

HP recommends the following drivers, as appropriate, for use with the firmware provided in this package:

- HP QLogic P3P Drivers for VMware ESXi 5.0/vSphere 5.1, version 2015.02.23
- HP QLogic P3P iSCSI Drivers for VMware ESXi 5.0/vSphere 5.1, version 2015.07.17
- HP QLogic P3P Drivers for VMware vSphere 5.5/6.0, version 2015.02.23
- HP QLogic P3P iSCSI Drivers for VMware vSphere 5.5/6.0, version 2015.07.17
- HP QLogic P3P Drivers for VMware vSphere 6.0, version 2015.10.01
- HP QLogic P3P iSCSI Drivers for VMware vSphere 6.0, version 2015.10.01

### **Prerequisites**

This package requires the appropriate HP QLogic driver for VMware for your device to be installed before firmware can be updated.

### **Fixes**

This product addresses an issue that results in the Fibre Channel Ping command (fcping) taking more than 3ms for each ping.

### **Enhancements**

This product now supports VMware vSphere 6.0 Update 1.

### **Supported Devices and Features**

This package supports the following network adapters:

- HP CN1000Q Dual Port Converged Network Adapter
- HP NC523SFP 10Gb 2-port Ethernet Server Adapter
- HP FlexFabric 10Gb 2-port 526FLR-SFP+ Adapter

---

HPE Broadcom NX1 Online Firmware Upgrade Utility for Linux x86

Version: 2.17.6 **(Optional)**

Filename: hp-firmware-nic-broadcom-2.17.6-1.1.i386.rpm

### **Important Note!**

HPE recommends *HPE Broadcom tg3 Ethernet Drivers*, versions 3.137o or later, for use with this firmware.

### **Prerequisites**

This package can be used with the HP Smart Update Manager (HPSUM) version 7.0.0.0 or later. Earlier versions of HPSUM cannot install this package correctly.

This package requires the appropriate driver for your network adapter be installed and all Ethernet ports brought up (*ifup ethX* or *ifconfig ethX up*) before firmware can be updated.

### **Fixes**

This product addresses an issue where the server makes high speed fan noise after the PXE firmware on the adapter is updated to version 17.0.2.

This product addresses an issue where an incorrect firmware version is reported when updating firmware on the HP Ethernet 1Gb 2-port 332i Adapter.

This product addresses an issue where older smart components report an incorrect Bootcode version after the firmware on the adapter was originally updated using the component version 2.16.4 or later.

This product addresses an issue where an error code 7 is reported when updating firmware on the HP Ethernet 1Gb 4-port 331i-SPI Adapter.

---

HPE Broadcom NX1 Online Firmware Upgrade Utility for Linux x86\_64

Version: 2.17.6 **(Optional)**

Filename: hp-firmware-nic-broadcom-2.17.6-1.1.x86\_64.rpm

### **Important Note!**

HPE recommends *HPE Broadcom tg3 Ethernet Drivers*, versions 3.137o or later, for use with this firmware.

### **Prerequisites**

This package can be used with the HP Smart Update Manager (HPSUM) version 7.0.0.0 or later. Earlier versions of HPSUM cannot install this package correctly.

This package requires the appropriate driver for your network adapter be installed and all Ethernet ports brought up (*ifup ethX* or *ifconfig ethX up*) before firmware can be updated.

## **Fixes**

This product addresses an issue where the server makes high speed fan noise after the PXE firmware on the adapter is updated to version 17.0.2.

This product addresses an issue where an incorrect firmware version is reported when updating firmware on the HP Ethernet 1Gb 2-port 332i Adapter.

This product addresses an issue where older smart components report an incorrect Bootcode version after the firmware on the adapter was originally updated using the component version 2.16.4 or later.

This product addresses an issue where an error code 7 is reported when updating firmware on the HP Ethernet 1Gb 4-port 331i-SPI Adapter.

---

HPE Broadcom NX1 Online Firmware Upgrade Utility for VMware

Version: 1.14.5 **(Optional)**

Filename: CP028672.zip

## **Important Note!**

HPE recommends *HP Broadcom tg3 Ethernet Drivers for VMware*, versions 2015.10.01 or later, for use with this firmware.

## **Prerequisites**

This package requires the appropriate HPE Broadcom driver for VMware for your device to be installed before firmware can be updated.

## **Fixes**

This product addresses an issue where the server makes high speed fan noise after the PXE firmware on the adapter is updated to version 17.0.2.

---

HPE Broadcom NX1 Online Firmware Upgrade Utility for Windows Server 2008

Version: 5.0.0.22 **(Optional)**

Filename: cp028976.exe

## **Important Note!**

HPE recommends *HPE Broadcom 1Gb Driver for Windows Server 2008*, version 17.4.0.0 or later, for use with this firmware.

## **Prerequisites**

This package requires the *HPE Broadcom 1Gb Driver for Windows Server 2008* be installed before firmware can be updated.

## **Fixes**

This product addresses an issue where the server makes high speed fan noise after the PXE firmware on the adapter is updated to version 17.0.2.

---

HPE Broadcom NX1 Online Firmware Upgrade Utility for Windows Server x64 Editions

Version: 5.0.0.24 **(Optional)**

Filename: cp029395.exe

### **Important Note!**

HPE recommends *HPE Broadcom 1Gb Driver for Windows Server x64 Editions*, version 17.4.0.0, for use with this firmware.

### **Prerequisites**

This package requires the *HPE Broadcom 1Gb Driver for Windows Server x64 Editions* be installed before firmware can be updated.

### **Enhancements**

This product now supports Windows Server 2016.

---

HPE Firmware Flash for Emulex Converged Network Adapters - Linux (x64)

Version: 2016.10.05 **(Recommended)**

Filename: RPMS/x86\_64/hp-firmware-cna-emulex-2016.10.05-1.2.x86\_64.rpm

### **Important Note!**

Release Notes:

[HPE StoreFabric Emulex Adapters Release Notes](#)

### **Prerequisites**

Please consult SPOCK for a list of supported configurations available at the following link:

<http://www.hpe.com/storage/spock/>

The HPE supplied NIC driver must be installed prior to this firmware component if you want to update the firmware for the CNA. The driver is available on the HPE.com website at <http://www.hpe.com/>.

HPE Emulex 10Gbe Driver for Linux, version 11.1.183.21

Additional requirements:

The target environment must have the libsysfs or sysfsutils package installed prior to the installation of the firmware update kit. If not already present, the libsysfs or sysfsutils package can be obtained from the operating system installation media.

Environment must have 32-bit netlink library (libnl.so) installed for component to be able to discover Emulex HBAs/CNAs

Environment must be running the syslog daemon for the flash engine to run

Note: To enable the FCoE/iSCSI protocol on devices that support it, please install the appropriate HPE supplied Emulex FCoE/iSCSI driver. The FCoE protocol also requires the HPE Emulex Enablement Kit be installed. The driver and enablement kit are also available on the HPE.com website at <http://www.hpe.com/>.

The Enablement Kit requires that the target environment have the libHBAAPI package installed from your OS installation media.

Install the FC/FCoE Driver Kit, reboot, and then install the Enablement Kit.

### **Fixes**



This fix resolves the following:

- unexpected behavior in which ProLiant Gen 9 c-class server blades equipped with 650FLB or 650M adapters may not complete Power-On Self Test (POST)
- unexpected behavior which occurred after upgrading firmware to 11.1.183.23, resulting in network ports losing connections
- unexpected behavior in which 650FLB network ports were inadvertently assigned the same MAC address, resulting in network packets being sent to the incorrect ports.
- behavior in which Microsoft Windows terminates unexpectedly

## **Enhancements**

We have separate components to update fibre channel and converged network adapters. This is a converged network adapter update component.

Updated CNA (XE100 series) firmware

Contains:

CNA (BE3) firmware 11.1.183.23

CNA (XE100 series) firmware 11.1.183.62

## **Supported Devices and Features**

### **BE3:**

- HP NC552SFP 10Gb 2-port Ethernet Server Adapter
- HP NC553i 10Gb 2-port FlexFabric Converged Network Adapter
- HP CN1100E Dual Port Converged Network Adapter
- HP Flex-10 10Gb 2-port 552M Adapter
- HP FlexFabric 10Gb 2-port 554M Adapter
- HP FlexFabric 10Gb 2-port 554FLR-SFP+ Adapter
- HP FlexFabric 10Gb 2-port 554FLB Adapter

### **XE100 Series:**

- HP StoreFabric CN1200E Dual Port Converged Network Adapter
- HP Ethernet 10Gb 2-port 557SFP+ Adapter
- HP FlexFabric 20Gb 2-port 650FLB Adapter
- HP FlexFabric 20Gb 2-port 650M Adapter
- HP FlexFabric 10Gb 2-port 556FLR-SFP+ Adapter
- HPE StoreFabric CN1200E-T Adapter
- HPE FlexFabric 10Gb 2-port 556FLR-T Adapter

---

HPE Firmware Flash for Emulex Converged Network Adapters - Linux (x86)

Version: 2016.10.01 **(Recommended)**

Filename: RPMS/i386/hp-firmware-cna-emulex-2016.10.01-1.21.i386.rpm

## **Important Note!**

Release Notes:

[HPE StoreFabric Emulex Adapters Release Notes](#)

## **Prerequisites**

Please consult SPOCK for a list of supported configurations available at the following link:

<http://www.hpe.com/storage/spock/>

The HPE supplied NIC driver must be installed prior to this firmware component if you want to update the firmware for the CNA. The driver is available on the HPE.com website at <http://www.hpe.com/>.

HPE Emulex 10Gbe Driver for Linux, version 11.1.183.21

Additional requirements:

The target environment must have the libsysfs or sysfsutils package installed prior to the installation of the firmware update kit. If not already present, the libsysfs or sysfsutils package can be obtained from the operating system installation media.

Environment must have 32-bit netlink library (libnl.so) installed for component to be able to discover Emulex HBAs/CNAs

Environment must be running the syslog daemon for the flash engine to run

Note: To enable the FCoE/iSCSI protocol on devices that support it, please install the appropriate HPE supplied Emulex FCoE/iSCSI driver. The FCoE protocol also requires the HPE Emulex Enablement Kit be installed. The driver and enablement kit are also available on the HPE.com website at <http://www.hpe.com/>

The Enablement Kit requires that the target environment have the libHBAAPI package installed from your OS installation media.

Install the FC/FCoE Driver Kit, reboot, and then install the Enablement Kit.

## **Enhancements**

We have separate components to update fibre channel and converged network adapters. This is a converged network adapter update component.

Updated CNA (BE3) firmware

### **Firmware**

BE3 firmware:

- Provides a recovery mechanism that addresses unhandled exceptions on the supported devices
- Added Secure Firmware Update support
- Added PMCI Implementation Spec v1.03 (Active Health over MCTP)

Contains:

CNA (BE3) firmware 11.1.183.23

## **Supported Devices and Features**

### **BE3:**

- HP NC552SFP 10Gb 2-port Ethernet Server Adapter
- HP NC553i 10Gb 2-port FlexFabric Converged Network Adapter
- HP CN1100E Dual Port Converged Network Adapter
- HP Flex-10 10Gb 2-port 552M Adapter
- HP FlexFabric 10Gb 2-port 554M Adapter
- HP FlexFabric 10Gb 2-port 554FLR-SFP+ Adapter

HPE Firmware Flash for Emulex Converged Network Adapters - Windows (x64)

Version: 2016.10.05 **(Recommended)**

Filename: cp031846.exe

### **Important Note!**

Release Notes:

[HPE StoreFabric Emulex Adapters Release Notes](#)

### **Prerequisites**

Please consult SPOCK for a list of supported configurations available at the following link:

<http://www.hpe.com/storage/spock/>

The HPE supplied Emulex NIC driver must be installed prior to this firmware component being identified by HP SUM for deployment.

The driver is available on the HPE.com website at <http://www.hpe.com/>.

HPE Emulex 10GbE Driver for Windows Server 2008 x64 Editions v11.1.145.30 cp029510.exe

HPE Emulex 10GbE Driver for Windows Server 2008 R2 v11.1.145.30 cp029511.exe

HPE Emulex 10GbE Driver for Windows Server 2012 v11.1.145.30 cp029512.exe

HPE Emulex 10GbE Driver for Windows Server 2012 R2 v11.1.145.30 cp029513.exe

HPE Emulex 10/20 GbE Driver for Windows Server 2016 v11.1.196.4 cp029150.exe

Note: To enable the FCoE/iSCSI protocol on devices that support it, please install the appropriate HPE supplied Emulex FCoE/iSCSI driver which is available on the HPE.com website at <http://www.hpe.com/>.

### **Fixes**

This fix resolves the following:

- unexpected behavior in which ProLiant Gen 9 c-class server blades equipped with 650FLB or 650M adapters may not complete Power-On Self Test (POST)
- unexpected behavior which occurred after upgrading firmware to 11.1.183.23, resulting in network ports losing connections
- unexpected behavior in which 650FLB network ports were inadvertently assigned the same MAC address, resulting in network packets being sent to the incorrect ports.
- behavior in which Microsoft Windows terminates unexpectedly

### **Enhancements**

We have separate components to update fibre channel and converged network adapters. This is a converged network adapter update component.

Updated CNA (XE100 series) firmware

Contains:

CNA (BE3) firmware 11.1.183.23

CNA (XE100 series) firmware 11.1.183.62

## **Supported Devices and Features**

### **BE3:**

- HP NC552SFP 10Gb 2-port Ethernet Server Adapter
- HP NC553i 10Gb 2-port FlexFabric Converged Network Adapter
- HP CN1100E Dual Port Converged Network Adapter
- HP Flex-10 10Gb 2-port 552M Adapter
- HP FlexFabric 10Gb 2-port 554M Adapter
- HP FlexFabric 10Gb 2-port 554FLR-SFP+ Adapter
- HP FlexFabric 10Gb 2-port 554FLB Adapter

### **XE100 Series:**

- HP StoreFabric CN1200E Dual Port Converged Network Adapter
- HP Ethernet 10Gb 2-port 557SFP+ Adapter
- HP FlexFabric 20Gb 2-port 650FLB Adapter
- HP FlexFabric 20Gb 2-port 650M Adapter
- HP FlexFabric 10Gb 2-port 556FLR-SFP+ Adapter
- HPE StoreFabric CN1200E-T Adapter
- HPE FlexFabric 10Gb 2-port 556FLR-T Adapter

---

HPE Firmware Flash for Emulex Converged Network Adapters - Windows (x86)

Version: 2016.10.01 **(Recommended)**

Filename: cp029999.exe

### **Important Note!**

Release Notes:

[HPE StoreFabric Emulex Adapters Release Notes](#)

### **Prerequisites**

Please consult SPOCK for a list of supported configurations available at the following link:

<http://www.hpe.com/storage/spock/>

The HPE supplied Emulex NIC driver must be installed prior to this firmware component being identified by HP SUM for deployment.

The driver is available on the HPE.com website at <http://www.hpe.com/>.

HPE Emulex 10GbE Driver for Windows Server 2008 x86 Editions v11.1.145.30 cp029509.exe

Note: To enable the FCoE/iSCSI protocol on devices that support it, please install the appropriate HPE supplied Emulex FCoE/iSCSI driver available on the HPE.com website at <http://www.hpe.com/>.

### **Enhancements**

We have separate components to update fibre channel and converged network adapters. This is a converged network adapter update component.

Updated CNA (BE3) firmware

## **Firmware**

BE3 firmware:

- Provides a recovery mechanism that addresses unhandled exceptions on the supported devices
- Added Secure Firmware Update support
- Added PMCI Implementation Spec v1.03 (Active Health over MCTP)

Contains:

CNA (BE3) firmware 11.1.183.23

## **Supported Devices and Features**

### **BE3:**

- HP NC552SFP 10Gb 2-port Ethernet Server Adapter
- HP NC553i 10Gb 2-port FlexFabric Converged Network Adapter
- HP CN1100E Dual Port Converged Network Adapter
- HP Flex-10 10Gb 2-port 552M Adapter
- HP FlexFabric 10Gb 2-port 554M Adapter
- HP FlexFabric 10Gb 2-port 554FLR-SFP+ Adapter
- HP FlexFabric 10Gb 2-port 554FLB Adapter

---

HPE Intel Online Firmware Upgrade Utility for Linux x86

Version: 1.11.13 **(Recommended)**

Filename: hp-firmware-nic-intel-1.11.13-1.1.i386.rpm

### **Important Note!**

HPE recommends at least one of the following drivers, as appropriate for your device, for use with this firmware:

- HPE Intel igb Drivers for Linux, versions 5.3.5.3 or later
- HPE Intel ixgbe Drivers for Linux , versions 4.4.6 or later

### **Prerequisites**

This package requires the appropriate driver for your network adapter be installed before firmware can be updated.

This package can be used with the HP Smart Update Manager (HPSUM) version 7.0.0.0 or later. Earlier versions of HPSUM cannot install this package correctly.

### **Fixes**

This product fixes link flapping issue reported on the HP Ethernet 10Gb 2-port 560FLB Adapter.

## **Supported Devices and Features**

This package supports the following network adapters:

- HP Ethernet 1Gb 2-port 361i Adapter
- HP Ethernet 1Gb 2-port 361FLB Adapter
- HP Ethernet 1Gb 2-port 361T Adapter
- HP Ethernet 1Gb 2-port 363i Adapter
- HP Ethernet 1Gb 1-port 364i Adapter
- HP Ethernet 1Gb 4-port 366FLR Adapter
- HP Ethernet 1Gb 4-port 366i Adapter
- HP Ethernet 1Gb 4-port 366M Adapter
- HP Ethernet 1Gb 2-port 367i Adapter
- HP Ethernet 10Gb 2-port 560FLB Adapter
- HP Ethernet 10Gb 2-port 560FLR-SFP+ Adapter
- HP Ethernet 10Gb 2-port 560SFP+ Adapter
- HP Ethernet 10Gb 2-port 560M Adapter
- HP Ethernet 10Gb 2-port 561FLR-T Adapter
- HP Ethernet 10Gb 2-port 561T Adapter
- HP Ethernet 10Gb 2-port 562i Adapter

---

HPE Intel Online Firmware Upgrade Utility for Linux x86\_64

Version: 1.11.13 **(Recommended)**

Filename: hp-firmware-nic-intel-1.11.13-1.1x86\_64.rpm

### **Important Note!**

HPE recommends at least one of the following drivers, as appropriate for your device, for use with this firmware:

- HPE Intel igb Drivers for Linux, versions 5.3.5.3 or later
- HPE Intel ixgbe Drivers for Linux , versions 4.3.13 or later
- HPE Intel i40e Drivers for Linux, versions 1.3.46 or later

### **Prerequisites**

This product requires that the appropriate driver for the target device be installed before firmware can be updated.

This package can be used with the HP Smart Update Manager (HPSUM) version 7.0.0.0 or later. Earlier versions of HPSUM cannot install this package correctly.

### **Fixes**

This product fixes link flapping issue reported on the HP Ethernet 10Gb 2-port 560FLB Adapter.

This product addresses a security issue reported on the following network adapters:

- HP Ethernet 10Gb 2-port 562SFLR-FP+ Adapter
- HP Ethernet 10Gb 2-port 562SFP+ Adapter
- HPE Ethernet 10Gb 2-port 563i Adapter

See the security bulletin HPSBHF03695 for more information.

### **Supported Devices and Features**

This package supports the following network adapters:

- HP Ethernet 1Gb 2-port 361i Adapter

- HP Ethernet 1Gb 2-port 361FLB Adapter
- HP Ethernet 1Gb 2-port 361T Adapter
- HP Ethernet 1Gb 2-port 363i Adapter
- HP Ethernet 1Gb 1-port 364i Adapter
- HP Ethernet 1Gb 4-port 366FLR Adapter
- HP Ethernet 1Gb 4-port 366i Adapter
- HPE Ethernet 1Gb 4-port 366i Communication Board
- HP Ethernet 1Gb 4-port 366M Adapter
- HP Ethernet 1Gb 4-port 366T Adapter
- HP Ethernet 1Gb 2-port 367i Adapter
- HP Ethernet 10Gb 2-port 560FLB Adapter
- HP Ethernet 10Gb 2-port 560FLR-SFP+ Adapter
- HP Ethernet 10Gb 2-port 560SFP+ Adapter
- HP Ethernet 10Gb 2-port 560M Adapter
- HP Ethernet 10Gb 2-port 561FLR-T Adapter
- HP Ethernet 10Gb 2-port 561T Adapter
- HP Ethernet 10Gb 2-port 562i Adapter
- HPE Ethernet 10Gb 2-port 562SFLR-FP+ Adapter
- HPE Ethernet 10Gb 2-port 562SFP+ Adapter
- HPE Ethernet 10Gb 2-port 563i Adapter

---

HPE Intel Online Firmware Upgrade Utility for VMware

Version: 3.1.11 **(Recommended)**

Filename: CP031546.zip

### **Important Note!**

HPE recommends at least one of the following drivers, as appropriate for your device, for use with this firmware:

- *HPE Intel igb Drivers for VMware*, versions 2016.10.07 or later
- *HPE Intel ixgbe Drivers for VMware*, versions 2016.10.07 or later
- *HPE Intel i40e Drivers for VMware*, versions 2016.03.29 or later

### **Prerequisites**

This package requires the appropriate HPE Broadcom driver for VMware for your device to be installed before firmware can be updated.

### **Fixes**

This product fixes link flapping issue reported on the HP Ethernet 10Gb 2-port 560FLB Adapter.

This product addresses a security issue reported on the following network adapters:

- HP Ethernet 10Gb 2-port 562SFLR-FP+ Adapter
- HP Ethernet 10Gb 2-port 562SFP+ Adapter

See the security bulletin HPSBHF03695 for more information.

### **Supported Devices and Features**

This package supports the following network adapters:

- HP Ethernet 1Gb 2-port 361i Adapter

- HP Ethernet 1Gb 2-port 361FLB Adapter
- HP Ethernet 1Gb 2-port 361T Adapter
- HP Ethernet 1Gb 2-port 363i Adapter
- HP Ethernet 1Gb 1-port 364i Adapter
- HP Ethernet 1Gb 4-port 366FLR Adapter
- HP Ethernet 1Gb 4-port 366i Adapter
- HPE Ethernet 1Gb 4-port 366i Communication Board
- HP Ethernet 1Gb 4-port 366M Adapter
- HP Ethernet 1Gb 4-port 366T Adapter
- HP Ethernet 1Gb 2-port 367i Adapter
- HP Ethernet 10Gb 2-port 560FLB Adapter
- HP Ethernet 10Gb 2-port 560FLR-SFP+ Adapter
- HP Ethernet 10Gb 2-port 560SFP+ Adapter
- HP Ethernet 10Gb 2-port 560M Adapter
- HP Ethernet 10Gb 2-port 561FLR-T Adapter
- HP Ethernet 10Gb 2-port 561T Adapter
- HP Ethernet 10Gb 2-port 562i Adapter
- HPE Ethernet 10Gb 2-port 562SFLR-FP+ Adapter
- HPE Ethernet 10Gb 2-port 562SFP+ Adapter

---

HPE Intel Online Firmware Upgrade Utility for Windows Server 2008

Version: 5.0.0.27 (B) **(Recommended)**

Filename: cp031547.exe

### **Important Note!**

HPE recommends at least one of the following drivers, as appropriate for your device, for use with this firmware:

- *HP Intel E1R Driver for Windows Server 2008*, version 12.7.29.0(C) or later
- *HP Intel ixn/ixt Drivers for Windows Server 2008*, version 3.5.22.0(D) or later

### **Prerequisites**

This package requires the appropriate driver version for your network adapter be installed before firmware can be updated.

### **Fixes**

This product fixes link flapping issue reported on the HP Ethernet 10Gb 2-port 560FLB Adapter.

### **Supported Devices and Features**

This package supports the following network adapters:

- HP Ethernet 1Gb 2-port 361i Adapter
- HP Ethernet 1Gb 2-port 361FLB Adapter
- HP Ethernet 1Gb 2-port 361T Adapter
- HP Ethernet 1Gb 2-port 363i Adapter
- HP Ethernet 1Gb 1-port 364i Adapter
- HP Ethernet 1Gb 4-port 366FLR Adapter
- HP Ethernet 1Gb 4-port 366i Adapter
- HP Ethernet 1Gb 4-port 366M Adapter
- HP Ethernet 1Gb 2-port 367i Adapter



- HP Ethernet 10Gb 2-port 560FLB Adapter
- HP Ethernet 10Gb 2-port 560FLR-SFP+ Adapter
- HP Ethernet 10Gb 2-port 560SFP+ Adapter
- HP Ethernet 10Gb 2-port 560M Adapter
- HP Ethernet 10Gb 2-port 561FLR-T Adapter
- HP Ethernet 10Gb 2-port 561T Adapter
- HP Ethernet 10Gb 2-port 562i Adapter

---

HPE Intel Online Firmware Upgrade Utility for Windows Server x64 Editions

Version: 5.0.0.27 (B) **(Recommended)**

Filename: cp031548.exe

### **Important Note!**

HPE recommends at least one of the following, as appropriate for your device, for use with this firmware:

- *HP Intel E1R Driver for Windows Server 2008 x64 Editions*, version 12.7.29.0(C)
- *HPE Intel E1R Driver for Windows Server 2008 R2*, version 12.14.8.0
- *HPE Intel E1R Driver for Windows Server 2012*, version 12.14.8.0
- *HPE Intel E1R Driver for Windows Server 2012 R2*, version 12.14.8.0
- *HPE Intel E1R Driver for Windows Server 2016*, version 12.15.187.0
- *HP Intel ixn/ixt Drivers for Windows Server 2008 x64 Editions*, version 3.5.22.0(D)
- *HPE Intel ixn/ixt Drivers for Windows Server 2008 R2*, version 3.9.58.9101(C)
- *HPE Intel ixn/ixt Drivers for Windows Server 2012*, version 3.9.58.9101(C)
- *HPE Intel ixn/ixt Drivers for Windows Server 2012 R2*, version 3.9.58.9101(C)
- *HPE Intel ixn/ixt Drivers for Windows Server 2016*, version 4.0.213.0
- *HPE Intel i40ea Driver for Windows Server 2008 R2*, version 1.2.130.0 (C)
- *HPE Intel i40ea Driver for Windows Server 2012*, version 1.2.133.0 (B)
- *HPE Intel i40ea Driver for Windows Server 2012 R2*, version 1.2.133.0(C)
- *HPE Intel i40ea Driver for Windows Server 2016*, version 1.5.59.0

### **Prerequisites**

This package requires the appropriate driver for your network adapter be installed before firmware can be updated.

### **Fixes**

This product fixes link flapping issue reported on the HP Ethernet 10Gb 2-port 560FLB Adapter.

This product addresses a security issue reported on the following network adapters:

- HP Ethernet 10Gb 2-port 562SFLR-FP+ Adapter
- HP Ethernet 10Gb 2-port 562SFP+ Adapter

See the security bulletin HPSBHF03695 for more information.

### **Supported Devices and Features**

This package supports the following network adapters:

- HP Ethernet 1Gb 2-port 361i Adapter
- HP Ethernet 1Gb 2-port 361FLB Adapter

- HP Ethernet 1Gb 2-port 361T Adapter
- HP Ethernet 1Gb 2-port 363i Adapter
- HP Ethernet 1Gb 1-port 364i Adapter
- HP Ethernet 1Gb 4-port 366FLR Adapter
- HP Ethernet 1Gb 4-port 366i Adapter
- HPE Ethernet 1Gb 4-port 366i Communication Board
- HP Ethernet 1Gb 4-port 366M Adapter
- HP Ethernet 1Gb 4-port 366T Adapter
- HP Ethernet 1Gb 2-port 367i Adapter
- HP Ethernet 10Gb 2-port 560FLB Adapter
- HP Ethernet 10Gb 2-port 560FLR-SFP+ Adapter
- HP Ethernet 10Gb 2-port 560SFP+ Adapter
- HP Ethernet 10Gb 2-port 560M Adapter
- HP Ethernet 10Gb 2-port 561FLR-T Adapter
- HP Ethernet 10Gb 2-port 561T Adapter
- HP Ethernet 10Gb 2-port 562i Adapter
- HPE Ethernet 10Gb 2-port 562SFLR-FP+ Adapter
- HPE Ethernet 10Gb 2-port 562SFP+ Adapter

---

HPE QLogic NC382i/NC532x Online Firmware Upgrade Utility for Linux x86

Version: 2.18.1 **(Optional)**

Filename: CP028810.scexe; CP028810.txt; hp-firmware-nic-qlogic-57xx-2.18.1-1.1.i386.rpm

### **Important Note!**

HPE recommends the *HPE QLogic NX2 1/10/20 GbE Multifunction Drivers*, version 7.13.59-1 or later, for use with the firmware in this product.

### **Prerequisites**

This package can be used with the HP Smart Update Manager (HPSUM) version 7.0.0.0 or later. Earlier versions of HPSUM cannot install this package correctly.

This package requires the appropriate driver for your network adapter be installed and all Ethernet ports brought up (*ifup ethX* or *ifconfig ethX up*) before firmware can be updated.

### **Enhancements**

Initial release.

### **Supported Devices and Features**

This product supports the following network adapters:

- HP NC382i Integrated Dual Port Multifunction Gigabit Server Adapter
- HP NC532i Dual Port 10GbE Multifunction BL-c Adapter (3654)
- HP NC532i Dual Port 10GbE Multifunction BL-c Adapter (7058)
- HP NC532m Dual Port 10GbE Multifunction BL-c Adapter

---

HPE QLogic NC382i/NC532x Online Firmware Upgrade Utility for Linux x86\_64

Version: 2.18.1 **(Optional)**

### **Important Note!**

HPE recommends the *HPE QLogic NX2 1/10/20 GbE Multifunction Drivers*, version 7.13.59-1 or later, for use with the firmware in this product.

### **Prerequisites**

This package can be used with the HP Smart Update Manager (HPSUM) version 7.0.0.0 or later. Earlier versions of HPSUM cannot install this package correctly.

This package requires the appropriate driver for your network adapter be installed and all Ethernet ports brought up (*ifup ethX* or *ifconfig ethX up*) before firmware can be updated.

### **Enhancements**

Initial release.

### **Supported Devices and Features**

This product supports the following network adapters:

- HP NC382i Integrated Dual Port Multifunction Gigabit Server Adapter
- HP NC532i Dual Port 10GbE Multifunction BL-c Adapter (3654)
- HP NC532i Dual Port 10GbE Multifunction BL-c Adapter (7058)
- HP NC532m Dual Port 10GbE Multifunction BL-c Adapter

---

HPE QLogic NC382i/NC532x Online Firmware Upgrade Utility for VMware

Version: 1.15.1 **(Optional)**

Filename: CP028840.zip

### **Important Note!**

HPE recommends the *HPE QLogic NX2 1/10/20 GbE Multifunction Drivers for VMware*, version 2016.10.07 or later, for use with the firmware in this package.

### **Prerequisites**

This package requires the appropriate HPE QLogic NX2 driver for VMware for your device to be installed before firmware can be updated.

### **Enhancements**

Initial release.

### **Supported Devices and Features**

This product supports the following network adapters:

- HP NC382i Integrated Dual Port Multifunction Gigabit Server Adapter
- HP NC532i Dual Port 10GbE Multifunction BL-c Adapter
- HP NC532m Dual Port 10GbE Multifunction BL-c Adapter

---

HPE QLogic NC382i/NC532x Online Firmware Upgrade Utility for Windows Server 2008

Version: 4.1.0.25 **(Optional)**

Filename: cp028812.exe

### **Important Note!**

HPE recommends the following drivers, as applicable, for use with the firmware in this product:

- *HP Broadcom 1Gb Multifunction Drivers for Windows Server 2008*, version 7.8.50.0(D) or later
- *HPE QLogic NX2 10/20GbE Multifunction Driver for Windows Server 2008*, version 7.13.60.0 or later

### **Prerequisites**

This package requires the appropriate driver for your network adapter be installed before firmware can be updated.

### **Enhancements**

Initial release.

### **Supported Devices and Features**

This product supports the following network adapters:

- HP NC382i Integrated Dual Port Multifunction Gigabit Server Adapter
- HP NC532i Dual Port 10GbE Multifunction BL-c Adapter
- HP NC532m Dual Port 10GbE Multifunction BL-c Adapter

---

HPE QLogic NC382i/NC532x Online Firmware Upgrade Utility for Windows Server x64 Editions

Version: 4.1.0.25 **(Optional)**

Filename: cp028813.exe

### **Important Note!**

HPE recommends the following drivers, as applicable, for use with the firmware in this product:

- *HP Broadcom 1Gb Multifunction Drivers for Windows Server 2008 x64 Editions*, version 7.8.50.0(D) or later
- *HPE QLogic NX2 10/20GbE Multifunction Driver for Windows Server 2008 x64 Editions*, version 7.13.60.0 or later

### **Prerequisites**

This package requires the appropriate driver for your network adapter be installed before firmware can be updated.

### **Enhancements**

Initial release.

### **Supported Devices and Features**

This product supports the following network adapters:

- HP NC382i Integrated Dual Port Multifunction Gigabit Server Adapter
- HP NC532i Dual Port 10GbE Multifunction BL-c Adapter
- HP NC532m Dual Port 10GbE Multifunction BL-c Adapter

---

HPE QLogic NX2 Online Firmware Upgrade Utility for Linux x86

Version: 2.18.44 **(Optional)**

Filename: hp-firmware-nic-qlogic-nx2-2.18.44-1.1.i386.rpm

### **Important Note!**

HPE recommends *HPE QLogic NX2 1/10/20 GbE Multifunction Drivers for Linux*, versions 7.14.07 or later, for use with the firmware in this package.

### **Prerequisites**

This package can be used with the HP Smart Update Manager (HPSUM) version 7.0.0.0 or later. Earlier versions of HPSUM cannot install this package correctly.

This package requires the appropriate driver for your network adapter be installed and all Ethernet ports brought up (*ifup ethX* or *ifconfig ethX up*) before firmware can be updated.

### **Fixes**

This product addresses an issue where the iSCSI and FCoE configuration menus are displayed after NPAR is enabled.

This product addresses an issue where expected network devices don't appear in the Legacy BIOS Boot Order menu.

---

HPE QLogic NX2 Online Firmware Upgrade Utility for Linux x86\_64

Version: 2.18.44 **(Optional)**

Filename: hp-firmware-nic-qlogic-nx2-2.18.44-1.1.x86\_64.rpm

### **Important Note!**

HPE recommends *HPE QLogic NX2 1/10/20 GbE Multifunction Drivers for Linux*, versions 7.14.07 or later, for use with the firmware in this package.

### **Prerequisites**

This package can be used with the HP Smart Update Manager (HPSUM) version 7.0.0.0 or later. Earlier versions of HPSUM cannot install this package correctly.

This package requires the appropriate driver for your network adapter be installed and all Ethernet ports brought up (*ifup ethX* or *ifconfig ethX up*) before firmware can be updated.

### **Fixes**

This product addresses an issue where the iSCSI and FCoE configuration menus are displayed after NPAR is enabled.

This product addresses an issue where expected network devices don't appear in the Legacy BIOS Boot Order menu.

### **Enhancements**

This product now supports the following network adapters:

- HPE Synergy 3820C 10/20Gb Converged Network Adapter
- HPE Synergy 10Gb 2-port 2820C Converged Network Adapter

---

HPE QLogic NX2 Online Firmware Upgrade Utility for VMware

Version: 1.12.43 **(Optional)**

Filename: CPO28018.zip

### **Important Note!**

HPE recommends HPE QLogic NX2 1/10/20 GbE Multifunction Drivers for VMware, versions 2016.10.07 or later, for use with the firmware in this package.

### **Prerequisites**

This package requires the appropriate HPE QLogic NX2 driver for VMware for your device to be installed before firmware can be updated.

### **Enhancements**

This product now supports the following network adapters:

- HPE Synergy 10Gb 2820C Ethernet Adapter
- HPE Synergy 3820C 10/20Gb Converged Network Adapter

---

HPE QLogic NX2 Online Firmware Upgrade Utility for Windows Server 2008

Version: 5.0.0.24 **(Optional)**

Filename: cp028019.exe

### **Important Note!**

HPE recommends *HPE QLogic NX2 10/20GbE Multifunction Drivers for Windows Server 2008*, version 7.13.104.0 or later, for use with the firmware in this package.

### **Prerequisites**

This package requires the appropriate driver version for your network adapter be installed before firmware can be updated.

### **Fixes**

This product addresses an issue where the iSCSI and FCoE configuration menus are displayed after NPAR is enabled.

This product addresses an issue where expected network devices don't appear in the Legacy BIOS Boot Order menu.

---

HPE QLogic NX2 Online Firmware Upgrade Utility for Windows Server x64 Editions

Version: 5.0.0.24 **(Optional)**

Filename: cp028020.exe

### **Important Note!**

HPE recommends *HPE QLogic NX2 10/20GbE Multifunction Drivers for Windows Server 2008 x64 Editions*, version 7.13.104.0 or later, for use with the firmware in this package.

### **Prerequisites**

This package requires the appropriate driver version for your network adapter be installed before firmware can be updated.

### **Enhancements**

This product now supports Windows Server 2016.

This product now supports the following network adapters:

- HPE Synergy 10Gb 2820C Ethernet Adapter
- HPE Synergy 3820C 10/20Gb Converged Network Adapter

---

HPE QLogic P3P Online Firmware Upgrade Utility for Windows Server 2008

Version: 4.0.0.21 (C) **(Optional)**

Filename: cp027813.exe

### **Important Note!**

HPE recommends *HPE QLogic P3P Multifunction Driver for Windows Server 2008*, version 5.3.30.1001, for use with this firmware.

### **Prerequisites**

This package requires the driver for your adapter be installed before firmware can be updated.

### **Fixes**

This product addresses a rarely seen issue where an attempt to flash updates to an adapter results in an "incompatible table layout" error message.

### **Supported Devices and Features**

This package supports the following network adapters:

- HP CN1000Q Dual Port Converged Network Adapter
- HP NC523SFP 10Gb 2-port Ethernet Server Adapter
- HP FlexFabric 10Gb 2-port 526FLR-SFP+ Adapter

---

HPE QLogic P3P Online Firmware Upgrade Utility for Windows Server x64 Editions

Version: 4.0.0.21 (C) **(Optional)**

Filename: cp027814.exe

## **Important Note!**

HPE recommends the appropriate *HPE QLogic P3P Multifunction Driver*, versions 5.3.30.1001, for use with this firmware.

## **Prerequisites**

This package requires the appropriate driver for your platform be installed before firmware can be updated.

## **Fixes**

This product addresses a rarely seen issue where an attempt to flash updates to an adapter results in an "incompatible table layout" error message.

## **Supported Devices and Features**

This package supports the following network adapters:

- HP CN1000Q Dual Port Converged Network Adapter
- HP NC523SFP 10Gb 2-port Ethernet Server Adapter
- HP FlexFabric 10Gb 2-port 526FLR-SFP+ Adapter

---

Online Firmware Upgrade Utility (ESXi 5.5) for HPE Mellanox VPI (Ethernet and Infiniband mode) devices on VMware ESXi 5.5

Version: 1.0.4 (A) **(Recommended)**

Filename: CP030114.zip

## **Important Note!**

### **Known Issues:**

- Downgrading from v2.30.8000 or later to an earlier version than 2.30.8000 requires server reboot.  
**Workaround:** Reboot the server.
- On ConnectX-3 Ethernet adapter cards, there is a mismatch between the GUID value returned by firmware management cards tools and that returned by fabric/driver utilities that read the GUID via device firmware (e.g., using `ibstat`). `MLxburn/flint` return `0xffff` as GUID while the utilities return a value derived from the MAC address. For all driver/firmware/software purposes, the latter value should be used.  
**Workaround:** Use the GUID value returned by the fabric/driver utilities (not `0xffff`).
- SBR should be asserted for a minimum of 50 milliseconds for the ConnectX<sup>®</sup>-3 adapters.
- On Pilot1 SL230, PCIe link occasionally does not come up at Gen3 speed.
- RH6.3 Inbox driver causes kernel panic when SR-IOV is enabled on VPI cards due to driver compatibility issue.
- In advanced steering mode, side band management connectivity may be lost when having more than 8 QP per mcg.
- When SR-IOV is disabled in the system BIOS, a PCI issue is noticed in Ubuntu v12.04.3 with Linux kernel v3.8 which affects NICs of several manufacturers including Mellanox's, preventing them from operating.  
**Workaround:** Enable SR-IOV in the BIOS.
- PCIe Gen2 link unstable at temperature sweep of 10C/min for MT27518A1 FDIR-BV.
- When working in VPI mode with port1 FDR and port2 40G, error counters misbehave and increase rapidly.
- MFT tools might leave the flash semaphore locked if the tool operation is forced stopped. The locked semaphore prevents the firmware from accessing the flash and causes firmware hang.  
**Workaround:** Clear the semaphore using MFT command: `flint -clear_semaphore`
- Cable Info MAD reports a wrong cable info when using the MC2210411-SR4 module.
- Driver restart required when switching from InfiniBand FDR link with LLR enabled to InfiniBand link w/o LLR (for example: between



SwitchX® and GD4036).

- o Bloom filter is currently not supported.
- o When downgrading from firmware v2.11.0000 and using MFT 3.0.0-3, Release the following message is displayed due to the mlxconfig tool:  
DMFS steering mode with IB in Linux You are trying to override configurable FW by non-configurable FW. If you continue, old FW configurations will be cleared, do you want to continue ? (y/n) [n] : y  
You are trying to restore default configuration, do you want to continue ? (y/n) [n] :y
- o DMFS should not be enabled when working with InfiniBand on MLNX\_OFED-2.0.3.  
**Workaround:** Upgrade to MLNX\_OFED-2.1-x.x.x. or later.
- o VPD read-only fields are writable.  
**Workaround:** Do not write to read- only fields if you wish to preserve them.
- o Setting the device to 128Byte CQ/EQ stride will cause misbehavior of sideband management resulting in communication loss.
- o CQ and EQ cannot be configured to different stride sizes.
- o ConnectX-3 Pro VF device ID is presented the same as ConnectX-3 VF device ID due to driver limitations.  
**Workaround:** Use the physical function device ID to identify the device.
- o Changing port protocol from ETH to IB on port with NCSI/IPMI enabled while the port is connected to ETH switch is not supported.  
**Workaround:**
  - Unplug the cable from the switch
  - Restart driver
  - Change the protocol via the appropriate tools.
- o RDP over IPv6 is currently not functional.  
**Workaround:** Set the default RoCE mode in the software to RoCE v2 (also when not using RoCE).
- o Sniffer QP cannot be removed from the regular rule after adding the QP with insertion scheme equals to “push to that rule”.
- o The NIC does not notify the driver of a link-down incident when a cable is unplugged from a NIC port with 56GbE port link.
- o Since only a single Boot Entry Vector (BEV) per PCI Physical Function is supported, disabling the first port causes the second port to disappear as well.
- o 56GbE link is not raised when using 100GbE optic cables.

## **Fixes**

### **Fixes in 2.36.5000:**

- o Fixed an issue which caused packet transmission to get stuck when the software tried to send pause frames with dmac equal to one of the device's MAC addresses.
- o Fixed an issue which caused a firmware internal error when handling QP alternative context.
- o Fixed an issue which caused an internal firmware error when APM changed the QPs port mapping.
- o Fixed an issue which caused NVRAM to get stuck when it filled non-valid information in TLV.
- o Fixed an issue which caused lack of IB traffic on SR-IOV VPI.
- o Fixed a race in handling a duplicated “read request from middle”.
- o Fixed an issue which caused NVCONFIG to fail when the number of sector was set to 1 and the sector was zeroed.
- o Fixed an issue which caused TX traffic to stop when the message MTU size was larger than QP.mtu.
- o MLNX\_OEM command GET\_TEMP returned a wrong value in the max\_temp field.
- o Fixed a default hardware configuration issue which caused RDP over IPv4 traffic to be dropped.
- o Fixed performance issues causing slow performance when running in NO-DRAM-NIC mode.
- o Disabled High Rate Steering mode in the INI to enable its compatibility with NC-SI over VLAN.
- o Fixed failure instances when initiating FLR in the Physical Function.
- o Fixed a wrong returned status in cable info MAD when the cable was not connected.
- o Fixed the length calculation of UDP. The incorrect UDP length in the CNP packet caused miss-calculation of the ICRC.
- o Fixed a completion error issue when ECN was enabled. The ECN usage caused ordering errors in completion queues (CQ).

## **Enhancements**

### **Firmware for the following devices are updated to 2.36.5000:**

644161-B21  
644160-B21  
649282-B21  
649281-B21  
649283-B21

**Firmware for the following devices are updated to 2.36.5000:**

764282-B21  
764283-B21  
764284-B21

**Firmware for the following devices are updated to 2.36.5000:**

764285-B21  
764286-B21

**Supported Devices and Features**

**Supported Devices:**

HP Part Number	Device Name	PSID
644161-B21	HP InfiniBand FDR/EN 10/40Gb Dual Port 544M Adapter	HP_0240230019
644160-B21	HP InfiniBand QDR/EN 10Gb Dual Port 544M Adapter	HP_0250230018
649281-B21	HP InfiniBand FDR/EN 10/40Gb Dual Port 544QSFP Adapter	HP_0280210019
649282-B21	HP InfiniBand FDR/EN 10/40Gb Dual Port 544FLR-QSFP Adapter	HP_0230240019 HP_0230220019
649283-B21	HP InfiniBand QDR/EN 10Gb Dual Port 544FLR-QSFP Adapter	HP_0230240009 HP_0230220009
764282-B21	HP InfiniBand QDR/Ethernet 10Gb 2-port 544+M Adapter	HP_1350110023
764283-B21	HP InfiniBand FDR/Ethernet 10Gb/40Gb 2-port 544+M Adapter	HP_1360110017
764284-B21	HP InfiniBand FDR/Ethernet 10Gb/40Gb 2-port 544+QSFP Adapter	HP_1370110017
764285-B21	HP InfiniBand FDR/Ethernet 10Gb/40Gb 2-port 544+FLR-QSFP Adapter	HP_1380110017
764286-B21	HP InfiniBand QDR/Ethernet 10Gb 2-port 544+FLR-QSFP Adapter	HP_1390110023

---

Online Firmware Upgrade Utility (ESXi 6.0) for HPE Mellanox VPI (Ethernet and Infiniband mode) devices on VMware ESXi 6.0

Version: 1.0.4 (A) **(Recommended)**

Filename: CPO30115.zip

**Important Note!**

## Known Issues:

- Downgrading from v2.30.8000 or later to an earlier version than 2.30.8000 requires server reboot.  
**Workaround:** Reboot the server.
- On ConnectX-3 Ethernet adapter cards, there is a mismatch between the GUID value returned by firmware management cards tools and that returned by fabric/driver utilities that read the GUID via device firmware (e.g., using ibstat). MLxburn/flint return 0xffff as GUID while the utilities return a value derived from the MAC address. For all driver/firmware/software purposes, the latter value should be used.  
**Workaround:** Use the GUID value returned by the fabric/driver utilities (not 0xffff).
- SBR should be asserted for a minimum of 50 milliseconds for the ConnectX®-3 adapters.
- On Pilot1 SL230, PCIe link occasionally does not come up at Gen3 speed.
- RH6.3 Inbox driver causes kernel panic when SR-IOV is enabled on VPI cards due to driver compatibility issue.
- In advanced steering mode, side band management connectivity may be lost when having more than 8 QP per mcg.
- When SR-IOV is disabled in the system BIOS, a PCI issue is noticed in Ubuntu v12.04.3 with Linux kernel v3.8 which affects NICs of several manufacturers including Mellanox's, preventing them from operating.  
**Workaround:** Enable SR-IOV in the BIOS.
- PCIe Gen2 link unstable at temperature sweep of 10C/min for MT27518A1 FDIR-BV.
- When working in VPI mode with port1 FDR and port2 40G, error counters misbehave and increase rapidly.
- MFT tools might leave the flash semaphore locked if the tool operation is forced stopped. The locked semaphore prevents the firmware from accessing the flash and causes firmware hang.  
**Workaround:** Clear the semaphore using MFT command: flint -clear\_semaphore
- Cable Info MAD reports a wrong cable info when using the MC2210411-SR4 module.
- Driver restart required when switching from InfiniBand FDR link with LLR enabled to InfiniBand link w/o LLR (for example: between SwitchX® and GD4036).
- Bloom filter is currently not supported.
- When downgrading from firmware v2.11.0000 and using MFT 3.0.0-3, Release the following message is displayed due to the mlxconfig tool:  
DMFS steering mode with IB in Linux You are trying to override configurable FW by non-configurable FW. If you continue, old FW configurations will be cleared, do you want to continue ? (y/n) [n] : y  
You are trying to restore default configuration, do you want to continue ? (y/n) [n] : y
- DMFS should not be enabled when working with InfiniBand on MLNX\_OFED-2.0.3.  
**Workaround:** Upgrade to MLNX\_OFED-2.1-x.x.x. or later.
- VPD read-only fields are writable.  
**Workaround:** Do not write to read- only fields if you wish to preserve them.
- Setting the device to 128Byte CQ/EQ stride will cause misbehavior of sideband management resulting in communication loss.
- CQ and EQ cannot be configured to different stride sizes.
- ConnectX-3 Pro VF device ID is presented the same as ConnectX-3 VF device ID due to driver limitations.  
**Workaround:** Use the physical function device ID to identify the device.
- Changing port protocol from ETH to IB on port with NCSI/IPMI enabled while the port is connected to ETH switch is not supported.  
**Workaround:**
  - Unplug the cable from the switch
  - Restart driver
  - Change the protocol via the appropriate tools.
- RDP over IPv6 is currently not functional.  
**Workaround:** Set the default RoCE mode in the software to RoCE v2 (also when not using RoCE).
- Sniffer QP cannot be removed from the regular rule after adding the QP with insertion scheme equals to "push to that rule".
- The NIC does not notify the driver of a link-down incident when a cable is unplugged from a NIC port with 56GbE port link.
- Since only a single Boot Entry Vector (BEV) per PCI Physical Function is supported, disabling the first port causes the second port to disappear as well.
- 56GbE link is not raised when using 100GbE optic cables.

## **Fixes**

### **Fixes in 2.36.5000:**

- Fixed an issue which caused packet transmission to get stuck when the software tried to send pause frames with dmac equal to one of the device's MAC addresses.
- Fixed an issue which caused a firmware internal error when handling QP alternative context.
- Fixed an issue which caused an internal firmware error when APM changed the QPs port mapping.
- Fixed an issue which caused NVRAM to get stuck when it filled non-valid information in TLV.
- Fixed an issue which caused lack of IB traffic on SR-IOV VPI.
- Fixed a race in handling a duplicated "read request from middle".
- Fixed an issue which caused NVCONFIG to fail when the number of sector was set to 1 and the sector was zeroed.
- Fixed an issue which caused TX traffic to stop when the message MTU size was larger than QP.mtu.
- MLNX\_OEM command GET\_TEMP returned a wrong value in the max\_temp field.
- Fixed a default hardware configuration issue which caused RDP over IPv4 traffic to be dropped.
- Fixed performance issues causing slow performance when running in NO-DRAM-NIC mode.
- Disabled High Rate Steering mode in the INI to enable its compatibility with NC-SI over VLAN.
- Fixed failure instances when initiating FLR in the Physical Function.
- Fixed a wrong returned status in cable info MAD when the cable was not connected.
- Fixed the length calculation of UDP. The incorrect UDP length in the CNP packet caused miss-calculation of the ICRC.
- Fixed a completion error issue when ECN was enabled. The ECN usage caused ordering errors in completion queues (CQ).

## **Enhancements**

### **Firmware for the following devices are updated to 2.36.5000:**

644161-B21  
644160-B21  
649282-B21  
649281-B21  
649283-B21

### **Firmware for the following devices are updated to 2.36.5000:**

764282-B21  
764283-B21  
764284-B21

### **Firmware for the following devices are updated to 2.36.5000:**

764285-B21  
764286-B21

## **Supported Devices and Features**

### **Supported Devices:**

HP Part Number	Device Name	PSID
644161-B21	HP InfiniBand FDR/EN 10/40Gb Dual Port 544M Adapter	HP_0240230019
644160-B21	HP InfiniBand QDR/EN 10Gb Dual Port 544M Adapter	HP_0250230018

649281-B21	HP InfiniBand FDR/EN 10/40Gb Dual Port 544QSFP Adapter	HP_0280210019
649282-B21	HP InfiniBand FDR/EN 10/40Gb Dual Port 544FLR-QSFP Adapter	HP_0230240019 HP_0230220019
649283-B21	HP InfiniBand QDR/EN 10Gb Dual Port 544FLR-QSFP Adapter	HP_0230240009 HP_0230220009
764282-B21	HP InfiniBand QDR/Ethernet 10Gb 2-port 544+M Adapter	HP_1350110023
764283-B21	HP InfiniBand FDR/Ethernet 10Gb/40Gb 2-port 544+M Adapter	HP_1360110017
764284-B21	HP InfiniBand FDR/Ethernet 10Gb/40Gb 2-port 544+QSFP Adapter	HP_1370110017
764285-B21	HP InfiniBand FDR/Ethernet 10Gb/40Gb 2-port 544+FLR-QSFP Adapter	HP_1380110017
764286-B21	HP InfiniBand QDR/Ethernet 10Gb 2-port 544+FLR-QSFP Adapter	HP_1390110023

---

Online Firmware Upgrade Utility (Linux x86\_64) for HPE Mellanox VPI (Ethernet and Infiniband mode) devices on Linux x86\_64 platform

Version: 1.0.4 (A) **(Recommended)**

Filename: hp-firmware-hca-mellanox-vpi-eth-ib-1.0.4-2.1.x86\_64.rpm

### **Important Note!**

#### **Known Issues:**

- Downgrading from v2.30.8000 or later to an earlier version than 2.30.8000 requires server reboot.  
**Workaround:** Reboot the server.
- On ConnectX-3 Ethernet adapter cards, there is a mismatch between the GUID value returned by firmware management cards tools and that returned by fabric/driver utilities that read the GUID via device firmware (e.g., using ibstat). Mlxburn/flint return 0xffff as GUID while the utilities return a value derived from the MAC address. For all driver/firmware/software purposes, the latter value should be used.  
**Workaround:** Use the GUID value returned by the fabric/driver utilities (not 0xffff).
- SBR should be asserted for a minimum of 50 milliseconds for the ConnectX®-3 adapters.
- On Pilot1 SL230, PCIe link occasionally does not come up at Gen3 speed.
- RH6.3 Inbox driver causes kernel panic when SR-IOV is enabled on VPI cards due to driver compatibility issue.
- In advanced steering mode, side band management connectivity may be lost when having more than 8 QP per mcg.
- When SR-IOV is disabled in the system BIOS, a PCI issue is noticed in Ubuntu v12.04.3 with Linux kernel v3.8 which affects NICs of several manufacturers including Mellanox's, preventing them from operating.  
**Workaround:** Enable SR-IOV in the BIOS.
- PCIe Gen2 link unstable at temperature sweep of 10C/min for MT27518A1 FDIR-BV.
- When working in VPI mode with port1 FDR and port2 40G, error counters misbehave and increase rapidly.
- MFT tools might leave the flash semaphore locked if the tool operation is forced stopped. The locked semaphore prevents the firmware from accessing the flash and causes firmware hang.  
**Workaround:** Clear the semaphore using MFT command: flint -clear\_semaphore
- Cable Info MAD reports a wrong cable info when using the MC2210411-SR4 module.
- Driver restart required when switching from InfiniBand FDR link with LLR enabled to InfiniBand link w/o LLR (for example: between SwitchX® and GD4036).
- Bloom filter is currently not supported.
- When downgrading from firmware v2.11.0000 and using MFT 3.0.0-3, Release the following message is displayed due to the mlxconfig

tool:

DMFS steering mode with IB in Linux You are trying to override configurable FW by non-configurable FW. If you continue, old FW configurations will be cleared, do you want to continue ? (y/n) [n] : y

You are trying to restore default configuration, do you want to continue ? (y/n) [n] :y

- DMFS should not be enabled when working with InfiniBand on MLNX\_OFED-2.0.3.

**Workaround:** Upgrade to MLNX\_OFED-2.1-x.x.x. or later.

- VPD read-only fields are writable.

**Workaround:** Do not write to read- only fields if you wish to preserve them.

- Setting the device to 128Byte CQ/EQ stride will cause misbehavior of sideband management resulting in communication loss.
- CQ and EQ cannot be configured to different stride sizes.
- ConnectX-3 Pro VF device ID is presented the same as ConnectX-3 VF device ID due to driver limitations.

**Workaround:** Use the physical function device ID to identify the device.

- Changing port protocol from ETH to IB on port with NCSI/IPMI enabled while the port is connected to ETH switch is not supported.

**Workaround:**

- Unplug the cable from the switch
- Restart driver
- Change the protocol via the appropriate tools.

- RDP over IPv6 is currently not functional.

**Workaround:** Set the default RoCE mode in the software to RoCE v2 (also when not using RoCE).

- Sniffer QP cannot be removed from the regular rule after adding the QP with insertion scheme equals to "push to that rule".
- The NIC does not notify the driver of a link-down incident when a cable is unplugged from a NIC port with 56GbE port link.
- Since only a single Boot Entry Vector (BEV) per PCI Physical Function is supported, disabling the first port causes the second port to disappear as well.
- 56GbE link is not raised when using 100GbE optic cables.

## **Fixes**

### **Fixes in 2.36.5000:**

- Fixed an issue which caused packet transmission to get stuck when the software tried to send pause frames with dmac equal to one of the device's MAC addresses.
- Fixed an issue which caused a firmware internal error when handling QP alternative context.
- Fixed an issue which caused an internal firmware error when APM changed the QPs port mapping.
- Fixed an issue which caused NVRAM to get stuck when it filled non-valid information in TLV.
- Fixed an issue which caused lack of IB traffic on SR-IOV VPI.
- Fixed a race in handling a duplicated "read request from middle".
- Fixed an issue which caused NVCONFIG to fail when the number of sector was set to 1 and the sector was zeroed.
- Fixed an issue which caused TX traffic to stop when the message MTU size was larger than QP.mtu.
- MLNX\_OEM command GET\_TEMP returned a wrong value in the max\_temp field.
- Fixed a default hardware configuration issue which caused RDP over IPv4 traffic to be dropped.
- Fixed performance issues causing slow performance when running in NO-DRAM-NIC mode.
- Disabled High Rate Steering mode in the INI to enable its compatibility with NC-SI over VLAN.
- Fixed failure instances when initiating FLR in the Physical Function.
- Fixed a wrong returned status in cable info MAD when the cable was not connected.
- Fixed the length calculation of UDP. The incorrect UDP length in the CNP packet caused miss-calculation of the ICRC.
- Fixed a completion error issue when ECN was enabled. The ECN usage caused ordering errors in completion queues (CQ).

## **Enhancements**

### **Firmware for the following devices are updated to 2.36.5000:**

644161-B21  
 644160-B21  
 649282-B21  
 649281-B21  
 649283-B21

**Firmware for the following devices are updated to 2.36.5000:**

764282-B21  
 764283-B21  
 764284-B21

**Firmware for the following devices are updated to 2.36.5000:**

764285-B21  
 764286-B21

**Supported Devices and Features**

**Supported Devices:**

HP Part Number	Device Name	PSID
644161-B21	HP InfiniBand FDR/EN 10/40Gb Dual Port 544M Adapter	HP_0240230019
644160-B21	HP InfiniBand QDR/EN 10Gb Dual Port 544M Adapter	HP_0250230018
649281-B21	HP InfiniBand FDR/EN 10/40Gb Dual Port 544QSFP Adapter	HP_0280210019
649282-B21	HP InfiniBand FDR/EN 10/40Gb Dual Port 544FLR-QSFP Adapter	HP_0230240019 HP_0230220019
649283-B21	HP InfiniBand QDR/EN 10Gb Dual Port 544FLR-QSFP Adapter	HP_0230240009 HP_0230220009
764282-B21	HP InfiniBand QDR/Ethernet 10Gb 2-port 544+M Adapter	HP_1350110023
764283-B21	HP InfiniBand FDR/Ethernet 10Gb/40Gb 2-port 544+M Adapter	HP_1360110017
764284-B21	HP InfiniBand FDR/Ethernet 10Gb/40Gb 2-port 544+QSFP Adapter	HP_1370110017
764285-B21	HP InfiniBand FDR/Ethernet 10Gb/40Gb 2-port 544+FLR-QSFP Adapter	HP_1380110017
764286-B21	HP InfiniBand QDR/Ethernet 10Gb 2-port 544+FLR-QSFP Adapter	HP_1390110023
SL4540 & SL4545 LOM	HP Infiniband QDR/Ethernet 10Gb 2P 544i Adapter	HP_0280110018
778509-B21	HP Infiniband FDR/Ethernet 10Gb/40Gb 2-port 544+A8L Adapter	HP_2010110021

## **Important Note!**

### **Known Issues:**

- Downgrading from v2.30.8000 or later to an earlier version than 2.30.8000 requires server reboot.  
**Workaround:** Reboot the server.
- On ConnectX-3 Ethernet adapter cards, there is a mismatch between the GUID value returned by firmware management cards tools and that returned by fabric/driver utilities that read the GUID via device firmware (e.g., using `ibstat`). Mlxburn/flint return 0xffff as GUID while the utilities return a value derived from the MAC address. For all driver/firmware/software purposes, the latter value should be used.  
**Workaround:** Use the GUID value returned by the fabric/driver utilities (not 0xffff).
- SBR should be asserted for a minimum of 50 milliseconds for the ConnectX®-3 adapters.
- On Pilot1 SL230, PCIe link occasionally does not come up at Gen3 speed.
- RH6.3 Inbox driver causes kernel panic when SR-IOV is enabled on VPI cards due to driver compatibility issue.
- In advanced steering mode, side band management connectivity may be lost when having more than 8 QP per mcg.
- When SR-IOV is disabled in the system BIOS, a PCI issue is noticed in Ubuntu v12.04.3 with Linux kernel v3.8 which affects NICs of several manufacturers including Mellanox's, preventing them from operating.  
**Workaround:** Enable SR-IOV in the BIOS.
- PCIe Gen2 link unstable at temperature sweep of 10C/min for MT27518A1 FDIR-BV.
- When working in VPI mode with port1 FDR and port2 40G, error counters misbehave and increase rapidly.
- MFT tools might leave the flash semaphore locked if the tool operation is forced stopped. The locked semaphore prevents the firmware from accessing the flash and causes firmware hang..  
**Workaround:** Clear the semaphore using MFT command: `flint -clear_semaphore`
- Cable Info MAD reports a wrong cable info when using the MC2210411-SR4 module.
- Driver restart required when switching from InfiniBand FDR link with LLR enabled to InfiniBand link w/o LLR (for example: between SwitchX® and GD4036).
- Bloom filter is currently not supported.
- When downgrading from firmware v2.11.0000 and using MFT 3.0.0-3, Release the following message is displayed due to the `mlxconfig` tool:  
DMFS steering mode with IB in Linux You are trying to override configurable FW by non-configurable FW. If you continue, old FW configurations will be cleared, do you want to continue ? (y/n) [n] : y  
You are trying to restore default configuration, do you want to continue ? (y/n) [n] :y
- DMFS should not be enabled when working with InfiniBand on MLNX\_OFED-2.0.3.  
**Workaround:** Upgrade to MLNX\_OFED-2.1-x.x.x. or later.
- VPD read-only fields are writable.  
**Workaround:** Do not write to read- only fields if you wish to preserve them.
- Setting the device to 128Byte CQ/EQ stride will cause misbehavior of sideband management resulting in communication loss.
- CQ and EQ cannot be configured to different stride sizes.
- ConnectX-3 Pro VF device ID is presented the same as ConnectX-3 VF device ID due to driver limitations.  
**Workaround:** Use the physical function device ID to identify the device.
- Changing port protocol from ETH to IB on port with NCSI/IPMI enabled while the port is connected to ETH switch is not supported.  
**Workaround:**
  - Unplug the cable from the switch
  - Restart driver
  - Change the protocol via the appropriate tools.
- RDP over IPv6 is currently not functional.  
**Workaround:** Set the default RoCE mode in the software to RoCE v2 (also when not using RoCE).
- Sniffer QP cannot be removed from the regular rule after adding the QP with insertion scheme equals to "push to that rule".
- The NIC does not notify the driver of a link-down incident when a cable is unplugged from a NIC port with 56GbE port link.
- Since only a single Boot Entry Vector (BEV) per PCI Physical Function is supported, disabling the first port causes the second port to disappear as well.
- 56GbE link is not raised when using 100GbE optic cables.



## **Fixes**

### **Fixes in 2.36.5000:**

- Fixed an issue which caused packet transmission to get stuck when the software tried to send pause frames with dmac equal to one of the device's MAC addresses.
- Fixed an issue which caused a firmware internal error when handling QP alternative context.
- Fixed an issue which caused an internal firmware error when APM changed the QPs port mapping.
- Fixed an issue which caused NVRAM to get stuck when it filled non-valid information in TLV.
- Fixed an issue which caused lack of IB traffic on SR-IOV VPI.
- Fixed a race in handling a duplicated "read request from middle".
- Fixed an issue which caused NVCONFIG to fail when the number of sector was set to 1 and the sector was zeroed.
- Fixed an issue which caused TX traffic to stop when the message MTU size was larger than QP.mtu.
- MLNX\_OEM command GET\_TEMP returned a wrong value in the max\_temp field.
- Fixed a default hardware configuration issue which caused RDP over IPv4 traffic to be dropped.
- Fixed performance issues causing slow performance when running in NO-DRAM-NIC mode.
- Disabled High Rate Steering mode in the INI to enable its compatibility with NC-SI over VLAN.
- Fixed failure instances when initiating FLR in the Physical Function.
- Fixed a wrong returned status in cable info MAD when the cable was not connected.
- Fixed the length calculation of UDP. The incorrect UDP length in the CNP packet caused miss-calculation of the ICRC.
- Fixed a completion error issue when ECN was enabled. The ECN usage caused ordering errors in completion queues (CQ).

## **Enhancements**

### **Firmware for the following devices are updated to 2.36.5000:**

644161-B21  
644160-B21  
649282-B21  
649281-B21  
649283-B21

### **Firmware for the following devices are updated to 2.36.5000:**

764282-B21  
764283-B21  
764284-B21

### **Firmware for the following devices are updated to 2.36.5000:**

764285-B21  
764286-B21

## **Supported Devices and Features**

### **Supported Devices:**

HP Part Number	Device Name	PSID
644161-B21	HP InfiniBand FDR/EN 10/40Gb Dual Port 544M Adapter	HP_0240230019
644160-B21	HP InfiniBand QDR/EN 10Gb Dual Port 544M Adapter	HP_0250230018
649281-B21	HP InfiniBand FDR/EN 10/40Gb Dual Port 544QSFP Adapter	HP_0280210019
649282-B21	HP InfiniBand FDR/EN 10/40Gb Dual Port 544FLR-QSFP Adapter	HP_0230240019 HP_0230220019
649283-B21	HP InfiniBand QDR/EN 10Gb Dual Port 544FLR-QSFP Adapter	HP_0230240009 HP_0230220009
764282-B21	HP InfiniBand QDR/Ethernet 10Gb 2-port 544+M Adapter	HP_1350110023
764283-B21	HP InfiniBand FDR/Ethernet 10Gb/40Gb 2-port 544+M Adapter	HP_1360110017
764284-B21	HP InfiniBand FDR/Ethernet 10Gb/40Gb 2-port 544+QSFP Adapter	HP_1370110017
764285-B21	HP InfiniBand FDR/Ethernet 10Gb/40Gb 2-port 544+FLR-QSFP Adapter	HP_1380110017
764286-B21	HP InfiniBand QDR/Ethernet 10Gb 2-port 544+FLR-QSFP Adapter	HP_1390110023
SL4540 and SL4545 LOM	HP Infiniband QDR/Ethernet 10Gb 2P 544i Adapter	HP_0280110018

## Firmware - SAS Storage Disk

[Top](#)

Online ROM Flash Component for VMware ESXi - DG0146FARVU, DG0300FARVV, DG0146BAMYQ, DG0300BAMYR, EG0146FAWJC, and EG0300FAWJD Drives

Version: HPDG (F) **(Critical)**

Filename: CPO29329.zip

### **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**
- **Customers who already installed firmware version HPDG do not need to update to HPDG (F).**

### **Fixes**

#### **Problems Fixed:**

- This firmware corrects a possible condition in which stale data might be written to the disk. This results in unexpected data being returned in subsequent requests. This data issue has been duplicated in laboratory firmware stress tests.

#### **Problems Fixed for HPDG (F):**

- Component would fail to install drive firmware for drives present in a system configured with two or more external drive enclosures attached to an HP Host Bus Adapter H22x. The following message would be reported in the component log file - "Device appears more

than once in tree". The drive firmware installation failure was not observed in configurations having only one external drive enclosure attached to an HP Host Bus Adapter H22x.

## **Enhancements**

### **Enhancements/New Features:**

- Added support for VMware vSphere 5.5.
- Added support for UEFI (Universal Extensible Firmware Interface) based servers.

### **Enhancements/New Features for HPDG (D):**

- Updated the flash engine to standardize logging across all SAS drive components.
- Enhanced logging capability to improve the details provided in the component log file.

### **Enhancements/New Features for HPDG (E):**

- VMware Firmware Smart component packaging has changed from a \*.scexe package to a \*.zip package, which contains an executable binary that provides enhanced security during installation. The functionality of the VMware Smart Component has not changed.

---

Online ROM Flash Component for VMware ESXi - EG0300FBLSE, EG0450FBLSF, EG0600FBLSH, and EG0900FBLSK drives

Version: HPD8 (C) **(Recommended)**

Filename: CPO29335.zip

## **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**
- **Customers who already installed firmware version HPD8 do not need to update to HPD8 (C).**

## **Fixes**

### **Problems Fixed:**

- HP ProLiant servers would power down due a hard drive overtemp condition that was falsely reported. Hard disk drive firmware HPD8 resolves this issue.

### **Problems Fixed for HPD8 (C):**

- Component would fail to install drive firmware for drives present in a system configured with two or more external drive enclosures attached to an HP Host Bus Adapter H22x. The following message would be reported in the component log file - "Device appears more than once in tree". The drive firmware installation failure was not observed in configurations having only one external drive enclosure attached to an HP Host Bus Adapter H22x.

## **Enhancements**

### **Enhancements/New Features for HPD8 (B):**

- VMware Firmware Smart component packaging has changed from a \*.scexe package to a \*.zip package, which contains an executable binary that provides enhanced security during installation. The functionality of the VMware Smart Component has not changed.

---

Online ROM Flash Component for VMware ESXi - EG0600JETKA, EG0900JETKB, and EG1200JETKC Drives

Version: HPD4 **(Recommended)**

Filename: CPO30786.zip

### **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**

### **Enhancements**

#### **Enhancements/New Features:**

- Reliability enhancement for applications that write data to a narrow range of tracks.

---

Online ROM Flash Component for VMware ESXi - EH0146FBQDC and EH0300FBQDD drives

Version: HPD5 (B) **(Recommended)**

Filename: CPO29346.zip

### **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**
- **Customers who already installed firmware version HPD5 do not need to update to HPD5 (B).**

### **Fixes**

#### **Problems Fixed:**

- HP ProLiant servers would power down due a hard drive overtemp condition that was falsely reported. Hard disk drive firmware HPD5 resolves this issue.

#### **Problems Fixed for HPD5 (B):**

- Component would fail to install drive firmware for drives present in a system configured with two or more external drive enclosures attached to an HP Host Bus Adapter H22x. The following message would be reported in the component log file - "Device appears more than once in tree". The drive firmware installation failure was not observed in configurations having only one external drive enclosure attached to an HP Host Bus Adapter H22x.

---

Online ROM Flash Component for VMware ESXi - EH0600JDYTN Drive

Version: HPD5 (B) **(Recommended)**

Filename: CPO29350.zip

### **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**
- **Customers who already installed firmware version HPD5 do not need to update to HPD5 (B).**

## **Fixes**

### **Problems Fixed:**

- Self-initiated reset during ATI (Adjacent Track Interference) mitigation issue, where the drive reported a 06/29/04 (Self-Initiated Reset) to the controller. Then the controller would re-establish link with the drive and resend the command.
- Servo miscalculations that resulted in degraded drive performance.

### **Problems Fixed for HPD5 (B):**

- Component would fail to install drive firmware for drives present in a system configured with two or more external drive enclosures attached to an HP Host Bus Adapter H22x. The following message would be reported in the component log file - "Device appears more than once in tree". The drive firmware installation failure was not observed in configurations having only one external drive enclosure attached to an HP Host Bus Adapter H22x.

---

Online ROM Flash Component for VMware ESXi - MB1000FAMYU and MB2000FAMYV Drives

Version: HPD7 (F) **(Critical)**

Filename: CP029354.zip

## **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**
- **Customers who already installed firmware version HPD7 do not need to update to HPD7 (F).**

## **Fixes**

### **Problem Fixed:**

- This firmware prevents a rare condition that may occur during a WRITE SAME command sequence that may result in incorrect data being written to the hard drive. The WRITE SAME command may be used during RAID ARRAY parity initialization.

### **Problems Fixed for HPD7 (F):**

- Component would fail to install drive firmware for drives present in a system configured with two or more external drive enclosures attached to an HP Host Bus Adapter H22x. The following message would be reported in the component log file - "Device appears more than once in tree". The drive firmware installation failure was not observed in configurations having only one external drive enclosure attached to an HP Host Bus Adapter H22x.

## **Enhancements**

### **Enhancements/New Features:**

- Added support for VMware vSphere 5.5.
- Added support for UEFI (Universal Extensible Firmware Interface) based servers.

#### **Enhancements/New Features for HPD7 (D):**

- Updated the flash engine to standardize logging across all SAS drive components.
- Enhanced logging capability to improve the details provided in the component log file.

#### **Enhancements/New Features for HPD7 (E):**

- VMware Firmware Smart component packaging has changed from a \*.scexe package to a \*.zip package, which contains an executable binary that provides enhanced security during installation. The functionality of the VMware Smart Component has not changed.

---

Online ROM Flash Component for VMware ESXi - MB4000JEQNL and MB6000JEQNN Drives

Version: HPD7 (B) **(Critical)**

Filename: CP029372.zip

#### **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**
- **Customers who already installed firmware version HPD7 do not need to update to HPD7 (B).**

#### **Fixes**

##### **Problems Fixed:**

- This firmware fixes a potential incorrect data issue in write-cached enabled multi-initiator unaligned write environments, where reservation commands are used.

##### **Problems Fixed for HPD7 (B):**

- Component would fail to install drive firmware for drives present in a system configured with two or more external drive enclosures attached to an HP Host Bus Adapter H22x. The following message would be reported in the component log file - "Device appears more than once in tree". The drive firmware installation failure was not observed in configurations having only one external drive enclosure attached to an HP Host Bus Adapter H22x.

---

Online ROM Flash Component for VMware ESXi - MM0500FBFVQ and MM1000FBFVR Drives

Version: HPD9 (B) **(Recommended)**

Filename: CP029378.zip

#### **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**
- **Customers who already installed firmware version HPD9 do not need to update to HPD9 (B).**

## **Fixes**

### **Problems Fixed:**

- HPD9 firmware prevents a condition in which data fails to be committed to disk after the host issues a hard reset in a lab stress test environment with write cache enabled.

### **Problems Fixed for HPD9 (B):**

- Component would fail to install drive firmware for drives present in a system configured with two or more external drive enclosures attached to an HP Host Bus Adapter H22x. The following message would be reported in the component log file - "Device appears more than once in tree". The drive firmware installation failure was not observed in configurations having only one external drive enclosure attached to an HP Host Bus Adapter H22x.

---

Online ROM Flash Component for VMware ESXi - MM1000FECVH Drives

Version: HPD2 (B) **(Recommended)**

Filename: CPO29380.zip

## **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**
- **Customers who already installed firmware version HPD2 do not need to update to HPD2 (B).**

## **Fixes**

### **Problems Fixed:**

- Drive self-test did not complete within the specified time.
- During a fully cached workload, SMART would report incorrect temperature values.

### **Problems Fixed for HPD2 (B):**

- Component would fail to install drive firmware for drives present in a system configured with two or more external drive enclosures attached to an HP Host Bus Adapter H22x. The following message would be reported in the component log file - "Device appears more than once in tree". The drive firmware installation failure was not observed in configurations having only one external drive enclosure attached to an HP Host Bus Adapter H22x.

## **Enhancements**

### **Enhancements/New Features:**

- Added servo improvements which reduce power consumption.

---

Online ROM Flash Component for VMware ESXi - MM1000JEFRB and MM2000JEFRC Drives

Version: HPD4 (B) **(Recommended)**

Filename: CPO29382.zip

## **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**
- **Customers who already installed firmware version HPD4 do not need to update to HPD4 (B).**

## **Fixes**

### **Problems Fixed:**

- Version HPD4 prevents the potential for incorrect data to be written to the drive under extremely rare circumstances when the drive experiences a hard reset. This issue has only been observed in a rigorous test environment and has NOT been reported in a customer production environment.

### **Problems Fixed for HPD4 (B):**

- Component would fail to install drive firmware for drives present in a system configured with two or more external drive enclosures attached to an HP Host Bus Adapter H22x. The following message would be reported in the component log file - "Device appears more than once in tree". The drive firmware installation failure was not observed in configurations having only one external drive enclosure attached to an HP Host Bus Adapter H22x.

---

Online ROM Flash Component for VMware ESXi - MM1000JFJTH Drives

Version: HPD1 **(Recommended)**

Filename: CPO30809.zip

## **Important Note!**

- **Online firmware flashing of drives attached to an HP Smart Array controller running in Zero Memory (ZM) mode or an HP ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux and Microsoft Windows environments. All other OSes would require an offline update using the SPP and HP SUM.**

## **Fixes**

### **Problems Fixed:**

- This firmware improves HDD reliability when HDDs are exposed to long periods of host inactivity that exceed 1 second. HDDs may become unresponsive when using HDD firmware prior to version HPD1. This firmware also contains a change which prevents an incorrect reassign status of a repaired sector from being logged.

---

Online ROM Flash Component for VMware ESXi - DH0072FAQRD, DH0146FAQRE, EH0146FAWJB, and EH0072FAWJA Drives

Version: HPDK (B) **(Recommended)**

Filename: CPO29330.zip

## **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these**



**configurations.**

- o **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSES would require an offline update using the SPP and HP SUM.**
- o **Customers who already installed firmware version HPDK do not need to update to HPDK (B).**

## **Fixes**

### **Problems Fixed:**

- o HP ProLiant servers would power down due a hard drive overtemp condition that was falsely reported. Hard disk drive firmware HPDK resolves this issue.

### **Problems Fixed for HPDK (B):**

- o Component would fail to install drive firmware for drives present in a system configured with two or more external drive enclosures attached to an HP Host Bus Adapter H22x. The following message would be reported in the component log file - "Device appears more than once in tree". The drive firmware installation failure was not observed in configurations having only one external drive enclosure attached to an HP Host Bus Adapter H22x.

---

Online ROM Flash Component for VMware ESXi - EF0300FARMU, EF0450FARMV, EF0600FARNA Drives

Version: HPD9 **(Recommended)**

Filename: CPO30803.zip

## **Important Note!**

- **Online firmware flashing of drives attached to an HP Smart Array controller running in Zero Memory (ZM) mode or an HP ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux and Microsoft Windows environments. All other OSES would require an offline update using the SPP and HP SUM.**

## **Fixes**

### **Problems Fixed:**

- This firmware contains a change which prevents an incorrect reassign status of a repaired sector from being logged.

---

Online ROM Flash Component for VMware ESXi - EF0300FATFD, EF0450FATFE, and EF0600FATFF Drives

Version: HPDB (F) **(Critical)**

Filename: CPO29332.zip

## **Important Note!**

- o **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- o **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSES would require an offline update using the SPP and HP SUM.**
- o **Customers who already installed firmware version HPDB do not need to update to HPDB (F).**

## **Fixes**

### Problems Fixed:

- This firmware corrects a possible condition in which stale data might be written to the disk. This results in unexpected data being returned in subsequent requests. This data issue has been duplicated in laboratory firmware stress tests.

### Problems Fixed for HPDB (F):

- Component would fail to install drive firmware for drives present in a system configured with two or more external drive enclosures attached to an HP Host Bus Adapter H22x. The following message would be reported in the component log file - "Device appears more than once in tree". The drive firmware installation failure was not observed in configurations having only one external drive enclosure attached to an HP Host Bus Adapter H22x.

## Enhancements

### Enhancements/New Features:

- Added support for VMware vSphere 5.5.
- Added support for UEFI (Universal Extensible Firmware Interface) based servers.

### Enhancements/New Features for HPDB (D):

- Updated the flash engine to standardize logging across all SAS drive components.
- Enhanced logging capability to improve the details provided in the component log file.

### Enhancements/New Features for HPDB (E):

- VMware Firmware Smart component packaging has changed from a \*.scexe package to a \*.zip package, which contains an executable binary that provides enhanced security during installation. The functionality of the VMware Smart Component has not changed.

---

Online ROM Flash Component for VMware ESXi - EG0300FBDBR, EG0450FBDBT and EG0600FBDBU Drives

Version: HPDA (G) **(Critical)**

Filename: CPO29333.zip

### Important Note!

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**
- **Customers who already installed firmware version HPDA do not need to update to HPDA (G).**

## Fixes

### Firmware Dependency:

- **Minimum firmware required - HPD7. HPDA drive firmware will fail when downgrading to versions below HPD7.**

### Problems Fixed:

- This firmware corrects a possible condition in which stale data might be written to the disk. This results in unexpected data being returned in subsequent requests. This data issue has been duplicated in laboratory firmware stress tests.

### Problems Fixed for HPDA (G):

- Component would fail to install drive firmware for drives present in a system configured with two or more external drive enclosures attached to an HP Host Bus Adapter H22x. The following message would be reported in the component log file - "Device appears more than once in tree". The drive firmware installation failure was not observed in configurations having only one external drive enclosure attached to an HP Host Bus Adapter H22x.

## **Enhancements**

### **Enhancements/New Features:**

- Added support for VMware vSphere 5.5.
- Added support for UEFI (Universal Extensible Firmware Interface) based servers.

### **Enhancements/New Features for HPDA (E):**

- Updated the flash engine to standardize logging across all SAS drive components.
- Enhanced logging capability to improve the details provided in the component log file.

### **Enhancements/New Features for HPDA (F):**

- VMware Firmware Smart component packaging has changed from a \*.scexe package to a \*.zip package, which contains an executable binary that provides enhanced security during installation. The functionality of the VMware Smart Component has not changed.

---

Online ROM Flash Component for VMware ESXi - EG0300FBDSP, EG0450FBDSQ, and EG0600FBDSR drives

Version: HPD6 (F) **(Optional)**

Filename: CPO29334.zip

## **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**
- **Customers who already installed firmware version HPD6 do not need to update to HPD6 (F).**

## **Fixes**

### **Problems Fixed:**

- This firmware reduces the possibility of the controller and drive not properly negotiating link signaling, resulting in the controller not being able to identify a drive attached to a particular port/slot during system boot up. This firmware improves signal quality between the drive and the controller.

### **Problems Fixed for HPD6 (F):**

- Component would fail to install drive firmware for drives present in a system configured with two or more external drive enclosures attached to an HP Host Bus Adapter H22x. The following message would be reported in the component log file - "Device appears more than once in tree". The drive firmware installation failure was not observed in configurations having only one external drive enclosure attached to an HP Host Bus Adapter H22x.

## **Enhancements**

### **Enhancements/New Features:**

- Added support for VMware vSphere 5.5.
- Added support for UEFI (Universal Extensible Firmware Interface) based servers.

#### **Enhancements/New Features for HPD6 (D):**

- Updated the flash engine to standardize logging across all SAS drive components.
- Enhanced logging capability to improve the details provided in the component log file.

#### **Enhancements/New Features for HPD6 (E):**

- VMware Firmware Smart component packaging has changed from a \*.scexe package to a \*.zip package, which contains an executable binary that provides enhanced security during installation. The functionality of the VMware Smart Component has not changed.

---

Online ROM Flash Component for VMware ESXi - EG0300FBVFL, EG0450FBVFM, EG0600FBVFP, and EG0900FBVFQ Drives

Version: HPDE (B) **(Recommended)**

Filename: CPO29336.zip

#### **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**
- **Customers who already installed firmware version HPDE do not need to update to HPDE (B).**

#### **Fixes**

##### **Problems Fixed:**

- Drive self-test did not complete within the specified time.
- During a fully cached workload, SMART would report incorrect temperature values.

##### **Problems Fixed for HPDE (B):**

- Component would fail to install drive firmware for drives present in a system configured with two or more external drive enclosures attached to an HP Host Bus Adapter H22x. The following message would be reported in the component log file - "Device appears more than once in tree". The drive firmware installation failure was not observed in configurations having only one external drive enclosure attached to an HP Host Bus Adapter H22x.

#### **Enhancements**

##### **Enhancements/New Features:**

- Added servo improvements which reduce power consumption.

---

Online ROM Flash Component for VMware ESXi - EG0300FCHHR, EG0450FCHHT, EG0600FCHHU, and EG0900FCHHV Drives

Version: HPD8 (B) **(Recommended)**

Filename: CPO29337.zip

#### **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE**

**ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**

- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**
- **Customers who already installed firmware version HPD8 do not need to update to HPD8 (B).**

## **Fixes**

### **Problems Fixed:**

- A potential issue existed where the drive would become unresponsive if the host sent a high number of overlapping task management commands. The drive would require a power cycle to be recovered.

### **Problems Fixed for HPD8 (B):**

- Component would fail to install drive firmware for drives present in a system configured with two or more external drive enclosures attached to an HP Host Bus Adapter H22x. The following message would be reported in the component log file - "Device appears more than once in tree". The drive firmware installation failure was not observed in configurations having only one external drive enclosure attached to an HP Host Bus Adapter H22x.

## **Enhancements**

### **Enhancements/New Features:**

- Improved write protection robustness before drive spin down.
- Implemented minor performance improvements in RAID environments.

---

Online ROM Flash Component for VMware ESXi - EG0300FCVBF, EG0450FCVBH, EG0600FCVBK, and EG0900FCVBL Drives

Version: HPD9 (B) **(Recommended)**

Filename: CPO29338.zip

## **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**
- **Customers who already installed firmware version HPD9 do not need to update to HPD9 (B).**

## **Fixes**

### **Problems Fixed:**

- Drives could become unresponsive due to unexpected responses from the serial port diagnostic debug connection.

### **Problems Fixed for HPD9 (B):**

- Component would fail to install drive firmware for drives present in a system configured with two or more external drive enclosures attached to an HP Host Bus Adapter H22x. The following message would be reported in the component log file - "Device appears more than once in tree". The drive firmware installation failure was not observed in configurations having only one external drive enclosure attached to an HP Host Bus Adapter H22x.

---

Online ROM Flash Component for VMware ESXi - EG0300JEHLV, EG0600JEHMA, EG0900JEHMB, and EG1200JEHMC Drives

Version: HPD3 (B) **(Recommended)**

Filename: CPO29339.zip

### **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**
- **Customers who already installed firmware version HPD3 do not need to update to HPD3 (B).**

### **Fixes**

#### **Problems Fixed:**

- Self-initiated reset during ATI (Adjacent Track Interference) mitigation issue, where the drive reported a 06/29/04 (Self-Initiated Reset) to the controller. Then the controller would re-establish link with the drive and resend the command.
- Servo miscalculations that resulted in degraded drive performance.

#### **Problems Fixed for HPD3 (B):**

- Component would fail to install drive firmware for drives present in a system configured with two or more external drive enclosures attached to an HP Host Bus Adapter H22x. The following message would be reported in the component log file - "Device appears more than once in tree". The drive firmware installation failure was not observed in configurations having only one external drive enclosure attached to an HP Host Bus Adapter H22x.

---

Online ROM Flash Component for VMware ESXi - EG0300JFCKA, EG0600JEMCV, EG0900JFCKB, and EG1200JEMDA Drives

Version: HPD4 (B) **(Recommended)**

Filename: CPO29340.zip

### **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**
- **Customers who already installed firmware version HPD4 do not need to update to HPD4 (B).**

### **Fixes**

#### **Problems Fixed:**

- The expected time to completion of Sanitize, Format and DST operations was incorrectly reported in the Vital Products Data page D0h. If time to completion is used by an application to determine when to terminate an operation, the operation might be terminated before the operation completed. Firmware version HPD4 now correctly reports the expected time to completion for these operations.

#### **Problems Fixed for HPD4 (B):**

- Component would fail to install drive firmware for drives present in a system configured with two or more external drive enclosures

attached to an HP Host Bus Adapter H22x. The following message would be reported in the component log file - "Device appears more than once in tree". The drive firmware installation failure was not observed in configurations having only one external drive enclosure attached to an HP Host Bus Adapter H22x.

---

Online ROM Flash Component for VMware ESXi - EG0900FDJYR and EG1200FDJYT Drives

Version: HPD4 (B) **(Recommended)**

Filename: CPO29341.zip

### **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**
- **Customers who already installed firmware version HPD4 do not need to update to HPD4 (B).**

### **Fixes**

#### **Problems Fixed:**

- Prevents the potential for incorrect data from being "read from" or "written to" the drive under extremely rare circumstances where the drive experiences consecutive error recoveries during a background scan and the Error Correction Code (ECC) fails. This issue has only been observed in a rigorous test environment and has NOT been reported in a customer production environment.

#### **Problems Fixed for HPD4 (B):**

- Component would fail to install drive firmware for drives present in a system configured with two or more external drive enclosures attached to an HP Host Bus Adapter H22x. The following message would be reported in the component log file - "Device appears more than once in tree". The drive firmware installation failure was not observed in configurations having only one external drive enclosure attached to an HP Host Bus Adapter H22x.

---

Online ROM Flash Component for VMware ESXi - EG1200FDNJT and EG1200FCVBQ Drives

Version: HPD8 (B) **(Recommended)**

Filename: CPO29342.zip

### **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**
- **Customers who already installed firmware version HPD8 do not need to update to HPD8 (B).**

### **Fixes**

#### **Problems Fixed:**

- Drive self-test did not complete within the specified time.
- During a fully cached workload, SMART would report incorrect temperature values.

### Problems Fixed for HPD8 (B):

- Component would fail to install drive firmware for drives present in a system configured with two or more external drive enclosures attached to an HP Host Bus Adapter H22x. The following message would be reported in the component log file - "Device appears more than once in tree". The drive firmware installation failure was not observed in configurations having only one external drive enclosure attached to an HP Host Bus Adapter H22x.

### Enhancements

#### Enhancements/New Features:

- Added servo improvements which reduce power consumption.

---

Online ROM Flash Component for VMware ESXi - EG1800JEHMD Drive

Version: HPD4 (B) **(Recommended)**

Filename: CPO29343.zip

### Important Note!

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**
- **Customers who already installed firmware version HPD4 do not need to update to HPD4 (B).**

### Fixes

#### Problems Fixed:

- Self-initiated reset during ATI (Adjacent Track Interference) mitigation issue, where the drive reported a 06/29/04 (Self-Initiated Reset) to the controller. Then the controller would re-establish link with the drive and resend the command.
- Servo miscalculations that resulted in degraded drive performance.

### Problems Fixed for HPD4 (B):

- Component would fail to install drive firmware for drives present in a system configured with two or more external drive enclosures attached to an HP Host Bus Adapter H22x. The following message would be reported in the component log file - "Device appears more than once in tree". The drive firmware installation failure was not observed in configurations having only one external drive enclosure attached to an HP Host Bus Adapter H22x.

---

Online ROM Flash Component for VMware ESXi - EG1800JEMDB Drives

Version: HPD2 **(Recommended)**

Filename: CPO30028.zip

### Important Note!

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**



## Fixes

### **Problems Fixed:**

- This firmware improves HDD reliability when HDDs are exposed to long periods of host inactivity that exceed 1 second. HDDs may become unresponsive when using HDD firmware prior to version HPD2. This firmware also contains a change which prevents an incorrect reassign status of a repaired sector from being logged.

---

Online ROM Flash Component for VMware ESXi - EH0072FARUA and EH0146FARUB drives

Version: HPD9 (F) **(Optional)**

Filename: CPO29344.zip

### **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**
- **Customers who already installed firmware version HPD9 do not need to update to HPD9 (F).**

## Fixes

### **Problems Fixed:**

- This firmware reduces the possibility of the controller and drive not properly negotiating link signaling, resulting in the controller not being able to identify a drive attached to a particular port/slot during system boot up. This firmware improves signal quality between the drive and the controller.

### **Problems Fixed for HPD9 (F):**

- Component would fail to install drive firmware for drives present in a system configured with two or more external drive enclosures attached to an HP Host Bus Adapter H22x. The following message would be reported in the component log file - "Device appears more than once in tree". The drive firmware installation failure was not observed in configurations having only one external drive enclosure attached to an HP Host Bus Adapter H22x.

## Enhancements

### **Enhancements/New Features:**

- Added support for VMware vSphere 5.5.
- Added support for UEFI (Universal Extensible Firmware Interface) based servers.

### **Enhancements/New Features for HPD9 (D):**

- Updated the flash engine to standardize logging across all SAS drive components.
- Enhanced logging capability to improve the details provided in the component log file.

### **Enhancements/New Features for HPD9 (E):**

- VMware Firmware Smart component packaging has changed from a \*.scexe package to a \*.zip package, which contains an executable binary that provides enhanced security during installation. The functionality of the VMware Smart Component has not changed.

---

Online ROM Flash Component for VMware ESXi - EH0072FARWC and EH0146FARWD Drives

Version: HPDD (F) **(Critical)**

Filename: CPO29345.zip

### **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSES would require an offline update using the SPP and HP SUM.**
- **Customers who already installed firmware version HPDD do not need to update to HPDD (F).**

### **Fixes**

#### **Problems Fixed:**

- This firmware corrects a possible condition in which stale data might be written to the disk. This results in unexpected data being returned in subsequent requests. This data issue has been duplicated in laboratory firmware stress tests.

#### **Problems Fixed for HPDD (F):**

- Component would fail to install drive firmware for drives present in a system configured with two or more external drive enclosures attached to an HP Host Bus Adapter H22x. The following message would be reported in the component log file - "Device appears more than once in tree". The drive firmware installation failure was not observed in configurations having only one external drive enclosure attached to an HP Host Bus Adapter H22x.

### **Enhancements**

#### **Enhancements/New Features:**

- Added support for VMware vSphere 5.5.
- Added support for UEFI (Universal Extensible Firmware Interface) based servers.

#### **Enhancements/New Features for HPDD (D):**

- Updated the flash engine to standardize logging across all SAS drive components.
- Enhanced logging capability to improve the details provided in the component log file.

#### **Enhancements/New Features for HPDD (E):**

- VMware Firmware Smart component packaging has changed from a \*.scexe package to a \*.zip package, which contains an executable binary that provides enhanced security during installation. The functionality of the VMware Smart Component has not changed.

---

Online ROM Flash Component for VMware ESXi - EH0146FCBVB and EH0300FCBVC drives

Version: HPD8 **(Recommended)**

Filename: CPO30798.zip

### **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these**

configurations.

- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**

## **Fixes**

### **Problems Fixed:**

- Reliability enhancement for applications that write data to a narrow range of tracks.
- New SMART trip when device senses an abnormal change in the motor electric current.

---

Online ROM Flash Component for VMware ESXi - EH0300JDXBA, EH0450JDXBB, and EH0600JDXBC Drives

Version: HPD3 **(Recommended)**

Filename: CP029792.zip

## **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**

## **Enhancements**

### **Enhancements/New Features:**

- Reliability enhancement for applications that write data to a narrow range of tracks.

---

Online ROM Flash Component for VMware ESXi - EH0300JDYTH, EH0450JDYTK, and EH0600JDYTL Drives

Version: HPD4 (B) **(Recommended)**

Filename: CP029348.zip

## **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**
- **Customers who already installed firmware version HPD4 do not need to update to HPD4 (B).**

## **Fixes**

### **Problems Fixed:**

- Self-initiated reset during ATI (Adjacent Track Interference) mitigation issue, where the drive reported a 06/29/04 (Self-Initiated Reset) to the controller. Then the controller would re-establish link with the drive and resend the command.
- Servo miscalculations that resulted in degraded drive performance.

### **Problems Fixed for HPD4 (B):**

- Component would fail to install drive firmware for drives present in a system configured with two or more external drive enclosures attached to an HP Host Bus Adapter H22x. The following message would be reported in the component log file - "Device appears more than once in tree". The drive firmware installation failure was not observed in configurations having only one external drive enclosure attached to an HP Host Bus Adapter H22x.

---

Online ROM Flash Component for VMware ESXi - EH0300JEDHC, EH0450JEDHD, and EH0600JEDHE Drives

Version: HPD4 **(Recommended)**

Filename: CPO29742.zip

#### **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**

#### **Fixes**

##### **Problems Fixed:**

- This firmware improves HDD reliability when HDDs are exposed to long periods of host inactivity that exceed 1 second. HDDs may become unresponsive when using HDD firmware prior to version HPD4. This firmware also contains a change which prevents an incorrect reassign status of a repaired sector from being logged.

---

Online ROM Flash Component for VMware ESXi - EO0200FBRVV, MO0200FBRWB, EO0400FBRWA, MO0400FBRWC, and MO0800FBRWD drives

Version: HPD9 (F) **(Optional)**

Filename: CPO29351.zip

#### **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**
- **Customers who already installed firmware version HPD9 do not need to update to HPD9 (F).**

#### **Fixes**

##### **Problems Fixed:**

- In previous firmware revisions when the solid state drive was issued a Report Support Operation Code (RSOC) command (A3h) and the reporting options field was set to 001, the drive incorrectly responded with 05/24/00 indicating that the RSOC command was not supported. The error was logged in the system log files. The drive should have communicated non-support using the Command Data Parameter (CDP) format. The firmware now complies with the RSOC industry standard specification.

##### **Problems Fixed for HPD9 (F):**

- Component would fail to install drive firmware for drives present in a system configured with two or more external drive enclosures attached to an HP Host Bus Adapter H22x. The following message would be reported in the component log file - "Device appears more

than once in tree". The drive firmware installation failure was not observed in configurations having only one external drive enclosure attached to an HP Host Bus Adapter H22x.

## **Enhancements**

### **Enhancements/New Features:**

- Added support for VMware vSphere 5.5.
- Added support for UEFI (Universal Extensible Firmware Interface) based servers.

### **Enhancements/New Features for HPD9 (D):**

- Updated the flash engine to standardize logging across all SAS drive components.
- Enhanced logging capability to improve the details provided in the component log file.

### **Enhancements/New Features for HPD9 (E):**

- VMware Firmware Smart component packaging has changed from a \*.scexe package to a \*.zip package, which contains an executable binary that provides enhanced security during installation. The functionality of the VMware Smart Component has not changed.

---

Online ROM Flash Component for VMware ESXi - MB1000FBZPL and MB2000FBZPN drives

Version: HPD4 (B) **(Recommended)**

Filename: CPO29355.zip

## **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**
- **Customers who already installed firmware version HPD4 do not need to update to HPD4 (B).**

## **Fixes**

### **Problems Fixed:**

- ProLiant servers would power down due a hard drive over temperature condition that was falsely reported. HPD4 firmware resolves this issue.

### **Problems Fixed for HPD4 (B):**

- Component would fail to install drive firmware for drives present in a system configured with two or more external drive enclosures attached to an HP Host Bus Adapter H22x. The following message would be reported in the component log file - "Device appears more than once in tree". The drive firmware installation failure was not observed in configurations having only one external drive enclosure attached to an HP Host Bus Adapter H22x.

---

Online ROM Flash Component for VMware ESXi - MB1000FCWDE, MB2000FCWDF, MB3000FCWDH, and MB4000FCWDK Drives

Version: HPDA **(Recommended)**

Filename: CPO30186.zip

## **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**

## Fixes

### **Problems Fixed:**

- This firmware improves HDD reliability when HDDs are exposed to long periods of host inactivity that exceed 1 second. HDDs may become unresponsive when using HDD firmware prior to version HPDA.
- This firmware also contains a change which prevents an incorrect reassign status of a repaired sector from being logged.

---

Online ROM Flash Component for VMware ESXi - MB1000FCWPP, MB2000FCVBV, MB3000FCVCA, and MB4000FCVCB Drives

Version: HPD2 (D) **(Recommended)**

Filename: CPO29357.zip

## Important Note!

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**
- **Customers who already installed firmware version HPD2 do not need to update to HPD2 (D).**

## Fixes

### **Problems Fixed:**

- Component would fail to install drive firmware for drives present in a system configured with two or more external drive enclosures attached to an HP Host Bus Adapter H22x. The following message would be reported in the component log file - "Device appears more than once in tree". The drive firmware installation failure was not observed in configurations having only one external drive enclosure attached to an HP Host Bus Adapter H22x.

## Enhancements

### **Enhancements/New Features:**

- This firmware improves reliability by modifying the pivot bearing grease wear leveling algorithm, which if not implemented, could result in an increased drive failure rate for specific usage applications (eg, very long periods of small range seeks).
- Enhancements also include performance improvements.
- Added support for VMware vSphere 5.5.
- Added support for UEFI (Universal Extensible Firmware Interface) based servers.

### **Enhancements/New Features for HPD2 (B):**

- Updated the flash engine to standardize logging across all SAS drive components.
- Enhanced logging capability to improve the details provided in the component log file.

### **Enhancements/New Features for HPD2 (C):**

- VMware Firmware Smart component packaging has changed from a \*.scexe package to a \*.zip package, which contains an executable binary that provides enhanced security during installation. The functionality of the VMware Smart Component has not changed.

---

Online ROM Flash Component for VMware ESXi - MB2000FBUCL and MB3000FBUCN drives

Version: HPDA (E) **(Critical)**

Filename: CPO29362.zip

### **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**
- **Customers who already installed firmware version HPDA do not need to update to HPDA (E).**

### **Fixes**

#### **Problems Fixed:**

- This firmware improves background scans for media robustness, and also corrects a laboratory induced rare condition that could result in the disk not being updated with the latest cache data.

#### **Problems Fixed for HPDA (E):**

- Component would fail to install drive firmware for drives present in a system configured with two or more external drive enclosures attached to an HP Host Bus Adapter H22x. The following message would be reported in the component log file - "Device appears more than once in tree". The drive firmware installation failure was not observed in configurations having only one external drive enclosure attached to an HP Host Bus Adapter H22x.

### **Enhancements**

#### **Enhancements/New Features:**

- Added support for VMware vSphere 5.5.
- Added support for UEFI (Universal Extensible Firmware Interface) based servers.

#### **Enhancements/New Features for HPDA (C):**

- Updated the flash engine to standardize logging across all SAS drive components.
- Enhanced logging capability to improve the details provided in the component log file.

#### **Enhancements/New Features for HPDA (D):**

- VMware Firmware Smart component packaging has changed from a \*.scexe package to a \*.zip package, which contains an executable binary that provides enhanced security during installation. The functionality of the VMware Smart Component has not changed.

---

Online ROM Flash Component for VMware ESXi - MB2000FCQPF and MB3000FBNWV Drives

Version: HPD9 **(Recommended)**

Filename: CPO30829.zip

### **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**

## **Fixes**

### **Problems Fixed:**

- HP ProLiant servers would power down due a hard drive overtemp condition that was falsely reported. Hard disk drive firmware HPD9 resolves this issue.

---

Online ROM Flash Component for VMware ESXi - MB2000FCZGH, MB3000FCZGK, and MB4000FCZGL Drives

Version: HPD7 (B) **(Recommended)**

Filename: CPO29364.zip

## **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**
- **Customers who already installed firmware version HPD7 do not need to update to HPD7 (B).**

## **Fixes**

### **Problems Fixed:**

- This firmware corrects an issue which could result in a failure of the drive to be discovered after power on.

### **Problems Fixed for HPD7 (B):**

- Component would fail to install drive firmware for drives present in a system configured with two or more external drive enclosures attached to an HP Host Bus Adapter H22x. The following message would be reported in the component log file - "Device appears more than once in tree". The drive firmware installation failure was not observed in configurations having only one external drive enclosure attached to an HP Host Bus Adapter H22x.

---

Online ROM Flash Component for VMware ESXi - MB2000JFDSL and MB4000JFDSN Drives

Version: HPD1 **(Recommended)**

Filename: CPO30059.zip

## **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**



## **Enhancements**

### **Enhancements/New Features:**

- Reliability enhancement for applications that write data to a narrow range of tracks.

---

Online ROM Flash Component for VMware ESXi - MB2000JFEPA and MB4000JFEPB Drives

Version: HPD2 **(Recommended)**

Filename: CPO30845.zip

### **Important Note!**

- **Online firmware flashing of drives attached to an HP Smart Array controller running in Zero Memory (ZM) mode or an HP ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**

## **Fixes**

### **Problems Fixed:**

- This firmware improves HDD reliability when HDDs are exposed to long periods of host inactivity that exceed 1 second. HDDs may become unresponsive when using HDD firmware prior to version HPD2. This firmware also contains a change which prevents an incorrect reassign status of a repaired sector from being logged.

---

Online ROM Flash Component for VMware ESXi - MB4000JEFNC and MB6000JEFND Drives

Version: HPD5 **(Critical)**

Filename: CPO29714.zip

### **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**

## **Fixes**

### **Problems Fixed:**

- This firmware improves HDD reliability when HDDs are exposed to long periods of host inactivity that exceed 1 second. HDDs may become unresponsive when using HDD firmware prior to version HPD5. This firmware also contains a change which prevents an incorrect reassign status of a repaired sector from being logged.

---

Online ROM Flash Component for VMware ESXi - MB6000FEDAU Drives

Version: HPD4 (B) **(Recommended)**

Filename: CPO29373.zip

### **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**
- **Customers who already installed firmware version HPD4 do not need to update to HPD4 (B).**

### **Fixes**

#### **Problems Fixed:**

- This firmware corrects an issue which could result in a failure of the drive to be discovered after power on.

#### **Problems Fixed for HPD4 (B):**

- Component would fail to install drive firmware for drives present in a system configured with two or more external drive enclosures attached to an HP Host Bus Adapter H22x. The following message would be reported in the component log file - "Device appears more than once in tree". The drive firmware installation failure was not observed in configurations having only one external drive enclosure attached to an HP Host Bus Adapter H22x.

---

Online ROM Flash Component for VMware ESXi - MM0500FAMYT Drives

Version: HPD6 (F) **(Critical)**

Filename: CP029377.zip

### **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**
- **Customers who already installed firmware version HPD6 do not need to update to HPD6 (F).**

### **Fixes**

#### **Problem Fixed:**

- After long term use of the HDD, a rare condition might occur following a power cycle where the drive heads may land on areas of the disk containing data, which could potentially cause data loss or mechanical damage. Firmware version HPD6 prevents this condition from occurring.
- This firmware prevents a rare condition that may occur during a WRITE SAME command sequence that may result in incorrect data being written to the hard drive. The WRITE SAME command may be used during RAID ARRAY parity initialization.

#### **Problems Fixed for HPD6 (F):**

- Component would fail to install drive firmware for drives present in a system configured with two or more external drive enclosures attached to an HP Host Bus Adapter H22x. The following message would be reported in the component log file - "Device appears more than once in tree". The drive firmware installation failure was not observed in configurations having only one external drive enclosure attached to an HP Host Bus Adapter H22x.

## Enhancements

### Enhancements/New Features:

- Added support for VMware vSphere 5.5.
- Added support for UEFI (Universal Extensible Firmware Interface) based servers.

### Enhancements/New Features for HPD6 (D):

- Updated the flash engine to standardize logging across all SAS drive components.
- Enhanced logging capability to improve the details provided in the component log file.

### Enhancements/New Features for HPD6 (E):

- VMware Firmware Smart component packaging has changed from a \*.scexe package to a \*.zip package, which contains an executable binary that provides enhanced security during installation. The functionality of the VMware Smart Component has not changed.

---

Online ROM Flash Component for VMware ESXi - MO0200FCTRN, MO0400FCTRP, and MO0800FCTRQ drives

Version: HPD5 **(Recommended)**

Filename: CPO29540.zip

### Important Note!

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**

## Fixes

### Problems Fixed:

- An issue was found where the drive responded with a format error if power-cycled multiple times while in the process of un-mapping Logical Block Addresses (LBA). HPD5 firmware adds additional protection during power-cycles to ensure that the drive can recover its LBA to Physical Memory map.

---

Online ROM Flash Component for VMware ESXi - MO0200JDVET, MO0400JDVEU, MO0800JDVEV, EO0200JDVFA, EO0400JDVFB, and EO0800JDVFC Drives

Version: HPD2 (B) **(Optional)**

Filename: CPO29385.zip

### Important Note!

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**
- **Customers who already installed firmware version HPD2 do not need to update to HPD2 (B).**

## Fixes

### Problems Fixed:

- Solid-state drives (SSD) running firmware versions prior to HPD2 support Unmap commands. Application clients can make use of the Unmap command to specify certain LBAs do not contain vital data. The SSD can use the unmapped LBAs as needed. This feature will no longer be supported on these SSDs running firmware version HPD2 and later.

### Problems Fixed for HPD2 (B):

- Component would fail to install drive firmware for drives present in a system configured with two or more external drive enclosures attached to an HP Host Bus Adapter H22x. The following message would be reported in the component log file - "Device appears more than once in tree". The drive firmware installation failure was not observed in configurations having only one external drive enclosure attached to an HP Host Bus Adapter H22x.

---

Online ROM Flash Component for VMware ESXi - MO0200JEFNV, MO0400JEFPA, MO0800JEFPB, MO1600JEFPC, EO0200JEFPD, EO0400JEFPE, and EO0800JEFPF Drives

Version: HPD1 (C) **(Critical)**

Filename: CP029386.zip

### **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**
- **Customers who already installed firmware version HPD1 do not need to update to HPD1 (C).**

### **Fixes**

#### **Problem Fixed:**

- Incorrect data reads might occur when accessing unaligned 4k reads and the data read has zero content preceding customer data. For additional information please refer to the customer advisory #[c04650586](#)

#### **Problems Fixed for HPD1 (C):**

- Component would fail to install drive firmware for drives present in a system configured with two or more external drive enclosures attached to an HP Host Bus Adapter H22x. The following message would be reported in the component log file - "Device appears more than once in tree". The drive firmware installation failure was not observed in configurations having only one external drive enclosure attached to an HP Host Bus Adapter H22x.

### **Enhancements**

#### **Enhancements/New Features for HPD1(B):**

- VMware Firmware Smart component packaging has changed from a \*.scexe package to a \*.zip package, which contains an executable binary that provides enhanced security during installation. The functionality of the VMware Smart Component has not changed.

---

Online ROM Flash Component for VMware ESXi - MO0400JFFCF, MO0800JFFCH, MO1600JFFCK, and MO3200JFFCL Drives

Version: HPD4 **(Optional)**

Filename: CP029644.zip

### **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**

### **Fixes**

#### **Problems Fixed:**

- This firmware contains several low level maintenance fixes including debug data retrieval through read buffer. The fixes addressed events observed in a specialized lab testing environment, and are not expected to be experienced in customer use case scenarios.

---

Online ROM Flash Component for VMware ESXi - V00480JFDGT, V00960JFDGU, V01920JFDGV, and V03840JFDHA Drives

Version: HPD4 **(Optional)**

Filename: CP029645.zip

### **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**

### **Fixes**

#### **Problems Fixed:**

- This firmware contains several low level maintenance fixes including debug data retrieval through read buffer. The fixes addressed events observed in a specialized lab testing environment, and are not expected to be experienced in customer use case scenarios.

---

Online ROM Flash Component for VMware ESXi - V01920JEUQQ Drives

Version: HPD1 (B) **(Critical)**

Filename: CP029391.zip

### **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**
- **Customers who already installed firmware version HPD1 do not need to update to HPD1 (B).**

### **Fixes**

#### **Problem Fixed:**

- Incorrect data reads might occur when accessing unaligned 4k reads and the data read has zero content preceding customer data. (Additional information can be obtained for this issue in Customer Advisory [c04650586](#))

#### **Problems Fixed for HPD1 (B):**

- Component would fail to install drive firmware for drives present in a system configured with two or more external drive enclosures attached to an HP Host Bus Adapter H22x. The following message would be reported in the component log file - "Device appears more than once in tree". The drive firmware installation failure was not observed in configurations having only one external drive enclosure attached to an HP Host Bus Adapter H22x.

---

Online ROM Flash Component for Windows (x64) - DG0146FARVU, DG0300FARVV, DG0146BAMYQ, DG0300BAMYR, EG0146FAWJC, and EG0300FAWJD Drives

Version: HPDG (D) **(Critical)**

Filename: cp029243.exe; cp029243.md5

#### **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**
- **Customers who already installed firmware version HPDG do not need to update to HPDG (D).**

#### **Fixes**

##### **Problems Fixed:**

- This firmware corrects a possible condition in which stale data might be written to the disk. This results in unexpected data being returned in subsequent requests. This data issue has been duplicated in laboratory firmware stress tests.

##### **Problems Fixed for HPDG (C):**

- The component would fail to flash drive firmware on a server with a Trusted Platform Module (TPM) enabled when using the /tpmbypass switch.

##### **Problems Fixed for HPDG (D):**

- Component would fail to install drive firmware for drives present in a system configured with two or more external drive enclosures attached to an HP Host Bus Adapter H22x. The following message would be reported in the component log file - "Device appears more than once in tree". The drive firmware installation failure was not observed in configurations having only one external drive enclosure attached to an HP Host Bus Adapter H22x.
- Component would cause an exception error when deployed on a computer with a fully qualified domain name greater than 40 characters in length.

#### **Enhancements**

##### **Enhancements/New Features:**

- The firmware component installer can now install the drive firmware successfully when the new HP ProLiant Smart Array HPCISS3 Controller Driver (**hpciss3.sys**) is running on the system being updated.
- Added support for UEFI (Universal Extensible Firmware Interface) based servers.

##### **Enhancements/New Features for HPDG (B):**

- Updated the flash engine to standardize logging across all SAS drive components.
- Enhanced logging capability to improve the details provided in the component log file.
- Added support for Microsoft Windows Server 2016.

---

Online ROM Flash Component for Windows (x64) - DH0072FAQRD, DH0146FAQRE, EH0146FAWJB, and EH0072FAWJA Drives

Version: HPDK (B) **(Recommended)**

Filename: cp029244.exe; cp029244.md5

### **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**
- **Customers who already installed firmware version HPDK do not need to update to HPDK (B).**

### **Fixes**

#### **Problems Fixed:**

- HP ProLiant servers would power down due a hard drive overtemp condition that was falsely reported. Hard disk drive firmware HPDK resolves this issue.

#### **Problems Fixed for HPDK (B):**

- Component would fail to install drive firmware for drives present in a system configured with two or more external drive enclosures attached to an HP Host Bus Adapter H22x. The following message would be reported in the component log file - "Device appears more than once in tree". The drive firmware installation failure was not observed in configurations having only one external drive enclosure attached to an HP Host Bus Adapter H22x.
- Component would cause an exception error when deployed on a computer with a fully qualified domain name greater than 40 characters in length.

### **Enhancements**

#### **Enhancements/New Features:**

- Added support for Microsoft Windows Server 2016.

---

Online ROM Flash Component for Windows (x64) - EF0300FARMU, EF0450FARMV, EF0600FARNA drives

Version: HPD9 **(Recommended)**

Filename: cp030805.exe; cp030805.md5

### **Important Note!**

- **Online firmware flashing of drives attached to an HP Smart Array controller running in Zero Memory (ZM) mode or an HP ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux and Microsoft Windows environments. All other OSes would require an offline update using the SPP and HP SUM.**

## Fixes

### Problems Fixed:

- This firmware contains a change which prevents an incorrect reassign status of a repaired sector from being logged.

## Enhancements

### Enhancements/New Features:

- Added support for Microsoft Windows Server 2016.

---

Online ROM Flash Component for Windows (x64) - EF0300FATFD, EF0450FATFE, and EF0600FATFF Drives

Version: HPDB (D) **(Critical)**

Filename: cp029246.exe; cp029246.md5

## Important Note!

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSES would require an offline update using the SPP and HP SUM.**
- **Customers who already installed firmware version HPDB do not need to update to HPDB (D).**

## Fixes

### Problems Fixed:

- This firmware corrects a possible condition in which stale data might be written to the disk. This results in unexpected data being returned in subsequent requests. This data issue has been duplicated in laboratory firmware stress tests.

### Problems Fixed for HPDB (C):

- The component would fail to flash drive firmware on a server with a Trusted Platform Module (TPM) enabled when using the /tpmbypass switch.

### Problems Fixed for HPDB (D):

- Component would fail to install drive firmware for drives present in a system configured with two or more external drive enclosures attached to an HP Host Bus Adapter H22x. The following message would be reported in the component log file - "Device appears more than once in tree". The drive firmware installation failure was not observed in configurations having only one external drive enclosure attached to an HP Host Bus Adapter H22x.
- Component would cause an exception error when deployed on a computer with a fully qualified domain name greater than 40 characters in length.

## Enhancements

### Enhancements/New Features:

- The firmware component installer can now install the drive firmware successfully when the new HP ProLiant Smart Array HPCISS3 Controller Driver (**hpciss3.sys**) is running on the system being updated.
- Added support for UEFI (Universal Extensible Firmware Interface) based servers.



## Enhancements/New Features for HPDB (B):

- Updated the flash engine to standardize logging across all SAS drive components.
- Enhanced logging capability to improve the details provided in the component log file.
- Added support for Microsoft Windows Server 2016.

---

Online ROM Flash Component for Windows (x64) - EG0300FBDBR, EG0450FBDBT and EG0600FBDBU Drives

Version: HPDA (D) **(Critical)**

Filename: cp029247.exe; cp029247.md5

### **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**
- **Customers who already installed firmware version HPDA do not need to update to HPDA (D).**

### **Prerequisites**

- **Minimum firmware required - HPD7. HPDA drive firmware will fail when downgrading to versions below HPD7.**

### **Fixes**

#### **Firmware Dependency:**

- **Minimum firmware required - HPD7. HPDA drive firmware will fail when downgrading to versions below HPD7.**

#### **Problems Fixed:**

- This firmware corrects a possible condition in which stale data might be written to the disk. This results in unexpected data being returned in subsequent requests. This data issue has been duplicated in laboratory firmware stress tests.

#### **Problems Fixed for HPDA (C):**

- The component would fail to flash drive firmware on a server with a Trusted Platform Module (TPM) enabled when using the /tpmbypass switch.

#### **Problems Fixed for HPDA (D):**

- Component would fail to install drive firmware for drives present in a system configured with two or more external drive enclosures attached to an HP Host Bus Adapter H22x. The following message would be reported in the component log file - "Device appears more than once in tree". The drive firmware installation failure was not observed in configurations having only one external drive enclosure attached to an HP Host Bus Adapter H22x.
- Component would cause an exception error when deployed on a computer with a fully qualified domain name greater than 40 characters in length.

### **Enhancements**

#### **Enhancements/New Features:**

- Added support for UEFI (Universal Extensible Firmware Interface) based servers.

## Enhancements/New Features for HPDA (B):

- Updated the flash engine to standardize logging across all SAS drive components.
- Enhanced logging capability to improve the details provided in the component log file.
- Added support for Microsoft Windows Server 2016.

---

Online ROM Flash Component for Windows (x64) - EG0300FBDSR, EG0450FBDSQ, and EG0600FBDSR drives

Version: HPD6 (D) **(Optional)**

Filename: cp029248.exe; cp029248.md5

## **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**
- **Customers who already installed firmware version HPD6 do not need to update to HPD6 (D).**

## **Fixes**

### **Problems Fixed:**

- This firmware reduces the possibility of the controller and drive not properly negotiating link signaling, resulting in the controller not being able to identify a drive attached to a particular port/slot during system boot up. This firmware improves signal quality between the drive and the controller.

### **Problems Fixed for HPD6 (C):**

- The component would fail to flash drive firmware on a server with a Trusted Platform Module (TPM) enabled when using the /tpmbypass switch.

### **Problems Fixed for HPD6 (D):**

- Component would fail to install drive firmware for drives present in a system configured with two or more external drive enclosures attached to an HP Host Bus Adapter H22x. The following message would be reported in the component log file - "Device appears more than once in tree". The drive firmware installation failure was not observed in configurations having only one external drive enclosure attached to an HP Host Bus Adapter H22x.
- Component would cause an exception error when deployed on a computer with a fully qualified domain name greater than 40 characters in length.

## **Enhancements**

### **Enhancements/New Features:**

- The firmware component installer can now install the drive firmware successfully when the new HP ProLiant Smart Array HPCISS3 Controller Driver (**hpciss3.sys**) is running on the system being updated.
- Added support for UEFI (Universal Extensible Firmware Interface) based servers.

### **Enhancements/New Features for HPD6 (B):**

- Updated the flash engine to standardize logging across all SAS drive components.
- Enhanced logging capability to improve the details provided in the component log file.
- Added support for Microsoft Windows Server 2016.

---

Online ROM Flash Component for Windows (x64) - EG0300FBLSE, EG0450FBLSF, EG0600FBLSH, and EG0900FBLSK drives

Version: HPD8 (C) **(Recommended)**

Filename: cp029249.exe; cp029249.md5

### **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**
- **Customers who already installed firmware version HPD8 do not need to update to HPD8 (C).**

### **Fixes**

#### **Problems Fixed:**

- HP ProLiant servers would power down due a hard drive overtemp condition that was falsely reported. Hard disk drive firmware HPD8 resolves this issue.

#### **Problems Fixed for HPD8 (B):**

- The component would fail to flash drive firmware on a server with a Trusted Platform Module (TPM) enabled when using the /tpmbypass switch.

#### **Problems Fixed for HPD8 (C):**

- Component would fail to install drive firmware for drives present in a system configured with two or more external drive enclosures attached to an HP Host Bus Adapter H22x. The following message would be reported in the component log file - "Device appears more than once in tree". The drive firmware installation failure was not observed in configurations having only one external drive enclosure attached to an HP Host Bus Adapter H22x.
- Component would cause an exception error when deployed on a computer with a fully qualified domain name greater than 40 characters in length.

### **Enhancements**

#### **Enhancements/New Features:**

- Added support for Microsoft Windows Server 2016.

---

Online ROM Flash Component for Windows (x64) - EG0300FBVFL, EG0450FBVFM, EG0600FBVFP, and EG0900FBVFQ Drives

Version: HPDE (B) **(Recommended)**

Filename: cp029250.exe; cp029250.md5

### **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**

- o **Customers who already installed firmware version HPDE do not need to update to HPDE (B).**

## **Fixes**

### **Problems Fixed:**

- o Drive self-test did not complete within the specified time.
- o During a fully cached workload, SMART would report incorrect temperature values.
- o The component would fail to flash drive firmware on a server with a Trusted Platform Module (TPM) enabled when using the /tpmbypass switch.

### **Problems Fixed for HPDE (B):**

- o Component would fail to install drive firmware for drives present in a system configured with two or more external drive enclosures attached to an HP Host Bus Adapter H22x. The following message would be reported in the component log file - "Device appears more than once in tree". The drive firmware installation failure was not observed in configurations having only one external drive enclosure attached to an HP Host Bus Adapter H22x.
- o Component would cause an exception error when deployed on a computer with a fully qualified domain name greater than 40 characters in length.

## **Enhancements**

### **Enhancements/New Features:**

- o Added servo improvements which reduce power consumption.
- o Added support for Microsoft Windows Server 2016.

---

Online ROM Flash Component for Windows (x64) - EG0300FCHHR, EG0450FCHHT, EG0600FCHHU, and EG0900FCHHV Drives  
Version: HPD8 (C) **(Recommended)**  
Filename: cp029251.exe; cp029251.md5

## **Important Note!**

- o **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- o **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**
- o **Customers who already installed firmware version HPD8 do not need to update to HPD8 (C).**

## **Fixes**

### **Problems Fixed:**

- o A potential issue existed where the drive would become unresponsive if the host sent a high number of overlapping task management commands. The drive would require a power cycle to be recovered.

### **Problems Fixed for HPD8 (B):**

- o The component would fail to flash drive firmware on a server with a Trusted Platform Module (TPM) enabled when using the /tpmbypass switch.

### **Problems Fixed for HPD8 (C):**

- Component would fail to install drive firmware for drives present in a system configured with two or more external drive enclosures attached to an HP Host Bus Adapter H22x. The following message would be reported in the component log file - "Device appears more than once in tree". The drive firmware installation failure was not observed in configurations having only one external drive enclosure attached to an HP Host Bus Adapter H22x.
- Component would cause an exception error when deployed on a computer with a fully qualified domain name greater than 40 characters in length.

## **Enhancements**

### **Enhancements/New Features:**

- Improved write protection robustness before drive spin down.
- Implemented minor performance improvements in RAID environments.
- Added support for Microsoft Windows Server 2016.

---

Online ROM Flash Component for Windows (x64) - EG0300FCVBF, EG0450FCVBH, EG0600FCVBK, and EG0900FCVBL Drives

Version: HPD9 (C) **(Recommended)**

Filename: cp029252.exe; cp029252.md5

## **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**
- **Customers who already installed firmware version HPD9 do not need to update to HPD9 (C).**

## **Fixes**

### **Problems Fixed:**

- Drives could become unresponsive due to unexpected responses from the serial port diagnostic debug connection.

### **Problems Fixed for HPD9 (B):**

- The component would fail to flash drive firmware on a server with a Trusted Platform Module (TPM) enabled when using the /tpmbypass switch.

### **Problems Fixed for HPD9 (C):**

- Component would fail to install drive firmware for drives present in a system configured with two or more external drive enclosures attached to an HP Host Bus Adapter H22x. The following message would be reported in the component log file - "Device appears more than once in tree". The drive firmware installation failure was not observed in configurations having only one external drive enclosure attached to an HP Host Bus Adapter H22x.
- Component would cause an exception error when deployed on a computer with a fully qualified domain name greater than 40 characters in length.

## **Enhancements**

### **Enhancements/New Features:**

- Added support for Microsoft Windows Server 2016.

---

Online ROM Flash Component for Windows (x64) - EG0300JEHLV, EG0600JEHMA, EG0900JEHMB, and EG1200JEHMC Drives

Version: HPD3 (C) **(Recommended)**

Filename: cp029253.exe; cp029253.md5

### **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**
- **Customers who already installed firmware version HPD3 do not need to update to HPD3 (C).**

### **Fixes**

#### **Problems Fixed:**

- Self-initiated reset during ATI (Adjacent Track Interference) mitigation issue, where the drive reported a 06/29/04 (Self-Initiated Reset) to the controller. Then the controller would re-establish link with the drive and resend the command.
- Servo miscalculations that resulted in degraded drive performance.

#### **Problems Fixed for HPD3 (B):**

- The component would fail to flash drive firmware on a server with a Trusted Platform Module (TPM) enabled when using the /tpmbypass switch.

#### **Problems Fixed for HPD3 (C):**

- Component would fail to install drive firmware for drives present in a system configured with two or more external drive enclosures attached to an HP Host Bus Adapter H22x. The following message would be reported in the component log file - "Device appears more than once in tree". The drive firmware installation failure was not observed in configurations having only one external drive enclosure attached to an HP Host Bus Adapter H22x.
- Component would cause an exception error when deployed on a computer with a fully qualified domain name greater than 40 characters in length.

### **Enhancements**

#### **Enhancements/New Features:**

- Added support for Microsoft Windows Server 2016.

---

Online ROM Flash Component for Windows (x64) - EG0300JFCKA, EG0600JEMCV, EG0900JFCKB, and EG1200JEMDA Drives

Version: HPD4 (C) **(Recommended)**

Filename: cp029254.exe; cp029254.md5

### **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft**

- **Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**
- **Customers who already installed firmware version HPD4 do not need to update to HPD4 (C).**

## **Fixes**

### **Problems Fixed:**

- The expected time to completion of Sanitize, Format and DST operations was incorrectly reported in the Vital Products Data page D0h. If time to completion is used by an application to determine when to terminate an operation, the operation might be terminated before the operation completed. Firmware version HPD4 now correctly reports the expected time to completion for these operations.

### **Problems Fixed for HPD4 (B):**

- The component would fail to flash drive firmware on a server with a Trusted Platform Module (TPM) enabled when using the /tpmbypass switch.

### **Problems Fixed for HPD4 (C):**

- Component would fail to install drive firmware for drives present in a system configured with two or more external drive enclosures attached to an HP Host Bus Adapter H22x. The following message would be reported in the component log file - "Device appears more than once in tree". The drive firmware installation failure was not observed in configurations having only one external drive enclosure attached to an HP Host Bus Adapter H22x.
- Component would cause an exception error when deployed on a computer with a fully qualified domain name greater than 40 characters in length.

## **Enhancements**

### **Enhancements/New Features:**

- Added support for Microsoft Windows Server 2016.

---

Online ROM Flash Component for Windows (x64) - EG0600JETKA, EG0900JETKB, and EG1200JETKC Drives

Version: HPD4 (B) **(Recommended)**

Filename: cp030990.exe; cp030990.md5

## **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**
- **Customers who already installed firmware version HPD5 do not need to update to HPD4 (B).**

## **Enhancements**

### **Enhancements/New Features:**

- Reliability enhancement for applications that write data to a narrow range of tracks.

### **Enhancements/New Features for HPD4 (B):**

- Added support for Microsoft Windows Server 2016.

---

Online ROM Flash Component for Windows (x64) - EG0900FDJYR and EG1200FDJYT Drives

Version: HPD4 (C) **(Recommended)**

Filename: cp029255.exe; cp029255.md5

### **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSES would require an offline update using the SPP and HP SUM.**
- **Customers who already installed firmware version HPD4 do not need to update to HPD4 (C).**

### **Fixes**

#### **Problems Fixed:**

- Prevents the potential for incorrect data from being “read from” or “written to” the drive under extremely rare circumstances where the drive experiences consecutive error recoveries during a background scan and the Error Correction Code (ECC) fails. This issue has only been observed in a rigorous test environment and has NOT been reported in a customer production environment.

#### **Problems Fixed for HPD4 (B):**

- The component would fail to flash drive firmware on a server with a Trusted Platform Module (TPM) enabled when using the /tpmbypass switch.

#### **Problems Fixed for HPD4 (C):**

- Component would fail to install drive firmware for drives present in a system configured with two or more external drive enclosures attached to an HP Host Bus Adapter H22x. The following message would be reported in the component log file - “Device appears more than once in tree”. The drive firmware installation failure was not observed in configurations having only one external drive enclosure attached to an HP Host Bus Adapter H22x.
- Component would cause an exception error when deployed on a computer with a fully qualified domain name greater than 40 characters in length.

### **Enhancements**

#### **Enhancements/New Features:**

- Added support for Microsoft Windows Server 2016.

---

Online ROM Flash Component for Windows (x64) - EG1200FDNJT and EG1200FCVBQ Drives

Version: HPD8 (B) **(Recommended)**

Filename: cp029256.exe; cp029256.md5

### **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSES would require an offline update using the SPP and HP SUM.**



- o **Customers who already installed firmware version HPD8 do not need to update to HPD8 (B).**

## **Fixes**

### **Problems Fixed:**

- o Drive self-test did not complete within the specified time.
- o During a fully cached workload, SMART would report incorrect temperature values.
- o The component would fail to flash drive firmware on a server with a Trusted Platform Module (TPM) enabled when using the /tpmbypass switch.

### **Problems Fixed for HPD8 (B):**

- o Component would fail to install drive firmware for drives present in a system configured with two or more external drive enclosures attached to an HP Host Bus Adapter H22x. The following message would be reported in the component log file - "Device appears more than once in tree". The drive firmware installation failure was not observed in configurations having only one external drive enclosure attached to an HP Host Bus Adapter H22x.
- o Component would cause an exception error when deployed on a computer with a fully qualified domain name greater than 40 characters in length.

## **Enhancements**

### **Enhancements/New Features:**

- o Added servo improvements which reduce power consumption.
- o Added support for Microsoft Windows Server 2016.

---

Online ROM Flash Component for Windows (x64) - EG1800JEHMD Drive

Version: HPD4 (C) **(Recommended)**

Filename: cp029257.exe; cp029257.md5

## **Important Note!**

- o **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- o **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**
- o **Customers who already installed firmware version HPD4 do not need to update to HPD4 (C).**

## **Fixes**

### **Problems Fixed:**

- o Self-initiated reset during ATI (Adjacent Track Interference) mitigation issue, where the drive reported a 06/29/04 (Self-Initiated Reset) to the controller. Then the controller would re-establish link with the drive and resend the command.
- o Servo miscalculations that resulted in degraded drive performance.

### **Problems Fixed for HPD4 (B):**

- o The component would fail to flash drive firmware on a server with a Trusted Platform Module (TPM) enabled when using the /tpmbypass switch.

### Problems Fixed for HPD4 (C):

- Component would fail to install drive firmware for drives present in a system configured with two or more external drive enclosures attached to an HP Host Bus Adapter H22x. The following message would be reported in the component log file - "Device appears more than once in tree". The drive firmware installation failure was not observed in configurations having only one external drive enclosure attached to an HP Host Bus Adapter H22x.
- Component would cause an exception error when deployed on a computer with a fully qualified domain name greater than 40 characters in length.

### Enhancements

#### Enhancements/New Features:

- Added support for Microsoft Windows Server 2016.

---

Online ROM Flash Component for Windows (x64) - EG1800JEMDB Drives

Version: HPD2 (**Recommended**)

Filename: cp030030.exe; cp030030.md5

### Important Note!

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**

### Fixes

#### Problems Fixed:

- This firmware improves HDD reliability when HDDs are exposed to long periods of host inactivity that exceed 1 second. HDDs may become unresponsive when using HDD firmware prior to version HPD2. This firmware also contains a change which prevents an incorrect reassign status of a repaired sector from being logged.

### Enhancements

#### Enhancements/New Features:

- Added support for Microsoft Windows Server 2016.

---

Online ROM Flash Component for Windows (x64) - EH0072FARUA and EH0146FARUB drives

Version: HPD9 (D) (**Optional**)

Filename: cp029258.exe; cp029258.md5

### Important Note!

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft**

**Windows, and VMware environments. All other OSES would require an offline update using the SPP and HP SUM.**

- **Customers who already installed firmware version HPD9 do not need to update to HPD9 (D).**

## **Fixes**

### **Problems Fixed:**

- This firmware reduces the possibility of the controller and drive not properly negotiating link signaling, resulting in the controller not being able to identify a drive attached to a particular port/slot during system boot up. This firmware improves signal quality between the drive and the controller.

### **Problems Fixed for HPD9 (C):**

- The component would fail to flash drive firmware on a server with a Trusted Platform Module (TPM) enabled when using the /tpmbypass switch.

### **Problems Fixed for HPD9 (D):**

- Component would fail to install drive firmware for drives present in a system configured with two or more external drive enclosures attached to an HP Host Bus Adapter H22x. The following message would be reported in the component log file - "Device appears more than once in tree". The drive firmware installation failure was not observed in configurations having only one external drive enclosure attached to an HP Host Bus Adapter H22x.
- Component would cause an exception error when deployed on a computer with a fully qualified domain name greater than 40 characters in length.

## **Enhancements**

### **Enhancements/New Features:**

- The firmware component installer can now install the drive firmware successfully when the new HP ProLiant Smart Array HPCISS3 Controller Driver (**hpciss3.sys**) is running on the system being updated.
- Added support for UEFI (Universal Extensible Firmware Interface) based servers.

### **Enhancements/New Features for HPD9 (B):**

- Updated the flash engine to standardize logging across all SAS drive components.
- Enhanced logging capability to improve the details provided in the component log file.
- Added support for Microsoft Windows Server 2016.

---

Online ROM Flash Component for Windows (x64) - EH0072FARWC and EH0146FARWD Drives

Version: HPDD (D) **(Critical)**

Filename: cp029259.exe; cp029259.md5

## **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSES would require an offline update using the SPP and HP SUM.**
- **Customers who already installed firmware version HPDD do not need to update to HPDD (D).**

## **Fixes**

### Problems Fixed:

- This firmware corrects a possible condition in which stale data might be written to the disk. This results in unexpected data being returned in subsequent requests. This data issue has been duplicated in laboratory firmware stress tests.

### Problems Fixed for HPDD (C):

- The component would fail to flash drive firmware on a server with a Trusted Platform Module (TPM) enabled when using the /tpmbypass switch.

### Problems Fixed for HPDD (D):

- Component would fail to install drive firmware for drives present in a system configured with two or more external drive enclosures attached to an HP Host Bus Adapter H22x. The following message would be reported in the component log file - "Device appears more than once in tree". The drive firmware installation failure was not observed in configurations having only one external drive enclosure attached to an HP Host Bus Adapter H22x.
- Component would cause an exception error when deployed on a computer with a fully qualified domain name greater than 40 characters in length.

## Enhancements

### Enhancements/New Features:

- The firmware component installer can now install the drive firmware successfully when the new HP ProLiant Smart Array HPCISS3 Controller Driver (**hpciss3.sys**) is running on the system being updated.
- Added support for UEFI (Universal Extensible Firmware Interface) based servers.

### Enhancements/New Features for HPDD (B):

- Updated the flash engine to standardize logging across all SAS drive components.
- Enhanced logging capability to improve the details provided in the component log file.
- Added support for Microsoft Windows Server 2016.

---

Online ROM Flash Component for Windows (x64) - EH0146FBQDC and EH0300FBQDD drives

Version: HPD5 (C) **(Recommended)**

Filename: cp029260.exe; cp029260.md5

### Important Note!

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**
- **Customers who already installed firmware version HPD5 do not need to update to HPD5 (C).**

## Fixes

### Problems Fixed:

- HP ProLiant servers would power down due a hard drive overtemp condition that was falsely reported. Hard disk drive firmware HPD5 resolves this issue.

### Problems Fixed for HPD5 (B):

- The component would fail to flash drive firmware on a server with a Trusted Platform Module (TPM) enabled when using the /tpmbypass switch.

#### **Problems Fixed for HPD5 (C):**

- Component would fail to install drive firmware for drives present in a system configured with two or more external drive enclosures attached to an HP Host Bus Adapter H22x. The following message would be reported in the component log file - "Device appears more than once in tree". The drive firmware installation failure was not observed in configurations having only one external drive enclosure attached to an HP Host Bus Adapter H22x.
- Component would cause an exception error when deployed on a computer with a fully qualified domain name greater than 40 characters in length.

#### **Enhancements**

##### **Enhancements/New Features:**

- Added support for Microsoft Windows Server 2016.

---

Online ROM Flash Component for Windows (x64) - EH0146FCBVB and EH0300FCBVC drives

Version: HPD8 (B) **(Recommended)**

Filename: cp030991.exe; cp030991.md5

#### **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**
- **Customers who already installed firmware version HPD5 do not need to update to HPD8 (B).**

#### **Fixes**

##### **Problems Fixed:**

- Reliability enhancement for applications that write data to a narrow range of tracks.
- New SMART trip when device senses an abnormal change in the motor electric current.

#### **Enhancements**

##### **Enhancements/New Features for HPD8 (B):**

- Added support for Microsoft Windows Server 2016.

---

Online ROM Flash Component for Windows (x64) - EH0300JDXBA, EH0450JDXBB, and EH0600JDXBC Drives

Version: HPD3 (B) **(Recommended)**

Filename: cp030992.exe; cp030992.md5

#### **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE**

**ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**

- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**
- **Customers who already installed firmware version HPD5 do not need to update to HPD3 (B).**

## **Enhancements**

### **Enhancements/New Features:**

- Reliability enhancement for applications that write data to a narrow range of tracks.

### **Enhancements/New Features for HPD3 (B):**

- Added support for Microsoft Windows Server 2016.

---

Online ROM Flash Component for Windows (x64) - EH0300JDYTH, EH0450JDYTK, and EH0600JDYTL Drives

Version: HPD4 (C) **(Recommended)**

Filename: cp029262.exe; cp029262.md5

## **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**
- **Customers who already installed firmware version HPD4 do not need to update to HPD4 (C).**

## **Fixes**

### **Problems Fixed:**

- Self-initiated reset during ATI (Adjacent Track Interference) mitigation issue, where the drive reported a 06/29/04 (Self-Initiated Reset) to the controller. Then the controller would re-establish link with the drive and resend the command.
- Servo miscalculations that resulted in degraded drive performance.

### **Problems Fixed for HPD4 (B):**

- The component would fail to flash drive firmware on a server with a Trusted Platform Module (TPM) enabled when using the /tpmbypass switch.

### **Problems Fixed for HPD4 (C):**

- Component would fail to install drive firmware for drives present in a system configured with two or more external drive enclosures attached to an HP Host Bus Adapter H22x. The following message would be reported in the component log file - "Device appears more than once in tree". The drive firmware installation failure was not observed in configurations having only one external drive enclosure attached to an HP Host Bus Adapter H22x.
- Component would cause an exception error when deployed on a computer with a fully qualified domain name greater than 40 characters in length.

## **Enhancements**

## Enhancements/New Features:

- Added support for Microsoft Windows Server 2016.

---

Online ROM Flash Component for Windows (x64) - EH0300JEDHC, EH0450JEDHD, and EH0600JEDHE Drives

Version: HPD4 (B) **(Recommended)**

Filename: cp030993.exe; cp030993.md5

### **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**
- **Customers who already installed firmware version HPD5 do not need to update to HPD4 (B).**

### **Fixes**

#### **Problems Fixed:**

- This firmware improves HDD reliability when HDDs are exposed to long periods of host inactivity that exceed 1 second. HDDs may become unresponsive when using HDD firmware prior to version HPD4. This firmware also contains a change which prevents an incorrect reassign status of a repaired sector from being logged.

### **Enhancements**

#### **Enhancements/New Features for HPD4 (B):**

- Added support for Microsoft Windows Server 2016.

---

Online ROM Flash Component for Windows (x64) - EH0600JDYTN Drive

Version: HPD5 (C) **(Recommended)**

Filename: cp029264.exe; cp029264.md5

### **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**
- **Customers who already installed firmware version HPD5 do not need to update to HPD5 (C).**

### **Fixes**

#### **Problems Fixed:**

- Self-initiated reset during ATI (Adjacent Track Interference) mitigation issue, where the drive reported a 06/29/04 (Self-Initiated Reset) to the controller. Then the controller would re-establish link with the drive and resend the command.
- Servo miscalculations that resulted in degraded drive performance.

### **Problems Fixed for HPD5(B):**

- The component would fail to flash drive firmware on a server with a Trusted Platform Module (TPM) enabled when using the /tpmbypass switch.

### **Problems Fixed for HPD5 (C):**

- Component would fail to install drive firmware for drives present in a system configured with two or more external drive enclosures attached to an HP Host Bus Adapter H22x. The following message would be reported in the component log file - "Device appears more than once in tree". The drive firmware installation failure was not observed in configurations having only one external drive enclosure attached to an HP Host Bus Adapter H22x.
- Component would cause an exception error when deployed on a computer with a fully qualified domain name greater than 40 characters in length.

## **Enhancements**

### **Enhancements/New Features:**

- Added support for Microsoft Windows Server 2016.

---

Online ROM Flash Component for Windows (x64) - E00200FBRVV, MO0200FBRWB, E00400FBRWA, MO0400FBRWC, and MO0800FBRWD drives

Version: HPD9 (D) **(Optional)**

Filename: cp029265.exe; cp029265.md5

## **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**
- **Customers who already installed firmware version HPD9 do not need to update to HPD9 (D).**

## **Fixes**

### **Problems Fixed:**

- In previous firmware revisions when the solid state drive was issued a Report Support Operation Code (RSOC) command (A3h) and the reporting options field was set to 001, the drive incorrectly responded with 05/24/00 indicating that the RSOC command was not supported. The error was logged in the system log files. The drive should have communicated non-support using the Command Data Parameter (CDP) format. The firmware now complies with the RSOC industry standard specification.

### **Problems Fixed for HPD9(C):**

- The component would fail to flash drive firmware on a server with a Trusted Platform Module (TPM) enabled when using the /tpmbypass switch.

### **Problems Fixed for HPD9 (D):**

- Component would fail to install drive firmware for drives present in a system configured with two or more external drive enclosures attached to an HP Host Bus Adapter H22x. The following message would be reported in the component log file - "Device appears more than once in tree". The drive firmware installation failure was not observed in configurations having only one external drive enclosure attached to an HP Host Bus Adapter H22x.
- Component would cause an exception error when deployed on a computer with a fully qualified domain name greater than 40



characters in length.

## **Enhancements**

### **Enhancements/New Features:**

- The firmware component installer can now install the drive firmware successfully when the new HP ProLiant Smart Array HPCISS3 Controller Driver (**hpciss3.sys**) is running on the system being updated.
- Added support for UEFI (Universal Extensible Firmware Interface) based servers.

### **Enhancements/New Features for HPD9 (B):**

- Updated the flash engine to standardize logging across all SAS drive components.
- Enhanced logging capability to improve the details provided in the component log file.
- Added support for Microsoft Windows Server 2016.

---

Online ROM Flash Component for Windows (x64) - MB1000FAMYU and MB2000FAMYV Drives

Version: HPD7 (D) **(Critical)**

Filename: cp029268.exe; cp029268.md5

## **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSES would require an offline update using the SPP and HP SUM.**
- **Customers who already installed firmware version HPD7 do not need to update to HPD7 (D).**

## **Fixes**

### **Problem Fixed:**

- This firmware prevents a rare condition that may occur during a WRITE SAME command sequence that may result in incorrect data being written to the hard drive. The WRITE SAME command may be used during RAID ARRAY parity initialization.

### **Problems Fixed for HPD7 (C):**

- The component would fail to flash drive firmware on a server with a Trusted Platform Module (TPM) enabled when using the /tpmbypass switch.

### **Problems Fixed for HPD7 (D):**

- Component would fail to install drive firmware for drives present in a system configured with two or more external drive enclosures attached to an HP Host Bus Adapter H22x. The following message would be reported in the component log file - "Device appears more than once in tree". The drive firmware installation failure was not observed in configurations having only one external drive enclosure attached to an HP Host Bus Adapter H22x.
- Component would cause an exception error when deployed on a computer with a fully qualified domain name greater than 40 characters in length.

## **Enhancements**

### **Enhancements/New Features:**

- The firmware component installer can now install the drive firmware successfully when the new HP ProLiant Smart Array HPCISS3 Controller Driver (**hpcisss3.sys**) is running on the system being updated.
- Added support for UEFI (Universal Extensible Firmware Interface) based servers.

#### **Enhancements/New Features for HPD7 (B):**

- Updated the flash engine to standardize logging across all SAS drive components.
- Enhanced logging capability to improve the details provided in the component log file.
- Added support for Microsoft Windows Server 2016.

---

Online ROM Flash Component for Windows (x64) - MB1000FBZPL and MB2000FBZPN drives

Version: HPD4 (B) **(Recommended)**

Filename: cp029269.exe; cp029269.md5

#### **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**
- **Customers who already installed firmware version HPD4 do not need to update to HPD4 (B).**

#### **Fixes**

##### **Problems Fixed:**

- ProLiant servers would power down due a hard drive over temperature condition that was falsely reported. HPD4 firmware resolves this issue.

##### **Problems Fixed for HPD4 (B):**

- Component would fail to install drive firmware for drives present in a system configured with two or more external drive enclosures attached to an HP Host Bus Adapter H22x. The following message would be reported in the component log file - "Device appears more than once in tree". The drive firmware installation failure was not observed in configurations having only one external drive enclosure attached to an HP Host Bus Adapter H22x.
- Component would cause an exception error when deployed on a computer with a fully qualified domain name greater than 40 characters in length.

#### **Enhancements**

##### **Enhancements/New Features:**

- Added support for Microsoft Windows Server 2016.

---

Online ROM Flash Component for Windows (x64) - MB1000FCWDE, MB2000FCWDF, MB3000FCWDH, and MB4000FCWDK Drives

Version: HPDA **(Recommended)**

Filename: cp030188.exe; cp030188.md5

#### **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE**

**ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**

- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**

## Fixes

### **Problems Fixed:**

- This firmware improves HDD reliability when HDDs are exposed to long periods of host inactivity that exceed 1 second. HDDs may become unresponsive when using HDD firmware prior to version HPDA.
- This firmware also contains a change which prevents an incorrect reassign status of a repaired sector from being logged.

## Enhancements

### **Enhancements/New Features:**

- Added support for Microsoft Windows Server 2016.

---

Online ROM Flash Component for Windows (x64) - MB1000FCWPP, MB2000FCVBV, MB3000FCVCA, and MB4000FCVCB Drives

Version: HPD2 (D) **(Recommended)**

Filename: cp029271.exe; cp029271.md5

## Important Note!

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**
- **Customers who already installed firmware version HPD2 do not need to update to HPD2 (D).**

## Fixes

### **Problems Fixed for HPD2 (C):**

- The component would fail to flash drive firmware on a server with a Trusted Platform Module (TPM) enabled when using the /tpmbypass switch.

### **Problems Fixed for HPD2 (D):**

- Component would fail to install drive firmware for drives present in a system configured with two or more external drive enclosures attached to an HP Host Bus Adapter H22x. The following message would be reported in the component log file - "Device appears more than once in tree". The drive firmware installation failure was not observed in configurations having only one external drive enclosure attached to an HP Host Bus Adapter H22x.
- Component would cause an exception error when deployed on a computer with a fully qualified domain name greater than 40 characters in length.

## Enhancements

### **Enhancements/New Features:**

- This firmware improves reliability by modifying the pivot bearing grease wear leveling algorithm, which if not implemented, could result in an increased drive failure rate for specific usage applications (eg, very long periods of small range seeks).
- Enhancements also include performance improvements.
- Added support for UEFI (Universal Extensible Firmware Interface) based servers.

#### **Enhancements/New Features for HPD2 (B):**

- Updated the flash engine to standardize logging across all SAS drive components.
- Enhanced logging capability to improve the details provided in the component log file.
- Added support for Microsoft Windows Server 2016.

---

Online ROM Flash Component for Windows (x64) - MB2000FBUCL and MB3000FBUCN drives

Version: HPDA (D) **(Critical)**

Filename: cp029276.exe; cp029276.md5

#### **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**
- **Customers who already installed firmware version HPDA do not need to update to HPDA (D).**

#### **Fixes**

##### **Problems Fixed:**

- This firmware improves background scans for media robustness, and also corrects a laboratory induced rare condition that could result in the disk not being updated with the latest cache data.

##### **Problems Fixed for HPDA (C):**

- The component would fail to flash drive firmware on a server with a Trusted Platform Module (TPM) enabled when using the /tpmbypass switch.

##### **Problems Fixed for HPDA (D):**

- Component would fail to install drive firmware for drives present in a system configured with two or more external drive enclosures attached to an HP Host Bus Adapter H22x. The following message would be reported in the component log file - "Device appears more than once in tree". The drive firmware installation failure was not observed in configurations having only one external drive enclosure attached to an HP Host Bus Adapter H22x.
- Component would cause an exception error when deployed on a computer with a fully qualified domain name greater than 40 characters in length.

#### **Enhancements**

##### **Enhancements/New Features:**

- Added support for UEFI (Universal Extensible Firmware Interface) based servers.

##### **Enhancements/New Features for HPDA (B):**

- Updated the flash engine to standardize logging across all SAS drive components.

- Enhanced logging capability to improve the details provided in the component log file.
- Added support for Microsoft Windows Server 2016.

---

Online ROM Flash Component for Windows (x64) - MB2000FCQPF and MB3000FBNWV Drives

Version: HPD9 **(Recommended)**

Filename: cp030831.exe; cp030831.md5

### **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**

### **Fixes**

#### **Problems Fixed:**

- HP ProLiant servers would power down due a hard drive overtemp condition that was falsely reported. Hard disk drive firmware HPD9 resolves this issue.

### **Enhancements**

#### **Enhancements/New Features:**

- Added support for Microsoft Windows Server 2016.

---

Online ROM Flash Component for Windows (x64) - MB2000FCZGH, MB3000FCZGK, and MB4000FCZGL Drives

Version: HPD7 (B) **(Recommended)**

Filename: cp029278.exe; cp029278.md5

### **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**
- **Customers who already installed firmware version HPD7 do not need to update to HPD7 (B).**

### **Fixes**

#### **Problems Fixed:**

- This firmware corrects an issue which could result in a failure of the drive to be discovered after power on.

#### **Problems Fixed for HPD7 (B):**

- Component would fail to install drive firmware for drives present in a system configured with two or more external drive enclosures attached to an HP Host Bus Adapter H22x. The following message would be reported in the component log file - "Device appears more

than once in tree". The drive firmware installation failure was not observed in configurations having only one external drive enclosure attached to an HP Host Bus Adapter H22x.

- Component would cause an exception error when deployed on a computer with a fully qualified domain name greater than 40 characters in length.

## **Enhancements**

### **Enhancements/New Features:**

- Added support for Microsoft Windows Server 2016.

---

Online ROM Flash Component for Windows (x64) - MB2000JFDSL and MB4000JFDSN Drives

Version: HPD1 **(Recommended)**

Filename: cp030061.exe; cp030061.md5

### **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**

## **Enhancements**

### **Enhancements/New Features:**

- Reliability enhancement for applications that write data to a narrow range of tracks.
- Added support for Microsoft Windows Server 2016.

---

Online ROM Flash Component for Windows (x64) - MB2000JFEPA and MB4000JFEPB Drives

Version: HPD2 **(Recommended)**

Filename: cp030847.exe; cp030847.md5

### **Important Note!**

- **Online firmware flashing of drives attached to an HP Smart Array controller running in Zero Memory (ZM) mode or an HP ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**

## **Fixes**

### **Problems Fixed:**

- This firmware improves HDD reliability when HDDs are exposed to long periods of host inactivity that exceed 1 second. HDDs may become unresponsive when using HDD firmware prior to version HPD2. This firmware also contains a change which prevents an incorrect reassign status of a repaired sector from being logged.

## **Enhancements**

### **Enhancements/New Features:**

- Added support for Microsoft Windows Server 2016.

---

Online ROM Flash Component for Windows (x64) - MB4000JEFNC and MB6000JEFND Drives

Version: HPD5 (B) **(Critical)**

Filename: cp030995.exe; cp030995.md5

### **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**
- **Customers who already installed firmware version HPD5 do not need to update to HPD5 (B).**

## **Fixes**

### **Problems Fixed:**

- This firmware improves HDD reliability when HDDs are exposed to long periods of host inactivity that exceed 1 second. HDDs may become unresponsive when using HDD firmware prior to version HPD5. This firmware also contains a change which prevents an incorrect reassign status of a repaired sector from being logged.

## **Enhancements**

### **Enhancements/New Features for HPD5 (B):**

- Added support for Microsoft Windows Server 2016.

---

Online ROM Flash Component for Windows (x64) - MB4000JEQNL and MB6000JEQNN Drives

Version: HPD7 (C) **(Critical)**

Filename: cp029286.exe; cp029286.md5

### **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**
- **Customers who already installed firmware version HPD7 do not need to update to HPD7 (C).**

## **Fixes**

### **Problems Fixed:**

- This firmware fixes a potential incorrect data issue in write-cached enabled multi-initiator unaligned write environments, where

reservation commands are used.

#### **Problems Fixed for HPD7 (B):**

- The component would fail to flash drive firmware on a server with a Trusted Platform Module (TPM) enabled when using the /tpmbypass switch.

#### **Problems Fixed for HPD7 (C):**

- Component would fail to install drive firmware for drives present in a system configured with two or more external drive enclosures attached to an HP Host Bus Adapter H22x. The following message would be reported in the component log file - "Device appears more than once in tree". The drive firmware installation failure was not observed in configurations having only one external drive enclosure attached to an HP Host Bus Adapter H22x.
- Component would cause an exception error when deployed on a computer with a fully qualified domain name greater than 40 characters in length.

### **Enhancements**

#### **Enhancements/New Features:**

- Added support for Microsoft Windows Server 2016.

---

Online ROM Flash Component for Windows (x64) - MB6000FEDAU Drives

Version: HPD4 (B) **(Recommended)**

Filename: cp029287.exe; cp029287.md5

### **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**
- **Customers who already installed firmware version HPD4 do not need to update to HPD4 (B).**

### **Fixes**

#### **Problems Fixed:**

- This firmware corrects an issue which could result in a failure of the drive to be discovered after power on.

#### **Problems Fixed for HPD4 (B):**

- Component would fail to install drive firmware for drives present in a system configured with two or more external drive enclosures attached to an HP Host Bus Adapter H22x. The following message would be reported in the component log file - "Device appears more than once in tree". The drive firmware installation failure was not observed in configurations having only one external drive enclosure attached to an HP Host Bus Adapter H22x.
- Component would cause an exception error when deployed on a computer with a fully qualified domain name greater than 40 characters in length.

### **Enhancements**

#### **Enhancements/New Features:**



- o Added support for Microsoft Windows Server 2016.

---

Online ROM Flash Component for Windows (x64) - MM0500FAMYT Drives

Version: HPD6 (D) **(Critical)**

Filename: cp029291.exe; cp029291.md5

### **Important Note!**

- o **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- o **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSES would require an offline update using the SPP and HP SUM.**
- o **Customers who already installed firmware version HPD6 do not need to update to HPD6 (D).**

### **Fixes**

#### **Problem Fixed:**

- o After long term use of the HDD, a rare condition might occur following a power cycle where the drive heads may land on areas of the disk containing data, which could potentially cause data loss or mechanical damage. Firmware version HPD6 prevents this condition from occurring.
- o This firmware prevents a rare condition that may occur during a WRITE SAME command sequence that may result in incorrect data being written to the hard drive. The WRITE SAME command may be used during RAID ARRAY parity initialization.

#### **Problems Fixed for HPD6 (C):**

- o The component would fail to flash drive firmware on a server with a Trusted Platform Module (TPM) enabled when using the /tpmbypass switch.

#### **Problems Fixed for HPD6 (D):**

- o Component would fail to install drive firmware for drives present in a system configured with two or more external drive enclosures attached to an HP Host Bus Adapter H22x. The following message would be reported in the component log file - "Device appears more than once in tree". The drive firmware installation failure was not observed in configurations having only one external drive enclosure attached to an HP Host Bus Adapter H22x.

Component would cause an exception error when deployed on a computer with a fully qualified domain name greater than 40 characters in length.

### **Enhancements**

#### **Enhancements/New Features:**

- o The firmware component installer can now install the drive firmware successfully when the new HP ProLiant Smart Array HPCISS3 Controller Driver (**hpciss3.sys**) is running on the system being updated.
- o Added support for UEFI (Universal Extensible Firmware Interface) based servers.

#### **Enhancements/New Features for HPD6 (B):**

- o Updated the flash engine to standardize logging across all SAS drive components.
- o Enhanced logging capability to improve the details provided in the component log file.
- o Added support for Microsoft Windows Server 2016.

---

Online ROM Flash Component for Windows (x64) - MM0500FBFVQ and MM1000FBFVR Drives

Version: HPD9 (B) **(Recommended)**

Filename: cp029292.exe; cp029292.md5

### **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**
- **Customers who already installed firmware version HPD9 do not need to update to HPD9 (B).**

### **Fixes**

#### **Problems Fixed:**

- HPD9 firmware prevents a condition in which data fails to be committed to disk after the host issues a hard reset in a lab stress test environment with write cache enabled.

#### **Problems Fixed for HPD9 (B):**

- Component would fail to install drive firmware for drives present in a system configured with two or more external drive enclosures attached to an HP Host Bus Adapter H22x. The following message would be reported in the component log file - "Device appears more than once in tree". The drive firmware installation failure was not observed in configurations having only one external drive enclosure attached to an HP Host Bus Adapter H22x.
- Component would cause an exception error when deployed on a computer with a fully qualified domain name greater than 40 characters in length.

### **Enhancements**

#### **Enhancements/New Features:**

- Added support for Microsoft Windows Server 2016.

---

Online ROM Flash Component for Windows (x64) - MM1000FECVH Drives

Version: HPD2 (B) **(Recommended)**

Filename: cp029294.exe; cp029294.md5

### **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**
- **Customers who already installed firmware version HPD2 do not need to update to HPD2 (B).**

### **Fixes**

#### **Problems Fixed:**

- Drive self-test did not complete within the specified time.
- During a fully cached workload, SMART would report incorrect temperature values.
- The component would fail to flash drive firmware on a server with a Trusted Platform Module (TPM) enabled when using the /tpmbypass switch.

#### **Problems Fixed for HPD2 (B):**

- Component would fail to install drive firmware for drives present in a system configured with two or more external drive enclosures attached to an HP Host Bus Adapter H22x. The following message would be reported in the component log file - "Device appears more than once in tree". The drive firmware installation failure was not observed in configurations having only one external drive enclosure attached to an HP Host Bus Adapter H22x.
- Component would cause an exception error when deployed on a computer with a fully qualified domain name greater than 40 characters in length.

## **Enhancements**

#### **Enhancements/New Features:**

- Added servo improvements which reduce power consumption.
- Added support for Microsoft Windows Server 2016.

---

Online ROM Flash Component for Windows (x64) - MM1000JEFRB and MM2000JEFRC Drives

Version: HPD4 (C) **(Recommended)**

Filename: cp029296.exe; cp029296.md5

#### **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**
- **Customers who already installed firmware version HPD4 do not need to update to HPD4 (C).**

## **Fixes**

#### **Problems Fixed:**

- Version HPD4 prevents the potential for incorrect data to be written to the drive under extremely rare circumstances when the drive experiences a hard reset. This issue has only been observed in a rigorous test environment and has NOT been reported in a customer production environment.

#### **Problems Fixed for HPD4 (B):**

- The component would fail to flash drive firmware on a server with a Trusted Platform Module (TPM) enabled when using the /tpmbypass switch.

#### **Problems Fixed for HPD4 (C):**

- Component would fail to install drive firmware for drives present in a system configured with two or more external drive enclosures attached to an HP Host Bus Adapter H22x. The following message would be reported in the component log file - "Device appears more than once in tree". The drive firmware installation failure was not observed in configurations having only one external drive enclosure attached to an HP Host Bus Adapter H22x.

Component would cause an exception error when deployed on a computer with a fully qualified domain name greater than 40 characters in length.

## **Enhancements**

### **Enhancements/New Features:**

- Added support for Microsoft Windows Server 2016.

---

Online ROM Flash Component for Windows (x64) - MM1000JFJTH Drives

Version: HPD1 **(Recommended)**

Filename: cp030811.exe; cp030811.md5

### **Important Note!**

- **Online firmware flashing of drives attached to an HP Smart Array controller running in Zero Memory (ZM) mode or an HP ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux and Microsoft Windows environments. All other OSes would require an offline update using the SPP and HP SUM.**

## **Fixes**

### **Problems Fixed:**

- This firmware improves HDD reliability when HDDs are exposed to long periods of host inactivity that exceed 1 second. HDDs may become unresponsive when using HDD firmware prior to version HPD1. This firmware also contains a change which prevents an incorrect reassign status of a repaired sector from being logged.

## **Enhancements**

### **Enhancements/New Features:**

- Added support for Microsoft Windows Server 2016.

---

Online ROM Flash Component for Windows (x64) - MO0200FCTRN, MO0400FCTRP, and MO0800FCTRQ drives

Version: HPD5 (C) **(Recommended)**

Filename: cp030996.exe; cp030996.md5

### **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**
- **Customers who already installed firmware version HPD5 do not need to update to HPD5 (C).**

## **Fixes**

### **Problems Fixed:**

- An issue was found where the drive responded with a format error if power-cycled multiple times while in the process of un-mapping Logical Block Addresses (LBA). HPD5 firmware adds additional protection during power-cycles to ensure that the drive can recover its LBA to Physical Memory map.

### **Problems Fixed for HPD5 (B):**

- Component would fail to install drive firmware for drives present in a system configured with two or more external drive enclosures attached to an HP Host Bus Adapter H22x. The following message would be reported in the component log file - "Device appears more than once in tree". The drive firmware installation failure was not observed in configurations having only one external drive enclosure attached to an HP Host Bus Adapter H22x.
- Component would cause an exception error when deployed on a computer with a fully qualified domain name greater than 40 characters in length.

## **Enhancements**

### **Enhancements/New Features for HPD5 (C):**

- Added support for Microsoft Windows Server 2016.

---

Online ROM Flash Component for Windows (x64) - MO0200JDVET, MO0400JDVEU, MO0800JDVEV, EO0200JDVFA, EO0400JDVFB, and EO0800JDVFC Drives

Version: HPD2 (C) **(Optional)**

Filename: cp029299.exe; cp029299.md5

## **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**
- **Customers who already installed firmware version HPD2 do not need to update to HPD2 (C).**

## **Fixes**

### **Problems Fixed:**

- Solid-state drives (SSD) running firmware versions prior to HPD2 support Unmap commands. Application clients can make use of the Unmap command to specify certain LBAs do not contain vital data. The SSD can use the unmapped LBAs as needed. This feature will no longer be supported on these SSDs running firmware version HPD2 and later.

### **Problems Fixed for HPD2 (B):**

- The component would fail to flash drive firmware on a server with a Trusted Platform Module (TPM) enabled when using the /tpmypass switch.

### **Problems Fixed for HPD2 (C):**

- Component would fail to install drive firmware for drives present in a system configured with two or more external drive enclosures attached to an HP Host Bus Adapter H22x. The following message would be reported in the component log file - "Device appears more than once in tree". The drive firmware installation failure was not observed in configurations having only one external drive enclosure attached to an HP Host Bus Adapter H22x.

- Component would cause an exception error when deployed on a computer with a fully qualified domain name greater than 40 characters in length.

## **Enhancements**

### **Enhancements/New Features:**

- Added support for Microsoft Windows Server 2016.

---

Online ROM Flash Component for Windows (x64) - MO0200JEFNV, MO0400JEFPA, MO0800JFPB, MO1600JFPC, EO0200JFPD, EO0400JFPE, and EO0800JFPF Drives

Version: HPD1 (C) **(Critical)**

Filename: cp029300.exe; cp029300.md5

## **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**
- **Customers who already installed firmware version HPD1 do not need to update to HPD1 (C).**

## **Fixes**

### **Problem Fixed:**

- Incorrect data reads might occur when accessing unaligned 4k reads and the data read has zero content preceding customer data. For additional information please refer to the customer advisory #[c04650586](#)

### **Problems Fixed for HPD1 (B):**

- The component would fail to flash drive firmware on a server with a Trusted Platform Module (TPM) enabled when using the /tpmbypass switch.

### **Problems Fixed for HPD1 (C):**

- Component would fail to install drive firmware for drives present in a system configured with two or more external drive enclosures attached to an HP Host Bus Adapter H22x. The following message would be reported in the component log file - "Device appears more than once in tree". The drive firmware installation failure was not observed in configurations having only one external drive enclosure attached to an HP Host Bus Adapter H22x.
- Component would cause an exception error when deployed on a computer with a fully qualified domain name greater than 40 characters in length.

## **Enhancements**

### **Enhancements/New Features:**

- Added support for Microsoft Windows Server 2016.

---

Online ROM Flash Component for Windows (x64) - MO0400JFFCF, MO0800JFFCH, MO1600JFFCK, and MO3200JFFCL Drives

Version: HPD4 (B) **(Optional)**

### **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**
- **Customers who already installed firmware version HPD5 do not need to update to HPD4 (B).**

### **Fixes**

#### **Problems Fixed:**

- This firmware contains several low level maintenance fixes including debug data retrieval through read buffer. The fixes addressed events observed in a specialized lab testing environment, and are not expected to be experienced in customer use case scenarios.

### **Enhancements**

#### **Enhancements/New Features for HPD4 (B):**

- Added support for Microsoft Windows Server 2016.

---

Online ROM Flash Component for Windows (x64) - V00480JFDGT, V00960JFDGU, V01920JFDGV, and V03840JFDHA Drives

Version: HPD4 (B) **(Optional)**

Filename: cp030998.exe; cp030998.md5

### **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**
- **Customers who already installed firmware version HPD5 do not need to update to HPD4 (B).**

### **Fixes**

#### **Problems Fixed:**

- This firmware contains several low level maintenance fixes including debug data retrieval through read buffer. The fixes addressed events observed in a specialized lab testing environment, and are not expected to be experienced in customer use case scenarios.

### **Enhancements**

#### **Enhancements/New Features for HPD4 (B):**

- Added support for Microsoft Windows Server 2016.

---

Online ROM Flash Component for Windows (x64) - V01920JEUQQ Drives

Version: HPD1 (C) **(Critical)**

Filename: cp029305.exe; cp029305.md5

### **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSES would require an offline update using the SPP and HP SUM.**
- **Customers who already installed firmware version HPD1 do not need to update to HPD1 (C).**

### **Fixes**

#### **Problem Fixed:**

- Incorrect data reads might occur when accessing unaligned 4k reads and the data read has zero content preceding customer data. (Additional information can be obtained for this issue in Customer Advisory [c04650586](#))

#### **Problems Fixed for HPD1 (B):**

- The component would fail to flash drive firmware on a server with a Trusted Platform Module (TPM) enabled when using the /tpmbypass switch.

#### **Problems Fixed for HPD1 (C):**

- Component would fail to install drive firmware for drives present in a system configured with two or more external drive enclosures attached to an HP Host Bus Adapter H22x. The following message would be reported in the component log file - "Device appears more than once in tree". The drive firmware installation failure was not observed in configurations having only one external drive enclosure attached to an HP Host Bus Adapter H22x.
- Component would cause an exception error when deployed on a computer with a fully qualified domain name greater than 40 characters in length.

### **Enhancements**

#### **Enhancements/New Features:**

- Added support for Microsoft Windows Server 2016.

---

Online ROM Flash Component for Windows - DG0146FARVU, DG0300FARVV, DG0146BAMYQ, DG0300BAMYR, EG0146FAWJC, and EG0300FAWJD Drives

Version: HPDG (B) **(Critical)**

Filename: cp020424.exe; cp020424.md5

### **Important Note!**

- **Online firmware flashing of drives attached to an HP Smart Array controller running in Zero Memory (ZM) mode or an HP ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux and Microsoft Windows environments. All other OSES would require an offline update using the SPP and HP SUM.**
- **Customers who already installed firmware version HPDG do not need to update to HPDG(B).**



## Fixes

### Problems Fixed:

- o This firmware corrects a possible condition in which stale data might be written to the disk. This results in unexpected data being returned in subsequent requests. This data issue has been duplicated in laboratory firmware stress tests.

## Enhancements

### Enhancements/New Features:

- o The firmware component installer can now install the drive firmware successfully when the new HP ProLiant Smart Array HPCISS3 Controller Driver (**hpciss3.sys**) is running on the system being updated.

---

Online ROM Flash Component for Windows - DH0072FAQRD, DH0146FAQRE, EH0146FAWJB, and EH0072FAWJA Drives

Version: HPDK **(Recommended)**

Filename: cp028852.exe; cp028852.md5

### Important Note!

- o **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- o **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**

## Fixes

### Problems Fixed:

- o HP ProLiant servers would power down due a hard drive overtemp condition that was falsely reported. Hard disk drive firmware HPDK resolves this issue.

---

Online ROM Flash Component for Windows - EF0300FARMU, EF0450FARMV, EF0600FARNA drives

Version: HPD9 **(Recommended)**

Filename: cp030801.exe; cp030801.md5

### Important Note!

- **Online firmware flashing of drives attached to an HP Smart Array controller running in Zero Memory (ZM) mode or an HP ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux and Microsoft Windows environments. All other OSes would require an offline update using the SPP and HP SUM.**

## Fixes

### Problems Fixed:

- This firmware contains a change which prevents an incorrect reassign status of a repaired sector from being logged.
-

Online ROM Flash Component for Windows - EF0300FATFD, EF0450FATFE, and EF0600FATFF Drives

Version: HPDB (B) **(Critical)**

Filename: cp020433.exe; cp020433.md5

### **Important Note!**

- **Online firmware flashing of drives attached to an HP Smart Array controller running in Zero Memory (ZM) mode or an HP ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux and Microsoft Windows environments. All other OSes would require an offline update using the SPP and HP SUM.**
- **Customers who already installed firmware version HPDB do not need to update to HPDB(B).**

### **Fixes**

#### **Problems Fixed:**

- This firmware corrects a possible condition in which stale data might be written to the disk. This results in unexpected data being returned in subsequent requests. This data issue has been duplicated in laboratory firmware stress tests.

### **Enhancements**

#### **Enhancements/New Features:**

- The firmware component installer can now install the drive firmware successfully when the new HP ProLiant Smart Array HPCISS3 Controller Driver (**hpciss3.sys**) is running on the system being updated.

---

Online ROM Flash Component for Windows - EG0300FBDBR, EG0450FBDBT and EG0600FBDBU Drives

Version: HPDA (B) **(Critical)**

Filename: cp020307.exe; cp020307.md5

### **Important Note!**

- **Online firmware flashing of drives attached to an HP Smart Array controller running in Zero Memory (ZM) mode or an HP ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**
- **Customers who already installed firmware version HPDA do not need to update to HPDA(B).**

### **Prerequisites**

- **Minimum firmware required - HPD7. HPDA drive firmware will fail when downgrading to versions below HPD7.**

### **Fixes**

#### **Firmware Dependency:**

- **Minimum firmware required - HPD7. HPDA drive firmware will fail when downgrading to versions below HPD7.**

#### **Problems Fixed:**

- This firmware corrects a possible condition in which stale data might be written to the disk. This results in unexpected data being returned in subsequent requests. This data issue has been duplicated in laboratory firmware stress tests.
-

Online ROM Flash Component for Windows - EG0300FBDSP, EG0450FBDSQ, and EG0600FBDSR drives

Version: HPD6 (B) **(Optional)**

Filename: cp020435.exe; cp020435.md5

### **Important Note!**

- **Online firmware flashing of drives attached to an HP Smart Array controller running in Zero Memory (ZM) mode or an HP ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux and Microsoft Windows environments. All other OSES would require an offline update using the SPP and HP SUM.**
- **Customers who already installed firmware version HPD6 do not need to update to HPD6(B).**

### **Fixes**

#### **Problems Fixed:**

- This firmware reduces the possibility of the controller and drive not properly negotiating link signaling, resulting in the controller not being able to identify a drive attached to a particular port/slot during system boot up. This firmware improves signal quality between the drive and the controller.

### **Enhancements**

#### **Enhancements/New Features:**

- The firmware component installer can now install the drive firmware successfully when the new HP ProLiant Smart Array HPCISS33 Controller Driver (**hpciss3.sys**) is running on the system being updated.

---

Online ROM Flash Component for Windows - EG0300FBLSE, EG0450FBLSF, EG0600FBLSH, and EG0900FBLSK drives

Version: HPD8 **(Recommended)**

Filename: cp025755.exe

### **Fixes**

#### **Problems Fixed:**

- HP ProLiant servers would power down due a hard drive overtemp condition that was falsely reported. Hard disk drive firmware HPD8 resolves this issue.

### **Enhancements**

#### **Enhancements/New Features:**

None

---

Online ROM Flash Component for Windows - EG0300FBVFL, EG0450FBVFM, EG0600FBVFP, and EG0900FBVFQ Drives

Version: HPDE **(Recommended)**

Filename: cp028191.exe; cp028191.md5

### **Important Note!**

- **Online firmware flashing of drives attached to an HP Smart Array controller running in Zero Memory (ZM) mode or an HP ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these**

configurations.

- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**

## Fixes

### **Problems Fixed:**

- Drive self-test did not complete within the specified time.
- During a fully cached workload, SMART would report incorrect temperature values.

## Enhancements

### **Enhancements/New Features:**

- Added servo improvements which reduce power consumption.

---

Online ROM Flash Component for Windows - EG0300FCVBF, EG0450FCVBH, EG0600FCVBK, and EG0900FCVBL Drives

Version: HPD9 **(Recommended)**

Filename: cp028285.exe; cp028285.md5

## Important Note!

- **Online firmware flashing of drives attached to an HP Smart Array controller running in Zero Memory (ZM) mode or an HP ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**

## Fixes

### **Problems Fixed:**

- Drives could become unresponsive due to unexpected responses from the serial port diagnostic debug connection.

---

Online ROM Flash Component for Windows - EG0900FDJYR and EG1200FDJYT Drives

Version: HPD4 **(Recommended)**

Filename: cp027736.exe; cp027736.md5

## Important Note!

- **Online firmware flashing of drives attached to an HP Smart Array controller running in Zero Memory (ZM) mode or an HP ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**

## Fixes

### **Problems Fixed:**

- Prevents the potential for incorrect data from being “read from” or “written to” the drive under extremely rare circumstances where the drive experiences consecutive error recoveries during a background scan and the Error Correction Code (ECC) fails. This issue has only been observed in a rigorous test environment and has NOT been reported in a customer production environment.

---

Online ROM Flash Component for Windows - EG1200FDNJT and EG1200FCVBQ Drives

Version: HPD8 **(Recommended)**

Filename: cp028210.exe; cp028210.md5

### **Important Note!**

- **Online firmware flashing of drives attached to an HP Smart Array controller running in Zero Memory (ZM) mode or an HP ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSES would require an offline update using the SPP and HP SUM.**

### **Fixes**

#### **Problems Fixed:**

- Drive self-test did not complete within the specified time.
- During a fully cached workload, SMART would report incorrect temperature values.

### **Enhancements**

#### **Enhancements/New Features:**

- Added servo improvements which reduce power consumption.

---

Online ROM Flash Component for Windows - EH0072FARUA and EH0146FARUB drives

Version: HPD9 (B) **(Optional)**

Filename: cp020437.exe; cp020437.md5

### **Important Note!**

- **Online firmware flashing of drives attached to an HP Smart Array controller running in Zero Memory (ZM) mode or an HP ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux and Microsoft Windows environments. All other OSES would require an offline update using the SPP and HP SUM.**
- **Customers who already installed firmware version HPD9 do not need to update to HPD9(B).**

### **Fixes**

#### **Problems Fixed:**

- This firmware reduces the possibility of the controller and drive not properly negotiating link signaling, resulting in the controller not being able to identify a drive attached to a particular port/slot during system boot up. This firmware improves signal quality between the drive and the controller.

## **Enhancements**

### **Enhancements/New Features:**

- The firmware component installer can now install the drive firmware successfully when the new HP ProLiant Smart Array HPCISS33 Controller Driver (**hpcisss3.sys**) is running on the system being updated.

---

Online ROM Flash Component for Windows - EH0072FARWC and EH0146FARWD Drives

Version: HPDD (B) **(Critical)**

Filename: cp020438.exe; cp020438.md5

### **Important Note!**

- **Online firmware flashing of drives attached to an HP Smart Array controller running in Zero Memory (ZM) mode or an HP ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux and Microsoft Windows environments. All other OSes would require an offline update using the SPP and HP SUM.**
- **Customers who already installed firmware version HPDD do not need to update to HPDD(B).**

## **Fixes**

### **Problems Fixed:**

- This firmware corrects a possible condition in which stale data might be written to the disk. This results in unexpected data being returned in subsequent requests. This data issue has been duplicated in laboratory firmware stress tests.

## **Enhancements**

### **Enhancements/New Features:**

- The firmware component installer can now install the drive firmware successfully when the new HP ProLiant Smart Array HPCISS33 Controller Driver (**hpcisss3.sys**) is running on the system being updated.

---

Online ROM Flash Component for Windows - EH0146FBQDC and EH0300FBQDD drives

Version: HPD5 **(Recommended)**

Filename: cp027318.exe; cp027318.md5

### **Important Note!**

- **Online firmware flashing of drives attached to an HP Smart Array controller running in Zero Memory (ZM) mode or an HP ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**

## **Fixes**

### **Problems Fixed:**

- HP ProLiant servers would power down due a hard drive overtemp condition that was falsely reported. Hard disk drive firmware HPD5 resolves this issue.

---

Online ROM Flash Component for Windows - EH0146FCBVB and EH0300FCBVC drives

Version: HPD8 **(Recommended)**

Filename: cp030797.exe; cp030797.md5

### **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**

### **Fixes**

#### **Problems Fixed:**

- Reliability enhancement for applications that write data to a narrow range of tracks.
- New SMART trip when device senses an abnormal change in the motor electric current.

---

Online ROM Flash Component for Windows - E00200FBRVV, MO0200FBRWB, E00400FBRWA, MO0400FBRWC, and MO0800FBRWD drives

Version: HPD9 (B) **(Recommended)**

Filename: cp020440.exe; cp020440.md5

### **Important Note!**

- **Online firmware flashing of drives attached to an HP Smart Array controller running in Zero Memory (ZM) mode or an HP ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux and Microsoft Windows environments. All other OSes would require an offline update using the SPP and HP SUM.**
- **Customers who already installed firmware version HPD9 do not need to update to HPD9(B).**

### **Fixes**

#### **Problems Fixed:**

- In previous firmware revisions when the solid state drive was issued a Report Support Operation Code (RSOC) command (A3h) and the reporting options field was set to 001, the drive incorrectly responded with 05/24/00 indicating that the RSOC command was not supported. The error was logged in the system log files. The drive should have communicated non-support using the Command Data Parameter (CDP) format. The firmware now complies with the RSOC industry standard specification.

### **Enhancements**

#### **Enhancements/New Features:**

- The firmware component installer can now install the drive firmware successfully when the new HP ProLiant Smart Array HPCISS3 Controller Driver (**hpciss3.sys**) is running on the system being updated.

---

Online ROM Flash Component for Windows - MB1000FAMYU and MB2000FAMYV Drives

Version: HPD7 (B) **(Critical)**

Filename: cp020455.exe; cp020455.md5

### **Important Note!**

- **Online firmware flashing of drives attached to an HP Smart Array controller running in Zero Memory (ZM) mode or an HP ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux and Microsoft Windows environments. All other OSes would require an offline update using the SPP and HP SUM.**
- **Customers who already installed firmware version HPD7 do not need to update to HPD7(B).**

### **Fixes**

#### **Problem Fixed:**

- This firmware prevents a rare condition that may occur during a WRITE SAME command sequence that may result in incorrect data being written to the hard drive. The WRITE SAME command may be used during RAID ARRAY parity initialization.

### **Enhancements**

#### **Enhancements/New Features:**

- The firmware component installer can now install the drive firmware successfully when the new HP ProLiant Smart Array HPCISS3 Controller Driver (**hpciss3.sys**) is running on the system being updated.

---

Online ROM Flash Component for Windows - MB1000FBZPL and MB2000FBZPN drives

Version: HPD4 **(Recommended)**

Filename: cp028674.exe; cp028674.md5

### **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**

### **Fixes**

#### **Problems Fixed:**

- ProLiant servers would power down due a hard drive over temperature condition that was falsely reported. HPD4 firmware resolves this issue.

---

Online ROM Flash Component for Windows - MB1000FCWDE, MB2000FCWDF, MB3000FCWDH, and MB4000FCWDK Drives

Version: HPDA **(Recommended)**

Filename: cp030190.exe; cp030190.md5

### **Important Note!**



- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**

## Fixes

### **Problems Fixed:**

- This firmware improves HDD reliability when HDDs are exposed to long periods of host inactivity that exceed 1 second. HDDs may become unresponsive when using HDD firmware prior to version HPDA.
- This firmware also contains a change which prevents an incorrect reassign status of a repaired sector from being logged.

---

Online ROM Flash Component for Windows - MB1000FCWPP, MB2000FCVBV, MB3000FCVCA, and MB4000FCVCB Drives

Version: HPD2 **(Recommended)**

Filename: cp022639.exe; cp022639.md5

## Important Note!

- **Online firmware flashing of drives attached to an HP Smart Array controller running in Zero Memory (ZM) mode or an HP ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**

## Enhancements

### **Enhancements/New Features:**

- This firmware improves reliability by modifying the pivot bearing grease wear leveling algorithm, which if not implemented, could result in an increased drive failure rate for specific usage applications (eg, very long periods of small range seeks).
- Enhancements also include performance improvements.

---

Online ROM Flash Component for Windows - MB2000FBUCL and MB3000FBUCN drives

Version: HPDA **(Critical)**

Filename: cp021545.exe; cp021545.md5

## Important Note!

- **Online firmware flashing of drives attached to an HP Smart Array controller running in Zero Memory (ZM) mode or an HP ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**

## Fixes

### **Problems Fixed:**

- This firmware improves background scans for media robustness, and also corrects a laboratory induced rare condition that could result in the disk not being updated with the latest cache data.

---

Online ROM Flash Component for Windows - MB2000FCQPF and MB3000FBNWV Drives

Version: HPD9 **(Recommended)**

Filename: cp030828.exe; cp030828.md5

### **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**

### **Fixes**

#### **Problems Fixed:**

- HP ProLiant servers would power down due a hard drive overtemp condition that was falsely reported. Hard disk drive firmware HPD9 resolves this issue.

---

Online ROM Flash Component for Windows - MM0500FAMYT Drives

Version: HPD6 (B) **(Critical)**

Filename: cp020466.exe; cp020466.md5

### **Important Note!**

- **Online firmware flashing of drives attached to an HP Smart Array controller running in Zero Memory (ZM) mode or an HP ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux and Microsoft Windows environments. All other OSes would require an offline update using the SPP and HP SUM.**
- **Customers who already installed firmware version HPD6 do not need to update to HPD6(B).**

### **Fixes**

#### **Problem Fixed:**

- After long term use of the HDD, a rare condition might occur following a power cycle where the drive heads may land on areas of the disk containing data, which could potentially cause data loss or mechanical damage. Firmware version HPD6 prevents this condition from occurring.
- This firmware prevents a rare condition that may occur during a WRITE SAME command sequence that may result in incorrect data being written to the hard drive. The WRITE SAME command may be used during RAID ARRAY parity initialization.

### **Enhancements**

#### **Enhancements/New Features:**

- The firmware component installer can now install the drive firmware successfully when the new HP ProLiant Smart Array HPCISS3

Controller Driver (**hpciss3.sys**) is running on the system being updated.

---

Online ROM Flash Component for Windows - MM0500FBFVQ and MM1000FBFVR Drives

Version: HPD9 (**Recommended**)

Filename: cp028681.exe; cp028681.md5

#### **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**

#### **Fixes**

##### **Problems Fixed:**

- HPD9 firmware prevents a condition in which data fails to be committed to disk after the host issues a hard reset in a lab stress test environment with write cache enabled.

---

Online ROM Flash Component for Windows - MO0200FCTRN, MO0400FCTRP, and MO0800FCTRQ Drives

Version: HPD5 (**Recommended**)

Filename: cp029640.exe; cp029640.md5

#### **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**

#### **Fixes**

##### **Problems Fixed:**

- An issue was found where the drive responded with a format error if power-cycled multiple times while in the process of un-mapping Logical Block Addresses (LBA). HPD5 firmware adds additional protection during power-cycles to ensure that the drive can recover its LBA to Physical Memory map.

---

Supplemental Update / Online ROM Flash Component for Linux - DG0146FARVU, DG0300FARVV, DG0146BAMYQ, DG0300BAMYR, EG0146FAWJC, and EG0300FAWJD Drives

Version: HPDG (C) (**Critical**)

Filename: CP022308.md5; CP022308.scexe

#### **Important Note!**

- **Online firmware flashing of drives attached to an HP Smart Array controller running in Zero Memory (ZM) mode or an HP ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these**

configurations.

- o **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSES would require an offline update using the SPP and HP SUM.**
- o **Customers who already installed firmware version HPDG do not need to update to HPDG(C).**

## **Fixes**

### **Problems Fixed:**

- o This firmware corrects a possible condition in which stale data might be written to the disk. This results in unexpected data being returned in subsequent requests. This data issue has been duplicated in laboratory firmware stress tests.
- o Flashing drives connected behind an HP H2xx Host Bus Adapter (HBA) no longer causes an interrupt resulting in drive firmware installation failures.

## **Enhancements**

### **Enhancements/New Features:**

- o Added support for UEFI (Universal Extensible Firmware Interface) based servers.

---

Supplemental Update / Online ROM Flash Component for Linux - EG0300FBDBR, EG0450FBDBT and EG0600FBDBU Drives

Version: HPDA (C) **(Critical)**

Filename: CP022312.md5; CP022312.scexe

## **Important Note!**

- o **Online firmware flashing of drives attached to an HP Smart Array controller running in Zero Memory (ZM) mode or an HP ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- o **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSES would require an offline update using the SPP and HP SUM.**
- o **Customers who already installed firmware version HPDA do not need to update to HPDA(C).**

## **Prerequisites**

- o **Minimum firmware required - HPD7. HPDA drive firmware will fail when downgrading to versions below HPD7.**

## **Fixes**

### **Firmware Dependency:**

- o **Minimum firmware required - HPD7. HPDA drive firmware will fail when downgrading to versions below HPD7.**

### **Problems Fixed:**

- o This firmware corrects a possible condition in which stale data might be written to the disk. This results in unexpected data being returned in subsequent requests. This data issue has been duplicated in laboratory firmware stress tests.

## **Enhancements**

### **Enhancements/New Features:**

- o Added support for UEFI (Universal Extensible Firmware Interface) based servers.

---

Supplemental Update / Online ROM Flash Component for Linux - EG0300FBDSQ, EG0450FBDSQ, and EG0600FBDSR drives

Version: HPD6 (C) **(Optional)**

Filename: CP022313.md5; CP022313.scexe

### **Important Note!**

- **Online firmware flashing of drives attached to an HP Smart Array controller running in Zero Memory (ZM) mode or an HP ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSES would require an offline update using the SPP and HP SUM.**
- **Customers who already installed firmware version HPD6 do not need to update to HPD6(C).**

### **Fixes**

#### **Problems Fixed:**

- This firmware reduces the possibility of the controller and drive not properly negotiating link signaling, resulting in the controller not being able to identify a drive attached to a particular port/slot during system boot up. This firmware improves signal quality between the drive and the controller.
- Flashing drives connected behind an HP H2xx Host Bus Adapter (HBA) no longer causes an interrupt resulting in drive firmware installation failures.

### **Enhancements**

#### **Enhancements/New Features:**

- Added support for UEFI (Universal Extensible Firmware Interface) based servers.

---

Supplemental Update / Online ROM Flash Component for Linux - EG0300FBLSE, EG0450FBLSF, EG0600FBLSH, and EG0900FBLSK drives

Version: HPD8 **(Recommended)**

Filename: rpm/RPMS/i386/hp-firmware-hdd-815e5e101b-HPD8-1.1.i386.rpm

### **Fixes**

#### **Problems Fixed:**

- HP ProLiant servers would power down due a hard drive overtemp condition that was falsely reported. Hard disk drive firmware HPD8 resolves this issue.

---

Supplemental Update / Online ROM Flash Component for Linux - EG0300FBVFL, EG0450FBVFM, EG0600FBVFP, and EG0900FBVFQ Drives

Version: HPDE **(Recommended)**

Filename: rpm/RPMS/i386/hp-firmware-hdd-b94f345c05-HPDE-1.1.i386.rpm

### **Important Note!**

- **Online firmware flashing of drives attached to an HP Smart Array controller running in Zero Memory (ZM) mode or an HP ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSES would require an offline update using the SPP and HP SUM.**

### **Fixes**

### Problems Fixed:

- Drive self-test did not complete within the specified time.
- During a fully cached workload, SMART would report incorrect temperature values.

### Enhancements

#### Enhancements/New Features:

- Added servo improvements which reduce power consumption.

---

Supplemental Update / Online ROM Flash Component for Linux - EG0900FDJYR and EG1200FDJYT Drives

Version: HPD4 **(Recommended)**

Filename: rpm/RPMS/i386/hp-firmware-hdd-7cfa9118b1-HPD4-1.1.i386.rpm

### Important Note!

- **Online firmware flashing of drives attached to an HP Smart Array controller running in Zero Memory (ZM) mode or an HP ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**

### Fixes

#### Problems Fixed:

- Prevents the potential for incorrect data from being "read from" or "written to" the drive under extremely rare circumstances where the drive experiences consecutive error recoveries during a background scan and the Error Correction Code (ECC) fails. This issue has only been observed in a rigorous test environment and has NOT been reported in a customer production environment.

---

Supplemental Update / Online ROM Flash Component for Linux - EG1200FDNJT and EG1200FCVBQ Drives

Version: HPD8 **(Recommended)**

Filename: rpm/RPMS/i386/hp-firmware-hdd-33aee979c2-HPD8-1.1.i386.rpm

### Important Note!

- **Online firmware flashing of drives attached to an HP Smart Array controller running in Zero Memory (ZM) mode or an HP ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**

### Fixes

#### Problems Fixed:

- Drive self-test did not complete within the specified time.
- During a fully cached workload, SMART would report incorrect temperature values.

## Enhancements

### Enhancements/New Features:

- Added servo improvements which reduce power consumption.

---

Supplemental Update / Online ROM Flash Component for Linux - EH0072FARUA and EH0146FARUB drives

Version: HPD9 (C) **(Optional)**

Filename: CP022318.md5; CP022318.sceexe

### **Important Note!**

- **Online firmware flashing of drives attached to an HP Smart Array controller running in Zero Memory (ZM) mode or an HP ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSES would require an offline update using the SPP and HP SUM.**
- **Customers who already installed firmware version HPD9 do not need to update to HPD9(C).**

## **Fixes**

### **Problems Fixed:**

- This firmware reduces the possibility of the controller and drive not properly negotiating link signaling, resulting in the controller not being able to identify a drive attached to a particular port/slot during system boot up. This firmware improves signal quality between the drive and the controller.
- Flashing drives connected behind an HP H2xx Host Bus Adapter (HBA) no longer causes an interrupt resulting in drive firmware installation failures.

## **Enhancements**

### **Enhancements/New Features:**

- Added support for UEFI (Universal Extensible Firmware Interface) based servers.

---

Supplemental Update / Online ROM Flash Component for Linux - EH0146FBQDC and EH0300FBQDD drives

Version: HPD5 **(Recommended)**

Filename: rpm/RPMS/i386/hp-firmware-hdd-1ec3c02013-HPD5-1.1.i386.rpm

### **Important Note!**

- **Online firmware flashing of drives attached to an HP Smart Array controller running in Zero Memory (ZM) mode or an HP ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSES would require an offline update using the SPP and HP SUM.**

## **Fixes**

### **Problems Fixed:**

- HP ProLiant servers would power down due a hard drive overtemp condition that was falsely reported. Hard disk drive firmware HPD5 resolves this issue.

---

Supplemental Update / Online ROM Flash Component for Linux - EH0146FCBVB and EH0300FCBVC drives

Version: HPD8 **(Recommended)**

Filename: rpm/RPMS/i386/hp-firmware-hdd-74df2d6c5c-HPD8-1.1.i386.rpm

### **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**

### **Fixes**

#### **Problems Fixed:**

- Reliability enhancement for applications that write data to a narrow range of tracks.
- New SMART trip when device senses an abnormal change in the motor electric current.

---

Supplemental Update / Online ROM Flash Component for Linux - E00200FBRVV, MO0200FBRWB, E00400FBRWA, MO0400FBRWC, and MO0800FBRWD drives

Version: HPD9 (C) **(Optional)**

Filename: CP022322.md5; CP022322.scexe

### **Important Note!**

- **Online firmware flashing of drives attached to an HP Smart Array controller running in Zero Memory (ZM) mode or an HP ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**
- **Customers who already installed firmware version HPD9 do not need to update to HPD9(C).**

### **Fixes**

#### **Problems Fixed:**

- In previous firmware revisions when the solid state drive was issued a Report Support Operation Code (RSOC) command (A3h) and the reporting options field was set to 001, the drive incorrectly responded with 05/24/00 indicating that the RSOC command was not supported. The error was logged in the system log files. The drive should have communicated non-support using the Command Data Parameter (CDP) format. The firmware now complies with the RSOC industry standard specification.
- Flashing drives connected behind an HP H2xx Host Bus Adapter (HBA) no longer causes an interrupt resulting in drive firmware installation failures.

### **Enhancements**

#### **Enhancements/New Features:**

- Added support for UEFI (Universal Extensible Firmware Interface) based servers.



---

Supplemental Update / Online ROM Flash Component for Linux - MB1000FAMYU and MB2000FAMYV Drives

Version: HPD7 (D) **(Critical)**

Filename: CPO22325.md5; CPO22325.scexe

### **Important Note!**

- **Online firmware flashing of drives attached to an HP Smart Array controller running in Zero Memory (ZM) mode or an HP ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**
- **Customers who already installed firmware version HPD7 do not need to update to HPD7(D).**

### **Fixes**

#### **Problem Fixed:**

- This firmware prevents a rare condition that may occur during a WRITE SAME command sequence that may result in incorrect data being written to the hard drive. The WRITE SAME command may be used during RAID ARRAY parity initialization.
- HPD7 (B) resolves an issue with offline flashing where the component would time out during the upgrade process.
- Flashing drives connected behind an HP H2xx Host Bus Adapter (HBA) no longer causes an interrupt resulting in drive firmware installation failures.

### **Enhancements**

#### **Enhancements/New Features:**

- Added support for UEFI (Universal Extensible Firmware Interface) based servers.

---

Supplemental Update / Online ROM Flash Component for Linux - MB1000FBZPL and MB2000FBZPN drives

Version: HPD4 **(Recommended)**

Filename: rpm/RPMS/i386/hp-firmware-hdd-b33fedbbdf-HPD4-1.1.i386.rpm

### **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**

### **Fixes**

#### **Problems Fixed:**

- ProLiant servers would power down due a hard drive over temperature condition that was falsely reported. HPD4 firmware resolves this issue.

---

Supplemental Update / Online ROM Flash Component for Linux - MB1000FCWPP, MB2000FCVBV, MB3000FCVCA, and MB4000FCVCB Drives

Version: HPD2 **(Recommended)**

### **Important Note!**

- **Online firmware flashing of drives attached to an HP Smart Array controller running in Zero Memory (ZM) mode or an HP ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSES would require an offline update using the SPP and HP SUM.**

### **Enhancements**

#### **Enhancements/New Features:**

- This firmware improves reliability by modifying the pivot bearing grease wear leveling algorithm, which if not implemented, could result in an increased drive failure rate for specific usage applications (eg, very long periods of small range seeks).
- Enhancements also include performance improvements.

---

Supplemental Update / Online ROM Flash Component for Linux - MM0500FAMYT Drives

Version: HPD6 (C) **(Critical)**

Filename: CP022338.md5; CP022338.scexe

### **Important Note!**

- **Online firmware flashing of drives attached to an HP Smart Array controller running in Zero Memory (ZM) mode or an HP ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSES would require an offline update using the SPP and HP SUM.**
- **Customers who already installed firmware version HPD6 do not need to update to HPD6(C).**

### **Fixes**

#### **Problem Fixed:**

- After long term use of the HDD, a rare condition might occur following a power cycle where the drive heads may land on areas of the disk containing data, which could potentially cause data loss or mechanical damage. Firmware version HPD6 prevents this condition from occurring.
- This firmware prevents a rare condition that may occur during a WRITE SAME command sequence that may result in incorrect data being written to the hard drive. The WRITE SAME command may be used during RAID ARRAY parity initialization.
- Flashing drives connected behind an HP H2xx Host Bus Adapter (HBA) no longer causes an interrupt resulting in drive firmware installation failures.

### **Enhancements**

#### **Enhancements/New Features:**

- Added support for UEFI (Universal Extensible Firmware Interface) based servers.

---

Supplemental Update / Online ROM Flash Component for Linux - MM0500FBFVQ and MM1000FBFVR Drives

Version: HPD9 **(Recommended)**

### **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSES would require an offline update using the SPP and HP SUM.**

### **Fixes**

#### **Problems Fixed:**

- HPD9 firmware prevents a condition in which data fails to be committed to disk after the host issues a hard reset in a lab stress test environment with write cache enabled.

---

Supplemental Update / Online ROM Flash Component for Linux - MO0200FCTRN, MO0400FCTRP, and MO0800FCTRQ Drives

Version: HPD5 **(Recommended)**

Filename: rpm/RPMS/i386/hp-firmware-hdd-37893275d3-HPD5-1.1.i386.rpm

### **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSES would require an offline update using the SPP and HP SUM.**

### **Fixes**

#### **Problems Fixed:**

- An issue was found where the drive responded with a format error if power-cycled multiple times while in the process of un-mapping Logical Block Addresses (LBA). HPD5 firmware adds additional protection during power-cycles to ensure that the drive can recover its LBA to Physical Memory map.

---

Supplemental Update / Online ROM Flash Component for Linux (x64) - DG0146FARVU, DG0300FARVV, DG0146BAMYQ, DG0300BAMYR, EG0146FAWJC, and EG0300FAWJD Drives

Version: HPDG (C) **(Critical)**

Filename: rpm/RPMS/x86\_64/hp-firmware-hdd-fdfb5070cf-HPDG-3.1.x86\_64.rpm

### **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSES would require an offline update using the SPP and HP SUM.**
- **Customers who already installed firmware version HPDG do not need to update to HPDG (C).**

## Fixes

### **Problems Fixed:**

- This firmware corrects a possible condition in which stale data might be written to the disk. This results in unexpected data being returned in subsequent requests. This data issue has been duplicated in laboratory firmware stress tests.
- Flashing drives connected behind an HP H2xx Host Bus Adapter (HBA) no longer causes an interrupt resulting in drive firmware installation failures.

### **Problems Fixed for HPDG (C):**

- Component would fail to install drive firmware for drives present in a system configured with two or more external drive enclosures attached to an HP Host Bus Adapter H22x. The following message would be reported in the component log file - "Device appears more than once in tree". The drive firmware installation failure was not observed in configurations having only one external drive enclosure attached to an HP Host Bus Adapter H22x.
- Component fails to update the firmware for drives connected behind an HP Smart Array P431 controller. Component reports the firmware update was successful. However, after a power cycle, the firmware version remains unchanged.

## Enhancements

### **Enhancements/New Features:**

- Added support for UEFI (Universal Extensible Firmware Interface) based servers.

### **Enhancements/New Features for HPDG (B):**

- Updated the flash engine to standardize logging across all SAS drive components.
- Enhanced logging capability to improve the details provided in the component log file.

---

Supplemental Update / Online ROM Flash Component for Linux (x64) - EG0300FBDBR, EG0450FBDBT and EG0600FBDBU Drives

Version: HPDA (C) **(Critical)**

Filename: rpm/RPMS/x86\_64/hp-firmware-hdd-f1eafd9715-HPDA-3.1.x86\_64.rpm

## Important Note!

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**
- **Customers who already installed firmware version HPDA do not need to update to HPDA (C).**

## Prerequisites

- **Minimum firmware required - HPD7. HPDA drive firmware will fail when downgrading to versions below HPD7.**

## Fixes

### **Firmware Dependency:**

- **Minimum firmware required - HPD7. HPDA drive firmware will fail when downgrading to versions below HPD7.**

### **Problems Fixed:**

- This firmware corrects a possible condition in which stale data might be written to the disk. This results in unexpected data being returned in subsequent requests. This data issue has been duplicated in laboratory firmware stress tests.

#### **Problems Fixed for HPDA (C):**

- Component would fail to install drive firmware for drives present in a system configured with two or more external drive enclosures attached to an HP Host Bus Adapter H22x. The following message would be reported in the component log file - "Device appears more than once in tree". The drive firmware installation failure was not observed in configurations having only one external drive enclosure attached to an HP Host Bus Adapter H22x.
- Component fails to update the firmware for drives connected behind an HP Smart Array P431 controller. Component reports the firmware update was successful. However, after a power cycle, the firmware version remains unchanged.

#### **Enhancements**

##### **Enhancements/New Features:**

- Added support for UEFI (Universal Extensible Firmware Interface) based servers.

##### **Enhancements/New Features for HPDA (B):**

- Updated the flash engine to standardize logging across all SAS drive components.
- Enhanced logging capability to improve the details provided in the component log file.

---

Supplemental Update / Online ROM Flash Component for Linux (x64) - EG0600JETKA, EG0900JETKB, and EG1200JETKC Drives

Version: HPD4 (**Recommended**)

Filename: rpm/RPMS/x86\_64/hp-firmware-hdd-7505dfb5ae-HPD4-1.1.x86\_64.rpm

#### **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**

#### **Enhancements**

##### **Enhancements/New Features:**

- Reliability enhancement for applications that write data to a narrow range of tracks.

---

Supplemental Update / Online ROM Flash Component for Linux (x64) - MM1000FECVH Drives

Version: HPD2 (B) (**Recommended**)

Filename: rpm/RPMS/x86\_64/hp-firmware-hdd-eb0a0d48e5-HPD2-2.1.x86\_64.rpm

#### **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**
- **Customers who already installed firmware version HPD2 do not need to update to HPD2 (B).**

## Fixes

### **Problems Fixed:**

- Drive self-test did not complete within the specified time.
- During a fully cached workload, SMART would report incorrect temperature values.

### **Problems Fixed for HPD2 (B):**

- Component would fail to install drive firmware for drives present in a system configured with two or more external drive enclosures attached to an HP Host Bus Adapter H22x. The following message would be reported in the component log file - "Device appears more than once in tree". The drive firmware installation failure was not observed in configurations having only one external drive enclosure attached to an HP Host Bus Adapter H22x.
- Component fails to update the firmware for drives connected behind an HP Smart Array P431 controller. Component reports the firmware update was successful. However, after a power cycle, the firmware version remains unchanged.

## Enhancements

### **Enhancements/New Features:**

- Added servo improvements which reduce power consumption.

---

Supplemental Update / Online ROM Flash Component for Linux (x64) - MM1000JEFRB and MM2000JEFRC Drives

Version: HPD4 (B) **(Recommended)**

Filename: rpm/RPMS/x86\_64/hp-firmware-hdd-b04257b77b-HPD4-2.1.x86\_64.rpm

## Important Note!

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**
- **Customers who already installed firmware version HPD4 do not need to update to HPD4 (B).**

## Fixes

### **Problems Fixed:**

- Version HPD4 prevents the potential for incorrect data to be written to the drive under extremely rare circumstances when the drive experiences a hard reset. This issue has only been observed in a rigorous test environment and has NOT been reported in a customer production environment.

### **Problems Fixed for HPD4 (B):**

- Component would fail to install drive firmware for drives present in a system configured with two or more external drive enclosures attached to an HP Host Bus Adapter H22x. The following message would be reported in the component log file - "Device appears more than once in tree". The drive firmware installation failure was not observed in configurations having only one external drive enclosure attached to an HP Host Bus Adapter H22x.
- Component fails to update the firmware for drives connected behind an HP Smart Array P431 controller. Component reports the firmware update was successful. However, after a power cycle, the firmware version remains unchanged.

---

Supplemental Update / Online ROM Flash Component for Linux (x64) - DH0072FAQRD, DH0146FAQRE, EH0146FAWJB, and EH0072FAWJA Drives  
Version: HPDK (B) **(Recommended)**  
Filename: rpm/RPMS/x86\_64/hp-firmware-hdd-ca173adbad-HPDK-2.1.x86\_64.rpm

### **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSES would require an offline update using the SPP and HP SUM.**
- **Customers who already installed firmware version HPDK do not need to update to HPDK (B).**

### **Fixes**

#### **Problems Fixed:**

- HP ProLiant servers would power down due a hard drive overtemp condition that was falsely reported. Hard disk drive firmware HPDK resolves this issue.

#### **Problems Fixed for HPDK (B):**

- Component would fail to install drive firmware for drives present in a system configured with two or more external drive enclosures attached to an HP Host Bus Adapter H22x. The following message would be reported in the component log file - "Device appears more than once in tree". The drive firmware installation failure was not observed in configurations having only one external drive enclosure attached to an HP Host Bus Adapter H22x.
- Component fails to update the firmware for drives connected behind an HP Smart Array P431 controller. Component reports the firmware update was successful. However, after a power cycle, the firmware version remains unchanged.

---

Supplemental Update / Online ROM Flash Component for Linux (x64) - EF0300FARMU, EF0450FARMV, and EF0600FARNA Drives  
Version: HPD9 **(Recommended)**  
Filename: rpm/RPMS/x86\_64/hp-firmware-hdd-c7ed905f46-HPD9-1.1.x86\_64.rpm

### **Important Note!**

- **Online firmware flashing of drives attached to an HP Smart Array controller running in Zero Memory (ZM) mode or an HP ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux and Microsoft Windows environments. All other OSES would require an offline update using the SPP and HP SUM.**

### **Fixes**

#### **Problems Fixed:**

- This firmware contains a change which prevents an incorrect reassign status of a repaired sector from being logged.

---

Supplemental Update / Online ROM Flash Component for Linux (x64) - EF0300FATFD, EF0450FATFE, and EF0600FATFF Drives  
Version: HPDB (C) **(Critical)**  
Filename: rpm/RPMS/x86\_64/hp-firmware-hdd-009c9a2503-HPDB-3.1.x86\_64.rpm

### **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**
- **Customers who already installed firmware version HPDB do not need to update to HPDB (C).**

### **Fixes**

#### **Problems Fixed:**

- This firmware corrects a possible condition in which stale data might be written to the disk. This results in unexpected data being returned in subsequent requests. This data issue has been duplicated in laboratory firmware stress tests.
- Flashing drives connected behind an HP H2xx Host Bus Adapter (HBA) no longer causes an interrupt resulting in drive firmware installation failures.

#### **Problems Fixed for HPDB (C):**

- Component would fail to install drive firmware for drives present in a system configured with two or more external drive enclosures attached to an HP Host Bus Adapter H22x. The following message would be reported in the component log file - "Device appears more than once in tree". The drive firmware installation failure was not observed in configurations having only one external drive enclosure attached to an HP Host Bus Adapter H22x.
- Component fails to update the firmware for drives connected behind an HP Smart Array P431 controller. Component reports the firmware update was successful. However, after a power cycle, the firmware version remains unchanged.

### **Enhancements**

#### **Enhancements/New Features:**

- Added support for UEFI (Universal Extensible Firmware Interface) based servers.

#### **Enhancements/New Features for HPDB (B):**

- Updated the flash engine to standardize logging across all SAS drive components.
- Enhanced logging capability to improve the details provided in the component log file.

---

Supplemental Update / Online ROM Flash Component for Linux (x64) - EG0300FBDSP, EG0450FBDSQ, and EG0600FBDSR Drives

Version: HPD6 (C) **(Optional)**

Filename: rpm/RPMS/x86\_64/hp-firmware-hdd-06ac84a5d4-HPD6-3.1.x86\_64.rpm

### **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**
- **Customers who already installed firmware version HPD6 do not need to update to HPD6 (C).**

### **Fixes**



### Problems Fixed:

- This firmware reduces the possibility of the controller and drive not properly negotiating link signaling, resulting in the controller not being able to identify a drive attached to a particular port/slot during system boot up. This firmware improves signal quality between the drive and the controller.
- Flashing drives connected behind an HP H2xx Host Bus Adapter (HBA) no longer causes an interrupt resulting in drive firmware installation failures.

### Problems Fixed for HPD6 (C):

- Component would fail to install drive firmware for drives present in a system configured with two or more external drive enclosures attached to an HP Host Bus Adapter H22x. The following message would be reported in the component log file - "Device appears more than once in tree". The drive firmware installation failure was not observed in configurations having only one external drive enclosure attached to an HP Host Bus Adapter H22x.
- Component fails to update the firmware for drives connected behind an HP Smart Array P431 controller. Component reports the firmware update was successful. However, after a power cycle, the firmware version remains unchanged.

## Enhancements

### Enhancements/New Features:

- Added support for UEFI (Universal Extensible Firmware Interface) based servers.

### Enhancements/New Features for HPD6 (B):

- Updated the flash engine to standardize logging across all SAS drive components.
- Enhanced logging capability to improve the details provided in the component log file.

---

Supplemental Update / Online ROM Flash Component for Linux (x64) - EG0300FBLSE, EG0450FBLSF, EG0600FBLSH, and EG0900FBLSK Drives

Version: HPD8 (B) **(Recommended)**

Filename: rpm/RPMS/x86\_64/hp-firmware-hdd-815e5e101b-HPD8-2.1.x86\_64.rpm

## Important Note!

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**
- **Customers who already installed firmware version HPD8 do not need to update to HPD8 (B).**

## Fixes

### Problems Fixed:

- HP ProLiant servers would power down due a hard drive overtemp condition that was falsely reported. Hard disk drive firmware HPD8 resolves this issue.

### Problems Fixed for HPD8 (B):

- Component would fail to install drive firmware for drives present in a system configured with two or more external drive enclosures attached to an HP Host Bus Adapter H22x. The following message would be reported in the component log file - "Device appears more than once in tree". The drive firmware installation failure was not observed in configurations having only one external drive enclosure attached to an HP Host Bus Adapter H22x.
- Component fails to update the firmware for drives connected behind an HP Smart Array P431 controller. Component reports the

firmware update was successful. However, after a power cycle, the firmware version remains unchanged.

---

Supplemental Update / Online ROM Flash Component for Linux (x64) - EG0300FBVFL, EG0450FBVFM, EG0600FBVFP, and EG0900FBVFQ Drives  
Version: HPDE (B) **(Recommended)**  
Filename: rpm/RPMS/x86\_64/hp-firmware-hdd-b94f345c05-HPDE-2.1.x86\_64.rpm

### **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**
- **Customers who already installed firmware version HPDE do not need to update to HPDE (B).**

### **Fixes**

#### **Problems Fixed:**

- Drive self-test did not complete within the specified time.
- During a fully cached workload, SMART would report incorrect temperature values.

#### **Problems Fixed for HPDE (B):**

- Component would fail to install drive firmware for drives present in a system configured with two or more external drive enclosures attached to an HP Host Bus Adapter H22x. The following message would be reported in the component log file - "Device appears more than once in tree". The drive firmware installation failure was not observed in configurations having only one external drive enclosure attached to an HP Host Bus Adapter H22x.
- Component fails to update the firmware for drives connected behind an HP Smart Array P431 controller. Component reports the firmware update was successful. However, after a power cycle, the firmware version remains unchanged.

### **Enhancements**

#### **Enhancements/New Features:**

- Added servo improvements which reduce power consumption.

---

Supplemental Update / Online ROM Flash Component for Linux (x64) - EG0300FCHHR, EG0450FCHHT, EG0600FCHHU, and EG0900FCHHV Drives  
Version: HPD8 (B) **(Recommended)**  
Filename: rpm/RPMS/x86\_64/hp-firmware-hdd-8a9b54701e-HPD8-2.1.x86\_64.rpm

### **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**
- **Customers who already installed firmware version HPD8 do not need to update to HPD8 (B).**

### **Fixes**

### **Problems Fixed:**

- A potential issue existed where the drive would become unresponsive if the host sent a high number of overlapping task management commands. The drive would require a power cycle to be recovered.

### **Problems Fixed for HPD8 (B):**

- Component would fail to install drive firmware for drives present in a system configured with two or more external drive enclosures attached to an HP Host Bus Adapter H22x. The following message would be reported in the component log file - "Device appears more than once in tree". The drive firmware installation failure was not observed in configurations having only one external drive enclosure attached to an HP Host Bus Adapter H22x.
- Component fails to update the firmware for drives connected behind an HP Smart Array P431 controller. Component reports the firmware update was successful. However, after a power cycle, the firmware version remains unchanged.

## **Enhancements**

### **Enhancements/New Features:**

- Improved write protection robustness before drive spin down.
- Implemented minor performance improvements in RAID environments.

---

Supplemental Update / Online ROM Flash Component for Linux (x64) - EG0300FCVBF, EG0450FCVBH, EG0600FCVBK, and EG0900FCVBL Drives  
Version: HPD9 (B) **(Recommended)**

Filename: rpm/RPMS/x86\_64/hp-firmware-hdd-415992e26f-HPD9-2.1x86\_64.rpm

### **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSES would require an offline update using the SPP and HP SUM.**
- **Customers who already installed firmware version HPD9 do not need to update to HPD9 (B).**

## **Fixes**

### **Problems Fixed:**

- Drives could become unresponsive due to unexpected responses from the serial port diagnostic debug connection.

### **Problems Fixed for HPD9 (B):**

- Component would fail to install drive firmware for drives present in a system configured with two or more external drive enclosures attached to an HP Host Bus Adapter H22x. The following message would be reported in the component log file - "Device appears more than once in tree". The drive firmware installation failure was not observed in configurations having only one external drive enclosure attached to an HP Host Bus Adapter H22x.
- Component fails to update the firmware for drives connected behind an HP Smart Array P431 controller. Component reports the firmware update was successful. However, after a power cycle, the firmware version remains unchanged.

---

Supplemental Update / Online ROM Flash Component for Linux (x64) - EG0300JEHLV, EG0600JEHMA, EG0900JEHMB, and EG1200JEHMC Drives  
Version: HPD3 (B) **(Recommended)**

### **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**
- **Customers who already installed firmware version HPD3 do not need to update to HPD3 (B).**

### **Fixes**

#### **Problems Fixed:**

- Self-initiated reset during ATI (Adjacent Track Interference) mitigation issue, where the drive reported a 06/29/04 (Self-Initiated Reset) to the controller. Then the controller would re-establish link with the drive and resend the command.
- Servo miscalculations that resulted in degraded drive performance.

#### **Problems Fixed for HPD3 (B):**

- Component would fail to install drive firmware for drives present in a system configured with two or more external drive enclosures attached to an HP Host Bus Adapter H22x. The following message would be reported in the component log file - "Device appears more than once in tree". The drive firmware installation failure was not observed in configurations having only one external drive enclosure attached to an HP Host Bus Adapter H22x.
- Component fails to update the firmware for drives connected behind an HP Smart Array P431 controller. Component reports the firmware update was successful. However, after a power cycle, the firmware version remains unchanged.

---

Supplemental Update / Online ROM Flash Component for Linux (x64) - EG0300JFCKA, EG0600JEMCV, EG0900JFCKB, and EG1200JEMDA Drives  
Version: HPD4 (B) **(Recommended)**

Filename: rpm/RPMS/x86\_64/hp-firmware-hdd-ac3fda26eb-HPD4-2.1.x86\_64.rpm

### **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**
- **Customers who already installed firmware version HPD4 do not need to update to HPD4 (B).**

### **Fixes**

#### **Problems Fixed:**

- The expected time to completion of Sanitize, Format and DST operations was incorrectly reported in the Vital Products Data page D0h. If time to completion is used by an application to determine when to terminate an operation, the operation might be terminated before the operation completed. Firmware version HPD4 now correctly reports the expected time to completion for these operations.

#### **Problems Fixed for HPD4 (B):**

- Component would fail to install drive firmware for drives present in a system configured with two or more external drive enclosures attached to an HP Host Bus Adapter H22x. The following message would be reported in the component log file - "Device appears more than once in tree". The drive firmware installation failure was not observed in configurations having only one external drive enclosure

attached to an HP Host Bus Adapter H22x.

- Component fails to update the firmware for drives connected behind an HP Smart Array P431 controller. Component reports the firmware update was successful. However, after a power cycle, the firmware version remains unchanged.

---

Supplemental Update / Online ROM Flash Component for Linux (x64) - EG0900FDJYR and EG1200FDJYT Drives

Version: HPD4 (C) **(Recommended)**

Filename: rpm/RPMS/x86\_64/hp-firmware-hdd-7cfa9118b1-HPD4-3.1.x86\_64.rpm

### **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**
- **Customers who already installed firmware version HPD4 do not need to update to HPD4 (C).**

### **Fixes**

#### **Problems Fixed:**

- Prevents the potential for incorrect data from being "read from" or "written to" the drive under extremely rare circumstances where the drive experiences consecutive error recoveries during a background scan and the Error Correction Code (ECC) fails. This issue has only been observed in a rigorous test environment and has NOT been reported in a customer production environment.

#### **Problems Fixed for HPD4 (B):**

- Linux Smart Component fails to update the firmware for drives connected behind an HP Smart Array P431 controller. Component reports the firmware update was successful. However, after a power cycle, the firmware version remains unchanged.

#### **Problems Fixed for HPD4 (C):**

- Component would fail to install drive firmware for drives present in a system configured with two or more external drive enclosures attached to an HP Host Bus Adapter H22x. The following message would be reported in the component log file - "Device appears more than once in tree". The drive firmware installation failure was not observed in configurations having only one external drive enclosure attached to an HP Host Bus Adapter H22x.

---

Supplemental Update / Online ROM Flash Component for Linux (x64) - EG1200FDNJT and EG1200FCVBQ Drives

Version: HPD8 (B) **(Recommended)**

Filename: rpm/RPMS/x86\_64/hp-firmware-hdd-33aee979c2-HPD8-2.1.x86\_64.rpm

### **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**
- **Customers who already installed firmware version HPD8 do not need to update to HPD8 (B).**

### **Fixes**

### Problems Fixed:

- Drive self-test did not complete within the specified time.
- During a fully cached workload, SMART would report incorrect temperature values.

### Problems Fixed for HPD8 (B):

- Component would fail to install drive firmware for drives present in a system configured with two or more external drive enclosures attached to an HP Host Bus Adapter H22x. The following message would be reported in the component log file - "Device appears more than once in tree". The drive firmware installation failure was not observed in configurations having only one external drive enclosure attached to an HP Host Bus Adapter H22x.
- Component fails to update the firmware for drives connected behind an HP Smart Array P431 controller. Component reports the firmware update was successful. However, after a power cycle, the firmware version remains unchanged.

## Enhancements

### Enhancements/New Features:

- Added servo improvements which reduce power consumption.

---

Supplemental Update / Online ROM Flash Component for Linux (x64) - EG1800JEHMD Drive

Version: HPD4 (C) **(Recommended)**

Filename: rpm/RPMS/x86\_64/hp-firmware-hdd-8a2c06af48-HPD4-3.1.x86\_64.rpm

### Important Note!

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**
- **Customers who already installed firmware version HPD4 do not need to update to HPD4 (C).**

## Fixes

### Problems Fixed:

- Self-initiated reset during ATI (Adjacent Track Interference) mitigation issue, where the drive reported a 06/29/04 (Self-Initiated Reset) to the controller. Then the controller would re-establish link with the drive and resend the command.
- Servo miscalculations that resulted in degraded drive performance.

### Problems Fixed for HPD4 (B):

- Linux Smart Component fails to update the firmware for drives connected behind an HP Smart Array P431 controller. Component reports the firmware update was successful. However, after a power cycle, the firmware version remains unchanged.

### Problems Fixed for HPD4 (C):

- Component would fail to install drive firmware for drives present in a system configured with two or more external drive enclosures attached to an HP Host Bus Adapter H22x. The following message would be reported in the component log file - "Device appears more than once in tree". The drive firmware installation failure was not observed in configurations having only one external drive enclosure attached to an HP Host Bus Adapter H22x.
- Component fails to update the firmware for drives connected behind an HP Smart Array P431 controller. Component reports the firmware update was successful. However, after a power cycle, the firmware version remains unchanged.

---

Supplemental Update / Online ROM Flash Component for Linux (x64) - EG1800JEMDB Drives

Version: HPD2 **(Recommended)**

Filename: rpm/RPMS/x86\_64/hp-firmware-hdd-0a38b25661-HPD2-1.1.x86\_64.rpm

### **Important Note!**

- o **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- o **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**

### **Fixes**

#### **Problems Fixed:**

- o This firmware improves HDD reliability when HDDs are exposed to long periods of host inactivity that exceed 1 second. HDDs may become unresponsive when using HDD firmware prior to version HPD2. This firmware also contains a change which prevents an incorrect reassign status of a repaired sector from being logged.

---

Supplemental Update / Online ROM Flash Component for Linux (x64) - EH0072FARUA and EH0146FARUB Drives

Version: HPD9 (C) **(Optional)**

Filename: rpm/RPMS/x86\_64/hp-firmware-hdd-88df5ee1cd-HPD9-3.1.x86\_64.rpm

### **Important Note!**

- o **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- o **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**
- o **Customers who already installed firmware version HPD9 do not need to update to HPD9 (C).**

### **Fixes**

#### **Problems Fixed:**

- o This firmware reduces the possibility of the controller and drive not properly negotiating link signaling, resulting in the controller not being able to identify a drive attached to a particular port/slot during system boot up. This firmware improves signal quality between the drive and the controller.
- o Flashing drives connected behind an HP H2xx Host Bus Adapter (HBA) no longer causes an interrupt resulting in drive firmware installation failures.

#### **Problems Fixed for HPD9 (C):**

- o Component would fail to install drive firmware for drives present in a system configured with two or more external drive enclosures attached to an HP Host Bus Adapter H22x. The following message would be reported in the component log file - "Device appears more than once in tree". The drive firmware installation failure was not observed in configurations having only one external drive enclosure attached to an HP Host Bus Adapter H22x.
- o Component fails to update the firmware for drives connected behind an HP Smart Array P431 controller. Component reports the firmware update was successful. However, after a power cycle, the firmware version remains unchanged.

## **Enhancements**

### **Enhancements/New Features:**

- Added support for UEFI (Universal Extensible Firmware Interface) based servers.

### **Enhancements/New Features for HPD9 (B):**

- Updated the flash engine to standardize logging across all SAS drive components.
- Enhanced logging capability to improve the details provided in the component log file.

---

Supplemental Update / Online ROM Flash Component for Linux (x64) - EH0072FARWC and EH0146FARWD Drives

Version: HPDD (C) **(Critical)**

Filename: rpm/RPMS/x86\_64/hp-firmware-hdd-92875cb465-HPDD-3.1.x86\_64.rpm

## **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**
- **Customers who already installed firmware version HPDD do not need to update to HPDD (C).**

## **Fixes**

### **Problems Fixed:**

- This firmware corrects a possible condition in which stale data might be written to the disk. This results in unexpected data being returned in subsequent requests. This data issue has been duplicated in laboratory firmware stress tests.
- Flashing drives connected behind an HP H2xx Host Bus Adapter (HBA) no longer causes an interrupt resulting in drive firmware installation failures.

### **Problems Fixed for HPDD (C):**

- Component would fail to install drive firmware for drives present in a system configured with two or more external drive enclosures attached to an HP Host Bus Adapter H22x. The following message would be reported in the component log file - "Device appears more than once in tree". The drive firmware installation failure was not observed in configurations having only one external drive enclosure attached to an HP Host Bus Adapter H22x.
- Component fails to update the firmware for drives connected behind an HP Smart Array P431 controller. Component reports the firmware update was successful. However, after a power cycle, the firmware version remains unchanged.

## **Enhancements**

### **Enhancements/New Features:**

- Added support for UEFI (Universal Extensible Firmware Interface) based servers.

### **Enhancements/New Features for HPDD (B):**

- Updated the flash engine to standardize logging across all SAS drive components.
  - Enhanced logging capability to improve the details provided in the component log file.
-



### **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSES would require an offline update using the SPP and HP SUM.**
- **Customers who already installed firmware version HPD5 do not need to update to HPD5 (B).**

### **Fixes**

#### **Problems Fixed:**

- HP ProLiant servers would power down due a hard drive overtemp condition that was falsely reported. Hard disk drive firmware HPD5 resolves this issue.

#### **Problems Fixed for HPD5 (B):**

- Component would fail to install drive firmware for drives present in a system configured with two or more external drive enclosures attached to an HP Host Bus Adapter H22x. The following message would be reported in the component log file - "Device appears more than once in tree". The drive firmware installation failure was not observed in configurations having only one external drive enclosure attached to an HP Host Bus Adapter H22x.
- Component fails to update the firmware for drives connected behind an HP Smart Array P431 controller. Component reports the firmware update was successful. However, after a power cycle, the firmware version remains unchanged.

### **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSES would require an offline update using the SPP and HP SUM.**

### **Fixes**

#### **Problems Fixed:**

- Reliability enhancement for applications that write data to a narrow range of tracks.
- New SMART trip when device senses an abnormal change in the motor electric current.

### **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**

### **Enhancements**

#### **Enhancements/New Features:**

- Reliability enhancement for applications that write data to a narrow range of tracks.

---

Supplemental Update / Online ROM Flash Component for Linux (x64) - EH0300JDYTH, EH0450JDYTK, and EH0600JDYTL Drives

Version: HPD4 (B) **(Recommended)**

Filename: rpm/RPMS/x86\_64/hp-firmware-hdd-b9340d29be-HPD4-2.1.x86\_64.rpm

### **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**
- **Customers who already installed firmware version HPD4 do not need to update to HPD4 (B).**

### **Fixes**

#### **Problems Fixed:**

- Self-initiated reset during ATI (Adjacent Track Interference) mitigation issue, where the drive reported a 06/29/04 (Self-Initiated Reset) to the controller. Then the controller would re-establish link with the drive and resend the command.
- Servo miscalculations that resulted in degraded drive performance.

#### **Problems Fixed for HPD4 (B):**

- Component would fail to install drive firmware for drives present in a system configured with two or more external drive enclosures attached to an HP Host Bus Adapter H22x. The following message would be reported in the component log file - "Device appears more than once in tree". The drive firmware installation failure was not observed in configurations having only one external drive enclosure attached to an HP Host Bus Adapter H22x.
- Component fails to update the firmware for drives connected behind an HP Smart Array P431 controller. Component reports the firmware update was successful. However, after a power cycle, the firmware version remains unchanged.

---

Supplemental Update / Online ROM Flash Component for Linux (x64) - EH0300JEDHC, EH0450JEDHD, and EH0600JEDHE Drives

Version: HPD4 **(Recommended)**

Filename: rpm/RPMS/x86\_64/hp-firmware-hdd-8c4a212ff9-HPD4-1.1.x86\_64.rpm

### **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE**

**ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**

- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**

## Fixes

### **Problems Fixed:**

- This firmware improves HDD reliability when HDDs are exposed to long periods of host inactivity that exceed 1 second. HDDs may become unresponsive when using HDD firmware prior to version HPD4. This firmware also contains a change which prevents an incorrect reassigned status of a repaired sector from being logged.

---

Supplemental Update / Online ROM Flash Component for Linux (x64) - EH0600JDYTN Drive

Version: HPD5 (B) **(Recommended)**

Filename: rpm/RPMS/x86\_64/hp-firmware-hdd-f3faa195ff-HPD5-2.1.x86\_64.rpm

## Important Note!

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**
- **Customers who already installed firmware version HPD5 do not need to update to HPD5 (B).**

## Fixes

### **Problems Fixed:**

- Self-initiated reset during ATI (Adjacent Track Interference) mitigation issue, where the drive reported a 06/29/04 (Self-Initiated Reset) to the controller. Then the controller would re-establish link with the drive and resend the command.
- Servo miscalculations that resulted in degraded drive performance.

### **Problems Fixed for HPD5 (B):**

- Component would fail to install drive firmware for drives present in a system configured with two or more external drive enclosures attached to an HP Host Bus Adapter H22x. The following message would be reported in the component log file - "Device appears more than once in tree". The drive firmware installation failure was not observed in configurations having only one external drive enclosure attached to an HP Host Bus Adapter H22x.
- Component fails to update the firmware for drives connected behind an HP Smart Array P431 controller. Component reports the firmware update was successful. However, after a power cycle, the firmware version remains unchanged.

---

Supplemental Update / Online ROM Flash Component for Linux (x64) - E00200FBRVV, MO0200FBRWB, E00400FBRWA, MO0400FBRWC, and MO0800FBRWD Drives

Version: HPD9 (C) **(Optional)**

Filename: rpm/RPMS/x86\_64/hp-firmware-hdd-792f35abb6-HPD9-3.1.x86\_64.rpm

## Important Note!

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE**

**ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**

- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**
- **Customers who already installed firmware version HPD9 do not need to update to HPD9 (C).**

## Fixes

### **Problems Fixed:**

- In previous firmware revisions when the solid state drive was issued a Report Support Operation Code (RSOC) command (A3h) and the reporting options field was set to 001, the drive incorrectly responded with 05/24/00 indicating that the RSOC command was not supported. The error was logged in the system log files. The drive should have communicated non-support using the Command Data Parameter (CDP) format. The firmware now complies with the RSOC industry standard specification.
- Flashing drives connected behind an HP H2xx Host Bus Adapter (HBA) no longer causes an interrupt resulting in drive firmware installation failures.

### **Problems Fixed for HPD9 (C):**

- Component would fail to install drive firmware for drives present in a system configured with two or more external drive enclosures attached to an HP Host Bus Adapter H22x. The following message would be reported in the component log file - "Device appears more than once in tree". The drive firmware installation failure was not observed in configurations having only one external drive enclosure attached to an HP Host Bus Adapter H22x.
- Component fails to update the firmware for drives connected behind an HP Smart Array P431 controller. Component reports the firmware update was successful. However, after a power cycle, the firmware version remains unchanged.

## Enhancements

### **Enhancements/New Features:**

- Added support for UEFI (Universal Extensible Firmware Interface) based servers.

### **Enhancements/New Features for HPD9 (B):**

- Updated the flash engine to standardize logging across all SAS drive components.
- Enhanced logging capability to improve the details provided in the component log file.

---

Supplemental Update / Online ROM Flash Component for Linux (x64) - MB1000FAMYU and MB2000FAMYV Drives

Version: HPD7 (C) **(Critical)**

Filename: rpm/RPMS/x86\_64/hp-firmware-hdd-2db44cb024-HPD7-3.1.x86\_64.rpm

## Important Note!

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**
- **Customers who already installed firmware version HPD7 do not need to update to HPD7 (C).**

## Fixes

### **Problem Fixed:**

- This firmware prevents a rare condition that may occur during a WRITE SAME command sequence that may result in incorrect data being written to the hard drive. The WRITE SAME command may be used during RAID ARRAY parity initialization.
- HPD7 (B) resolves an issue with offline flashing where the component would time out during the upgrade process.
- Flashing drives connected behind an HP H2xx Host Bus Adapter (HBA) no longer causes an interrupt resulting in drive firmware installation failures.

#### **Problems Fixed for HPD7 (C):**

- Component would fail to install drive firmware for drives present in a system configured with two or more external drive enclosures attached to an HP Host Bus Adapter H22x. The following message would be reported in the component log file - "Device appears more than once in tree". The drive firmware installation failure was not observed in configurations having only one external drive enclosure attached to an HP Host Bus Adapter H22x.
- Component fails to update the firmware for drives connected behind an HP Smart Array P431 controller. Component reports the firmware update was successful. However, after a power cycle, the firmware version remains unchanged.

### **Enhancements**

#### **Enhancements/New Features:**

- Added support for UEFI (Universal Extensible Firmware Interface) based servers.

#### **Enhancements/New Features for HPD7 (B):**

- Updated the flash engine to standardize logging across all SAS drive components.
- Enhanced logging capability to improve the details provided in the component log file.

---

Supplemental Update / Online ROM Flash Component for Linux (x64) - MB1000FBZPL and MB2000FBZPN Drives

Version: HPD4 (B) **(Recommended)**

Filename: rpm/RPMS/x86\_64/hp-firmware-hdd-b33fedbbdf-HPD4-2.1.x86\_64.rpm

### **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**
- **Customers who already installed firmware version HPD4 do not need to update to HPD4 (B).**

### **Fixes**

#### **Problems Fixed:**

- ProLiant servers would power down due a hard drive over temperature condition that was falsely reported. HPD4 firmware resolves this issue.

#### **Problems Fixed for HPD4 (B):**

- Component would fail to install drive firmware for drives present in a system configured with two or more external drive enclosures attached to an HP Host Bus Adapter H22x. The following message would be reported in the component log file - "Device appears more than once in tree". The drive firmware installation failure was not observed in configurations having only one external drive enclosure attached to an HP Host Bus Adapter H22x.
- Component fails to update the firmware for drives connected behind an HP Smart Array P431 controller. Component reports the firmware update was successful. However, after a power cycle, the firmware version remains unchanged.

---

Supplemental Update / Online ROM Flash Component for Linux (x64) - MB1000FCWDE, MB2000FCWDF, MB3000FCWDH, and MB4000FCWDK Drives

Version: HPDA **(Recommended)**

Filename: rpm/RPMS/x86\_64/hp-firmware-hdd-4892d09bcf-HPDA-1.1.x86\_64.rpm

### **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**

### **Fixes**

#### **Problems Fixed:**

- This firmware improves HDD reliability when HDDs are exposed to long periods of host inactivity that exceed 1 second. HDDs may become unresponsive when using HDD firmware prior to version HPDA.
- This firmware also contains a change which prevents an incorrect reassign status of a repaired sector from being logged.

---

Supplemental Update / Online ROM Flash Component for Linux (x64) - MB1000FCWPP, MB2000FCVBV, MB3000FCVCA, and MB4000FCVCB Drives

Version: HPD2 (C) **(Recommended)**

Filename: rpm/RPMS/x86\_64/hp-firmware-hdd-64ffa21017-HPD2-3.1.x86\_64.rpm

### **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**
- **Customers who already installed firmware version HPD2 do not need to update to HPD2 (C).**

### **Fixes**

#### **Problems Fixed for HPD2 (C):**

- Component would fail to install drive firmware for drives present in a system configured with two or more external drive enclosures attached to an HP Host Bus Adapter H22x. The following message would be reported in the component log file - "Device appears more than once in tree". The drive firmware installation failure was not observed in configurations having only one external drive enclosure attached to an HP Host Bus Adapter H22x.
- Component fails to update the firmware for drives connected behind an HP Smart Array P431 controller. Component reports the firmware update was successful. However, after a power cycle, the firmware version remains unchanged.

### **Enhancements**

#### **Enhancements/New Features:**

- This firmware improves reliability by modifying the pivot bearing grease wear leveling algorithm, which if not implemented, could result in

- an increased drive failure rate for specific usage applications (eg. very long periods of small range seeks).
- Enhancements also include performance improvements.

#### **Enhancements/New Features HPD2(B):**

- Updated the flash engine to standardize logging across all SAS drive components.
- Enhanced logging capability to improve the details provided in the component log file.

---

Supplemental Update / Online ROM Flash Component for Linux (x64) - MB2000FBUCL and MB3000FBUCN Drives

Version: HPDA (C) **(Critical)**

Filename: rpm/RPMS/x86\_64/hp-firmware-hdd-e0a45065fd-HPDA-3.1.x86\_64.rpm

#### **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**
- **Customers who already installed firmware version HPDA do not need to update to HPDA (C).**

#### **Fixes**

##### **Problems Fixed:**

- This firmware improves background scans for media robustness, and also corrects a laboratory induced rare condition that could result in the disk not being updated with the latest cache data.

##### **Problems Fixed for HPDA (C):**

- Component would fail to install drive firmware for drives present in a system configured with two or more external drive enclosures attached to an HP Host Bus Adapter H22x. The following message would be reported in the component log file - "Device appears more than once in tree". The drive firmware installation failure was not observed in configurations having only one external drive enclosure attached to an HP Host Bus Adapter H22x.
- Component fails to update the firmware for drives connected behind an HP Smart Array P431 controller. Component reports the firmware update was successful. However, after a power cycle, the firmware version remains unchanged.

#### **Enhancements**

##### **Enhancements/New Features:**

- Added support for UEFI (Universal Extensible Firmware Interface) based servers.

##### **Enhancements/New Features for HPDA (B):**

- Updated the flash engine to standardize logging across all SAS drive components.
- Enhanced logging capability to improve the details provided in the component log file.

---

Supplemental Update / Online ROM Flash Component for Linux (x64) - MB2000FCQPF and MB3000FBNWV Drives

Version: HPD9 **(Recommended)**

Filename: rpm/RPMS/x86\_64/hp-firmware-hdd-52de99d707-HPD9-1.1.x86\_64.rpm

### **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSES would require an offline update using the SPP and HP SUM.**

### **Fixes**

#### **Problems Fixed:**

- HP ProLiant servers would power down due a hard drive overtemp condition that was falsely reported. Hard disk drive firmware HPD9 resolves this issue.

---

Supplemental Update / Online ROM Flash Component for Linux (x64) - MB2000FCZGH, MB3000FCZGK, and MB4000FCZGL Drives  
Version: HPD7 (B) **(Recommended)**  
Filename: rpm/RPMS/x86\_64/hp-firmware-a8d1969535-HPD7-2.1.x86\_64.rpm

### **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSES would require an offline update using the SPP and HP SUM.**
- **Customers who already installed firmware version HPD7 do not need to update to HPD7 (B).**

### **Fixes**

#### **Problems Fixed:**

- This firmware corrects an issue which could result in a failure of the drive to be discovered after power on.

#### **Problems Fixed for HPD7 (B):**

- Component would fail to install drive firmware for drives present in a system configured with two or more external drive enclosures attached to an HP Host Bus Adapter H22x. The following message would be reported in the component log file - "Device appears more than once in tree". The drive firmware installation failure was not observed in configurations having only one external drive enclosure attached to an HP Host Bus Adapter H22x.
- Component fails to update the firmware for drives connected behind an HP Smart Array P431 controller. Component reports the firmware update was successful. However, after a power cycle, the firmware version remains unchanged.

---

Supplemental Update / Online ROM Flash Component for Linux (x64) - MB2000JFDSL and MB4000JFDSN Drives  
Version: HPD1 **(Recommended)**  
Filename: rpm/RPMS/x86\_64/hp-firmware-hdd-46fc43ab26-HPD1-1.1.x86\_64.rpm

### **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these**



configurations.

- o **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**

## **Enhancements**

### **Enhancements/New Features:**

- o Reliability enhancement for applications that write data to a narrow range of tracks.

---

Supplemental Update / Online ROM Flash Component for Linux (x64) - MB2000JFEPA and MB4000JFEPB Drives

Version: HPD2 (**Recommended**)

Filename: rpm/RPMS/x86\_64/hp-firmware-hdd-326de7c0f2-HPD2-1.1.x86\_64.rpm

### **Important Note!**

- **Online firmware flashing of drives attached to an HP Smart Array controller running in Zero Memory (ZM) mode or an HP ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**

## **Fixes**

### **Problems Fixed:**

- This firmware improves HDD reliability when HDDs are exposed to long periods of host inactivity that exceed 1 second. HDDs may become unresponsive when using HDD firmware prior to version HPD2. This firmware also contains a change which prevents an incorrect reassign status of a repaired sector from being logged.

---

Supplemental Update / Online ROM Flash Component for Linux (x64) - MB4000JEFNC and MB6000JEFND Drives

Version: HPD5 (**Critical**)

Filename: rpm/RPMS/x86\_64/hp-firmware-hdd-af802bb412-HPD5-1.1.x86\_64.rpm

### **Important Note!**

- o **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- o **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**

## **Fixes**

### **Problems Fixed:**

- o This firmware improves HDD reliability when HDDs are exposed to long periods of host inactivity that exceed 1 second. HDDs may become unresponsive when using HDD firmware prior to version HPD5. This firmware also contains a change which prevents an incorrect reassign status of a repaired sector from being logged.
-

### **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**
- **Customers who already installed firmware version HPD7 do not need to update to HPD7 (B).**

### **Fixes**

#### **Problems Fixed:**

- This firmware fixes a potential incorrect data issue in write-cached enabled multi-initiator unaligned write environments, where reservation commands are used.

#### **Problems Fixed for HPD7 (B):**

- Component would fail to install drive firmware for drives present in a system configured with two or more external drive enclosures attached to an HP Host Bus Adapter H22x. The following message would be reported in the component log file - "Device appears more than once in tree". The drive firmware installation failure was not observed in configurations having only one external drive enclosure attached to an HP Host Bus Adapter H22x.
- Component fails to update the firmware for drives connected behind an HP Smart Array P431 controller. Component reports the firmware update was successful. However, after a power cycle, the firmware version remains unchanged.

### **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**
- **Customers who already installed firmware version HPD4 do not need to update to HPD4 (B).**

### **Fixes**

#### **Problems Fixed:**

- This firmware corrects an issue which could result in a failure of the drive to be discovered after power on.

#### **Problems Fixed for HPD4 (B):**

- Component would fail to install drive firmware for drives present in a system configured with two or more external drive enclosures attached to an HP Host Bus Adapter H22x. The following message would be reported in the component log file - "Device appears more than once in tree". The drive firmware installation failure was not observed in configurations having only one external drive enclosure

attached to an HP Host Bus Adapter H22x.

- Component fails to update the firmware for drives connected behind an HP Smart Array P431 controller. Component reports the firmware update was successful. However, after a power cycle, the firmware version remains unchanged.

---

Supplemental Update / Online ROM Flash Component for Linux (x64) - MM0500FAMYT Drives

Version: HPD6 (C) **(Critical)**

Filename: rpm/RPMS/x86\_64/hp-firmware-hdd-ff472f94c8-HPD6-3.1.x86\_64.rpm

### **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**
- **Customers who already installed firmware version HPD6 do not need to update to HPD6 (C).**

### **Fixes**

#### **Problem Fixed:**

- After long term use of the HDD, a rare condition might occur following a power cycle where the drive heads may land on areas of the disk containing data, which could potentially cause data loss or mechanical damage. Firmware version HPD6 prevents this condition from occurring.
- This firmware prevents a rare condition that may occur during a WRITE SAME command sequence that may result in incorrect data being written to the hard drive. The WRITE SAME command may be used during RAID ARRAY parity initialization.
- Flashing drives connected behind an HP H2xx Host Bus Adapter (HBA) no longer causes an interrupt resulting in drive firmware installation failures.

#### **Problems Fixed for HPD6 (C):**

- Component would fail to install drive firmware for drives present in a system configured with two or more external drive enclosures attached to an HP Host Bus Adapter H22x. The following message would be reported in the component log file - "Device appears more than once in tree". The drive firmware installation failure was not observed in configurations having only one external drive enclosure attached to an HP Host Bus Adapter H22x.
- Component fails to update the firmware for drives connected behind an HP Smart Array P431 controller. Component reports the firmware update was successful. However, after a power cycle, the firmware version remains unchanged.

### **Enhancements**

#### **Enhancements/New Features:**

- Added support for UEFI (Universal Extensible Firmware Interface) based servers.

#### **Enhancements/New Features for HPD6 (B):**

- Updated the flash engine to standardize logging across all SAS drive components.
- Enhanced logging capability to improve the details provided in the component log file.

---

Supplemental Update / Online ROM Flash Component for Linux (x64) - MM0500FBFVQ and MM1000FBFVR Drives

Version: HPD9 (B) **(Recommended)**

Filename: rpm/RPMS/x86\_64/hp-firmware-hdd-4b3e11848c-HPD9-2.1.x86\_64.rpm

### **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**
- **Customers who already installed firmware version HPD9 do not need to update to HPD9 (B).**

### **Fixes**

#### **Problems Fixed:**

- HPD9 firmware prevents a condition in which data fails to be committed to disk after the host issues a hard reset in a lab stress test environment with write cache enabled.

#### **Problems Fixed for HPD9 (B):**

- Component would fail to install drive firmware for drives present in a system configured with two or more external drive enclosures attached to an HP Host Bus Adapter H22x. The following message would be reported in the component log file - "Device appears more than once in tree". The drive firmware installation failure was not observed in configurations having only one external drive enclosure attached to an HP Host Bus Adapter H22x.
- Component fails to update the firmware for drives connected behind an HP Smart Array P431 controller. Component reports the firmware update was successful. However, after a power cycle, the firmware version remains unchanged.

---

Supplemental Update / Online ROM Flash Component for Linux (x64) - MM1000JFJTH Drives

Version: HPD1 (**Recommended**)

Filename: rpm/RPMS/x86\_64/hp-firmware-hdd-fa46c607d6-HPD1-1.1.x86\_64.rpm

### **Important Note!**

- **Online firmware flashing of drives attached to an HP Smart Array controller running in Zero Memory (ZM) mode or an HP ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux and Microsoft Windows environments. All other OSes would require an offline update using the SPP and HP SUM.**

### **Fixes**

#### **Problems Fixed:**

- This firmware improves HDD reliability when HDDs are exposed to long periods of host inactivity that exceed 1 second. HDDs may become unresponsive when using HDD firmware prior to version HPD1. This firmware also contains a change which prevents an incorrect reassign status of a repaired sector from being logged.

---

Supplemental Update / Online ROM Flash Component for Linux (x64) - MO0200FCTRN, MO0400FCTRP, and MO0800FCTRQ Drives

Version: HPD5 (**Recommended**)

Filename: rpm/RPMS/x86\_64/hp-firmware-hdd-37893275d3-HPD5-1.1.x86\_64.rpm

### **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSES would require an offline update using the SPP and HP SUM.**

## **Fixes**

### **Problems Fixed:**

- An issue was found where the drive responded with a format error if power-cycled multiple times while in the process of un-mapping Logical Block Addresses (LBA). HPD5 firmware adds additional protection during power-cycles to ensure that the drive can recover its LBA to Physical Memory map.

---

Supplemental Update / Online ROM Flash Component for Linux (x64) - MO0200JDVET, MO0400JDVEU, MO0800JDVEV, EO0200JDVFA, EO0400JDVFB, and EO0800JDVFC Drives

Version: HPD2 (B) **(Optional)**

Filename: rpm/RPMS/x86\_64/hp-firmware-hdd-8c5d34ba77-HPD2-2.1.x86\_64.rpm

## **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSES would require an offline update using the SPP and HP SUM.**
- **Customers who already installed firmware version HPD2 do not need to update to HPD2 (B).**

## **Fixes**

### **Problems Fixed:**

- Solid-state drives (SSD) running firmware versions prior to HPD2 support Unmap commands. Application clients can make use of the Unmap command to specify certain LBAs do not contain vital data. The SSD can use the unmapped LBAs as needed. This feature will no longer be supported on these SSDs running firmware version HPD2 and later.

### **Problems Fixed for HPD2 (B):**

- Component would fail to install drive firmware for drives present in a system configured with two or more external drive enclosures attached to an HP Host Bus Adapter H22x. The following message would be reported in the component log file - "Device appears more than once in tree". The drive firmware installation failure was not observed in configurations having only one external drive enclosure attached to an HP Host Bus Adapter H22x.
- Component fails to update the firmware for drives connected behind an HP Smart Array P431 controller. Component reports the firmware update was successful. However, after a power cycle, the firmware version remains unchanged.

---

Supplemental Update / Online ROM Flash Component for Linux (x64) - MO0200JEFNV, MO0400JEFPA, MO0800JFPB, MO1600JEFPC, EO0200JFPD, EO0400JEFPE, and EO0800JFPPF Drives

Version: HPD1 (B) **(Critical)**

Filename: rpm/RPMS/x86\_64/hp-firmware-hdd-71af849f3b-HPD1-2.1.x86\_64.rpm

## **Important Note!**

- o **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- o **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSES would require an offline update using the SPP and HP SUM.**
- o **Customers who already installed firmware version HPD1 do not need to update to HPD1 (B).**

## Fixes

### **Problem Fixed:**

- Incorrect data reads might occur when accessing unaligned 4k reads and the data read has zero content preceding customer data. For additional information please refer to the customer advisory #[c04650586](#)

### **Problems Fixed for HPD1 (B):**

- o Component would fail to install drive firmware for drives present in a system configured with two or more external drive enclosures attached to an HP Host Bus Adapter H22x. The following message would be reported in the component log file - "Device appears more than once in tree". The drive firmware installation failure was not observed in configurations having only one external drive enclosure attached to an HP Host Bus Adapter H22x.
- o Component fails to update the firmware for drives connected behind an HP Smart Array P431 controller. Component reports the firmware update was successful. However, after a power cycle, the firmware version remains unchanged.

---

Supplemental Update / Online ROM Flash Component for Linux (x64) - MO0400JFFCF, MO0800JFFCH, MO1600JFFCK, and MO3200JFFCL Drives  
Version: HPD4 **(Optional)**

Filename: rpm/RPMS/x86\_64/hp-firmware-hdd-edf6dcd906-HPD4-1.1.x86\_64.rpm

## Important Note!

- o **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- o **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSES would require an offline update using the SPP and HP SUM.**

## Fixes

### **Problems Fixed:**

- o This firmware contains several low level maintenance fixes including debug data retrieval through read buffer. The fixes addressed events observed in a specialized lab testing environment, and are not expected to be experienced in customer use case scenarios.

---

Supplemental Update / Online ROM Flash Component for Linux (x64) - VO0480JFDGT, VO0960JFDGU, VO1920JFDGV, and VO3840JFDHA Drives  
Version: HPD4 **(Optional)**

Filename: rpm/RPMS/x86\_64/hp-firmware-hdd-8ed8893abd-HPD4-1.1.x86\_64.rpm

## Important Note!

- o **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**

**Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSES would require an offline update using the SPP and HP SUM.**

## **Fixes**

### **Problems Fixed:**

- This firmware contains several low level maintenance fixes including debug data retrieval through read buffer. The fixes addressed events observed in a specialized lab testing environment, and are not expected to be experienced in customer use case scenarios.

---

Supplemental Update / Online ROM Flash Component for Linux (x64) - VO1920JEUQQ Drives

Version: HPD1 (B) **(Critical)**

Filename: rpm/RPMS/x86\_64/hp-firmware-hdd-5d9e841607-HPD1-2.1.x86\_64.rpm

## **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSES would require an offline update using the SPP and HP SUM.**
- **Customers who already installed firmware version HPD1 do not need to update to HPD1 (B).**

## **Fixes**

### **Problem Fixed:**

- Incorrect data reads might occur when accessing unaligned 4k reads and the data read has zero content preceding customer data.

### **Problems Fixed for HPD1 (B):**

- Component would fail to install drive firmware for drives present in a system configured with two or more external drive enclosures attached to an HP Host Bus Adapter H22x. The following message would be reported in the component log file - "Device appears more than once in tree". The drive firmware installation failure was not observed in configurations having only one external drive enclosure attached to an HP Host Bus Adapter H22x.
- Component fails to update the firmware for drives connected behind an HP Smart Array P431 controller. Component reports the firmware update was successful. However, after a power cycle, the firmware version remains unchanged.

---

Supplemental Update / Online ROM Flash Component for Linux - DH0072FAQRD, DH0146FAQRE, EH0146FAWJB, and EH0072FAWJA Drives

Version: HPDK **(Recommended)**

Filename: rpm/RPMS/i386/hp-firmware-ca173adbad-HPDK-1.1.i386.rpm

## **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSES would require an offline update using the SPP and HP SUM.**

## **Fixes**

### Problems Fixed:

- HP ProLiant servers would power down due a hard drive overtemp condition that was falsely reported. Hard disk drive firmware HPDK resolves this issue.

---

Supplemental Update / Online ROM Flash Component for Linux - EF0300FARMU, EF0450FARMV, and EF0600FARNA drives

Version: HPD9 **(Recommended)**

Filename: rpm/RPMS/i386/hp-firmware-hdd-c7ed905f46-HPD9-1.1.i386.rpm

### **Important Note!**

- **Online firmware flashing of drives attached to an HP Smart Array controller running in Zero Memory (ZM) mode or an HP ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux and Microsoft Windows environments. All other OSES would require an offline update using the SPP and HP SUM.**

### **Fixes**

#### **Problems Fixed:**

- This firmware contains a change which prevents an incorrect reassign status of a repaired sector from being logged.

---

Supplemental Update / Online ROM Flash Component for Linux - EF0300FATFD, EF0450FATFE, and EF0600FATFF Drives

Version: HPDB (C) **(Critical)**

Filename: CP022311.md5; CP022311.scexe

### **Important Note!**

- **Online firmware flashing of drives attached to an HP Smart Array controller running in Zero Memory (ZM) mode or an HP ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSES would require an offline update using the SPP and HP SUM.**
- **Customers who already installed firmware version HPDB do not need to update to HPDB(C).**

### **Fixes**

#### **Problems Fixed:**

- This firmware corrects a possible condition in which stale data might be written to the disk. This results in unexpected data being returned in subsequent requests. This data issue has been duplicated in laboratory firmware stress tests.
- Flashing drives connected behind an HP H2xx Host Bus Adapter (HBA) no longer causes an interrupt resulting in drive firmware installation failures.

### **Enhancements**

#### **Enhancements/New Features:**

- Added support for UEFI (Universal Extensible Firmware Interface) based servers.
-



Supplemental Update / Online ROM Flash Component for Linux - EG0300FCVBF, EG0450FCVBH, EG0600FCVBK, and EG0900FCVBL Drives

Version: HPD9 **(Recommended)**

Filename: rpm/RPMS/i386/hp-firmware-4.15992e26f-HPD9-1.1.i386.rpm

### **Important Note!**

- **Online firmware flashing of drives attached to an HP Smart Array controller running in Zero Memory (ZM) mode or an HP ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**

### **Fixes**

#### **Problems Fixed:**

- Drives could become unresponsive due to unexpected responses from the serial port diagnostic debug connection.

---

Supplemental Update / Online ROM Flash Component for Linux - EH0072FARWC and EH0146FARWD Drives

Version: HPDD (C) **(Critical)**

Filename: CP022319.md5; CP022319.scexe

### **Important Note!**

- **Online firmware flashing of drives attached to an HP Smart Array controller running in Zero Memory (ZM) mode or an HP ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**
- **Customers who already installed firmware version HPDD do not need to update to HPDD(C).**

### **Fixes**

#### **Problems Fixed:**

- This firmware corrects a possible condition in which stale data might be written to the disk. This results in unexpected data being returned in subsequent requests. This data issue has been duplicated in laboratory firmware stress tests.
- Flashing drives connected behind an HP H2xx Host Bus Adapter (HBA) no longer causes an interrupt resulting in drive firmware installation failures.

### **Enhancements**

#### **Enhancements/New Features:**

- Added support for UEFI (Universal Extensible Firmware Interface) based servers.

---

Supplemental Update / Online ROM Flash Component for Linux - MB1000FCWDE, MB2000FCWDF, MB3000FCWDH, and MB4000FCWDK Drives

Version: HPDA **(Recommended)**

Filename: rpm/RPMS/i386/hp-firmware-hdd-4892d09bcf-HPDA-1.1.i386.rpm

### **Important Note!**

**Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**

- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**

## Fixes

### **Problems Fixed:**

- This firmware improves HDD reliability when HDDs are exposed to long periods of host inactivity that exceed 1 second. HDDs may become unresponsive when using HDD firmware prior to version HPDA.
- This firmware also contains a change which prevents an incorrect reassign status of a repaired sector from being logged.

---

Supplemental Update / Online ROM Flash Component for Linux - MB2000FBUCL and MB3000FBUCN drives

Version: HPDA (B) **(Critical)**

Filename: CPO22332.md5; CPO22332.scexe

## Important Note!

- **Online firmware flashing of drives attached to an HP Smart Array controller running in Zero Memory (ZM) mode or an HP ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**
- **Customers who already installed firmware version HPDA do not need to update to HPDA(B).**

## Fixes

### **Problems Fixed:**

- This firmware improves background scans for media robustness, and also corrects a laboratory induced rare condition that could result in the disk not being updated with the latest cache data.

## Enhancements

### **Enhancements/New Features:**

- Added support for UEFI (Universal Extensible Firmware Interface) based servers.

---

Supplemental Update / Online ROM Flash Component for Linux - MB2000FCQPF and MB3000FBNWV Drives

Version: HPD9 **(Recommended)**

Filename: CPO30827.md5; CPO30827.scexe; rpm/RPMS/i386/hp-firmware-52de99d707-HPD9-1.1.i386.rpm

## Important Note!

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**

## Fixes

### Problems Fixed:

- HP ProLiant servers would power down due a hard drive overtemp condition that was falsely reported. Hard disk drive firmware HPD9 resolves this issue.

---

## **Firmware - SATA Storage Disk**

[Top](#)

Online ROM Flash Component for ESXi - MB3000EBKAB Drives

Version: HPG6 (F) **(Critical)**

Filename: CP029367.zip

### Important Note!

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**
- **Customers who already installed firmware version HPG6 do not need to update to HPG6 (F).**

## Fixes

### Problems Fixed:

- After long term use of the HDD, a rare condition might occur following a power cycle where the drive heads may land on areas of the disk containing data, which could potentially cause data loss or mechanical damage. Firmware version HPG6 prevents this condition from occurring.
- This firmware corrects "command timeouts" and seek errors which can result in poor performance or a Device Fault condition, the latter of which will result in the drive failed by the Controller or sub system.

### Problems Fixed for HPG6 (F):

- Component would fail to install drive firmware for drives present in a system configured with two or more external drive enclosures attached to an HP Host Bus Adapter H22x. The following message would be reported in the component log file - "Device appears more than once in tree". The drive firmware installation failure was not observed in configurations having only one external drive enclosure attached to an HP Host Bus Adapter H22x.

## Enhancements

### Enhancements/New Features:

- Added support for VMware vSphere 5.5.
- Added support for UEFI (Universal Extensible Firmware Interface) based servers.
- Added support for HP Dynamic Smart Array B140i Controller.

### Enhancements/New Features for HPG6 (E):

- Updated the flash engine to standardize logging across all SATA drive components.
- Enhanced logging capability to improve the details provided in the component log file.
- VMware Firmware Smart component packaging has changed from a \*.scexe package to a \*.zip package, which contains an executable binary that provides enhanced security during installation. The functionality of the VMware Smart Component has not changed.

---

Online ROM Flash Component for VMware ESXi - MB0500GCEHF, MB1000GCEHH, and MB2000GCEHK Drives

Version: HPGD (G) **(Critical)**

Filename: CPO29352.zip

### **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**
- **Customers who already installed firmware version HPGD do not need to update to HPGD (G).**

### **Fixes**

#### **Problems Fixed:**

- After long term use of the HDD, a rare condition might occur following a power cycle where the drive heads may land on areas of the disk containing data, which could potentially cause data loss or mechanical damage. Firmware version HPGD prevents this condition from occurring.

#### **Problems Fixed for HPGD (G):**

- Component would fail to install drive firmware for drives present in a system configured with two or more external drive enclosures attached to an HP Host Bus Adapter H22x. The following message would be reported in the component log file - "Device appears more than once in tree". The drive firmware installation failure was not observed in configurations having only one external drive enclosure attached to an HP Host Bus Adapter H22x.

### **Enhancements**

#### **Enhancements/New Features:**

- Added support for VMware vSphere 5.5.
- Added support for UEFI (Universal Extensible Firmware Interface) based servers.
- Added support for HP Dynamic Smart Array B140i Controller.

#### **Enhancements/New Features for HPGD(F):**

- Updated the flash engine to standardize logging across all SATA drive components.
- Enhanced logging capability to improve the details provided in the component log file.
- VMware Firmware Smart component packaging has changed from a \*.scexe package to a \*.zip package, which contains an executable binary that provides enhanced security during installation. The functionality of the VMware Smart Component has not changed.

---

Online ROM Flash Component for VMware ESXi - MB1000ECWCQ, MB2000ECWCR, MB3000ECWCT, and MB4000ECWCU Drives

Version: HPG5 **(Critical)**

Filename: CPO31115.zip

### **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE**

**ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**

- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**

## Fixes

### **Problems Fixed:**

- HPG5 firmware improves drive reliability where disk drives are exposed to long periods of host inactivity which exceed 1 second.

---

Online ROM Flash Component for VMware ESXi - MB1000GCEEK Drives

Version: HPG2 (B) **(Recommended)**

Filename: CPO29358.zip

## Important Note!

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**
- **Customers who already installed firmware version HPG2 do not need to update to HPG2 (B).**

## Fixes

### **Problems Fixed:**

- Component would fail to install drive firmware for drives present in a system configured with two or more external drive enclosures attached to an HP Host Bus Adapter H22x. The following message would be reported in the component log file - "Device appears more than once in tree". The drive firmware installation failure was not observed in configurations having only one external drive enclosure attached to an HP Host Bus Adapter H22x.

## Enhancements

### **Enhancements/New Features:**

- This firmware improves reliability by modifying the pivot bearing grease wear leveling algorithm, which if not implemented, could result in an increased drive failure rate for specific usage applications (eg, very long periods of small range seeks).

---

Online ROM Flash Component for VMware ESXi - MB1000GCWCV, MB2000GCWDA, MB3000GCWDB, and MB4000GCWDC Drives

Version: HPGH **(Critical)**

Filename: CPO29171.zip

## Important Note!

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**

## **Fixes**

### **Problems Fixed:**

- HPGH firmware improves drive reliability where disk drives are exposed to long periods of host inactivity which exceed 1 second. As a result, hard disk drives may become unresponsive.

---

Online ROM Flash Component for VMware ESXi - MB2000EAZNL Drives

Version: HPG4 (F) **(Optional)**

Filename: CP029359.zip

## **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**
- **Customers who already installed firmware version HPG4 do not need to update to HPG4 (F).**

## **Fixes**

### **Problems Fixed:**

- This firmware contains general maintenance release and code improvement items. Drives built with or upgraded to hard drive firmware version HPG4 should not be downgraded to an earlier version of firmware due to hard drive manufacturing process changes.

### **Problems Fixed for HPG4 (F):**

- Component would fail to install drive firmware for drives present in a system configured with two or more external drive enclosures attached to an HP Host Bus Adapter H22x. The following message would be reported in the component log file - "Device appears more than once in tree". The drive firmware installation failure was not observed in configurations having only one external drive enclosure attached to an HP Host Bus Adapter H22x.

## **Enhancements**

### **Enhancements/New Features:**

- Added support for VMware vSphere 5.5.
- Added support for UEFI (Universal Extensible Firmware Interface) based servers.
- Added support for HP Dynamic Smart Array B140i Controller.

### **Enhancements/New Features for HPG4 (E):**

- Updated the flash engine to standardize logging across all SATA drive components.
  - Enhanced logging capability to improve the details provided in the component log file.
  - VMware Firmware Smart component packaging has changed from a \*.scexe package to a \*.zip package, which contains an executable binary that provides enhanced security during installation. The functionality of the VMware Smart Component has not changed.
-

### **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSES would require an offline update using the SPP and HP SUM.**
- **Customers who already installed firmware version HPG4 do not need to update to HPG4 (F).**

### **Fixes**

#### **Problems Fixed:**

- The system did not recognize some drives after a power-cycle. This is due to the drive initialization process being interrupted by a reset, causing the drive to take more time than allotted to report commands.

#### **Problems Fixed for HPG4 (F):**

- Component would fail to install drive firmware for drives present in a system configured with two or more external drive enclosures attached to an HP Host Bus Adapter H22x. The following message would be reported in the component log file - "Device appears more than once in tree". The drive firmware installation failure was not observed in configurations having only one external drive enclosure attached to an HP Host Bus Adapter H22x.

### **Enhancements**

#### **Enhancements/New Features:**

- Added support for VMware vSphere 5.5.
- Added support for UEFI (Universal Extensible Firmware Interface) based servers.
- Added support for HP Dynamic Smart Array B140i Controller.

#### **Enhancements/New Features for HPG4 (E):**

- Updated the flash engine to standardize logging across all SATA drive components.
- Enhanced logging capability to improve the details provided in the component log file.
- VMware Firmware Smart component packaging has changed from a \*.scexe package to a \*.zip package, which contains an executable binary that provides enhanced security during installation. The functionality of the VMware Smart Component has not changed.

### **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSES would require an offline update using the SPP and HP SUM.**
- **Customers who already installed firmware version HPG5 do not need to update to HPG5 (C).**

## Fixes

### **Problem Fixed:**

- Fixes a rare but potential data integrity error during low 5v drive voltage and specific sequential data streaming conditions, which could result in data written to incorrect sectors.

### **Problems Fixed for HPG5 (C):**

- Component would fail to install drive firmware for drives present in a system configured with two or more external drive enclosures attached to an HP Host Bus Adapter H22x. The following message would be reported in the component log file - "Device appears more than once in tree". The drive firmware installation failure was not observed in configurations having only one external drive enclosure attached to an HP Host Bus Adapter H22x.

## Enhancements

### **Enhancements/New Features for HPG5 (B):**

- Updated the flash engine to standardize logging across all SATA drive components.
- Enhanced logging capability to improve the details provided in the component log file.
- VMware Firmware Smart component packaging has changed from a \*.scexe package to a \*.zip package, which contains an executable binary that provides enhanced security during installation. The functionality of the VMware Smart Component has not changed.

---

Online ROM Flash Component for VMware ESXi - MB2000ECWLP, MB3000ECWLQ, and MB4000ECWLR Drives

Version: HPG4 (**Recommended**)

Filename: CPO30519.zip

### **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**

## Fixes

### **Problems Fixed:**

- Improves the drive idle time behavior by reducing long periods of track dwell time, which if not implemented, could increase media lube depletion and reduce drive reliability.

---

Online ROM Flash Component for VMware ESXi - MB2000GBUPB and MB3000GBUCK drives

Version: HPG4 (F) (**Recommended**)

Filename: CPO29365.zip

### **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these**



**configurations.**

- o **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**
- o **Customers who already installed firmware version HPG4 do not need to update to HPG4 (F).**

## **Fixes**

### **Problems Fixed:**

- o The system did not recognize some drives after a power-cycle. This is due to the drive initialization process being interrupted by a reset, causing the drive to take more time than allotted to report commands.

### **Problems Fixed for HPG4 (F):**

- o Component would fail to install drive firmware for drives present in a system configured with two or more external drive enclosures attached to an HP Host Bus Adapter H22x. The following message would be reported in the component log file - "Device appears more than once in tree". The drive firmware installation failure was not observed in configurations having only one external drive enclosure attached to an HP Host Bus Adapter H22x.

## **Enhancements**

### **Enhancements/New Features:**

- o Added support for VMware vSphere 5.5.
- o Added support for UEFI (Universal Extensible Firmware Interface) based servers.
- o Added support for HP Dynamic Smart Array B140i Controller.

### **Enhancements/New Features for HPG4 (E):**

- o Updated the flash engine to standardize logging across all SATA drive components.
- o Enhanced logging capability to improve the details provided in the component log file.
- o VMware Firmware Smart component packaging has changed from a \*.scexe package to a \*.zip package, which contains an executable binary that provides enhanced security during installation. The functionality of the VMware Smart Component has not changed.

---

Online ROM Flash Component for VMware ESXi - MB2000GCQXQ and MB3000GBKAC Drives

Version: HPGK (**Recommended**)

Filename: CPO30682.zip

## **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**

## **Fixes**

### **Problem Fixed:**

- HP ProLiant servers would power down due a hard drive over temp condition that was falsely reported. Hard disk drive firmware HPGK resolves this issue.

---

Online ROM Flash Component for VMware ESXi - MB2000GCVBR, MB3000GCVBT, and MB4000GCVBU Drives

Version: HPG5 (C) **(Critical)**

Filename: CPO29366.zip

### **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**
- **Customers who already installed firmware version HPG5 do not need to update to HPG5 (C).**

### **Fixes**

#### **Problem Fixed:**

- Fixes a rare but potential data integrity error during low 5v drive voltage and specific sequential data streaming conditions, which could result in data written to incorrect sectors.

#### **Problems Fixed for HPG5 (C):**

- Component would fail to install drive firmware for drives present in a system configured with two or more external drive enclosures attached to an HP Host Bus Adapter H22x. The following message would be reported in the component log file - "Device appears more than once in tree". The drive firmware installation failure was not observed in configurations having only one external drive enclosure attached to an HP Host Bus Adapter H22x.

### **Enhancements**

#### **Enhancements/New Features for HPG5 (B):**

- Updated the flash engine to standardize logging across all SATA drive components.
- Enhanced logging capability to improve the details provided in the component log file.
- VMware Firmware Smart component packaging has changed from a \*.scexe package to a \*.zip package, which contains an executable binary that provides enhanced security during installation. The functionality of the VMware Smart Component has not changed.

---

Online ROM Flash Component for VMware ESXi - MB2000GCWLT, MB3000GCWLU, and MB4000GCWLX Drives

Version: HPG4 **(Recommended)**

Filename: CPO30522.zip

### **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**

### **Fixes**

#### **Problems Fixed:**

- Improves the drive idle time behavior by reducing long periods of track dwell time, which if not implemented, could increase media lube depletion and reduce drive reliability.

---

Online ROM Flash Component for VMware ESXi - MB4000GEQNH and MB6000GEQNK Drives

Version: HPG7 (B) **(Recommended)**

Filename: CP029370.zip

### **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**
- **Customers who already installed firmware version HPG7 do not need to update to HPG7 (B).**

### **Fixes**

#### **Problems Fixed:**

- This firmware corrects possible unrecovered errors caused by the track refresh algorithm not working properly.

#### **Problems Fixed for HPG7 (B):**

- Component would fail to install drive firmware for drives present in a system configured with two or more external drive enclosures attached to an HP Host Bus Adapter H22x. The following message would be reported in the component log file - "Device appears more than once in tree". The drive firmware installation failure was not observed in configurations having only one external drive enclosure attached to an HP Host Bus Adapter H22x.

---

Online ROM Flash Component for VMware ESXi - MB6000GEQUT and MB8000GEQUU Drives

Version: HPG7 (B) **(Recommended)**

Filename: CP029374.zip

### **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**
- **Customers who already installed firmware version HPG7 do not need to update to HPG7 (B).**

### **Fixes**

#### **Problems Fixed:**

- This firmware corrects possible unrecovered errors caused by the track refresh algorithm not working properly.

#### **Problems Fixed for HPG7 (B):**

- Component would fail to install drive firmware for drives present in a system configured with two or more external drive enclosures

attached to an HP Host Bus Adapter H22x. The following message would be reported in the component log file - "Device appears more than once in tree". The drive firmware installation failure was not observed in configurations having only one external drive enclosure attached to an HP Host Bus Adapter H22x.

---

Online ROM Flash Component for VMware ESXi - MK0100GCTYU, MK0200GCTYV, MK0400GCTZA, and MK0800GCTZB Drives

Version: HPG4 (D) **(Optional)**

Filename: CP029375.zip

### **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**
- **Customers who already installed firmware version HPG4 do not need to update to HPG4 (D).**

### **Fixes**

#### **Problems Fixed:**

- This maintenance release corrects a failure seen during a HP Insight Diagnostic hard drive test. The failure was due to Device Extended Self-Test not completing in the drives advertised Self-Test completion time. This failure is not an indication that the drive is bad or marginal.

#### **Problems Fixed for HPG4 (D):**

- Component would fail to install drive firmware for drives present in a system configured with two or more external drive enclosures attached to an HP Host Bus Adapter H22x. The following message would be reported in the component log file - "Device appears more than once in tree". The drive firmware installation failure was not observed in configurations having only one external drive enclosure attached to an HP Host Bus Adapter H22x.

### **Enhancements**

#### **Enhancements/New Features:**

- Added support for HP Dynamic Smart Array B140i Controller.

#### **Enhancements/New Features for HPG4 (C):**

- Updated the flash engine to standardize logging across all SATA drive components.
- Enhanced logging capability to improve the details provided in the component log file.
- VMware Firmware Smart component packaging has changed from a \*.scexe package to a \*.zip package, which contains an executable binary that provides enhanced security during installation. The functionality of the VMware Smart Component has not changed.

---

Online ROM Flash Component for VMware ESXi - MK0960GECQK Drives

Version: HPG3 (B) **(Critical)**

Filename: CP029376.zip

### **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**
- **Customers who already installed firmware version HPG3 do not need to update to HPG3 (B).**

## **Fixes**

### **Problems Fixed:**

- Firmware resolves a data mismanagement issue associated with unaligned sequential write operations.

### **Problems Fixed for HPG3 (B):**

- Component would fail to install drive firmware for drives present in a system configured with two or more external drive enclosures attached to an HP Host Bus Adapter H22x. The following message would be reported in the component log file - "Device appears more than once in tree". The drive firmware installation failure was not observed in configurations having only one external drive enclosure attached to an HP Host Bus Adapter H22x.

---

Online ROM Flash Component for VMware ESXi - MM0500GBKAK and MM1000GBKAL Drives

Version: HPGE (**Recommended**)

Filename: CPO30581.zip

## **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**

## **Fixes**

### **Problems Fixed:**

- Corrected a medium level assert that can occur when the host issues resets after >250ms of idle time. If a drive is affected by the issue, it might display reduced performance and possibly would cease to operate. A hot plug removal and insertion of the affected drive temporarily resolves this issue. Update to drive firmware version HPGE to resolve this issue.

---

Online ROM Flash Component for VMware ESXi - MM1000GEFQV and MM2000GEFRA Drives

Version: HPG3 (B) (**Recommended**)

Filename: CPO29381.zip

## **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**

- o **Customers who already installed firmware version HPG3 do not need to update to HPG3 (B).**

## Fixes

### **Problems Fixed:**

- o After HDD power cycle, the Background Media Scan (BGMS) pointer would invoke a second BGMS routine starting at LBA 0, which could affect performance until the second BGMS has completed.
- o When writing to the HDD after it entered or returned from a standby state, the potential existed for a Non Volatile Cache issue to occur.

### **Problems Fixed for HPG3 (B):**

- o Component would fail to install drive firmware for drives present in a system configured with two or more external drive enclosures attached to an HP Host Bus Adapter H22x. The following message would be reported in the component log file - "Device appears more than once in tree". The drive firmware installation failure was not observed in configurations having only one external drive enclosure attached to an HP Host Bus Adapter H22x.

---

Online ROM Flash Component for VMware ESXi - MM1000GFJTE Drives

Version: HPG1 **(Recommended)**

Filename: CPO30832.zip

### **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**

## Fixes

### **Problems Fixed:**

- This firmware improves HDD reliability when HDDs are exposed to long periods of host inactivity that exceed 1 second. HDDs may become unresponsive when using HDD firmware prior to version HPG1.
- This firmware also contains a change which prevents an incorrect reassign status of a repaired sector from being logged.

---

Online ROM Flash Component for VMware ESXi - TK0120GECQL, VK0240GECQN, and VK0480GECQP Drives

Version: HPG3 (B) **(Critical)**

Filename: CPO29387.zip

### **Important Note!**

- o **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- o **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**
- o **Customers who already installed firmware version HPG3 do not need to update to HPG3 (B).**

## Fixes

### Problems Fixed:

- Firmware resolves a data mismanagement issue associated with unaligned sequential write operations.

### Problems Fixed for HPG3 (B):

- Component would fail to install drive firmware for drives present in a system configured with two or more external drive enclosures attached to an HP Host Bus Adapter H22x. The following message would be reported in the component log file - "Device appears more than once in tree". The drive firmware installation failure was not observed in configurations having only one external drive enclosure attached to an HP Host Bus Adapter H22x.

---

Online ROM Flash Component for VMware ESXi - VK0240GDJXU, VK0300GDUQV, VK0480GDJXV, VK0600GDUTQ, and VK0800GDJYA Drives  
Version: HPG1 (C) **(Optional)**

Filename: CP029390.zip

### **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**
- **Customers who already installed firmware version HPG1 do not need to update to HPG1 (C).**

### **Fixes**

#### Problems Fixed:

- This maintenance firmware updates temperature reporting, Sanitize Block Erase and includes read performance improvements.

#### Problems Fixed for HPG1 (C):

- Component would fail to install drive firmware for drives present in a system configured with two or more external drive enclosures attached to an HP Host Bus Adapter H22x. The following message would be reported in the component log file - "Device appears more than once in tree". The drive firmware installation failure was not observed in configurations having only one external drive enclosure attached to an HP Host Bus Adapter H22x.

---

Online ROM Flash Component for VMware ESXi - XP0032GDZME Drives

Version: HPS5 **(Recommended)**

Filename: CP030369.zip

### **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**

### **Fixes**

### Problems Fixed:

- Resolves an issue with the option kit in which an M.2 SSD is installed: when RAID 1 is selected, devices go into a RAID rebuild mode

### Enhancements

#### Enhancements/New Features:

- Enables sanitize device function for HP specific environments
- Adds UECC Read-retry algorithm for timeout handling
- Adds single binary file drive firmware update support

---

Online ROM Flash Component for VMware ESXi - XP0032GEFEN Drives

Version: HPS5 **(Recommended)**

Filename: CPO30372.zip

### Important Note!

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**

### Fixes

#### Problems Fixed:

- Resolves an issue with the option kit in which an M.2 SSD is installed: when RAID 1 is selected, devices go into a RAID rebuild mode

### Enhancements

#### Enhancements/New Features:

- Enables sanitize device function for HP specific environments
- Adds UECC Read-retry algorithm for timeout handling
- Adds single binary file drive firmware update support

---

Online ROM Flash Component for VMware ESXi - XP0064GDZMF Drives

Version: HPS5 **(Recommended)**

Filename: CPO30375.zip

### Important Note!

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**



## Fixes

### Problems Fixed:

- Resolves an issue with the option kit in which an M.2 SSD is installed: when RAID 1 is selected, devices go into a RAID rebuild mode

## Enhancements

### Enhancements/New Features:

- Enables sanitize device function for HP specific environments
- Adds UECC Read-retry algorithm for timeout handling
- Adds single binary file drive firmware update support

---

Online ROM Flash Component for VMware ESXi - XP0064GEFEP Drives

Version: HPS5 **(Recommended)**

Filename: CPO30378.zip

### **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**

## Fixes

### Problems Fixed:

- Resolves an issue with the option kit in which an M.2 SSD is installed: when RAID 1 is selected, devices go into a RAID rebuild mode

## Enhancements

### Enhancements/New Features:

- Enables sanitize device function for HP specific environments
- Adds UECC Read-retry algorithm for timeout handling
- Adds single binary file drive firmware update support

---

Online ROM Flash Component for Windows (x64) - XP0032GDZME Drives

Version: HPS5 **(Recommended)**

Filename: cp030371.exe; cp030371.md5

### **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**

## **Fixes**

### **Problems Fixed:**

- Resolves an issue with the option kit in which an M.2 SSD is installed: when RAID 1 is selected, devices go into a RAID rebuild mode

## **Enhancements**

### **Enhancements/New Features:**

- Enables sanitize device function for HP specific environments
- Adds UECC Read-retry algorithm for timeout handling
- Adds single binary file drive firmware update support
- Added support for Microsoft Windows Server 2016.

---

Online ROM Flash Component for Windows (x64) - XP0032GEFEN Drives

Version: HPS5 (**Recommended**)

Filename: cp030374.exe; cp030374.md5

### **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**

## **Fixes**

### **Problems Fixed:**

- Resolves an issue with the option kit in which an M.2 SSD is installed: when RAID 1 is selected, devices go into a RAID rebuild mode

## **Enhancements**

### **Enhancements/New Features:**

- Enables sanitize device function for HP specific environments
- Adds UECC Read-retry algorithm for timeout handling
- Adds single binary file drive firmware update support
- Added support for Microsoft Windows Server 2016.

---

Online ROM Flash Component for Windows (x64) - XP0064GEFEP Drives

Version: HPS5 (B) (**Recommended**)

Filename: cp031000.exe; cp031000.md5

### **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these**

configurations.

- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**
- **Customers who already installed firmware version HPD5 do not need to update to HPS5 (B).**

## Fixes

### **Problems Fixed:**

- Resolves an issue with the option kit in which an M.2 SSD is installed: when RAID 1 is selected, devices go into a RAID rebuild mode

## Enhancements

### **Enhancements/New Features:**

- Enables sanitize device function for HP specific environments
- Adds UECC Read-retry algorithm for timeout handling
- Adds single binary file drive firmware update support

### **Enhancements/New Features for HPS5 (B):**

- Added support for Microsoft Windows Server 2016.

---

Online ROM Flash Component for Windows (x64) - MB0500GCEHF, MB1000GCEHH, and MB2000GCEHK Drives

Version: HPGD (D) **(Critical)**

Filename: cp029266.exe; cp029266.md5

## Important Note!

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**
- **Customers who already installed firmware version HPGD do not need to update to HPGD (D).**

## Fixes

### **Problems Fixed:**

- After long term use of the HDD, a rare condition might occur following a power cycle where the drive heads may land on areas of the disk containing data, which could potentially cause data loss or mechanical damage. Firmware version HPGD prevents this condition from occurring.

### **Problems Fixed for HPGD(C):**

- The component would fail to flash drive firmware on a server with a Trusted Platform Module (TPM) enabled when using the /tpmbypass switch.

### **Problems Fixed for HPGD (D):**

- Component would fail to install drive firmware for drives present in a system configured with two or more external drive enclosures attached to an HP Host Bus Adapter H22x. The following message would be reported in the component log file - "Device appears more than once in tree". The drive firmware installation failure was not observed in configurations having only one external drive enclosure

attached to an HP Host Bus Adapter H22x.

- Component would cause an exception error when deployed on a computer with a fully qualified domain name greater than 40 characters in length.

## **Enhancements**

### **Enhancements/New Features:**

- The firmware component installer can now install the drive firmware successfully when the new HP ProLiant Smart Array HPCISS3 Controller Driver (**hpciss3.sys**) is running on the system being updated.
- Updated the flash engine to standardize logging across all SATA drive components.
- Enhanced logging capability to improve the details provided in the component log file.
- Added support for Microsoft Windows Server 2016.

---

Online ROM Flash Component for Windows (x64) - MB1000ECWCQ, MB2000ECWCR, MB3000ECWCT, and MB4000ECWCU Drives

Version: HPG5 **(Critical)**

Filename: cp031117.exe; cp031117.md5

### **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**

## **Fixes**

### **Problems Fixed:**

- HPG5 firmware improves drive reliability where disk drives are exposed to long periods of host inactivity which exceed 1 second.

---

Online ROM Flash Component for Windows (x64) - MB1000GCEEK Drives

Version: HPG2 (C) **(Recommended)**

Filename: cp029272.exe; cp029272.md5

### **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**
- **Customers who already installed firmware version HPG2 do not need to update to HPG2 (C).**

## **Fixes**

### **Problems Fixed for HPG2 (B):**

- o The component would fail to flash drive firmware on a server with a Trusted Platform Module (TPM) enabled when using the /tpmbypass switch.

#### **Problems Fixed for HPG2 (C):**

- o Component would fail to install drive firmware for drives present in a system configured with two or more external drive enclosures attached to an HP Host Bus Adapter H22x. The following message would be reported in the component log file - "Device appears more than once in tree". The drive firmware installation failure was not observed in configurations having only one external drive enclosure attached to an HP Host Bus Adapter H22x.
- o Component would cause an exception error when deployed on a computer with a fully qualified domain name greater than 40 characters in length.

### **Enhancements**

#### **Enhancements/New Features:**

- o This firmware improves reliability by modifying the pivot bearing grease wear leveling algorithm, which if not implemented, could result in an increased drive failure rate for specific usage applications (eg, very long periods of small range seeks).
- o Added support for Microsoft Windows Server 2016.

---

Online ROM Flash Component for Windows (x64) - MB1000GCWCV, MB2000GCWDA, MB3000GCWDB, and MB4000GCWDC Drives

Version: HPGH (B) **(Critical)**

Filename: cp030994.exe; cp030994.md5

### **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**
- **Customers who already installed firmware version HPD5 do not need to update to HPGH (B).**

### **Fixes**

#### **Problems Fixed:**

- o HPGH firmware improves drive reliability where disk drives are exposed to long periods of host inactivity which exceed 1 second. As a result, hard disk drives may become unresponsive.

### **Enhancements**

#### **Enhancements/New Features for HPGH (B):**

- Added support for Microsoft Windows Server 2016.

---

Online ROM Flash Component for Windows (x64) - MB1000GDUNU, MB2000GDUNV, MB3000GDUPA, and MB4000GDUPB Drives

Version: HPG4 **(Recommended)**

Filename: cp030808.exe; cp030808.md5

### **Important Note!**

- **Online firmware flashing of drives attached to an HP Smart Array controller running in Zero Memory (ZM) mode or an HP ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux and Microsoft Windows environments. All other OSes would require an offline update using the SPP and HP SUM.**

## Fixes

### **Problems Fixed:**

- Reliability enhancement for applications that write data to a narrow range of tracks.

### **Known Issues:**

- Firmware cannot be downgraded to HPG3 after updating to HPG4.

## Enhancements

### **Enhancements/New Features:**

- Added support for Microsoft Windows Server 2016.

---

Online ROM Flash Component for Windows (x64) - MB2000EAZNL Drives

Version: HPG4 (D) **(Optional)**

Filename: cp029273.exe; cp029273.md5

## Important Note!

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**
- **Customers who already installed firmware version HPG4 do not need to update to HPG4 (D).**

## Fixes

### **Problems Fixed:**

- This firmware contains general maintenance release and code improvement items. Drives built with or upgraded to hard drive firmware version HPG4 should not be downgraded to an earlier version of firmware due to hard drive manufacturing process changes.

### **Problems Fixed for HPG4 (C):**

- The component would fail to flash drive firmware on a server with a Trusted Platform Module (TPM) enabled when using the /tpmbypass switch.

### **Problems Fixed for HPG4 (D):**

- Component would fail to install drive firmware for drives present in a system configured with two or more external drive enclosures attached to an HP Host Bus Adapter H22x. The following message would be reported in the component log file - "Device appears more than once in tree". The drive firmware installation failure was not observed in configurations having only one external drive enclosure attached to an HP Host Bus Adapter H22x.

Component would cause an exception error when deployed on a computer with a fully qualified domain name greater than 40 characters in length.

## **Enhancements**

### **Enhancements/New Features:**

- Improvements have been made to enhance drive reliability, performance and handle sudden shock situations.
- Updated the flash engine to standardize logging across all SATA drive components.
- Enhanced logging capability to improve the details provided in the component log file.
- Added support for Microsoft Windows Server 2016.

---

Online ROM Flash Component for Windows (x64) - MB2000EBUCF and MB3000EBUCH Drives

Version: HPG4 (D) **(Recommended)**

Filename: cp029274.exe; cp029274.md5

## **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**
- **Customers who already installed firmware version HPG4 do not need to update to HPG4 (D).**

## **Fixes**

### **Problems Fixed:**

- The system did not recognize some drives after a power-cycle. This is due to the drive initialization process being interrupted by a reset, causing the drive to take more time than allotted to report commands.

### **Problems Fixed for HPG4 (C):**

- The component would fail to flash drive firmware on a server with a Trusted Platform Module (TPM) enabled when using the /tpmbypass switch.

### **Problems Fixed for HPG4 (D):**

- Component would fail to install drive firmware for drives present in a system configured with two or more external drive enclosures attached to an HP Host Bus Adapter H22x. The following message would be reported in the component log file - "Device appears more than once in tree". The drive firmware installation failure was not observed in configurations having only one external drive enclosure attached to an HP Host Bus Adapter H22x.
- Component would cause an exception error when deployed on a computer with a fully qualified domain name greater than 40 characters in length.

## **Enhancements**

### **Enhancements/New Features:**

- Improvements have been made to enhance drive reliability, performance and handle sudden shock situations.
- Updated the flash engine to standardize logging across all SATA drive components.
- Enhanced logging capability to improve the details provided in the component log file.

- o Added support for Microsoft Windows Server 2016.

---

Online ROM Flash Component for Windows (x64) - MB2000ECVJF, MB3000ECVJH, and MB4000ECVJK Drives

Version: HPG5 (C) **(Critical)**

Filename: cp029275.exe; cp029275.md5

### **Important Note!**

- o **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- o **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**
- o **Customers who already installed firmware version HPG5 do not need to update to HPG5 (C).**

### **Fixes**

#### **Problem Fixed:**

- o Fixes a rare but potential data integrity error during low 5v drive voltage and specific sequential data streaming conditions, which could result in data written to incorrect sectors.

#### **Problems Fixed for HPG5 (B):**

- o The component would fail to flash drive firmware on a server with a Trusted Platform Module (TPM) enabled when using the /tpmbypass switch.

#### **Problems Fixed for HPG5 (C):**

- o Component would fail to install drive firmware for drives present in a system configured with two or more external drive enclosures attached to an HP Host Bus Adapter H22x. The following message would be reported in the component log file - "Device appears more than once in tree". The drive firmware installation failure was not observed in configurations having only one external drive enclosure attached to an HP Host Bus Adapter H22x.
- o Component would cause an exception error when deployed on a computer with a fully qualified domain name greater than 40 characters in length.

### **Enhancements**

#### **Enhancements/New Features:**

- o Improvements have been made to enhance drive reliability, performance and handle sudden shock situations.
- o Updated the flash engine to standardize logging across all SATA drive components.
- o Enhanced logging capability to improve the details provided in the component log file.
- o Added support for Microsoft Windows Server 2016.

---

Online ROM Flash Component for Windows (x64) - MB2000ECWLP, MB3000ECWLQ, and MB4000ECWLR Drives

Version: HPG4 **(Recommended)**

Filename: cp030518.exe; cp030518.md5

### **Important Note!**

- o **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE**



**ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**

- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**

## Fixes

### **Problems Fixed:**

- Improves the drive idle time behavior by reducing long periods of track dwell time, which if not implemented, could increase media lube depletion and reduce drive reliability.

## Enhancements

### **Enhancements/New Features:**

- Added support for Microsoft Windows Server 2016.

---

Online ROM Flash Component for Windows (x64) - MB2000GBUPB and MB3000GBUCK Drives

Version: HPG4 (D) **(Recommended)**

Filename: cp029279.exe; cp029279.md5

## Important Note!

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**
- **Customers who already installed firmware version HPG4 do not need to update to HPG4 (D).**

## Fixes

### **Problems Fixed:**

- The system did not recognize some drives after a power-cycle. This is due to the drive initialization process being interrupted by a reset, causing the drive to take more time than allotted to report commands.

### **Problems Fixed for HPG4 (C):**

- The component would fail to flash drive firmware on a server with a Trusted Platform Module (TPM) enabled when using the /tpmbypass switch.

### **Problems Fixed for HPG4 (D):**

- Component would fail to install drive firmware for drives present in a system configured with two or more external drive enclosures attached to an HP Host Bus Adapter H22x. The following message would be reported in the component log file - "Device appears more than once in tree". The drive firmware installation failure was not observed in configurations having only one external drive enclosure attached to an HP Host Bus Adapter H22x.
- Component would cause an exception error when deployed on a computer with a fully qualified domain name greater than 40 characters in length.

## Enhancements

### Enhancements/New Features:

- Improvements have been made to enhance drive reliability, performance and handle sudden shock situations.
- Updated the flash engine to standardize logging across all SATA drive components.
- Enhanced logging capability to improve the details provided in the component log file.
- Added support for Microsoft Windows Server 2016.

---

Online ROM Flash Component for Windows (x64) - MB2000GCQXQ and MB3000GBKAC Drives

Version: HPGK **(Recommended)**

Filename: cp030684.exe; cp030684.md5

### **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**

### **Fixes**

#### **Problem Fixed:**

- HP ProLiant servers would power down due a hard drive over temp condition that was falsely reported. Hard disk drive firmware HPGK resolves this issue.

## Enhancements

### Enhancements/New Features:

- Added support for Microsoft Windows Server 2016.

---

Online ROM Flash Component for Windows (x64) - MB2000GCVBR, MB3000GCVBT, and MB4000GCVBU Drives

Version: HPG5 (C) **(Critical)**

Filename: cp029280.exe; cp029280.md5

### **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**
- **Customers who already installed firmware version HPG5 do not need to update to HPG5 (C).**

### **Fixes**

#### **Problem Fixed:**

Fixes a rare but potential data integrity error during low 5v drive voltage and specific sequential data streaming conditions, which could result in data written to incorrect sectors.

#### **Problems Fixed for HPG5 (B):**

- The component would fail to flash drive firmware on a server with a Trusted Platform Module (TPM) enabled when using the /tpmbypass switch.

#### **Problems Fixed for HPG5 (C):**

- Component would fail to install drive firmware for drives present in a system configured with two or more external drive enclosures attached to an HP Host Bus Adapter H22x. The following message would be reported in the component log file - "Device appears more than once in tree". The drive firmware installation failure was not observed in configurations having only one external drive enclosure attached to an HP Host Bus Adapter H22x.
- Component would cause an exception error when deployed on a computer with a fully qualified domain name greater than 40 characters in length.

### **Enhancements**

#### **Enhancements/New Features:**

- Improvements have been made to enhance drive reliability, performance and handle sudden shock situations.
- Updated the flash engine to standardize logging across all SATA drive components.
- Enhanced logging capability to improve the details provided in the component log file.
- Added support for Microsoft Windows Server 2016.

---

Online ROM Flash Component for Windows (x64) - MB2000GCWLT, MB3000GCWLU, and MB4000GCWLX Drives

Version: HPG4 (**Recommended**)

Filename: cp030521.exe; cp030521.md5

### **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**

### **Fixes**

#### **Problems Fixed:**

- Improves the drive idle time behavior by reducing long periods of track dwell time, which if not implemented, could increase media lube depletion and reduce drive reliability.

### **Enhancements**

#### **Enhancements/New Features:**

- Added support for Microsoft Windows Server 2016.

---

Online ROM Flash Component for Windows (x64) - MB3000EBKAB Drives

### **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**
- **Customers who already installed firmware version HPG6 do not need to update to HPG6 (D).**

### **Fixes**

#### **Problems Fixed:**

- After long term use of the HDD, a rare condition might occur following a power cycle where the drive heads may land on areas of the disk containing data, which could potentially cause data loss or mechanical damage. Firmware version HPG6 prevents this condition from occurring.
- This firmware corrects "command timeouts" and seek errors which can result in poor performance or a Device Fault condition, the latter of which will result in the drive failed by the Controller or sub system.

#### **Problems Fixed for HPG6 (C):**

- The component would fail to flash drive firmware on a server with a Trusted Platform Module (TPM) enabled when using the /tpmbypass switch.

#### **Problems Fixed for HPG6 (D):**

- Component would fail to install drive firmware for drives present in a system configured with two or more external drive enclosures attached to an HP Host Bus Adapter H22x. The following message would be reported in the component log file - "Device appears more than once in tree". The drive firmware installation failure was not observed in configurations having only one external drive enclosure attached to an HP Host Bus Adapter H22x.
- Component would cause an exception error when deployed on a computer with a fully qualified domain name greater than 40 characters in length.

### **Enhancements**

#### **Enhancements/New Features:**

- The firmware component installer can now install the drive firmware successfully when the new HP ProLiant Smart Array HPCISS3 Controller Driver (**hpciss3.sys**) is running on the system being updated.

#### **Enhancements/New Features for (B):**

- Updated the flash engine to standardize logging across all SATA drive components.
- Enhanced logging capability to improve the details provided in the component log file.
- Added support for Microsoft Windows Server 2016.

### **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**

### **Fixes**

#### **Problems Fixed:**

- This firmware improves HDD reliability when HDDs are exposed to long periods of host inactivity that exceed 1 second. HDDs may become unresponsive when using HDD firmware prior to version HPG4. This firmware also contains a change which prevents an incorrect reassign status of a repaired sector from being logged.

### **Enhancements**

#### **Enhancements/New Features:**

- Added support for Microsoft Windows Server 2016.

---

Online ROM Flash Component for Windows (x64) - MB4000GEQNH and MB6000GEQNK Drives

Version: HPG7 (C) **(Recommended)**

Filename: cp029284.exe; cp029284.md5

### **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**
- **Customers who already installed firmware version HPG7 do not need to update to HPG7 (C).**

### **Fixes**

#### **Problems Fixed:**

- This firmware corrects possible unrecovered errors caused by the track refresh algorithm not working properly.

#### **Problems Fixed for HPG7 (B):**

- The component would fail to flash drive firmware on a server with a Trusted Platform Module (TPM) enabled when using the /tpmbypass switch.

#### **Problems Fixed for HPG7 (C):**

- Component would fail to install drive firmware for drives present in a system configured with two or more external drive enclosures attached to an HP Host Bus Adapter H22x. The following message would be reported in the component log file - "Device appears more than once in tree". The drive firmware installation failure was not observed in configurations having only one external drive enclosure attached to an HP Host Bus Adapter H22x.

Component would cause an exception error when deployed on a computer with a fully qualified domain name greater than 40 characters in length.

## **Enhancements**

### **Enhancements/New Features:**

- Added support for Microsoft Windows Server 2016.

---

Online ROM Flash Component for Windows (x64) - MB6000GEQUT and MB8000GEQUU Drives

Version: HPG7 (C) **(Recommended)**

Filename: cp029288.exe; cp029288.md5

## **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**
- **Customers who already installed firmware version HPG7 do not need to update to HPG7 (C).**

## **Fixes**

### **Problems Fixed:**

- This firmware corrects possible unrecovered errors caused by the track refresh algorithm not working properly.

### **Problems Fixed for HPG7 (B):**

- The component would fail to flash drive firmware on a server with a Trusted Platform Module (TPM) enabled when using the /tpmbypass switch.

### **Problems Fixed for HPG7 (C):**

- Component would fail to install drive firmware for drives present in a system configured with two or more external drive enclosures attached to an HP Host Bus Adapter H22x. The following message would be reported in the component log file - "Device appears more than once in tree". The drive firmware installation failure was not observed in configurations having only one external drive enclosure attached to an HP Host Bus Adapter H22x.
- Component would cause an exception error when deployed on a computer with a fully qualified domain name greater than 40 characters in length.

## **Enhancements**

### **Enhancements/New Features:**

- Added support for Microsoft Windows Server 2016.

---

Online ROM Flash Component for Windows (x64) - MB6000GEXXV Drives

Version: HPG2 **(Recommended)**

Filename: cp030840.exe; cp030840.md5

### **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**

### **Fixes**

#### **Problems Fixed:**

- Reliability enhancement for applications that write data to a narrow range of tracks.

### **Enhancements**

#### **Enhancements/New Features:**

- Added support for Microsoft Windows Server 2016.

---

Online ROM Flash Component for Windows (x64) - MB8000GFECR Drives

Version: HPG3 **(Recommended)**

Filename: cp030844.exe; cp030844.md5

### **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**

### **Fixes**

#### **Problems Fixed:**

- This firmware improves HDD reliability when HDDs are exposed to long periods of host inactivity that exceed 1 second. HDDs may become unresponsive when using HDD firmware prior to version HPG3.

### **Enhancements**

#### **Enhancements/New Features:**

- Added support for Microsoft Windows Server 2016.

---

Online ROM Flash Component for Windows (x64) - MK0100GCTYU, MK0200GCTYV, MK0400GCTZA, and MK0800GCTZB Drives

Version: HPG4 (D) **(Optional)**

Filename: cp029289.exe; cp029289.md5

### **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSES would require an offline update using the SPP and HP SUM.**
- **Customers who already installed firmware version HPG4 do not need to update to HPG4 (D).**

## **Fixes**

### **Problems Fixed:**

- This maintenance release corrects a failure seen during a HP Insight Diagnostic hard drive test. The failure was due to Device Extended Self-Test not completing in the drives advertised Self-Test completion time. This failure is not an indication that the drive is bad or marginal.

### **Problems Fixed for HPG4 (C):**

- The component would fail to flash drive firmware on a server with a Trusted Platform Module (TPM) enabled when using the /tpmbypass switch.

### **Problems Fixed for HPG4 (D):**

- Component would fail to install drive firmware for drives present in a system configured with two or more external drive enclosures attached to an HP Host Bus Adapter H22x. The following message would be reported in the component log file - "Device appears more than once in tree". The drive firmware installation failure was not observed in configurations having only one external drive enclosure attached to an HP Host Bus Adapter H22x.
- Component would cause an exception error when deployed on a computer with a fully qualified domain name greater than 40 characters in length.

## **Enhancements**

### **Enhancements/New Features:**

- Improvements have been made to enhance drive reliability, performance and handle sudden shock situations.
- Updated the flash engine to standardize logging across all SATA drive components.
- Enhanced logging capability to improve the details provided in the component log file.
- Added support for Microsoft Windows Server 2016.

---

Online ROM Flash Component for Windows (x64) - MK0960GECQK Drives

Version: HPG3 (C) **(Critical)**

Filename: cp029290.exe; cp029290.md5

## **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSES would require an offline update using the SPP and HP SUM.**
- **Customers who already installed firmware version HPG3 do not need to update to HPG3 (C).**

## **Fixes**



### Problems Fixed:

- Firmware resolves a data mismanagement issue associated with unaligned sequential write operations.

### Problems Fixed for HPG3 (B):

- The component would fail to flash drive firmware on a server with a Trusted Platform Module (TPM) enabled when using the /tpmbypass switch.

### Problems Fixed for HPG3 (C):

- Component would fail to install drive firmware for drives present in a system configured with two or more external drive enclosures attached to an HP Host Bus Adapter H22x. The following message would be reported in the component log file - "Device appears more than once in tree". The drive firmware installation failure was not observed in configurations having only one external drive enclosure attached to an HP Host Bus Adapter H22x.
- Component would cause an exception error when deployed on a computer with a fully qualified domain name greater than 40 characters in length.

## Enhancements

### Enhancements/New Features:

- Added support for Microsoft Windows Server 2016.

---

Online ROM Flash Component for Windows (x64) - MM0500GBKAK and MM1000GBKAL Drives

Version: HPGE **(Recommended)**

Filename: cp030583.exe; cp030583.md5

### Important Note!

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**

## Fixes

### Problems Fixed:

- Corrected a medium level assert that can occur when the host issues resets after >250ms of idle time. If a drive is affected by the issue, it might display reduced performance and possibly would cease to operate. A hot plug removal and insertion of the affected drive temporarily resolves this issue. Update to drive firmware version HPGE to resolve this issue.

## Enhancements

### Enhancements/New Features:

- Added support for Microsoft Windows Server 2016.

---

Online ROM Flash Component for Windows (x64) - MM1000GEFQV and MM2000GEFRA Drives

Version: HPG3 (B) **(Recommended)**

### **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSES would require an offline update using the SPP and HP SUM.**
- **Customers who already installed firmware version HPG3 do not need to update to HPG3 (B).**

### **Fixes**

#### **Problems Fixed:**

- After HDD power cycle, the Background Media Scan (BGMS) pointer would invoke a second BGMS routine starting at LBA 0, which could affect performance until the second BGMS has completed.
- When writing to the HDD after it entered or returned from a standby state, the potential existed for a Non Volatile Cache issue to occur.
- The component would fail to flash drive firmware on a server with a Trusted Platform Module (TPM) enabled when using the /tpmbypass switch.

#### **Problems Fixed for HPG3 (B):**

- Component would fail to install drive firmware for drives present in a system configured with two or more external drive enclosures attached to an HP Host Bus Adapter H22x. The following message would be reported in the component log file - "Device appears more than once in tree". The drive firmware installation failure was not observed in configurations having only one external drive enclosure attached to an HP Host Bus Adapter H22x.
- Component would cause an exception error when deployed on a computer with a fully qualified domain name greater than 40 characters in length.

### **Enhancements**

#### **Enhancements/New Features:**

- Added support for Microsoft Windows Server 2016.

---

Online ROM Flash Component for Windows (x64) - MM1000GFJTE Drives

Version: HPG1 (**Recommended**)

Filename: cp030834.exe; cp030834.md5

### **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSES would require an offline update using the SPP and HP SUM.**

### **Fixes**

#### **Problems Fixed:**

- This firmware improves HDD reliability when HDDs are exposed to long periods of host inactivity that exceed 1 second. HDDs may

become unresponsive when using HDD firmware prior to version HPG1.

- This firmware also contains a change which prevents an incorrect reassign status of a repaired sector from being logged.

## **Enhancements**

### **Enhancements/New Features:**

- Added support for Microsoft Windows Server 2016.

---

Online ROM Flash Component for Windows (x64) - MO0100EBTJT, MO0200EBTJU, and MO0400EBTJV drives

Version: HPG4 (C) **(Optional)**

Filename: cp029297.exe; cp029297.md5

## **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSES would require an offline update using the SPP and HP SUM.**
- **Customers who already installed firmware version HPG4 do not need to update to HPG4 (C).**

## **Fixes**

### **Problems Fixed:**

- Firmware version HPG4 resolved a wear-out issue which was caused by frequently issued PIO commands and resulted in a non-responsive drive.

### **Problems Fixed for HPG4 (B):**

- The component would fail to flash drive firmware on a server with a Trusted Platform Module (TPM) enabled when using the /tpmbypass switch.

### **Problems Fixed for HPG4 (C):**

- Component would fail to install drive firmware for drives present in a system configured with two or more external drive enclosures attached to an HP Host Bus Adapter H22x. The following message would be reported in the component log file - "Device appears more than once in tree". The drive firmware installation failure was not observed in configurations having only one external drive enclosure attached to an HP Host Bus Adapter H22x.
- Component would cause an exception error when deployed on a computer with a fully qualified domain name greater than 40 characters in length.

## **Enhancements**

### **Enhancements/New Features:**

- Added support for Microsoft Windows Server 2016.

---

Online ROM Flash Component for Windows (x64) - TK0120GECQL, VK0240GECQN, and VK0480GECQP Drives

Version: HPG3 (C) **(Critical)**

Filename: cp029301.exe; cp029301.md5

### **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**
- **Customers who already installed firmware version HPG3 do not need to update to HPG3 (C).**

### **Fixes**

#### **Problems Fixed:**

- Firmware resolves a data mismanagement issue associated with unaligned sequential write operations.

#### **Problems Fixed for HPG3 (B):**

- The component would fail to flash drive firmware on a server with a Trusted Platform Module (TPM) enabled when using the /tpmbypass switch.

#### **Problems Fixed for HPG3 (C):**

- Component would fail to install drive firmware for drives present in a system configured with two or more external drive enclosures attached to an HP Host Bus Adapter H22x. The following message would be reported in the component log file - "Device appears more than once in tree". The drive firmware installation failure was not observed in configurations having only one external drive enclosure attached to an HP Host Bus Adapter H22x.
- Component would cause an exception error when deployed on a computer with a fully qualified domain name greater than 40 characters in length.

### **Enhancements**

#### **Enhancements/New Features:**

- Added support for Microsoft Windows Server 2016.

---

Online ROM Flash Component for Windows (x64) - VB0160EAVEQ and VB0160CBCDE Drives

Version: HPG9 (D) **(Recommended)**

Filename: cp029302.exe; cp029302.md5

### **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**
- **Customers who already installed firmware version HPG9 do not need to update to HPG9 (D).**

### **Fixes**

#### **Problems Fixed:**

This firmware corrects the possibility of the drive becoming unresponsive and requiring a power cycle following a soft system reboot. This behavior appears as if the drive is no longer attached to the system following the system soft reboot. It is most often observed during Operating System Installation but can occur following any system soft reboot.

#### **Problems Fixed for HPG9 (C):**

- The component would fail to flash drive firmware on a server with a Trusted Platform Module (TPM) enabled when using the /tpmbypass switch.

#### **Problems Fixed for HPG9 (D):**

- Component would fail to install drive firmware for drives present in a system configured with two or more external drive enclosures attached to an HP Host Bus Adapter H22x. The following message would be reported in the component log file - "Device appears more than once in tree". The drive firmware installation failure was not observed in configurations having only one external drive enclosure attached to an HP Host Bus Adapter H22x.
- Component would cause an exception error when deployed on a computer with a fully qualified domain name greater than 40 characters in length.

### **Enhancements**

#### **Enhancements/New Features:**

- The firmware component installer can now install the drive firmware successfully when the new HP ProLiant Smart Array HPCISS3 Controller Driver (**hpciss3.sys**) is running on the system being updated.

#### **Enhancements/New Features for (B):**

- Updated the flash engine to standardize logging across all SATA drive components.
- Enhanced logging capability to improve the details provided in the component log file.
- Added support for Microsoft Windows Server 2016.

---

Online ROM Flash Component for Windows (x64) - VB0250EAVR Drives

Version: HPG9 (D) **(Recommended)**

Filename: cp029303.exe; cp029303.md5

### **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSES would require an offline update using the SPP and HP SUM.**
- **Customers who already installed firmware version HPG9 do not need to update to HPG9 (D).**

### **Fixes**

#### **Problems Fixed:**

- This firmware corrects the possibility of the drive becoming unresponsive and requiring a power cycle following a soft system reboot. This behavior appears as if the drive is no longer attached to the system following the system soft reboot. It is most often observed during Operating System Installation but can occur following any system soft reboot.

### Problems Fixed for HPG9 (C):

- The component would fail to flash drive firmware on a server with a Trusted Platform Module (TPM) enabled when using the /tpmbypass switch.

### Problems Fixed for HPG9 (D):

- Component would fail to install drive firmware for drives present in a system configured with two or more external drive enclosures attached to an HP Host Bus Adapter H22x. The following message would be reported in the component log file - "Device appears more than once in tree". The drive firmware installation failure was not observed in configurations having only one external drive enclosure attached to an HP Host Bus Adapter H22x.
- Component would cause an exception error when deployed on a computer with a fully qualified domain name greater than 40 characters in length.

## Enhancements

### Enhancements/New Features:

- The firmware component installer can now install the drive firmware successfully when the new HP ProLiant Smart Array HPCISS3 Controller Driver (**hpcisss3.sys**) is running on the system being updated.

### Enhancements/New Features for (B):

- Updated the flash engine to standardize logging across all SATA drive components.
- Enhanced logging capability to improve the details provided in the component log file.
- Added support for Microsoft Windows Server 2016.

---

Online ROM Flash Component for Windows (x64) - VK0240GDJXU, VK0300GDUQV, VK0480GDJXV, VK0600GDUTQ, and VK0800GDJYA Drives  
Version: HPG1 (C) **(Optional)**  
Filename: cp029304.exe; cp029304.md5

## Important Note!

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**
- **Customers who already installed firmware version HPG1 do not need to update to HPG1 (C).**

## Fixes

### Problems Fixed:

- This maintenance firmware updates temperature reporting, Sanitize Block Erase and includes read performance improvements.

### Problems Fixed for HPG1 (B):

- The component would fail to flash drive firmware on a server with a Trusted Platform Module (TPM) enabled when using the /tpmbypass switch.

### Problems Fixed for HPG1 (C):

- Component would fail to install drive firmware for drives present in a system configured with two or more external drive enclosures attached to an HP Host Bus Adapter H22x. The following message would be reported in the component log file - "Device appears more

than once in tree". The drive firmware installation failure was not observed in configurations having only one external drive enclosure attached to an HP Host Bus Adapter H22x.

- Component would cause an exception error when deployed on a computer with a fully qualified domain name greater than 40 characters in length.

## **Enhancements**

### **Enhancements/New Features:**

- Added support for Microsoft Windows Server 2016.

---

Online ROM Flash Component for Windows (x64) - XP0064GDZMF Drives

Version: HPS5 (B) **(Recommended)**

Filename: cp030999.exe; cp030999.md5

### **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSES would require an offline update using the SPP and HP SUM.**
- **Customers who already installed firmware version HPD5 do not need to update to HPS5 (B).**

## **Fixes**

### **Problems Fixed:**

- Resolves an issue with the option kit in which an M.2 SSD is installed: when RAID 1 is selected, devices go into a RAID rebuild mode

## **Enhancements**

### **Enhancements/New Features:**

- Enables sanitize device function for HP specific environments
- Adds UECC Read-retry algorithm for timeout handling
- Adds single binary file drive firmware update support

### **Enhancements/New Features for HPS5 (B):**

- Added support for Microsoft Windows Server 2016.

---

Online ROM Flash Component for Windows - MB0500GCEHF, MB1000GCEHH, and MB2000GCEHK Drives

Version: HPGD (B) **(Critical)**

Filename: cp020453.exe; cp020453.md5

### **Important Note!**

- **Online firmware flashing of drives attached to an HP Smart Array controller running in Zero Memory (ZM) mode or an HP ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**

**Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux and Microsoft Windows environments. All other OSES would require an offline update using the SPP and HP SUM.**

- o **Customers who already installed firmware version HPGD do not need to update to HPGD(B).**

## Fixes

### **Problems Fixed:**

- o After long term use of the HDD, a rare condition might occur following a power cycle where the drive heads may land on areas of the disk containing data, which could potentially cause data loss or mechanical damage. Firmware version HPGD prevents this condition from occurring.

## Enhancements

### **Enhancements/New Features:**

- o The firmware component installer can now install the drive firmware successfully when the new HP ProLiant Smart Array HPCISS3 Controller Driver (**hpciss3.sys**) is running on the system being updated.

---

Online ROM Flash Component for Windows - MB1000ECWCQ, MB2000ECWCR, MB3000ECWCT, and MB4000ECWCU Drives

Version: HPG5 **(Critical)**

Filename: cp031119.exe; cp031119.md5

## Important Note!

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSES would require an offline update using the SPP and HP SUM.**

## Fixes

### **Problems Fixed:**

- HPG5 firmware improves drive reliability where disk drives are exposed to long periods of host inactivity which exceed 1 second.

---

Online ROM Flash Component for Windows - MB1000GCWCV, MB2000GCWDA, MB3000GCWDB, and MB4000GCWDC Drives

Version: HPGH **(Critical)**

Filename: cp029175.exe; cp029175.md5

## Important Note!

- o **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- o **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSES would require an offline update using the SPP and HP SUM.**

## Fixes



### Problems Fixed:

- HPGH firmware improves drive reliability where disk drives are exposed to long periods of host inactivity which exceed 1 second. As a result, hard disk drives may become unresponsive.

---

Online ROM Flash Component for Windows - MB2000EAZNL Drives

Version: HPG4 **(Optional)**

Filename: cp020390.exe; cp020390.md5

### **Important Note!**

- **Online firmware flashing of drives attached to an HP Smart Array controller running in Zero Memory (ZM) mode or an HP ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**

### **Fixes**

#### **Problems Fixed:**

- This firmware contains general maintenance release and code improvement items. Drives built with or upgraded to hard drive firmware version HPG4 should not be downgraded to an earlier version of firmware due to hard drive manufacturing process changes.

---

Online ROM Flash Component for Windows - MB2000EBUGF and MB3000EBUGH Drives

Version: HPG4 **(Recommended)**

Filename: cp020667.exe; cp020667.md5

### **Important Note!**

- **Online firmware flashing of drives attached to an HP Smart Array controller running in Zero Memory (ZM) mode or an HP ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**

### **Fixes**

#### **Problems Fixed:**

- The system did not recognize some drives after a power-cycle. This is due to the drive initialization process being interrupted by a reset, causing the drive to take more time than allotted to report commands.

---

Online ROM Flash Component for Windows - MB2000ECVJF, MB3000ECVJH, and MB4000ECVJK Drives

Version: HPG5 **(Critical)**

Filename: cp025326.exe; cp025326.md5

### **Important Note!**

- **Online firmware flashing of drives attached to an HP Smart Array controller running in Zero Memory (ZM) mode or an HP ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these**

**configurations.**

- o **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSES would require an offline update using the SPP and HP SUM.**

## **Fixes**

### **Problem Fixed:**

- o Fixes a rare but potential data integrity error during low 5v drive voltage and specific sequential data streaming conditions, which could result in data written to incorrect sectors.

---

Online ROM Flash Component for Windows - MB2000GBUPB and MB3000GBUCK Drives

Version: HPG4 **(Recommended)**

Filename: cp020664.exe; cp020664.md5

## **Important Note!**

- o **Online firmware flashing of drives attached to an HP Smart Array controller running in Zero Memory (ZM) mode or an HP ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- o **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSES would require an offline update using the SPP and HP SUM.**

## **Fixes**

### **Problems Fixed:**

- o The system did not recognize some drives after a power-cycle. This is due to the drive initialization process being interrupted by a reset, causing the drive to take more time than allotted to report commands.

---

Online ROM Flash Component for Windows - MB2000GCQXQ and MB3000GBKAC Drives

Version: HPGK **(Recommended)**

Filename: cp030680.exe; cp030680.md5

## **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSES would require an offline update using the SPP and HP SUM.**

## **Fixes**

### **Problem Fixed:**

- HP ProLiant servers would power down due a hard drive over temp condition that was falsely reported. Hard disk drive firmware HPGK resolves this issue.

---

Online ROM Flash Component for Windows - MB2000GCVBR, MB3000GCVBT, and MB4000GCVBU Drives

Version: HPG5 **(Critical)**

Filename: cp025321.exe; cp025321.md5

### **Important Note!**

- **Online firmware flashing of drives attached to an HP Smart Array controller running in Zero Memory (ZM) mode or an HP ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSES would require an offline update using the SPP and HP SUM.**

### **Fixes**

#### **Problem Fixed:**

- Fixes a rare but potential data integrity error during low 5v drive voltage and specific sequential data streaming conditions, which could result in data written to incorrect sectors.

---

Online ROM Flash Component for Windows - MB3000EBKAB Drives

Version: HPG6 (B) **(Critical)**

Filename: cp020461.exe; cp020461.md5

### **Important Note!**

- **Online firmware flashing of drives attached to an HP Smart Array controller running in Zero Memory (ZM) mode or an HP ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux and Microsoft Windows environments. All other OSES would require an offline update using the SPP and HP SUM.**
- **Customers who already installed firmware version HPG6 do not need to update to HPG6(B).**

### **Fixes**

#### **Problems Fixed:**

- After long term use of the HDD, a rare condition might occur following a power cycle where the drive heads may land on areas of the disk containing data, which could potentially cause data loss or mechanical damage. Firmware version HPG6 prevents this condition from occurring.
- This firmware corrects "command timeouts" and seek errors which can result in poor performance or a Device Fault condition, the latter of which will result in the drive failed by the Controller or sub system.

### **Enhancements**

#### **Enhancements/New Features:**

- The firmware component installer can now install the drive firmware successfully when the new HP ProLiant Smart Array HPCISS3 Controller Driver (**hpciss3.sys**) is running on the system being updated.

---

Online ROM Flash Component for Windows - MK0100GCTYU, MK0200GCTYV, MK0400GCTZA, and MK0800GCTZB Drives

Version: HPG4 **(Optional)**

### **Important Note!**

- **Online firmware flashing of drives attached to an HP Smart Array controller running in Zero Memory (ZM) mode or an HP ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**

### **Fixes**

#### **Problems Fixed:**

- This maintenance release corrects a failure seen during a HP Insight Diagnostic hard drive test. The failure was due to Device Extended Self-Test not completing in the drives advertised Self-Test completion time. This failure is not an indication that the drive is bad or marginal.

---

Online ROM Flash Component for Windows - MM0500GBKAK and MM1000GBKAL Drives

Version: HPGE **(Recommended)**

Filename: cp030584.exe; cp030584.md5

### **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**

### **Fixes**

#### **Problems Fixed:**

- Corrected a medium level assert that can occur when the host issues resets after >250ms of idle time. If a drive is affected by the issue, it might display reduced performance and possibly would cease to operate. A hot plug removal and insertion of the affected drive temporarily resolves this issue. Update to drive firmware version HPGE to resolve this issue.

---

Online ROM Flash Component for Windows - MO0100EBTJT, MO0200EBTJU, and MO0400EBTJV drives

Version: HPG4 **(Optional)**

Filename: cp024525.exe; cp024525.md5

### **Important Note!**

- **Online firmware flashing of drives attached to an HP Smart Array controller running in Zero Memory (ZM) mode or an HP ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**

### **Fixes**

### Problems Fixed:

- Firmware version HPG4 resolved a wear-out issue which was caused by frequently issued PIO commands and resulted in a non-responsive drive.

---

Online ROM Flash Component for Windows - VB0160EAVEQ and VB0160CBCDE Drives

Version: HPG9 (B) **(Recommended)**

Filename: cp020477.exe; cp020477.md5

### **Important Note!**

- **Online firmware flashing of drives attached to an HP Smart Array controller running in Zero Memory (ZM) mode or an HP ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux and Microsoft Windows environments. All other OSes would require an offline update using the SPP and HP SUM.**
- **Customers who already installed firmware version HPG9 do not need to update to HPG9(B).**

### **Fixes**

#### **Problems Fixed:**

- This firmware corrects the possibility of the drive becoming unresponsive and requiring a power cycle following a soft system reboot. This behavior appears as if the drive is no longer attached to the system following the system soft reboot. It is most often observed during Operating System Installation but can occur following any system soft reboot.

### **Enhancements**

#### **Enhancements/New Features:**

- The firmware component installer can now install the drive firmware successfully when the new HP ProLiant Smart Array HPCISS3 Controller Driver (**hpciss3.sys**) is running on the system being updated.

---

Online ROM Flash Component for Windows - VB0250EAVER Drives

Version: HPG9 (B) **(Recommended)**

Filename: cp020478.exe; cp020478.md5

### **Important Note!**

- **Online firmware flashing of drives attached to an HP Smart Array controller running in Zero Memory (ZM) mode or an HP ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux and Microsoft Windows environments. All other OSes would require an offline update using the SPP and HP SUM.**
- **Customers who already installed firmware version HPG9 do not need to update to HPG9(B).**

### **Fixes**

#### **Problems Fixed:**

- This firmware corrects the possibility of the drive becoming unresponsive and requiring a power cycle following a soft system reboot. This behavior appears as if the drive is no longer attached to the system following the system soft reboot. It is most often observed during Operating System Installation but can occur following any system soft reboot.

## **Enhancements**

### **Enhancements/New Features:**

- The firmware component installer can now install the drive firmware successfully when the new HP ProLiant Smart Array HPCISS3 Controller Driver (**hpcisss3.sys**) is running on the system being updated.

---

Online ROM Flash Component for Windows - VK0240GDJXU, VK0300GDUQV, VK0480GDJXV, VK0600GDUTQ, and VK0800GDJYA Drives

Version: HPG1 (B) **(Optional)**

Filename: cp026952.exe; cp026952.md5

### **Important Note!**

- **Online firmware flashing of drives attached to an HP Smart Array controller running in Zero Memory (ZM) mode or an HP ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSES would require an offline update using the SPP and HP SUM.**
- **Customers who already installed firmware version HPG1 do not need to update to HPG1(B).**

## **Fixes**

### **Problems Fixed:**

- This maintenance firmware updates temperature reporting, Sanitize Block Erase and includes read performance improvements.

---

Supplemental Update / Online ROM Flash Component for ESXi - MB1000GDUNU, MB2000GDUNV, MB3000GDUPA, and MB4000GDUPB Drives

Version: HPG4 **(Recommended)**

Filename: CPO30806.zip

### **Important Note!**

- **Online firmware flashing of drives attached to an HP Smart Array controller running in Zero Memory (ZM) mode or an HP ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux and Microsoft Windows environments. All other OSES would require an offline update using the SPP and HP SUM.**

## **Fixes**

### **Problems Fixed:**

- Reliability enhancement for applications that write data to a narrow range of tracks.

### **Known Issues:**

- Firmware cannot be downgraded to HPG3 after updating to HPG4.

---

Supplemental Update / Online ROM Flash Component for ESXi - MB4000GEFNA and MB6000GEFNB Drives

Version: HPG4 **(Recommended)**

Filename: CP030031.zip

### **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSES would require an offline update using the SPP and HP SUM.**

### **Fixes**

#### **Problems Fixed:**

- This firmware improves HDD reliability when HDDs are exposed to long periods of host inactivity that exceed 1 second. HDDs may become unresponsive when using HDD firmware prior to version HPG4. This firmware also contains a change which prevents an incorrect reassign status of a repaired sector from being logged.

---

Supplemental Update / Online ROM Flash Component for ESXi - MB6000GEXXV Drives

Version: HPG2 (**Recommended**)

Filename: CP030838.zip

### **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSES would require an offline update using the SPP and HP SUM.**

### **Fixes**

#### **Problems Fixed:**

- Reliability enhancement for applications that write data to a narrow range of tracks.

---

Supplemental Update / Online ROM Flash Component for ESXi - MB8000GFECR Drives

Version: HPG3 (**Recommended**)

Filename: CP030842.zip

### **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSES would require an offline update using the SPP and HP SUM.**

### **Fixes**

#### **Problems Fixed:**

- This firmware improves HDD reliability when HDDs are exposed to long periods of host inactivity that exceed 1 second. HDDs may become unresponsive when using HDD firmware prior to version HPG3.

---

Supplemental Update / Online ROM Flash Component for ESXi - MO0100EBTJT, MO0200EBTJU, and MO0400EBTJV drives

Version: HPG4 (B) **(Optional)**

Filename: CP029383.zip

### **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**
- **Customers who already installed firmware version HPG4 do not need to update to HPG4 (B).**

### **Fixes**

#### **Problems Fixed:**

- Firmware version HPG4 resolved a wear-out issue which was caused by frequently issued PIO commands and resulted in a non-responsive drive.

#### **Problems Fixed for HPG4 (B):**

- Component would fail to install drive firmware for drives present in a system configured with two or more external drive enclosures attached to an HP Host Bus Adapter H22x. The following message would be reported in the component log file - "Device appears more than once in tree". The drive firmware installation failure was not observed in configurations having only one external drive enclosure attached to an HP Host Bus Adapter H22x.

---

Supplemental Update / Online ROM Flash Component for ESXi - VB0160EAVEQ and VB0160CBCDE Drives

Version: HPG9 (F) **(Recommended)**

Filename: CP029388.zip

### **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**
- **Customers who already installed firmware version HPG9 do not need to update to HPG9 (F).**

### **Fixes**

#### **Problems Fixed:**

- This firmware corrects the possibility of the drive becoming unresponsive and requiring a power cycle following a soft system reboot. This behavior appears as if the drive is no longer attached to the system following the system soft reboot. It is most often observed during Operating System Installation but can occur following any system soft reboot.



### **Problems Fixed for HPG9 (F):**

- Component would fail to install drive firmware for drives present in a system configured with two or more external drive enclosures attached to an HP Host Bus Adapter H22x. The following message would be reported in the component log file - "Device appears more than once in tree". The drive firmware installation failure was not observed in configurations having only one external drive enclosure attached to an HP Host Bus Adapter H22x.

### **Enhancements**

#### **Enhancements/New Features:**

- Added support for VMware vSphere 5.5.
- Added support for UEFI (Universal Extensible Firmware Interface) based servers.
- Added support for HP Dynamic Smart Array B140i Controller.

#### **Enhancements/New Features for HPG9 (E):**

- Updated the flash engine to standardize logging across all SATA drive components.
- Enhanced logging capability to improve the details provided in the component log file.
- VMware Firmware Smart component packaging has changed from a \*.scexe package to a \*.zip package, which contains an executable binary that provides enhanced security during installation. The functionality of the VMware Smart Component has not changed.

---

Supplemental Update / Online ROM Flash Component for ESXi - VB0250EAVER Drives

Version: HPG9 (F) **(Recommended)**

Filename: CPO29389.zip

### **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**
- **Customers who already installed firmware version HPG9 do not need to update to HPG9 (F).**

### **Fixes**

#### **Problems Fixed:**

- This firmware corrects the possibility of the drive becoming unresponsive and requiring a power cycle following a soft system reboot. This behavior appears as if the drive is no longer attached to the system following the system soft reboot. It is most often observed during Operating System Installation but can occur following any system soft reboot.

#### **Problems Fixed for HPG9 (F):**

- Component would fail to install drive firmware for drives present in a system configured with two or more external drive enclosures attached to an HP Host Bus Adapter H22x. The following message would be reported in the component log file - "Device appears more than once in tree". The drive firmware installation failure was not observed in configurations having only one external drive enclosure attached to an HP Host Bus Adapter H22x.

### **Enhancements**

#### **Enhancements/New Features:**

- Added support for VMware vSphere 5.5.
- Added support for UEFI (Universal Extensible Firmware Interface) based servers.
- Added support for HP Dynamic Smart Array B140i Controller.

#### **Enhancements/New Features for HPG9 (E):**

- Updated the flash engine to standardize logging across all SATA drive components.
- Enhanced logging capability to improve the details provided in the component log file.
- VMware Firmware Smart component packaging has changed from a \*.scexe package to a \*.zip package, which contains an executable binary that provides enhanced security during installation. The functionality of the VMware Smart Component has not changed.

---

Supplemental Update / Online ROM Flash Component for Linux - MB2000EAZNL drives

Version: HPG4 (B) **(Optional)**

Filename: CP022329.md5; CP022329.scexe

#### **Important Note!**

- **Online firmware flashing of drives attached to an HP Smart Array controller running in Zero Memory (ZM) mode or an HP ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**
- **Customers who already installed firmware version HPG4 do not need to update to HPG4(B).**

#### **Fixes**

##### **Problems Fixed:**

- This firmware contains general maintenance release and code improvement items. Drives built with or upgraded to hard drive firmware version HPG4 should not be downgraded to an earlier version of firmware due to hard drive manufacturing process changes.

#### **Enhancements**

##### **Enhancements/New Features:**

- Added support for UEFI (Universal Extensible Firmware Interface) based servers.

---

Supplemental Update / Online ROM Flash Component for Linux - MB2000EBUGF and MB3000EBUGH Drives

Version: HPG4 (B) **(Recommended)**

Filename: CP022330.md5; CP022330.scexe

#### **Important Note!**

- **Online firmware flashing of drives attached to an HP Smart Array controller running in Zero Memory (ZM) mode or an HP ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**
- **Customers who already installed firmware version HPG4 do not need to update to HPG4(B).**

#### **Fixes**

**Problems Fixed:**

- o The system did not recognize some drives after a power-cycle. This is due to the drive initialization process being interrupted by a reset, causing the drive to take more time than allotted to report commands.

**Enhancements****Enhancements/New Features:**

- o Added support for UEFI (Universal Extensible Firmware Interface) based servers.

---

Supplemental Update / Online ROM Flash Component for Linux - MB2000GBUPB and MB3000GBUCK drives

Version: HPG4 (B) **(Recommended)**

Filename: CP022333.md5; CP022333.scexe

**Important Note!**

- o **Online firmware flashing of drives attached to an HP Smart Array controller running in Zero Memory (ZM) mode or an HP ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- o **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**
- o **Customers who already installed firmware version HPG4 do not need to update to HPG4(B).**

**Fixes****Problems Fixed:**

- o The system did not recognize some drives after a power-cycle. This is due to the drive initialization process being interrupted by a reset, causing the drive to take more time than allotted to report commands.

**Enhancements****Enhancements/New Features:**

- o Added support for UEFI (Universal Extensible Firmware Interface) based servers.

---

Supplemental Update / Online ROM Flash Component for Linux (x64) - XP0064GEFEP Drives

Version: HPS5 **(Recommended)**

Filename: rpm/RPMS/x86\_64/hp-firmware-hdd-e151c3ad27-HPS5-1.1.x86\_64.rpm

**Important Note!**

- o **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- o **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**

**Fixes****Problems Fixed:**

- o Resolves an issue with the option kit in which an M.2 SSD is installed: when RAID 1 is selected, devices go into a RAID rebuild mode

## **Enhancements**

### **Enhancements/New Features:**

- Enables sanitize device function for HP specific environments
- Adds UECC Read-retry algorithm for timeout handling
- Adds single binary file drive firmware update support

---

Supplemental Update / Online ROM Flash Component for Linux (x64) - MB0500GCEHF, MB1000GCEHH, and MB2000GCEHK Drives

Version: HPGD (D) **(Critical)**

Filename: rpm/RPMS/x86\_64/hp-firmware-hdd-b583d96f94-HPGD-4.1.x86\_64.rpm

### **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSES would require an offline update using the SPP and HP SUM.**
- **Customers who already installed firmware version HPGD do not need to update to HPGD (D).**

## **Fixes**

### **Problems Fixed:**

- After long term use of the HDD, a rare condition might occur following a power cycle where the drive heads may land on areas of the disk containing data, which could potentially cause data loss or mechanical damage. Firmware version HPGD prevents this condition from occurring.
- Flashing drives connected behind an HP H2xx Host Bus Adapter (HBA) no longer causes an interrupt resulting in drive firmware installation failures.
- Resolved a component installation issue where the drive model, MB2000GCEHK, was being detected, but would fail to flash.
- Linux Smart Component fails to update firmware on SATA drive connected behind a SATA HBA controller. Component reports the firmware update was successful. However, after a power cycle, the firmware version remains unchanged.

### **Problems Fixed for HPGD (D):**

- Component would fail to install drive firmware for drives present in a system configured with two or more external drive enclosures attached to an HP Host Bus Adapter H22x. The following message would be reported in the component log file - "Device appears more than once in tree". The drive firmware installation failure was not observed in configurations having only one external drive enclosure attached to an HP Host Bus Adapter H22x.
- Component fails to update the firmware for drives connected behind an HP Smart Array P431 controller. Component reports the firmware update was successful. However, after a power cycle, the firmware version remains unchanged.

## **Enhancements**

### **Enhancements/New Features:**

- Added support for UEFI (Universal Extensible Firmware Interface) based servers.

### **Enhancements/New Features for HPGD (C):**

- Updated the flash engine to standardize logging across all SATA drive components.

Enhanced logging capability to improve the details provided in the component log file.

---

Supplemental Update / Online ROM Flash Component for Linux (x64) - MB1000ECWCQ, MB2000ECWCR, MB3000ECWCT, and MB4000ECWCU Drives

Version: HPG5 **(Critical)**

Filename: rpm/RPMS/x86\_64/hp-firmware-hdd-a92b4196b5-HPG5-1.1.x86\_64.rpm

### **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSES would require an offline update using the SPP and HP SUM.**

### **Fixes**

#### **Problems Fixed:**

- HPG5 firmware improves drive reliability where disk drives are exposed to long periods of host inactivity which exceed 1 second.

---

Supplemental Update / Online ROM Flash Component for Linux (x64) - MB1000GCEEK Drives

Version: HPG2 (B) **(Recommended)**

Filename: rpm/RPMS/x86\_64/hp-firmware-hdd-7aa341f927-HPG2-2.1.x86\_64.rpm

### **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSES would require an offline update using the SPP and HP SUM.**
- **Customers who already installed firmware version HPG2 do not need to update to HPG2 (B).**

### **Fixes**

#### **Problems Fixed for HPG2 (B):**

- Component would fail to install drive firmware for drives present in a system configured with two or more external drive enclosures attached to an HP Host Bus Adapter H22x. The following message would be reported in the component log file - "Device appears more than once in tree". The drive firmware installation failure was not observed in configurations having only one external drive enclosure attached to an HP Host Bus Adapter H22x.
- Component fails to update the firmware for drives connected behind an HP Smart Array P431 controller. Component reports the firmware update was successful. However, after a power cycle, the firmware version remains unchanged.

### **Enhancements**

#### **Enhancements/New Features:**

- This firmware improves reliability by modifying the pivot bearing grease wear leveling algorithm, which if not implemented, could result in

an increased drive failure rate for specific usage applications (eg. very long periods of small range seeks).

---

Supplemental Update / Online ROM Flash Component for Linux (x64) - MB1000GCWCV, MB2000GCWDA, MB3000GCWDB, and MB4000GCWDC Drives

Version: HPGH **(Critical)**

Filename: rpm/RPMS/x86\_64/hp-firmware-hdd-a1b08f8a6b-HPGH-1.1.x86\_64.rpm

**Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**

**Fixes**

**Problems Fixed:**

- HPGH firmware improves drive reliability where disk drives are exposed to long periods of host inactivity which exceed 1 second. As a result, hard disk drives may become unresponsive.

---

Supplemental Update / Online ROM Flash Component for Linux (x64) - MB1000GDUNU, MB2000GDUNV, MB3000GDUPA, and MB4000GDUPB Drives

Version: HPG4 **(Recommended)**

Filename: rpm/RPMS/x86\_64/hp-firmware-hdd-3ab4c70e64-HPG4-1.1.x86\_64.rpm

**Important Note!**

- **Online firmware flashing of drives attached to an HP Smart Array controller running in Zero Memory (ZM) mode or an HP ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux and Microsoft Windows environments. All other OSes would require an offline update using the SPP and HP SUM.**

**Fixes**

**Problems Fixed:**

- Reliability enhancement for applications that write data to a narrow range of tracks.

**Known Issues:**

- Firmware cannot be downgraded to HPG3 after updating to HPG4.

---

Supplemental Update / Online ROM Flash Component for Linux (x64) - MB2000EAZNL Drives

Version: HPG4 (D) **(Optional)**

Filename: rpm/RPMS/x86\_64/hp-firmware-hdd-800c4d6b2e-HPG4-4.1.x86\_64.rpm

**Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**
- **Customers who already installed firmware version HPG4 do not need to update to HPG4 (D).**

## **Fixes**

### **Problems Fixed:**

- This firmware contains general maintenance release and code improvement items. Drives built with or upgraded to hard drive firmware version HPG4 should not be downgraded to an earlier version of firmware due to hard drive manufacturing process changes.
- Linux Smart Component fails to update firmware on SATA drive connected behind a SATA HBA controller. Component reports the firmware update was successful. However, after a power cycle, the firmware version remains unchanged.

### **Problems Fixed for HPG4 (D):**

- Component would fail to install drive firmware for drives present in a system configured with two or more external drive enclosures attached to an HP Host Bus Adapter H22x. The following message would be reported in the component log file - "Device appears more than once in tree". The drive firmware installation failure was not observed in configurations having only one external drive enclosure attached to an HP Host Bus Adapter H22x.
- Component fails to update the firmware for drives connected behind an HP Smart Array P431 controller. Component reports the firmware update was successful. However, after a power cycle, the firmware version remains unchanged.

## **Enhancements**

### **Enhancements/New Features:**

- Added support for UEFI (Universal Extensible Firmware Interface) based servers.

### **Enhancements/New Features for (C):**

- Updated the flash engine to standardize logging across all SATA drive components.
- Enhanced logging capability to improve the details provided in the component log file.

---

Supplemental Update / Online ROM Flash Component for Linux (x64) - MB2000EBUGF and MB3000EBUGH Drives

Version: HPG4 (D) **(Recommended)**

Filename: rpm/RPMS/x86\_64/hp-firmware-hdd-74fefb9767-HPG4-4.1.x86\_64.rpm

## **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**
- **Customers who already installed firmware version HPG4 do not need to update to HPG4 (D).**

## **Fixes**

## Problems Fixed:

- The system did not recognize some drives after a power-cycle. This is due to the drive initialization process being interrupted by a reset, causing the drive to take more time than allotted to report commands.
- Linux Smart Component fails to update firmware on SATA drive connected behind a SATA HBA controller. Component reports the firmware update was successful. However, after a power cycle, the firmware version remains unchanged.

## Problems Fixed for HPG4 (D):

- Component would fail to install drive firmware for drives present in a system configured with two or more external drive enclosures attached to an HP Host Bus Adapter H22x. The following message would be reported in the component log file - "Device appears more than once in tree". The drive firmware installation failure was not observed in configurations having only one external drive enclosure attached to an HP Host Bus Adapter H22x.
- Component fails to update the firmware for drives connected behind an HP Smart Array P431 controller. Component reports the firmware update was successful. However, after a power cycle, the firmware version remains unchanged.

## Enhancements

### Enhancements/New Features:

- Added support for UEFI (Universal Extensible Firmware Interface) based servers.

### Enhancements/New Features for (C):

- Updated the flash engine to standardize logging across all SATA drive components.
- Enhanced logging capability to improve the details provided in the component log file.

---

Supplemental Update / Online ROM Flash Component for Linux (x64) - MB2000ECVJF, MB3000ECVJH, and MB4000ECVJK Drives  
Version: HPG5 (B) **(Critical)**  
Filename: rpm/RPMS/x86\_64/hp-firmware-hdd-b923956874-HPG5-2.1.x86\_64.rpm

## Important Note!

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**
- **Customers who already installed firmware version HPG5 do not need to update to HPG5 (B).**

## Fixes

### Problem Fixed:

- Fixes a rare but potential data integrity error during low 5v drive voltage and specific sequential data streaming conditions, which could result in data written to incorrect sectors.

### Problems Fixed for HPG5 (B):

- Component would fail to install drive firmware for drives present in a system configured with two or more external drive enclosures attached to an HP Host Bus Adapter H22x. The following message would be reported in the component log file - "Device appears more than once in tree". The drive firmware installation failure was not observed in configurations having only one external drive enclosure attached to an HP Host Bus Adapter H22x.
- Component fails to update the firmware for drives connected behind an HP Smart Array P431 controller. Component reports the



firmware update was successful. However, after a power cycle, the firmware version remains unchanged.

## **Enhancements**

### **Enhancements/New Features:**

- Added support for UEFI (Universal Extensible Firmware Interface) based servers.
- Updated the flash engine to standardize logging across all SATA drive components.
- Enhanced logging capability to improve the details provided in the component log file.

---

Supplemental Update / Online ROM Flash Component for Linux (x64) - MB2000ECWLP, MB3000ECWLQ, and MB4000ECWLR Drives

Version: HPG4 **(Recommended)**

Filename: rpm/RPMS/x86\_64/hp-firmware-b508a3352b-HPG4-1.1.x86\_64.rpm

### **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**

## **Fixes**

### **Problems Fixed:**

- Improves the drive idle time behavior by reducing long periods of track dwell time, which if not implemented, could increase media lube depletion and reduce drive reliability.

---

Supplemental Update / Online ROM Flash Component for Linux (x64) - MB2000GBUPB and MB3000GBUCK Drives

Version: HPG4 (D) **(Recommended)**

Filename: rpm/RPMS/x86\_64/hp-firmware-hdd-166dc88573-HPG4-4.1.x86\_64.rpm

### **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**
- **Customers who already installed firmware version HPG4 do not need to update to HPG4 (D).**

## **Fixes**

### **Problems Fixed:**

- The system did not recognize some drives after a power-cycle. This is due to the drive initialization process being interrupted by a reset, causing the drive to take more time than allotted to report commands.
- Linux Smart Component fails to update firmware on SATA drive connected behind a SATA HBA controller. Component reports the firmware update was successful. However, after a power cycle, the firmware version remains unchanged.

### Problems Fixed for HPG4 (D):

- Component would fail to install drive firmware for drives present in a system configured with two or more external drive enclosures attached to an HP Host Bus Adapter H22x. The following message would be reported in the component log file - "Device appears more than once in tree". The drive firmware installation failure was not observed in configurations having only one external drive enclosure attached to an HP Host Bus Adapter H22x.
- Component fails to update the firmware for drives connected behind an HP Smart Array P431 controller. Component reports the firmware update was successful. However, after a power cycle, the firmware version remains unchanged.

### Enhancements

#### Enhancements/New Features:

- Added support for UEFI (Universal Extensible Firmware Interface) based servers.

#### Enhancements/New Features for HPG4 (C):

- Updated the flash engine to standardize logging across all SATA drive components.
- Enhanced logging capability to improve the details provided in the component log file.

---

Supplemental Update / Online ROM Flash Component for Linux (x64) - MB2000GCQXQ and MB3000GBKAC Drives

Version: HPGK (**Recommended**)

Filename: rpm/RPMS/x86\_64/hp-firmware-hdd-c9026c29f7-HPGK-1.1.x86\_64.rpm

### Important Note!

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**

### Fixes

#### Problem Fixed:

- HP ProLiant servers would power down due a hard drive over temp condition that was falsely reported. Hard disk drive firmware HPGK resolves this issue.

---

Supplemental Update / Online ROM Flash Component for Linux (x64) - MB2000GCVBR, MB3000GCVBT, and MB4000GCVBU Drives

Version: HPG5 (B) (**Critical**)

Filename: rpm/RPMS/x86\_64/hp-firmware-hdd-e4f5b5c9a7-HPG5-2.1.x86\_64.rpm

### Important Note!

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**
- **Customers who already installed firmware version HPG5 do not need to update to HPG5 (B).**

## Fixes

### **Problem Fixed:**

- Fixes a rare but potential data integrity error during low 5v drive voltage and specific sequential data streaming conditions, which could result in data written to incorrect sectors.

### **Problems Fixed for HPG5 (B):**

- Component would fail to install drive firmware for drives present in a system configured with two or more external drive enclosures attached to an HP Host Bus Adapter H22x. The following message would be reported in the component log file - "Device appears more than once in tree". The drive firmware installation failure was not observed in configurations having only one external drive enclosure attached to an HP Host Bus Adapter H22x.
- Component fails to update the firmware for drives connected behind an HP Smart Array P431 controller. Component reports the firmware update was successful. However, after a power cycle, the firmware version remains unchanged.

## Enhancements

### **Enhancements/New Features:**

- Added support for UEFI (Universal Extensible Firmware Interface) based servers.
- Updated the flash engine to standardize logging across all SATA drive components.
- Enhanced logging capability to improve the details provided in the component log file.

---

Supplemental Update / Online ROM Flash Component for Linux (x64) - MB2000GCWLT, MB3000GCWLU, and MB4000GCWLV Drives

Version: HPG4 **(Recommended)**

Filename: rpm/RPMS/x86\_64/hp-firmware-2e70ce7412-HPG4-1.1.x86\_64.rpm

### **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**

## Fixes

### **Problems Fixed:**

- Improves the drive idle time behavior by reducing long periods of track dwell time, which if not implemented, could increase media lube depletion and reduce drive reliability.

---

Supplemental Update / Online ROM Flash Component for Linux (x64) - MB3000EBKAB Drives

Version: HPG6 (D) **(Critical)**

Filename: rpm/RPMS/x86\_64/hp-firmware-hdd-3675aa63c9-HPG6-4.1.x86\_64.rpm

### **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these**

#### **configurations.**

- o **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSES would require an offline update using the SPP and HP SUM.**
- o **Customers who already installed firmware version HPG6 do not need to update to HPG6 (D).**

## **Fixes**

### **Problems Fixed:**

- o After long term use of the HDD, a rare condition might occur following a power cycle where the drive heads may land on areas of the disk containing data, which could potentially cause data loss or mechanical damage. Firmware version HPG6 prevents this condition from occurring.
- o This firmware corrects "command timeouts" and seek errors which can result in poor performance or a Device Fault condition, the latter of which will result in the drive failed by the Controller or sub system.
- o Flashing drives connected behind an HP H2xx Host Bus Adapter (HBA) no longer causes an interrupt resulting in drive firmware installation failures.
- o Linux Smart Component fails to update firmware on SATA drive connected behind a SATA HBA controller. Component reports the firmware update was successful. However, after a power cycle, the firmware version remains unchanged.

### **Problems Fixed for HPG6 (D):**

- o Component would fail to install drive firmware for drives present in a system configured with two or more external drive enclosures attached to an HP Host Bus Adapter H22x. The following message would be reported in the component log file - "Device appears more than once in tree". The drive firmware installation failure was not observed in configurations having only one external drive enclosure attached to an HP Host Bus Adapter H22x.
- o Component fails to update the firmware for drives connected behind an HP Smart Array P431 controller. Component reports the firmware update was successful. However, after a power cycle, the firmware version remains unchanged.

## **Enhancements**

### **Enhancements/New Features:**

- o Added support for UEFI (Universal Extensible Firmware Interface) based servers.

### **Enhancements/New Features for HPG6 (C):**

- o Updated the flash engine to standardize logging across all SATA drive components.
- o Enhanced logging capability to improve the details provided in the component log file.

---

Supplemental Update / Online ROM Flash Component for Linux (x64) - MB4000GEFNA and MB6000GEFNB Drives

Version: HPG4 **(Recommended)**

Filename: rpm/RPMS/x86\_64/hp-firmware-hdd-40277d55d3-HPG4-1.1.x86\_64.rpm

## **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSES would require an offline update using the SPP and HP SUM.**

## **Fixes**

### Problems Fixed:

- This firmware improves HDD reliability when HDDs are exposed to long periods of host inactivity that exceed 1 second. HDDs may become unresponsive when using HDD firmware prior to version HPG4. This firmware also contains a change which prevents an incorrect reassigned status of a repaired sector from being logged.

---

Supplemental Update / Online ROM Flash Component for Linux (x64) - MB4000GEQNH and MB6000GEQNK Drives

Version: HPG7 (B) **(Recommended)**

Filename: rpm/RPMS/x86\_64/hp-firmware-hdd-bfc95f0628-HPG7-2.1.x86\_64.rpm

### **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**
- **Customers who already installed firmware version HPG7 do not need to update to HPG7 (B).**

### **Fixes**

#### **Problems Fixed:**

- This firmware corrects possible unrecovered errors caused by the track refresh algorithm not working properly.

#### **Problems Fixed for HPG7 (B):**

- Component would fail to install drive firmware for drives present in a system configured with two or more external drive enclosures attached to an HP Host Bus Adapter H22x. The following message would be reported in the component log file - "Device appears more than once in tree". The drive firmware installation failure was not observed in configurations having only one external drive enclosure attached to an HP Host Bus Adapter H22x.
- Component fails to update the firmware for drives connected behind an HP Smart Array P431 controller. Component reports the firmware update was successful. However, after a power cycle, the firmware version remains unchanged.

---

Supplemental Update / Online ROM Flash Component for Linux (x64) - MB6000GEQUT and MB8000GEQUU Drives

Version: HPG7 (C) **(Recommended)**

Filename: rpm/RPMS/x86\_64/hp-firmware-hdd-1d7f19120b-HPG7-3.1.x86\_64.rpm

### **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**
- **Customers who already installed firmware version HPG7 do not need to update to HPG7 (C).**

### **Fixes**

#### **Problems Fixed:**

- This firmware corrects possible unrecovered errors caused by the track refresh algorithm not working properly.

### Problems Fixed for HPG7 (C):

- Component would fail to install drive firmware for drives present in a system configured with two or more external drive enclosures attached to an HP Host Bus Adapter H22x. The following message would be reported in the component log file - "Device appears more than once in tree". The drive firmware installation failure was not observed in configurations having only one external drive enclosure attached to an HP Host Bus Adapter H22x.
- Component fails to update the firmware for drives connected behind an HP Smart Array P431 controller. Component reports the firmware update was successful. However, after a power cycle, the firmware version remains unchanged.

---

Supplemental Update / Online ROM Flash Component for Linux (x64) - MB6000GEXXV Drives

Version: HPG2 (**Recommended**)

Filename: rpm/RPMS/x86\_64/hp-firmware-hdd-a629fcea59-HPG2-1.1.x86\_64.rpm

### **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**

### **Fixes**

#### **Problems Fixed:**

- Reliability enhancement for applications that write data to a narrow range of tracks.

---

Supplemental Update / Online ROM Flash Component for Linux (x64) - MB8000GFECR Drives

Version: HPG3 (**Recommended**)

Filename: rpm/RPMS/x86\_64/hp-firmware-hdd-6d922fc9a8-HPG3-1.1.x86\_64.rpm

### **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**

### **Fixes**

#### **Problems Fixed:**

- This firmware improves HDD reliability when HDDs are exposed to long periods of host inactivity that exceed 1 second. HDDs may become unresponsive when using HDD firmware prior to version HPG3.

---

Supplemental Update / Online ROM Flash Component for Linux (x64) - MK0100GCTYU, MK0200GCTYV, MK0400GCTZA, and MK0800GCTZB Drives

Version: HPG4 (D) (**Optional**)

Filename: rpm/RPMS/x86\_64/hp-firmware-hdd-b2d9e3a264-HPG4-4.1.x86\_64.rpm

### **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**
- **Customers who already installed firmware version HPG4 do not need to update to HPG4 (D).**

### **Fixes**

#### **Problems Fixed:**

- This maintenance release corrects a failure seen during a HP Insight Diagnostic hard drive test. The failure was due to Device Extended Self-Test not completing in the drives advertised Self-Test completion time. This failure is not an indication that the drive is bad or marginal.
- Linux Smart Component fails to update firmware on SATA drive connected behind a SATA HBA controller. Component reports the firmware update was successful. However, after a power cycle, the firmware version remains unchanged.

#### **Problems Fixed for HPG4 (D):**

- Component would fail to install drive firmware for drives present in a system configured with two or more external drive enclosures attached to an HP Host Bus Adapter H22x. The following message would be reported in the component log file - "Device appears more than once in tree". The drive firmware installation failure was not observed in configurations having only one external drive enclosure attached to an HP Host Bus Adapter H22x.
- Component fails to update the firmware for drives connected behind an HP Smart Array P431 controller. Component reports the firmware update was successful. However, after a power cycle, the firmware version remains unchanged.

### **Enhancements**

#### **Enhancements/New Features:**

- Added support for UEFI (Universal Extensible Firmware Interface) based servers.
- Updated the flash engine to standardize logging across all SATA drive components.
- Enhanced logging capability to improve the details provided in the component log file.

---

Supplemental Update / Online ROM Flash Component for Linux (x64) - MK0960GECQK Drives

Version: HPG3 (B) **(Critical)**

Filename: rpm/RPMS/x86\_64/hp-firmware-hdd-3e34285be7-HPG3-2.1.x86\_64.rpm

### **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**
- **Customers who already installed firmware version HPG3 do not need to update to HPG3 (B).**

### **Fixes**

#### **Problems Fixed:**

- Firmware resolves a data mismanagement issue associated with unaligned sequential write operations.

#### **Problems Fixed for HPG3 (B):**

- Component would fail to install drive firmware for drives present in a system configured with two or more external drive enclosures attached to an HP Host Bus Adapter H22x. The following message would be reported in the component log file - "Device appears more than once in tree". The drive firmware installation failure was not observed in configurations having only one external drive enclosure attached to an HP Host Bus Adapter H22x.
- Component fails to update the firmware for drives connected behind an HP Smart Array P431 controller. Component reports the firmware update was successful. However, after a power cycle, the firmware version remains unchanged.

---

Supplemental Update / Online ROM Flash Component for Linux (x64) - MM0500GBKAK and MM1000GBKAL Drives

Version: HPGE **(Recommended)**

Filename: rpm/RPMS/x86\_64/hp-firmware-hdd-a08f92a4f9-HPGE-1.1.x86\_64.rpm

#### **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**

#### **Fixes**

##### **Problems Fixed:**

- Corrected a medium level assert that can occur when the host issues resets after >250ms of idle time. If a drive is affected by the issue, it might display reduced performance and possibly would cease to operate. A hot plug removal and insertion of the affected drive temporarily resolves this issue. Update to drive firmware version HPGE to resolve this issue.

---

Supplemental Update / Online ROM Flash Component for Linux (x64) - MM1000GEFQV and MM2000GEFRA Drives

Version: HPG3 (B) **(Recommended)**

Filename: rpm/RPMS/x86\_64/hp-firmware-hdd-ec908c3650-HPG3-2.1.x86\_64.rpm

#### **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**
- **Customers who already installed firmware version HPG3 do not need to update to HPG3 (B).**

#### **Fixes**

##### **Problems Fixed:**

- After HDD power cycle, the Background Media Scan (BGMS) pointer would invoke a second BGMS routine starting at LBA 0, which could affect performance until the second BGMS has completed.
- When writing to the HDD after it entered or returned from a standby state, the potential existed for a Non Volatile Cache issue to occur.



### Problems Fixed for HPG3 (B):

- Component would fail to install drive firmware for drives present in a system configured with two or more external drive enclosures attached to an HP Host Bus Adapter H22x. The following message would be reported in the component log file - "Device appears more than once in tree". The drive firmware installation failure was not observed in configurations having only one external drive enclosure attached to an HP Host Bus Adapter H22x.
- Component fails to update the firmware for drives connected behind an HP Smart Array P431 controller. Component reports the firmware update was successful. However, after a power cycle, the firmware version remains unchanged.

---

Supplemental Update / Online ROM Flash Component for Linux (x64) - MM1000GFJTE Drives

Version: HPG1 (**Recommended**)

Filename: rpm/RPMS/x86\_64/hp-firmware-hdd-95af9a555e-HPG1-1.1.x86\_64.rpm

### **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSES would require an offline update using the SPP and HP SUM.**

### **Fixes**

#### **Problems Fixed:**

- This firmware improves HDD reliability when HDDs are exposed to long periods of host inactivity that exceed 1 second. HDDs may become unresponsive when using HDD firmware prior to version HPG1.
- This firmware also contains a change which prevents an incorrect reassign status of a repaired sector from being logged.

---

Supplemental Update / Online ROM Flash Component for Linux (x64) - MO0100EBTJT, MO0200EBTJU, and MO0400EBTJV drives

Version: HPG4 (C) (**Optional**)

Filename: rpm/RPMS/x86\_64/hp-firmware-hdd-72e5d6942f-HPG4-3.1.x86\_64.rpm

### **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSES would require an offline update using the SPP and HP SUM.**
- **Customers who already installed firmware version HPG4 do not need to update to HPG4 (C).**

### **Fixes**

#### **Problems Fixed:**

- Firmware version HPG4 resolved a wear-out issue which was caused by frequently issued PIO commands and resulted in a non-responsive drive.

### **Problems Fixed for HPG4 (C):**

- o Component would fail to install drive firmware for drives present in a system configured with two or more external drive enclosures attached to an HP Host Bus Adapter H22x. The following message would be reported in the component log file - "Device appears more than once in tree". The drive firmware installation failure was not observed in configurations having only one external drive enclosure attached to an HP Host Bus Adapter H22x.
- o Component fails to update the firmware for drives connected behind an HP Smart Array P431 controller. Component reports the firmware update was successful. However, after a power cycle, the firmware version remains unchanged.

## **Enhancements**

### **Enhancements/New Features for HPG4 (B):**

- o Updated the flash engine to standardize logging across all SATA drive components.
- o Enhanced logging capability to improve the details provided in the component log file.

---

Supplemental Update / Online ROM Flash Component for Linux (x64) - TK0120GECQL, VK0240GECQN, and VK0480GECQP Drives

Version: HPG3 (B) **(Critical)**

Filename: rpm/RPMS/x86\_64/hp-firmware-hdd-5699d4778d-HPG3-2.1.x86\_64.rpm

### **Important Note!**

- o **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- o **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**
- o **Customers who already installed firmware version HPG3 do not need to update to HPG3 (B).**

## **Fixes**

### **Problems Fixed:**

- o Firmware resolves a data mismanagement issue associated with unaligned sequential write operations.

### **Problems Fixed for HPG3 (B):**

- o Component would fail to install drive firmware for drives present in a system configured with two or more external drive enclosures attached to an HP Host Bus Adapter H22x. The following message would be reported in the component log file - "Device appears more than once in tree". The drive firmware installation failure was not observed in configurations having only one external drive enclosure attached to an HP Host Bus Adapter H22x.
- o Component fails to update the firmware for drives connected behind an HP Smart Array P431 controller. Component reports the firmware update was successful. However, after a power cycle, the firmware version remains unchanged.

---

Supplemental Update / Online ROM Flash Component for Linux (x64) - VB0160EAVEQ and VB0160CBCDE Drives

Version: HPG9 (D) **(Recommended)**

Filename: rpm/RPMS/x86\_64/hp-firmware-hdd-181eec78ee-HPG9-4.1.x86\_64.rpm

### **Important Note!**

- o **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**

**Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**

- o **Customers who already installed firmware version HPG9 do not need to update to HPG9 (D).**

## Fixes

### **Problems Fixed:**

- o This firmware corrects the possibility of the drive becoming unresponsive and requiring a power cycle following a soft system reboot. This behavior appears as if the drive is no longer attached to the system following the system soft reboot. It is most often observed during Operating System Installation but can occur following any system soft reboot.
- o Flashing drives connected behind an HP H2xx Host Bus Adapter (HBA) no longer causes an interrupt resulting in drive firmware installation failures.
- o Linux Smart Component fails to update firmware on SATA drive connected behind a SATA HBA controller. Component reports the firmware update was successful. However, after a power cycle, the firmware version remains unchanged.

### **Problems Fixed for HPG9 (D):**

- o Component would fail to install drive firmware for drives present in a system configured with two or more external drive enclosures attached to an HP Host Bus Adapter H22x. The following message would be reported in the component log file - "Device appears more than once in tree". The drive firmware installation failure was not observed in configurations having only one external drive enclosure attached to an HP Host Bus Adapter H22x.
- o Component fails to update the firmware for drives connected behind an HP Smart Array P431 controller. Component reports the firmware update was successful. However, after a power cycle, the firmware version remains unchanged.

## Enhancements

### **Enhancements/New Features:**

- o Added support for UEFI (Universal Extensible Firmware Interface) based servers.

### **Enhancements/New Features for (C):**

- o Updated the flash engine to standardize logging across all SATA drive components.
- o Enhanced logging capability to improve the details provided in the component log file.

---

Supplemental Update / Online ROM Flash Component for Linux (x64) - VBO250EAVR Drives

Version: HPG9 (D) **(Recommended)**

Filename: rpm/RPMS/x86\_64/hp-firmware-hdd-e6bc718d4e-HPG9-4.1.x86\_64.rpm

## Important Note!

- o **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- o **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**
- o **Customers who already installed firmware version HPD9 do not need to update to HPD9 (D).**

## Fixes

### **Problems Fixed:**

- This firmware corrects the possibility of the drive becoming unresponsive and requiring a power cycle following a soft system reboot. This behavior appears as if the drive is no longer attached to the system following the system soft reboot. It is most often observed during Operating System Installation but can occur following any system soft reboot.
- Flashing drives connected behind an HP H2xx Host Bus Adapter (HBA) no longer causes an interrupt resulting in drive firmware installation failures.
- Linux Smart Component fails to update firmware on SATA drive connected behind a SATA HBA controller. Component reports the firmware update was successful. However, after a power cycle, the firmware version remains unchanged.

#### **Problems Fixed for HPG9 (D):**

- Component would fail to install drive firmware for drives present in a system configured with two or more external drive enclosures attached to an HP Host Bus Adapter H22x. The following message would be reported in the component log file - "Device appears more than once in tree". The drive firmware installation failure was not observed in configurations having only one external drive enclosure attached to an HP Host Bus Adapter H22x.
- Component fails to update the firmware for drives connected behind an HP Smart Array P431 controller. Component reports the firmware update was successful. However, after a power cycle, the firmware version remains unchanged.

### **Enhancements**

#### **Enhancements/New Features:**

- Added support for UEFI (Universal Extensible Firmware Interface) based servers.

#### **Enhancements/New Features for HPG9 (C):**

- Updated the flash engine to standardize logging across all SATA drive components.
- Enhanced logging capability to improve the details provided in the component log file.

---

Supplemental Update / Online ROM Flash Component for Linux (x64) - VK0240GDJXU, VK0300GDUQV, VK0480GDJXV, VK0600GDUTQ, and VK0800GDJYA Drives

Version: HPG1 (B) **(Optional)**

Filename: rpm/RPMS/x86\_64/hp-firmware-ef3ea1e703-HPG1-2.1.x86\_64.rpm

### **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**
- **Customers who already installed firmware version HPG1 do not need to update to HPG1 (B).**

### **Fixes**

#### **Problems Fixed:**

- This maintenance firmware updates temperature reporting, Sanitize Block Erase and includes read performance improvements.

#### **Problems Fixed for HPG1 (B):**

- Component would fail to install drive firmware for drives present in a system configured with two or more external drive enclosures attached to an HP Host Bus Adapter H22x. The following message would be reported in the component log file - "Device appears more than once in tree". The drive firmware installation failure was not observed in configurations having only one external drive enclosure attached to an HP Host Bus Adapter H22x.

- Component fails to update the firmware for drives connected behind an HP Smart Array P431 controller. Component reports the firmware update was successful. However, after a power cycle, the firmware version remains unchanged.

---

Supplemental Update / Online ROM Flash Component for Linux (x64) - XP0032GDZME Drives

Version: HPS5 (**Recommended**)

Filename: rpm/RPMS/x86\_64/hp-firmware-hdd-62faa20443-HPS5-1.1.x86\_64.rpm

### **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**

### **Fixes**

#### **Problems Fixed:**

- Resolves an issue with the option kit in which an M.2 SSD is installed: when RAID 1 is selected, devices go into a RAID rebuild mode

### **Enhancements**

#### **Enhancements/New Features:**

- Enables sanitize device function for HP specific environments
- Adds UECC Read-retry algorithm for timeout handling
- Adds single binary file drive firmware update support

---

Supplemental Update / Online ROM Flash Component for Linux (x64) - XP0032GEFEN Drives

Version: HPS5 (**Recommended**)

Filename: rpm/RPMS/x86\_64/hp-firmware-hdd-f286f98973-HPS5-1.1.x86\_64.rpm

### **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**

### **Fixes**

#### **Problems Fixed:**

- Resolves an issue with the option kit in which an M.2 SSD is installed: when RAID 1 is selected, devices go into a RAID rebuild mode

### **Enhancements**

#### **Enhancements/New Features:**

- Enables sanitize device function for HP specific environments
- Adds UECC Read-retry algorithm for timeout handling
- Adds single binary file drive firmware update support

---

Supplemental Update / Online ROM Flash Component for Linux (x64) - XP0064GDZMF Drives

Version: HPS5 (**Recommended**)

Filename: rpm/RPMS/x86\_64/hp-firmware-hdd-43bc195082-HPS5-1.1.x86\_64.rpm

### **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**

### **Fixes**

#### **Problems Fixed:**

- Resolves an issue with the option kit in which an M.2 SSD is installed: when RAID 1 is selected, devices go into a RAID rebuild mode

### **Enhancements**

#### **Enhancements/New Features:**

- Enables sanitize device function for HP specific environments
- Adds UECC Read-retry algorithm for timeout handling
- Adds single binary file drive firmware update support

---

Supplemental Update / Online ROM Flash Component for Linux - MB0500GCEHF, MB1000GCEHH, and MB2000GCEHK Drives

Version: HPGD (E) (**Critical**)

Filename: CP022323.md5; CP022323.scexe

### **Important Note!**

- **Online firmware flashing of drives attached to an HP Smart Array controller running in Zero Memory (ZM) mode or an HP ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**
- **Customers who already installed firmware version HPGD do not need to update to HPGD(E).**

### **Fixes**

#### **Problems Fixed:**

- After long term use of the HDD, a rare condition might occur following a power cycle where the drive heads may land on areas of the disk containing data, which could potentially cause data loss or mechanical damage. Firmware version HPGD prevents this condition from occurring.
- Flashing drives connected behind an HP H2xx Host Bus Adapter (HBA) no longer causes an interrupt resulting in drive firmware

installation failures.

- o **HPGD (D)** resolved a component installation issue where the drive model, MB2000GCEHK, was being detected, but would fail to flash.

## **Enhancements**

### **Enhancements/New Features:**

- o Added support for UEFI (Universal Extensible Firmware Interface) based servers.

---

Supplemental Update / Online ROM Flash Component for Linux - MB1000ECWCQ, MB2000ECWCR, MB3000ECWCT, and MB4000ECWCU Drives

Version: HPG5 **(Critical)**

Filename: rpm/RPMS/i386/hp-firmware-a92b4196b5-HPG5-1.1.i386.rpm

## **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**

## **Fixes**

### **Problems Fixed:**

- HPG5 firmware improves drive reliability where disk drives are exposed to long periods of host inactivity which exceed 1 second.

---

Supplemental Update / Online ROM Flash Component for Linux - MB1000GCWCV, MB2000GCWDA, MB3000GCWDB, and MB4000GCWDC Drives

Version: HPGH **(Critical)**

Filename: rpm/RPMS/i386/hp-firmware-a1b08f8a6b-HPGH-1.1.i386.rpm

## **Important Note!**

- o **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- o **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**

## **Fixes**

### **Problems Fixed:**

- o HPGH firmware improves drive reliability where disk drives are exposed to long periods of host inactivity which exceed 1 second. As a result, hard disk drives may become unresponsive.

---

Supplemental Update / Online ROM Flash Component for Linux - MB2000ECVJF, MB3000ECVJH, and MB4000ECVJK Drives

Version: HPG5 **(Critical)**

Filename: rpm/RPMS/i386/hp-firmware-b923956874-HPG5-1.1.i386.rpm

### **Important Note!**

- **Online firmware flashing of drives attached to an HP Smart Array controller running in Zero Memory (ZM) mode or an HP ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**

### **Fixes**

#### **Problem Fixed:**

- Fixes a rare but potential data integrity error during low 5v drive voltage and specific sequential data streaming conditions, which could result in data written to incorrect sectors.

---

Supplemental Update / Online ROM Flash Component for Linux - MB2000GCQXQ and MB3000GBKAC Drives

Version: HPGK (**Recommended**)

Filename: rpm/RPMS/i386/hp-firmware-c9026c29f7-HPGK-1.1.i386.rpm

### **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**

### **Fixes**

#### **Problem Fixed:**

- HP ProLiant servers would power down due a hard drive over temp condition that was falsely reported. Hard disk drive firmware HPGK resolves this issue.

---

Supplemental Update / Online ROM Flash Component for Linux - MB2000GCVBR, MB3000GCVBT, and MB4000GCVBU Drives

Version: HPG5 (**Critical**)

Filename: rpm/RPMS/i386/hp-firmware-e4f5b5c9a7-HPG5-1.1.i386.rpm

### **Important Note!**

- **Online firmware flashing of drives attached to an HP Smart Array controller running in Zero Memory (ZM) mode or an HP ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**

### **Fixes**

#### **Problem Fixed:**

- Fixes a rare but potential data integrity error during low 5v drive voltage and specific sequential data streaming conditions, which could



result in data written to incorrect sectors.

---

Supplemental Update / Online ROM Flash Component for Linux - MB3000EBKAB Drives

Version: HPG6 (C) **(Critical)**

Filename: CP022335.md5; CP022335.scexe

### **Important Note!**

- **Online firmware flashing of drives attached to an HP Smart Array controller running in Zero Memory (ZM) mode or an HP ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**
- **Customers who already installed firmware version HPG6 do not need to update to HPG6(C).**

### **Fixes**

#### **Problems Fixed:**

- After long term use of the HDD, a rare condition might occur following a power cycle where the drive heads may land on areas of the disk containing data, which could potentially cause data loss or mechanical damage. Firmware version HPG6 prevents this condition from occurring.
- This firmware corrects "command timeouts" and seek errors which can result in poor performance or a Device Fault condition, the latter of which will result in the drive failed by the Controller or sub system.
- Flashing drives connected behind an HP H2xx Host Bus Adapter (HBA) no longer causes an interrupt resulting in drive firmware installation failures.

### **Enhancements**

#### **Enhancements/New Features:**

- Added support for UEFI (Universal Extensible Firmware Interface) based servers.

---

Supplemental Update / Online ROM Flash Component for Linux - MK0100GCTYU, MK0200GCTYV, MK0400GCTZA, and MK0800GCTZB Drives

Version: HPG4 **(Optional)**

Filename: CP022698.md5; CP022698.scexe

### **Important Note!**

- **Online firmware flashing of drives attached to an HP Smart Array controller running in Zero Memory (ZM) mode or an HP ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**

### **Fixes**

#### **Problems Fixed:**

- This maintenance release corrects a failure seen during a HP Insight Diagnostic hard drive test. The failure was due to Device Extended Self-Test not completing in the drives advertised Self-Test completion time. This failure is not an indication that the drive is bad or marginal.

---

Supplemental Update / Online ROM Flash Component for Linux - MM0500GBKAK and MM1000GBKAL Drives

Version: HPGE **(Recommended)**

Filename: rpm/RPMS/i386/hp-firmware-a08f92a4f9-HPGE-1.1.i386.rpm

### **Important Note!**

- **Online firmware flashing of drives attached to an HPE Smart Array controller running in Zero Memory (ZM) mode or an HPE ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSES would require an offline update using the SPP and HP SUM.**

### **Fixes**

#### **Problems Fixed:**

- Corrected a medium level assert that can occur when the host issues resets after >250ms of idle time. If a drive is affected by the issue, it might display reduced performance and possibly would cease to operate. A hot plug removal and insertion of the affected drive temporarily resolves this issue. Update to drive firmware version HPGE to resolve this issue.

---

Supplemental Update / Online ROM Flash Component for Linux - MO0100EBTJT, MO0200EBTJU, and MO0400EBTJV drives

Version: HPG4 **(Optional)**

Filename: rpm/RPMS/i386/hp-firmware-72e5d6942f-HPG4-1.1.i386.rpm

### **Important Note!**

- **Online firmware flashing of drives attached to an HP Smart Array controller running in Zero Memory (ZM) mode or an HP ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSES would require an offline update using the SPP and HP SUM.**

### **Fixes**

#### **Problems Fixed:**

- Firmware version HPG4 resolved a wear-out issue which was caused by frequently issued PIO commands and resulted in a non-responsive drive.

---

Supplemental Update / Online ROM Flash Component for Linux - VB0160EAVEQ and VB0160CBCDE Drives

Version: HPG9 (C) **(Recommended)**

Filename: CP022342.md5; CP022342.scexe

### **Important Note!**

- **Online firmware flashing of drives attached to an HP Smart Array controller running in Zero Memory (ZM) mode or an HP ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft**

**Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**

- o **Customers who already installed firmware version HPG9 do not need to update to HPG9(C).**

## **Fixes**

### **Problems Fixed:**

- o This firmware corrects the possibility of the drive becoming unresponsive and requiring a power cycle following a soft system reboot. This behavior appears as if the drive is no longer attached to the system following the system soft reboot. It is most often observed during Operating System Installation but can occur following any system soft reboot.
- o Flashing drives connected behind an HP H2xx Host Bus Adapter (HBA) no longer causes an interrupt resulting in drive firmware installation failures.

## **Enhancements**

### **Enhancements/New Features:**

- o Added support for UEFI (Universal Extensible Firmware Interface) based servers.

---

Supplemental Update / Online ROM Flash Component for Linux - VB0250EAVER Drives

Version: HPG9 (C) **(Recommended)**

Filename: CP022343.md5; CP022343.scexe

## **Important Note!**

- o **Online firmware flashing of drives attached to an HP Smart Array controller running in Zero Memory (ZM) mode or an HP ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- o **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSes would require an offline update using the SPP and HP SUM.**
- o **Customers who already installed firmware version HPG9 do not need to update to HPG9(C).**

## **Fixes**

### **Problems Fixed:**

- o This firmware corrects the possibility of the drive becoming unresponsive and requiring a power cycle following a soft system reboot. This behavior appears as if the drive is no longer attached to the system following the system soft reboot. It is most often observed during Operating System Installation but can occur following any system soft reboot.
- o Flashing drives connected behind an HP H2xx Host Bus Adapter (HBA) no longer causes an interrupt resulting in drive firmware installation failures.

## **Enhancements**

### **Enhancements/New Features:**

- o Added support for UEFI (Universal Extensible Firmware Interface) based servers.

---

Supplemental Update / Online ROM Flash Component for Linux - VK0240GDJXU, VK0300GDUQV, VK0480GDJXV, VK0600GDUTQ, and VK0800GDJYA Drives

Version: HPG1 (C) **(Optional)**

Filename: rpm/RPMS/i386/hp-firmware-ef3ea1e703-HPG1-3.i386.rpm

### **Important Note!**

- **Online firmware flashing of drives attached to an HP Smart Array controller running in Zero Memory (ZM) mode or an HP ProLiant host bus adapter (HBA) is NOT supported. Only offline firmware flashing of drives is supported for these configurations.**
- **Online drive firmware update available for Smart Array Controllers configured in systems running supported Linux, Microsoft Windows, and VMware environments. All other OSES would require an offline update using the SPP and HP SUM.**
- **Customers who already installed firmware version HPG1 do not need to update to HPG1(C).**

### **Fixes**

#### **Problems Fixed:**

- This maintenance firmware updates temperature reporting, Sanitize Block Erase and includes read performance improvements.

#### **Problem fixed in HPG1(B):**

- Linux Smart Component fails to update firmware on SATA drive connected behind a SATA HBA controller. Component reports the firmware update was successful. However, after a power cycle, the firmware version remains unchanged.

---

## **Firmware - Storage Controller**

[Top](#)

HP D6000 6Gb SAS Disk Enclosure ROM Flash Component for Windows (x64)

Version: 2.98 **(Critical)**

Filename: cp029908.exe; cp029908.md5

### **Important Note!**

**IMPORTANT:** Firmware updates must be performed during a system maintenance window, with all I/O to the system halted.

**IMPORTANT:** Power up/down sequence is important to maintain integrity of the configuration, please refer to "HP D6000 Disk Enclosure User Guide" document for more details.

**WARNING!** Do not power cycle or restart during the firmware update as this can result in loss of capabilities for this unit. It typically takes several minutes for the firmware to load.

**NOTE:**All firmware flash progress messages are logged to %systemdrive%\CPQSYSTEM\Log\Verbose.log and flash summary is logged to %systemdrive%\CPQSYSTEM\Log\cpqsetup.log.

### **Prerequisites**

**IMPORTANT:** Firmware updates must be performed during a system maintenance window, with all I/O to the system halted.

**WARNING!** Do not power cycle or restart during the firmware update as this can result in loss of capabilities for this unit. It typically takes several minutes for the firmware to load.

**NOTE:**All firmware flash progress messages are logged to %systemdrive%\CPQSYSTEM\Log\Verbose.log and flash summary is logged to %systemdrive%\CPQSYSTEM\Log\cpqsetup.log.

### **Fixes**

#### **Following issue is fixed in this version of firmware:**

Changed the settings in the SAS Expander to support disk discovery when 12Gb SAS HDDs are installed in the enclosure

## **Supported Devices and Features**

HP D6000 Disk Enclosure can be connected behind any of the following devices :

- HP H222 Host Bus Adapter
- HP H221 Host Bus Adapter
- HP H241 Smart Host Bus Adapter
- HP Smart Array P731m Controller
- HP Smart Array P741m Controller
- HP Smart Array P721m Controller
- HP Smart Array P441 Controller
- HP Smart Array P431 Controller
- HP Smart Array P822 Controller
- HP Smart Array P841 Controller
- HP Smart Array P421 Controller

---

HP D6000 6Gb SAS Disk Enclosure ROM Flash Component for Windows (x86)

Version: 2.98 **(Critical)**

Filename: cp029005.exe; cp029005.md5

### **Important Note!**

**IMPORTANT:** Firmware updates must be performed during a system maintenance window, with all I/O to the system halted.

**IMPORTANT:** Power up/down sequence is important to maintain integrity of the configuration, please refer to "HP D6000 Disk Enclosure User Guide" document for more details.

**WARNING!** Do not power cycle or restart during the firmware update as this can result in loss of capabilities for this unit. It typically takes several minutes for the firmware to load.

**NOTE:**All firmware flash progress messages are logged to %systemdrive%\CPQSYSTEM\Log\Verbose.log and flash summary is logged to %systemdrive%\CPQSYSTEM\Log\cpqsetup.log.

### **Prerequisites**

**IMPORTANT:** Firmware updates must be performed during a system maintenance window, with all I/O to the system halted.

**WARNING!** Do not power cycle or restart during the firmware update as this can result in loss of capabilities for this unit. It typically takes several minutes for the firmware to load.

**NOTE:**All firmware flash progress messages are logged to %systemdrive%\CPQSYSTEM\Log\Verbose.log and flash summary is logged to %systemdrive%\CPQSYSTEM\Log\cpqsetup.log.

### **Fixes**

**Following issue is fixed in this version of firmware:**

Changed the settings in the SAS Expander to support disk discovery when 12Gb SAS HDDs are installed in the enclosure

## **Supported Devices and Features**

HP D6000 Disk Enclosure can be connected behind any of the following devices :

- HP H222 Host Bus Adapter
- HP H221 Host Bus Adapter
- HP H241 Smart Host Bus Adapter
- HP Smart Array P731m Controller
- HP Smart Array P741m Controller
- HP Smart Array P721m Controller
- HP Smart Array P441 Controller
- HP Smart Array P431 Controller
- HP Smart Array P822 Controller
- HP Smart Array P841 Controller
- HP Smart Array P421 Controller

---

HP D3600/D3700 12Gb SAS Disk Enclosure ROM Flash Component for Linux (x64)

Version: 3.61 **(Critical)**

Filename: RPMS/x86\_64/hp-firmware-d3600-d3700-3.61-1.1.x86\_64.rpm

### **Important Note!**

**IMPORTANT:** Firmware updates must be performed during a system maintenance window, with all I/O to the system halted.

**WARNING!** Do not power cycle or restart during the firmware update as this can result in loss of capabilities for this unit. It typically takes several minutes for the firmware to load.

**NOTE:** All firmware flash progress messages are logged to /var/cpq/D3000.log and flash summary is logged to /var/cpq/Component.log.

### **Prerequisites**

IMPORTANT: Firmware updates must be performed during a system maintenance window, with all I/O to the system halted.

WARNING! Do not power cycle or restart during the firmware update as this can result in loss of capabilities for this unit. It typically takes several minutes for the firmware to load.

NOTE: All firmware flash progress messages are logged to /var/cpq/D3000.log and flash summary is logged to /var/cpq/Component.log.

### **Fixes**

**The following issues were fixed in firmware 3.61:**

- Few drives moved to Not Available state after power cycle.
- False positive in sherlock: Pcfg file JBOD ID and reported ID from JBOD do not match - but there were no mismatch in logs.

### **Supported Devices and Features**

The D3600 / D3700 Enclosure can be attached to any of the following HP Storage Controllers and Host Bus Adapters :

- HP H222 Host Bus Adapter
- HP H221 Host Bus Adapter
- HP H241 Smart Host Bus Adapter
- HP Smart Array P731m Controller

- HP Smart Array P741m Controller
- HP Smart Array P721m Controller
- HP Smart Array P441 Controller
- HP Smart Array P431 Controller
- HP Smart Array P421 Controller
- HP Smart Array P822 Controller
- HP Smart Array P841 Controller

---

HP D3600/D3700 12Gb SAS Disk Enclosure ROM Flash Component for Linux (x86)

Version: 3.61 **(Critical)**

Filename: RPMS/i386/hp-firmware-d3600-d3700-3.61-1.1.i386.rpm

### **Important Note!**

**IMPORTANT:** Firmware updates must be performed during a system maintenance window, with all I/O to the system halted.

**WARNING!** Do not power cycle or restart during the firmware update as this can result in loss of capabilities for this unit. It typically takes several minutes for the firmware to load.

**NOTE:** All firmware flash progress messages are logged to /var/cpq/D3000.log and flash summary is logged to /var/cpq/Component.log.

### **Prerequisites**

IMPORTANT: Firmware updates must be performed during a system maintenance window, with all I/O to the system halted.

WARNING! Do not power cycle or restart during the firmware update as this can result in loss of capabilities for this unit. It typically takes several minutes for the firmware to load.

NOTE: All firmware flash progress messages are logged to /var/cpq/D3000.log and flash summary is logged to /var/cpq/Component.log.

### **Fixes**

#### **The following issues were fixed in firmware 3.61:**

- Few drives moved to Not Available state after power cycle.
- False positive in sherlock: Pcfg file JBOD ID and reported ID from JBOD do not match - but there were no mismatch in logs.

### **Supported Devices and Features**

The D3600 / D3700 Enclosure can be attached to any of the following HP Storage Controllers and Host Bus Adapters :

- HP H222 Host Bus Adapter
- HP H221 Host Bus Adapter
- HP H241 Smart Host Bus Adapter
- HP Smart Array P731m Controller
- HP Smart Array P741m Controller
- HP Smart Array P721m Controller
- HP Smart Array P441 Controller
- HP Smart Array P431 Controller
- HP Smart Array P421 Controller

- HP Smart Array P822 Controller
- HP Smart Array P841 Controller

---

HP D3600/D3700 12Gb SAS Disk Enclosure ROM Flash Component for VMware (esxi)

Version: 3.61 **(Critical)**

Filename: CP032023.md5; CP032023.zip

### **Important Note!**

**IMPORTANT:** Firmware updates must be performed during a system maintenance window, with all I/O to the system halted.

**WARNING!** Do not power cycle or restart during the firmware update as this can result in loss of capabilities for this unit. It typically takes several minutes for the firmware to load.

**NOTE:**All firmware flash progress messages are logged to /var/cpq/D3000.log and flash summary is logged to /var/cpq/Component.log.

### **Prerequisites**

IMPORTANT: Firmware updates must be performed during a system maintenance window, with all I/O to the system halted.

WARNING! Do not power cycle or restart during the firmware update as this can result in loss of capabilities for this unit. It typically takes several minutes for the firmware to load.

NOTE:All firmware flash progress messages are logged to /var/cpq/D3000.log and flash summary is logged to /var/cpq/Component.log.

### **Fixes**

#### **The following issues were fixed in firmware 3.61:**

- Few drives moved to Not Available state after power cycle.
- False positive in sherlock: Pcfg file JBOD ID and reported ID from JBOD do not match - but there were no mismatch in logs.

### **Supported Devices and Features**

The D3600 / D3700 Enclosure can be attached to any of the following HP Storage Controllers and Host Bus Adapters :

- HP H222 Host Bus Adapter
- HP H221 Host Bus Adapter
- HP H241 Smart Host Bus Adapter
- HP Smart Array P731m Controller
- HP Smart Array P741m Controller
- HP Smart Array P721m Controller
- HP Smart Array P441 Controller
- HP Smart Array P431 Controller
- HP Smart Array P421 Controller
- HP Smart Array P822 Controller
- HP Smart Array P841 Controller

---

HP D3600/D3700 12Gb SAS Disk Enclosure ROM Flash Component for Windows (x64)



### **Important Note!**

**IMPORTANT:** Firmware updates must be performed during a system maintenance window, with all I/O to the system halted.

**WARNING!** Do not power cycle or restart during the firmware update as this can result in loss of capabilities for this unit. It typically takes several minutes for the firmware to load.

**NOTE:**All firmware flash progress messages are logged to %systemdrive%\CPQSYSTEM\Log\D3000.log and flash summary is logged to %systemdrive%\CPQSYSTEM\Log\cpqsetup.log.

### **Prerequisites**

IMPORTANT: Firmware updates must be performed during a system maintenance window, with all I/O to the system halted.

WARNING! Do not power cycle or restart during the firmware update as this can result in loss of capabilities for this unit. It typically takes several minutes for the firmware to load.

NOTE:All firmware flash progress messages are logged to %systemdrive%\CPQSYSTEM\Log\D3000.log and flash summary is logged to %systemdrive%\CPQSYSTEM\Log\cpqsetup.log.

### **Fixes**

#### **The following issues were fixed in firmware 3.61:**

- Few drives moved to Not Available state after power cycle.
- False positive in sherlock: Pcfg file JBOD ID and reported ID from JBOD do not match - but there were no mismatch in logs.

### **Supported Devices and Features**

The D3600 / D3700 Enclosure can be attached to any of the following HP Storage Controllers and Host Bus Adapters :

- HP H222 Host Bus Adapter
- HP H221 Host Bus Adapter
- HP H241 Smart Host Bus Adapter
- HP Smart Array P731m Controller
- HP Smart Array P741m Controller
- HP Smart Array P721m Controller
- HP Smart Array P441 Controller
- HP Smart Array P431 Controller
- HP Smart Array P421 Controller
- HP Smart Array P822 Controller
- HP Smart Array P841 Controller

### **Important Note!**

**IMPORTANT:** Firmware updates must be performed during a system maintenance window, with all I/O to the system halted.

**WARNING!** Do not power cycle or restart during the firmware update as this can result in loss of capabilities for this unit. It typically takes several minutes for the firmware to load.

**NOTE:**All firmware flash progress messages are logged to %systemdrive%\CPQSYSTEM\Log\D3000.log and flash summary is logged to %systemdrive%\CPQSYSTEM\Log\cpqsetup.log.

### **Prerequisites**

**IMPORTANT:** Firmware updates must be performed during a system maintenance window, with all I/O to the system halted.

**WARNING!** Do not power cycle or restart during the firmware update as this can result in loss of capabilities for this unit. It typically takes several minutes for the firmware to load.

**NOTE:**All firmware flash progress messages are logged to %systemdrive%\CPQSYSTEM\Log\D3000.log and flash summary is logged to %systemdrive%\CPQSYSTEM\Log\cpqsetup.log.

### **Fixes**

#### **The following issues were fixed in firmware 3.61:**

- Few drives moved to Not Available state after power cycle.
- False positive in sherlock: Pcfg file JBOD ID and reported ID from JBOD do not match - but there were no mismatch in logs.

### **Supported Devices and Features**

The D3600 / D3700 Enclosure can be attached to any of the following HP Storage Controllers and Host Bus Adapters :

- HP H222 Host Bus Adapter
- HP H221 Host Bus Adapter
- HP H241 Smart Host Bus Adapter
- HP Smart Array P731m Controller
- HP Smart Array P741m Controller
- HP Smart Array P721m Controller
- HP Smart Array P441 Controller
- HP Smart Array P431 Controller
- HP Smart Array P421 Controller
- HP Smart Array P822 Controller
- HP Smart Array P841 Controller

---

HP D6000 6Gb SAS Disk Enclosure ROM Flash Component for Linux (x64)

Version: 2.98 **(Critical)**

Filename: RPMS/x86\_64/hp-firmware-smartarray-d6000-2.98-1.1.x86\_64.rpm

### **Important Note!**

**IMPORTANT:** Firmware updates must be performed during a system maintenance window, with all I/O to the system halted.

**IMPORTANT:** Power up/down sequence is important to maintain integrity of the configuration, please refer to "HP D6000 Disk Enclosure User Guide" document for more details.

**WARNING!** Do not power cycle or restart during the firmware update as this can result in loss of capabilities for this unit. It typically takes several minutes for the firmware to load.

**NOTE:**All firmware flash progress messages are logged to /var/cpq/Verbose.log and flash summary is logged to /var/cpq/Component.log.

### **Prerequisites**

IMPORTANT: Firmware updates must be performed during a system maintenance window, with all I/O to the system halted.

**WARNING!** Do not power cycle or restart during the firmware update as this can result in loss of capabilities for this unit. It typically takes several minutes for the firmware to load.

**NOTE:**All firmware flash progress messages are logged to /var/cpq/Verbose.log and flash summary is logged to /var/cpq/Component.log.

### **Fixes**

#### **Following issue is fixed in this version of firmware:**

Changed the settings in the SAS Expander to support disk discovery when 12Gb SAS HDDs are installed in the enclosure

### **Supported Devices and Features**

HP D6000 Disk Enclosure can be connected behind any of the following devices :

- HP H222 Host Bus Adapter
- HP H221 Host Bus Adapter
- HP H241 Smart Host Bus Adapter
- HP Smart Array P731m Controller
- HP Smart Array P741m Controller
- HP Smart Array P721m Controller
- HP Smart Array P441 Controller
- HP Smart Array P431 Controller
- HP Smart Array P822 Controller
- HP Smart Array P841 Controller
- HP Smart Array P421 Controller

---

HP D6000 6Gb SAS Disk Enclosure ROM Flash Component for Linux (x86)

Version: 2.98 **(Critical)**

Filename: RPMS/i386/hp-firmware-smartarray-d6000-2.98-1.1.i386.rpm

### **Important Note!**

**IMPORTANT:** Firmware updates must be performed during a system maintenance window, with all I/O to the system halted.

**IMPORTANT:** Power up/down sequence is important to maintain integrity of the configuration, please refer to "HP D6000 Disk Enclosure User Guide" document for more details.

**WARNING!** Do not power cycle or restart during the firmware update as this can result in loss of capabilities for this unit. It typically takes several minutes for the firmware to load.

**NOTE:**All firmware flash progress messages are logged to /var/cpq/Verbose.log and flash summary is logged to /var/cpq/Component.log.

### **Prerequisites**

IMPORTANT: Firmware updates must be performed during a system maintenance window, with all I/O to the system halted.

WARNING! Do not power cycle or restart during the firmware update as this can result in loss of capabilities for this unit. It typically takes several minutes for the firmware to load.

NOTE: All firmware flash progress messages are logged to /var/cpq/Verbose.log and flash summary is logged to /var/cpq/Component.log.

## **Fixes**

### **Following issue is fixed in this version of firmware:**

Changed the settings in the SAS Expander to support disk discovery when 12Gb SAS HDDs are installed in the enclosure

## **Supported Devices and Features**

HP D6000 Disk Enclosure can be connected behind any of the following devices :

- HP H222 Host Bus Adapter
- HP H221 Host Bus Adapter
- HP H241 Smart Host Bus Adapter
- HP Smart Array P731m Controller
- HP Smart Array P741m Controller
- HP Smart Array P721m Controller
- HP Smart Array P441 Controller
- HP Smart Array P431 Controller
- HP Smart Array P822 Controller
- HP Smart Array P841 Controller
- HP Smart Array P421 Controller

---

HP D6000 6Gb SAS Disk Enclosure ROM Flash Component for VMware (esxi)

Version: 2.98 **(Critical)**

Filename: CP029051.md5; CP029051.zip

## **Important Note!**

**IMPORTANT:** Firmware updates must be performed during a system maintenance window, with all I/O to the system halted.

**IMPORTANT:** Power up/down sequence is important to maintain integrity of the configuration, please refer to HP D6000 Disk Enclosure User Guide document for more details.

**WARNING!** Do not power cycle or restart during the firmware update as this can result in loss of capabilities for this unit. It typically takes several minutes for the firmware to load.

**NOTE:** All firmware flash progress messages are logged to /var/cpq/Verbose.log and flash summary is logged to /var/cpq/Component.log.

## **Prerequisites**

IMPORTANT: Firmware updates must be performed during a system maintenance window, with all I/O to the system halted.

WARNING! Do not power cycle or restart during the firmware update as this can result in loss of capabilities for this unit. It typically takes several minutes for the firmware to load.

NOTE: All firmware flash progress messages are logged to /var/cpq/Verbose.log and flash summary is logged to /var/cpq/Component.log.

## **Fixes**

### **Following issue is fixed in this version of firmware:**

Changed the settings in the SAS Expander to support disk discovery when 12Gb SAS HDDs are installed in the enclosure

## **Supported Devices and Features**

HP D6000 Disk Enclosure can be connected behind any of the following devices :

- HP H222 Host Bus Adapter
- HP H221 Host Bus Adapter
- HP H241 Smart Host Bus Adapter
- HP Smart Array P731m Controller
- HP Smart Array P741m Controller
- HP Smart Array P721m Controller
- HP Smart Array P441 Controller
- HP Smart Array P431 Controller
- HP Smart Array P822 Controller
- HP Smart Array P841 Controller
- HP Smart Array P421 Controller

---

Online ROM Flash Component for VMware ESXi - Smart Array P212, P410, P410i, P411, P711m, P712m, and P812

Version: 6.64 (B) **(Recommended)**

Filename: CP027482.zip

## **Fixes**

- Running SMARTCTL (smartmontools) on HP Proliant G6/G7 (Px1x) Smart Array controllers that have firmware version 5.70 to 6.62 installed with SATA drives attached may result in system not responding or reboot. When reboot occurred, a reboot 1719 POST error message with lockup 0x15 displayed.

---

Online ROM Flash Component for Windows (x64) - Smart Array P212, P410, P410i, P411, P711m, P712m, and P812

Version: 6.64 (B) **(Recommended)**

Filename: cp027485.exe; cp027485.md5

## **Fixes**

- Running SMARTCTL (smartmontools) on HP Proliant G6/G7 (Px1x) Smart Array controllers that have firmware version 5.70 to 6.62 installed with SATA drives attached may result in system not responding or reboot. When reboot occurred, a reboot 1719 POST error message with lockup 0x15 displayed.

---

Online ROM Flash Component for Windows (x64) - Smart Array P220i, P222, P420i, P420, P421, P721m, and P822

Version: 8.00 **(Recommended)**

Filename: cp030726.exe; cp030726.md5

## **Fixes**

- Drive temperatures for SATA drives might not be reported after hot-inserting the drive.

- System might hang at POST following a reboot.
- System fans might go to 100% if connected drives were spun down.
- SATA SSD's were incorrectly marked as worn out.

### **Enhancements**

- Increased performance of SATA drives by increasing command queue depth.

---

Online ROM Flash Component for Windows - Smart Array P212, P410, P410i, P411, P711m, P712m, and P812

Version: 6.64 (B) **(Recommended)**

Filename: cp027484.exe; cp027484.md5

### **Fixes**

- Running SMARTCTL (smartmontools) on HP ProLiant G6/G7 (Px1x) Smart Array controllers that have firmware version 5.70 to 6.62 installed with SATA drives attached may result in system not responding or reboot. When reboot occurred, a reboot 1719 POST error message with lockup 0x15 displayed.

---

Online ROM Flash Component for Windows - Smart Array P220i, P222, P420i, P420, P421, P721m, and P822

Version: 8.00 **(Recommended)**

Filename: cp030725.exe; cp030725.md5

### **Fixes**

- Drive temperatures for SATA drives might not be reported after hot-inserting the drive.
- System might hang at POST following a reboot.
- System fans might go to 100% if connected drives were spun down.
- SATA SSD's were incorrectly marked as worn out.

### **Enhancements**

- Increased performance of SATA drives by increasing command queue depth.

---

Online ROM Flash Component for Windows - Smart Array P700m

Version: 7.24 (B) **(Recommended)**

Filename: cp019156.exe; cp019156.md5

### **Important Note!**

Customers who already installed firmware version 7.24 do not need to update to 7.24(B).

### **Fixes**

#### **Firmware Dependency:**

- Updating the HP DL360G5 System ROM to revision P58 3/9/08 or higher is required in addition to updating to this HP Smart Array firmware revision for the modified shutdown sequence to ensure sufficient time for HDD head parking of internal HDDs.
- Updating the HP MSA 60 and/or MSA 70 firmware version to 2.16 or higher is required to enable dual domain functionality.

#### **Problems Fixed:**

- Resolved an issue where the server's system event log would fill with Event ID 129 warnings and the Smart Array controller would become unresponsive.
- **FW version 7.24(B)** - Fixed an issue where a decimal conversion was not being interpreted correctly when installing the component under certain regional settings in Windows. This would cause the component installation to end with a return code 3 (already up to date) and a force install would be required to successfully update the FW.

---

Supplemental Update / Online ROM Flash Component for Linux (x64) - Smart Array P212, P410, P410i, P411, P711m, P712m, and P812

Version: 6.64 (B) **(Recommended)**

Filename: hp-firmware-smartarray-14ef73e580-6.64-2.x86\_64.rpm

### **Important Note!**

- **Customers who already installed firmware version 6.64 do not need to update to 6.64 (B).**

### **Fixes**

- Running SMARTCTL (smartmontools) on HP Proliant G6/G7 (Px1x) Smart Array controllers that have firmware version 5.70 to 6.62 installed with SATA drives attached may result in system not responding or reboot. When reboot occurred, a reboot 1719 POST error message with lockup 0x15 displayed.

---

Supplemental Update / Online ROM Flash Component for Linux (x64) - Smart Array P220i, P222, P420i, P420, P421, P721m, and P822

Version: 8.00 **(Recommended)**

Filename: rpm/RPMS/x86\_64/hp-firmware-smartarray-46a4d957a7-8.00-1.1.x86\_64.rpm

### **Important Note!**

- When booting a system running Red Hat Enterprise Linux 7.1 Operating System, the HP Smart Array controllers might not be recognized. This issue is due to changes in the OS where the sg driver is no longer loaded during system boot. The work around for this issue is to manually issue a "**modprobe sg**" command which should load the sg driver. After the sg driver is loaded, the /dev/sg\* devices should be present and the sg driver can be used to access SCSI devices.

### **Fixes**

- Drive temperatures for SATA drives might not be reported after hot-inserting the drive.
- System might hang at POST following a reboot.
- System fans might go to 100% if connected drives were spun down.
- SATA SSD's were incorrectly marked as worn out.

### **Enhancements**

- Increased performance of SATA drives by increasing command queue depth.

---

Supplemental Update / Online ROM Flash Component for Linux - Smart Array P212, P410, P410i, P411, P711m, P712m, and P812

Version: 6.64 (B) **(Recommended)**

Filename: hp-firmware-smartarray-14ef73e580-6.64-2.i386.rpm

### **Fixes**

Running SMARTCTL (smartmontools) on HP Proliant G6/G7 (Px1x) Smart Array controllers that have firmware version 5.70 to 6.62 installed with SATA drives attached may result in system not responding or reboot. When reboot occurred, a reboot 1719 POST error message with lockup 0x15 displayed.

---

Supplemental Update / Online ROM Flash Component for Linux - Smart Array P220i, P222, P420i, P420, P421, P721m, and P822

Version: 8.00 **(Recommended)**

Filename: rpm/RPMS/i386/hp-firmware-smartarray-46a4d957a7-8.00-1.1.i386.rpm

### **Important Note!**

- When booting a system running Red Hat Enterprise Linux 7.1 Operating System, the HP Smart Array controllers might not be recognized. This issue is due to changes in the OS where the sg driver is no longer loaded during system boot. The work around for this issue is to manually issue a "**modprobe sg**" command which should load the sg driver. After the sg driver is loaded, the /dev/sg\* devices should be present and the sg driver can be used to access SCSI devices.

### **Fixes**

- Drive temperatures for SATA drives might not be reported after hot-inserting the drive.
- System might hang at POST following a reboot.
- System fans might go to 100% if connected drives were spun down.
- SATA SSD's were incorrectly marked as worn out.

### **Enhancements**

- Increased performance of SATA drives by increasing command queue depth.

---

Supplemental Update / Online ROM Flash Component for Linux - Smart Array P700m

Version: 7.24 **(Recommended)**

Filename: CP017696.md5; CP017696.scexe

### **Important Note!**

**When running VMware ESX/ESXi, only offline updates are supported using the HP Smart Update Manager on the Firmware Maintenance CD.**

### **Fixes**

#### **Firmware Dependency:**

- Updating the HP DL360G5 System ROM to revision P58 3/9/08 or higher is required in addition to updating to this HP Smart Array firmware revision for the modified shutdown sequence to ensure sufficient time for HDD head parking of internal HDDs.
- Updating the HP MSA 60 and/or MSA 70 firmware version to 2.16 or higher is required to enable dual domain functionality.

#### **Problems Fixed:**

- Resolved an issue where the server's system event log would fill with Event ID 129 warnings and the Smart Array controller would become unresponsive.



HP Firmware Flash for QLogic BR-series Fibre Channel Host Bus Adapters - Linux (x86\_64)

Version: 2015.02.01 (B) **(Recommended)**

Filename: RPMS/x86\_64/hp-firmware-fc-brocade-2015.02.01-2.x86\_64.rpm

### **Important Note!**

Release Notes:

[HP StorageWorks Brocade Fibre Channel Host Bus Adapters Release Notes](#)

### **Prerequisites**

The HP supplied enablement kit must be installed prior to this firmware component being identified by HP SUM for deployment. The software is available from [www.hp.com/go/fchba](http://www.hp.com/go/fchba). Select your product and then select the Software and Drivers page to find the enablement kit. The enablement kit is also available on the HP Service Pack for Proliant (SPP) version 2015.03.0 which is available at [www.hp.com/go/spp/download](http://www.hp.com/go/spp/download).

- HP Fibre Channel Enablement Kit for Linux, HP-FC-Brocade-Enablement-Kit-5.0.0.0-3.x86\_64.rpm

### **Enhancements**

This component contains the same payload as version 2015.02.01. However, the resulting executable files contained within the rpm have been renamed for commonality across all HP Linux firmware components.

Contains updated boot bios version 3.2.5.0. This version is supported on the following operating systems:

- Red Hat Enterprise Linux 6 updates 5 and 6
- Red Hat Enterprise Linux 7
- SUSE Linux Enterprise Server 12

### **Supported Devices and Features**

This firmware supports the following HP adapters:

- HP 81B PCIe 8Gb Fibre Channel Single Port Host Bus Adapter
- HP 82B PCIe 8Gb Fibre Channel Dual Port Host Bus Adapter
- Brocade 804 8Gb Fibre Channel HBA for c-Class BladeSystem

---

HP Firmware Flash for QLogic BR-series Fibre Channel Host Bus Adapters for vSphere 5.5 and 6.0

Version: 2015.02.01 (b) **(Recommended)**

Filename: CP025934.md5; CP025934.zip

### **Important Note!**

Release Notes:

[HP StorageWorks Brocade Fibre Channel Host Bus Adapters Release Notes](#)

### **Enhancements**

This component contains the same payload as version 2015.02.01. However, the resulting executable format has been changed from .scexe to .zip.

Contains boot bios, version 3.2.5.0.

## Supported Devices and Features

This firmware supports the following HP adapters:

- HP 81B PCIe 8Gb Fibre Channel Single Port Host Bus Adapter
- HP 82B PCIe 8Gb Fibre Channel Dual Port Host Bus Adapter
- Brocade 804 8Gb Fibre Channel HBA for c-Class BladeSystem

---

HP Firmware Online Flash for QLogic BR-series Fibre Channel Host Bus Adapters - Windows 2008 R2/2012/2012 R2 (x64)

Version: 2015.02.01 **(Recommended)**

Filename: cp025186.exe

### **Important Note!**

Release Notes:

[HP StorageWorks Brocade Fibre Channel Host Bus Adapters Release Notes](#)

### **Prerequisites**

The HP supplied QLogic BR-series driver must be installed prior to this firmware component being identified by HP SUM for deployment. The software is available from [www.hp.com/go/fchba](http://www.hp.com/go/fchba). Select your product and then select the Software and Drivers page to find the required driver. The HP Brocade driver is also available on the HP Service Pack for ProLiant (SPP) version 2015.03.0 which is available at [www.hp.com/go/spp/download](http://www.hp.com/go/spp/download).

- HP Storage x64 QLogic BR-series Storport Fibre Channel Host Bus Adapter Driver for Microsoft Windows Server 2008 R2, version 3.2.5.0, cp025314.exe
- HP Storage x64 QLogic BR-series Storport Fibre Channel Host Bus Adapter Driver for Microsoft Windows Server 2012, version 3.2.5.0, cp025313.exe
- HP Storage x64 QLogic BR-series Storport Fibre Channel Host Bus Adapter Driver for Microsoft Windows Server 2012 R2, version 3.2.5.0, cp025052.exe

### **Enhancements**

Boot bios updated to version 3.2.5.0 to synchronize with HP's QLogic BR-series 3.2.5.0 driver.

## Supported Devices and Features

This firmware supports the following HP adapters:

- HP 81B PCIe 8Gb Fibre Channel Single Port Host Bus Adapter
- HP 82B PCIe 8Gb Fibre Channel Dual Port Host Bus Adapter
- Brocade 804 8Gb Fibre Channel HBA for c-Class BladeSystem

---

HPE Firmware Flash for Emulex Fibre Channel Host Bus Adapters - Linux (x64)

Version: 2016.10.04 **(Recommended)**

Filename: RPMS/x86\_64/hp-firmware-fc-emulex-2016.10.04-1.5.x86\_64.rpm

### **Important Note!**

Release Notes:

[HPE StoreFabric Emulex Adapters Release Notes](#)

## **Prerequisites**

Please consult SPOCK for a list of supported configurations available at the following link:

<http://www.hpe.com/storage/spock/>

The HPE supplied Emulex driver and enablement kit must be installed prior to this firmware component being identified by HP SUM for deployment. The driver and enablement kit are available on the HPE.com website which is available at <http://www.hpe.com/>.

Linux FC Driver Kit for HPE Branded Emulex FC HBAs and mezz cards, version 11.1.183.21, for RedHat 6, RedHat 7, and Novell SUSE 11, SUSE12

HPE Fibre Channel Enablement Kit for Linux, HP-CNA-FC-Emulex\_Enablement-Kit, version 11.1.183.22-1

The Enablement Kit requires that the target environment have the libHBAAPI package installed from your OS installation media.

Install the FC Driver Kit, reboot, and then install the Enablement Kit.

Additional requirements:

Environment must be running the syslog daemon for the flash engine to run

Environment must have 32-bit netlink library (libnl.so) installed for component to be able to discover Emulex HBAs

## **Fixes**

This fix resolves an issue in which 16Gb HBAs were unable to login when connected directly to a target port on 3PAR arrays

## **Enhancements**

We have separate components to update fibre channel and converged network adapters. This is a fibre channel update component.

Updated 16Gb HBA/Mezz universal boot

Contains:

16 Gb HBA/Mezz universal boot 11.1.183.58

8 Gb standup/mezz firmware 2.03X6

8 Gb standup universal boot image 5.21x11 (2.20a7 BIOS, 4.20a15 UEFI)

8 Gb mezzanine universal boot image 6.21x1 (3.30a14 BIOS, 4.20a15 UEFI)

## **Supported Devices and Features**

- HP SN1000E 16Gb Dual Port Fibre Channel Host Bus Adapter
- HP SN1000E 16Gb Single Port Fibre Channel Host Bus Adapter
- HP 82E 8Gb Dual Port PCIe Fibre Channel Host Bus Adapter
- HP 81E 8Gb Single Port PCIe Fibre Channel Host Bus Adapter
- HP LPe1205A 8Gb Fibre Channel Host Bus Adapter for BladeSystem c-Class
- Emulex LPe1205 8Gb Fibre Channel Host Bus Adapter for c-Class BladeSystem
- HP SN1100E 16Gb Dual Port Fibre Channel Host Bus Adapter
- HP SN1100E 16Gb Single Port Fibre Channel Host Bus Adapter
- HP Fibre Channel 16Gb LPe1605 Mezz

- HP StoreFabric 84E 4-Port Fibre Channel Host Bus Adapter
- HPE Synergy 3530C 16Gb Fibre Channel Host Bus Adapter
- HPE StoreFabric SN1100E 4P 16Gb FC HBA

---

HPE Firmware Flash for Emulex Fibre Channel Host Bus Adapters - Linux (x86)

Version: 2016.10.04 **(Recommended)**

Filename: RPMS/i386/hp-firmware-fc-emulex-2016.10.04-1.3.i386.rpm

### **Important Note!**

Release Notes:

[HPE StoreFabric Emulex Adapters Release Notes](#)

### **Prerequisites**

Please consult SPOCK for a list of supported configurations available at the following link:

<http://www.hpe.com/storage/spock/>

The HPE supplied Emulex driver and enablement kit must be installed prior to this firmware component being identified by HP SUM for deployment. The driver and enablement kit are available on the HPE.com website which is available at <http://www.hpe.com/>.

Linux FC Driver Kit for HPE Branded Emulex FC HBAs and mezz cards, version 11.1.183.21, for RedHat 6, RedHat 7, and Novell SUSE 11, SUSE12

HPE Fibre Channel Enablement Kit for Linux, HP-CNA-FC-Emulex\_Enablement-Kit, version 11.1.183.22-1

The Enablement Kit requires that the target environment have the libHBAAPI package installed from your OS installation media.

Install the FC Driver Kit, reboot, and then install the Enablement Kit.

Additional requirements:

Environment must be running the syslog daemon for the flash engine to run

Environment must have 32-bit netlink library (libnl.so) installed for component to be able to discover Emulex HBAs

### **Fixes**

This fix resolves an issue in which 16Gb HBAs were unable to login when connected directly to a target port on 3PAR arrays

### **Enhancements**

We have separate components to update fibre channel and converged network adapters. This is a fibre channel update component.

Updated 16 Gb HBA/Mezz universal boot

Contains:

16 Gb HBA/Mezz universal boot 11.1.183.58

8 Gb standup/mezz firmware 2.03X6

8 Gb standup universal boot image 5.21x11 (2.20a7 BIOS, 4.20a15 UEFI)

## **Supported Devices and Features**

- HP SN1000E 16Gb Dual Port Fibre Channel Host Bus Adapter
- HP SN1000E 16Gb Single Port Fibre Channel Host Bus Adapter
- HP 82E 8Gb Dual Port PCIe Fibre Channel Host Bus Adapter
- HP 81E 8Gb Single Port PCIe Fibre Channel Host Bus Adapter
- HP LPe1205A 8Gb Fibre Channel Host Bus Adapter for BladeSystem c-Class
- Emulex LPe1205 8Gb Fibre Channel Host Bus Adapter for c-Class BladeSystem
- HP SN1100E 16Gb Dual Port Fibre Channel Host Bus Adapter
- HP SN1100E 16Gb Single Port Fibre Channel Host Bus Adapter
- HP Fibre Channel 16Gb LPe1605 Mezz
- HP StoreFabric 84E 4-Port Fibre Channel Host Bus Adapter

---

HPE Firmware Flash for Emulex Fibre Channel Host Bus and Converged Network Adapters for VMware vSphere 5.5 and 6.0

Version: 2016.10.05 **(Recommended)**

Filename: CPO31843.md5; CPO31843.zip

## **Important Note!**

Release Notes:

[HPE StoreFabric Emulex Adapter Release Notes](#)

## **Prerequisites**

Please consult SPOCK for a list of supported configurations available at the following link:

<http://www.hpe.com/storage/spock/>

## **Fixes**

This fix resolves the following:

- unexpected behavior in which ProLiant Gen 9 c-class server blades equipped with 650FLB or 650M adapters may not complete Power-On Self Test (POST)
- unexpected behavior which occurred after upgrading firmware to 11.1.183.23, resulting in network ports losing connections
- unexpected behavior in which 650FLB network ports were inadvertently assigned the same MAC address, resulting in network packets being sent to the incorrect ports.
- behavior in which Microsoft Windows terminates unexpectedly
- resolves an issue in which 16Gb HBAs were unable to login when connected directly to a target port on 3PAR arrays

## **Enhancements**

Updated CNA (XE100 series) firmware

### **Contains:**

CNA (BE3) firmware 11.1.183.23

CNA (XE100 series) firmware 11.1.183.62

16 Gb HBA/Mezz universal boot 11.1.183.58

8 Gb standup/mezz firmware 2.03x6

8 Gb standup universal boot image 5.21x11 (2.20a7 BIOS, 4.20a15 UEFI)

8 Gb mezzanine universal boot image 6.21x1 (3.30a14 BIOS, 4.20a15 UEFI)

## **Supported Devices and Features**

### **8Gb FC:**

- HP 81E 8Gb Single Port PCIe Fibre Channel Host Bus Adapter
- HP 82E 8Gb Dual Port PCIe Fibre Channel Host Bus Adapter
- Emulex LPe1205 8Gb Fibre Channel Host Bus Adapter for c-Class BladeSystem
- HP LPe1205A 8Gb Fibre Channel Host Bus Adapter for BladeSystem c-Class
- HP StoreFabric 84E 4-Port Fibre Channel Host Bus Adapter

### **16Gb FC:**

- HP SN1000E 16Gb Dual Port Fibre Channel Host Bus Adapter
- HP SN1000E 16Gb Single Port Fibre Channel Host Bus Adapter
- HP Fibre Channel 16Gb LPe1605 Mezz
- HP SN1100E 16Gb Dual Port Fibre Channel Host Bus Adapter
- HP SN1100E 16Gb Single Port Fibre Channel Host Bus Adapter
- HPE StoreFabric SN1100E 4P 16Gb FC HBA
- HPE Synergy 3530C 16Gb Fibre Channel Host Bus Adapter

### **BE3:**

- HP NC552SFP 10Gb 2-port Ethernet Server Adapter
- HP NC553i 10Gb 2-port FlexFabric Converged Network Adapter
- HP CN1100E Dual Port Converged Network Adapter
- HP Flex-10 10Gb 2-port 552M Adapter
- HP FlexFabric 10Gb 2-port 554M Adapter
- HP FlexFabric 10Gb 2-port 554FLR-SFP+ Adapter
- HP FlexFabric 10Gb 2-port 554FLB Adapter

### **XE100 Series:**

- HP StoreFabric CN1200E Dual Port Converged Network Adapter
- HP Ethernet 10Gb 2-port 557SFP+ Adapter
- HP FlexFabric 20Gb 2-port 650FLB Adapter
- HP FlexFabric 20Gb 2-port 650M Adapter
- HP FlexFabric 10Gb 2-port 556FLR-SFP+ Adapter
- HPE StoreFabric CN1200E-T Adapter
- HPE FlexFabric 10Gb 2-port 556FLR-T Adapter

---

HPE Firmware Flash for QLogic Fibre Channel Host Bus Adapters - Linux (x86)

Version: 2016.10.01 **(Recommended)**

Filename: RPMS/i386/hp-firmware-fc-qlogic-2016.10.01-1.22.i386.rpm

## **Important Note!**

Release Notes:

## **Prerequisites**

Please consult SPOCK for a list of supported configurations available at the following link:

<http://www.hpe.com/storage/spock/>

The HPE supplied QLogic driver and enablement kit must be installed prior to this firmware component being identified by HP SUM for deployment. The software is available in the Service Pack for ProLiant 2016.10.0, which is available at <http://www.hpe.com/servers/spp/download>:

- SUSE Linux Enterprise Server 11 (x86) FCoE/FC Driver Kit for HPE Qlogic CNAs, HBAs and mezzanine HBAs, version 8.07.00.34.11.3-k
- HPE Fibre Channel Enablement Kit for Linux - QLogic, version 6.0.0.0-2

## **Enhancements**

Updated the Firmware/BIOS/UEFI packages for 8 Gb and 16 Gb products.

- 8 Gb HBA/Mezz
  - Package 3.75.07
  - Firmware 8.02.00
  - UEFI 6.45
  - BIOS 3.31
- 16 Gb HBA/Mezz
  - Package 6.01.14
  - Firmware 8.02.51
  - UEFI 6.39
  - BIOS 3.31

## **Supported Devices and Features**

This firmware supports the following HP adapters:

- HP 81Q PCIe Fibre Channel Host Bus Adapter
- HP 82Q 8Gb Dual Port PCIe Fibre Channel Host Bus Adapter
- QLogic QMH2562 8Gb Fibre Channel Host Bus Adapter for c-Class BladeSystem
- HP QMH2572 8Gb Fibre Channel Host Bus Adapter for c-Class BladeSystem
- HP QMH2672 16Gb FC HBA for c-Class BladeSystem
- HP StoreFabric SN1000Q 16GB 2-port PCIe Fibre Channel Host Bus Adapter
- HP StoreFabric SN1000Q 16GB 1-port PCIe Fibre Channel Host Bus Adapter

## **Important Note!**

Release Notes:

[HPE StoreFabric QLogic Adapter Release Notes](#)

## **Prerequisites**

Please consult SPOCK for a list of supported configurations available at the following link:

<http://www.hpe.com/storage/spock/>

The HPE supplied QLogic driver and enablement kit must be installed prior to this firmware component being identified by HP SUM for deployment. Use the appropriate software included in the Service Pack for ProLiant 2016.10.0, which is available at

[www.hpe.com/servers/spp/download](http://www.hpe.com/servers/spp/download)

- Red Hat Enterprise Linux 6 Server (x86-64) FCoE/FC Driver Kit for HPE Qlogic CNAs, HBAs and mezzanine HBAs, version 8.07.00.34.06.0-k4
- Red Hat Enterprise Linux 7 Server FCoE/FC Driver Kit for HPE QLogic CNAs, HBAs and mezzanine HBAs and CNAs, version 8.07.00.34.07.0-k4
- SUSE Linux Enterprise Server 11 (AMD64/EM64T) FCoE/FC Driver Kit for HPE Qlogic CNAs, HBAs and mezzanine HBAs, version 8.07.00.34.11.3-k
- SUSE Linux Enterprise Server 12 FCoE/FC Driver Kit for HPE QLogic CNAs, HBAs and mezzanine HBAs and CNAs version 8.07.00.34.12.0-k1
- HPE Fibre Channel Enablement Kit for Linux - QLogic, version 6.0.0.0-2

## **Enhancements**

Add support for the following devices:

- HPE StoreFabric 84Q 4P 8Gb Fibre Channel HBA
- HPE StoreFabric SN1100Q 16Gb 2P FC HBA
- HPE StoreFabric SN1100Q 16Gb 1P FC HBA
- HPE Synergy 3830C 16G Fibre Channel Host Bus Adapter

Updated the Firmware/BIOS/UEFI packages for 8 Gb and 16 Gb products.

- 8 Gb HBA/Mezz
  - Package 3.75.07
  - Firmware 8.02.00
  - UEFI 6.45
  - BIOS 3.31
- 16 Gb HBA/Mezz
  - Package 6.01.14
  - Firmware 8.02.51
  - UEFI 6.39
  - BIOS 3.31
- 16 Gb SN1100Q
  - Package 01.70.17
  - Firmware 8.03.05
  - UEFI 6.19



- BIOS 3.37

## **Supported Devices and Features**

This firmware supports the following HP adapters:

- HP 81Q PCIe Fibre Channel Host Bus Adapter
- HP 82Q 8Gb Dual Port PCIe Fibre Channel Host Bus Adapter
- QLogic QMH2562 8Gb Fibre Channel Host Bus Adapter for c-Class BladeSystem
- HP QMH2572 8Gb Fibre Channel Host Bus Adapter for c-Class BladeSystem
- HP QMH2672 16Gb FC HBA for c-Class BladeSystem
- HP StoreFabric SN1000Q 16GB 2-port PCIe Fibre Channel Host Bus Adapter
- HP StoreFabric SN1000Q 16GB 1-port PCIe Fibre Channel Host Bus Adapter
- HPE StoreFabric SN1100Q 16Gb 2P FC HBA
- HPE StoreFabric SN1100Q 16Gb 1P FC HBA
- HPE StoreFabric 84Q 4P 8Gb Fibre Channel HBA
- HPE Synergy 3830C 16G Fibre Channel Host Bus Adapter

---

HPE Firmware Flash for QLogic Fibre Channel Host Bus Adapters for VMware vSphere 5.5 and VMware vSphere 6.0

Version: 2016.10.01 **(Recommended)**

Filename: CPO29695.md5; CPO29695.zip

## **Important Note!**

[HPE StoreFabric QLogic Adapter Release Notes](#)

## **Prerequisites**

Please consult SPOCK for a list of supported configurations available at the following link:

<http://www.hpe.com/storage/spock/>

## **Enhancements**

Add support for the following devices:

- HPE StoreFabric 84Q 4P 8Gb Fibre Channel HBA
- HPE StoreFabric SN1100Q 16Gb 2P FC HBA
- HPE StoreFabric SN1100Q 16Gb 1P FC HBA
- HPE Synergy 3830C 16G Fibre Channel Host Bus Adapter

Updated the Firmware/BIOS/UEFI packages for 8 Gb and 16 Gb products.

- 8 Gb HBA/Mezz
  - Package 3.75.07
  - Firmware 8.02.00
  - UEFI 6.45
  - BIOS 3.31
- 16 Gb HBA/Mezz
  - Package 6.01.14
  - Firmware 8.02.51

- UEFI 6.39
- BIOS 3.31
  
- 16 Gb SN1100Q
  - Package 1.70.17
  - Firmware 8.03.05
  - UEFI 6.19
  - BIOS 3.37

## **Supported Devices and Features**

This firmware supports the following HPE adapters:

- HP 81Q PCIe Fibre Channel Host Bus Adapter
- HP 82Q 8Gb Dual Port PCIe Fibre Channel Host Bus Adapter
- QLogic QMH2562 8Gb Fibre Channel Host Bus Adapter for c-Class BladeSystem
- HP QMH2572 8Gb Fibre Channel Host Bus Adapter for c-Class BladeSystem
- HP StoreFabric SN1000Q 16Gb Fibre Channel Host Bus Adapter
- HP QMH2672 16Gb FC HBA for c-Class BladeSystem
- HPE StoreFabric SN1100Q 16Gb 1P FC HBA
- HPE StoreFabric SN1100Q 16Gb 2P FC HBA
- HPE StoreFabric 84Q 4P 8Gb Fibre Channel HBA
- HPE Synergy 3830C 16G Fibre Channel Host Bus Adapter

---

HPE Firmware Online Flash for Emulex Fibre Channel Host Bus Adapters - Windows 2008 x86

Version: 2016.10.04 **(Recommended)**

Filename: cp031815.exe

## **Important Note!**

Release Notes:

[HPE StoreFabric Emulex Adapters Release Notes](#)

## **Prerequisites**

Please consult SPOCK for a list of supported configurations available at the following link:

<http://www.hpe.com/storage/spock/>

The HPE supplied Emulex driver must be installed prior to this firmware component being identified by HP SUM for deployment. The driver is available on the HPE.com website at <http://www.hpe.com/>:

HPE Storage Fibre Channel Adapter Kit for the x86 Emulex Storport Driver v11.1.145.16 cp029980.exe

## **Fixes**

This fix resolves an issue in which 16Gb HBAs were unable to login when connected directly to a target port on 3PAR arrays

## Enhancements

We have separate components to update fibre channel and converged network adapters. This is a fibre channel update component.

Updated 16 Gb HBA/Mezz universal boot

Contains:

16 Gb HBA/Mezz universal boot 11.1.183.58

8 Gb standup/mezz firmware 2.03X6

8 Gb standup universal boot image 5.21x11 (2.20a7 BIOS, 4.20a15 UEFI)

8 Gb mezzanine universal boot image 6.21x1 (3.30a14 BIOS, 4.20a15 UEFI)

## **Supported Devices and Features**

- HP SN1000E 16Gb Dual Port Fibre Channel Host Bus Adapter
- HP SN1000E 16Gb Single Port Fibre Channel Host Bus Adapter
- HP 82E 8Gb Dual Port PCIe Fibre Channel Host Bus Adapter
- HP 81E 8Gb Single Port PCIe Fibre Channel Host Bus Adapter
- HP LPe1205A 8Gb Fibre Channel Host Bus Adapter for BladeSystem c-Class
- Emulex LPe1205 8Gb Fibre Channel Host Bus Adapter for c-Class BladeSystem
- HP SN1100E 16Gb Dual Port Fibre Channel Host Bus Adapter
- HP SN1100E 16Gb Single Port Fibre Channel Host Bus Adapter
- HP Fibre Channel 16Gb LPe1605 Mezz
- HP StoreFabric 84E 4-Port Fibre Channel Host Bus Adapter

---

HPE Firmware Online Flash for Emulex Fibre Channel Host Bus Adapters - Windows 2008/2012/2012 R2/2016 x64

Version: 2016.10.04 **(Recommended)**

Filename: cp031813.exe

## **Important Note!**

Release Notes:

[HPE StoreFabric Emulex Adapters Release Notes](#)

## **Prerequisites**

Please consult SPOCK for a list of supported configurations available at the following link:

<http://www.hpe.com/storage/spock/>

The HPE supplied Emulex driver must be installed prior to this firmware component being identified by HP SUM for deployment. The driver is available on the HPE.com website at <http://www.hpe.com/>:

HPE Storage Fibre Channel Adapter Kit for the x64 Emulex Storport Driver v11.1.145.16 cp029981.exe

## **Fixes**

This fix resolves an issue in which 16Gb HBAs were unable to login when connected directly to a target port on 3PAR arrays

## **Enhancements**

We have separate components to update fibre channel and converged network adapters. This is a fibre channel update component.

Updated 16 Gb HBA/Mezz universal boot

Contains:

16 Gb HBA/Mezz universal boot 11.1.183.58

8 Gb standup/mezz firmware 2.03X6

8 Gb standup universal boot image 5.21x11 (2.20a7 BIOS, 4.20a15 UEFI)

8 Gb mezzanine universal boot image 6.21x1 (3.30a14 BIOS, 4.20a15 UEFI)

## **Supported Devices and Features**

- HP SN1000E 16Gb Dual Port Fibre Channel Host Bus Adapter
- HP SN1000E 16Gb Single Port Fibre Channel Host Bus Adapter
- HP 82E 8Gb Dual Port PCIe Fibre Channel Host Bus Adapter
- HP 81E 8Gb Single Port PCIe Fibre Channel Host Bus Adapter
- HP LPe1205A 8Gb Fibre Channel Host Bus Adapter for BladeSystem c-Class
- Emulex LPe1205 8Gb Fibre Channel Host Bus Adapter for c-Class BladeSystem
- HP SN1100E 16Gb Dual Port Fibre Channel Host Bus Adapter
- HP SN1100E 16Gb Single Port Fibre Channel Host Bus Adapter
- HP Fibre Channel 16Gb LPe1605 Mezz
- HP StoreFabric 84E 4-Port Fibre Channel Host Bus Adapter
- HPE Synergy 3530C 16Gb Fibre Channel Host Bus Adapter
- HPE StoreFabric SN1100E 4P 16Gb FC HBA

---

HPE Firmware Online Flash for QLogic Fibre Channel Host Bus Adapters - Windows 2008 (x86)

Version: 2016.10.01 **(Recommended)**

Filename: cp028117.exe

## **Important Note!**

Release Notes:

[HPE StoreFabric QLogic Adapters Release Notes](#)

## **Prerequisites**

Please consult SPOCK for a list of supported configurations available at the following link:

<http://www.hpe.com/storage/spock/>

The HPE supplied QLogic driver must be installed prior to this firmware component being identified by HP SUM for deployment. Use the appropriate driver included in the Service Pack for ProLiant 2016.10.0, which is available at <http://www.hpe.com/servers/spp/download>:

- HPE Storage Fibre Channel Adapter Kit for the x86 QLogic Storport Driver v9.1.17.22, cp028132.exe
- HPE Storage Fibre Channel Over Ethernet Adapter Kit for the x86 QLogic Storport Driver v9.1.13.10, cp025686.exe

## **Enhancements**

Updated the Firmware/BIOS/UEFI packages for 8 Gb and 16 Gb products.

- 8 Gb HBA/Mezz
  - Package 3.75.07
  - Firmware 8.02.00
  - UEFI 6.45
  - BIOS 3.31
- 16 Gb HBA/Mezz
  - Package 6.01.14
  - Firmware 8.02.51
  - UEFI 6.39
  - BIOS 3.31

## **Supported Devices and Features**

This firmware supports the following HP adapters:

- HP 81Q PCIe Fibre Channel Host Bus Adapter
- HP 82Q 8Gb Dual Port PCIe Fibre Channel Host Bus Adapter
- QLogic QMH2562 8Gb Fibre Channel Host Bus Adapter for c-Class BladeSystem
- HP QMH2572 8Gb Fibre Channel Host Bus Adapter for c-Class BladeSystem
- HP QMH2672 16Gb FC HBA for c-Class BladeSystem
- HP StoreFabric SN1000Q 16GB 2-port PCIe Fibre Channel Host Bus Adapter
- HP StoreFabric SN1000Q 16GB 1-port PCIe Fibre Channel Host Bus Adapter

---

HPE Firmware Online Flash for QLogic Fibre Channel Host Bus Adapters - Windows 2008/2012 (x64)

Version: 2016.10.01 **(Recommended)**

Filename: cp029691.exe

### **Important Note!**

Release Notes:

[HPE StoreFabric QLogic Adapters Release Notes](#)

### **Prerequisites**

Please consult SPOCK for a list of supported configurations available at the following link:

<http://www.hpe.com/storage/spock/>

The HPE supplied QLogic driver must be installed prior to this firmware component being identified by HP SUM for deployment. Use the appropriate driver included in the Service Pack for ProLiant 2016.10.0, which is available at <http://www.hpe.com/servers/spp/download>:

- HPE Storage Fibre Channel Adapter Kit for the x64 QLogic Storport Driver v9.1.17.22, cp028133.exe
- HPE Storage Fibre Channel Adapter Kit for the QLogic Storport Driver for Windows Server 2012 and 2012 R2 v9.1.17.22,

cp028134.exe

- HPE Storage Fibre Channel Over Ethernet Adapter Kit for the x64 QLogic Storport Driver v9.1.13.10, cp025685.exe
- HPE Storage Fibre Channel Over Ethernet Adapter Kit for the QLogic Storport Driver for Windows Server 2012 and 2012 R2 v9.1.13.10, cp025684.exe

## **Enhancements**

Added support for the following devices:

- HPE StoreFabric 84Q 4P 8Gb Fibre Channel HBA
- HPE StoreFabric SN1100Q 16Gb 2P FC HBA
- HPE StoreFabric SN1100Q 16Gb 1P FC HBA
- HPE Synergy 3830C 16G Fibre Channel Host Bus Adapter

Updated the Firmware/BIOS/UEFI packages for 8 Gb and 16 Gb products.

- 8 Gb HBA/Mezz
  - Package 3.75.07
  - Firmware 8.02.00
  - UEFI 6.45
  - BIOS 3.31
- 16 Gb HBA/Mezz
  - Package 6.01.14
  - Firmware 8.02.51
  - UEFI 6.39
  - BIOS 3.31
- 16 Gb SN1100Q
  - Package 01.70.17
  - Firmware 8.03.05
  - UEFI 6.19
  - BIOS 3.37

## **Supported Devices and Features**

This firmware supports the following adapters:

- HP 81Q PCIe Fibre Channel Host Bus Adapter
- HP 82Q 8Gb Dual Port PCIe Fibre Channel Host Bus Adapter
- QLogic QMH2562 8Gb Fibre Channel Host Bus Adapter for c-Class BladeSystem
- HP QMH2572 8Gb Fibre Channel Host Bus Adapter for c-Class BladeSystem
- HP StoreFabric SN1000Q 16Gb Fibre Channel Host Bus Adapter
- HP QMH2672 16Gb FC HBA for c-Class BladeSystem
- HP StoreFabric SN1000Q 16GB 2-port PCIe Fibre Channel Host Bus Adapter
- HP StoreFabric SN1000Q 16GB 1-port PCIe Fibre Channel Host Bus Adapter
- HPE StoreFabric SN1100Q 16Gb 2P FC HBA
- HPE StoreFabric SN1100Q 16Gb 1P FC HBA
- HPE StoreFabric 84Q 4P 8Gb Fibre Channel HBA
- HPE Synergy 3830C 16G Fibre Channel Host Bus Adapter

---

HPE Firmware Online Flash for QLogic Fibre Channel Host Bus Adapters - Windows Server 2016

Version: 2016.10.01 **(Recommended)**

Filename: cp030690.exe

### **Important Note!**

Release Notes:

[HPE StoreFabric QLogic Adapters Release Notes](#)

### **Prerequisites**

Please consult SPOCK for a list of supported configurations available at the following link:

<http://www.hpe.com/storage/spock/>

The HPE supplied QLogic driver must be installed prior to this firmware component being identified by HP SUM for deployment. Use the appropriate driver included in the HPE Service Pack for ProLiant 2016.10.0, which is available at <http://www.hpe.com/servers/spp/download>:

- HPE Storage Fibre Channel Adapter Kit for the QLogic Storport Driver for Windows Server 2016 version 9.2.2.20, cp029979.exe

### **Enhancements**

Added support for the following devices:

- HPE StoreFabric 84Q 4P 8Gb Fibre Channel HBA
- HPE StoreFabric SN1100Q 16Gb 2P FC HBA
- HPE StoreFabric SN1100Q 16Gb 1P FC HBA
- HPE Synergy 3830C 16G Fibre Channel Host Bus Adapter

Updated the Firmware/BIOS/UEFI packages for 8 Gb and 16 Gb products.

- 8 Gb HBA/Mezz
  - Package 3.75.07
  - Firmware 8.02.00
  - UEFI 6.45
  - BIOS 3.31
- 16 Gb HBA/Mezz
  - Package 6.01.14
  - Firmware 8.02.51
  - UEFI 6.39
  - BIOS 3.31
- 16 Gb SN1100Q
  - Package 01.70.17
  - Firmware 8.03.05
  - UEFI 6.19
  - BIOS 3.37

### **Supported Devices and Features**

This firmware supports the following adapters:

- HP 81Q PCIe Fibre Channel Host Bus Adapter
- HP 82Q 8Gb Dual Port PCIe Fibre Channel Host Bus Adapter
- QLogic QMH2562 8Gb Fibre Channel Host Bus Adapter for c-Class BladeSystem
- HP QMH2572 8Gb Fibre Channel Host Bus Adapter for c-Class BladeSystem
- HP StoreFabric SN1000Q 16Gb Fibre Channel Host Bus Adapter
- HP QMH2672 16Gb FC HBA for c-Class BladeSystem
- HP StoreFabric SN1000Q 16GB 2-port PCIe Fibre Channel Host Bus Adapter
- HP StoreFabric SN1000Q 16GB 1-port PCIe Fibre Channel Host Bus Adapter
- HPE StoreFabric SN1100Q 16Gb 2P FC HBA
- HPE StoreFabric SN1100Q 16Gb 1P FC HBA
- HPE StoreFabric 84Q 4P 8Gb Fibre Channel HBA
- HPE Synergy 3830C 16G Fibre Channel Host Bus Adapter

---

## Firmware - Storage Tape

[Top](#)

HPE StoreEver Tape Firmware for Microsoft Windows

Version: 4.1.0.0 **(Optional)**

Filename: cp030021.exe

### Fixes

The following issues are resolved in firmware revisions listed below:

#### **StoreEver LTO-6 Ultrium 6250 SAS Tape Drive**

**Drive firmware version** 35BD

**Supersedes** 353D

- Reduced the occurrence of a class of write failure (0x5093) events.
- Fixed a rare case where the tape drive could report an incorrect LAST LOGICAL OBJECT POSITION to the host after a **READ POSITION** command.
- Corrected the reporting of product IDs on Inquiry Page CCh.

#### **StoreEver LTO-6 Ultrium 6650 SAS Tape Drive**

**Drive firmware version** 05DD

**Supersedes** 053D

- Reduced the occurrence of a class of write failure (0x5093) events.
- Fixed a rare case where the tape drive could report an incorrect LAST LOGICAL OBJECT POSITION to the host after a **READ POSITION** command.
- Corrected the reporting of product IDs on Inquiry Page CCh.

#### **StoreEver LTO-5 Ultrium 3000 SAS Tape Drive**

**Drive firmware version** Z6ED

**Supersedes** Z64D

- Possibility of a drive reset (assert) after an off-track event due to additional write position checks introduced in previous code release.

#### **StoreEver LTO-5 Ultrium 3280 SAS Tape Drive**

**Drive firmware version** X6ED



## **Supersedes X64D**

- Possibility of a drive reset (assert) after an off-track event due to additional write position checks introduced in previous code release.

## **Enhancements**

The enhancements below are only applicable for the following firmware revisions and devices:

### **StoreEver LTO-6 Ultrium 6250 SAS Tape Drive**

#### **Drive firmware version 35BD**

#### **Supersedes 353D**

- New error code 0x50b4 reported for a Space to EOD failure if cartridge memory (CM) indicates no valid EOD on tape.
- Improved tape alert reporting for additional types of load and read failures.
- Improved supportability by enhancing internal drive logging.
- Improved supportability by enhancing the **VERIFY** command.
  - Added Immediate mode support on primary port when VTE=1.
  - Added Verify by Filemarks (VBF) bit.
- A TapeAlert is now reported for a previously undetected CM problem.

### **StoreEver LTO-6 Ultrium 6650 SAS Tape Drive**

#### **Drive firmware version O5DD**

#### **Supersedes O53D**

- New error code 0x50b4 reported for a Space to EOD failure if cartridge memory (CM) indicates no valid EOD on tape.
- Improved tape alert reporting for additional types of load and read failures.
- Improved supportability by enhancing internal drive logging.
- Improved supportability by enhancing the **VERIFY** command.
  - Added Immediate mode support on primary port when VTE=1.
  - Added Verify by Filemarks (VBF) bit.
- A TapeAlert is now reported for a previously undetected CM problem.

### **StoreEver LTO-5 Ultrium 3000 SAS Tape Drive**

#### **Drive firmware version Z6ED**

#### **Supersedes Z64D**

- Added a cleaning request following a space failure.
- New error code 0x50b4 reported for a Space to EOD failure if CM indicates no valid EOD on tape.
- Added functionality to the **READ POSITION** command for support of Last Logical Object Position.
- Improved supportability by enhancing internal drive logging.
- Improved supportability by enhancing the **VERIFY** command.
  - Added the Verify to End (VTE), Verify Logical Block Protection Method (VLBPM), and Verify by Filemarks (VBF) bits.
  - Added Immediate mode support on primary port when VTE=1.
- Improved tape alert reporting for additional types of load and read failures.

### **StoreEver LTO-5 Ultrium 3280 SAS Tape Drive**

#### **Drive firmware version X6ED**

#### **Supersedes X64D**

- Added a cleaning request following a space failure.
- New error code 0x50b4 reported for a Space to EOD failure if CM indicates no valid EOD on tape.
- Added functionality to the **READ POSITION** command for support of Last Logical Object Position.

- Improved supportability by enhancing internal drive logging.
- Improved supportability by enhancing the **VERIFY** command.
  - Added the Verify to End (VTE), Verify Logical Block Protection Method (VLBPM), and Verify by Filemarks (VBF) bits.
  - Added Immediate mode support on primary port when VTE=1.
- Improved tape alert reporting for additional types of load and read failures.

## **Supported Devices and Features**

Supported tape drives and firmware revisions included in this package

<b>Tape Drive</b>	<b>Firmware Revision</b>
HP DAT 72 USB	ZUD4
HP DAT160 USB	WU8B
HP DAT160 SAS	WSB8
HP DAT320 USB	VUA8
HP DAT320 SAS	VSA6
HP Ultrium 232 SCSI	P61D
HP Ultrium 448 SCSI	S65D
HP Ultrium 448 SAS	T65D
HP Ultrium 460 SCSI	F63D
HP Ultrium 920 SCSI	D26D
HP Ultrium 920 SAS	C26D
HP Ultrium 920 SAS	Q51D
HP Ultrium 960 SCSI	G66D
HP Ultrium 1760 SAS	U64D
HP Ultrium 1760 SCSI	W62D
HP Ultrium 1840 SAS	A63D
HP Ultrium 1840 SCSI	B63D
HP Ultrium 3000 SAS	Z6ED
HP Ultrium 3280 SAS	X6ED
HP Ultrium 6250 SAS	35BD
HP Ultrium 6650 SAS	O5DD

---

### **Software - Lights-Out Management**

[Top](#)

Headless Server Registry Update for Windows Server 2008 to Server 2012 R2

Version: 1.0.0.0 (I) **(Optional)**

Filename: cp029425.exe

### **Enhancements**

- The component executable is now digitally signed with both SHA-1 and SHA-256 signatures.
- Updated component installer to only support Windows Server 2008 to Server 2012 R2.

---

HP Lights-Out Online Configuration Utility for Linux (AMD64/EM64T)

Version: 4.6.0-0 **(Optional)**

Filename: hponcfg-4.6.0-0.x86\_64.rpm

### **Prerequisites**

This utility requires the following minimum firmware revisions:

- Integrated Lights-Out 2 firmware v1.00 or later
- Integrated Lights-Out 3 firmware v1.00 or later
- Integrated Lights-Out 4 firmware v1.00 or later

The management interface driver and management agents must be installed on the server.

### **Fixes**

HPONCFG displays an appropriate error message with -w option when LOCK\_CONFIGURATION is enabled.

---

HP Lights-Out Online Configuration Utility for Linux (AMD64/EM64T)

Version: 5.1.0-0 **(Recommended)**

Filename: hponcfg-5.1.0-0.x86\_64.compsig; hponcfg-5.1.0-0.x86\_64.rpm

### **Prerequisites**

This utility requires the following minimum firmware revisions:

- Integrated Lights-Out 3 firmware v1.00 or later
- Integrated Lights-Out 4 firmware v1.00 or later
- Integrated Lights-Out 5 firmware v1.10 or later

The management interface driver and management agents must be installed on the server.

For iLO 5, openssl v1.0.x or later is required in addition to above packages.

Customers who manually compile and install openssl or intentionally relocate /usr/bin/openssl, need to set PATH environment variable to direct HPONCFG to the right/intended openssl.

### **Enhancements**

Introduced support for iLO 5 v1.15.

---

HP Lights-Out Online Configuration Utility for Linux (x86/AMD32)

Version: 4.6.0 **(Optional)**

Filename: hponcfg-4.6.0-0.i386.rpm

### **Prerequisites**

This utility requires the following minimum firmware revisions:

- Integrated Lights-Out 2 firmware v1.00 or later
- Integrated Lights-Out 3 firmware v1.00 or later
- Integrated Lights-Out 4 firmware v1.00 or later

The management interface driver and management agents must be installed on the server.

### **Fixes**

HPONCFG displays an appropriate error message with -w option when LOCK\_CONFIGURATION is enabled.

---

HP Lights-Out Online Configuration Utility for Windows Server 2008

Version: 4.8.0.0 **(Recommended)**

Filename: cp028861.exe

### **Prerequisites**

This utility requires the following minimum firmware revisions:

- Integrated Lights-Out 2 firmware v1.00 or later
- Integrated Lights-Out 3 firmware v1.00 or later
- Integrated Lights-Out 4 firmware v1.00 or later

The management interface driver must be installed on the server.

Microsoft .Net Framework 2.0 or later is required to launch HPONCFG GUI.

### **Fixes**

- HPONCFG command line interface when used with option 's' displays an error message when substituting values for same key multiple times.
- HPONCFG allows iLO firmware update only with file extension ".bin".
- HPONCFG GUI displays valid range for VLAN ID when wrong value is set.
- Added length validation for Kerberos realm in HPONCFG GUI.
- Network settings which are not applicable for Blade Servers are now grayed out in HPONCFG GUI.

---

HP Lights-Out Online Configuration Utility for Windows x64 Editions

Version: 5.1.0.0 **(Recommended)**

Filename: cp032766.compsig; cp032766.exe

### **Important Note!**

HPONCFG for Windows Server supports iLO in PRODUCTION/HIGH/FIPS security state only.

### **Prerequisites**

This utility requires the following minimum firmware revisions:

- Integrated Lights-Out 3 firmware v1.00 or later
- Integrated Lights-Out 4 firmware v1.00 or later
- Integrated Lights-Out 5 firmware v1.10 or later

The management interface driver must be installed on the server.

Microsoft .Net Framework 2.0 or later is required to launch HPONCFG GUI.

### **Enhancements**

- Higher security states support enabled in HPONCFG when iLO is set to HIGH/FIPS Security States.
- Use /u and /p command line arguments when iLO is in HIGH/FIPS Security States.
- HPONCFG is now signed by Hewlett Packard Enterprise.

Note: Command line user name and password override those which are in the script file.

---

PFA Server Registry Update for Windows Server 2008 R2 to Server 2012 R2

Version: 1.0.0.0 (G) **(Optional)**

Filename: cp029408.exe

### **Enhancements**

Updated component installer to only support Windows Server 2008 R2 to Server 2012 R2.

---

## **Software - Network**

[Top](#)

Broadcom Active Health System Agent for HPE ProLiant Network Adapters for Linux i586

Version: 1.0.20-1 **(Optional)**

Filename: hp-tg3sd-1.0.20-1.i586.rpm; hp-tg3sd-1.0.20-1.i586.txt

### **Fixes**

This product addresses an issue where the tg3sd daemon must be started after rpm installation.

### **Supported Devices and Features**

This software supports the following Broadcom network adapters:

- HP Ethernet 1Gb 2-port 330i Adapter (18D2)
- HP Ethernet 1Gb 4-port 331i Adapter (3372)
- HP Ethernet 1Gb 4-port 331T Adapter
- HP Ethernet 1Gb 4-port 331FLR Adapter
- HP Ethernet 1Gb 2-port 332i Adapter (2133)
- HP Ethernet 1Gb 2-port 332T Adapter

---

Broadcom Active Health System Agent for HPE ProLiant Network Adapters for Linux x86\_64

Version: 1.0.20-1 **(Optional)**

Filename: hp-tg3sd-1.0.20-1.x86\_64.rpm; hp-tg3sd-1.0.20-1.x86\_64.txt

### **Fixes**

This product addresses an issue where the tg3sd daemon must be started after rpm installation.

### **Supported Devices and Features**

This software supports the following Broadcom network adapters:

- HP Ethernet 1Gb 2-port 330i Adapter (182D)
- HP Ethernet 1Gb 2-port 330i Adapter (22BD)
- HP Ethernet 1Gb 4-port 331i Adapter (3372)
- HP Ethernet 1Gb 4-port 331i Adapter (22BE)

- HP Ethernet 1Gb 4-port 331FLR Adapter
- HP Ethernet 1Gb 4-port 331T Adapter
- HP Ethernet 1Gb 2-port 332i Adapter (2133)
- HP Ethernet 1Gb 2-port 332i Adapter (22E8)
- HP Ethernet 1Gb 2-port 332T Adapter

---

HPE Intel esx-provider for VMware

Version: 2016.10.07 **(Optional)**

Filename: cp029084.zip

### **Fixes**

This product resolves an issue where an excessive number of error messages is logged.

### **Supported Devices and Features**

These drivers support the following network adapters:

- HP Ethernet 1Gb 2-port 361i Adapter
- HP Ethernet 1Gb 2-port 361FLB Adapter
- HP Ethernet 1Gb 2-port 361T Adapter
- HP Ethernet 1Gb 4-port 366FLR Adapter
- HP Ethernet 1Gb 4-port 366i Adapter
- HP Ethernet 1Gb 4-port 366M Adapter
- HP Ethernet 1Gb 4-port 366T Adapter
- HP Ethernet 10Gb 2-port 560FLB Adapter
- HP Ethernet 10Gb 2-port 560FLR-SFP+ Adapter
- HP Ethernet 10Gb 2-port 560M Adapter
- HP Ethernet 10Gb 2-port 560SFP+ Adapter
- HP Ethernet 10Gb 2-port 561FLR-T Adapter
- HP Ethernet 10Gb 2-port 561T Adapter
- HP Ethernet 10Gb 2-port 562FLR-SFP+ Adapter
- HP Ethernet 10Gb 2-port 562SFP+ Adapter

---

Intel Active Health System Agent for HPE ProLiant Network Adapters for Linux i586

Version: 1.1.80.0-1 **(Optional)**

Filename: hp-ocsbbd-1.1.80.0-1.i586.rpm; hp-ocsbbd-1.1.80.0-1.i586.txt

### **Fixes**

This product addresses an issue where the ocsbbd daemon must be started after rpm installation.

This product addresses an issue where there is a discrepancy in the display of the NIC firmware version and serial number on the Active Health System (AHS) Dashboard.

### **Supported Devices and Features**

This software supports the following Intel network adapters:

- HP Ethernet 1Gb 2-port 361i Adapter
- HP Ethernet 1Gb 2-port 361FLB Adapter

- HP Ethernet 1Gb 2-port 361T Adapter
- HP Ethernet 1Gb 2-port 363i Adapter
- HP Ethernet 1Gb 2-port 364i Adapter
- HP Ethernet 1Gb 4-port 366FLR Adapter
- HP Ethernet 1Gb 4-port 366i Adapter
- HP Ethernet 1Gb 4-port 366M Adapter
- HP Ethernet 1Gb 2-port 367i Adapter
- HP Ethernet 10Gb 2-port 560FLB Adapter
- HP Ethernet 10Gb 2-port 560FLR-SFP+ Adapter
- HP Ethernet 10Gb 2-port 560M Adapter
- HP Ethernet 10Gb 2-port 560SFP+ Adapter
- HP Ethernet 10Gb 2-port 561FLR-T Adapter
- HP Ethernet 10Gb 2-port 561T Adapter
- HP Ethernet 10Gb 2-port 562i Adapter

---

Intel Active Health System Agent for HPE ProLiant Network Adapters for Linux x86\_64

Version: 1.1.80.0-1 **(Optional)**

Filename: hp-ocsbbd-1.1.80.0-1.x86\_64.rpm; hp-ocsbbd-1.1.80.0-1.x86\_64.txt

### **Fixes**

This product addresses an issue where the ocsbbd daemon must be started after rpm installation.

This product addresses an issue where there is a discrepancy in the display of the NIC firmware version and serial number on the Active Health System (AHS) Dashboard.

### **Supported Devices and Features**

This software supports the following Intel network adapters:

- HP Ethernet 1Gb 2-port 361i Adapter
- HP Ethernet 1Gb 2-port 361FLB Adapter
- HP Ethernet 1Gb 2-port 361T Adapter
- HP Ethernet 1Gb 2-port 363i Adapter
- HP Ethernet 1Gb 2-port 364i Adapter
- HP Ethernet 1Gb 4-port 366FLR Adapter
- HP Ethernet 1Gb 4-port 366i Adapter
- HP Ethernet 1Gb 4-port 366M Adapter
- HP Ethernet 1Gb 2-port 367i Adapter
- HP Ethernet 10Gb 2-port 560FLB Adapter
- HP Ethernet 10Gb 2-port 560FLR-SFP+ Adapter
- HP Ethernet 10Gb 2-port 560M Adapter
- HP Ethernet 10Gb 2-port 560SFP+ Adapter
- HP Ethernet 10Gb 2-port 561FLR-T Adapter
- HP Ethernet 10Gb 2-port 561T Adapter
- HP Ethernet 10Gb 2-port 562i Adapter

---

### **Software - Storage Controller**

HP ProLiant Smart Array SAS/SATA Event Notification Service for for 64-bit Windows Server Editions

Version: 6.46.0.64 (A) **(Optional)**

[Top](#)

Filename: cp030137.exe

### **Enhancements**

Added support for Microsoft Windows Server 2016

---

HP ProLiant Smart Array SAS/SATA Event Notification Service for Windows Server 2008 (x86) 32-bit

Version: 6.36.0.32 **(Optional)**

Filename: cp0211155.exe

### **Fixes**

Fixed issue in which "last lockup code" was not being reported in proper hex format.

### **Enhancements**

- Added support for new PHY disabled event.
  - Added support for new PHY threshold exceeded events.
- 

## **Software - Storage Fibre Channel**

[Top](#)

Emulex Fibre Channel driver component for VMware vSphere 5.5

Version: 2016.10.02 (B) **(Recommended)**

Filename: cp031675.zip

### **Important Note!**

This component is intended to be used by HP applications. It is a zip that contains the same driver deliverable available from the vmware.com and the HP vibsdepot.hp.com webpages, plus an HP specific CPXXXX.xml file.

### **Fixes**

This driver version, 11.1.183.43, resolves an unexpected behavior where I/O operations appear unresponsive when T10 DIF is enabled on the host.

### **Enhancements**

This driver, version 11.1.183.43, adds support for the following devices:

- HPE StoreFabric SN1200E 16Gb 2P FC HBA
- HPE StoreFabric SN1200E 16Gb 1P FC HBA

### **Supported Devices and Features**

- HP NC553i 10Gb 2-port FlexFabric Converged Network Adapter
- HP SN1000E 16Gb Dual Port Fibre Channel Host Bus Adapter
- HP SN1000E 16Gb Single Port Fibre Channel Host Bus Adapter
- HP 82E 8Gb Dual Port PCIe Fibre Channel Host Bus Adapter
- HP 81E 8Gb Single Port PCIe Fibre Channel Host Bus Adapter



- HP CN1100E Dual Port Converged Network Adapter
- HP FlexFabric 10Gb 2-port 554M Adapter
- HP FlexFabric 10Gb 2-port 554FLR-SFP+ Adapter
- HP FlexFabric 10Gb 2-port 554FLB Adapter
- HP LPe1205A 8Gb Fibre Channel Host Bus Adapter for BladeSystem c-Class
- Emulex LPe1205 8Gb Fibre Channel Host Bus Adapter for c-Class BladeSystem
- HP SN1100E 16Gb Dual Port Fibre Channel Host Bus Adapter
- HP SN1100E 16Gb Single Port Fibre Channel Host Bus Adapter
- HP Fibre Channel 16Gb LPe1605 Mezz
- HP StoreFabric CN1200E Dual Port Converged Network Adapter
- HP FlexFabric 20Gb 2-port 650FLB Adapter
- HP FlexFabric 20Gb 2-port 650M Adapter
- HP FlexFabric 10Gb 2-port 556FLR-SFP+ Adapter
- HPE FlexFabric 10Gb 2-port 556FLR-T Adapter
- HPE StoreFabric CN1200E-T 10GBASE-T Converged Network Adapter
- HP StoreFabric 84E 4-port Fibre Channel Host Bus Adapter
- HPE Synergy 3530C 16Gb Fibre Channel Host Bus Adapter
- HPE StoreFabric SN1100E 4P 16Gb FC HBA
- HPE StoreFabric SN1200E 16Gb 2P FC HBA
- HPE StoreFabric SN1200E 16Gb 1P FC HBA

---

Emulex Fibre Channel driver component for VMware vSphere 6.0

Version: 2016.10.02 (B) **(Recommended)**

Filename: cp031676.zip

### **Important Note!**

This component is intended to be used by HP applications. It is a zip that contains the same driver deliverable available from the vmware.com and the HP vibsdepot.hp.com webpages, plus an HP specific CPXXXX.xml file.

### **Fixes**

This driver version, 11.1.183.43, resolves an unexpected behavior where I/O operations appear unresponsive when T10 DIF is enabled on the host.

### **Enhancements**

This driver, version 11.1.183.43, adds support for the following devices:

- HPE StoreFabric SN1200E 16Gb 2P FC HBA
- HPE StoreFabric SN1200E 16Gb 1P FC HBA
- HPE StoreFabric SN1600E 32Gb 2p FC HBA
- HPE StoreFabric SN1600E 32Gb 1p FC HBA

### **Supported Devices and Features**

- HP NC553i 10Gb 2-port FlexFabric Converged Network Adapter
- HP SN1000E 16Gb Dual Port Fibre Channel Host Bus Adapter
- HP SN1000E 16Gb Single Port Fibre Channel Host Bus Adapter
- HP 82E 8Gb Dual Port PCIe Fibre Channel Host Bus Adapter
- HP 81E 8Gb Single Port PCIe Fibre Channel Host Bus Adapter

- HP CN1100E Dual Port Converged Network Adapter
- HP FlexFabric 10Gb 2-port 554M Adapter
- HP FlexFabric 10Gb 2-port 554FLR-SFP+ Adapter
- HP FlexFabric 10Gb 2-port 554FLB Adapter
- HP LPe1205A 8Gb Fibre Channel Host Bus Adapter for BladeSystem c-Class
- Emulex LPe1205 8Gb Fibre Channel Host Bus Adapter for c-Class BladeSystem
- HP SN1100E 16Gb Dual Port Fibre Channel Host Bus Adapter
- HP SN1100E 16Gb Single Port Fibre Channel Host Bus Adapter
- HP Fibre Channel 16Gb LPe1605 Mezz
- HP StoreFabric CN1200E Dual Port Converged Network Adapter
- HP FlexFabric 20Gb 2-port 650FLB Adapter
- HP FlexFabric 20Gb 2-port 650M Adapter
- HP FlexFabric 10Gb 2-port 556FLR-SFP+ Adapter
- HPE FlexFabric 10Gb 2-port 556FLR-T Adapter
- HPE StoreFabric CN1200E-T 10GBASE-T Converged Network Adapter
- HP StoreFabric 84E 4-port Fibre Channel Host Bus Adapter
- HPE Synergy 3530C 16Gb Fibre Channel Host Bus Adapter
- HPE StoreFabric SN1100E 4P 16Gb FC HBA
- HPE StoreFabric SN1200E 16Gb 2P FC HBA
- HPE StoreFabric SN1200E 16Gb 1P FC HBA
- HPE StoreFabric SN1600E 32Gb 2p FC HBA
- HPE StoreFabric SN1600E 32Gb 1p FC HBA

---

QLogic BR-series Fibre Channel driver component for VMware vSphere 5.5/6.0

Version: 2016.06.01 **(Recommended)**

Filename: cp028780.zip

### **Important Note!**

This component is intended to be used by HP applications. It is a zip that contains the same driver deliverable available from the vmware.com and the HP vibsdepot.hp.com webpages, plus an HP specific CPXXXX.xml file.

To keep drivers and boot code synchronized, be sure to update your adapter with the latest boot image from [www.hpe.com](http://www.hpe.com) before you install or update adapter driver packages.

### **Fixes**

This driver version corrects a system instability issue seen on VMware vSphere 6.0.

### **Enhancements**

Updated driver version to 3.2.6.0.

This driver will identify 8Gb HBA cards as "QLogic" or "QLogic BR-series" in product description displays.

### **Supported Devices and Features**

This driver component supports the following HPE adapters:

- HP 81B PCIe 8Gb Fibre Channel Single Port Host Bus Adapter
- HP 82B PCIe 8Gb Fibre Channel Dual Port Host Bus Adapter

---

QLogic Fibre Channel driver component for VMware vSphere 5.5

Version: 2016.12.01 **(Recommended)**

Filename: cp031259.zip

### **Important Note!**

This component is intended to be used by HPE applications. It is a zip that contains the same driver deliverable available from the vmware.com and the HPE vibsdepot.hp.com webpages, plus an HPE specific CPXXXX.xml file.

### **Prerequisites**

Please consult SPOCK for a list of supported configurations available at the following link:

<http://www.hpe.com/storage/spock/>

### **Fixes**

Fix for an unexpected behavior in the Hewlett Packard Enterprise QLogic 16Gb Fibre Channel HBA firmware which causes a small amount of resources within the HBA to remain unavailable for use following Read Diagnostic Parameter (RDP) exchanges. Over time this can result in an unresponsive system.

### **Enhancements**

Updated driver component for VMware vSphere 5.5 with version 1.1.77.0

### **Supported Devices and Features**

- HP FC1142SR 4Gb PCIe Host Bus Adapter
- HP FC1242SR 4Gb PCIe DC Host Bus Adapter
- HP 81Q PCIe Fibre Channel Host Bus Adapter
- HP 82Q 8Gb Dual Port PCIe Fibre Channel Host Bus Adapter
- QLogic QMH2562 8Gb Fibre Channel Host Bus Adapter for c-Class BladeSystem
- QLogic QMH2462 4Gb Fibre Channel Host Bus Adapter for c-Class BladeSystem
- HP QMH2572 8Gb Fibre Channel Host Bus Adapter for c-Class BladeSystem
- HP StoreFabric SN1000Q 16Gb Fibre Channel Host Bus Adapter
- HP QMH2672 16Gb FC HBA for c-Class BladeSystem
- HP CN1000Q Dual Port Converged Network Adapter
- HP FlexFabric 10Gb 2-port 526FLR-SFP+ Adapter
- HPE Synergy 3830C 16G Fibre Channel Host Bus Adapter
- HPE StoreFabric SN1100Q 16Gb 2P FC HBA
- HPE StoreFabric SN1100Q 16Gb 1P FC HBA
- HPE StoreFabric 84Q 4P 8Gb Fibre Channel HBA

---

QLogic Fibre Channel driver component for VMware vSphere 6.0

Version: 2016.10.01 **(Recommended)**

Filename: cp028144.zip

## **Important Note!**

This component is intended to be used by HPE applications. It is a zip that contains the same driver deliverable available from the vmware.com and the HPE vibsdepot.hp.com webpages, plus an HPE specific CPXXXX.xml file.

## **Fixes**

This driver version resolves the following:

- Corrected multiple PSODs
- Corrected instance where the system terminates unexpectedly while running scsi passthru traffic
- Corrected instances where certain port states were not being displayed properly in a user-space application

## **Enhancements**

Updated the driver component for VMware vSphere 6.0 with driver version 2.1.50.0.

Added support for the following devices:

- HPE StoreFabric SN1100Q 16GB 2-port PCIe Fibre Channel Host Bus Adapter
- HPE StoreFabric SN1100Q 16GB 1-port PCIe Fibre Channel Host Bus Adapter
- HPE StoreFabric 84Q 4P 8Gb Fibre Channel HBA
- HPE Synergy 3830C 16G Fibre Channel Host Bus Adapter

## **Supported Devices and Features**

- HP 81Q PCIe Fibre Channel Host Bus Adapter
- HP 82Q 8Gb Dual Port PCIe Fibre Channel Host Bus Adapter
- QLogic QMH2562 8Gb Fibre Channel Host Bus Adapter for c-Class BladeSystem
- HP QMH2572 8Gb Fibre Channel Host Bus Adapter for c-Class BladeSystem
- HP StoreFabric SN1000Q 16Gb Fibre Channel Host Bus Adapter
- HP QMH2672 16Gb FC HBA for c-Class BladeSystem
- HP CN1000Q Dual Port Converged Network Adapter
- HP FlexFabric 10Gb 2-port 526FLR-SFP+ Adapter
- HP StoreFabric SN1000Q 16GB 2-port PCIe Fibre Channel Host Bus Adapter
- HP StoreFabric SN1000Q 16GB 1-port PCIe Fibre Channel Host Bus Adapter
- HP Synergy 3830C 16G Fibre Channel Host Bus Adapter
- HPE StoreFabric SN1100Q 16Gb 2P FC HBA
- HPE StoreFabric SN1100Q 16Gb 1P FC HBA
- HPE StoreFabric 84Q 4P 8Gb Fibre Channel HBA

---

## **Software - Storage Fibre Channel HBA**

Fibreutils for HPE Storage Fibre Channel Host Bus Adapters for Linux (x86)

Version: 3.3-1 **(Optional)**

Filename: fibreutils-3.3-1.i386.rpm

[Top](#)

### **Prerequisites**

- Requires the following packages to be installed: glibc libgcc libstdc++ bash perl

### **Enhancements**

General update.

---

Fibreutils for HPE Storage Fibre Channel Host Bus Adapters for Linux (x86\_64)

Version: 3.3-1 (B) **(Optional)**

Filename: fibreutils-3.3-1.x86\_64.rpm

### **Prerequisites**

- Requires the following packages to be installed: glibc libgcc libstdc++ bash perl

### **Enhancements**

General update.

---

Fibreutils for HPE Storage Fibre Channel Host Bus Adapters for Linux (x86\_64)

Version: 3.3-3 **(Optional)**

Filename: fibreutils-3.3-3.x86\_64.rpm

### **Prerequisites**

- Requires the following packages to be installed: glibc libgcc libstdc++ bash perl

### **Enhancements**

General update.

---

HP Fibre Channel Enablement Kit for Linux - QLogic BR-Series

Version: 5.0.0.0 (D) **(Recommended)**

Filename: HP-FC-Brocade-Enablement-Kit-5.0.0.0-3.x86\_64.rpm

### **Important Note!**

Release Notes:

[HP StorageWorks Brocade Fibre Channel Host Bus Adapters Release Notes](#)

### **Enhancements**

Added support for Red Hat Enterprise Linux 7 operating system

## **Supported Devices and Features**

- HP 81B PCIe 8Gb Fibre Channel Single Port Host Bus Adapter
- HP 82B PCIe 8Gb Fibre Channel Dual Port Host Bus Adapter
- Brocade 804 8Gb Fibre Channel HBA for c-Class BladeSystem

---

HPE Emulex Smart SAN Enablement Kit for Linux

Version: 1.0.0.0-2 **(Optional)**

Filename: hpe-emulex-smartsan-enablement-kit-1.0.0.0-2.noarch.rpm

## **Important Note!**

To obtain the 3PAR Smart SAN User Guide to go the Storage Information Library at the following link:

[Storage Information Library](#)

(<http://www.hpe.com/info/storage/docs/>)

By default, **HP 3PAR Storage** is selected under

## **Products and Solutions**

## **Prerequisites**

Please consult SPOCK for a list of supported configurations available at the following link:

<http://www.hpe.com/storage/spock/>

The HPE supplied fibre channel driver must be installed prior to this enablement kit component if you want to enable Smart SAN functionality. Use the appropriate driver included in the HP Service Pack for ProLiant 2016.04.0, which is available at [www.hpe.com/servers/spp/download](http://www.hpe.com/servers/spp/download).

However, if a Smart SAN enabled driver is not installed at execution time, the component will land the enablement kit files for future use after the driver has been installed.

## **Enhancements**

Added support for the HPE StoreFabric 84E 4-Port Fibre Channel Host Bus Adapter

## **Supported Devices and Features**

- HP 82E 8Gb Dual Port PCIe Fibre Channel Host Bus Adapter
- HP 81E 8Gb Single Port PCIe Fibre Channel Host Bus Adapter
- HP SN1000E 16Gb Dual Port Fibre Channel Host Bus Adapter
- HP SN1000E 16Gb Single Port Fibre Channel Host Bus Adapter
- HP SN1100E 16Gb Dual Port Fibre Channel Host Bus Adapter
- HP SN1100E 16Gb Single Port Fibre Channel Host Bus Adapter
- HP Fibre Channel 16Gb LPe1605 Mezz Adapter
- HPE StoreFabric SN1100E 4P 16Gb Fibre Channel Host Bus Adapter

HPE Emulex Smart SAN Enablement Kit for Windows 64 bit operating systems

Version: 1.0.0.1 (c) **(Optional)**

Filename: cp030472.exe

### **Important Note!**

The Smart SAN enablement kit will not execute when an operating system has only the inbox fibre channel driver installed. An out of box (OOB) fibre channel driver is needed to utilize Smart SAN functionality. If any OOB driver is installed, the enablement kit will pre-enable/disable Smart SAN functionality for future use. It can then be activated once a Smart SAN enabled OOB driver is installed (see Prerequisite Notes) and after a reboot has occurred.

To obtain the 3PAR Smart SAN User Guide to go the Storage Information Library at the following link:

[Storage Information Library](#)

(<http://www.hpe.com/info/storage/docs/>)

By default, **HP 3PAR Storage** is selected under

### **Products and Solutions.**

### **Prerequisites**

Please consult SPOCK for a list of supported configurations available at the following link:

<http://www.hpe.com/storage/spock/>

The HPE supplied fibre channel driver must be installed prior to this enablement kit component if you want to enable Smart SAN functionality. Use the appropriate driver included in the HP Service Pack for ProLiant 2016.04.0, which is available at [www.hpe.com/servers/spp/download](http://www.hpe.com/servers/spp/download).

However, if a Smart SAN enabled driver is not installed at execution time, the component will land the enablement kit files for future use after the driver has been installed.

### **Enhancements**

Added support for the HPE StoreFabric 84E 4-Port Fibre Channel Host Bus Adapter

Added support for Microsoft Windows Server 2016 operating system

### **Supported Devices and Features**

- HP 82E 8Gb Dual Port PCIe Fibre Channel Host Bus Adapter
- HP 81E 8Gb Single Port PCIe Fibre Channel Host Bus Adapter
- HP SN1000E 16Gb Dual Port Fibre Channel Host Bus Adapter
- HP SN1000E 16Gb Single Port Fibre Channel Host Bus Adapter
- HP SN1100E 16Gb Dual Port Fibre Channel Host Bus Adapter
- HP SN1100E 16Gb Single Port Fibre Channel Host Bus Adapter
- HP Fibre Channel 16Gb LPe1605 Mezz Adapter
- HPE StoreFabric SN1100E 4P 16Gb Fibre Channel Host Bus Adapter
- HPE StoreFabric 84E 4-Port Fibre Channel Host Bus Adapter

---

HPE Fibre Channel Enablement Kit for Linux - QLogic

Version: 6.0.0.0-2 **(Recommended)**

Filename: HP-CNA-FC-hpqlgc-Enablement-Kit-6.0.0.0-2.noarch.rpm

### **Important Note!**

Release Notes:

[HPE StoreFabric QLogic Adapters Release Notes](#)

### **Enhancements**

Updated the kit to version 6.0.0.0-2

Added support for the following devices:

- HPE StoreFabric SN1100Q 16GB 2-port PCIe Fibre Channel Host Bus Adapter
- HPE StoreFabric SN1100Q 16GB 1-port PCIe Fibre Channel Host Bus Adapter
- HPE StoreFabric 84Q 4P 8Gb Fibre Channel HBA
- HPE Synergy 3830C 16G Fibre Channel Host Bus Adapter

### **Supported Devices and Features**

This version of Enablement kit supports following Devices:

- HP FC1142SR 4Gb PCIe Host Bus Adapter
- HP FC1242SR 4Gb PCIe DC Host Bus Adapter
- HP 81Q PCIe Fibre Channel Host Bus Adapter
- HP 82Q 8Gb Dual Port PCIe Fibre Channel Host Bus Adapter
- QLogic QMH2562 8Gb Fibre Channel Host Bus Adapter for c-Class BladeSystem
- QLogic QMH2462 4Gb Fibre Channel Host Bus Adapter for c-Class BladeSystem
- HP QMH2572 8Gb Fibre Channel Host Bus Adapter for c-Class BladeSystem
- HP StoreFabric SN1000Q 16Gb PCIe Fibre Channel Host Bus Adapter
- HP QMH2672 16Gb FC HBA for c-Class BladeSystem
- HP FlexFabric 10Gb 2-port 526FLR-SFP+ Adapter
- HP CN1000Q Dual Port Converged Network Adapter
- HP StoreFabric SN1000Q 16GB 2-port PCIe Fibre Channel Host Bus Adapter
- HP StoreFabric SN1000Q 16GB 1-port PCIe Fibre Channel Host Bus Adapter
- HPE Synergy 3830C 16G Fibre Channel Host Bus Adapter
- HPE StoreFabric 84Q 4P 8Gb Fibre Channel HBA
- HPE StoreFabric SN1100Q 16Gb 2P FC HBA
- HPE StoreFabric SN1100Q 16Gb 1P FC HBA

---

HPE Fibre Channel Enablement Kit for Red Hat Enterprise Linux 6 Server - Emulex

Version: 11.1.183.22 **(Recommended)**

Filename: HP-CNA-FC-Emulex-Enablement-Kit-11.1.183.22-1.rhel6.x86\_64.rpm

### **Important Note!**

Release Notes:

[HPE StoreFabric Emulex Adapters Release Notes](#)



## **Prerequisites**

The target environment must have the libHBAAPI Package installed prior to the installation of the enablement kit. (If not already present, the libHBAAPI Package can be obtained from the operating system installation media.)

## **Enhancements**

This kit, version 11.1.183.22, adds support for the following devices:

- HPE StoreFabric SN1200E 16Gb 2P FC HBA
- HPE StoreFabric SN1200E 16Gb 1P FC HBA
- HPE StoreFabric SN1600E 32Gb 2p FC HBA
- HPE StoreFabric SN1600E 32Gb 1p FC HBA

## **Supported Devices and Features**

- HP NC553i 10Gb 2-port FlexFabric Converged Network Adapter
- HP SN1000E 16Gb Dual Port Fibre Channel Host Bus Adapter
- HP SN1000E 16Gb Single Port Fibre Channel Host Bus Adapter
- HP 82E 8Gb Dual Port PCIe Fibre Channel Host Bus Adapter
- HP 81E 8Gb Single Port PCIe Fibre Channel Host Bus Adapter
- HP CN1100E Dual Port Converged Network Adapter
- HP FlexFabric 10Gb 2-port 554M Adapter
- HP FlexFabric 10Gb 2-port 554FLR-SFP+ Adapter
- HP FlexFabric 10Gb 2-port 554FLB Adapter
- HP LPe1205A 8Gb Fibre Channel Host Bus Adapter for BladeSystem c-Class
- Emulex LPe1205 8Gb Fibre Channel Host Bus Adapter for c-Class BladeSystem
- HP SN1100E 16Gb Dual Port Fibre Channel Host Bus Adapter
- HP SN1100E 16Gb Single Port Fibre Channel Host Bus Adapter
- HP LPe1605 16Gb Fibre Channel Host Bus Adapter for BladeSystem c-Class
- HP FlexFabric 20Gb 2-port 650FLB Adapter
- HP FlexFabric 20Gb 2-port 650M Adapter
- HP FlexFabric 10Gb 2-port 556FLR-SFP+ Adapter
- HP StoreFabric CN1200E Dual Port Converged Network Adapter
- HPE FlexFabric 10Gb 2-port 556FLR-T Adapter
- HPE StoreFabric CN1200E-T 10GBASE-T Converged Network Adapter
- HP StoreFabric 84E 4-Port Fibre Channel Host Bus Adapter
- HPE Synergy 3530C 16Gb Fibre Channel Host Bus Adapter
- HPE StoreFabric SN1100E 4P 16Gb FC HBA
- HPE StoreFabric SN1200E 16Gb 2P FC HBA
- HPE StoreFabric SN1200E 16Gb 1P FC HBA
- HPE StoreFabric SN1600E 32Gb 2p FC HBA
- HPE StoreFabric SN1600E 32Gb 1p FC HBA

---

HPE Fibre Channel Enablement Kit for Red Hat Enterprise Linux 7 Server - Emulex

Version: 11.1.183.22 **(Recommended)**

Filename: HP-CNA-FC-Emulex-Enablement-Kit-11.1.183.22-1.rhel7.x86\_64.rpm

## **Important Note!**

Release Notes:

## **Prerequisites**

The target environment must have the libHBAAPI Package installed prior to the installation of the enablement kit. (If not already present, the libHBAAPI Package can be obtained from the operating system installation media.)

## **Enhancements**

This kit, version 11.1.183.22, adds support for the following devices:

- HPE StoreFabric SN1200E 16Gb 2P FC HBA
- HPE StoreFabric SN1200E 16Gb 1P FC HBA
- HPE StoreFabric SN1600E 32Gb 2p FC HBA
- HPE StoreFabric SN1600E 32Gb 1p FC HBA

## **Supported Devices and Features**

- HP NC553i 10Gb 2-port FlexFabric Converged Network Adapter
- HP SN1000E 16Gb Dual Port Fibre Channel Host Bus Adapter
- HP SN1000E 16Gb Single Port Fibre Channel Host Bus Adapter
- HP 82E 8Gb Dual Port PCIe Fibre Channel Host Bus Adapter
- HP 81E 8Gb Single Port PCIe Fibre Channel Host Bus Adapter
- HP CN1100E Dual Port Converged Network Adapter
- HP FlexFabric 10Gb 2-port 554M Adapter
- HP FlexFabric 10Gb 2-port 554FLR-SFP+ Adapter
- HP FlexFabric 10Gb 2-port 554FLB Adapter
- HP LPe1205A 8Gb Fibre Channel Host Bus Adapter for BladeSystem c-Class
- Emulex LPe1205 8Gb Fibre Channel Host Bus Adapter for c-Class BladeSystem
- HP SN1100E 16Gb Dual Port Fibre Channel Host Bus Adapter
- HP SN1100E 16Gb Single Port Fibre Channel Host Bus Adapter
- HP LPe1605 16Gb Fibre Channel Host Bus Adapter for BladeSystem c-Class
- HP FlexFabric 20Gb 2-port 650FLB Adapter
- HP FlexFabric 20Gb 2-port 650M Adapter
- HP FlexFabric 10Gb 2-port 556FLR-SFP+ Adapter
- HP StoreFabric CN1200E Dual Port Converged Network Adapter
- HPE FlexFabric 10Gb 2-port 556FLR-T Adapter
- HPE StoreFabric CN1200E-T 10GBASE-T Converged Network Adapter
- HP StoreFabric 84E 4-Port Fibre Channel Host Bus Adapter
- HPE Synergy 3530C 16Gb Fibre Channel Host Bus Adapter
- HPE StoreFabric SN1100E 4P 16Gb FC HBA
- HPE StoreFabric SN1200E 16Gb 2P FC HBA
- HPE StoreFabric SN1200E 16Gb 1P FC HBA
- HPE StoreFabric SN1600E 32Gb 2p FC HBA
- HPE StoreFabric SN1600E 32Gb 1p FC HBA

## **Important Note!**

Release Notes:

[HPE StoreFabric Adapters Release Notes](#)

## **Prerequisites**

The target environment must have the libHBAAPI Package installed prior to the installation of the enablement kit. (If not already present, the libHBAAPI Package can be obtained from the operating system installation media.)

## **Enhancements**

This kit, version 11.1.183.22, adds support for the following devices:

- HPE StoreFabric SN1200E 16Gb 2P FC HBA
- HPE StoreFabric SN1200E 16Gb 1P FC HBA
- HPE StoreFabric SN1600E 32Gb 2p FC HBA
- HPE StoreFabric SN1600E 32Gb 1p FC HBA

## **Supported Devices and Features**

- HP NC553i 10Gb 2-port FlexFabric Converged Network Adapter
- HP SN1000E 16Gb Dual Port Fibre Channel Host Bus Adapter
- HP SN1000E 16Gb Single Port Fibre Channel Host Bus Adapter
- HP 82E 8Gb Dual Port PCIe Fibre Channel Host Bus Adapter
- HP 81E 8Gb Single Port PCIe Fibre Channel Host Bus Adapter
- HP CN1100E Dual Port Converged Network Adapter
- HP FlexFabric 10Gb 2-port 554M Adapter
- HP FlexFabric 10Gb 2-port 554FLR-SFP+ Adapter
- HP FlexFabric 10Gb 2-port 554FLB Adapter
- HP LPe1205A 8Gb Fibre Channel Host Bus Adapter for BladeSystem c-Class
- Emulex LPe1205 8Gb Fibre Channel Host Bus Adapter for c-Class BladeSystem
- HP SN1100E 16Gb Dual Port Fibre Channel Host Bus Adapter
- HP SN1100E 16Gb Single Port Fibre Channel Host Bus Adapter
- HP LPe1605 16Gb Fibre Channel Host Bus Adapter for BladeSystem c-Class
- HP FlexFabric 20Gb 2-port 650FLB Adapter
- HP FlexFabric 20Gb 2-port 650M Adapter
- HP FlexFabric 10Gb 2-port 556FLR-SFP+ Adapter
- HP StoreFabric CN1200E Dual Port Converged Network Adapter
- HPE FlexFabric 10Gb 2-port 556FLR-T Adapter
- HPE StoreFabric CN1200E-T 10GBASE-T Converged Network Adapter
- HP StoreFabric 84E 4-Port Fibre Channel Host Bus Adapter
- HPE Synergy 3530C 16Gb Fibre Channel Host Bus Adapter
- HPE StoreFabric SN1100E 4P 16Gb FC HBA
- HPE StoreFabric SN1200E 16Gb 2P FC HBA
- HPE StoreFabric SN1200E 16Gb 1P FC HBA
- HPE StoreFabric SN1600E 32Gb 2p FC HBA
- HPE StoreFabric SN1600E 32Gb 1p FC HBA

Version: 11.1.183.22 **(Recommended)**

Filename: HP-CNA-FC-Emulex-Enablement-Kit-11.1.183.22-1.sles11sp3.i386.rpm; HP-CNA-FC-Emulex-Enablement-Kit-11.1.183.22-1.sles11sp4.i386.rpm

### **Important Note!**

Release Notes:

[HPE StoreFabric Emulex Adapters Release Notes](#)

### **Prerequisites**

The target environment must have the libHBAAPI Package installed prior to the installation of the enablement kit. (If not already present, the libHBAAPI Package can be obtained from the operating system installation media.)

### **Enhancements**

Updated to version 11.1.183.22

### **Supported Devices and Features**

- HP NC553i 10Gb 2-port FlexFabric Converged Network Adapter
- HP SN1000E 16Gb Dual Port Fibre Channel Host Bus Adapter
- HP SN1000E 16Gb Single Port Fibre Channel Host Bus Adapter
- HP 82E 8Gb Dual Port PCIe Fibre Channel Host Bus Adapter
- HP 81E 8Gb Single Port PCIe Fibre Channel Host Bus Adapter
- HP CN1100E Dual Port Converged Network Adapter
- HP FlexFabric 10Gb 2-port 554M Adapter
- HP FlexFabric 10Gb 2-port 554FLR-SFP+ Adapter
- HP FlexFabric 10Gb 2-port 554FLB Adapter
- HP LPe1205A 8Gb Fibre Channel Host Bus Adapter for BladeSystem c-Class
- Emulex LPe1205 8Gb Fibre Channel Host Bus Adapter for c-Class BladeSystem
- HP SN1100E 16Gb Dual Port Fibre Channel Host Bus Adapter
- HP SN1100E 16Gb Single Port Fibre Channel Host Bus Adapter
- HP LPe1605 16Gb Fibre Channel Host Bus Adapter for BladeSystem c-Class
- HP StoreFabric 84E 4-Port Fibre Channel Host Bus Adapter

---

HPE Fibre Channel Enablement Kit for SUSE Linux Enterprise Server 12- Emulex

Version: 11.1.183.22 **(Recommended)**

Filename: HP-CNA-FC-Emulex-Enablement-Kit-11.1.183.22-1.sles12sp0.x86\_64.rpm; HP-CNA-FC-Emulex-Enablement-Kit-11.1.183.22-1.sles12sp1.x86\_64.rpm

### **Important Note!**

Release Notes:

[HPE StoreFabric Emulex Adapters Release Notes](#)

### **Prerequisites**

The target environment must have the libHBAAPI Package installed prior to the installation of the enablement kit. (If not already present, the

libHBAAPI Package can be obtained from the operating system installation media.)

## **Enhancements**

Updated to version 11.1.183.22

## **Supported Devices and Features**

- HP NC553i 10Gb 2-port FlexFabric Converged Network Adapter
- HP SN1000E 16Gb Dual Port Fibre Channel Host Bus Adapter
- HP SN1000E 16Gb Single Port Fibre Channel Host Bus Adapter
- HP 82E 8Gb Dual Port PCIe Fibre Channel Host Bus Adapter
- HP 81E 8Gb Single Port PCIe Fibre Channel Host Bus Adapter
- HP CN1100E Dual Port Converged Network Adapter
- HP FlexFabric 10Gb 2-port 554M Adapter
- HP FlexFabric 10Gb 2-port 554FLR-SFP+ Adapter
- HP FlexFabric 10Gb 2-port 554FLB Adapter
- HP LPe1205A 8Gb Fibre Channel Host Bus Adapter for BladeSystem c-Class
- Emulex LPe1205 8Gb Fibre Channel Host Bus Adapter for c-Class BladeSystem
- HP SN1100E 16Gb Dual Port Fibre Channel Host Bus Adapter
- HP SN1100E 16Gb Single Port Fibre Channel Host Bus Adapter
- HP LPe1605 16Gb Fibre Channel Host Bus Adapter for BladeSystem c-Class
- HP FlexFabric 20Gb 2-port 650FLB Adapter
- HP FlexFabric 20Gb 2-port 650M Adapter
- HP FlexFabric 10Gb 2-port 556FLR-SFP+ Adapter
- HP StoreFabric CN1200E Dual Port Converged Network Adapter
- HPE FlexFabric 10Gb 2-port 556FLR-T Adapter
- HPE StoreFabric CN1200E-T 10GBASE-T Converged Network Adapter
- HP StoreFabric 84E 4-Port Fibre Channel Host Bus Adapter
- HPE Synergy 3530C 16Gb Fibre Channel Host Bus Adapter
- HPE StoreFabric SN1100E 4P 16Gb FC HBA

---

HPE Fibre Channel Enablement Kit for SUSE Linux Enterprise Server 12- Emulex

Version: 11.1.183.38 **(Recommended)**

Filename: HP-CNA-FC-Emulex-Enablement-Kit-11.1.183.38-1.sles12sp2.x86\_64.rpm

## **Important Note!**

Release Notes:

[HPE StoreFabric Emulex Adapters Release Notes](#)

## **Prerequisites**

The target environment must have the libHBAAPI Package installed prior to the installation of the enablement kit. (If not already present, the libHBAAPI Package can be obtained from the operating system installation media.)

## **Enhancements**

Initial support for SUSE Linux Enterprise Server 12.

Initial support for the following devices:

- HPE StoreFabric SN1200E 16Gb 2P FC HBA
- HPE StoreFabric SN1200E 16Gb 1P FC HBA
- HPE StoreFabric SN1600E 32Gb 2p FC HBA
- HPE StoreFabric SN1600E 32Gb 1p FC HBA

### **Supported Devices and Features**

- HP NC553i 10Gb 2-port FlexFabric Converged Network Adapter
- HP SN1000E 16Gb Dual Port Fibre Channel Host Bus Adapter
- HP SN1000E 16Gb Single Port Fibre Channel Host Bus Adapter
- HP 82E 8Gb Dual Port PCIe Fibre Channel Host Bus Adapter
- HP 81E 8Gb Single Port PCIe Fibre Channel Host Bus Adapter
- HP CN1100E Dual Port Converged Network Adapter
- HP FlexFabric 10Gb 2-port 554M Adapter
- HP FlexFabric 10Gb 2-port 554FLR-SFP+ Adapter
- HP FlexFabric 10Gb 2-port 554FLB Adapter
- HP LPe1205A 8Gb Fibre Channel Host Bus Adapter for BladeSystem c-Class
- Emulex LPe1205 8Gb Fibre Channel Host Bus Adapter for c-Class BladeSystem
- HP SN1100E 16Gb Dual Port Fibre Channel Host Bus Adapter
- HP SN1100E 16Gb Single Port Fibre Channel Host Bus Adapter
- HP LPe1605 16Gb Fibre Channel Host Bus Adapter for BladeSystem c-Class
- HP FlexFabric 20Gb 2-port 650FLB Adapter
- HP FlexFabric 20Gb 2-port 650M Adapter
- HP FlexFabric 10Gb 2-port 556FLR-SFP+ Adapter
- HP StoreFabric CN1200E Dual Port Converged Network Adapter
- HPE FlexFabric 10Gb 2-port 556FLR-T Adapter
- HPE StoreFabric CN1200E-T 10GBASE-T Converged Network Adapter
- HP StoreFabric 84E 4-Port Fibre Channel Host Bus Adapter
- HPE Synergy 3530C 16Gb Fibre Channel Host Bus Adapter
- HPE StoreFabric SN1100E 4P 16Gb FC HBA
- HPE StoreFabric SN1200E 16Gb 2P FC HBA
- HPE StoreFabric SN1200E 16Gb 1P FC HBA
- HPE StoreFabric SN1600E 32Gb 2p FC HBA
- HPE StoreFabric SN1600E 32Gb 1p FC HBA

---

HPE Fibre Channel Enablement Kit for SUSE Linux Enterprise Server 12- Emulex

Version: 11.1.183.22 (C) **(Recommended)**

Filename: HP-CNA-FC-Emulex-Enablement-Kit-11.1.183.22-1.sles12sp0.x86\_64.rpm; HP-CNA-FC-Emulex-Enablement-Kit-11.1.183.22-1.sles12sp1.x86\_64.rpm

### **Important Note!**

Release Notes:

[HPE StoreFabric Emulex Adapters Release Notes](#)

### **Prerequisites**

The target environment must have the libHBAAPI Package installed prior to the installation of the enablement kit. (If not already present, the libHBAAPI Package can be obtained from the operating system installation media.)

## **Enhancements**

This kit, version 11.1.183.22, adds support for the following devices:

- HPE StoreFabric SN1200E 16Gb 2P FC HBA
- HPE StoreFabric SN1200E 16Gb 1P FC HBA
- HPE StoreFabric SN1600E 32Gb 2p FC HBA
- HPE StoreFabric SN1600E 32Gb 1p FC HBA

## **Supported Devices and Features**

- HP NC553i 10Gb 2-port FlexFabric Converged Network Adapter
- HP SN1000E 16Gb Dual Port Fibre Channel Host Bus Adapter
- HP SN1000E 16Gb Single Port Fibre Channel Host Bus Adapter
- HP 82E 8Gb Dual Port PCIe Fibre Channel Host Bus Adapter
- HP 81E 8Gb Single Port PCIe Fibre Channel Host Bus Adapter
- HP CN1100E Dual Port Converged Network Adapter
- HP FlexFabric 10Gb 2-port 554M Adapter
- HP FlexFabric 10Gb 2-port 554FLR-SFP+ Adapter
- HP FlexFabric 10Gb 2-port 554FLB Adapter
- HP LPe1205A 8Gb Fibre Channel Host Bus Adapter for BladeSystem c-Class
- Emulex LPe1205 8Gb Fibre Channel Host Bus Adapter for c-Class BladeSystem
- HP SN1100E 16Gb Dual Port Fibre Channel Host Bus Adapter
- HP SN1100E 16Gb Single Port Fibre Channel Host Bus Adapter
- HP LPe1605 16Gb Fibre Channel Host Bus Adapter for BladeSystem c-Class
- HP FlexFabric 20Gb 2-port 650FLB Adapter
- HP FlexFabric 20Gb 2-port 650M Adapter
- HP FlexFabric 10Gb 2-port 556FLR-SFP+ Adapter
- HP StoreFabric CN1200E Dual Port Converged Network Adapter
- HPE FlexFabric 10Gb 2-port 556FLR-T Adapter
- HPE StoreFabric CN1200E-T 10GBASE-T Converged Network Adapter
- HP StoreFabric 84E 4-Port Fibre Channel Host Bus Adapter
- HPE Synergy 3530C 16Gb Fibre Channel Host Bus Adapter
- HPE StoreFabric SN1100E 4P 16Gb FC HBA
- HPE StoreFabric SN1200E 16Gb 2P FC HBA
- HPE StoreFabric SN1200E 16Gb 1P FC HBA
- HPE StoreFabric SN1600E 32Gb 2p FC HBA
- HPE StoreFabric SN1600E 32Gb 1p FC HBA

---

HPE QLogic Smart SAN enablement kit for Linux

Version: 3.3-1 **(Optional)**

Filename: hpe-qlogic-smartsan-enablement-kit-3.3-1.noarch.rpm

## **Important Note!**

To obtain the 3PAR Smart SAN User Guide to go the Storage Information Library at the following link:

[Storage Information Library](#)

(<http://www.hpe.com/info/storage/docs/>)

By default, **HP 3PAR Storage** is selected under

## **Products and Solutions**

### **Prerequisites**

Please consult SPOCK for a list of supported configurations available at the following link:

<http://www.hpe.com/storage/spock/>

The HPE supplied fibre channel driver must be installed prior to this enablement kit component if you want to enable Smart SAN functionality. Use the appropriate driver included in the HP Service Pack for ProLiant 2016.04.0, which is available at [www.hpe.com/servers/spp/download](http://www.hpe.com/servers/spp/download).

However, if a Smart SAN enabled driver is not installed at execution time, the component will land the enablement kit files for future use after the driver has been installed.

### **Enhancements**

This is the initial release of a configurable component using the QLogic Smart SAN executable.

### **Supported Devices and Features**

- HP 81Q 8Gb Single Port PCIe Fibre Channel Host Bus Adapter
- HP 82Q 8Gb Dual Port PCIe Fibre Channel Host Bus Adapter
- HP QMH2672 16Gb Fibre Channel Host Bus Adapter for c-Class BladeSystem
- HP StoreFabric SN1000Q 16GB 2-port PCIe Fibre Channel Host Bus Adapter
- HP StoreFabric SN1000Q 16GB 1-port PCIe Fibre Channel Host Bus Adapter
- HP StoreFabric SN1100Q 16GB 2-port PCIe Fibre Channel Host Bus Adapter
- HP StoreFabric SN1100Q 16GB 1-port PCIe Fibre Channel Host Bus Adapter

---

HPE QLogic Smart SAN Enablement Kit for Windows 64 bit operating systems

Version: 1.0.0.1 (b) **(Optional)**

Filename: cp030243.exe

### **Important Note!**

The Smart SAN enablement kit will not execute when an operating system has only the inbox fibre channel driver installed. An out of box (OOB) fibre channel driver is needed to utilize Smart SAN functionality. If any OOB driver is installed, the enablement kit will pre-enable/disable Smart SAN functionality for future use. It can then be activated once a Smart SAN enabled OOB driver is installed (see Prerequisite Notes) and after a reboot has occurred.

To obtain the 3PAR Smart SAN User Guide to go the Storage Information Library at the following link:

[Storage Information Library](#)

(<http://www.hpe.com/info/storage/docs/>)

By default, **HP 3PAR Storage** is selected under



## Products and Solutions

### **Prerequisites**

Please consult SPOCK for a list of supported configurations available at the following link:

<http://www.hpe.com/storage/spock/>

The HPE supplied fibre channel driver must be installed prior to this enablement kit component if you want to enable Smart SAN functionality. Use the appropriate driver included in the HP Service Pack for ProLiant 2016.04.0, which is available at [www.hpe.com/servers/spp/download](http://www.hpe.com/servers/spp/download).

However, if a Smart SAN enabled driver is not installed at execution time, the component will land the enablement kit files for future use after the driver has been installed.

### **Enhancements**

Added support for Microsoft Windows Server 2016 operating system

### **Supported Devices and Features**

This enablement kit is supported on the following HPE adapters:

- HP 81Q PCIe Fibre Channel Host Bus Adapter
- HP 82Q 8Gb Dual Port PCIe Fibre Channel Host Bus Adapter
- HP QMH2672 16Gb Fibre Channel Host Bus Adapter for c-Class BladeSystem
- HP StoreFabric SN1000Q 16GB 2-port PCIe Fibre Channel Host Bus Adapter
- HP StoreFabric SN1000Q 16GB 1-port PCIe Fibre Channel Host Bus Adapter
- HP StoreFabric SN1100Q 16GB 2-port PCIe Fibre Channel Host Bus Adapter
- HP StoreFabric SN1100Q 16GB 1-port PCIe Fibre Channel Host Bus Adapter

---

### **Software - System Management**

[Top](#)

HP ProLiant DL980 System Providers for Windows Server x64 Editions

Version: 9.3.0.2 (B) **(Recommended)**

Filename: cp024577.exe

### **Enhancements**

Component packaging has been updated; no impact to product's functionality

---

HPE Insight Management Agents for Windows Server

Version: 10.60.0.0 **(Optional)**

Filename: cp030266.exe

### **Important Note!**

#### **Change in existing feature with SNMP as data source:**

The existing feature on SMH, "SMH->SNMP & Agents Settings-> Threshold Text mode" will depend on Java runtime (JRE) when it is set to 'UI Mode' i.e. Disable. And in this mode it is observed that, the recent Java versions (v7.x onwards) is taking significant amount of time to load the webapp links on SMH which is affecting the agents performance. So, this feature is modified to disable the 'UI mode' and display the threshold

settings only in 'Text mode' from HP Insight Management Agents v10.50.0.0 and later releases.

### **Prerequisites**

SNMP Service.

### **Fixes**

**The following items have been fixed:**

#### **Server / Foundation Agents:**

- VCA showing incorrect installed version of Advanced Power Capping
- Incorrect memory rank information displayed in SMH
- Agents reporting degraded events when cluster resource of Virtual Machine type is taken offline
- Hyphens are now allowed in SNMP community name
- "NVRAM space" field is missing in SMH iLO Self Test results
- Incorrect name of NIC cards displayed under PCI Devices in SMH
- RNVDIMM Technology is not displayed correctly in SMH
- Incorrect name of Mellanox adapters in PCI Devices
- CSRF vulnerabilities have been rectified in the SMH Settings tab
- SMH links which has Threshold settings feature are taking long time to load/refresh in UI Mode. This mode will use Java Runtime(JRE) and latest Java releases (7.x or later) is causing the delay. So, the UI Mode is disabled and now the Threshold settings will display in Text Mode only.
- Event Notifier Not Sending Email alert for storage system Power Supply failure trap.
- Displaying rebranded name 'HPE' in Agents Control panel Applet
- On SMH Wrong OS name displaying for core OS installation
- cpqHeResMem2ModuleTechnology showing wrong values
- cpqHeFitToIPwrSupplyStatus showing wrong value .

### **Enhancements**

#### **Server/Foundation Agents:**

- Update NIC device database.

---

HPE Insight Management Agents for Windows Server x64 Editions

Version: 10.60.0.0 **(Optional)**

Filename: cp030048.exe

### **Prerequisites**

SNMP service.

### **Fixes**

**The following items have been fixed:**

#### **Server / Foundation Agents:**

- VCA showing incorrect installed version of Advanced Power Capping
- Incorrect memory rank information displayed in SMH

- Agents reporting degraded events when cluster resource of Virtual Machine type is taken offline
- Hyphens are now allowed in SNMP community name
- "NVRAM space" field is missing in SMH iLO Self Test results
- Incorrect name of NIC cards displayed under PCI Devices in SMH
- RNVDIMM Technology is not displayed correctly in SMH
- Incorrect name of Mellanox adapters in PCI Devices
- CSRF vulnerabilities have been rectified in the SMH Settings tab.
- SMH links which has Threshold settings feature are taking long time to load/refresh in UI Mode. This mode will use Java Runtime(JRE) and latest Java releases (7.x or later) is causing the delay. So, the UI Mode is disabled and now the Threshold settings will display in Text Mode only.
- Event Notifier Not Sending Email alert for storage system Power Supply failure trap.
- Displaying rebranded name 'HPE' in Agents Control panel Applet
- On SMH Wrong OS name displaying for WS2k16 Storage Server
- On SMH Wrong OS name displaying for core OS installation.
- cpqHeResMem2ModuleTechnology showing wrong values
- cpqHeFitToIPwrSupplyStatus showing wrong value .

### **Enhancements**

- WS2016 OS Support

#### **Server/Foundation Agents:**

- Update NIC device database.

#### **Network Agents:**

Added support for following network adapters:

- HPE Ethernet 25Gb 4-port 620QSFP28 Adapter
- HPE Ethernet 25Gb 2-port 640FLR-SFP28 Adapter
- HPE Ethernet 25Gb 2-port 640SFP28 Adapter
- HPE FlexFabric 10Gb 4-port 536FLR-T Adapter
- HPE FlexFabric 10Gb 2-port 556FLB Adapter
- HPE Synergy 10Gb 2-port 2820C Converged Network Adapter
- HPE Synergy 3520C 10/20Gb Converged Network Adapter
- HPE Synergy 3820C 10/20Gb Converged Network Adapter

---

HPE Insight Management WBEM Providers for Windows Server

Version: 10.60.0.0 **(Optional)**

Filename: cp030090.exe

### **Important Note!**

Version 10.60.0.0 will be the last HPE Insight Management WBEM Providers release. Though HPE Insight Management WBEM Providers 10.60.0.0 will be available in Gen10 Snap1 SPP, but it will only support Gen 8 and Gen 9 servers.

### **Prerequisites**

The HPE Insight Management WBEM Providers require the HPE ProLiant iLO 3/4 Channel Interface and Management Controller Drivers (version 3.4.0.0 or later) for Windows X64 to be installed prior to this component.

In addition, the System Management Homepage (SMH) component (version 7.2.2.9 or later) is required for a single server web-based user

interface.

## **Fixes**

- Fixed the issue with Insight Management WBEM override root\interop namespace for Hyper-V.
- 50% slow performance/backup issue with HP Ultrium/LTO polling issues.
- Tape backup fails randomly (irrespective of any server or controller/backup software) when HPE Insight Management WBEM Providers is upgraded to version 10.X.
- Providers are causing spare drives to be spun up every few minutes.

## **Enhancements**

Added support for new ProLiant servers and options.

---

HPE Insight Management WBEM Providers for Windows Server x64 Editions

Version: 10.61.0.0 **(Optional)**

Filename: cp031735.exe

## **Important Note!**

Version 10.61.0.0 will be the last HPE Insight Management WBEM Providers release to support Gen8 servers and below.

## **Prerequisites**

The HPE Insight Management WBEM Providers require the HPE ProLiant iLO 3/4 Channel Interface and Management Controller Drivers (version 3.4.0.0 or later) for Windows X64 to be installed prior to this component.

In addition, the System Management Homepage (SMH) component (version 7.2.2.9 or later) is required for a single server web-based user interface.

## **Fixes**

None

## **Enhancements**

- Applied a SHA-256 digital signature to the WBEM Providers MSI file as well as all the binary files contained in it.
- Allowed installation to proceed on systems with the Windows Remote Registry service disabled.

---

HPE Smart Storage Administrator (HPE SSA) CLI for Linux

Version: 2.65-7.0 **(Optional)**

Filename: ssacli-2.65-7.0.i386.compsig; ssacli-2.65-7.0.i386.rpm; ssacli-2.65-7.0.i386.txt

## **Important Note!**

HPE SSACLI will allow you to configure and manage your storage as before, but now with additional features, abilities, and supported devices. Existing ACUCLI scripts should only need to make minimal changes such as calling the appropriate binary or executable in order to maintain compatibility.

## **Fixes**

SSA incorrectly displays 64 characters for the encryption master key length in local mode. The length was changed to 32 characters.

---

HPE Smart Storage Administrator (HPE SSA) CLI for Linux 64-bit  
Version: 2.60-19.0 **(Optional)**  
Filename: ssacli-2.60-19.0.x86\_64.rpm; ssacli-2.60-19.0.x86\_64.txt

## **Important Note!**

HPE SSACLI will allow you to configure and manage your storage as before, but now with additional features, abilities, and supported devices. Existing ACUCLI scripts should only need to make minimal changes such as calling the appropriate binary or executable in order to maintain compatibility.

## **Enhancements**

Support for:

Smart Array H240nr

Smart Array P240nr

Smart Array P542D

Added Sanitize Erase for supporting controllers

Added ability to enable erase and stop erase on multiple drives

---

HPE Smart Storage Administrator (HPE SSA) CLI for Linux 64-bit  
Version: 2.65-7.0 **(Optional)**  
Filename: ssacli-2.65-7.0.x86\_64.compsig; ssacli-2.65-7.0.x86\_64.rpm; ssacli-2.65-7.0.x86\_64.txt

## **Important Note!**

HPE SSACLI will allow you to configure and manage your storage as before, but now with additional features, abilities, and supported devices. Existing ACUCLI scripts should only need to make minimal changes such as calling the appropriate binary or executable in order to maintain compatibility.

## **Fixes**

SSA incorrectly displays 64 characters for the encryption master key length in local mode. The length was changed to 32 characters.

---

HPE Smart Storage Administrator (HPE SSA) CLI for Windows  
Version: 2.50.5.0 **(Optional)**

Filename: cp028650.exe

### **Important Note!**

HPE SSACLI will allow you to configure and manage your storage as before, but now with additional features, abilities, and supported devices. Existing ACUCLI scripts should only need to make minimal changes such as calling the appropriate binary or executable in order to maintain compatibility.

### **Enhancements**

Support for:

Smart Array H240nr

Smart Array P240nr

Smart Array P542D

Added Sanitize Erase for Smart Array Px4x Controllers

Added ability to enable erase and stop erase on multiple drives

Added dual path support when specifying physical drives on the create/move/add/remove/and heal commands, for example:

```
ctrl slot=1 create type=ld drives=[1e:1:1,1e:4:1],[1e:1:2,1e:4:2]
```

Scripting now accepts drive input of the form:

```
Drive= 1E:1:1 [2E:2:1],...
```

On playback, Scripting will attempt to find the first path, 1E:1:1. If this doesn't exist, it will try the second path, 2E:2:1.

This change is to support dual domain systems where different controllers in a system may not see the same paths to a targeted physical drive.

---

HPE Smart Storage Administrator (HPE SSA) CLI for Windows 64-bit

Version: 2.65.7.0 **(Optional)**

Filename: cp031009.exe

### **Important Note!**

HPE SSACLI will allow you to configure and manage your storage as before, but now with additional features, abilities, and supported devices. Existing ACUCLI scripts should only need to make minimal changes such as calling the appropriate binary or executable in order to maintain compatibility.

### **Fixes**

SSA incorrectly displays 64 characters for the encryption master key length in local mode. The length was changed to 32 characters.

---

HPE Smart Storage Administrator (HPE SSA) for Linux

Version: 2.65-7.0 **(Optional)**

Filename: ssa-2.65-7.0.i386.compsig; ssa-2.65-7.0.i386.rpm; ssa-2.65-7.0.i386.txt

## **Important Note!**

HPE SSA replaces the existing HP Array Configuration Utility, or ACU, with an updated design and will deliver new features and functionality for various Smart Storage initiatives as they come online. HPE Smart Array Advanced Pack 1.0 and 2.0 features are now part of the baseline features of HPE SSA, with the appropriate firmware.

HPE SSA will allow you to configure and manage your storage as before, but now with additional features, abilities, and supported devices. Existing ACU scripts should only need to make minimal changes such as calling the appropriate binary or executable in order to maintain compatibility.

## **Prerequisites**

The HPE Smart Storage Administrator for Linux requires the HPE System Management Homepage software to be installed on the server. If the HPE System Management Homepage software is not already installed on your server, please download it from HPE.com and install it before installing the HPE Smart Storage Administrator for Linux.

**IMPORTANT UPDATE:** HPE SSA (GUI) for Linux can now be run without requiring the HPE System Management Homepage. HPE SSA now supports a Local Application Mode for Linux. The HPE System Management Homepage is still supported, but no longer required to run the HPE SSA GUI.

To invoke, enter the following at the command prompt:

```
ssa -local
```

The command will start HP SSA in a new Firefox browser window. When the browser window is closed, HP SSA will automatically stop. This is only valid for the loopback interface, and not visible to external network connections.

## **Fixes**

SSA incorrectly displays 64 characters for the encryption master key length in local mode. The length was changed to 32 characters.

---

HPE Smart Storage Administrator (HPE SSA) for Linux 64-bit  
Version: 2.60-18.0 **(Optional)**  
Filename: ssa-2.60-18.0.x86\_64.rpm; ssa-2.60-18.0.x86\_64.txt

## **Important Note!**

HPE SSA replaces the existing HP Array Configuration Utility, or ACU, with an updated design and will deliver new features and functionality for various Smart Storage initiatives as they come online. HPE Smart Array Advanced Pack 1.0 and 2.0 features are now part of the baseline features of HPE SSA, with the appropriate firmware.

HPE SSA will allow you to configure and manage your storage as before, but now with additional features, abilities, and supported devices. Existing ACU scripts should only need to make minimal changes such as calling the appropriate binary or executable in order to maintain compatibility.

## **Prerequisites**

The HPE Smart Storage Administrator for Linux requires the HPE System Management Homepage software to be installed on the server. If the HPE System Management Homepage software is not already installed on your server, please download it from HPE.com and install it before

installing the HPE Smart Storage Administrator for Linux.

**IMPORTANT UPDATE:** HPE SSA (GUI) for Linux can now be run without requiring the HPE System Management Homepage. HPE SSA now supports a Local Application Mode for Linux. The HPE System Management Homepage is still supported, but no longer required to run the HPE SSA GUI.

To invoke, enter the following at the command prompt:

```
ssa -local
```

The command will start HP SSA in a new Firefox browser window. When the browser window is closed, HP SSA will automatically stop. This is only valid for the loopback interface, and not visible to external network connections.

## **Enhancements**

Support for:

Smart Array H240nr

Smart Array P240nr

Smart Array P542D

Added Sanitize Erase for supporting controllers

Added ability to enable erase and stop erase on multiple drives

---

HPE Smart Storage Administrator (HPE SSA) for Linux 64-bit

Version: 2.65-7.0 **(Optional)**

Filename: ssa-2.65-7.0.x86\_64.compsig; ssa-2.65-7.0.x86\_64.rpm; ssa-2.65-7.0.x86\_64.txt

## **Important Note!**

HPE SSA replaces the existing HP Array Configuration Utility, or ACU, with an updated design and will deliver new features and functionality for various Smart Storage initiatives as they come online. HPE Smart Array Advanced Pack 1.0 and 2.0 features are now part of the baseline features of HPE SSA, with the appropriate firmware.

HPE SSA will allow you to configure and manage your storage as before, but now with additional features, abilities, and supported devices. Existing ACU scripts should only need to make minimal changes such as calling the appropriate binary or executable in order to maintain compatibility.

## **Prerequisites**

The HPE Smart Storage Administrator for Linux requires the HPE System Management Homepage software to be installed on the server. If the HPE System Management Homepage software is not already installed on your server, please download it from HPE.com and install it before installing the HPE Smart Storage Administrator for Linux.

**IMPORTANT UPDATE:** HPE SSA (GUI) for Linux can now be run without requiring the HPE System Management Homepage. HPE SSA now supports a Local Application Mode for Linux. The HPE System Management Homepage is still supported, but no longer required to run the HPE SSA GUI.

To invoke, enter the following at the command prompt:



ssa -local

The command will start HP SSA in a new Firefox browser window. When the browser window is closed, HP SSA will automatically stop. This is only valid for the loopback interface, and not visible to external network connections.

### **Fixes**

SSA incorrectly displays 64 characters for the encryption master key length in local mode. The length was changed to 32 characters.

---

HPE Smart Storage Administrator (HPE SSA) for Windows

Version: 2.50.5.0 **(Optional)**

Filename: cp028648.exe

### **Important Note!**

HPE SSA replaces the existing HP Array Configuration Utility, or ACU, with an updated design and will deliver new features and functionality for various Smart Storage initiatives as they come online. HPE Smart Array Advanced Pack 1.0 and 2.0 features are now part of the baseline features of HPE SSA, with the appropriate firmware.

HPE SSA will allow you to configure and manage your storage as before, but now with additional features, abilities, and supported devices. Existing ACU scripts should only need to make minimal changes such as calling the appropriate binary or executable in order to maintain compatibility.

### **Enhancements**

Support for:

Smart Array H240nr

Smart Array P240nr

Smart Array P542D

Added Sanitize Erase for supporting controllers

Added ability to enable erase and stop erase on multiple drives

---

HPE Smart Storage Administrator (HPE SSA) for Windows 64-bit

Version: 2.65.7.0 **(Optional)**

Filename: cp031007.exe

### **Important Note!**

HPE SSA replaces the existing HP Array Configuration Utility, or ACU, with an updated design and will deliver new features and functionality for various Smart Storage initiatives as they come online. HPE Smart Array Advanced Pack 1.0 and 2.0 features are now part of the baseline features of HPE SSA, with the appropriate firmware.

HPE SSA will allow you to configure and manage your storage as before, but now with additional features, abilities, and supported devices. Existing ACU scripts should only need to make minimal changes such as calling the appropriate binary or executable in order to maintain compatibility.

## **Fixes**

SSA incorrectly displays 64 characters for the encryption master key length in local mode. The length was changed to 32 characters.

---

HPE Smart Storage Administrator Diagnostic Utility (HPE SSADU) CLI for Linux

Version: 2.65-7.0 **(Optional)**

Filename: ssaducli-2.65-7.0.i386.compsig; ssaducli-2.65-7.0.i386.rpm; ssaducli-2.65-7.0.i386.txt

## **Important Note!**

This stand alone version of the HPE Smart Storage Administrator's Diagnostic feature is available only in CLI form. For the GUI version of Diagnostic reports, please use HPE Smart Storage Administrator (HPE SSA).

## **Fixes**

SSA incorrectly displays 64 characters for the encryption master key length in local mode. The length was changed to 32 characters.

---

HPE Smart Storage Administrator Diagnostic Utility (HPE SSADU) CLI for Linux 64-bit

Version: 2.60-18.0 **(Optional)**

Filename: ssaducli-2.60-18.0.x86\_64.rpm; ssaducli-2.60-18.0.x86\_64.txt

## **Important Note!**

This stand alone version of the HPE Smart Storage Administrator's Diagnostic feature is available only in CLI form. For the GUI version of Diagnostic reports, please use HPE Smart Storage Administrator (HPE SSA).

## **Enhancements**

Support for:

Smart Array H240nr

Smart Array P240nr

Smart Array P542D

Added Sanitize Erase for supporting controllers

Added ability to enable erase and stop erase on multiple drives

---

HPE Smart Storage Administrator Diagnostic Utility (HPE SSADU) CLI for Linux 64-bit

Version: 2.65-7.0 **(Optional)**

Filename: ssaducli-2.65-7.0.x86\_64.compsig; ssaducli-2.65-7.0.x86\_64.rpm; ssaducli-2.65-7.0.x86\_64.txt

## **Important Note!**

This stand alone version of the HPE Smart Storage Administrator's Diagnostic feature is available only in CLI form. For the GUI version of Diagnostic reports, please use HPE Smart Storage Administrator (HPE SSA).

## **Fixes**

SSA incorrectly displays 64 characters for the encryption master key length in local mode. The length was changed to 32 characters.

---

HPE Smart Storage Administrator Diagnostic Utility (HPE SSADU) CLI for Windows

Version: 2.50.5.0 **(Optional)**

Filename: cp028652.exe

## **Important Note!**

This stand alone version of the HPE Smart Storage Administrator's Diagnostic feature is available only in CLI form. For the GUI version of Diagnostic reports, please use HPE Smart Storage Administrator (HPE SSA).

## **Enhancements**

Support for:

Smart Array H240nr

Smart Array P240nr

Smart Array P542D

Added Sanitize Erase for Smart Array Px4x Controllers

Added ability to enable erase and stop erase on multiple drives

Added dual path support when specifying physical drives on the create/move/add/remove/and heal commands, for example:

```
ctrl slot=1 create type=ld drives=[1e:1:1,1e:4:1],[1e:1:2,1e:4:2]
```

Scripting now accepts drive input of the form:

```
Drive= 1E:1:1 [2E:2:1],...
```

On playback, Scripting will attempt to find the first path, 1E:1:1. If this doesn't exist, it will try the second path, 2E:2:1.

This change is to support dual domain systems where different controllers in a system may not see the same paths to a targeted physical drive.

---

HPE Smart Storage Administrator Diagnostic Utility (HPE SSADU) CLI for Windows 64-bit

Version: 2.65.7.0 **(Optional)**

Filename: cp031011.exe

## **Important Note!**

This stand alone version of the HPE Smart Storage Administrator's Diagnostic feature is available only in CLI form. For the GUI version of Diagnostic reports, please use HPE Smart Storage Administrator (HPE SSA).

## **Fixes**

SSA incorrectly displays 64 characters for the encryption master key length in local mode. The length was changed to 32 characters.

---

HPE SNMP Agents for Red Hat Enterprise Linux 6 (AMD64/EM64T)

Version: 10.6.1 **(Optional)**

Filename: hp-snmp-agents-10.61-2939.2.rhel6.x86\_64.rpm

### **Prerequisites**

The hp-health and hp-snmp-agents run as 32 bit applications in the x86\_64 environment. The Linux kernel 32 bit compatibility must be enabled (usual default for Linux) and the 32 bit compatibility libraries must be present.

To get the list of all dependency files for hp-snmp-agents type:

```
rpm -qp --requires hp-snmp-agents-<version>.rpm
```

### **Fixes**

Fixed the following items:

- Files in directories under /var/spool/compaq/hpasm/registry/ have SGID bit set
- Total MEM shows“OMB” w/ 32pcs 128G DIMM in SMH-System Board in Linux
- HPSUM discovery works for G7 platforms

---

HPE SNMP Agents for Red Hat Enterprise Linux 6 (x86)

Version: 10.6.1 **(Optional)**

Filename: hp-snmp-agents-10.61-2939.2.rhel6.i686.rpm

### **Prerequisites**

The **hp-snmp-agents** RPM install will fail, if all dependencies are not installed. The administrator can verify the list of dependencies required by running this command. If the repositories being used by yum or zypper, includes these dependencies, the installation tool will automatically retrieve them. However if they are not present, the user must manually install them prior to proceeding with the RPM install.

To get the list of all dependency files for hp-snmp-agents type:

```
rpm -qp --requires hp-snmp-agents-<version>.rpm
```

### **Fixes**

Fixed the following items:

- Files in directories under /var/spool/compaq/hpasm/registry/ have SGID bit set
- Total MEM shows“OMB” w/ 32pcs 128G DIMM in SMH-System Board in Linux
- HPSUM discovery works for G7 platforms

### **Enhancements**

cpqnicd stability improvements

---

HPE SNMP Agents for Red Hat Enterprise Linux 7 Server

Version: 10.6.1 **(Optional)**

Filename: hp-snmp-agents-10.61-2939.2.rhel7.x86\_64.rpm

## **Prerequisites**

The hp-health and hp-snmp-agents run as 32 bit applications in the x86\_64 environment. The Linux kernel 32 bit compatibility must be enabled (usual default for Linux) and the 32 bit compatibility libraries must be present.

To get the list of all dependency files for hp-snmp-agents type:

```
rpm -qp --requires hp-snmp-agents-<version>.rpm
```

## **Fixes**

Fixed the following items:

- Files in directories under /var/spool/compaq/hpasm/registry/ have SGID bit set
- Total MEM shows "OMB" w/ 32pcs 128G DIMM in SMH-System Board in Linux
- HPSUM discovery works for G7 platforms

---

HPE SNMP Agents for SUSE LINUX Enterprise Server 11 (AMD64/EM64T)

Version: 10.6.1 **(Optional)**

Filename: hp-snmp-agents-10.61-2939.2.sles11.x86\_64.rpm

## **Prerequisites**

The hp-health and hp-snmp-agents run as 32 bit applications in the x86\_64 environment. The Linux kernel 32 bit compatibility must be enabled (usual default for Linux) and the 32 bit compatibility libraries must be present.

To get the list of all dependency files for hp-snmp-agents type:

```
rpm -qp --requires hp-snmp-agents-<version>.rpm
```

## **Fixes**

Fixed the following items:

- Files in directories under /var/spool/compaq/hpasm/registry/ have SGID bit set
- Total MEM shows "OMB" w/ 32pcs 128G DIMM in SMH-System Board in Linux
- HPSUM discovery works for G7 platforms

---

HPE SNMP Agents for SUSE LINUX Enterprise Server 11 (x86)

Version: 10.6.1 **(Optional)**

Filename: hp-snmp-agents-10.61-2939.2.sles11.i586.rpm

## **Prerequisites**

The **hp-snmp-agents** RPM install will fail, if all dependencies are not installed. The administrator can verify the list of dependencies required by running this command. If the repositories being used by yum or zypper, includes these dependencies, the installation tool will automatically retrieve them. However if they are not present, the user must manually install them prior to proceeding with the RPM install.

To get the list of all dependency files for hp-snmp-agents type:

```
rpm -qp --requires hp-snmp-agents-<version>.rpm
```

## **Fixes**

Fixed the following items:

- Files in directories under /var/spool/compaq/hpasm/registry/ have SGID bit set
- Total MEM shows "OMB" w/ 32pcs 128G DIMM in SMH-System Board in Linux
- HPSUM discovery works for G7 platforms

## **Enhancements**

cpqnicd stability improvements

---

HPE SNMP Agents for SUSE LINUX Enterprise Server 12

Version: 10.5.0 **(Optional)**

Filename: hp-snmp-agents-10.50-2926.40.sles12.x86\_64.rpm

## **Prerequisites**

The hp-health and hp-snmp-agents run as 32 bit applications in the x86\_64 environment. The Linux kernel 32 bit compatibility must be enabled (usual default for Linux) and the 32 bit compatibility libraries must be present.

To get the list of all dependency files for hp-snmp-agents type:

***rpm -qp --requires hp-snmp-agents-<version>.rpm***

## **Fixes**

- SMH showing complete 'System ROM' version in System section.
- cmahostd handles nfs and autofs mount point to fix performance problem.

## **Enhancements**

Added support for new HPE ProLiant Gen9 Servers.

Added support for the following storage controllers:

- HPE Smart Array P240nr Controller
- HPE Smart HBA H240nr Controller
- HPE Smart Array P542D Controller

Added support for the following network adapters:

- HPE Synergy 3520C 10/20Gb Converged Network Adapter
- HPE FlexFabric 10Gb 2-port 556FLB Adapter
- HPE FlexFabric 10Gb 4-port 536FLR-T Adapter
- HPE Ethernet 25Gb 4-port 620SFP28 Adapter
- HPE Ethernet 10Gb 2-port 563i Adapter

---

HPE SNMP Agents for SUSE LINUX Enterprise Server 12

Version: 10.6.1 **(Optional)**

Filename: hp-snmp-agents-10.61-2939.2.sles12.x86\_64.rpm

## **Prerequisites**

The hp-health and hp-snmp-agents run as 32 bit applications in the x86\_64 environment. The Linux kernel 32 bit compatibility must be enabled (usual default for Linux) and the 32 bit compatibility libraries must be present.

To get the list of all dependency files for hp-snmp-agents type:

```
rpm -qp --requires hp-snmp-agents-<version>.rpm
```

## **Fixes**

Fixed the following items:

- Files in directories under /var/spool/compaq/hpasm/registry/ have SGID bit set
- Total MEM shows "OMB" w/ 32pcs 128G DIMM in SMH-System Board in Linux
- HPSUM discovery works for G7 platforms

---

HPE System Health Application and Command Line Utilities for Red Hat Enterprise Linux 6 (AMD64/EM64T)

Version: 10.6.0 (a) **(Optional)**

Filename: hp-health-10.6.0-1838.1.rhel6.x86\_64.rpm

## **Prerequisites**

The hp-health and hp-snmp-agents run as 32 bit applications in the x86\_64 environment. The Linux kernel 32 bit compatibility must be enabled (usual default for Linux) and the 32 bit compatibility libraries must be present.

To get the list of all dependency files for hp-health, type:

```
rpm -qp --requires hp-health-< version >.rpm
```

## **Fixes**

Fixed the following items:

- File permissions for hp-health services
- HPSUM discovery works with G7 platforms

## **Enhancements**

- Fixed hp-health to work with linux kernel versions 4.X

---

HPE System Health Application and Command Line Utilities for Red Hat Enterprise Linux 6 (x86)

Version: 10.6.0 (a) **(Optional)**

Filename: hp-health-10.6.0-1838.1.rhel6.i686.rpm

## **Prerequisites**

The **hp-health** RPM install will fail, if all dependencies are not installed. The administrator can verify the list of dependencies required by running this command. If the repositories being used by yum or zypper, includes these dependencies, the installation tool will automatically retrieve them. However if they are not present, the user must manually install them prior to proceeding with the RPM install.

To get the list of all dependency files for hp-health, type:

```
rpm -qp --requires hp-health-< version >.rpm
```

### **Fixes**

Fixed the following items:

- File permissions for hp-health services
- HPSUM discovery works with G7 platforms

### **Enhancements**

- Fixed hp-health to work with linux kernel versions 4.X

---

HPE System Health Application and Command Line Utilities for Red Hat Enterprise Linux 7 Server

Version: 10.6.0 (a) **(Optional)**

Filename: hp-health-10.60-1838.1.rhel7.x86\_64.rpm

### **Prerequisites**

The hp-health and hp-snmp-agents run as 32 bit applications in the x86\_64 environment. The Linux kernel 32 bit compatibility must be enabled (usual default for Linux) and the 32 bit compatibility libraries must be present.

To get the list of all dependency files for hp-health, type:

```
rpm -qp --requires hp-health-< version >.rpm
```

### **Fixes**

Fixed the following items:

- File permissions for hp-health services
- HPSUM discovery works with G7 platforms

### **Enhancements**

- Fixed hp-health to work with linux kernel versions 4.X

---

HPE System Health Application and Command Line Utilities for SUSE LINUX Enterprise Server 11 (AMD64/EM64T)

Version: 10.6.0 (a) **(Optional)**

Filename: hp-health-10.60-1838.1.sles11.x86\_64.rpm

### **Prerequisites**

The hp-health and hp-snmp-agents run as 32 bit applications in the x86\_64 environment. The Linux kernel 32 bit compatibility must be enabled (usual default for Linux) and the 32 bit compatibility libraries must be present.

To get the list of all dependency files for hp-health, type:

```
rpm -qp --requires hp-health-< version >.rpm
```



## **Fixes**

Fixed the following items:

- File permissions for hp-health services
- HPSUM discovery works with G7 platforms

## **Enhancements**

- Fixed hp-health to work with linux kernel versions 4.X

---

HPE System Health Application and Command Line Utilities for SUSE LINUX Enterprise Server 11 (x86)

Version: 10.6.0 (a) **(Optional)**

Filename: hp-health-10.60-1838.1.sles11.i586.rpm

## **Prerequisites**

The **hp-health** RPM install will fail, if all dependencies are not installed. The administrator can verify the list of dependencies required by running this command. If the repositories being used by yum or zypper, includes these dependencies, the installation tool will automatically retrieve them. However if they are not present, the user must manually install them prior to proceeding with the RPM install.

To get the list of all dependency files for hp-health, type:

```
rpm -qp --requires hp-health-< version >.rpm
```

## **Fixes**

Fixed the following items:

- File permissions for hp-health services
- HPSUM discovery works with G7 platforms

## **Enhancements**

- Fixed hp-health to work with linux kernel versions 4.X

---

HPE System Health Application and Command Line Utilities for SUSE LINUX Enterprise Server 12

Version: 10.5.0 **(Optional)**

Filename: hp-health-10.50-1826.37.sles12.x86\_64.rpm

## **Prerequisites**

The hp-health and hp-snmp-agents run as 32 bit applications in the x86\_64 environment. The Linux kernel 32 bit compatibility must be enabled (usual default for Linux) and the 32 bit compatibility libraries must be present.

To get the list of all dependency files for hp-health, type:

```
rpm -qp --requires hp-health-< version >.rpm
```

## **Fixes**

- iLO reset doesn't affect running hp-health service.
- Fixed an issue where hp-health was consuming 100% CPU utilization on hpsmxd (iLO2).
- After modifying execution order of asr and hp-health service, hp-asrd runs properly.
- Fixed hp-health and iLO target connectivity issue.
- The hpsmcli command 'show server' now displays embedded NICs.

### **Enhancements**

Added support for new HPE ProLiant Gen9 Servers.

---

HPE System Health Application and Command Line Utilities for SUSE LINUX Enterprise Server 12

Version: 10.6.0 (a) **(Optional)**

Filename: hp-health-10.60-1838.1.sles12.x86\_64.rpm

### **Prerequisites**

The hp-health and hp-snmp-agents run as 32 bit applications in the x86\_64 environment. The Linux kernel 32 bit compatibility must be enabled (usual default for Linux) and the 32 bit compatibility libraries must be present.

To get the list of all dependency files for hp-health, type:

```
rpm -qp --requires hp-health-< version >.rpm
```

### **Fixes**

Fixed the following items:

- File permissions for hp-health services
- HPSUM discovery works with G7 platforms

### **Enhancements**

- Fixed hp-health to work with linux kernel versions 4.X

---

HPE System Management Homepage for Linux (AMD64/EM64T)

Version: 7.6.0-11 **(Recommended)**

Filename: hpsmh-7.6.0-11.x86\_64.rpm

### **Important Note!**

Version 7.6.0 will be the last SMH release. Though SMH 7.6.0 will be available in Gen10 Snap1 SPP, but it will only support Gen 8 and Gen 9 servers. Any future patch releases will be available, only on SMH web page. Please refer to HPE SMH [Release Notes](#)

### **Prerequisites**

Before installing the SMH software, the RPM verifies that the required versions of Linux library dependencies are present. If any dependencies are not present, then a list of the missing dependencies is provided. The user must manually install all missing dependencies to satisfy the prerequisites before proceeding with the RPM installation.

## **Fixes**

- Proper handling of Single Sign-On requests and certificates, which are in bad format
- HPE Rebranding changes

## **Enhancements**

- Updated the following components:
  - PHP to version 5.5.38
  - Curl to version 7.49.1
  - OpenSSL to version 1.0.2h
  - Libxml2 to version libxml2-2.9.4
- SSL Cipher Suite is set to TLSv1.2 as default
- Improved Security features [Please find more details in the Security Bulletin (ID: HPSBMU03653)]

---

HPE System Management Homepage for Linux (x86)

Version: 7.6.0-11 **(Recommended)**

Filename: hpsmh-7.6.0-11.i386.rpm

## **Important Note!**

Version 7.6.0 will be the last SMH release. Though SMH 7.6.0 will be available in Gen10 Snap1 SPP, but it will only support Gen 8 and Gen 9 servers. Any future patch releases will be available, only on SMH web page. Please refer to HPE SMH [Release Notes](#)

## **Prerequisites**

Before installing the SMH software, the RPM verifies that the required versions of Linux library dependencies are present. If any dependencies are not present, then a list of the missing dependencies is provided. The user must manually install all missing dependencies to satisfy the prerequisites before proceeding with the RPM installation.

## **Fixes**

- Proper handling of Single Sign-On requests and certificates, which are in bad format
- HPE Rebranding changes

## **Enhancements**

- Updated the following components:
  - PHP to version 5.5.38
  - Curl to version 7.49.1
  - OpenSSL to version 1.0.2h
  - Libxml2 to version libxml2-2.9.4

SSL Cipher Suite is set to TLSv1.2 as default

- Improved Security features [Please find more details in the Security Bulletin (ID: HPSBMU03653)]

---

HPE System Management Homepage for Windows x64

Version: 7.6.0.11 **(Recommended)**

Filename: cp029674.exe

### **Important Note!**

Version 7.6.0 will be the last SMH release. Though SMH 7.6.0 will be available in Gen10 Snap1 SPP, but it will only support Gen 8 and Gen 9 servers. Any future patch releases will be available, only on SMH web page. Please refer to HPE SMH [Release Notes](#)

### **Fixes**

- Proper handling of Single Sign-On requests and certificates, which are in bad format
- HPE Rebranding changes

### **Enhancements**

- Updated the following components:
  - PHP to version 5.5.38
  - Curl to version 7.49.1
  - OpenSSL to version 1.0.2h
  - Libxml2 to version libxml2-2.9.4
- SSL Cipher Suite is set to TLSv1.2 as default
- Improved Security features [Please find more details in the Security Bulletin (ID: HPSBMU03653)]

---

HPE System Management Homepage for Windows x86

Version: 7.6.0.11 **(Recommended)**

Filename: cp029673.exe

### **Important Note!**

Version 7.6.0 will be the last SMH release. Though SMH 7.6.0 will be available in Gen10 Snap1 SPP, but it will only support Gen 8 and Gen 9 servers. Any future patch releases will be available, only on SMH web page. Please refer to HPE SMH [Release Notes](#)

### **Fixes**

- Proper handling of Single Sign-On requests and certificates, which are in bad format
- HPE Rebranding changes

### **Enhancements**

- Updated the following components:

- PHP to version 5.5.38
- Curl to version 7.49.1
- OpenSSL to version 1.0.2h
- Libxml2 to version libxml2-2.9.4
- SSL Cipher Suite is set to TLSv1.2 as default
- Improved Security features [Please find more details in the Security Bulletin (ID: HPSBMU03653)]

---

HPE System Management Homepage Templates for Linux

Version: 10.5.0 **(Optional)**

Filename: hp-smh-templates-10.5.0-1462.26.noarch.rpm

### **Important Note!**

The HP System Health Application and Insight Management Agents (hpsm) version 8.0.0 was split into three individual rpm packages:

- HP System Health Application and Command Line Utilities (hp-health) version 8.1.0
- HP SNMP Agents (hp-snmp-agents) version 8.1.0
- HP System Management Homepage Templates (hp-smh-templates) version 8.1.0

These three packages provide equivalent functionality as hpsm v8.0.0 and allow for more modular installation choices.

### **Prerequisites**

To get the list of all dependency files for hp-smh-templates type:

```
rpm -qp --requires hp-smh-templates-<version>.rpm
```

### **Enhancements**

Added support for new HPE ProLiant Gen9 Servers.

---

HPE System Management Homepage Templates for Linux

Version: 10.6.1 **(Optional)**

Filename: hp-smh-templates-10.6.1-1481.4.noarch.rpm

### **Important Note!**

The HP System Health Application and Insight Management Agents (hpsm) version 8.0.0 was split into three individual rpm packages:

- HP System Health Application and Command Line Utilities (hp-health) version 8.1.0
- HP SNMP Agents (hp-snmp-agents) version 8.1.0
- HP System Management Homepage Templates (hp-smh-templates) version 8.1.0

These three packages provide equivalent functionality as hpsm v8.0.0 and allow for more modular installation choices.

### **Prerequisites**

The **hp-smh-templates** RPM install will fail, if all dependencies are not installed. The administrator can verify the list of dependencies required

by running this command. If the repositories being used by yum or zypper, includes these dependencies, the installation tool will automatically retrieve them. However if they are not present, the user must manually install them prior to proceeding with the RPM install.

To get the list of all dependency files for hp-smh-templates type:

```
rpm -qp --requires hp-smh-templates-<version>.rpm
```

## **Fixes**

Fixed the following items:

- NIC tab is now visible on SMH Home page after setting data source as snmp
- HPSUM discovery works for G7 platforms

---

Insight Diagnostics Online Edition for Linux (x86 32-bit)

Version: 10.60.2109 **(Recommended)**

Filename: hpdiaags-10.60.2109-2176.linux.i586.rpm

## **Important Note!**

The online version of Insight Diagnostics provides the same functionality as the Survey Utility for Windows and Linux and does not perform any hardware tests on the system. Although not required, it is recommended that you uninstall the current Survey Utility for Windows or Linux before beginning the installation of Insight Diagnostics Online Edition.

## **Prerequisites**

The following component(s) are required for Insight Diagnostics Online Edition for Linux:

- System Management Homepage, version 7.0.0-12 or higher

The following component(s) are recommended for HP Insight Diagnostics Online Edition for Linux to make full use of its capabilities:

- System Health Application, version 9.0.0 or higher

## **Fixes**

- Translations fixes.
- Fixed a problem where saving the survey with a system with 124+ luns failed.
- Fixed a problem where the crontab entry from the Insight Diagnostics schedule feature was not removed when uninstalled.

## **Enhancements**

Added support for P542D storage controller.

Added support for NVIDIA Tesla K40 XL 12Gb Module.

Support Wellsburg 6-Port SATA Controller.

Support for new Gen9 systems.

See the [Service Pack for ProLiant Release Notes](#) for more information.

See the [Service Pack for ProLiant Server Support Guide](#) for information on supported servers.

---

Insight Diagnostics Online Edition for Linux (x86-64)

Version: 10.60.2109 **(Recommended)**

Filename: hpdiaqs-10.60.2109-2176.linux.x86\_64.rpm

### **Important Note!**

The online version of Insight Diagnostics provides the same functionality as the Survey Utility for Windows and Linux and does not perform any hardware tests on the system. Although not required, it is recommended that you uninstall the current Survey Utility for Windows or Linux before beginning the installation of Insight Diagnostics Online Edition.

### **Prerequisites**

The following component(s) are required for Insight Diagnostics Online Edition for Linux:

- System Management Homepage, version 7.0.0-12 or higher

The following component(s) are recommended for Insight Diagnostics Online Edition for Linux to make full use of its capabilities:

- System Health Application, version 9.0.0 or higher

You can install them by using the SPP or downloading them individually from HPE Support Center.

### **Fixes**

- Translations fixes.
- Fixed a problem where saving the survey with a system with 124+ luns failed.
- Fixed a problem where the crontab entry from the Insight Diagnostics schedule feature was not removed when uninstalled.

### **Enhancements**

Added support for P542D storage controller.

Added support for NVIDIA Tesla K40 XL 12Gb Module.

Support Wellsburg 6-Port SATA Controller.

Support for new Gen9 systems.

See the [Service Pack for ProLiant Release Notes](#) for more information.

See the [Service Pack for ProLiant Server Support Guide](#) for information on supported servers.

---

Insight Diagnostics Online Edition for Windows

Version: 10.60.2116.0 **(Recommended)**

Filename: cp028680.exe

### **Important Note!**

#### **Known Limitations**

1. Under Insight Diagnostics Online Edition for Windows, the Survey feature no longer supports displaying properties of Logical Drives that are attached to certain Smart Array controllers, either directly or through an enclosure (such as an Modular Smart Array). The controllers affected are:

- Smart Array 6i Controller

- Smart Array 641 Controller
- Smart Array 642 Controller
- Smart Array 6402 Controller
- Smart Array 6404 Controller

These controllers do not support the commands used to obtain logical drive properties. There are currently no plans to add such support to the controllers, nor to add legacy support to future versions of Insight Diagnostics.

As a work-around, Insight Diagnostics Online Edition for Windows, version **8.5 or earlier**, may be used to display logical drive properties in Survey. The Array Configuration Utility, available from [hpe.com](http://hpe.com), can also display information about logical drives attached to these controllers.

2. Windows Server 2008 R2 SP1 is the minimum requirement for Gen9 platforms.

3. Adaptec devices are no longer supported on this version, please use version 10.16.1650 for this.

#### **Other:**

1. The online version of Insight Diagnostics provides the same functionality as the Survey Utility for Windows and Linux and does not perform any hardware tests on the system. Although not required, it is recommended that you uninstall the current Survey Utility for Windows or Linux before beginning the installation of Insight Diagnostics Online Edition.

#### **Prerequisites**

The following component(s) are required for Insight Diagnostics Online Edition for Windows:

- System Management Homepage, version 7.0.0-12 or higher

The following component(s) are recommended for Insight Diagnostics Online Edition for Windows to make full use of its capabilities:

- ProLiant Agentless Management Service, version 9.0.0.0 or higher
- ProLiant Integrated Lights-Out Management Interface Driver, version 1.15.0.0 or higher

#### **Fixes**

- Translations fixes.
- Fixed a problem where saving the survey with a system with 124+ luns failed.

#### **Enhancements**

Added support for P542D storage controller.

Added support for NVIDIA Tesla K40 XL 12Gb Module.

Support Wellsburg 6-Port SATA Controller.

Support for new Gen9 systems.

See the [Service Pack for ProLiant Release Notes](#) for more information.

See the [Service Pack for ProLiant Server Support Guide](#) for information on supported servers.



## **Important Note!**

### **Known Limitations**

1. Under Insight Diagnostics Online Edition for Windows, the Survey feature no longer supports displaying properties of Logical Drives that are attached to certain Smart Array controllers, either directly or through an enclosure (such as an Modular Smart Array). The controllers affected are:

- Smart Array 6i Controller
- Smart Array 641 Controller
- Smart Array 642 Controller
- Smart Array 6402 Controller
- Smart Array 6404 Controller

These controllers do not support the commands used to obtain logical drive properties. There are currently no plans to add such support to the controllers, nor to add legacy support to future versions of Insight Diagnostics.

As a work-around, Insight Diagnostics Online Edition for Windows, version **8.5 or earlier**, may be used to display logical drive properties in Survey. The Array Configuration Utility, available from [hpe.com](http://hpe.com), can also display information about logical drives attached to these controllers.

2. Windows Server 2008 R2 SP1 is the minimum requirement for Gen9 platforms.

3. Adaptec devices are no longer supported on this version, please use version 10.16.1650 for this.

### **Other:**

1. The online version of Insight Diagnostics provides the same functionality as the Survey Utility for Windows and Linux and does not perform any hardware tests on the system. Although not required, it is recommended that you uninstall the current Survey Utility for Windows or Linux before beginning the installation of Insight Diagnostics Online Edition.

## **Prerequisites**

The following component(s) are required for Insight Diagnostics Online Edition for Windows:

- System Management Homepage, version 7.0.0-12 or higher

The following component(s) are recommended for Insight Diagnostics Online Edition for Windows to make full use of its capabilities:

- ProLiant Agentless Management Service, version 9.0.0.0 or higher
- ProLiant Integrated Lights-Out Management Interface Driver, version 1.15.0.0 or higher

## **Fixes**

- Translations fixes.
- Fixed a problem where saving the survey with a system with 124+ luns failed.

## **Enhancements**

Added support for P542D storage controller.

Added support for NVIDIA Tesla K40 XL 12Gb Module.

Support Wellsburg 6-Port SATA Controller.

Support for new Gen9 systems.

See the [Service Pack for ProLiant Release Notes](#) for more information.

See the [Service Pack for ProLiant Server Support Guide](#) for information on supported servers.

---

Integrated Management Log Viewer for Windows Server x64 Editions

Version: 7.8.0.0 **(Optional)**

Filename: cp029435.exe

### **Important Note!**

Starting with version 7.0.0.0, this application will only install on HP ProLiant systems supporting the iLO 2, iLO 3, or iLO 4 management controllers. Installation in a virtual machine is no longer supported.

Starting with version 6.5.0.0, this application requires Administrator privileges through Windows User Account Control.

Version 6.2.0.0 of this application is the final version that will support installation under Windows Server 2003 x64 Edition.

Starting with version 6.0.0.0, the dependencies on the HP ProLiant Remote Monitor Service and the HP ProLiant Remote IML Service have been removed. This application no longer provides access to the Integrated Management Log on a remote system.

Starting with version 5.22.0.0, separate 32-bit and 64-bit releases of this application are available. If you wish to downgrade to version 5.21.0.0 or earlier, use Windows Add or Remove Programs to uninstall the 64-bit release before installing the earlier 32-bit version.

### **Enhancements**

Add support for Windows Server 2016.

---

Integrated Management Log Viewer for Windows Server x86 Editions

Version: 7.7.0.0 **(Optional)**

Filename: cp028661.exe

### **Important Note!**

Starting with version 7.0.0.0, this application will only install on HP ProLiant systems supporting the iLO 2, iLO 3, or iLO 4 management controllers. Installation in a virtual machine is no longer supported.

Starting with version 6.5.0.0, this application requires Administrator privileges through Windows User Account Control.

Version 6.2.0.0 of this application is the final version that will support installation under Windows Server 2003.

Starting with version 6.0.0.0, the dependencies on the HP ProLiant Remote Monitor Service and the HP ProLiant Remote IML Service have been removed. This application no longer provides access to the Integrated Management Log on a remote system.

Starting with version 5.22.0.0, a 64-bit release of this application is available. Version 5.22.0.0 and later of the 32-bit release will not install under 64-bit Windows.

Starting with version 5.3.0.0, installation is based on the Microsoft Installer (MSI). If you wish to downgrade to version 5.2.0.0 or earlier, use Windows Add or Remove Programs to uninstall this application before installing the earlier version.

## **Enhancements**

- Add new events to the Power Subsystem class.
  - The component executable is now digitally signed with both SHA-1 and SHA-256 signatures.
- 

System file generation using manifest file

Version: 7.2.1.0 **(Optional)**

Filename: mapping.xml

## **Fixes**

See the [HP SUM Release Notes](#) for information about the issues resolved in this release.

---

System file generation using manifest file

Version: 7.4.0.0 **(Optional)**

Filename: mapping.xml

## **Fixes**

See the [HP SUM Release Notes](#) for information about the issues resolved in this release.

---

System file generation using manifest file

Version: 7.3.9.9 **(Optional)**

Filename: mapping.xml

## **Fixes**

See the [HP SUM Release Notes](#) for information about the issues resolved in this release.

---

System file generation using manifest file

Version: 7.5.0.0 **(Optional)**

Filename: mapping.xml

## **Fixes**

See the [HP SUM Release Notes](#) for information about the issues resolved in this release.

---

System file generation using manifest file

Version: 7.5.9.9 **(Optional)**

Filename: mapping.xml

## **Fixes**

See the [HP SUM Release Notes](#) for information about the issues resolved in this release.

---

