

Service Pack for ProLiant version 2020.09.0 Contents

This table lists all of the software and firmware on this Service Pack for ProLiant. For more information on this deliverable go to www.hpe.com/servers/spp/download.

Product Category	Description	Build #	Version	Upgrade Requirement	Filename	Release Status
Application - System Management	Integrated Smart Update Tools for Windows x64	22	2.7.0.0	Recommended	cp041077.exe	update
Application - System Management	HPE MegaRAID Storage Administrator StorCLI for VMware6.7	4	2019.09.00	Optional	cp040119.zip	new
Application - System Management	Integrated Smart Update Tools 2.7.0 for ESXi 6.7	30	2020.09.00	Recommended	cp041079.zip	update
Application - System Management	Integrated Smart Update Tools 2.7.0 for ESXi 7.0	25	2020.09.00	Recommended	cp043666.zip	new
Application - System Management	Integrated Smart Update Tools 2.7.0 for ESXi 6.5	31	2020.09.00	Recommended	cp041078.zip	update
Application - System Management	Integrated Smart Update Tools for Linux x64	26	2.7.0.0	Recommended	sut-2.7.0-26.linux.x86_64.rpm	update
Application - System Management	HPE MegaRAID Storage Administrator StorCLI for VMware6.5	2	2019.09.00	Optional	cp040118.zip	update
BIOS - System ROM	Online ROM Flash Component for VMware - HPE ProLiant DL20 Gen9 (U22) Servers	12	2.86_05-28-2020	Recommended	CP043533.zip	update

BIOS - System ROM	Online ROM Flash Component for Linux - HPE ProLiant XL260a Gen9/XL2x260w (U24) Server	1	1.60_01-22-2018 (B)	Critical	firmware-system-u24-1.60_2018_01_22-2.1.i386.rpm	update
BIOS - System ROM	Online ROM Flash Component for VMware - HPE ProLiant BL660c Gen9 (I38) Servers	3	2.76_10-21-2019 (B)	Recommended	CP042597.zip	update
BIOS - System ROM	Online ROM Flash Component for Windows x64 - HPE Apollo 2000 Gen10/HPE ProLiant XL170r/XL190r Gen10 (U38) Servers	4	2.36_07-16-2020	Optional	cp044574.exe	update
BIOS - System ROM	Online ROM Flash Component for Windows x64 - HPE ProLiant DL560 Gen10/DL580 Gen10 (U34) Servers	4	2.36_07-16-2020	Optional	cp044683.exe	update
BIOS - System ROM	Online ROM Flash Component for Windows x64 - HPE ProLiant DL60 Gen9/DL80 Gen9 (U15) Servers	1	2.76_10-21-2019	Recommended	cp041819.exe	update
BIOS - System ROM	Online ROM Flash Component for Linux - HPE Apollo 4200 Gen10/HPE ProLiant XL420 Gen10 (U39) Servers	4	2.36_07-16-2020	Optional	firmware-system-u39-2.36_2020_07_16-1.1.x86_64.rpm	new

BIOS - System ROM	Online ROM Flash Component for Linux - HPE ProLiant ML110 Gen9 (P99) Servers	1	2.76_10-21-2019	Recommended	firmware-system-p99-2.76_2019_10_21-1.1.i386.rpm	update
BIOS - System ROM	Online ROM Flash Component for Linux - HPE ProLiant ML30 Gen9 (U23) Servers	4	2.86_05-28-2020	Recommended	firmware-system-u23-2.86_2020_05_28-1.1.i386.rpm	update
BIOS - System ROM	Online ROM Flash Component for Linux - HPE ProLiant DL560 Gen10/DL580 Gen10 (U34) Servers	4	2.36_07-16-2020	Optional	firmware-system-u34-2.36_2020_07_16-1.1.x86_64.rpm	update
BIOS - System ROM	Online ROM Flash Component for Linux - HPE ProLiant DL385 Gen10 Plus (A42) Servers	21	1.30_07-18-2020	Optional	firmware-system-a42-1.30_2020_07_18-1.1.x86_64.rpm	new
BIOS - System ROM	Online ROM Flash Component for Linux - HPE ProLiant DL325 Gen10 Plus (A43) Servers	20	1.30_07-18-2020	Recommended	firmware-system-a43-1.30_2020_07_18-1.1.x86_64.rpm	new
BIOS - System ROM	Online ROM Flash Component for Linux - HPE ProLiant DL560 Gen9 (P85) Servers	1	2.76_10-21-2019	Recommended	firmware-system-p85-2.76_2019_10_21-1.1.i386.rpm	update
BIOS - System ROM	ROM Flash Firmware Package - HPE Apollo 4200 Gen10/HPE ProLiant XL420	4	2.36_07-16-2020	Optional	U39_2.36_07_16_2020.fwpkg	new

	Gen10 (U39) Servers					
BIOS - System ROM	Online ROM Flash Component for Windows x64 - HPE ProLiant ML30 Gen10 (U44) Servers	1	2.18_06-24-2020	Optional	cp044716.exe	update
BIOS - System ROM	Online ROM Flash Component for Windows x64 - HPE ProLiant BL660c Gen9 (I38) Servers	1	2.76_10-21-2019	Recommended	cp041813.exe	update
BIOS - System ROM	Online ROM Flash Component for Linux - HPE ProLiant DL360 Gen10 (U32) Servers	3	2.36_07-16-2020	Optional	firmware-system-u32-2.36_2020_07_16-1.1.x86_64.rpm	update
BIOS - System ROM	Online ROM Flash Component for VMware - HPE ProLiant BL460c Gen9/WS460c Gen9 (I36) Servers	5	2.76_10-21-2019 (B)	Recommended	CP042585.zip	update
BIOS - System ROM	Online ROM Flash Component for Windows x64 - HPE ProLiant ML110 Gen9 (P99) Servers	1	2.76_10-21-2019	Recommended	cp041816.exe	update
BIOS - System ROM	Online ROM Flash Component for Windows x64 - HPE ProLiant DL360 Gen10 (U32) Servers	3	2.36_07-16-2020	Optional	cp044667.exe	update
BIOS - System ROM	Online ROM Flash Component for Windows x64 - HPE ProLiant	3	2.36_07-16-2020	Optional	cp044689.exe	update

	ML110 Gen10 (U33) Servers					
BIOS - System ROM	Online ROM Flash Component for Windows x64 - HPE ProLiant DL380 Gen10 (U30) Servers	3	2.36_07-16-2020	Optional	cp044661.exe	update
BIOS - System ROM	Online ROM Flash Component for Linux - HPE ProLiant XL730f/XL740f/XL750f Gen9 (U18) Servers	1	2.76_10-21-2019	Recommended	firmware-system-u18-2.76_2019_10_21-1.1.i386.rpm	update
BIOS - System ROM	ROM Flash Firmware Package - HPE ProLiant XL225n Gen10 Plus (A46) Servers	20	1.30_07-18-2020	Recommended	A46_1.30_07_18_2020.fwpkg	new
BIOS - System ROM	ROM Flash Firmware Package - HPE ProLiant ML350 Gen10 (U41) Servers	3	2.36_07-16-2020	Optional	U41_2.36_07_16_2020.fwpkg	update
BIOS - System ROM	Online ROM Flash Component for Windows x64 - HPE ProLiant DL580 Gen9 (U17) Servers	1	2.76_10-21-2019	Recommended	cp041797.exe	update
BIOS - System ROM	Online ROM Flash Component for VMware - HPE Apollo 4200 Gen9/HPE ProLiant XL420 Gen9 (U19) Servers	1	2.76_10-21-2019	Recommended	CP041824.zip	update

BIOS - System ROM	ROM Flash Firmware Package - HPE ProLiant DL20 Gen10 (U43) Servers	3	2.18_06-24-2020	Optional	U43_2.18_06_24_2020.fwpkg	update
BIOS - System ROM	Online ROM Flash Component for Windows x64 - HPE ProLiant MicroServer Gen10 Plus (U48) Servers	1	2.18_06-24-2020	Optional	cp044719.exe	new
BIOS - System ROM	Online ROM Flash Component for Windows x64 - HPE ProLiant EC200a (U26) Server/HPE ProLiant Thin Micro TM200 (U26) Server	5	2.66_07-19-2019	Recommended	cp040771.exe	update
BIOS - System ROM	Online ROM Flash Component for Linux - HPE ProLiant MicroServer Gen10 Plus (U48) Servers	2	2.18_06-24-2020	Optional	firmware-system-u48-2.18_2020_06_24-1.1.x86_64.rpm	new
BIOS - System ROM	Online ROM Flash Component for Linux - HPE ProLiant DL60 Gen9/DL80 Gen9 (U15) Servers	1	2.76_10-21-2019	Recommended	firmware-system-u15-2.76_2019_10_21-1.1.i386.rpm	update
BIOS - System ROM	ROM Flash Firmware Package - HPE ProLiant DL160 Gen10/DL180 Gen10 (U31) Servers	3	2.36_07-16-2020	Optional	U31_2.36_07_16_2020.fwpkg	new

BIOS - System ROM	Online ROM Flash Component for Windows x64 - HPE Apollo 4510 Gen10/HPE ProLiant XL450 Gen10 (U40) Servers	3	2.36_07-16-2020	Optional	cp044676.exe	update
BIOS - System ROM	Online ROM Flash Component for Linux - HPE ProLiant BL460c Gen10 (I41) Servers	4	2.36_07-16-2020	Optional	firmware-system-i41-2.36_2020_07_16-1.1.x86_64.rpm	update
BIOS - System ROM	Online ROM Flash Component for Linux - HPE ProLiant DL580 Gen9 (U17) Servers	1	2.76_10-21-2019 (B)	Recommended	firmware-system-u17-2.76_2019_10_21-2.1.i386.rpm	update
BIOS - System ROM	Online ROM Flash Component for Linux - HPE ProLiant BL660c Gen9 (I38) Servers	1	2.76_10-21-2019	Recommended	firmware-system-i38-2.76_2019_10_21-1.1.i386.rpm	update
BIOS - System ROM	ROM Flash Firmware Package - HPE ProLiant BL460c Gen10 (I41) Servers	6	2.36_07-16-2020	Optional	I41_2.36_07_16_2020.fwpkg	update
BIOS - System ROM	Online ROM Flash Component for Linux - HPE ProLiant DL20 Gen10 (U43) Servers	2	2.18_06-24-2020	Optional	firmware-system-u43-2.18_2020_06_24-1.1.x86_64.rpm	update
BIOS - System ROM	Online ROM Flash Component for Linux - HPE Apollo 4200 Gen9/HPE ProLiant XL420	1	2.76_10-21-2019	Recommended	firmware-system-u19-2.76_2019_10_21-1.1.i386.rpm	update

	Gen9 (U19) Servers					
BIOS - System ROM	ROM Flash Firmware Package - HPE ProLiant ML110 Gen10 (U33) Servers	3	2.36_07- 16-2020	Optional	U33_2.36_07- 16_2020.fwpk g	update
BIOS - System ROM	ROM Flash Firmware Package - HPE Apollo 6500 Gen10/HPE ProLiant XL270d Gen10 (U45) Servers	4	2.36_07- 16-2020	Optional	U45_2.36_07- 16_2020.fwpk g	update
BIOS - System ROM	Online ROM Flash Component for VMware - HPE ProLiant DL60 Gen9/DL80 Gen9 (U15) Servers	1	2.76_10- 21-2019	Recommended	CP041821.zip	update
BIOS - System ROM	Online ROM Flash Component for Linux - HPE ProLiant ML30 Gen10 (U44) Servers	1	2.18_06- 24-2020	Optional	firmware- system-u44- 2.18_2020_06 _24- 1.1.x86_64.rp m	update
BIOS - System ROM	Online ROM Flash Component for VMware - HPE ProLiant DL580 Gen9 (U17) Servers	4	2.76_10- 21-2019 (B)	Recommended	CP042593.zip	update
BIOS - System ROM	Online ROM Flash Component for Windows x64 - HPE ProLiant DL385 Gen10 (A40) Servers	4	2.42_07- 17-2020	Recommended	cp044653.exe	update
BIOS - System ROM	Online ROM Flash Component for VMware - HPE	1	2.76_10- 21-2019	Recommended	CP041818.zip	update

	ProLiant ML110 Gen9 (P99) Servers					
BIOS - System ROM	Online ROM Flash Component for VMware - HPE ProLiant DL380 Gen9/DL360 Gen9 (P89) Servers	3	2.76_10-21-2019 (B)	Recommended	CP042589.zip	update
BIOS - System ROM	Online ROM Flash Component for VMware - HPE ProLiant ML350 Gen9 (P92) Servers	2	2.76_10-21-2019	Recommended	CP041732.zip	update
BIOS - System ROM	Online ROM Flash Component for Linux - HPE ProLiant XL450 Gen9 (U21) Servers	1	2.76_10-21-2019	Recommended	firmware-system-u21-2.76_2019_10_21-1.1.i386.rpm	update
BIOS - System ROM	Online ROM Flash Component for Windows x64 - HPE ProLiant DL325 Gen10 (A41) Servers	7	2.42_07-17-2020	Recommended	cp044639.exe	update
BIOS - System ROM	Online ROM Flash Component for Windows x64 - HPE ProLiant XL230a/XL250a Gen9 (U13) Servers	1	2.76_10-21-2019	Recommended	cp041761.exe	update
BIOS - System ROM	Online ROM Flash Component for Linux - HPE ProLiant XL230a/XL250a Gen9 (U13) Servers	1	2.76_10-21-2019	Recommended	firmware-system-u13-2.76_2019_10_21-1.1.i386.rpm	update

BIOS - System ROM	Online ROM Flash Component for Linux - HPE Apollo 2000 Gen10/HPE ProLiant XL170r/XL190r Gen10 (U38) Servers	4	2.36_07-16-2020	Optional	firmware-system-u38-2.36_2020_07_16-1.1.x86_64.rpm	update
BIOS - System ROM	ROM Flash Universal Firmware Package - HPE ProLiant DL385 Gen10 Plus (A42) Servers	22	1.30_07-18-2020	Recommended	A42_1.30_07_18_2020.fwpkg	new
BIOS - System ROM	Online ROM Flash Component for Linux - HPE ProLiant ML110 Gen10 (U33) Servers	4	2.36_07-16-2020	Optional	firmware-system-u33-2.36_2020_07_16-1.1.x86_64.rpm	update
BIOS - System ROM	Online ROM Flash Component for Linux - HPE ProLiant DL380 Gen10 (U30) Servers	3	2.36_07-16-2020	Optional	firmware-system-u30-2.36_2020_07_16-1.1.x86_64.rpm	update
BIOS - System ROM	Online ROM Flash Component for Linux - HPE ProLiant DL325 Gen10 (A41) Servers	5	2.42_07-17-2020	Recommended	firmware-system-a41-2.42_2020_07_17-1.1.x86_64.rpm	update
BIOS - System ROM	Online ROM Flash Component for Windows x64 - HPE ProLiant DL560 Gen9 (P85) Servers	1	2.76_10-21-2019	Recommended	cp041769.exe	update
BIOS - System ROM	Online ROM Flash Component for Linux - HPE ProLiant XL270d	1	2.76_10-21-2019	Recommended	firmware-system-u25-2.76_2019_10	update

	(U25) Accelerator Tray				_21- 1.1.i386.rpm	
BIOS - System ROM	Online ROM Flash Component for Windows x64 - HPE ProLiant ML30 Gen9 (U23) Servers	12	2.86_05-28-2020	Recommended	cp044253.exe	update
BIOS - System ROM	Online ROM Flash Component for Linux - HPE Apollo 4510 Gen10/HPE ProLiant XL450 Gen10 (U40) Servers	3	2.36_07-16-2020	Optional	firmware-system-u40-2.36_2020_07_16-1.1.x86_64.rpm	update
BIOS - System ROM	Online ROM Flash Component for Windows x64 - HPE ProLiant XL450 Gen9 (U21) Servers	1	2.76_10-21-2019	Recommended	cp041755.exe	update
BIOS - System ROM	Online ROM Flash Component for Linux - HPE ProLiant DL380 Gen9/DL360 Gen9 (P89) Servers	1	2.76_10-21-2019	Recommended	firmware-system-p89-2.76_2019_10_21-1.1.i386.rpm	update
BIOS - System ROM	Online ROM Flash Component for Windows x64 - HPE ProLiant DL385 Gen10 Plus (A42) Servers	22	1.30_07-18-2020	Recommended	cp041357.exe	new
BIOS - System ROM	ROM Flash Firmware Package - HPE ProLiant XL230k Gen10 (U37) Server	5	2.36_07-16-2020	Optional	U37_2.36_07_16_2020.fwpkg	update

BIOS - System ROM	Online ROM Flash Component for VMware - HPE ProLiant XL170r/XL190r Gen9 (U14) Servers	3	2.76_10-21-2019 (B)	Recommended	CP042591.zip	update
BIOS - System ROM	ROM Flash Firmware Package - HPE ProLiant ML30 Gen10 (U44) Servers	1	2.18_06-24-2020	Optional	U44_2.18_06_24_2020.fwpkg	update
BIOS - System ROM	Online ROM Flash Component for Linux - HPE ProLiant ML150 Gen9 (P95) Servers	1	2.76_10-21-2019	Recommended	firmware-system-p95-2.76_2019_10_21-1.1.i386.rpm	update
BIOS - System ROM	Online ROM Flash Component for VMware - HPE ProLiant ML150 Gen9 (P95) Servers	1	2.76_10-21-2019	Recommended	CP041802.zip	update
BIOS - System ROM	Online ROM Flash Component for Windows x64 - HPE Apollo 4200 Gen10/HPE ProLiant XL420 Gen10 (U39) Servers	4	2.36_07-16-2020	Optional	cp044674.exe	new
BIOS - System ROM	ROM Flash Firmware Package - HPE Apollo 2000 Gen10/HPE ProLiant XL170r/XL190r Gen10 (U38) Servers	4	2.36_07-16-2020	Optional	U38_2.36_07_16_2020.fwpkg	update

BIOS - System ROM	Online ROM Flash Component for Linux - HPE ProLiant XL230k Gen10 (U37) Server	5	2.36_07-16-2020	Optional	firmware-system-u37-2.36_2020_07_16-1.1.x86_64.rpm	update
BIOS - System ROM	ROM Flash Firmware Package - HPE ProLiant DL385 Gen10 (A40) Servers	4	2.42_07-17-2020	Recommended	A40_2.42_07_17_2020.fwpkg	update
BIOS - System ROM	Online ROM Flash Component for Linux - HPE ProLiant BL460c Gen9/WS460c Gen9 (I36) Servers	1	2.76_10-21-2019	Recommended	firmware-system-i36-2.76_2019_10_21-1.1.i386.rpm	update
BIOS - System ROM	Online ROM Flash Component for Windows x64 - HPE Apollo 6500 Gen10/HPE ProLiant XL270d Gen10 (U45) Servers	4	2.36_07-16-2020	Optional	cp044577.exe	update
BIOS - System ROM	Online ROM Flash Component for Linux - HPE ProLiant XL170r/XL190r Gen9 (U14) Servers	1	2.76_10-21-2019	Recommended	firmware-system-u14-2.76_2019_10_21-1.1.i386.rpm	update
BIOS - System ROM	Online ROM Flash Component for Linux - HPE ProLiant DL20 Gen9 (U22) Servers	5	2.86_05-28-2020	Recommended	firmware-system-u22-2.86_2020_05_28-1.1.i386.rpm	update
BIOS - System ROM	Online ROM Flash Component for Windows x64 - HPE ProLiant	2	2.76_10-21-2019	Recommended	cp041730.exe	update

	ML350 Gen9 (P92) Servers					
BIOS - System ROM	Online ROM Flash Component for VMware - HPE ProLiant DL120 Gen9 (P86) Servers	2	2.76_10-21-2019 (B)	Recommended	CP042588.zip	update
BIOS - System ROM	Online ROM Flash Component for Windows x64 - HPE Apollo 4200 Gen9/HPE ProLiant XL420 Gen9 (U19) Servers	1	2.76_10-21-2019	Recommended	cp041822.exe	update
BIOS - System ROM	ROM Flash Firmware Package - HPE ProLiant DL325 Gen10 (A41) Servers	5	2.42_07-17-2020	Recommended	A41_2.42_07_17_2020.fwpkg	update
BIOS - System ROM	Online ROM Flash Component for Windows x64 - HPE ProLiant BL460c Gen9/WS460c Gen9 (I36) Servers	1	2.76_10-21-2019	Recommended	cp041810.exe	update
BIOS - System ROM	ROM Flash Firmware Package - HPE Apollo 4510 Gen10/HPE ProLiant XL450 Gen10 (U40) Servers	3	2.36_07-16-2020	Optional	U40_2.36_07_16_2020.fwpkg	update
BIOS - System ROM	Online ROM Flash Component for Windows x64 - HPE ProLiant XL270d (U25) Accelerator Tray	1	2.76_10-21-2019	Recommended	cp041733.exe	update

BIOS - System ROM	Online ROM Flash Component for Windows x64 - HPE ProLiant DL20 Gen9 (U22) Servers	13	2.86_05-28-2020	Recommended	cp043531.exe	update
BIOS - System ROM	Online ROM Flash Component for Windows x64 - HPE ProLiant BL460c Gen10 (I41) Servers	4	2.36_07-16-2020	Optional	cp044580.exe	update
BIOS - System ROM	Online ROM Flash Component for VMware - HPE ProLiant ML30 Gen9 (U23) Servers	3	2.86_05-28-2020	Recommended	CP044251.zip	update
BIOS - System ROM	Online ROM Flash Component for VMware - HPE ProLiant DL160 Gen9/DL180 Gen9 (U20) Servers	1	2.76_10-21-2019	Recommended	CP041774.zip	update
BIOS - System ROM	Online ROM Flash Component for Linux - HPE ProLiant DL160 Gen10/DL180 Gen10 (U31) Servers	3	2.36_07-16-2020	Optional	firmware-system-u31-2.36_2020_07_16-1.1.x86_64.rpm	new
BIOS - System ROM	Online ROM Flash Component for VMware - HPE ProLiant DL560 Gen9 (P85) Servers	3	2.76_10-21-2019 (B)	Recommended	CP042598.zip	update
BIOS - System ROM	ROM Flash Firmware Package - HPE ProLiant DL360 Gen10 (U32) Servers	4	2.36_07-16-2020	Optional	U32_2.36_07_16_2020.fwpkg	update

BIOS - System ROM	Online ROM Flash Component for Windows x64 - HPE ProLiant ML150 Gen9 (P95) Servers	1	2.76_10-21-2019	Recommended	cp041800.exe	update
BIOS - System ROM	ROM Flash Firmware Package - HPE ProLiant DL560 Gen10/DL580 Gen10 (U34) Servers	4	2.36_07-16-2020	Optional	U34_2.36_07_16_2020.fwpkg	update
BIOS - System ROM	Online ROM Flash Component for Linux - HPE ProLiant DL385 Gen10 (A40) Servers	4	2.42_07-17-2020	Recommended	firmware-system-a40-2.42_2020_07_17-1.1.x86_64.rpm	update
BIOS - System ROM	Online ROM Flash Component for VMware - HPE ProLiant XL450 Gen9 (U21) Servers	1	2.76_10-21-2019	Recommended	CP041757.zip	update
BIOS - System ROM	Online ROM Flash Component for Windows x64 - HPE ProLiant DL325 Gen10 Plus (A43) Servers	23	1.30_07-18-2020	Recommended	cp041360.exe	new
BIOS - System ROM	Online ROM Flash Component for Windows x64 - HPE ProLiant DL380 Gen9/DL360 Gen9 (P89) Servers	1	2.76_10-21-2019	Recommended	cp041766.exe	update
BIOS - System ROM	ROM Flash Firmware Package - HPE ProLiant	1	2.18_06-24-2020	Optional	U48_2.18_06_24_2020.fwpkg	new

	MicroServer Gen10 Plus (U48) Servers					
BIOS - System ROM	ROM Flash Firmware Package - HPE ProLiant DL380 Gen10 (U30) Servers	10	2.36_07- 16-2020	Optional	U30_2.36_07- 16_2020.fwpk g	update
BIOS - System ROM	Online ROM Flash Component for Linux - HPE ProLiant ML350 Gen10 (U41) Servers	3	2.36_07- 16-2020	Optional	firmware- system-u41- 2.36_2020_07- 16- 1.1.x86_64.rp m	update
BIOS - System ROM	Online ROM Flash Component for VMware ESXi- HPE ProLiant XL230a/XL250a Gen9 (U13) Servers	1	2.76_10- 21-2019	Recommended	CP041763.zip	update
BIOS - System ROM	Online ROM Flash Component for Windows x64 - HPE ProLiant DL160 Gen10/DL180 Gen10 (U31) Servers	4	2.36_07- 16-2020	Optional	cp044662.exe	new
BIOS - System ROM	ROM Flash Universal Firmware Package - HPE ProLiant DL325 Gen10 Plus (A43) Servers	21	1.30_07- 18-2020	Recommended	A43_1.30_07- 18_2020.fwpk g	new
BIOS - System ROM	Online ROM Flash Component for Linux - HPE ProLiant DL120 Gen9 (P86) Servers	1	2.76_10- 21-2019	Recommended	firmware- system-p86- 2.76_2019_10- 21- 1.1.i386.rpm	update

BIOS - System ROM	Online ROM Flash Component for Windows x64 - HPE ProLiant DL160 Gen9/DL180 Gen9 (U20) Servers	1	2.76_10-21-2019	Recommended	cp041772.exe	update
BIOS - System ROM	Online ROM Flash Component for VMware - HPE ProLiant EC200a (U26) Server/HPE ProLiant Thin Micro TM200 (U26) Server	4	2.66_07-19-2019	Recommended	CP040773.zip	update
BIOS - System ROM	Online ROM Flash Component for Windows x64 - HPE ProLiant DL120 Gen9 (P86) Servers	1	2.76_10-21-2019	Recommended	cp041778.exe	update
BIOS - System ROM	Online ROM Flash Component for Linux - HPE ProLiant ML350 Gen9 (P92) Servers	2	2.76_10-21-2019	Recommended	firmware-system-p92-2.76_2019_10_21-1.1.i386.rpm	update
BIOS - System ROM	Online ROM Flash Component for Linux - HPE ProLiant DL160 Gen9/DL180 Gen9 (U20) Servers	1	2.76_10-21-2019	Recommended	firmware-system-u20-2.76_2019_10_21-1.1.i386.rpm	update
BIOS - System ROM	Online ROM Flash Component for Linux - HPE ProLiant EC200a (U26) Server/HPE ProLiant Thin Micro TM200 (U26) Server	5	2.66_07-19-2019	Recommended	firmware-system-u26-2.66_2019_07_19-1.1.i386.rpm	update

BIOS - System ROM	Online ROM Flash Component for Windows x64 - HPE ProLiant XL170r/XL190r Gen9 (U14) Servers	1	2.76_10-21-2019	Recommended	cp041758.exe	update
BIOS - System ROM	Online ROM Flash Component for Windows x64 - HPE ProLiant XL230k Gen10 (U37) Server	5	2.36_07-16-2020	Optional	cp044284.exe	update
BIOS - System ROM	Online ROM Flash Component for Windows x64 - HPE ProLiant XL225n Gen10 Plus (A46) Server	20	1.30_07-18-2020	Recommended	cp041721.exe	new
BIOS - System ROM	Online ROM Flash Component for Linux - HPE ProLiant XL225n Gen10 Plus (A46) Servers	20	1.30_07-18-2020	Recommended	firmware-system-a46-1.30_2020_07_18-1.1.x86_64.rpm	new
BIOS - System ROM	Online ROM Flash Component for Linux - HPE Apollo 6500 Gen10/HPE ProLiant XL270d Gen10 (U45) Servers	4	2.36_07-16-2020	Optional	firmware-system-u45-2.36_2020_07_16-1.1.x86_64.rpm	update
BIOS - System ROM	Online ROM Flash Component for Windows x64 - HPE ProLiant DL20 Gen10 (U43) Servers	1	2.18_06-24-2020	Optional	cp044713.exe	update
BIOS - System ROM	Online ROM Flash Component for Windows x64 - HPE ProLiant	3	2.36_07-16-2020	Optional	cp044686.exe	update

	ML350 Gen10 (U41) Servers					
Driver - Network	HPE Blade Intel ixgbe Drivers for Red Hat Enterprise Linux 8	3	5.6.4-1 (B)	Optional	kmod-hp-ixgbe_bl-5.6.4-1.rhel8u0.x86_64.rpm	new
Driver - Network	HPE Blade Intel ixgbevf Drivers for SUSE Linux Enterprise Server 15	4	4.6.2-1 (B)	Optional	hp-ixgbevf_bl-kmp-default-4.6.2_k4.12.14_195-1.sles15sp1.x86_64.rpm hp-ixgbevf_bl-kmp-default-4.6.2_k4.12.14_23-1.sles15sp0.x86_64.rpm	new
Driver - Network	HPE Intel igbn Driver for VMware vSphere 6.7	19	2019.12.20	Optional	cp040829.zip	update
Driver - Network	HPE Emulex 10/20GbE Drivers for Red Hat Enterprise Linux 8	2	12.0.128 0.17-1 (B)	Optional	kmod-be2net-12.0.1280.17-1.rhel8u0.x86_64.rpm	new
Driver - Network	HPE Intel i40en Driver for VMware vSphere 7.0	15	2020.05.29	Optional	cp041295.zip	new
Driver - Network	HPE QLogic NX2 10/20 GbE Multifunction Driver for VMware vSphere 6.7	15	2020.09.14	Optional	cp042873.zip	update
Driver - Network	HPE Blade Emulex 10/20GbE iSCSI Drivers for SUSE Linux Enterprise Server 15	6	12.0.125 9.0-1	Optional	be2iscsi_bl-kmp-default-12.0.1259.0_k4.12.14_23-1.sles15sp0.x86_64.rpm be2iscsi_bl-kmp-default-12.0.1259.0_k4.12.14_195-	new

					1.sles15sp1.x86_64.rpm	
Driver - Network	HPE Blade Intel ixgbe Drivers for Red Hat Enterprise Linux 7	4	5.6.4-1 (B)	Optional	kmod-hp-ixgbe_bl-5.6.4-1.rhel7u6.x86_64.rpm kmod-hp-ixgbe_bl-5.6.4-1.rhel7u7.x86_64.rpm	new
Driver - Network	HPE Mellanox RoCE (RDMA over Converged Ethernet) Driver for Mellanox ConnectX-4, ConnectX-5 and ConnectX-6 Adapters for SUSE LINUX Enterprise Server 12 SP4 (AMD64/EM64T)	8	5.0	Recommended	mlnx-ofa_kernel-5.0-OFED.5.0.2.1.8.1.g5f67178.sles12sp4.x86_64.rpm mlnx-ofa_kernel-kmp-default-5.0_k4.12.14_94.41-OFED.5.0.2.1.8.1.g5f67178.sles12sp4.x86_64.rpm	new
Driver - Network	HPE Intel ixS Driver for Windows Server 2012 R2	6	3.14.214.0	Optional	cp042030.exe	update
Driver - Network	HPE Blade QLogic NX2 10/20 GbE Multifunction Drivers for Red Hat Enterprise Linux 7	5	7.14.63.1-1 (B)	Optional	kmod-netxtreme2_bl-7.14.63.1-1.rhel7u7.x86_64.rpm kmod-netxtreme2_bl-7.14.63.1-1.rhel7u6.x86_64.rpm	new
Driver - Network	HPE Blade Emulex 10/20GbE Drivers for SUSE Linux Enterprise Server 12	6	12.0.126.1.0-1	Optional	be2net_bl-kmp-default-12.0.1261.0_k4.12.14_94.41-1.sles12sp4.x86_64.rpm be2net_bl-	new

					kmp-default-12.0.1261.0_k4.4.103_6.38-1.sles12sp3MU5.x86_64.rpm	
Driver - Network	HPE Mellanox RoCE (RDMA over Converged Ethernet) Driver for Red Hat Enterprise Linux 7 Update 7 (x86_64)	2	4.9	Recommended	kmod-mlnx-ofa_kernel-4.9-OFED.4.9.0.1.7.1.gd3d963b.rhel7u7.x86_64.rpm mlnx-ofa_kernel-4.9-OFED.4.9.0.1.7.1.gd3d963b.rhel7u7.x86_64.rpm	new
Driver - Network	HPE Broadcom NetXtreme-E RoCE Library for SUSE Linux Enterprise Server 12 SP4	9	216.0.88.3	Optional	libbnxt_re-216.0.88.3-sles12sp4.x86_64.rpm	new
Driver - Network	HPE Blade Emulex 10/20GbE Drivers for Red Hat Enterprise Linux 7	5	12.0.1261.0-1	Optional	kmod-be2net_bl-12.0.1261.0-1.rhel7u6.x86_64.rpm kmod-be2net_bl-12.0.1261.0-1.rhel7u7.x86_64.rpm	new
Driver - Network	HPE Intel ixS Driver for Windows Server 2019	9	4.1.197.0	Optional	cp042032.exe	new
Driver - Network	HPE Intel ixgben Driver for VMware vSphere 6.7	10	2020.09.14	Optional	cp042680.zip	update
Driver - Network	HPE Intel iavf Driver for	39	1.7.119.0	Optional	cp040867.exe	update

	Windows Server 2012 R2					
Driver - Network	HPE Broadcom NetXtreme-E Drivers for Red Hat Enterprise Linux 7	9	1.10.1-216.0.169.4	Optional	kmod-bnxt_en-1.10.1-216.0.169.4.rhel7u8.x86_64.rpm kmod-bnxt_en-1.10.1-216.0.169.4.rhel7u7.x86_64.rpm	update
Driver - Network	HPE Broadcom NX1 1Gb Driver for Windows Server x64 Editions	7	214.0.0.4	Optional	cp043306.exe	update
Driver - Network	HPE QLogic FastLinQ 10/25/50 GbE Drivers for SUSE Linux Enterprise Server 12 x86_64	16	8.50.25.0-1	Optional	qlgc-fastlinq-kmp-default-8.50.25.0_k4.12.14_120-1.sles12sp5.x86_64.rpm qlgc-fastlinq-kmp-default-8.50.25.0_k4.12.14_94.41-1.sles12sp4.x86_64.rpm	update
Driver - Network	HPE Blade QLogic NX2 10/20 GbE Multifunction Driver for VMware vSphere 7.0	15	2020.06.01	Optional	cp041436.zip	new
Driver - Network	HPE Intel i40ea Driver for Windows Server 2016	11	1.12.171.0	Optional	cp043120.exe	update
Driver - Network	HPE QLogic NX2 10/20 GbE Multifunction Driver for VMware vSphere 6.5	15	2020.09.14	Optional	cp042872.zip	update

Driver - Network	HPE Intel igb Drivers for SUSE Linux Enterprise Server 12 x86_64	24	6.2.3-1	Optional	hp-igb-kmp-default-6.2.3_k4.12.14_94.41-1.sles12sp4.x86_64.rpm hp-igb-kmp-default-6.2.3_k4.12.14_120-1.sles12sp5.x86_64.rpm	update
Driver - Network	HPE Blade QLogic NX2 iSCSI Offload IO Daemon for SUSE Linux Enterprise Server 15 SP0	4	2.11.5.13-3 (B)	Optional	iscsiuio_bl-2.11.5.13-3.sles15sp0.x86_64.rpm	new
Driver - Network	HPE Intel ixS Driver for Windows Server 2016	8	4.1.199.0	Optional	cp042031.exe	update
Driver - Network	HPE Broadcom tg3 Ethernet Drivers for SUSE Linux Enterprise Server 12 x86_64	6	3.138b-2	Optional	tg3-kmp-default-3.138b_k4.12.14_94.41-2.sles12sp4.x86_64.rpm tg3-kmp-default-3.138b_k4.12.14_120-2.sles12sp5.x86_64.rpm	update
Driver - Network	HPE Emulex 10/20GbE Drivers for Red Hat Enterprise Linux 7 x86_64	2	12.0.1280.17-1 (B)	Optional	kmod-be2net-12.0.1280.17-1.rhel7u7.x86_64.rpm	update
Driver - Network	HPE Intel igbn Driver for VMware vSphere 6.5	24	2019.12.20	Optional	cp040825.zip	update

Driver - Network	HPE Emulex 10/20GbE iSCSI Drivers for SUSE Linux Enterprise Server 12 x86_64	1	12.0.1259.0-1 (B)	Optional	be2iscsi-kmp-default-12.0.1259.0_k4.12.14_94.41-1.sles12sp4.x86_64.rpm	update
Driver - Network	HPE QLogic FastLinQ Open-iSCSI Driver for SUSE Linux Enterprise Server 15 SP0	35	2.0-873.113-1 (D)	Optional	qlgc-open-iscsi-2.0_873.113.sles15sp0-1.x86_64.rpm	update
Driver - Network	HPE Blade Intel ixgben Driver for VMware vSphere 6.5	9	2019.12.20	Optional	cp039952.zip	new
Driver - Network	HPE Intel iavf Driver for Windows Server 2016	38	1.7.119.0	Optional	cp040868.exe	update
Driver - Network	HPE Intel ixn Driver for Windows Server 2016	8	4.1.199.0	Optional	cp042028.exe	update
Driver - Network	HPE Intel i40en Driver for VMware vSphere 6.5	14	2020.09.14	Optional	cp042675.zip	update
Driver - Network	HPE Intel ixgben Driver for VMware vSphere 6.5	10	2020.09.14	Optional	cp042679.zip	update
Driver - Network	HPE Emulex 10/20 GbE iSCSI Driver for Windows Server 2012 R2	1	12.0.117.1.0 (C)	Optional	cp044560.exe	update
Driver - Network	HPE Intel E1R Driver for Windows Server 2012 R2	20	12.14.8.1	Optional	cp040854.exe	update

Driver - Network	HPE Blade QLogic NX2 10/20 GbE Multifunction Drivers for SUSE Linux Enterprise Server 15	5	7.14.63.1-1 (B)	Optional	netxtreme2_bl-kmp-default-7.14.63.1_k4.1_2.14_195-1.sles15sp1.x86_64.rpm netxtreme2_bl-kmp-default-7.14.63.1_k4.1_2.14_23-1.sles15sp0.x86_64.rpm	new
Driver - Network	HPE QLogic FastLinQ Open-iSCSI Driver for SUSE Linux Enterprise Server 15 SP1	21	2.0-873.113-1	Optional	qlgc-open-iscsi-2.0_873.113.sles15sp1-1.x86_64.rpm	new
Driver - Network	HPE Mellanox CX4LX and CX5 Driver for Microsoft Windows Server 2012 R2	9	2.40.225.11.0	Optional	cp042797.exe	update
Driver - Network	HPE Mellanox RoCE (RDMA over Converged Ethernet) Driver for Mellanox ConnectX-4, ConnectX-5 and ConnectX-6 Adapters for Red Hat Enterprise Linux 7 Update 8 (x86_64)	5	5.0	Recommended	mlnx-ofa_kernel-5.0-OFED.5.0.2.1.8.1.g5f67178.rhel7u8.x86_64.rpm kmod-mlnx-ofa_kernel-5.0-OFED.5.0.2.1.8.1.g5f67178.rhel7u8.x86_64.rpm	new
Driver - Network	HPE Blade Emulex 10/20GbE iSCSI Driver for Windows Server 2012 R2	10	12.0.117.1.0	Optional	cp039930.exe	new
Driver - Network	HPE Intel ixgben Driver for VMware vSphere 7.0	21	2020.05.29	Optional	cp041297.zip	new

Driver - Network	HPE Intel ixn Driver for Windows Server 2012 R2	18	3.14.214.0	Optional	cp042027.exe	update
Driver - Network	HPE Blade Emulex 10/20GbE iSCSI Drivers for SUSE Linux Enterprise Server 12	6	12.0.1259.0-1	Optional	be2iscsi_bl-kmp-default-12.0.1259.0_k4.4.103_6.38-1.sles12sp3MU5.x86_64.rpm be2iscsi_bl-kmp-default-12.0.1259.0_k4.12.14_94.41-1.sles12sp4.x86_64.rpm	new
Driver - Network	HPE Emulex 10/20 GbE Driver for Windows Server 2019	4	12.0.1195.0 (C)	Optional	cp044542.exe	update
Driver - Network	HPE Emulex 10/20 GbE iSCSI Driver for Windows Server 2019	2	12.0.1171.0 (C)	Optional	cp044562.exe	update
Driver - Network	HPE Intel iavf Drivers for SUSE Linux Enterprise Server 15	24	3.9.5-1	Optional	hp-iavf-kmp-default-3.9.5_k4.12.14_23-1.sles15sp0.x86_64.rpm hp-iavf-kmp-default-3.9.5_k4.12.14_195-1.sles15sp1.x86_64.rpm	update
Driver - Network	HPE Blade QLogic NX2 iSCSI Offload IO Daemon for SUSE Linux Enterprise Server 15 SP1	4	2.11.5.13-3 (B)	Optional	iscsiuio_bl-2.11.5.13-3.sles15sp1.x86_64.rpm	new

Driver - Network	HPE Intel iavf Driver for Windows Server 2019	35	1.7.119.0	Optional	cp040869.exe	new
Driver - Network	HPE Mellanox RoCE (RDMA over Converged Ethernet) Driver for Mellanox ConnectX-4, ConnectX-5 and ConnectX-6 Adapters for Red Hat Enterprise Linux 8 Update 2 (x86_64)	6	5.0	Recommended	mlnx-ofa_kernel-5.0-OFED.5.0.2.1.8.1.g5f67178.2.rhel8u2.x86_64.rpm kmod-mlnx-ofa_kernel-5.0-OFED.5.0.2.1.8.1.g5f67178.rhel8u2.x86_64.rpm	new
Driver - Network	HPE Blade Emulex 10/20GbE Driver for VMware vSphere 6.5	4	2020.03.09	Optional	cp042919.zip	new
Driver - Network	HPE Intel ixgbevf Drivers for SUSE Linux Enterprise Server 12 x86_64	27	4.7.1-1	Optional	hp-ixgbevf-kmp-default-4.7.1_k4.12.14_94.41-1.sles12sp4.x86_64.rpm hp-ixgbevf-kmp-default-4.7.1_k4.12.14_120-1.sles12sp5.x86_64.rpm	update
Driver - Network	HPE Blade Emulex 10/20GbE Driver for Windows Server 2012 R2	13	12.0.119.5.0	Optional	cp039927.exe	new
Driver - Network	HPE Blade Intel ixgbevf Drivers for SUSE Linux Enterprise Server 12	4	4.6.2-1 (B)	Optional	hp-ixgbevf-bl-kmp-default-4.6.2_k4.4.73_5-1.sles12sp3.x86_64.rpm hp-ixgbevf-bl-kmp-default-	new

					4.6.2_k4.12.14_94.41-1.sles12sp4.x86_64.rpm	
Driver - Network	nmlx5_en Driver Component for VMware 6.7	6	2020.03.09	Recommended	cp043197.zip	new
Driver - Network	HPE Blade QLogic NX2 iSCSI Offload IO Daemon for Red Hat Enterprise Linux 7 Update 7	4	2.11.5.13-3 (B)	Optional	iscsiuio_bl-2.11.5.13-3.rhel7u7.x86_64.rpm	new
Driver - Network	HPE Mellanox RoCE (RDMA over Converged Ethernet) Driver for Mellanox ConnectX-4, ConnectX-5 and ConnectX-6 Adapters for SUSE LINUX Enterprise Server 15 SP1 (AMD64/EM64T)	8	5.0	Recommended	mlnx-ofa_kernel-5.0-OFED.5.0.2.1.8.1.g5f67178.sles15sp1.x86_64.rpm mlnx-ofa_kernel-kmp-default-5.0_k4.12.14_195-OFED.5.0.2.1.8.1.g5f67178.sles15sp1.x86_64.rpm	new
Driver - Network	HPE Emulex 10/20 GbE Driver for VMware vSphere 6.5	2	2020.09.14	Optional	cp044545.zip	update
Driver - Network	HPE Intel i40eb Driver for Windows Server 2019	9	1.12.171.0	Optional	cp043238.exe	new
Driver - Network	HPE Broadcom NetXtreme-E Driver for Windows Server 2016	13	216.0.143.3	Optional	cp043303.exe	update
Driver - Network	HPE Mellanox CX3 Driver for	14	5.35.12978.0 (B)	Optional	cp040882.exe	update

	Windows Server 2012 R2					
Driver - Network	HPE Blade QLogic NX2 10/20 GbE Multifunction Drivers for Red Hat Enterprise Linux 8	5	7.14.63.1-1 (B)	Optional	kmod-netxtreme2_bl-7.14.63.1-1.rhel8u0.x86_64.rpm	new
Driver - Network	HPE Blade Intel ixgbe Drivers for SUSE Linux Enterprise Server 12	4	5.6.4-1 (B)	Optional	hp-ixgbe_bl-kmp-default-5.6.4_k4.4.73_5-1.sles12sp3.x86_64.rpm hp-ixgbe_bl-kmp-default-5.6.4_k4.12.14_94.41-1.sles12sp4.x86_64.rpm	new
Driver - Network	HPE Emulex 10/20GbE iSCSI Drivers for Red Hat Enterprise Linux 7 x86_64	1	12.0.1259.0-1 (B)	Optional	kmod-be2iscsi-12.0.1259.0-1.rhel7u7.x86_64.rpm	update
Driver - Network	HPE Intel i40ea Driver for Windows Server 2012 R2	8	1.12.171.0	Optional	cp043119.exe	update
Driver - Network	HPE QLogic FastLinQ 10/25/50 GbE Drivers for Red Hat Enterprise Linux 8	29	8.50.25.0-1	Optional	kmod-qlgc-fastlinq-8.50.25.0-1.rhel8u1.x86_64.rpm kmod-qlgc-fastlinq-8.50.25.0-1.rhel8u0.x86_64.rpm	new
Driver - Network	HPE Intel ixn Driver for Windows Server 2019	8	4.1.197.0	Optional	cp042029.exe	new

Driver - Network	HPE Blade Emulex 10/20GbE Driver for VMware vSphere 6.7	5	2020.03.09	Optional	cp042920.zip	new
Driver - Network	HPE Mellanox MFT Driver and Firmware Tools for Red Hat Enterprise Linux 7 Update 8 (x86_64)	3	4.14	Optional	mft-4.14.0-105.rhel7u8.x86_64.rpm kmod-kernel-mft-mlnx-4.14.0-1.rhel7u8.x86_64.rpm	new
Driver - Network	HPE QLogic iSCSI Offload IO Daemon for SUSE Linux Enterprise Server 12 SP4	18	2.11.5.13-3 (B)	Optional	iscsiuio-2.11.5.13-3.sles12sp4.x86_64.rpm	new
Driver - Network	HPE Broadcom NetXtreme-E Driver for Windows Server 2012 R2	10	214.0.247.1	Optional	cp041785.exe	update
Driver - Network	Mellanox CX5 and CX6DX Driver for Windows Server 2019	24	2.40.22511.0	Optional	cp043354.exe	new
Driver - Network	HPE QLogic iSCSI Offload IO Daemon for Red Hat Enterprise Linux 7 Update 7	7	2.11.5.13-3	Optional	iscsiuio-2.11.5.13-3.rhel7u7.x86_64.rpm	new
Driver - Network	HPE Intel vxs Driver for Windows Server 2016	8	2.1.192.0	Optional	cp042037.exe	new
Driver - Network	HPE QLogic FastLinQ Open-iSCSI Driver for SUSE Linux	37	2.0-873.113-1 (D)	Optional	qlgc-open-iscsi-2.0_873.113.sles12sp4-1.x86_64.rpm	new

	Enterprise Server 12 SP4					
Driver - Network	HPE Mellanox RoCE (RDMA over Converged Ethernet) Driver for SUSE LINUX Enterprise Server 15 SP1 (AMD64/EM64T)	3	4.9	Recommended	mlnx- ofa_kernel- kmp-default- 4.9_k4.12.14_ 195- OFED.4.9.0.1. 7.1.gd3d963b. sles15sp1.x86 _64.rpm mlnx- ofa_kernel-4.9- OFED.4.9.0.1. 7.1.gd3d963b. sles15sp1.x86 _64.rpm	new
Driver - Network	HPE Intel E1R Driver for Windows Server 2019	20	12.18.9.1	Optional	cp040874.exe	new
Driver - Network	HPE QLogic iSCSI Offload IO Daemon for Red Hat Enterprise Linux 8 Update 1	14	2.11.5.13 -3	Optional	iscsiuio- 2.11.5.13- 3.rhel8u1.x86_ 64.rpm	new
Driver - Network	HPE QLogic NX2 10/20 GbE Multifunction Drivers for SUSE Linux Enterprise Server 15	18	7.14.70-1	Optional	netxtreme2- kmp-default- 7.14.70.1_k5.3 .18_22- 1.sles15sp2.x8 6_64.rpm netxtreme2- kmp-default- 7.14.70_k4.12. 14_195- 1.sles15sp1.x8 6_64.rpm	update
Driver - Network	HPE Emulex 10/20GbE iSCSI Drivers for SUSE Linux Enterprise Server 15	1	12.0.125 9.0-1 (B)	Optional	be2iscsi-kmp- default- 12.0.1259.0_k 4.12.14_23- 1.sles15sp0.x8 6_64.rpm be2iscsi-kmp- default-	update

					12.0.1259.0_k 4.12.14_195- 1.sles15sp1.x8 6_64.rpm	
Driver - Network	HPE Mellanox RoCE (RDMA over Converged Ethernet) Driver for Red Hat Enterprise Linux 7 Update 8 (x86_64)	5	4.9	Recommended	kmod-mlx- ofa_kernel-4.9- OFED.4.9.0.1. 7.1.gd3d963b.r hel7u8.x86_64 .rpm mlx- ofa_kernel-4.9- OFED.4.9.0.1. 7.1.gd3d963b.r hel7u8.x86_64 .rpm	new
Driver - Network	HPE Broadcom NetXtreme-E Driver for Windows Server 2019	10	216.0.14 3.3	Optional	cp043304.exe	new
Driver - Network	HPE Broadcom NetXtreme-E RoCE Library for Red Hat Enterprise Linux 7 Update 7	9	216.0.88. 3	Optional	libbnxt_re- 216.0.88.3- rhel7u7.x86_6 4.rpm	new
Driver - Network	HPE Mellanox CX4LX and CX5 Driver for Microsoft Windows Server 2016	11	2.40.225 11.0	Optional	cp042798.exe	update
Driver - Network	HPE Intel ixgbe Drivers for SUSE Linux Enterprise Server 15	33	5.7.1-1	Optional	hp-ixgbe-kmp- default- 5.7.1_k4.12.14 _195- 1.sles15sp1.x8 6_64.rpm hp-ixgbe-kmp- default- 5.7.1_k4.12.14 _23- 1.sles15sp0.x8 6_64.rpm	update

Driver - Network	HPE Broadcom NetXtreme-E RoCE Library for Red Hat Enterprise Linux 8	12	216.0.88.3	Optional	libbnxt_re-216.0.88.3-rhel8u0.x86_64.rpm	new
Driver - Network	HPE Mellanox MFT Driver and Firmware Tools for SUSE Linux Enterprise Server 12 SP5 (AMD64/EM64T)	4	4.14	Optional	kernel-mft-mlnx-kmp-default-4.14.0_k4.12.1_4_120-1.sles12sp5.x86_64.rpm mft-4.14.0-105.1.sles12sp5.x86_64.rpm	new
Driver - Network	HPE QLogic FastLinQ Open-iSCSI Driver for Red Hat Enterprise Linux 7 Update 7	18	2.0-873.113-1	Optional	qlgc-open-iscsi-2.0_873.113.rhel7u7-1.x86_64.rpm	new
Driver - Network	HPE Mellanox RoCE (RDMA over Converged Ethernet) Driver for Red Hat Enterprise Linux 8 update 1 (x86_64)	2	4.9	Recommended	kmod-mlnx-ofa_kernel-4.9-OFED.4.9.0.1.7.1.gd3d963b.rhel8u1.x86_64.rpm mlnx-ofa_kernel-4.9-OFED.4.9.0.1.7.1.gd3d963b.rhel8u1.x86_64.rpm	new
Driver - Network	HPE Broadcom NetXtreme-E RoCE Library for SUSE Linux Enterprise Server 15 SP1	9	216.0.88.3	Optional	libbnxt_re-216.0.88.3-sles15sp1.x86_64.rpm	new
Driver - Network	HPE Blade QLogic NX2 10/20 GbE Multifunction Driver for VMware vSphere 6.7	11	2019.12.20	Optional	cp039955.zip	new

Driver - Network	HPE Intel iavf Drivers for Red Hat Enterprise Linux 8	24	3.9.5-1	Optional	kmod-hp-iavf-3.9.5-1.rhel8u1.x86_64.rpm kmod-hp-iavf-3.9.5-1.rhel8u0.x86_64.rpm	new
Driver - Network	HPE Intel i40e Drivers for Red Hat Enterprise Linux 7 x86_64	29	2.11.27-1	Optional	kmod-hp-i40e-2.11.27-1.rhel7u8.x86_64.rpm kmod-hp-i40e-2.11.27-1.rhel7u7.x86_64.rpm	update
Driver - Network	nmlx4_en Driver Component for VMware 6.5	3	2019.06.14	Recommended	cp040179.zip	update
Driver - Network	HPE Broadcom tg3 Ethernet Drivers for Red Hat Enterprise Linux 8	6	3.138b-1	Optional	kmod-tg3-3.138b-1.rhel8u0.x86_64.rpm kmod-tg3-3.138b-1.rhel8u1.x86_64.rpm	new
Driver - Network	HPE Intel ixgbevf Drivers for Red Hat Enterprise Linux 7 x86_64	1	4.7.1-1	Optional	kmod-hp-ixgbevf-4.7.1-1.rhel7u7.x86_64.rpm kmod-hp-ixgbevf-4.7.1-1.rhel7u8.x86_64.rpm	update
Driver - Network	HPE Intel i40eb Driver for Windows Server 2016	10	1.12.171.0	Optional	cp043236.exe	update
Driver - Network	HPE Blade Emulex 10/20GbE Driver for Windows Server 2019	13	12.0.119.5.0	Optional	cp039929.exe	new

Driver - Network	HPE QLogic FastLinQ 10/25/50 GbE Multifunction Driver for VMware vSphere 7.0	27	2020.05.29	Optional	cp041271.zip	new
Driver - Network	HPE QLogic FastLinQ 10/25/50 GbE Multifunction Driver for VMware vSphere 6.5	5	2020.09.14	Optional	cp044296.zip	update
Driver - Network	HPE Emulex 10/20GbE Drivers for SUSE Linux Enterprise Server 15	2	12.0.1280.17-1 (B)	Optional	be2net-kmp-default-12.0.1280.17_k4.12.14_195-1.sles15sp1.x86_64.rpm be2net-kmp-default-12.0.1280.17_k4.12.14_23-1.sles15sp0.x86_64.rpm	update
Driver - Network	HPE QLogic NX2 10/20 GbE Multifunction Drivers for Red Hat Enterprise Linux 8	17	7.14.70-1	Optional	kmod-netxtreme2-7.14.70-1.rhel8u0.x86_64.rpm kmod-netxtreme2-7.14.70-1.rhel8u1.x86_64.rpm	new
Driver - Network	HPE Intel vxn Driver for Windows Server 2016	10	2.1.192.0	Optional	cp042034.exe	update
Driver - Network	HPE Broadcom NetXtreme-E RoCE Library for SUSE Linux Enterprise Server 15	9	216.0.88.3	Optional	libbnxt_re-216.0.88.3-sles15sp0.x86_64.rpm	update

Driver - Network	HPE Blade Intel ixgbe Drivers for SUSE Linux Enterprise Server 15	4	5.6.4-1 (B)	Optional	hp-ixgbe_bl-kmp-default-5.6.4_k4.12.14_195-1.sles15sp1.x86_64.rpm hp-ixgbe_bl-kmp-default-5.6.4_k4.12.14_23-1.sles15sp0.x86_64.rpm	new
Driver - Network	HPE Intel i40en Driver for VMware vSphere 6.7	14	2020.09.14	Optional	cp042676.zip	update
Driver - Network	HPE Emulex 10/20 GbE Driver for Windows Server 2016	3	12.0.119 5.0 (C)	Optional	cp044541.exe	update
Driver - Network	HPE Broadcom tg3 Ethernet Drivers for Red Hat Enterprise Linux 7 x86_64	6	3.138b-1	Optional	kmod-tg3-3.138b-1.rhel7u7.x86_64.rpm kmod-tg3-3.138b-1.rhel7u8.x86_64.rpm	update
Driver - Network	HPE Blade Intel ixgben Driver for VMware vSphere 6.7	11	2019.12.20	Optional	cp039953.zip	new
Driver - Network	nmlx4_en driver component for VMware ESXi 6.7	3	2020.05.26	Recommended	cp035114.zip	new
Driver - Network	HPE Intel igb Drivers for Red Hat Enterprise Linux 7 x86_64	29	6.2.3-1	Optional	kmod-hp-igb-6.2.3-1.rhel7u7.x86_64.rpm kmod-hp-igb-6.2.3-1.rhel7u8.x86_64.rpm	update

Driver - Network	HPE Blade Emulex 10/20GbE iSCSI Driver for Windows Server 2019	13	12.0.117.1.0	Optional	cp039932.exe	new
Driver - Network	HPE Intel iavf Drivers for Red Hat Enterprise Linux 7 x86_64	26	3.9.5-1	Optional	kmod-hp-iavf-3.9.5-1.rhel7u8.x86_64.rpm kmod-hp-iavf-3.9.5-1.rhel7u7.x86_64.rpm	update
Driver - Network	HPE Intel ixgbe Drivers for SUSE Linux Enterprise Server 12 x86_64	31	5.7.1-1	Optional	hp-ixgbe-kmp-default-5.7.1_k4.12.14_94.41-1.sles12sp4.x86_64.rpm hp-ixgbe-kmp-default-5.7.1_k4.12.14_120-1.sles12sp5.x86_64.rpm	update
Driver - Network	HPE Blade Intel ixn Driver for Windows Server 2016	17	4.1.131.0	Optional	cp039940.exe	new
Driver - Network	HPE Broadcom NetXtreme-E RoCE Library for SUSE Linux Enterprise Server 12 SP5	9	216.0.88.3	Optional	libbnxt_re-216.0.88.3-sles12sp5.x86_64.rpm	new
Driver - Network	HPE Mellanox MFT Driver and Firmware Tools for Red Hat Enterprise Linux 7 Update 7 (x86_64)	4	4.14	Optional	mft-4.14.0-105.rhel7u7.x86_64.rpm kmod-kernel-mft-mlnx-4.14.0-1.rhel7u7.x86_64.rpm	new

Driver - Network	net-mst kernel module driver component for VMware ESXi 7.0	4	2020.05.20	Recommended	cp044401.zip	new
Driver - Network	HPE Blade Intel ixgbevf Drivers for Red Hat Enterprise Linux 8	4	4.6.2-1 (B)	Optional	kmod-hp-ixgbevf_bl-4.6.2-1.rhel8u0.x86_64.rpm	new
Driver - Network	HPE Blade QLogic NX2 iSCSI Offload IO Daemon for SUSE Linux Enterprise Server 12 SP4	4	2.11.5.13-3 (B)	Optional	iscsiuio_bl-2.11.5.13-3.sles12sp4.x86_64.rpm	new
Driver - Network	HPE Blade Intel vxn Driver for Windows Server 2019	19	2.1.138.0	Optional	cp039945.exe	new
Driver - Network	HPE Broadcom NetXtreme-E Drivers for SUSE Linux Enterprise Server 15	9	1.10.1-216.0.169.4	Optional	bnxt_en-kmp-default-1.10.1_k4.12.14_195-216.0.169.4.sles15sp1.x86_64.rpm bnxt_en-kmp-default-1.10.1_k4.12.14_23-216.0.169.4.sles15sp0.x86_64.rpm	update
Driver - Network	HPE Intel i40ea Driver for Windows Server 2019	12	1.12.171.0	Optional	cp043121.exe	new
Driver - Network	HPE Mellanox CX4LX and CX5 Driver for Microsoft Windows Server 2019	9	2.40.22511.0	Optional	cp042799.exe	new

Driver - Network	HPE Mellanox RoCE (RDMA over Converged Ethernet) Driver for Red Hat Enterprise Linux 8 update 2 (x86_64)	3	4.9	Recommended	kmod-mlnx-ofa_kernel-4.9-OFED.4.9.0.1.7.1.gd3d963b.rhel8u2.x86_64.rpm mlnx-ofa_kernel-4.9-OFED.4.9.0.1.7.1.gd3d963b.rhel8u2.x86_64.rpm	new
Driver - Network	net-mst kernel module driver component for VMware ESXi 6.5 and 6.7	11	2019.09.11	Recommended	cp041339.zip	update
Driver - Network	HPE Intel i40e Drivers for SUSE Linux Enterprise Server 12 x86_64	26	2.11.27-1	Optional	hp-i40e-kmp-default-2.11.27_k4.12.14_120-1.sles12sp5.x86_64.rpm hp-i40e-kmp-default-2.11.27_k4.12.14_94.41-1.sles12sp4.x86_64.rpm	update
Driver - Network	HPE Intel ixgbev Drivers for SUSE Linux Enterprise Server 15	1	4.7.1-1	Optional	hp-ixgbev-kmp-default-4.7.1_k4.12.14_23-1.sles15sp0.x86_64.rpm hp-ixgbev-kmp-default-4.7.1_k4.12.14_195-1.sles15sp1.x86_64.rpm	update
Driver - Network	HPE Broadcom NetXtreme-E RoCE Library for Red Hat Enterprise Linux 8 Update 1.	14	216.0.88.3	Optional	libbnxt_re-216.0.88.3-rhel8u1.x86_64.rpm	new

Driver - Network	HPE Intel ixgbe Drivers for Red Hat Enterprise Linux 8	31	5.7.1-1	Optional	kmod-hp-ixgbe-5.7.1-1.rhel8u0.x86_64.rpm kmod-hp-ixgbe-5.7.1-1.rhel8u1.x86_64.rpm	new
Driver - Network	HPE Mellanox RoCE (RDMA over Converged Ethernet) Driver for SUSE LINUX Enterprise Server 12 SP5 (AMD64/EM64T)	2	4.9	Recommended	mlnx-ofa_kernel-4.9-OFED.4.9.0.1.7.1.gd3d963b.sles12sp5.x86_64.rpm mlnx-ofa_kernel-kmp-default-4.9_k4.12.14_120-OFED.4.9.0.1.7.1.gd3d963b.sles12sp5.x86_64.rpm	new
Driver - Network	HPE QLogic FastLinQ 10/25/50 GbE Drivers for Windows Server x64 Editions	13	8.50.10.0	Optional	cp043122.exe	update
Driver - Network	HPE Blade QLogic NX2 iSCSI Offload IO Daemon for Red Hat Enterprise Linux 8 Update 0	4	2.11.5.13-3 (B)	Optional	iscsiuio_bl-2.11.5.13-3.rhel8u0.x86_64.rpm	new
Driver - Network	HPE Blade Intel vxn Driver for Windows Server 2016	12	2.0.210.0	Optional	cp039944.exe	new
Driver - Network	nmlx5_en Driver Component for VMware 7.0	3	2020.05.26	Recommended	cp043205.zip	new

Driver - Network	Intel i350 Driver for Windows Server 2016	6	12.15.18 4.7	Optional	cp041189.exe	new
Driver - Network	nmlx5_en Driver Component for VMware 6.5	6	2020.03. 09	Recommended	cp043371.zip	update
Driver - Network	HPE Mellanox MFT Driver and Firmware Tools for SUSE Linux Enterprise Server 12 SP4 (AMD64/EM64T)	3	4.14	Optional	kernel-mft- mlnx-kmp- default- 4.14.0_k4.12.1 4_94.41- 1.sles12sp4.x8 6_64.rpm mft-4.14.0- 105.sles12sp4. x86_64.rpm	new
Driver - Network	HPE Mellanox MFT Driver and Firmware Tools for SUSE Linux Enterprise Server 15 SP1 (AMD64/EM64T)	4	4.14	Optional	kernel-mft- mlnx-kmp- default- 4.14.0_k4.12.1 4_195- 1.sles15sp1.x8 6_64.rpm mft-4.14.0- 105.sles15sp1. x86_64.rpm	new
Driver - Network	HPE Broadcom NetXtreme-E Drivers for VMware vSphere 7.0	8	2020.09. 14	Optional	cp043308.zip	new
Driver - Network	HPE Blade Intel vxn Driver for Windows Server 2012 R2	16	1.0.16.1	Optional	cp039943.exe	new
Driver - Network	HPE Emulex 10/20 GbE iSCSI Driver for Windows Server 2016	1	12.0.117 1.0 (C)	Optional	cp044561.exe	update
Driver - Network	HPE Mellanox RoCE (RDMA over Converged	6	5.0	Recommended	kmod-mlnx- ofa_kernel-5.0- OFED.5.0.2.1.	new

	Ethernet) Driver for Mellanox ConnectX-4, ConnectX-5 and ConnectX-6 Adapters for Red Hat Enterprise Linux 8 Update 1 (x86_64)				8.1.g5f67178.rhel8u1.x86_64.rpm mlnx-ofa_kernel-5.0-OFED.5.0.2.1.8.1.g5f67178.rhel8u1.x86_64.rpm	
Driver - Network	HPE Mellanox RoCE (RDMA over Converged Ethernet) Driver for Mellanox ConnectX-4, ConnectX-5 and ConnectX-6 Adapters for Red Hat Enterprise Linux 7 Update 7 (x86_64)	8	5.0	Recommended	kmod-mlnx-ofa_kernel-5.0-OFED.5.0.2.1.8.1.g5f67178.rhel7u7.x86_64.rpm mlnx-ofa_kernel-5.0-OFED.5.0.2.1.8.1.g5f67178.rhel7u7.x86_64.rpm	new
Driver - Network	HPE Intel i40eb Driver for Windows Server 2012 R2	15	1.12.171.0	Optional	cp043237.exe	update
Driver - Network	HPE Intel vxn Driver for Windows Server 2012 R2	8	1.2.199.0	Optional	cp042033.exe	update
Driver - Network	Intel i350 Driver for Windows Server 2019	4	12.18.9.1	Optional	cp041190.exe	new
Driver - Network	HPE Emulex 10/20GbE iSCSI Driver for VMware vSphere 6.5	2	2020.09.14	Optional	cp044543.zip	update
Driver - Network	HPE Mellanox RoCE (RDMA over Converged Ethernet) Driver for Mellanox ConnectX-4, ConnectX-5 and ConnectX-6	8	5.0	Recommended	mlnx-ofa_kernel-5.0-OFED.5.0.2.1.8.1.g5f67178.1.sles12sp5.x86_64.rpm mlnx-ofa_kernel-	new

	Adapters for SUSE LINUX Enterprise Server 12 SP5 (AMD64/EM64T)				kmp-default- 5.0_k4.12.14_ 120- OFED.5.0.2.1. 8.1.g5f67178.s les12sp5.x86_ 64.rpm	
Driver - Network	HPE Mellanox MFT Driver and Firmware Tools for Red Hat Enterprise Linux 8 Update 1 (x86_64)	3	4.14	Optional	mft-4.14.0- 105.rhel8u1.x8 6_64.rpm kmod-kernel- mft-mlnx- 4.14.0- 1.rhel8u1.x86_ 64.rpm	new
Driver - Network	HPE QLogic FastLinQ 10/25/50 GbE Drivers for SUSE Linux Enterprise Server 15	17	8.50.25.0 -1	Optional	qlgc-fastlinq- kmp-default- 8.50.25.0_k4.1 2.14_195- 1.sles15sp1.x8 6_64.rpm qlgc-fastlinq- kmp-default- 8.50.25.1_k5.3 .18_22- 1.sles15sp2.x8 6_64.rpm	update
Driver - Network	HPE QLogic NX2 10/20 GbE Multifunction Drivers for Windows Server x64 Editions	13	7.13.187. 0	Optional	cp043244.exe	update
Driver - Network	Mellanox CX5 and CX6DX Driver for Windows Server 2016	12	2.40.225 11.0	Optional	cp043353.exe	new
Driver - Network	HPE Blade Intel ixn Driver for Windows Server 2012 R2	11	3.14.132. 0	Optional	cp039939.exe	new
Driver - Network	HPE QLogic NX2 10/20 GbE	17	7.14.70-1	Optional	netxtreme2- kmp-default-	update

	Multifunction Drivers for SUSE Linux Enterprise Server 12 x86_64				7.14.70_k4.12.14_120-1.sles12sp5.x86_64.rpm netxtreme2-kmp-default-7.14.70_k4.12.14_94.41-1.sles12sp4.x86_64.rpm	
Driver - Network	HPE Intel igb Drivers for Red Hat Enterprise Linux 8	26	6.2.3-1	Optional	kmod-hp-igb-6.2.3-1.rhel8u1.x86_64.rpm kmod-hp-igb-6.2.3-1.rhel8u0.x86_64.rpm	new
Driver - Network	HPE Blade Intel ixn Driver for Windows Server 2019	11	4.1.143.0	Optional	cp039941.exe	new
Driver - Network	HPE Intel ixgbe Drivers for Red Hat Enterprise Linux 7 x86_64	33	5.7.1-1	Optional	kmod-hp-ixgbe-5.7.1-1.rhel7u7.x86_64.rpm kmod-hp-ixgbe-5.7.1-1.rhel7u8.x86_64.rpm	update
Driver - Network	HPE Broadcom NetXtreme-E Drivers for VMware vSphere 6.7	10	2020.09.14	Optional	cp043311.zip	update
Driver - Network	HPE Intel i40e Drivers for Red Hat Enterprise Linux 8	28	2.11.27-1	Optional	kmod-hp-i40e-2.11.27-1.rhel8u0.x86_64.rpm kmod-hp-i40e-2.11.27-1.rhel8u1.x86_64.rpm	new

Driver - Network	HPE Intel vxn Driver for Windows Server 2019	9	2.1.191.0	Optional	cp042035.exe	new
Driver - Network	HPE Blade Intel ixgbev Drivers for Red Hat Enterprise Linux 7	4	4.6.2-1 (B)	Optional	kmod-hp-ixgbev_f_bl-4.6.2-1.rhel7u6.x86_64.rpm kmod-hp-ixgbev_f_bl-4.6.2-1.rhel7u7.x86_64.rpm	new
Driver - Network	HPE QLogic NX2 10/20 GbE Multifunction Driver for VMware vSphere 7.0	20	2020.05.29	Optional	cp041163.zip	new
Driver - Network	HPE QLogic FastLinQ 10/25/50 GbE Multifunction Driver for VMware vSphere 6.7	10	2020.09.14	Optional	cp044297.zip	update
Driver - Network	HPE Intel igbn Driver for VMware vSphere 7.0	21	2020.05.29	Optional	cp041296.zip	new
Driver - Network	HPE QLogic NX2 10/20 GbE Multifunction Drivers for Red Hat Enterprise Linux 7 x86_64	17	7.14.70-1	Optional	kmod-netxtreme2-7.14.70-1.rhel7u7.x86_64.rpm kmod-netxtreme2-7.14.70-1.rhel7u8.x86_64.rpm	update
Driver - Network	HPE Blade QLogic NX2 10/20 GbE Multifunction Driver for VMware vSphere 6.5	13	2019.12.20	Optional	cp039954.zip	new

Driver - Network	HPE Mellanox MFT Driver and Firmware Tools for Red Hat Enterprise Linux 8 Update 2 (x86_64)	4	4.14	Optional	mft-4.14.0-105.2.rhel8u2.x86_64.rpm kmod-kernel-mft-mlnx-4.14.0-1.rhel8u2.x86_64.rpm	new
Driver - Network	HPE Blade Emulex 10/20GbE Driver for Windows Server 2016	11	12.0.119.5.0	Optional	cp039928.exe	new
Driver - Network	HPE Mellanox RoCE (RDMA over Converged Ethernet) Driver for SUSE LINUX Enterprise Server 12 SP4 (AMD64/EM64T)	2	4.9	Recommended	mlnx-ofa_kernel-kmp-default-4.9_k4.12.14_94.41-OFED.4.9.0.1.7.1.gd3d963b.sles12sp4.x86_64.rpm mlnx-ofa_kernel-4.9-OFED.4.9.0.1.7.1.gd3d963b.sles12sp4.x86_64.rpm	new
Driver - Network	HPE Emulex 10/20 GbE Driver for VMware vSphere 6.7	2	2020.09.14	Optional	cp044546.zip	update
Driver - Network	HPE Emulex 10/20GbE iSCSI Driver for VMware vSphere 6.7	2	2020.09.14	Optional	cp044544.zip	update
Driver - Network	HPE Broadcom NetXtreme-E Drivers for SUSE Linux Enterprise Server 12 x86_64	9	1.10.1-216.0.16.9.4	Optional	bnxt_en-kmp-default-1.10.1_k4.12.14_120-216.0.169.4.sles12sp5.x86_64.rpm bnxt_en-kmp-default-1.10.1_k4.12.1	update

					4_94.41-216.0.169.4.sles12sp4.x86_64.rpm	
Driver - Network	HPE Intel ixgbevf Drivers for Red Hat Enterprise Linux 8	24	4.7.1-1	Optional	kmod-hp-ixgbevf-4.7.1-1.rhel8u0.x86_64.rpm kmod-hp-ixgbevf-4.7.1-1.rhel8u1.x86_64.rpm	new
Driver - Network	HPE Intel E1R Driver for Windows Server 2016	17	12.15.184.7	Optional	cp040879.exe	update
Driver - Network	HPE Intel igb Drivers for SUSE Linux Enterprise Server 15	24	6.2.3-1	Optional	hp-igb-kmp-default-6.2.3_k4.12.14_23-1.sles15sp0.x86_64.rpm hp-igb-kmp-default-6.2.3_k4.12.14_195-1.sles15sp1.x86_64.rpm	update
Driver - Network	HPE QLogic FastLinQ Open-iSCSI Driver for Red Hat Enterprise Linux 8 Update 0	21	2.0-873.113-1	Optional	qlgc-open-iscsi-2.0_873.113.rhel8u0-1.x86_64.rpm	new
Driver - Network	HPE QLogic FastLinQ 10/25/50 GbE Drivers for Red Hat Enterprise Linux 7 x86_64	15	8.50.25.0-1	Optional	kmod-qlgc-fastlinq-8.50.25.0-1.rhel7u8.x86_64.rpm kmod-qlgc-fastlinq-8.50.25.0-1.rhel7u7.x86_64.rpm	update

Driver - Network	HPE Blade Emulex 10/20GbE Drivers for SUSE Linux Enterprise Server 15	6	12.0.126 1.0-1	Optional	be2net_bl-kmp-default-12.0.1261.0_k4.12.14_195-1.sles15sp1.x86_64.rpm be2net_bl-kmp-default-12.0.1261.0_k4.12.14_23-1.sles15sp0.x86_64.rpm	new
Driver - Network	HPE Blade Emulex 10/20GbE iSCSI Driver for VMware vSphere 6.7	7	2019.12.20	Optional	cp039935.zip	new
Driver - Network	HPE Broadcom NetXtreme-E Drivers for VMware vSphere 6.5	10	2020.09.14	Optional	cp043310.zip	update
Driver - Network	HPE Blade QLogic NX2 10/20 GbE Multifunction Drivers for Windows Server x64 Editions	2	7.13.171.0 (D)	Optional	cp045325.exe	new
Driver - Network	HPE Broadcom tg3 Ethernet Drivers for SUSE Linux Enterprise Server 15	8	3.138a-2	Optional	tg3-kmp-default-3.138a_k4.12.14_23-2.sles15sp0.x86_64.rpm tg3-kmp-default-3.138a_k4.12.14_195-2.sles15sp1.x86_64.rpm	update
Driver - Network	HPE Emulex 10/20 GbE Driver for Windows Server 2012 R2	3	12.0.119 5.0 (C)	Optional	cp044540.exe	update

Driver - Network	HPE QLogic iSCSI Offload IO Daemon for SUSE Linux Enterprise Server 15 SP0	27	2.11.5.13-3 (B)	Optional	iscsiuio-2.11.5.13-3.sles15sp0.x86_64.rpm	update
Driver - Network	HPE QLogic iSCSI Offload IO Daemon for SUSE Linux Enterprise Server 15 SP1	7	2.11.5.13-3	Optional	iscsiuio-2.11.5.13-3.sles15sp1.x86_64.rpm	new
Driver - Network	Broadcom NetXtreme-E Driver for Windows Server 2016	20	216.0.143.3	Optional	cp043516.exe	new
Driver - Network	HPE Emulex 10/20GbE Drivers for SUSE Linux Enterprise Server 12 x86_64	2	12.0.1280.17-1 (B)	Optional	be2net-kmp-default-12.0.1280.17_k4.12.14_94.41-1.sles12sp4.x86_64.rpm	update
Driver - Network	HPE Intel vxs Driver for Windows Server 2019	11	2.1.191.0	Optional	cp042038.exe	new
Driver - Network	HPE Blade Intel ixgben Driver for VMware vSphere 7.0	13	2020.06.01	Optional	cp041435.zip	new
Driver - Network	HPE Intel vxs Driver for Windows Server 2012 R2	10	1.2.199.0	Optional	cp042036.exe	new
Driver - Network	HPE Blade Emulex 10/20GbE iSCSI Drivers for Red Hat Enterprise Linux 7	6	12.0.1259.0-1	Optional	kmod-be2iscsi_bl-12.0.1259.0-1.rhel7u6.x86_64.rpm kmod-be2iscsi_bl-	new

					12.0.1259.0-1.rhel7u7.x86_64.rpm	
Driver - Network	HPE Mellanox CX3 Driver for Windows Server 2016	15	5.35.12978.0 (D)	Optional	cp040866.exe	update
Driver - Network	Broadcom NetXtreme-E Driver for Windows Server 2019	25	216.0.143.3	Optional	cp043517.exe	new
Driver - Network	HPE QLogic iSCSI Offload IO Daemon for Red Hat Enterprise Linux 8 Update 0	11	2.11.5.13-3	Optional	iscsiuio-2.11.5.13-3.rhel8u0.x86_64.rpm	new
Driver - Network	HPE Blade QLogic NX2 10/20 GbE Multifunction Drivers for SUSE Linux Enterprise Server 12	5	7.14.63.1-1 (B)	Optional	netxtreme2_bl-kmp-default-7.14.63.1_k4.4.73_5-1.sles12sp3.x86_64.rpm netxtreme2_bl-kmp-default-7.14.63.1_k4.12.14_94.41-1.sles12sp4.x86_64.rpm	new
Driver - Network	HPE Broadcom NetXtreme-E RoCE Library for Red Hat Enterprise Linux 7 Update 8	9	216.0.88.3	Optional	libbnxt_re-216.0.88.3-rhel7u8.x86_64.rpm	new
Driver - Network	HPE Intel i40e Drivers for SUSE Linux Enterprise Server 15	26	2.11.27-1	Optional	hp-i40e-kmp-default-2.11.27_k4.12.14_23-1.sles15sp0.x86_64.rpm hp-i40e-kmp-default-2.11.27_k4.12.	update

					14_195-1.sles15sp1.x86_64.rpm	
Driver - Network	HPE Intel iavf Drivers for SUSE Linux Enterprise Server 12 x86_64	24	3.9.5-1	Optional	hp-iavf-kmp-default-3.9.5_k4.12.14_94.41-1.sles12sp4.x86_64.rpm hp-iavf-kmp-default-3.9.5_k4.12.14_120-1.sles12sp5.x86_64.rpm	update
Driver - Network	HPE Emulex 10/20GbE iSCSI Drivers for Red Hat Enterprise Linux 8	1	12.0.1259.0-1 (B)	Optional	kmod-be2iscsi-12.0.1259.0-1.rhel8u0.x86_64.rpm	new
Driver - Network	Marvell FastLinQ 10/25/50 GbE Drivers for Windows Server x64 Editions	12	8.50.10.0	Optional	cp043118.exe	new
Driver - Network	HPE Blade Emulex 10/20GbE iSCSI Driver for Windows Server 2016	8	12.0.1171.0	Optional	cp039931.exe	new
Driver - Network	HPE Broadcom NetXtreme-E Drivers for Red Hat Enterprise Linux 8	9	1.10.1-216.0.169.4	Optional	kmod-bnxt_en-1.10.1-216.0.169.4.rhel8u1.x86_64.rpm kmod-bnxt_en-1.10.1-216.0.169.4.rhel8u0.x86_64.rpm	new
Driver - Network	HPE Blade Emulex 10/20GbE iSCSI	8	2019.12.20	Optional	cp039936.zip	new

	Driver for VMware vSphere 6.5					
Driver - Storage Controller	HPE ProLiant Gen10 and Gen10Plus Smart Array Controller (64-bit) Driver for Red Hat Enterprise Linux 8 (64-bit)	2	1.2.14-016	Recommended	kmod-smartpqi-1.2.14-016.rhel8u1.x86_64.rpm kmod-smartpqi-1.2.14-016.rhel8u2.x86_64.rpm	new
Driver - Storage Controller	HPE Smart Array P824i-p MR controller (64-bit) Driver for vSphere 6.7 (Driver Component)	4	2019.12.13	Recommended	cp042807.zip	new
Driver - Storage Controller	HPE H2xx SAS/SATA Host Bus Adapter Driver for Microsoft Windows Server 2012 R2 64-bit Editions	3	2.68.64.1 (B)	Optional	cp032453.exe	same
Driver - Storage Controller	HPE Dynamic Smart Array B140i Controller Driver for VMware vSphere 6.5 (Driver Component).	5	2019.05.01	Recommended	cp039786.zip	update
Driver - Storage Controller	HPE H2xx SAS/SATA Host Bus Adapter Driver for 64-bit Microsoft Windows Server 2016 Editions	1	2.68.64.2 (C)	Recommended	cp037731.exe	same
Driver - Storage Controller	HPE Smart Array P824i-p MR controller Driver	3	07.706.05.00-14	Recommended	kmod-megaraid_sas-07.706.05.00-	update

	for 64-bit Red Hat Enterprise Linux 7				14.rhel7u6.x86_64.rpm kmod-megaraid_sas-07.706.05.00-14.rhel7u5.x86_64.rpm	
Driver - Storage Controller	HPE ProLiant Smart Array Controller (64-bit) Driver for Red Hat Enterprise Linux 7 (64-bit)	3	3.4.20-191	Recommended	kmod-hpsa-3.4.20-191.rhel7u7.x86_64.rpm kmod-hpsa-3.4.20-191.rhel7u8.x86_64.rpm	update
Driver - Storage Controller	HPE ProLiant Gen10 and Gen10Plus Smart Array Controller (64-bit) Driver for SUSE LINUX Enterprise Server 15 (64-bit)	2	1.2.14-017	Recommended	smartpqi-kmp-default-1.2.14-017.sles15sp1.x86_64.rpm smartpqi-kmp-default-1.2.14-017.sles15sp2.x86_64.rpm	update
Driver - Storage Controller	HPE Smart Array P824i-p MR 64-bit controller driver for Microsoft Windows 2016 edition.	10	6.714.18.0	Recommended	cp034411.exe	update
Driver - Storage Controller	HPE ProLiant Gen10 and Gen10Plus Smart Array Controller (64-bit) Driver for Red Hat Enterprise Linux 7 (64-bit)	2	1.2.14-016	Recommended	kmod-smartpqi-1.2.14-016.rhel7u7.x86_64.rpm kmod-smartpqi-1.2.14-016.rhel7u8.x86_64.rpm	update
Driver - Storage Controller	HPE Dynamic Smart Array B140i SATA RAID Controller Driver for Red Hat Enterprise Linux 7 (64-bit)	3	1.2.10-179	Recommended	kmod-hpdsa-1.2.10-179.rhel7u8.x86_64.rpm kmod-hpdsa-1.2.10-	update

					179.rhel7u7.x86_64.rpm	
Driver - Storage Controller	HPE ProLiant Smart Array Controller Driver for VMware vSphere 6.7 (Driver Component).	6	2019.09.01	Recommended	cp040735.zip	new
Driver - Storage Controller	HPE H2xx SAS/SATA Host Bus Adapter Driver for SUSE LINUX Enterprise Server 12 (64-bit)	3	15.10.09.00-1	Recommended	lsi-mpt2sas-kmp-default-15.10.09.00-1.sles12sp4.x86_64.rpm	update
Driver - Storage Controller	HPE Smart Array Gen10 Controller Driver for Windows Server 2012 R2, Windows Server 2016, and Windows Server 2019	7	106.178.0.1009	Recommended	cp043158.exe	update
Driver - Storage Controller	HPE Smart Array P824i-p MR 64-bit controller driver for Microsoft Windows 2012 R2 edition.	9	6.714.18.0	Recommended	cp034410.exe	update
Driver - Storage Controller	HPE Smart Array P824i-p MR controller Driver for 64-bit SUSE LINUX Enterprise Server 12	9	07.706.05.00-14	Recommended	lsi-megaraid_sas-kmp-default-07.706.05.00-14.sles12sp3.x86_64.rpm lsi-megaraid_sas-kmp-default-07.706.05.00-14.sles12sp4.x86_64.rpm	update

Driver - Storage Controller	HPE ProLiant Gen10 Smart Array Controller Driver for VMware vSphere 6.7 (Driver Component).	4	2019.12.01	Recommended	cp040981.zip	update
Driver - Storage Controller	HPE ProLiant Gen10 and Gen10Plus Smart Array Controller (64-bit) Driver for SUSE LINUX Enterprise Server 12 (64-bit)	4	1.2.14-016	Recommended	smartpqi-kmp-default-1.2.14-016.sles12sp4.x86_64.rpm smartpqi-kmp-default-1.2.14-016.sles12sp5.x86_64.rpm	update
Driver - Storage Controller	HPE ProLiant Smart Array Controller (64-bit) Driver for SUSE LINUX Enterprise Server 15 (64-bit)	2	3.4.20-197	Recommended	hpsa-kmp-default-3.4.20-197.sles15sp1.x86_64.rpm hpsa-kmp-default-3.4.20-197.sles15sp2.x86_64.rpm	update
Driver - Storage Controller	HPE Dynamic Smart Array B140i Controller Driver for VMware vSphere 6.7 (Driver Component).	4	2019.05.01	Recommended	cp039788.zip	new
Driver - Storage Controller	HPE Dynamic Smart Array B140i SATA RAID Controller Driver for Red Hat Enterprise Linux 8 (64-bit)	1	1.2.10-181	Recommended	kmod-hpdsa-1.2.10-181.rhel8u1.x86_64.rpm kmod-hpdsa-1.2.10-181.rhel8u2.x86_64.rpm	new
Driver - Storage Controller	HPE ProLiant Smart Array Controller Driver for VMware vSphere 6.5 (Driver Component).	5	2019.09.01	Recommended	cp040734.zip	update

Driver - Storage Controller	HPE Smart Array P824i-p MR 64-bit controller driver for Microsoft Windows 2019 edition.	5	6.714.18.0	Recommended	cp038009.exe	new
Driver - Storage Controller	HPE Dynamic Smart Array B140i SATA RAID Controller Driver for SUSE LINUX Enterprise Server 12 (64-bit)	2	1.2.10-176	Recommended	hpdsa-kmp-default-1.2.10-176.sles12sp4.x86_64.rpm hpdsa-kmp-default-1.2.10-176.sles12sp5.x86_64.rpm	update
Driver - Storage Controller	HPE ProLiant Gen10 Smart Array Controller Driver for VMware vSphere 6.5 (Driver Component).	5	2019.12.01	Recommended	cp040982.zip	update
Driver - Storage Controller	HPE H2xx SAS/SATA Host Bus Adapter Driver for Red Hat Enterprise Linux 7 (64-bit)	4	15.10.09.00-2	Recommended	kmod-mpt2sas-15.10.07.00-3.rhel7u5.x86_64.rpm kmod-mpt2sas-15.10.09.00-2.rhel7u6.x86_64.rpm	update
Driver - Storage Controller	HPE ProLiant Smart Array Controller (64-bit) Driver for SUSE LINUX Enterprise Server 12 (64-bit)	1	3.4.20-188	Recommended	hpsa-kmp-default-3.4.20-188.sles12sp5.x86_64.rpm hpsa-kmp-default-3.4.20-188.sles12sp4.x86_64.rpm	update
Driver - Storage Controller	HPE H2xx SAS/SATA Host Bus Adapter (64-bit) Driver for vSphere 6.5 (Driver Component).	2	2017.01.20 (A)	Optional	cp032277.zip	same

Driver - Storage Controller	HPE Dynamic Smart Array B140i SATA RAID Controller Driver for SUSE LINUX Enterprise Server 15 (64-bit)	2	1.2.10-182	Recommended	hpdsa-kmp-default-1.2.10-182.sles15sp2.x86_64.rpm hpdsa-kmp-default-1.2.10-182.sles15sp1.x86_64.rpm	update
Driver - Storage Controller	HPE ProLiant Smart Array HPCISSS3 Controller Driver for 64-bit Microsoft Windows Server 2012/2012 R2/2016/2019 Editions	4	106.26.0.64	Recommended	cp037982.exe	update
Driver - Storage Controller	HPE Smart Array P824i-p MR controller (64-bit) Driver for vSphere 6.5 (Driver Component)	9	2019.12.13	Recommended	cp042803.zip	update
Driver - Storage Controller	HPE Smart Array P824i-p MR controller DRIVER for 64-bit SUSE LINUX Enterprise Server 15	2	07.706.05.00-14	Recommended	lsi-megaraid_sas-kmp-default-07.706.05.00-14.sles15sp0.x86_64.rpm	update
Driver - Storage Controller	HPE ProLiant Smart Array Controller (64-bit) Driver for Red Hat Enterprise Linux 8 (64-bit)	1	3.4.20-196	Recommended	kmod-hpsa-3.4.20-196.rhel8u1.x86_64.rpm kmod-hpsa-3.4.20-196.rhel8u2.x86_64.rpm	new
Driver - Storage Fibre Channel and Fibre Channel	SUSE Linux Enterprise Server 15 Service Pack 1 FCoE Driver Kit for HPE Emulex(BRCM) Converged	1	12.0.1259.0 (c)	Recommended	brcmfcoe-kmp-default-12.0.1259.0_k4.12.14_195-1.sles15sp1.x86_64.rpm	update

Over Ethernet	Network Adapters(CNAs) and mezzanine Converged Network Adapters(CNAs)					
Driver - Storage Fibre Channel and Fibre Channel Over Ethernet	Red Hat Enterprise Linux 8 Update 2 Fibre Channel Driver Kit for HPE QLogic Host Bus Adapters	9	10.01.00.64.08.0-k1	Recommended	kmod-qlgc-qla2xxx-10.01.00.64.08.0_k1-1.rhel8u2.x86_64.rpm	new
Driver - Storage Fibre Channel and Fibre Channel Over Ethernet	HPE Storage Mezzanine Fibre Channel Adapter Kit for the x64 Emulex Storport Driver for Microsoft Windows Server 2019	7	12.4.243.4	Recommended	cp042264.exe	new
Driver - Storage Fibre Channel and Fibre Channel Over Ethernet	Red Hat Enterprise Linux 8 Update 1 Server Fibre Channel Driver Kit for HPE Emulex Host Bus Adapters	8	12.6.275.14	Recommended	kmod-elx-lpfc-12.6.275.14-1.rhel8u1.x86_64.rpm	new
Driver - Storage Fibre Channel and Fibre Channel Over Ethernet	Red Hat Enterprise Linux 7 Update 8 Server Fibre Channel Driver Kit for HPE QLogic Host Bus Adapters	8	10.01.00.64.07.6-k1a	Recommended	kmod-qlgc-qla2xxx-10.01.00.64.07.6_k1a-1.rhel7u8.x86_64.rpm	update
Driver - Storage Fibre Channel and Fibre Channel	SUSE Linux Enterprise Server 12 Service Pack 5 Fibre Channel Driver Kit for HPE QLogic Host Bus Adapters	7	10.01.00.64.12.5-k1	Recommended	qlgc-qla2xxx-kmp-default-10.01.00.64.12.5_k1_k4.12.1_4_120-1.sles12sp5.x86_64.rpm	update

Over Ethernet						
Driver - Storage Fibre Channel and Fibre Channel Over Ethernet	SUSE Linux Enterprise Server 15 Service Pack 1 Fibre Channel Driver Kit for HPE Emulex Mezzanine Host Bus Adapters	17	12.4.270.3	Recommended	elx-lpfc-kmp-default-12.4.270.3_k4.12.14_195-1.sles15sp1.x86_64.rpm	new
Driver - Storage Fibre Channel and Fibre Channel Over Ethernet	HPE Storage Fibre Channel Adapter Kit for the x64 QLogic Storport Driver for Microsoft Windows Server 2019	8	9.4.1.20	Recommended	cp042520.exe	update
Driver - Storage Fibre Channel and Fibre Channel Over Ethernet	SUSE Linux Enterprise Server 12 Service Pack 4 Fibre Channel Driver Kit for HPE QLogic Mezzanine Host Bus Adapters	7	10.01.00.57.12.4-k1	Recommended	qlgc-qla2xxx-kmp-default-10.01.00.57.12.4_k1_k4.12.14_94.41-1.sles12sp4.x86_64.rpm	new
Driver - Storage Fibre Channel and Fibre Channel Over Ethernet	HPE Storage Mezzanine Fibre Channel Adapter Kit for the x64 QLogic Storport Driver for Microsoft Windows Server 2016	12	9.3.3.20	Recommended	cp042212.exe	new
Driver - Storage Fibre Channel and Fibre Channel Over Ethernet	Red Hat Enterprise Linux 7 Update 7 Server Fibre Channel Driver Kit for HPE Emulex Host Bus Adapters	21	12.6.275.14	Recommended	kmod-elx-lpfc-12.6.275.14-1.rhel7u7.x86_64.rpm	new

Driver - Storage Fibre Channel and Fibre Channel Over Ethernet	SUSE Linux Enterprise Server 12 Service Pack 4 Fibre Channel Driver Kit for HPE Emulex Host Bus Adapters	20	12.6.275.14	Recommended	elx-lpfc-kmp-default-12.6.275.14_k4.12.14_94.41-1.sles12sp4.x86_64.rpm	new
Driver - Storage Fibre Channel and Fibre Channel Over Ethernet	HPE Storage Fibre Channel Adapter Kit for the x64 Emulex Storport Driver for Microsoft Windows Server 2012R2/2016	8	12.6.165.0 (b)	Recommended	cp041717.exe	update
Driver - Storage Fibre Channel and Fibre Channel Over Ethernet	SUSE Linux Enterprise Server 15 Service Pack 1 Fibre Channel Driver Kit for HPE Emulex Host Bus Adapters	20	12.6.275.14	Recommended	elx-lpfc-kmp-default-12.6.275.14_k4.12.14_195-1.sles15sp1.x86_64.rpm	new
Driver - Storage Fibre Channel and Fibre Channel Over Ethernet	Red Hat Enterprise Linux 8 Update 1 Fibre Channel Driver Kit for HPE QLogic Host Bus Adapters	8	10.01.00.64.08.0-k1	Recommended	kmod-qlgc-qla2xxx-10.01.00.64.08.0_k1-1.rhel8u1.x86_64.rpm	new
Driver - Storage Fibre Channel and Fibre Channel Over Ethernet	HPE Storage Fibre Channel Adapter Kit for the x64 Emulex Storport Driver for Microsoft Windows Server 2019	7	12.6.165.0 (b)	Recommended	cp041729.exe	new
Driver - Storage Fibre Channel and Fibre Channel	Red Hat Enterprise Linux 7 Update 7 Server FCoE Driver Kit for HPE Emulex(BRCM)	1	12.0.1259.0 (c)	Recommended	kmod-brcmfcoe-12.0.1259.0-1.rhel7u7.x86_64.rpm	update

Over Ethernet	Converged Network Adapters(CNAs) and mezzanine Converged Network Adapters(CNAs)					
Driver - Storage Fibre Channel and Fibre Channel Over Ethernet	SUSE Linux Enterprise Server 15 Service Pack 1 Fibre Channel Driver Kit for HPE QLogic Host Bus Adapters	8	10.01.00.64.15.1-k1	Recommended	qlgc-qla2xxx-kmp-default-10.01.00.64.15.1_k1_k4.12.14_195-1.sles15sp1.x86_64.rpm	new
Driver - Storage Fibre Channel and Fibre Channel Over Ethernet	Red Hat Enterprise Linux 8 Update 2 Server Fibre Channel Driver Kit for HPE Emulex Host Bus Adapters	18	12.6.275.14	Recommended	kmod-elx-lpfc-12.6.275.14-1.rhel8u2.x86_64.rpm	new
Driver - Storage Fibre Channel and Fibre Channel Over Ethernet	SUSE Linux Enterprise Server 12 Service Pack 4 FCoE Driver Kit for HPE Emulex(BRCM) Converged Network Adapters(CNAs) and mezzanine Converged Network Adapters(CNAs)	1	12.0.125 9.0 (c)	Recommended	brcmfcoe-kmp-default-12.0.1259.0_k4.12.14_94.41-1.sles12sp4.x86_64.rpm	update
Driver - Storage Fibre Channel and Fibre Channel Over Ethernet	SUSE Linux Enterprise Server 12 Service Pack 4 Fibre Channel Driver Kit for HPE Emulex Mezzanine Host Bus Adapters	17	12.4.270.3	Recommended	elx-lpfc-kmp-default-12.4.270.3_k4.12.14_94.41-1.sles12sp4.x86_64.rpm	new

Driver - Storage Fibre Channel and Fibre Channel Over Ethernet	SUSE Linux Enterprise Server 12 Service Pack 4 Fibre Channel Driver Kit for HPE QLogic Host Bus Adapters	10	10.01.00. 64.12.4- k1b	Recommended	qlgc-qla2xxx- kmp-default- 10.01.00.64.12 .4_k1b_k4.12. 14_94.41- 1.sles12sp4.x8 6_64.rpm	new
Driver - Storage Fibre Channel and Fibre Channel Over Ethernet	Red Hat Enterprise Linux 7 Update 7 Server Fibre Channel Driver Kit for HPE QLogic Host Bus Adapters	9	10.01.00. 64.07.6- k1a	Recommended	kmod-qlgc- qla2xxx- 10.01.00.64.07 .6_k1a- 1.rhel7u7.x86_ 64.rpm	new
Driver - Storage Fibre Channel and Fibre Channel Over Ethernet	HPE Storage Mezzanine Fibre Channel Adapter Kit for the x64 Emulex Storport Driver for Microsoft Windows Server 2012R2/2016	7	12.4.243. 4	Recommended	cp042265.exe	new
Driver - Storage Fibre Channel and Fibre Channel Over Ethernet	HPE Storage Mezzanine Fibre Channel Adapter Kit for the x64 QLogic Storport Driver for Microsoft Windows Server 2012 R2	10	9.3.3.20	Recommended	cp042971.exe	new
Driver - Storage Fibre Channel and Fibre Channel Over Ethernet	Red Hat Enterprise Linux 7 Update 7 Server Fibre Channel Driver Kit for HPE Emulex Mezzanine Host Bus Adapters	16	12.4.270. 3	Recommended	kmod-elx-lpfc- 12.4.270.3- 1.rhel7u7.x86_ 64.rpm	new
Driver - Storage Fibre Channel and	HPE Storage Mezzanine Fibre Channel Adapter Kit for the x64	9	9.3.3.20	Recommended	cp042213.exe	new

Fibre Channel Over Ethernet	QLogic Storport Driver for Microsoft Windows Server 2019					
Driver - Storage Fibre Channel and Fibre Channel Over Ethernet	Red Hat Enterprise Linux 7 Update 8 Server Fibre Channel Driver Kit for HPE Emulex Host Bus Adapters	20	12.6.275.14	Recommended	kmod-elx-lpfc-12.6.275.14-1.rhel7u8.x86_64.rpm	update
Driver - Storage Fibre Channel and Fibre Channel Over Ethernet	HPE Storage Fibre Channel Over Ethernet Adapter Kit for the x64 Emulex Storport Driver for Windows 2019	2	12.0.119 2.0 (d)	Recommended	cp044553.exe	update
Driver - Storage Fibre Channel and Fibre Channel Over Ethernet	HPE Storage Fibre Channel Over Ethernet Adapter Kit for the x64 Emulex Storport Driver for Windows 2012R2 and Windows 2016	1	12.0.119 2.0 (c)	Recommended	cp044554.exe	update
Driver - Storage Fibre Channel and Fibre Channel Over Ethernet	SUSE Linux Enterprise Server 15 Service Pack 2 Fibre Channel Driver Kit for HPE QLogic Host Bus Adapters	19	10.01.00.64.15.2-k1b	Recommended	qlgc-qla2xxx-kmp-default-10.01.00.64.15.2_k1b_k5.3.1_8_22-1.sles15sp2.x86_64.rpm	update
Driver - Storage Fibre Channel and Fibre Channel Over Ethernet	Red Hat Enterprise Linux 7 Update 7 Server Fibre Channel Driver Kit for HPE QLogic Mezzanine Host Bus Adapters	7	10.01.00.57.07.6-k1	Recommended	kmod-qlgc-qla2xxx-10.01.00.57.07.6_k1-1.rhel7u7.x86_64.rpm	new

Driver - Storage Fibre Channel and Fibre Channel Over Ethernet	HPE Storage Fibre Channel Adapter Kit for the x64 QLogic Storport Driver for Microsoft Windows Server 2016	7	9.4.1.20	Recommended	cp042519.exe	update
Driver - Storage Fibre Channel and Fibre Channel Over Ethernet	HPE Storage Fibre Channel Adapter Kit for the x64 QLogic Storport Driver for Microsoft Windows Server 2012 R2	7	9.4.1.20	Recommended	cp042970.exe	update
Driver - Storage Fibre Channel and Fibre Channel Over Ethernet	Red Hat Enterprise Linux 8 update 1 Server Fibre Channel Driver Kit for HPE QLogic Mezzanine Host Bus Adapters	7	10.01.00.57.08.0-k1	Recommended	kmod-qlgc-qla2xxx-10.01.00.57.08.0_k1-1.rhel8u1.x86_64.rpm	new
Driver - Storage Fibre Channel and Fibre Channel Over Ethernet	SUSE Linux Enterprise Server 15 Service Pack 1 Fibre Channel Driver Kit Host Bus Adapters for HPE QLogic Mezzanine Host Bus Adapters	7	10.01.00.57.15.1-k1	Recommended	qlgc-qla2xxx-kmp-default-10.01.00.57.15.1_k1_k4.12.14_195-1.sles15sp1.x86_64.rpm	new
Driver - Storage Fibre Channel and Fibre Channel Over Ethernet	SUSE Linux Enterprise Server 15 Service Pack 2 Fibre Channel Driver Kit for HPE Emulex Host Bus Adapters	21	12.6.275.20	Recommended	elx-lpfc-kmp-default-12.6.275.20_k5.3.18_22-1.sles15sp2.x86_64.rpm	update
Driver - Storage Fibre Channel and Fibre	SUSE Linux Enterprise Server 12 Service Pack 5 Fibre Channel Driver Kit for HPE	20	12.6.275.14	Recommended	elx-lpfc-kmp-default-12.6.275.14_k4.12.14_120-	update

Channel Over Ethernet	Emulex Host Bus Adapters				1.sles12sp5.x86_64.rpm	
Driver - Video	Matrox G200eH3 Video Controller Driver for Windows Server 2012 R2	5	9.15.1.224 (B)	Optional	cp040214.exe	update
Driver - Video	Matrox G200eH3 Video Controller Driver for Windows Server 2016 and Server 2019	5	9.15.1.224 (B)	Optional	cp040215.exe	update
Driver - Video	Matrox G200eH Video Controller Driver for Windows Server 2016 and Server 2019	5	9.15.1.224	Optional	cp038692.exe	update
Driver - Video	Matrox G200eH Video Controller Driver for Windows Server 2012 and Server 2012 R2	5	9.15.1.224	Optional	cp038691.exe	update
Driver - System Management	iLO 5 Channel Interface Driver for Windows Server 2012 R2	5	4.6.0.0	Optional	cp040013.exe	update
Driver - System Management	iLO 4 Management Controller Driver Package for Windows Server 2016 and Server 2019	5	4.0.0.0 (B)	Optional	cp037927.exe	update
Driver - System Management	iLO 5 Automatic Server Recovery Driver for Windows Server 2012 R2	3	4.7.0.0	Optional	cp041378.exe	update

Driver - System Management	iLO 4 Management Controller Driver Package for Windows Server 2012 and Server 2012 R2	10	4.0.0.0	Optional	cp035109.exe	update
Driver - System Management	iLO 5 Automatic Server Recovery Driver for Windows Server 2016 and Server 2019	3	4.7.0.0	Optional	cp041379.exe	update
Driver - System Management	iLO 4 Channel Interface Driver for Windows Server 2016 and Server 2019	3	4.1.0.0	Recommended	cp039985.exe	update
Driver - System Management	iLO 5 Channel Interface Driver for Windows Server 2016 and Server 2019	4	4.6.0.0 (C)	Optional	cp041932.exe	update
Driver - System Management	iLO 4 Channel Interface Driver for Windows Server 2012 and Server 2012 R2	3	4.1.0.0	Recommended	cp039984.exe	update
Driver - System Management	HPE ProLiant Gen9 Chipset Identifier for Windows Server 2012 R2 to Server 2019	4	10.1.179.69.8134	Optional	cp040885.exe	update
Driver - Storage	HPE Smart Array S100i SR Gen10 SW RAID Driver for Windows Server 2012 R2, Windows Server 2016, and Windows Server 2019	4	106.12.6.0	Recommended	cp043250.exe	update

Driver - Storage	HPE Smart Array S100i SR Gen10 Plus SW RAID Driver for Windows Server 2016, and Windows Server 2019	32	106.64.4.1384	Recommended	cp039949.exe	new
Driver - Storage	Dynamic Smart Array B140i Controller Driver for 64-bit Microsoft Windows Server 2012/2012 R2/2016/2019 Editions	11	62.16.2.64	Recommended	cp042594.exe	update
Driver - Chipset	Identifiers for Intel Xeon E-2xxx Processor for Windows	12	10.1.180.15.8142	Optional	cp039323.exe	update
Driver - Chipset	Identifiers for AMD EPYC Processors for Windows	5	3.0.0.0 (B)	Optional	cp040146.exe	update
Driver - Chipset	Identifiers for Intel Xeon Scalable Processors (First and Second Generation) for Windows	9	10.1.180.15.8142	Optional	cp040561.exe	update
Driver - System	HPE Non-Volatile Memory Drivers for Microsoft Windows Server 2012 R2 and 2016	4	3.0.1.2	Recommended	cp038534.exe	update
Firmware - Network	Online Firmware Upgrade Utility (Linux x86_64) for HPE Mellanox VPI (Ethernet and Infiniband mode)	3	1.0.11	Recommended	firmware-hca-mellanox-vpi-eth-ib-1.0.11-1.1.x86_64.rpm	update

	devices on Linux x86_64 platform					
Firmware - Network	HPE Broadcom NetXtreme-E Online Firmware Upgrade Utility for Windows Server x64 Editions	13	5.2.3.0	Optional	cp043301.exe	update
Firmware - Network	Online Firmware Upgrade Utility (ESXi 7.0) for Mellanox Open Ethernet cards	6	1.0.0	Recommended	CP044391.zip	new
Firmware - Network	Online Firmware Upgrade Utility (Windows x64) for Mellanox Open VPI (Ethernet and Infiniband mode) ConnectX6 devices on Windows x86_64 platform	3	1.0.0.2	Recommended	cp044422.exe	new
Firmware - Network	HPE QLogic NX2 Online Firmware Upgrade Utility for VMware	57	1.27.11	Optional	CP041878.zip	update
Firmware - Network	Online Firmware Upgrade Utility (ESXi 6.7) for Mellanox ConnectX6Dx Open Ethernet cards	9	1.0.2	Recommended	CP044266.zip	new
Firmware - Network	HPE QLogic FastLinQ Online Firmware Upgrade Utility for VMware	45	4.12.12	Optional	CP041875.zip	update
Firmware - Network	Online Firmware Upgrade Utility (ESXi 7.0) for Mellanox Open	7	1.0.0	Recommended	CP044420.zip	new

	VPI (Ethernet and Infiniband mode) ConnectX6 devices on VMware ESXi 7.0					
Firmware - Network	Marvell FastLinQ Online Firmware Upgrade Utility for VMware	42	4.12.14	Optional	CP042279.zip	new
Firmware - Network	HPE Firmware Flash for Emulex Converged Network Adapters for Linux (x64)	17	2020.09. 01	Recommended	firmware-cna- emulex- 2020.09.01- 1.17.x86_64.rp m	update
Firmware - Network	Online Firmware Upgrade Utility (Windows x64) for HPE Mellanox VPI (Ethernet and Infiniband mode) ConnectX6 devices on Windows x86_64 platform	5	1.0.0.2	Recommended	cp044485.exe	new
Firmware - Network	Online Firmware Upgrade Utility (Windows x64) for HPE Mellanox IB only ConnectX4 and ConnectX5 devices on Windows x86_64 platform	3	1.0.0.6	Recommended	cp044357.exe	update
Firmware - Network	HPE Firmware Flash for Emulex Converged Network Adapters for VMware vSphere 6.5	5	2020.09. 01 (b)	Recommended	CP044549.zip	update
Firmware - Network	Online Firmware Upgrade Utility (ESXi 7.0) for HPE Mellanox	3	1.0.0	Recommended	CP044390.zip	new

	Ethernet only adapters					
Firmware - Network	HPE QLogic FastLinQ Online Firmware Upgrade Utility for Windows Server x64 Editions	20	5.2.3.0	Optional	cp041876.exe	update
Firmware - Network	Online Firmware Upgrade Utility (ESXi 6.7) for HPE Ethernet 10Gb 2-port 548SFP+ Adapter	4	1.0.3	Recommended	CP044322.zip	new
Firmware - Network	Online Firmware Upgrade Utility (ESXi 6.7) for HPE Mellanox VPI (Ethernet and Infiniband mode) ConnectX4 and ConnectX5 devices on VMware ESXi 6.7	4	1.0.3	Recommended	CP044171.zip	new
Firmware - Network	HPE Intel Online Firmware Upgrade Utility for Linux x86_64	22	1.20.10	Optional	firmware-nic-intel-1.20.10-1.1.x86_64.rpm	update
Firmware - Network	Broadcom NetXtreme-E Online Firmware Upgrade Utility for Windows Server x64 Editions	26	5.2.3.0	Optional	cp043169.exe	new
Firmware - Network	HPE Broadcom NetXtreme-E Online Firmware Upgrade Utility for Linux x86_64	11	1.9.3	Optional	firmware-nic-bcm-nxe-1.9.3-1.1.x86_64.rpm	update
Firmware - Network	Online Firmware Upgrade Utility (Windows x64) for HPE Mellanox	3	1.0.0.13	Recommended	cp044409.exe	update

	Ethernet only adapters					
Firmware - Network	Online Firmware Upgrade Utility (Windows x64) for HPE Mellanox VPI (Ethernet and Infiniband mode) devices on Windows x86_64 platform	2	1.0.0.11	Recommended	cp044336.exe	update
Firmware - Network	Online Firmware Upgrade Utility (Linux x86_64) for HPE Ethernet 10Gb 2-port 548SFP+ Adapter	5	1.0.3	Recommended	firmware-nic-mellanox-eth-only-mft-1.0.3-1.1.x86_64.rpm	new
Firmware - Network	HPE Broadcom NX1 Online Firmware Upgrade Utility for Linux x86_64	4	2.26.1	Optional	firmware-nic-broadcom-2.26.1-1.1.x86_64.rpm	update
Firmware - Network	Online Firmware Upgrade Utility (Windows x64) for Mellanox ConnectX6Dx Open Ethernet cards	9	1.0.0.2	Recommended	cp044267.exe	new
Firmware - Network	Online Firmware Upgrade Utility (Linux x86_64) for Mellanox ConnectX6Dx Open Ethernet cards	6	1.0.2	Recommended	firmware-nic-open-cx6dx-mellanox-eth-mft-1.0.2-1.1.x86_64.rpm	new
Firmware - Network	Online Firmware Upgrade Utility (ESXi 6.5) for HPE Mellanox VPI (Ethernet and Infiniband mode) ConnectX4 and ConnectX5	4	1.0.7	Recommended	CP044170.zip	update

	devices on VMware ESXi 6.5					
Firmware - Network	Online Firmware Upgrade Utility (ESXi 6.7) for HPE Mellanox VPI (Ethernet and Infiniband mode) ConnectX6 devices on VMware ESXi 6.7	4	1.0.0	Recommended	CP044415.zip	new
Firmware - Network	Online Firmware Upgrade Utility (ESXi 6.5) for HPE Mellanox VPI (Ethernet and Infiniband mode) devices on VMware ESXi 6.5	2	1.0.6	Recommended	CP044334.zip	update
Firmware - Network	HPE Blade QLogic NX2 Online Firmware Upgrade Utility for Linux	18	1.0.9	Optional	firmware-nic-qlogic-nx2-bl-1.0.9-1.1.x86_64.rpm	new
Firmware - Network	Broadcom NetXtreme-E Online Firmware Upgrade Utility for Linux x86_64	31	1.9.4	Optional	firmware-nic-is-bcm-nxe-1.9.4-1.1.x86_64.rpm	new
Firmware - Network	Online Firmware Upgrade Utility (ESXi 6.5) for HPE Mellanox Ethernet only adapters	3	1.0.8	Recommended	CP044339.zip	update
Firmware - Network	Online Firmware Upgrade Utility (ESXi 7.0) for HPE Ethernet 10Gb 2-port 548SFP+ Adapter	7	1.0.0	Recommended	CP044411.zip	new
Firmware - Network	Online Firmware Upgrade Utility	4	1.0.3	Recommended	firmware-nic-open-	new

	(Linux x86_64) for Mellanox Open Ethernet cards				mellanox-eth-mft-1.0.3-1.1.x86_64.rpm	
Firmware - Network	Online Firmware Upgrade Utility (ESXi 6.7) for HPE Mellanox Ethernet only adapters	3	1.0.4	Recommended	CP044340.zip	new
Firmware - Network	HPE Blade Intel Online Firmware Upgrade Utility for Windows Server x64 Editions	19	1.0.0.5	Optional	cp040422.exe	new
Firmware - Network	Marvell FastLinQ Online Firmware Upgrade Utility for Windows Server x64 Editions	31	5.2.3.0	Optional	cp042280.exe	new
Firmware - Network	Intel Online Firmware Upgrade Utility for VMware	43	3.13.12	Optional	CP041853.zip	new
Firmware - Network	Online Firmware Upgrade Utility (ESXi 6.5) for Mellanox Open VPI (Ethernet and Infiniband mode) ConnectX6 devices on VMware ESXi 6.5	4	1.0.0	Recommended	CP044418.zip	new
Firmware - Network	Online Firmware Upgrade Utility (Linux x86_64) for HPE Infiniband FDR 2P 545QSFP Adapter (HP Part # 702211-B21), HPE Infiniband FDR 2P 545FLR-QSFP Adapter	2	1.0.7	Recommended	firmware-hca-mellanox-infiniband-only-1.0.7-1.1.x86_64.rpm	update

	(HP Part # 702212-B21) and HPE Infiniband FDR 2P 545M Adapter (HP Part #702213-B21)					
Firmware - Network	Online Firmware Upgrade Utility (ESXi 7.0) for HPE Mellanox VPI (Ethernet and Infiniband mode) ConnectX4 and ConnectX5 devices on VMware ESXi 7.0	16	1.0.0	Recommended	CP044083.zip	new
Firmware - Network	HPE Broadcom NX1 Online Firmware Upgrade Utility for Windows Server x64 Editions	5	5.2.3.0	Optional	cp043298.exe	update
Firmware - Network	HPE Blade Intel Online Firmware Upgrade Utility for VMware	38	1.1.2	Optional	CP042573.zip	new
Firmware - Network	Online Firmware Upgrade Utility (Linux x86_64) for HPE Intel OPA adapters	2	1.9.2	Recommended	firmware-nic-intel-opa-hfi-1.9.2-1.1.x86_64.rpm	update
Firmware - Network	Online Firmware Upgrade Utility (Linux x86_64) for Mellanox Open VPI (Ethernet and Infiniband mode) ConnectX6 devices on Linux x86_64 platform	4	1.0.2	Recommended	firmware-hca-open-mellanox-vpi-connectx6-mft-1.0.2-1.1.x86_64.rpm	new
Firmware - Network	Intel Online Firmware Upgrade Utility for Linux x86_64	30	1.20.11	Optional	firmware-nic-is-intel-1.20.11-	new

					1.1.x86_64.rpm	
Firmware - Network	HPE Intel Online Firmware Upgrade Utility for Windows Server x64 Editions	21	5.2.3.0	Optional	cp041704.exe	update
Firmware - Network	Online Firmware Upgrade Utility (ESXi 7.0) for HPE Mellanox VPI (Ethernet and Infiniband mode) devices on VMware ESXi 7.0	3	1.0.0	Recommended	CP044389.zip	new
Firmware - Network	Online Firmware Upgrade Utility (Linux x86_64) for HPE Mellanox VPI (Ethernet and Infiniband mode) ConnectX6 devices on Linux x86_64 platform	3	1.0.5	Recommended	firmware-hca-mellanox-vpi-connectx6-mft-1.0.5-1.1.x86_64.rpm	new
Firmware - Network	Marvell FastLinQ Online Firmware Upgrade Utility for Linux x86_64	25	1.9.10	Optional	firmware-nic-is-marvell-flq-1.9.10-1.1.x86_64.rpm	new
Firmware - Network	Online Firmware Upgrade Utility (ESXi 6.7) for Mellanox Open Ethernet cards	6	1.0.3	Recommended	CP044346.zip	new
Firmware - Network	Intel Online Firmware Upgrade Utility for Windows Server x64 Editions	27	5.2.3.0	Optional	cp041854.exe	new
Firmware - Network	Online Firmware Upgrade Utility (ESXi 6.7) for HPE Mellanox	2	1.0.4	Recommended	CP044335.zip	new

	VPI (Ethernet and Infiniband mode) devices on VMware ESXi 6.7					
Firmware - Network	HPE Firmware Flash for Emulex Converged Network Adapters for VMware vSphere 7.0	7	2020.09.01 (b)	Recommended	CP044565.zip	new
Firmware - Network	Online Firmware Upgrade Utility (ESXi 6.7) for Mellanox Open VPI (Ethernet and Infiniband mode) ConnectX6 devices on VMware ESXi 6.7	4	1.0.0	Recommended	CP044419.zip	new
Firmware - Network	Online Firmware Upgrade Utility (ESXi 6.5) for HPE Mellanox VPI (Ethernet and Infiniband mode) ConnectX6 devices on VMware ESXi 6.5	4	1.0.0	Recommended	CP044414.zip	new
Firmware - Network	Online Firmware Upgrade Utility (Linux x86_64) for HPE Mellanox IB only ConnectX4 and ConnectX5 devices on Linux x86_64 platform	3	1.0.6	Recommended	firmware-nic-mellanox-ib-cx4-cx5-1.0.6-1.1.x86_64.rpm	update
Firmware - Network	HPE Blade QLogic NX2 Online Firmware Upgrade Utility for VMware	41	1.1.1	Optional	CP042923.zip	new
Firmware - Network	Online Firmware Upgrade Utility (Windows x64) for	2	1.0.0.8	Recommended	cp044172.exe	update

	HPE Mellanox VPI (Ethernet and Infiniband mode) ConnectX4 and ConnectX5 devices on Windows x86_64 platform					
Firmware - Network	Online Firmware Upgrade Utility (Windows x64) for Mellanox Open Ethernet cards	8	1.0.0.3	Recommended	cp044408.exe	new
Firmware - Network	Online Firmware Upgrade Utility (ESXi 7.0) for HPE Mellanox VPI (Ethernet and Infiniband mode) ConnectX6 devices on VMware ESXi 7.0	9	1.0.0	Recommended	CP044416.zip	new
Firmware - Network	Online Firmware Upgrade Utility (ESXi 6.5) for Mellanox Open Ethernet cards	6	1.0.3	Recommended	CP044345.zip	new
Firmware - Network	HPE Firmware Flash for Emulex Converged Network Adapters for Windows (x64)	3	2020.09.01	Recommended	cp044552.exe	update
Firmware - Network	HPE Blade Intel Online Firmware Upgrade Utility for Linux	22	1.0.14	Optional	firmware-nic-intel-bl-1.0.14-1.1.x86_64.rpm	new
Firmware - Network	HPE Blade QLogic NX2 Online Firmware Upgrade Utility for Windows Server x64 Editions	2	1.0.0.9 (C)	Recommended	cp044984.exe	new

Firmware - Network	Broadcom NetXtreme-E Online Firmware Upgrade Utility for VMware	30	5.11.6	Optional	CP043168.zip	new
Firmware - Network	Online Firmware Upgrade Utility (ESXi 7.0) for Mellanox ConnectX6Dx Open Ethernet cards	8	1.0.0	Recommended	CP044406.zip	new
Firmware - Network	Online Firmware Upgrade Utility (ESXi 6.5) for HPE Ethernet 10Gb 2-port 548SFP+ Adapter	5	1.0.3	Recommended	CP044321.zip	new
Firmware - Network	Online Firmware Upgrade Utility (Windows x64) for HPE Ethernet 10Gb 2-port 548SFP+ Adapter	4	1.0.0.3	Recommended	cp044323.exe	new
Firmware - Network	HPE QLogic FastLinQ Online Firmware Upgrade Utility for Linux x86_64	20	1.9.8	Optional	firmware-nic-qlogic-flq-1.9.8-1.1.x86_64.rpm	update
Firmware - Network	HPE QLogic NX2 Online Firmware Upgrade Utility for Windows Server x64 Editions	16	5.2.3.0	Optional	cp041879.exe	update
Firmware - Network	HPE Intel Online Firmware Upgrade Utility for VMware	43	3.13.15	Optional	CP041856.zip	update
Firmware - Network	HPE Broadcom NX1 Online Firmware Upgrade Utility for VMware	50	1.27.5	Optional	CP043297.zip	update

Firmware - Network	Online Firmware Upgrade Utility (Linux x86_64) for HPE Mellanox VPI (Ethernet and Infiniband mode) ConnectX4 and ConnectX5 devices on Linux x86_64 platform	2	1.0.9	Recommended	firmware-hca-mellanox-vpi-connectx4-1.0.9-1.1.x86_64.rpm	update
Firmware - Network	HPE Broadcom NetXtreme-E Online Firmware Upgrade Utility for VMware	28	5.11.6	Optional	CP043300.zip	update
Firmware - Network	HPE Firmware Flash for Emulex Converged Network Adapters for VMware vSphere 6.7	5	2020.09.01 (b)	Recommended	CP044550.zip	update
Firmware - Network	Online Firmware Upgrade Utility (ESXi 6.5) for Mellanox Open ConnectX6Dx Ethernet cards	9	1.0.2	Recommended	CP044265.zip	new
Firmware - Network	HPE QLogic NX2 Online Firmware Upgrade Utility for Linux x86_64	14	2.27.8	Optional	firmware-nic-qlogic-nx2-2.27.8-1.1.x86_64.rpm	update
Firmware - Network	Online Firmware Upgrade Utility (Linux x86_64) for HPE Mellanox Ethernet only adapters	3	1.0.13	Recommended	firmware-nic-mellanox-ethernet-only-1.0.13-1.1.x86_64.rpm	update
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Windows (x64) - EG000300JWFV B Drive	3	HPD2 (D)	Optional	cp043922.exe	update

Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Linux (x64) - MB6000JEQUV and MB8000JEQVA Drives	2	HPDB (F)	Recommended	firmware-hdd-df22f7effd-HPDB-6.1.x86_64.rpm	update
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Windows (x64) - EG1800JFHH Drive	3	HPD7 (E)	Recommended	cp043912.exe	update
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for VMware ESXi - MB8000JFECQ Drive	3	HPD7 (F)	Recommended	CP043853.zip	update
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Linux (x64) - MB4000JEQNL and MB6000JEQNN Drives	2	HPDB (F)	Recommended	firmware-hdd-2cfaac41db-HPDB-6.1.x86_64.rpm	update
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for VMware ESXi - EG000300JWFV B Drive	6	HPD2 (F)	Recommended	CP043779.zip	update
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for VMware ESXi - EH000300JWCP K, EH000600JWCP L and EH000900JWCP N Drives	4	HPD5 (D)	Recommended	CP043771.zip	update
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Windows (x64) -	4	HPD4 (B)	Recommended	cp043964.exe	new

	EH000900JWHP K and EH000600JWHP H Drives					
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Linux (x64) - MB008000JWRT D Drive	2	HPD1 (C)	Recommended	firmware-hdd- 8b26d1ef02- HPD1- 3.1.x86_64.rp m	new
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for VMware ESXi - MB4000JEFNC and MB6000JEFND Drives	3	HPD9 (G)	Recommended	CP043764.zip	update
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for VMware ESXi - MB010000JWAY K and MB008000JWAY H Drives	4	HPD5 (E)	Critical	CP043784.zip	update
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Linux (x64) - MB004000JWKG U Drive	2	HPD1 (C)	Recommended	firmware-hdd- 2c27a7a9a4- HPD1- 3.1.x86_64.rp m	new
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Linux (x64) - EG1800JEMDB Drive	5	HPD5 (F)	Recommended	firmware-hdd- 0a38b25661- HPD5- 6.1.x86_64.rp m	update
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Linux (x64) - MB008000JWJR Q and MB006000JWJR P Drives	2	HPD5 (B)	Recommended	firmware-hdd- faf39e0ff7- HPD5- 2.1.x86_64.rp m	new

Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Windows (x64) - EG000600JWJN P and EG001200JWJN Q Drives	3	HPD3 (B)	Recommended	cp043966.exe	update
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for VMware ESXi - MB012000JWDF D Drive	4	HPD2 (E)	Critical	CP043803.zip	new
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Windows (x64) - MB6000JVYYV Drive	6	HPD2 (E)	Recommended	cp043901.exe	update
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for VMware ESXi - EG001800JWJNL and EG002400JWJN N Drive	2	HPD2 (E)	Recommended	CP043821.zip	new
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Linux (x64) - EO000400JWDK P, EO000800JWDK Q, EO001600JWDK R, MO000400JWDK U, MO000800JWDK V, MO001600JWDL A and MO003200JWDL B Drives	2	HPD2 (D)	Recommended	firmware-hdd-5dcf26fa42-HPD2-4.1.x86_64.rpm	update

Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for VMware ESXi - MB2000JFEML and MB4000JFEMN Drives	4	HPD6 (G)	Critical	CP043785.zip	update
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Linux (x64) - EG1800JEHMD Drive	3	HPD6 (G)	Recommended	firmware-hdd-8a2c06af48-HPD6-7.1.x86_64.rpm	update
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for VMware ESXi - MB4000JEQNL and MB6000JEQNN Drives	3	HPDB (G)	Recommended	CP043765.zip	update
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Windows (x64) - MB6000JVYZD and MB4000JVYZC Drives	5	HPD4 (C)	Recommended	cp043917.exe	update
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Linux (x64) - EG0600JETKA, EG0900JETKB and EG1200JETKC Drives	3	HPD7 (D)	Recommended	firmware-hdd-7505dfb5ae-HPD7-4.1.x86_64.rpm	update
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Windows (x64) - MB004000JWFV K and MB006000JWFV L Drives	7	HPD3 (B)	Recommended	cp043967.exe	new

Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Linux (x64) - EG000300JWBH R Drive	3	HPD4 (D)	Recommended	firmware-hdd-2e4c61fc63-HPD4-4.1.x86_64.rpm	update
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Linux (x64) - EG1800JFHHM Drive	3	HPD7 (E)	Recommended	firmware-hdd-7fc5497116-HPD7-5.1.x86_64.rpm	update
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Windows (x64) - EG0300JEHLV, EG0600JEHMA, EG0900JEHMB and EG1200JEHMC Drives	3	HPD5 (F)	Recommended	cp043909.exe	update
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for VMware ESXi - VO1920JEUQQ Drive	4	HPD3 (G)	Recommended	CP043777.zip	update
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Linux (x64) - MB2000JFEPA and MB4000JFEPB Drives	2	HPD5 (F)	Recommended	firmware-hdd-326de7c0f2-HPD5-6.1.x86_64.rpm	update
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for VMware ESXi - MB6000JVYZD and MB4000JVYZC Drives	3	HPD4 (E)	Recommended	CP044489.zip	update
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for VMware ESXi - EG0300JFCKA, EG0600JEMCV, EG0900JFCKB	5	HPD6 (G)	Recommended	CP043839.zip	update

	and EG1200JEMDA Drives					
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Windows (x64) - MB008000JWWQ P and MB006000JWWQ N Drives	2	HPD2 (B)	Recommended	cp044201.exe	new
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for VMware ESXi - VO007680JWCN K and VO015300JWCN L Drives	3	HPD8 (C)	Critical	CP043835.zip	new
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Linux (x64) - EK0800JVYPN, EO1600JVYPP, MK0800JVYPQ and MO1600JVYPR Drives	2	HPD7 (B)	Critical	firmware-hdd- 481c8ea9a7- HPD7- 2.1.x86_64.rp m	new
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Windows (x64) - EO000400JWDK P, EO000800JWDK Q, EO001600JWDK R, MO000400JWDK U, MO000800JWDK V, MO001600JWDL A and MO003200JWDL B Drives	7	HPD2 (C)	Recommended	cp043918.exe	update

Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Windows (x64) - EG1800JEHMD Drive	5	HPD6 (F)	Recommended	cp043910.exe	update
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Linux (x64) - MO000400JWUF T, MO000800JWUF U, MO001600JWUF V, MO003200JWUG A, MO006400JWUG B, EO000400JWUG C, EO000800JWUG D and EO001600JWUG E Drives	2	HPD1 (D)	Optional	firmware-hdd-ef93133161-HPD1-4.1.x86_64.rpm	new
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Windows (x64) - EG000600JWFU V and EG001200JWFV A Drives	4	HPD3 (D)	Optional	cp043921.exe	update
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Linux (x64) - VO1920JEUQQ Drive	2	HPD3 (F)	Recommended	firmware-hdd-5d9e841607-HPD3-6.1.x86_64.rpm	update
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Linux (x64) - EG000600JWJN P and EG001200JWJN Q Drives	3	HPD3 (B)	Recommended	firmware-hdd-bdfb8e99d9-HPD3-2.1.x86_64.rpm	update

Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for VMware ESXi - EH0300JDYTH, EH0450JDYTK and EH0600JDYTL Drives	6	HPD6 (H)	Recommended	CP043783.zip	update
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Linux (x64) - EG000300JWFV B Drive	2	HPD2 (E)	Optional	firmware-hdd-c5cd837c29-HPD2-5.1.x86_64.rpm	update
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Windows (x64) - MB2000JFDSL and MB4000JFDSN Drives	4	HPD4 (E)	Recommended	cp043887.exe	update
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Linux (x64) - MO0200JEFNV, MO0400JEFPB, MO0800JEFPB, MO1600JEFPB, EO0200JEFPD, EO0400JEFPD and EO0800JEFPD Drives	2	HPD3 (F)	Recommended	firmware-hdd-71af849f3b-HPD3-6.1.x86_64.rpm	update
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Windows (x64) - EH0300JDYTH, EH0450JDYTK and EH0600JDYTL Drives	3	HPD6 (F)	Recommended	cp043911.exe	update
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Linux (x64) - MB006000JWKG N Drive	2	HPD1 (C)	Recommended	firmware-hdd-a886842a99-HPD1-3.1.x86_64.rpm	new

Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Windows (x64) - EG001800JWFV C Drive	5	HPD3 (C)	Recommended	cp043908.exe	update
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Linux (x64) - EG001800JWFV C Drive	3	HPD3 (E)	Recommended	firmware-hdd-693b9a2853-HPD3-5.1.x86_64.rpm	update
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Windows (x64) - MB4000JEFNC and MB6000JEFND Drives	7	HPD9 (E)	Recommended	cp043881.exe	update
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Linux (x64) - VK000960JWSS Q, VK001920JWSS R, VK003840JWSST , VK007680JWSS U and VO015300JWSS V Drives	2	HPD8 (C)	Critical	firmware-hdd-1e51a57347-HPD8-3.1.x86_64.rpm	new
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for VMware ESXi - EG000600JWFU V and EG001200JWFV A Drives	4	HPD3 (F)	Optional	CP043780.zip	update
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for VMware ESXi - MB6000JVYYV Drive	3	HPD2 (G)	Recommended	CP043854.zip	update

Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Windows (x64) - VO0480JFDGT, VO0960JFDGU, VO1920JFDGV and VO3840JFDHA Drives	2	HPD9 (B)	Recommended	cp043976.exe	update
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Windows (x64) - MB008000JWJR Q and MB006000JWJR P Drives	2	HPD5 (B)	Recommended	cp044157.exe	new
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for VMware ESXi - EH000900JWHP P, EH000600JWHP N and EH000300JWHP L Drives	4	HPD4 (C)	Recommended	CP043829.zip	new
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Windows (x64) - EG001800JWJN R and EG002400JWJNT Drives	5	HPD5 (B)	Recommended	cp043965.exe	update
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Windows (x64) - MB6000JEQUV and MB8000JEQVA Drives	2	HPDB (E)	Recommended	cp043893.exe	update
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for VMware ESXi -	4	HPD1 (D)	Optional	CP043808.zip	new

	MO000400JWUF T, MO000800JWUF U, MO001600JWUF V, MO003200JWUG A, MO006400JWUG B, EO000400JWUG C, EO000800JWUG D and EO001600JWUG E Drives					
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Windows (x64) - EG001800JWJNL and EG002400JWJN N Drives	1	HPD2 (D)	Recommended	cp043973.exe	new
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Linux (x64) - MB004000JWWQ B, MB002000JWWQ A and MB001000JWWP V Drives	2	HPD2 (B)	Recommended	firmware-hdd- adb3ab8147- HPD2- 2.1.x86_64.rp m	new
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for VMware ESXi - MB008000JWWQ P and MB006000JWWQ N Drives	4	HPD2 (B)	Recommended	CP044203.zip	new
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for VMware ESXi - MB014000JWRT H, MB012000JWRT	5	HPD2 (D)	Recommended	CP043825.zip	new

	F and MB010000JWRT E Drives					
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Linux (x64) - MB010000JWAY K and MB008000JWAY H Drives	3	HPD5 (E)	Critical	firmware-hdd-6ec35faf90-HPD5-5.1.x86_64.rpm	update
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Linux (x64) - MB002000JWFV N and MB004000JWFV P Drives	2	HPD3 (B)	Recommended	firmware-hdd-d7af557f47-HPD3-2.1.x86_64.rpm	new
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Linux (x64) - EH000900JWHP P, EH000600JWHP N and EH000300JWHP L Drives	2	HPD4 (B)	Recommended	firmware-hdd-8d68452816-HPD4-2.1.x86_64.rpm	new
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Windows (x64) - MB004000JWWQ B, MB002000JWWQ A and MB001000JWWP V Drives	4	HPD2 (B)	Recommended	cp044220.exe	new
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Linux (x64) - MB4000JEFNC and MB6000JEFND Drives	2	HPD9 (F)	Recommended	firmware-hdd-af802bb412-HPD9-6.1.x86_64.rpm	update

Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Linux (x64) - EG000600JWFU V and EG001200JWFV A Drives	3	HPD3 (E)	Optional	firmware-hdd-f0c91d2fe3-HPD3-5.1.x86_64.rpm	update
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for VMware ESXi - EH0300JEDHC, EH0450JEDHD and EH0600JEDHE Drives	4	HPD4 (H)	Recommended	CP043761.zip	update
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Windows (x64) - MB4000JEXYA and MB6000JEXYB Drives	1	HPD9 (C)	Recommended	cp043900.exe	update
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for VMware ESXi - MM1000JEFRB and MM2000JEFRC Drives	3	HPD8 (F)	Optional	CP043838.zip	update
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Linux (x64) - EG000300JWSJP , EG000600JWJN H and EG001200JWJN K Drive	3	HPD2 (C)	Recommended	firmware-hdd-24fe569b72-HPD2-3.1.x86_64.rpm	new
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for VMware ESXi - EG000300JWBH R Drive	2	HPD4 (E)	Recommended	CP044494.zip	update

Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Windows (x64) - EG0300JFCKA, EG0600JEMCV, EG0900JFCKB and EG1200JEMDA Drives	4	HPD6 (E)	Recommended	cp043879.exe	update
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Windows (x64) - MO0400JFFCF, MO0800JFFCH, MO1600JFFCK and MO3200JFFCL Drives	4	HPD9 (B)	Recommended	cp043975.exe	update
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Windows (x64) - VK000960JWSS Q, VK001920JWSS R, VK003840JWSST , VK007680JWSS U and VO015300JWSS V Drives	2	HPD8 (B)	Critical	cp043573.exe	new
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Linux (x64) - MM1000JEFRB and MM2000JEFRB Drives	3	HPD8 (E)	Optional	firmware-hdd-b04257b77b-HPD8-5.1.x86_64.rpm	update
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Windows (x64) - VO1920JEUQQ Drive	2	HPD3 (E)	Recommended	cp043906.exe	update

Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Windows (x64) - VO000960JWTK, VO001920JWTL, VO003840JWTN, VO007680JWTP, MO000400JWTBQ, MO000800JWTB R, MO001600JWBT, MO003200JWBU, MO006400JWTD, EO000400JWTV, EO000800JWTA and EO001600JWTC B Drives	10	HPD7 (C)	Recommended	cp043941.exe	new
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Windows (x64) - MM1000JFJTH Drive	6	HPD3 (D)	Optional	cp043891.exe	update
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for VMware ESXi - EG000600JWJNP and EG001200JWJNQ Drives	5	HPD3 (C)	Recommended	CP043849.zip	update
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Windows (x64) - MB014000JWUDB Drive	2	HPD2 (C)	Recommended	cp043958.exe	new

Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Windows (x64) - MO000400JWFW N, MO000800JWFW P, MO001600JWFW Q, MO003200JWFW R, MO000960JWFW T, MO001920JWFW U and MO003840JWFW V Drives	8	HPD5 (C)	Recommended	cp043948.exe	new
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Windows (x64) - VO007680JWCN K and VO015300JWCN L Drives	3	HPD8 (B)	Critical	cp043961.exe	new
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for VMware ESXi - EG000300JWSJP , EG000600JWJN H and EG001200JWJN K Drive	5	HPD2 (D)	Recommended	CP043828.zip	new
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for VMware ESXi - VO000480JWDA R, VO000960JWDA T, VO001920JWDA U and VO003840JWDA V Drives	3	HPD8 (D)	Critical	CP044493.zip	new

Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Linux (x64) - EH000900JWHP K and EH000600JWHP H Drives	2	HPD4 (B)	Recommended	firmware-hdd-c7df7ceedb-HPD4-2.1.x86_64.rpm	new
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Windows (x64) - EH0300JEDHC, EH0450JEDHD and EH0600JEDHE Drives	3	HPD4 (G)	Recommended	cp043875.exe	update
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Windows (x64) - MO000400JWUF T, MO000800JWUF U, MO001600JWUF V, MO003200JWUG A, MO006400JWUG B, EO000400JWUG C, EO000800JWUG D and EO001600JWUG E Drives	5	HPD1 (C)	Optional	cp043935.exe	new
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Linux (x64) - EH000600JWC P F and EH000900JWC P H Drives	3	HPD7 (D)	Recommended	firmware-hdd-a05f29cef3-HPD7-4.1.x86_64.rpm	update
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Linux (x64) - MB6000JVYYV Drive	2	HPD2 (F)	Recommended	firmware-hdd-0595c2a887-HPD2-6.1.x86_64.rpm	update

Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Linux (x64) - MB008000JWWQ P and MB006000JWWQ N Drives	2	HPD2 (B)	Recommended	firmware-hdd-ae6b41e855-HPD2-2.1.x86_64.rpm	new
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Linux (x64) - VO000960JWTK, VO001920JWTKBL, VO003840JWTKN, VO007680JWTKP, MO000400JWTKQ, MO000800JWTKR, MO001600JWTKT, MO003200JWTKU, MO006400JWTKD, EO000400JWTKV, EO000800JWTKA and EO001600JWTKB Drives	3	HPD7 (E)	Recommended	firmware-hdd-9ad359dac1-HPD7-5.1.x86_64.rpm	new
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Linux (x64) - EG001800JWJNR and EG002400JWJNT Drives	3	HPD5 (B)	Recommended	firmware-hdd-b1c9eaf74c-HPD5-2.1.x86_64.rpm	update
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for VMware ESXi - EG1800JEHMD Drive	4	HPD6 (H)	Recommended	CP043781.zip	update

Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Windows (x64) - EH0600JDYTN Drive	2	HPD7 (D)	Critical	cp043926.exe	new
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for VMware ESXi - MO000400JWFW N, MO000800JWFW P, MO001600JWFW Q, MO003200JWFW R, MO000960JWFW T, MO001920JWFW U and MO003840JWFW V Drives	3	HPD5 (D)	Recommended	CP043826.zip	new
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Linux (x64) - EH0300JDYTH, EH0450JDYTK and EH0600JDYTL Drives	2	HPD6 (G)	Recommended	firmware-hdd-b9340d29be-HPD6-7.1.x86_64.rpm	update
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for VMware ESXi - EH0600JDYTN Drive	4	HPD7 (F)	Critical	CP043798.zip	new
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for VMware ESXi - VO0480JFDGT, VO0960JFDGU, VO1920JFDGV and VO3840JFDHA Drives	6	HPD9 (B)	Recommended	CP043845.zip	update

Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Linux (x64) - MB2000JFEML and MB4000JFEMN Drives	2	HPD6 (F)	Critical	firmware-hdd-624b75c7e2-HPD6-6.1.x86_64.rpm	update
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Windows (x64) - MB008000JWRT D Drive	5	HPD1 (C)	Recommended	cp043951.exe	new
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Linux (x64) - MB2000JFDSL and MB4000JFDSN Drives	2	HPD4 (F)	Recommended	firmware-hdd-46fc43ab26-HPD4-6.1.x86_64.rpm	update
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Linux (x64) - MO0400JFFCF, MO0800JFFCH, MO1600JFFCK and MO3200JFFCL Drives	2	HPD9 (B)	Recommended	firmware-hdd-edf6dcd906-HPD9-2.1.x86_64.rpm	update
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Windows (x64) - EG000300JWBH R Drive	11	HPD4 (C)	Recommended	cp043897.exe	update
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Linux (x64) - MB012000JWDF D Drive	3	HPD2 (E)	Critical	firmware-hdd-aaf1014ede-HPD2-5.1.x86_64.rpm	new
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for VMware ESXi -	7	HPD5 (C)	Recommended	CP043848.zip	update

	EG001800JWJNR and EG002400JWJNT Drives					
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for VMware ESXi - MB4000JEXYA and MB6000JEXYB Drives	4	HPD9 (D)	Recommended	CP043805.zip	update
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Linux (x64) - EH000300JWCP K, EH000600JWCP L and EH000900JWCP N Drives	3	HPD5 (D)	Recommended	firmware-hdd- 3d97759111- HPD5- 4.1.x86_64.rp m	update
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Linux (x64) - MB014000JWRT H, MB012000JWRT F and MB010000JWRT E Drives	3	HPD2 (D)	Recommended	firmware-hdd- 10385ef3e6- HPD2- 4.1.x86_64.rp m	new
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for VMware ESXi - EH0300JDXBA, EH0450JDXBB and EH0600JDXBC Drives	4	HPD5 (G)	Recommended	CP043760.zip	update
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Linux (x64) - EG0300JFCKA, EG0600JEMCV, EG0900JFCKB and EG1200JEMDA Drives	3	HPD6 (G)	Recommended	firmware-hdd- ac3fda26eb- HPD6- 7.1.x86_64.rp m	update

Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Windows (x64) - MM1000JEFRB and MM2000JEFRC Drives	4	HPD8 (D)	Optional	cp043878.exe	update
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Windows (x64) - VO000960RWUE V, VO001920RWUF A, VO003840RWUF B, VO007680RWUF C, VO000960RWUF D, VO001920RWUF E and VO003840RWUF F Drives	1	HPD3 (B)	Recommended	cp043977.exe	new
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Windows (x64) - MB004000JWKG U Drive	5	HPD1 (C)	Recommended	cp043954.exe	new
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for VMware ESXi - EG1800JEMDB Drive	8	HPD5 (G)	Recommended	CP043759.zip	update
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for VMware ESXi - MM1000JFJTH Drive	5	HPD3 (F)	Optional	CP043775.zip	update
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Windows (x64) - MB8000JFECQ Drive	4	HPD7 (D)	Recommended	cp043899.exe	update

Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for VMware ESXi - MB004000JWWQ B, MB002000JWWQ A and MB001000JWWP V Drives	5	HPD2 (B)	Recommended	CP044219.zip	new
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Linux (x64) - MB4000JEXYA and MB6000JEXYB Drives	3	HPD9 (D)	Recommended	firmware-hdd-0f923833e9-HPD9-4.1.x86_64.rpm	update
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Linux (x64) - MB004000JWFV K and MB006000JWFV L Drives	2	HPD3 (B)	Recommended	firmware-hdd-f6d00bd17e-HPD3-2.1.x86_64.rpm	new
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Windows (x64) - MB012000JWDF D Drive	4	HPD2 (D)	Critical	cp043923.exe	new
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Windows (x64) - EH000300JWCP K, EH000600JWCP L and EH000900JWCP N Drives	4	HPD5 (C)	Recommended	cp043903.exe	update
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Windows (x64) - VO000480JWDA R,	2	HPD8 (B)	Critical	cp043572.exe	new

	VO000960JWDA T, VO001920JWDA U and VO003840JWDA V Drives					
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Linux (x64) - VO000480JWDA R, VO000960JWDA T, VO001920JWDA U and VO003840JWDA V Drives	2	HPD8 (B)	Critical	firmware-hdd- 2eb810cdd7- HPD8- 2.1.x86_64.rp m	new
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Linux (x64) - MB014000JWUD B Drive	3	HPD2 (C)	Recommended	firmware-hdd- cfd7436fcc- HPD2- 3.1.x86_64.rp m	new
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for VMware ESXi - EG0300FCSPH, EG0450FCSPK, EG0600FCSPK and EG0900FCSPN Drives	6	HPD2 (G)	Recommended	CP043769.zip	update
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Windows (x64) - MB010000JWAY K and MB008000JWAY H Drives	2	HPD5 (D)	Critical	cp043913.exe	update
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for VMware ESXi - MB002000JWFV N and	4	HPD3 (C)	Recommended	CP043832.zip	new

	MB004000JWFV P Drives					
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Linux (x64) - EG001800JWJNL and EG002400JWJN N Drives	1	HPD2 (D)	Recommended	firmware-hdd- 852266afdf- HPD2- 4.1.x86_64.rp m	new
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for VMware ESXi - EG1800JFHHM Drive	5	HPD7 (F)	Recommended	CP043782.zip	update
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for VMware ESXi - MB008000JWRT D Drive	6	HPD1 (D)	Recommended	CP043822.zip	new
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for VMware ESXi - VO000960JWTB K, VO001920JWTB L, VO003840JWTB N, VO007680JWTB P, MO000400JWTB Q, MO000800JWTB R, MO001600JWTB T, MO003200JWTB U, MO006400JWTC D, EO000400JWTB V, EO000800JWTC A, EO001600JWTC B Drives	3	HPD7 (D)	Recommended	CP043816.zip	new

Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Windows (x64) - EH0300JDXBA, EH0450JDXBB and EH0600JDXBC Drives	2	HPD5 (E)	Recommended	cp043882.exe	update
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for VMware ESXi - EG001800JWFV C Drive	4	HPD3 (D)	Recommended	CP043768.zip	update
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Windows (x64) - EK0800JVYPN, EO1600JVYPP, MK0800JVYPQ and MO1600JVYPR Drives	5	HPD7 (B)	Critical	cp044216.exe	new
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Windows (x64) - MO0200JEFNV, MO0400JEFPA, MO0800JEFPB, MO1600JEFPC, EO0200JEFPD, EO0400JEFPE and EO0800JEFPF Drives	2	HPD3 (E)	Recommended	cp043873.exe	update
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Linux (x64) - MM1000JFJTH Drive	2	HPD3 (E)	Optional	firmware-hdd-fa46c607d6-HPD3-5.1.x86_64.rpm	update
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Windows (x64) - MB2000JFEML and	6	HPD6 (E)	Critical	cp043914.exe	update

	MB4000JFEMN Drives					
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for VMware ESXi - EH000900JWHP K and EH000600JWHP H Drives	4	HPD4 (C)	Recommended	CP043743.zip	new
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Windows (x64) - MB006000JWKG N Drive	2	HPD1 (C)	Recommended	cp043953.exe	new
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for VMware ESXi - MO0400JFFCF, MO0800JFFCH, MO1600JFFCK and MO3200JFFCL Drives	5	HPD9 (B)	Recommended	CP043791.zip	update
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Linux (x64) - MB8000JFECQ Drive	2	HPD7 (E)	Recommended	firmware-hdd-252770cdda-HPD7-5.1.x86_64.rpm	update
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Linux (x64) - MB6000JVYZD and MB4000JVYZC Drives	2	HPD4 (D)	Recommended	firmware-hdd-e800e8d3b9-HPD4-4.1.x86_64.rpm	update
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for VMware ESXi - MB014000JWUD B Drive	4	HPD2 (D)	Recommended	CP043831.zip	new

Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Windows (x64) - MB1000JVYZL, MB2000JVYZN, MB3000JVYZP and MB4000JVYZQ Drives	2	HPD3 (C)	Recommended	cp043930.exe	update
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for VMware ESXi - MB004000JWFV K and MB006000JWFV L Drives	4	HPD3 (C)	Recommended	CP043847.zip	new
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Linux (x64) - EG0300FCSPH, EG0450FCSPK, EG0600FCSPL and EG0900FCSPN Drives	3	HPD2 (F)	Recommended	firmware-hdd-7c1a1734f9-HPD2-6.1.x86_64.rpm	update
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Windows (x64) - EH000900JWHP P, EH000600JWHP N and EH000300JWHP L Drives	4	HPD4 (B)	Recommended	cp043963.exe	new
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Windows (x64) - MB2000JFEPA and MB4000JFEPB Drives	8	HPD5 (E)	Recommended	cp043888.exe	update
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Linux (x64) -	2	HPD9 (B)	Recommended	firmware-hdd-8ed8893abd-HPD9-	update

	VO0480JFDGT, VO0960JFDGU, VO1920JFDGV and VO3840JFDHA Drives				2.1.x86_64.rpm	
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for VMware ESXi - VK000960JWSS Q, VK001920JWSS R, VK003840JWSST , VK007680JWSS U and VO015300JWSS V Drives	2	HPD8 (C)	Critical	CP043834.zip	new
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for VMware ESXi - MB006000JWKG N Drive	5	HPD1 (D)	Recommended	CP043819.zip	new
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Linux (x64) - EH0300JDXBA, EH0450JDXBB and EH0600JDXBC Drives	2	HPD5 (F)	Recommended	firmware-hdd- 1cbab97ff0- HPD5- 6.1.x86_64.rpm	update
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for VMware ESXi - MO0200JEFNV, MO0400JEFPA, MO0800JEFPB, MO1600JEFPC, EO0200JEFPD, EO0400JEFPE and EO0800JEFPF Drives	3	HPD3 (G)	Recommended	CP043752.zip	update

Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Linux (x64) - MO000400JWFW N, MO000800JWFW P, MO001600JWFW Q, MO003200JWFW R, MO000960JWFW T, MO001920JWFW U and MO003840JWFW V Drives	2	HPD5 (C)	Recommended	firmware-hdd-b8a60fbe9a-HPD5-3.1.x86_64.rpm	new
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Windows (x64) - EG000300JWSJP, EG000600JWJNH and EG001200JWJNK Drives	2	HPD2 (C)	Recommended	cp043960.exe	new
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Linux (x64) - VO000960RWUE V, VO001920RWUF A, VO003840RWUF B, VO007680RWUF C, VO000960RWUF D, VO001920RWUF E and VO003840RWUF F Drives	1	HPD3 (B)	Recommended	firmware-hdd-8fafc9efb2-HPD3-2.1.x86_64.rpm	new
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for VMware ESXi - MB2000JFDSL and	5	HPD4 (G)	Recommended	CP043858.zip	update

	MB4000JFDSN Drives					
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Windows (x64) - EG0300FCSPH, EG0450FCSPK, EG0600FCSPL and EG0900FCSPN Drives	4	HPD2 (E)	Recommended	cp043898.exe	update
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Windows (x64) - EG0600JETKA, EG0900JETKB and EG1200JETKC Drives	7	HPD7 (C)	Recommended	cp043884.exe	update
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Linux (x64) - EH0600JDYTN Drive	2	HPD7 (F)	Critical	firmware-hdd-f3faa195ff-HPD7-6.1.x86_64.rpm	new
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Linux (x64) - EG0300JEHLV, EG0600JEHMA, EG0900JEHMB and EG1200JEHMC Drives	3	HPD5 (G)	Recommended	firmware-hdd-31f91b8622-HPD5-7.1.x86_64.rpm	update
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for VMware ESXi - EG0600JETKA, EG0900JETKB and EG1200JETKC Drives	6	HPD7 (D)	Recommended	CP043758.zip	update
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Linux (x64) -	2	HPD4 (G)	Recommended	firmware-hdd-8c4a212ff9-HPD4-	update

	EH0300JEDHC, EH0450JEDHD and EH0600JEDHE Drives				7.1.x86_64.rpm	
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Windows (x64) - MB002000JWFV N and MB004000JWFV P Drives	9	HPD3 (B)	Recommended	cp043968.exe	new
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Linux (x64) - MB1000JVYZL, MB2000JVYZN, MB3000JVYZP and MB4000JVYZQ Drives	2	HPD3 (D)	Recommended	firmware-hdd- b85516c7d2- HPD3- 4.1.x86_64.rpm	update
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for VMware ESXi - MB008000JWJR Q and MB006000JWJR P Drives	4	HPD5 (B)	Recommended	CP044156.zip	new
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Linux (x64) - VO007680JWCN K and VO015300JWCN L Drives	2	HPD8 (B)	Critical	firmware-hdd- 4c048aaeb0- HPD8- 2.1.x86_64.rpm	new
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for VMware ESXi - EH000600JWCP F and EH000900JWCP H Drives	5	HPD7 (D)	Recommended	CP043770.zip	update

Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Windows (x64) - MB4000JEQNL and MB6000JEQNN Drives	4	HPDB (E)	Recommended	cp043876.exe	update
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for VMware ESXi - MB1000JVYZL, MB2000JVYZN, MB3000JVYZP and MB4000JVYZQ Drives	4	HPD3 (D)	Recommended	CP043790.zip	update
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Windows (x64) - MB014000JWRT H, MB012000JWRT F and MB010000JWRT E Drives	8	HPD2 (C)	Recommended	cp043950.exe	new
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for VMware ESXi - EK0800JVYPN, EO1600JVYPP, MK0800JVYPQ and MO1600JVYPR Drives	5	HPD7 (B)	Critical	CP044215.zip	new
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for VMware ESXi - EG0300JEHLV, EG0600JEHMA, EG0900JEHMB, and EG1200JEHMC Drives	4	HPD5 (H)	Recommended	CP043841.zip	update

Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for VMware ESXi - MB004000JWKG U Drive	7	HPD1 (D)	Recommended	CP043818.zip	new
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for VMware ESXi - MB2000JFEPA and MB4000JFEPB Drives	4	HPD5 (G)	Recommended	CP043857.zip	update
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Windows (x64) - EG1800JEMDB Drive	3	HPD5 (E)	Recommended	cp043940.exe	update
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for VMware ESXi - MB6000JEQUV and MB8000JEQVA Drives	3	HPDB (G)	Recommended	CP043774.zip	update
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Windows (x64) - EH000600JWCP F and EH000900JWCP H Drives	3	HPD7 (C)	Recommended	cp043902.exe	update
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for VMware ESXi - VO000960RWUE V, VO001920RWUF A, VO003840RWUF B, VO007680RWUF C, VO000960RWUF	2	HPD3 (C)	Recommended	CP043850.zip	new

	D, VO001920RWUF E and VO003840RWUF F Drives					
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for VMware ESXi - EO000400JWDK P, EO000800JWDK Q, EO001600JWDK R, MO000400JWDK U, MO000800JWDK V, MO001600JWDL A and MO003200JWDL B Drives	4	HPD2 (D)	Recommended	CP043788.zip	update
Firmware - Blade Infrastructur e	HPE BladeSystem c- Class Virtual Connect Firmware, Ethernet plus 8Gb 20-port and 8/16Gb 24-port FC Edition Component for Linux	9	4.85	Recommended	firmware- vceth-4.85- 1.1.x86_64.rp m	update
Firmware - Blade Infrastructur e	HPE BladeSystem c- Class Virtual Connect Firmware, Ethernet plus 8Gb 20-port and 8/16Gb 24-port FC Edition Component for Windows	11	4.85	Recommended	cp043332.exe	update
Firmware - Blade	Online HPE BladeSystem c- Class Onboard	3	4.96	Recommended	cp042537.exe	update

Infrastructure	Administrator Firmware Component for Windows					
Firmware - Blade Infrastructure	Online HP 6Gb SAS BL Switch Firmware Smart Component for Linux (x86/x64)	1	4.3.6.0 (B)	Optional	firmware-solex6gb-solex-4.3.6.0-2.1.i586.rpm	same
Firmware - Blade Infrastructure	Online HPE BladeSystem c-Class Onboard Administrator Firmware Component for Linux	3	4.96	Recommended	firmware-oa-4.96-1.1.x86_64.rpm	update
Firmware - Blade Infrastructure	Online HPE 6Gb SAS BL Switch Firmware Smart Component for Windows (x86/x64)	1	4.3.6.0 (C)	Optional	cp038273.exe	update
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for Linux (x64) - MB006000GWBX Q and MB008000GWBY L Drives	2	HPG8 (D)	Recommended	firmware-hdd-a1fd19f9ca-HPG8-4.1.x86_64.rpm	update
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for VMware ESXi - MB004000GWKG V Drive	5	HPG1 (D)	Recommended	CP043817.zip	new
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for Windows (x64) - VK000480GWTH A, VK000960GWTH B, VK001920GWTH	4	HPG1 (C)	Optional	cp043956.exe	new

	C and VK003840GWTH D Drives					
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for Windows (x64) - MM1000GEFQV and MM2000GEFRA Drives	6	HPG8 (E)	Recommended	cp043880.exe	update
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for VMware ESXi - MB008000GWRT C Drive	4	HPG1 (D)	Recommended	CP043820.zip	new
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for Linux (x64) - MK000240GWCE U, MK000480GWCE V, MK000960GWCF A and MK001920GWCF B Drives	2	HPG3 (E)	Recommended	firmware-hdd- 7677644a25- HPG3- 5.1.x86_64.rp m	new
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for Windows (x64) - MB012000GWDF E Drive	2	HPG2 (D)	Critical	cp043924.exe	new
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for VMware ESXi - MM1000GEFQV and MM2000GEFRA Drives	4	HPG8 (F)	Recommended	CP043795.zip	update
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for VMware ESXi -	4	HPG1 (D)	Recommended	CP043830.zip	new

	MB006000GWKG R Drive					
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for Windows (x64) - VK000240GWSR Q, VK000480GWSR R, VK000960GWSR T, VK001920GWSR U and VK003840GWSR V Drives	3	HPG3 (B)	Recommended	cp043972.exe	new
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for Linux (x64) - MK000480GWXF F, MK000960GWXF H, MK001920GWXF K and MK003840GWXF L Drives	2	HPG1 (B)	Recommended	firmware-hdd- 8e1e8083c5- HPG1- 2.1.x86_64.rp m	new
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for Linux (x64) - MB6000GEXXV Drive	2	HPG2 (H)	Recommended	firmware-hdd- a629fcea59- HPG2- 8.1.x86_64.rp m	update
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for Linux (x64) - MB2000GCWLT, MB3000GCWLU and MB4000GCWL V Drives	2	HPG4 (H)	Recommended	firmware-hdd- 2e70ce7412- HPG4- 8.1.x86_64.rp m	update
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for Linux (x64) - MK000480GWSS C, MK000960GWSS	2	HPG2 (B)	Recommended	firmware-hdd- f693ccc138- HPG2- 2.1.x86_64.rp m	new

	D, MK001920GWSS E and MK003840GWSS F Drives					
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for Windows (x64) - MB6000GEBTP Drive	3	HPG4 (F)	Recommended	cp043904.exe	update
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for Linux (x64) - MB014000GWUD A Drive	3	HPG2 (C)	Recommended	firmware-hdd- 41cdb1c9da- HPG2- 3.1.x86_64.rp m	new
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for Linux (x64) - VK000150GWCN N, VK000240GWCN P, VK000480GWCN Q, VK000960GWCN R and VK001600GWCN T Drives	2	HPG1 (D)	Recommended	firmware-hdd- 6e3845def5- HPG1- 4.1.x86_64.rp m	new
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for Windows (x64) - MB001000GWCB C and MB002000GWCB D Drives	7	HPG6 (C)	Recommended	cp043896.exe	update
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for VMware ESXi - MB2000GFEMH and MB4000GFEMK Drives	4	HPG6 (G)	Critical	CP043792.zip	update

Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for Windows (x64) - VK000150GWCN N, VK000240GWCN P, VK000480GWCN Q, VK000960GWCN R and VK001600GWCN T Drives	5	HPG1 (C)	Recommended	cp043931.exe	new
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for Linux (x64) - MB006000GWKG R Drive	2	HPG1 (C)	Recommended	firmware-hdd- 7f2a26e6d0- HPG1- 3.1.x86_64.rp m	new
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for VMware ESXi - MK000240GWCE U, MK000480GWCE V, MK000960GWCF A and MK001920GWCF B Drives	3	HPG3 (E)	Recommended	CP043794.zip	new
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for Linux (x64) - VK0120GFDKE, VK0240GFDKF, VK0480GFDKH, VK0960GFDKK, VK1920GFDKL and VK3840GFDKN Drives	3	HPG1 (H)	Recommended	firmware-hdd- a2d4b5c742- HPG1- 8.1.x86_64.rp m	update
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for Linux (x64) - MB8000GFECR Drive	2	HPG6 (D)	Recommended	firmware-hdd- 6d922fc9a8- HPG6- 4.1.x86_64.rp m	update

Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for Windows (x64) - MB004000GWW QH, MB002000GWW QF and MB001000GWW QE Drives	3	HPG2 (B)	Recommended	cp044228.exe	new
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for Windows (x64) - MK0960GECQK Drive	2	HPG3 (I)	Critical	cp043874.exe	update
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for Windows (x64) - VK000240GWTS V, VK000480GWTT A, VK000960GWTT B, VK001920GWTT C, VK003840GWTT D, MK000480GWTT H, MK000960GWTT K, MK001920GWTT L and MK003840GWTT N Drives	2	HPG3 (C)	Recommended	cp043946.exe	new
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for VMware ESXi - VK0240GEPQN, VK0480GEPQP and VK0960GEPQQ Drives	3	HPG1 (H)	Recommended	CP043776.zip	update
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for VMware ESXi	5	HPG4 (G)	Recommended	CP043856.zip	update

	- MB6000GEBTP Drive					
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for Linux (x64) - MB1000GDUNU, MB2000GDUNV, MB3000GDUPA and MB4000GDUPB Drives	3	HPG4 (H)	Recommended	firmware-hdd-3ab4c70e64-HPG4-8.1.x86_64.rpm	update
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for VMware ESXi - VK000240GWJPD, VK000480GWJPE, VK000960GWJPF, VK001920GWJPH, VK003840GWJPK, MK000240GWKVK, MK000480GWJPN, MK000960GWJPP and MK001920GWJPQ Drives	2	HPG5 (D)	Critical	CP043793.zip	new
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for Linux (x64) - VK0240GEPQN, VK0480GEPQP and VK0960GEPQQ Drives	2	HPG1 (G)	Recommended	firmware-hdd-1a516522d1-HPG1-7.1.x86_64.rpm	update
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for VMware ESXi - MB2000GCWLT, MB3000GCWLU and	4	HPG4 (I)	Recommended	CP043763.zip	update

	MB4000GCWLV Drives					
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for VMware ESXi - VK000480GWTH A, VK000960GWTH B, VK001920GWTH C and VK003840GWTH D Drives	3	HPG1 (D)	Optional	CP043827.zip	new
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for VMware ESXi - VK000240GWTS V, VK000480GWTT A, VK000960GWTT B, VK001920GWTT C, VK003840GWTT D, MK000480GWTT H, MK000960GWTT K, MK001920GWTT L and MK003840GWTT N Drives	4	HPG3 (D)	Recommended	CP043812.zip	new
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for Linux (x64) - MB6000GEBTP Drive	2	HPG4 (G)	Recommended	firmware-hdd-3243fce9a0-HPG4-7.1.x86_64.rpm	update
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for Linux (x64) - MB002000GWFG H and MB001000GWFG F Drives	2	HPG3 (F)	Optional	firmware-hdd-0b575b5895-HPG3-6.1.x86_64.rpm	update

Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for VMware ESXi - MB6000GEQUT and MB8000GEQUU Drives	3	HPGB (G)	Critical	CP043786.zip	update
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for Linux (x64) - MB2000GFEMH and MB4000GFEMK Drives	2	HPG6 (G)	Critical	firmware-hdd- 70e3962f98- HPG6- 7.1.x86_64.rp m	update
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for Windows (x64) - MK000240GWCE U, MK000480GWCE V, MK000960GWCF A and MK001920GWCF B Drives	2	HPG3 (D)	Recommended	cp043937.exe	new
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for Windows (x64) - MB008000GWW QU and MB006000GWW QT Drives	3	HPG2 (B)	Recommended	cp044209.exe	new
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for Linux (x64) - MB008000GWRT C Drive	2	HPG1 (C)	Recommended	firmware-hdd- 82894b9e0a- HPG1- 3.1.x86_64.rp m	new
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for VMware ESXi - MK003840GWHT E Drive	3	HPG6 (D)	Recommended	CP043810.zip	new

Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for Linux (x64) - VK007680GWSX N Drive	3	HPG2 (D)	Recommended	firmware-hdd-b460823f70-HPG2-4.1.x86_64.rpm	new
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for Windows (x64) - VK007680GWSX N Drive	4	HPG2 (C)	Recommended	cp043943.exe	new
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for Linux (x64) - MM1000GFJTE Drive	2	HPG5 (D)	Optional	firmware-hdd-95af9a555e-HPG5-4.1.x86_64.rpm	update
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for Windows (x64) - MR000240GWFL U, MR000480GWFL V, VR000480GWFM D, MR000960GWFM A, VR000960GWFM E, MR001920GWFM B and VR001920GWFM C Drives	7	HPGE (C)	Recommended	cp043928.exe	new
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for Windows (x64) - MM1000GFJTE Drive	2	HPG5 (C)	Optional	cp043929.exe	update
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for VMware ESXi - MB012000GWDF E Drive	9	HPG2 (E)	Critical	CP043801.zip	new

Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for Linux (x64) - VK000240GWTS V, VK000480GWTT A, VK000960GWTT B, VK001920GWTT C, VK003840GWTT D, MK000480GWTT H, MK000960GWTT K, MK001920GWTT L and MK003840GWTT N Drives	3	HPG3 (D)	Recommended	firmware-hdd- c566d63ca0- HPG3- 4.1.x86_64.rp m	new
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for Linux (x64) - MK0960GECQK Drive	2	HPG3 (I)	Critical	firmware-hdd- 3e34285be7- HPG3- 9.1.x86_64.rp m	update
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for VMware ESXi - MM1000GFJTE Drive	3	HPG5 (D)	Optional	CP043842.zip	update
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for Windows (x64) - VK000240GWJP D, VK000480GWJP E, VK000960GWJP F, VK001920GWJP H, VK003840GWJP K, MK000240GWKV K, MK000480GWJP N,	1	HPG5 (C)	Critical	cp043927.exe	new

	MK000960GWJP P and MK001920GWJP Q Drives					
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for Linux (x64) - MB4000GEQNH and MB6000GEQNK Drives	2	HPGB (G)	Critical	firmware-hdd- bfc95f0628- HPGB- 7.1.x86_64.rp m	update
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for Linux (x64) - VK000240GWSR Q, VK000480GWSR R, VK000960GWSR T, VK001920GWSR U and VK003840GWSR V Drives	2	HPG3 (B)	Recommended	firmware-hdd- db687966b4- HPG3- 2.1.x86_64.rp m	new
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for Windows (x64) - VK003840GWSX L Drive	5	HPG2 (C)	Recommended	cp043942.exe	new
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for VMware ESXi - VK0120GFDKE, VK0240GFDKF, VK0480GFDKH, VK0960GFDKK, VK1920GFDKL, and VK3840GFDKN Drives	5	HPG1 (H)	Recommended	CP043840.zip	update
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for Windows (x64) - MB001000GWF	5	HPG6 (C)	Recommended	cp043907.exe	update

	WK and MB002000GWF WL Drives					
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for VMware ESXi - MB1000GVYZE, MB2000GVYZF, MB3000GVYZH and MB4000GVYZK Drives	5	HPG4 (G)	Recommended	CP043859.zip	update
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for Windows (x64) - MK000480GWXF F, MK000960GWXF H, MK001920GWXF K and MK003840GWXF L Drives	4	HPG1 (B)	Recommended	cp044206.exe	new
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for Windows (x64) - MB006000GWJR R and MB008000GWJR T Drives	1	HPG4 (B)	Recommended	cp044437.exe	new
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for Linux (x64) - MM1000GEFQV and MM2000GEFRA Drives	2	HPG8 (F)	Recommended	firmware-hdd-ec908c3650-HPG8-6.1.x86_64.rpm	update
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for Windows (x64) - VK000240GWCF D, VK000480GWCF	4	HPG3 (D)	Recommended	cp043932.exe	new

	E, VK000960GWCF F, VK001920GWCF H and VK003840GWCF K Drives					
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for Windows (x64) - MB014000GWRT N, MB012000GWRT L and MB010000GWRT K Drives	3	HPG2 (C)	Recommended	cp043949.exe	new
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for Windows (x64) - EK000200GWEP D, EK000400GWEP E, EK000800GWEP F and EK001600GWEP H Drives	6	HPG3 (D)	Recommended	cp043939.exe	new
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for Linux (x64) - MB6000GVYYU Drive	2	HPG2 (G)	Recommended	firmware-hdd- bdc37cb37f- HPG2- 7.1.x86_64.rp m	update
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for VMware ESXi - VK007680GWSX N Drive	3	HPG2 (D)	Recommended	CP043815.zip	new
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for VMware ESXi - MB6000GEXXV Drive	5	HPG2 (I)	Recommended	CP043855.zip	update

Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for Linux (x64) - MB004000GWKG V Drive	2	HPG1 (C)	Recommended	firmware-hdd-ca21e169e2-HPG1-3.1.x86_64.rpm	new
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for Linux (x64) - VK000240GWJP D, VK000480GWJP E, VK000960GWJP F, VK001920GWJP H, VK003840GWJP K, MK000240GWKV K, MK000480GWJP N, MK000960GWJP P and MK001920GWJP Q Drives	1	HPG5 (D)	Critical	firmware-hdd-aef2a690c9-HPG5-4.1.x86_64.rpm	new
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for Windows (x64) - MB6000GVYYU Drive	2	HPG2 (F)	Recommended	cp043938.exe	update
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for Linux (x64) - MB001000GWJAN, MB002000GWF WA and MB004000GWF WB Drives	2	HPG1 (D)	Recommended	firmware-hdd-d39e7a7e75-HPG1-4.1.x86_64.rpm	new
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for VMware ESXi - MB001000GWCB C and MB002000GWCB D Drives	4	HPG6 (D)	Recommended	CP043772.zip	update

Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for Windows (x64) - VK000240GWEZ B, VK000480GWEZ C, VK000960GWEZ D, VK001920GWEZ E, MK000240GWEZ F, MK000480GWEZ H, MK000960GWEZ K and MK001920GWHR U Drives	4	HPGE (C)	Optional	cp043970.exe	new
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for Windows (x64) - MB8000GFECR Drive	6	HPG6 (C)	Recommended	cp043890.exe	update
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for Linux (x64) - MK003840GWHT E Drive	3	HPG6 (C)	Recommended	firmware-hdd- ac20a1e1c6- HPG6- 3.1.x86_64.rp m	new
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for VMware ESXi - MB001000GWF WK and MB002000GWF WL Drives	4	HPG6 (D)	Recommended	CP043860.zip	update
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for Linux (x64) - VK000240GWCF D, VK000480GWCF E, VK000960GWCF F, VK001920GWCF	2	HPG3 (E)	Recommended	firmware-hdd- f42438de3d- HPG3- 5.1.x86_64.rp m	new

	H and VK003840GWCF K Drives					
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for Linux (x64) - EK000200GWEP D, EK000400GWEP E, EK000800GWEP F and EK001600GWEP H Drives	2	HPG3 (E)	Recommended	firmware-hdd- 5bf9355926- HPG3- 5.1.x86_64.rp m	new
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for Windows (x64) - MB006000GWKG R Drive	4	HPG1 (C)	Recommended	cp043959.exe	new
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for Linux (x64) - VK003840GWSX L Drive	3	HPG2 (D)	Recommended	firmware-hdd- d1cf327bc4- HPG2- 4.1.x86_64.rp m	new
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for Windows (x64) - MB012000GWTF E and MB014000GWTF F Drives	3	HPG6 (B)	Optional	cp043962.exe	new
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for Windows (x64) - VK0120GFDKE, VK0240GFDKF, VK0480GFDKH, VK0960GFDKK, VK1920GFDKL and VK3840GFDKN Drives	2	HPG1 (F)	Recommended	cp043892.exe	update

Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for Linux (x64) - VK000240GWEZ B, VK000480GWEZ C, VK000960GWEZ D, VK001920GWEZ E, MK000240GWEZ F, MK000480GWEZ H, MK000960GWEZ K and MK001920GWHR U Drives	4	HPGE (C)	Optional	firmware-hdd- 3db7640485- HPGE- 3.1.x86_64.rp m	new
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for Windows (x64) - MB2000GFEMH and MB4000GFEMK Drives	6	HPG6 (F)	Critical	cp043915.exe	update
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for Linux (x64) - MB6000GVYZB and MB4000GVYZA Drives	2	HPG4 (D)	Recommended	firmware-hdd- 0a7d4aa47f- HPG4- 4.1.x86_64.rp m	new
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for Linux (x64) - MB004000GWW QH, MB002000GWW QF and MB001000GWW QE Drives	2	HPG2 (B)	Recommended	firmware-hdd- 12304c1aca- HPG2- 2.1.x86_64.rp m	new
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for VMware ESXi - MB8000GFECR Drive	3	HPG6 (E)	Recommended	CP044490.zip	update

Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for Windows (x64) - MB014000GWUD A Drive	5	HPG2 (C)	Recommended	cp043957.exe	new
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for Windows (x64) - VK000480GWSX F, VK000960GWSX H, VK001920GWSX K, MK000480GWUG F, MK000960GWUG H and MK001920GWUG K Drives	2	HPG2 (C)	Recommended	cp043944.exe	new
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for VMware ESXi - MB014000GWUD A Drive	5	HPG2 (D)	Recommended	CP043824.zip	new
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for VMware ESXi - VK000240GWEZ B, VK000480GWEZ C, VK000960GWEZ D, VK001920GWEZ E, MK000240GWEZ F, MK000480GWEZ H, MK000960GWEZ K and MK001920GWHR U Drives	5	HPGE (E)	Optional	CP044252.zip	new

Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for Windows (x64) - MB006000GWBX Q and MB008000GWBX L Drives	2	HPG8 (C)	Recommended	cp043945.exe	update
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for VMware ESXi - MB004000GWW QH, MB002000GWW QF and MB001000GWW QE Drives	10	HPG2 (B)	Recommended	CP044227.zip	new
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for Linux (x64) - VK000480GWTH A, VK000960GWTH B, VK001920GWTH C and VK003840GWTH D Drives	3	HPG1 (C)	Optional	firmware-hdd- 492a9952f6- HPG1- 3.1.x86_64.rp m	new
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for Windows (x64) - MB4000GEQNH and MB6000GEQNK Drives	2	HPGB (F)	Critical	cp043877.exe	update
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for Linux (x64) - MR000240GWFL U, MR000480GWFL V, VR000480GWFM D, MR000960GWFM A, VR000960GWFM	2	HPGE (C)	Recommended	firmware-hdd- 9196d4f720- HPGE- 3.1.x86_64.rp m	new

	E, MR001920GWFM B and VR001920GWFM C Drives					
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for Windows (x64) - XP0120GFJSL and XP0240GFJSN Drives	2	HPS4 (F)	Recommended	cp043894.exe	update
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for VMware ESXi - MB012000GWTF E and MB014000GWTF F Drives	4	HPG6 (C)	Optional	CP043833.zip	new
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for VMware ESXi - MK000480GWXF F, MK000960GWXF H, MK001920GWXF K and MK003840GWXF L Drives	4	HPG1 (B)	Recommended	CP044205.zip	new
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for VMware ESXi - XP0120GFJSL and XP0240GFJSN Drives	4	HPS4 (H)	Recommended	CP043778.zip	update
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for VMware ESXi - MB001000GWJA N, MB002000GWF	4	HPG1 (D)	Recommended	CP043800.zip	new

	WA and MB004000GWF WB Drives					
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for Linux (x64) - MB012000GWDF E Drive	3	HPG2 (E)	Critical	firmware-hdd-059b8654a6-HPG2-5.1.x86_64.rpm	new
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for Windows (x64) - MB008000GWRT C Drive	7	HPG1 (C)	Recommended	cp043952.exe	new
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for Windows (x64) - MB1000GVYZE, MB2000GVYZF, MB3000GVYZH and MB4000GVYZK Drives	4	HPG4 (G)	Recommended	cp043905.exe	update
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for VMware ESXi - MB014000GWRT N, MB012000GWRT L and MB010000GWRT K Drives	5	HPG2 (D)	Recommended	CP043823.zip	new
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for Linux (x64) - MB012000GWTF E and MB014000GWTF F Drives	2	HPG6 (B)	Optional	firmware-hdd-b78255e146-HPG6-2.1.x86_64.rpm	new
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for VMware ESXi -	3	HPG2 (D)	Recommended	CP043813.zip	new

	VK000480GWSX F, VK000960GWSX H, VK001920GWSX K, MK000480GWUG F, MK000960GWUG H and MK001920GWUG K Drives					
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for Linux (x64) - MB010000GWAY N and MB008000GWAY L Drives	2	HPG5 (E)	Critical	firmware-hdd- cc819d4bff- HPG5- 5.1.x86_64.rp m	update
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for Windows (x64) - MB4000GEFNA and MB6000GEFNB Drives	7	HPG6 (G)	Recommended	cp043866.exe	update
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for VMware ESXi - MB002000GWFG H and MB001000GWFG F Drives	4	HPG3 (F)	Optional	CP043789.zip	update
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for VMware ESXi - MB1000GDUNU, MB2000GDUNV, MB3000GDUPA and MB4000GDUPB Drives	5	HPG4 (I)	Recommended	CP043762.zip	update

Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for Windows (x64) - MK003840GWHT E Drive	2	HPG6 (C)	Recommended	cp043947.exe	new
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for Linux (x64) - MB014000GWRT N, MB012000GWRT L and MB010000GWRT K Drives	2	HPG2 (D)	Recommended	firmware-hdd- 6b7ce3da0e- HPG2- 4.1.x86_64.rp m	new
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for Windows (x64) - MB002000GWFG H and MB001000GWFG F Drives	6	HPG3 (E)	Optional	cp043920.exe	update
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for VMware ESXi - VK000240GWSR Q, VK000480GWSR R, VK000960GWSR T, VK001920GWSR U, VK003840GWSR V Drives	13	HPG3 (B)	Recommended	CP043836.zip	new
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for VMware ESXi - MB008000GWW QU and MB006000GWW QT Drives	5	HPG2 (B)	Recommended	CP044208.zip	new

Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for VMware ESXi - MB006000GWBX Q and MB008000GWBX L Drives	5	HPG8 (D)	Recommended	CP043809.zip	update
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for VMware ESXi - MK0960GECQK Drive	3	HPG3 (J)	Critical	CP043837.zip	update
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for VMware ESXi - MB006000GWJR R and MB008000GWJR T Drives	7	HPG4 (B)	Recommended	CP044435.zip	new
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for VMware ESXi - MK000480GWSS C, MK000960GWSS D, MK001920GWSS E and MK003840GWSS F Drives	3	HPG2 (C)	Recommended	CP044492.zip	new
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for Windows (x64) - VR000150GWEP P and VR000480GWEP R Drives	7	HPG1 (D)	Critical	cp043933.exe	new
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for Linux (x64) - VR000150GWEP P and	2	HPG1 (E)	Critical	firmware-hdd- b7eb905efe- HPG1- 5.1.x86_64.rp m	new

	VR000480GWEP R Drives					
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for VMware ESXi - VK000240GWCF D, VK000480GWCF E, VK000960GWCF F, VK001920GWCF H and VK003840GWCF K Drives.	5	HPG3 (E)	Recommended	CP043796.zip	new
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for VMware ESXi - VK000150GWCN N, VK000240GWCN P, VK000480GWCN Q, VK000960GWCN R and VK001600GWCN T Drives	4	HPG1 (D)	Recommended	CP043843.zip	new
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for VMware ESXi - MR000240GWFL U, MR000480GWFL V, VR000480GWFM D, MR000960GWFM A, VR000960GWFM E, MR001920GWFM B and VR001920GWFM C Drives	3	HPGE (D)	Recommended	CP043811.zip	new

Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for Linux (x64) - XP0120GFJSL and XP0240GFJSN Drives	3	HPS4 (H)	Recommended	firmware-hdd-d355375539-HPS4-8.1.x86_64.rpm	update
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for Windows (x64) - MB6000GEXXV Drive	2	HPG2 (G)	Recommended	cp043889.exe	update
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for Windows (x64) - MB001000GWJAN, MB002000GWFWA and MB004000GWFWB Drives	2	HPG1 (C)	Recommended	cp043936.exe	new
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for VMware ESXi - MB4000GEFNA and MB6000GEFNB Drives	7	HPG6 (G)	Recommended	CP043750.zip	update
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for VMware ESXi - VK003840GWSXL Drive	3	HPG2 (D)	Recommended	CP043814.zip	new
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for VMware ESXi - VR000150GWEP and VR000480GWEP R Drives	5	HPG1 (E)	Critical	CP043797.zip	new

Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for VMware ESXi - EK000200GWEP D, EK000400GWEP E, EK000800GWEP F and EK001600GWEP H Drives	4	HPG3 (E)	Recommended	CP043799.zip	new
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for Linux (x64) - MB006000GWJR R and MB008000GWJR T Drives	2	HPG4 (B)	Recommended	firmware-hdd- c993b31232- HPG4- 2.1.x86_64.rp m	new
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for Linux (x64) - MB001000GWF WK and MB002000GWF WL Drives	2	HPG6 (C)	Recommended	firmware-hdd- bfc4af697b- HPG6- 3.1.x86_64.rp m	update
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for Windows (x64) - MB2000GCWLT, MB3000GCWLU and MB4000GCWL V Drives	6	HPG4 (G)	Recommended	cp043886.exe	update
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for Windows (x64) - MB6000GVYZB and MB4000GVYZA Drives	3	HPG4 (C)	Recommended	cp043925.exe	new
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for Linux (x64) - MB1000GVYZE,	2	HPG4 (H)	Recommended	firmware-hdd- 0a7010918e- HPG4-	update

	MB2000GVYZF, MB3000GVYZH and MB4000GVYZK Drives				8.1.x86_64.rpm	
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for Linux (x64) - MB008000GWW QU and MB006000GWW QT Drives	2	HPG2 (B)	Recommended	firmware-hdd- 18e328f036- HPG2- 2.1.x86_64.rpm	new
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for Linux (x64) - MB4000GEFNA and MB6000GEFNB Drives	2	HPG6 (H)	Recommended	firmware-hdd- 40277d55d3- HPG6- 8.1.x86_64.rpm	update
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for VMware ESXi - MB6000GVYYU Drive	3	HPG2 (G)	Recommended	CP043806.zip	update
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for VMware ESXi - MB010000GWAY N and MB008000GWAY L Drives	7	HPG5 (E)	Critical	CP043207.zip	update
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for Windows (x64) - VK0240GEPQN, VK0480GEPQP and VK0960GEPQQ Drives	13	HPG1 (F)	Recommended	cp043895.exe	update
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for Windows (x64) -	3	HPG1 (C)	Recommended	cp043955.exe	new

	MB004000GWKG V Drive					
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for Windows (x64) - MK000480GWSS C, MK000960GWSS D, MK001920GWSS E and MK003840GWSS F Drives	2	HPG2 (B)	Recommended	cp043974.exe	new
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for Linux (x64) - VK000480GWSX F, VK000960GWSX H, VK001920GWSX K, MK000480GWUG F, MK000960GWUG H and MK001920GWUG K Drives	3	HPG2 (D)	Recommended	firmware-hdd- 9e87eecb3f- HPG2- 4.1.x86_64.rp m	new
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for Linux (x64) - MB6000GEQUT and MB8000GEQUU Drives	2	HPGB (G)	Critical	firmware-hdd- 1d7f19120b- HPGB- 7.1.x86_64.rp m	update
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for VMware ESXi - MB4000GEQNH and MB6000GEQNK Drives	4	HPGB (G)	Critical	CP043804.zip	update
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for Windows (x64)	5	HPG4 (G)	Recommended	cp043885.exe	update

	- MB1000GDUNU, MB2000GDUNV, MB3000GDUPA and MB4000GDUPB Drives					
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for VMware ESXi - MB6000GVYZB and MB4000GVYZA Drives	4	HPG4 (D)	Recommended	CP043807.zip	new
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for Windows (x64) - MB6000GEQUT and MB8000GEQUU Drives	3	HPGB (F)	Critical	cp043919.exe	update
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for Linux (x64) - MB001000GWCB C and MB002000GWCB D Drives	2	HPG6 (D)	Recommended	firmware-hdd-68b12e54d2-HPG6-4.1.x86_64.rpm	update
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for Windows (x64) - MB010000GWAY N and MB008000GWAY L Drives	3	HPG5 (D)	Critical	cp043916.exe	update
Firmware - System	Online ROM Flash for Linux - HPE Gen10 Innovation Engine Firmware for HPE Gen10 Servers	4	0.2.2.0	Optional	firmware-iegen10-0.2.2.0-1.1.x86_64.rpm	new

Firmware - System	ROM Flash Firmware Package - Server Platform Services (SPS) Firmware for HPE Gen10 Servers	4	05.01.04.113	Recommended	DL20ML30Gen10SPS_05.01.04.113.fwpkg	new
Firmware - System	Online Flash Component for Linux - NVMe Backplane PIC Firmware	3	8.4 (D)	Optional	firmware-nvmebackplane-8.4-4.1.i386.rpm	update
Firmware - System	Online Flash Component for Windows x64 - Gen10 NVMe Backplane PIC Firmware	3	1.20 (D)	Optional	cp037722.exe	same
Firmware - System	Online Flash Component for VMware - NVMe Backplane PIC Firmware	1	8.4 (D)	Optional	CP035161.zip	update
Firmware - System	Online ROM Flash for Windows x64 - HPE Gen10 Innovation Engine Firmware for HPE Gen10 Servers	5	0.2.2.0	Optional	cp043588.exe	new
Firmware - System	Online ROM Flash for Linux - Server Platform Services (SPS) Firmware for HPE Gen10 Servers	3	04.01.04.339	Recommended	firmware-spsgen10-04.01.04.339-1.1.x86_64.rpm	new
Firmware - System	Online Flash Component for Linux - Gen10 NVMe Backplane PIC Firmware	2	1.20 (E)	Optional	firmware-nvmebackplane-gen10-1.20-5.1.x86_64.rpm	same
Firmware - System	Online ROM Flash for Linux -	5	05.01.04.113	Recommended	firmware-dl20ml30gen1	new

	Server Platform Services (SPS) Firmware for HPE ProLiant DL20/ML30 Gen10				0sps-05.01.04.113-1.1.x86_64.rpm	
Firmware - System	ROM Flash Firmware Package - Server Platform Services (SPS) Firmware for HPE Gen10 Servers	4	04.01.04.339 (B)	Recommended	SPSGen10_04.01.04.339.fwpkg	new
Firmware - System	ROM Flash Firmware Package - HPE Gen10 Innovation Engine Firmware for HPE Gen10 Servers	3	0.2.2.0	Optional	IEGen10_0.2.2.0.fwpkg	new
Firmware - System	Firmware Package - Gen10 NVMe Backplane PIC Firmware	8	1.20	Optional	ISS_NVMe_BP_PIC_flashV1B20.fwpkg	same
Firmware - System	Online ROM Flash Component for Windows x64 - Server Platform Services (SPS) Firmware for HPE Gen10 Servers	3	04.01.04.339	Recommended	cp040928.exe	new
Firmware - System	Online ROM Flash Component for Windows x64 - Server Platform Services (SPS) Firmware for HPE ProLiant DL20/ML30 Gen10	7	05.01.04.113	Recommended	cp044100.exe	new
Firmware - System	Online ROM Flash Component for Windows x64 - Server Platform	6	05.01.04.113	Recommended	cp044092.exe	new

	Services (SPS) Firmware for HPE MicroServer Gen10 Plus					
Firmware - System	Online ROM Flash for Linux - Server Platform Services (SPS) Firmware for HPE MicroServer Gen10 Plus	5	05.01.04.113	Recommended	firmware-microservergen10plussps-05.01.04.113-1.1.x86_64.rpm	new
Firmware - System	Online Flash Component for Windows x64 - NVMe Backplane PIC Firmware	1	8.4 (E)	Optional	cp037743.exe	same
Firmware - Storage Controller	Online ROM Flash Component for VMware ESXi - HPE Apollo 2000 Gen10 Backplane Expander Firmware	45	1.00 (E)	Recommended	CP044326.zip	update
Firmware - Storage Controller	Online ROM Flash Component for VMware ESXi - Smart Array P230i, P430, P431, P731m, P830i, and P830	12	5.02 (A)	Recommended	CP044328.zip	update
Firmware - Storage Controller	Online ROM Flash Component for Windows (x64) - HPE Apollo 2000 Gen10 Backplane Expander Firmware	1	1.00 (B)	Optional	cp037609.exe	update
Firmware - Storage Controller	Online ROM Flash Component for Windows (x64) - HPE Apollo 4200 Backplane	2	1.78 (A)	Optional	cp038812.exe	update

	Expander Firmware					
Firmware - Storage Controller	HPE D3600/D3700/D3610/D3710 12Gb SAS Disk Enclosure ROM Flash Component for VMware (ESXi)	43	5.04	Recommended	CP041860.zip	update
Firmware - Storage Controller	Online ROM Flash Component for ESXi (x86) - HPE Smart Array P824i-p MR Gen10	30	24.23.0-0043 (A)	Recommended	CP044443.zip	update
Firmware - Storage Controller	HPE D6020 12Gb SAS Disk Enclosure ROM Flash Component for Linux (x64)	4	2.74 (G)	Recommended	firmware-d6020-2.74-7.1.x86_64.rpm	update
Firmware - Storage Controller	Online ROM Flash Component for Windows (x64) - Smart Array P220i, P222, P420i, P420, P421, P721m, and P822	3	8.32 (C)	Recommended	cp037741.exe	same
Firmware - Storage Controller	Supplemental Update / Online ROM Flash Component for Linux (x64) - Smart Array P220i, P222, P420i, P420, P421, P721m, and P822	2	8.32	Recommended	hp-firmware-smartarray-46a4d957a7-8.32-1.1.x86_64.rpm	same
Firmware - Storage Controller	HPE D3600/D3700/D3610/D3710 12Gb SAS Disk Enclosure ROM	16	5.04	Recommended	cp041861.exe	update

	Flash Component for Windows (x64)					
Firmware - Storage Controller	Supplemental Update / Online ROM Flash Component for Linux (x64) - HPE Smart Array P408i-p, P408e-p, P408i-a, P408i-c, E208i-p, E208e-p, E208i-c, E208i-a, P408i-sb, P408e-m, P204i-c, P204i-b, P816i-a and P416ie-m SR Gen10	9	3.00	Critical	firmware-smartarray-f7c07bdbbd-3.00-1.1.x86_64.rpm	update
Firmware - Storage Controller	Online ROM Flash Component for VMware ESXi - HPE 12Gb/s SAS Expander Firmware for HPE Smart Array Controllers and HPE HBA Controllers	35	4.22 (A)	Recommended	CP044309.zip	update
Firmware - Storage Controller	Online ROM Flash Component for Linux - HPE Host Bus Adapters H221	4	15.10.10.00 (C)	Optional	firmware-43d7eff89e-15.10.10.00-3.1.i386.rpm	update
Firmware - Storage Controller	Online ROM Flash Component for Linux (x64) - HPE Smart Array P824i-p MR Gen10	2	24.23.0-0043 (A)	Recommended	firmware-cafee9b6e4-24.23.0_0043-1.1.x86_64.rpm	update
Firmware - Storage Controller	Online ROM Flash Component for VMware ESXi - HPE Apollo 2000 System - SAS Expander	10	1.52 (A)	Recommended	CP044350.zip	update

Firmware - Storage Controller	Online ROM Flash Component for VMware ESXi - HPE Express Bay Enablement Switch Card	131	1.78 (C)	Recommended	CP044313.zip	update
Firmware - Storage Controller	Online ROM Flash Component for Linux (x64) – HPE Apollo 4200 Backplane Expander Firmware	4	1.78 (A)	Optional	firmware-smartarray-f18fdefd0b-1.78-1.1.x86_64.rpm	update
Firmware - Storage Controller	Supplemental Update / Online ROM Flash Component for Linux (x64) – HPE 12Gb/s SAS Expander Firmware for HPE Smart Array Controllers and HPE HBA Controllers	2	4.22	Recommended	firmware-smartarray-2de15b6882-4.22-1.1.x86_64.rpm	update
Firmware - Storage Controller	HPE D8000 12Gb SAS Disk Enclosure ROM Flash Component for Linux (x64)	5	0107	Recommended	firmware-d8000-0107-1.1.x86_64.rpm	new
Firmware - Storage Controller	Supplemental Update / Online ROM Flash Component for Linux (x64) - Smart Array P230i, P430, P431, P731m, P830i, and P830	8	5.02	Recommended	firmware-smartarray-112204add8-5.02-1.1.x86_64.rpm	update
Firmware - Storage Controller	Supplemental Update / Online ROM Flash Component for Linux (x64) - Smart Array and Smart HBA	2	7.00	Recommended	firmware-smartarray-ea3138d8e8-7.00-1.1.x86_64.rpm	update

	H240ar, H240nr, H240, H241, H244br, P240nr, P244br, P246br, P440ar, P440, P441, P542D, P741m, P840, P840ar, and P841					
Firmware - Storage Controller	Online ROM Flash Component for VMware ESXi - Smart Array P220i, P222, P420i, P420, P421, P721m, and P822	6	8.32 (D)	Recommended	CP044338.zip	update
Firmware - Storage Controller	Supplemental Update / Online ROM Flash Component for Linux (x64) – HPE Express Bay Enablement Switch Card	2	1.78 (B)	Optional	firmware-smartarray-94189dca85-1.78-2.1.x86_64.rpm	same
Firmware - Storage Controller	Online Firmware Flash for Windows - HPE NS204i-p Gen10+ Boot Controller	42	1.0.14.10 47	Recommended	cp041688.exe	new
Firmware - Storage Controller	Online ROM Flash Component for Windows (x64) - HPE Apollo 2000 System - SAS Expander	3	1.00 (E)	Recommended	cp037691.exe	same
Firmware - Storage Controller	Online ROM Flash Component for Windows (x64) - Smart Array and Smart HBA H240ar, H240nr, H240, H241, H244br, P240nr, P244br, P246br, P440ar, P440, P441, P542D,	13	7.00	Recommended	cp039995.exe	update

	P741m, P840, P840ar, and P841					
Firmware - Storage Controller	Online ROM Flash Component for Linux (x64) - HPE SAS Expander Firmware for HPE D2500sb Storage Blade	1	2.00 (B)	Optional	firmware-smartarray-1d0696d939-2.00-2.1.x86_64.rpm	same
Firmware - Storage Controller	Online ROM Flash Component for ESXi - HPE Smart Array P408i-p, P408e-p, P408i-a, P408i-c, E208i-p, E208e-p, E208i-c, E208i-a, P408i-sb, P408e-m, P204i-c, P204i-b, P816i-a and P416ie-m SR Gen10	15	3.00	Critical	CP044423.zip	update
Firmware - Storage Controller	Online ROM Flash Component for VMware ESXi - HPE Apollo 45xx Gen9 Backplane Expander Firmware	11	2.50 (A)	Recommended	CP044311.zip	update
Firmware - Storage Controller	Online Firmware Flash for ESXi - HPE NS204i-p Gen10+ Boot Controller	39	1.0.14.10 47	Recommended	CP041687.zip	new
Firmware - Storage Controller	Online ROM Flash Component for Windows (x64) - HPE SAS Expander Firmware for HPE D2500sb Storage Blade	1	2.00 (B)	Optional	cp037679.exe	same

Firmware - Storage Controller	Online ROM Flash Component for Windows (x64) - HPE Smart Array P824i-p MR Gen10	2	24.23.0-0043 (A)	Recommended	cp044919.exe	update
Firmware - Storage Controller	Online ROM Flash Component for Windows (x64) - HPE 12Gb/s SAS Expander Firmware for HPE Smart Array Controllers and HPE HBA Controllers	2	4.22	Recommended	cp040619.exe	update
Firmware - Storage Controller	HPE D3600/D3700/D3610/D3710 12Gb SAS Disk Enclosure ROM Flash Component for Linux (x64)	5	5.04	Recommended	firmware-d3000-5.04-1.1.x86_64.rpm	update
Firmware - Storage Controller	Online ROM Flash Component for Windows (x64) - HPE Apollo 45xx Gen9 Backplane Expander Firmware	1	2.50	Optional	cp038040.exe	update
Firmware - Storage Controller	HPE D8000 12Gb SAS Disk Enclosure ROM Flash Component for Windows (x64)	14	0107	Recommended	cp043713.exe	new
Firmware - Storage Controller	Online ROM Flash Component for VMware ESXi - HPE Apollo 45xx Gen10 Backplane Expander Firmware	34	1.56 (F)	Recommended	CP044312.zip	update

Firmware - Storage Controller	HPE D6020 12Gb SAS Disk Enclosure ROM Flash Component for Windows (x64)	8	2.74 (G)	Recommended	cp043654.exe	update
Firmware - Storage Controller	Online ROM Flash Component for VMware ESXi - HPE SAS Expander Firmware for HPE D2500sb Storage Blade	27	2.02 (A)	Recommended	CP044325.zip	update
Firmware - Storage Controller	Online ROM Flash Component for VMware ESXi - HPE Apollo 4200 Backplane Expander Firmware	14	1.79 (A)	Recommended	CP044499.zip	update
Firmware - Storage Controller	Online ROM Flash Component for Windows (x64) - HPE Host Bus Adapters H221	12	15.10.10.00 (E)	Optional	cp038049.exe	update
Firmware - Storage Controller	Supplemental Update / Online ROM Flash Component for Linux (x64) – HPE Apollo 45xx Gen9 Backplane Expander Firmware	1	2.50	Optional	firmware-smartarray-7bdfcd246b-2.50-1.1.x86_64.rpm	update
Firmware - Storage Controller	Online ROM Flash component for VMware ESXi - HPE Dual 8GB microSD USB	2	1.3.2.215 (B)	Recommended	CP037940.zip	update
Firmware - Storage Controller	Online ROM Flash Component for Windows (x64) - HPE Express	8	1.78 (C)	Optional	cp037730.exe	same

	Bay Enablement Switch Card					
Firmware - Storage Controller	Online ROM Flash Component for Linux (x64) – HPE Apollo 2000 Gen10 Backplane Expander Firmware	1	1.00 (B)	Optional	firmware-smartarray-9f082dff4-1.00-2.1.x86_64.rpm	update
Firmware - Storage Controller	Online ROM Flash Component for VMware ESXi - Smart Array and Smart HBA H240ar, H240nr, H240, H241, H244br, P240nr, P244br, P246br, P440ar, P440, P441, P542D, P741m, P840, P840ar, and P841	15	7.00 (B)	Recommended	CP044327.zip	update
Firmware - Storage Controller	Online Firmware Flash for Linux(x64) - HPE NS204i-p Gen10+ Boot Controller	33	1.0.14.1047	Recommended	firmware-9041739931-1.0.14.1047-1.1.x86_64.rpm	new
Firmware - Storage Controller	Online ROM Flash Component for Windows (x64) - HPE Smart Array P408i-p, P408e-p, P408i-a, P408i-c, E208i-p, E208e-p, E208i-c, E208i-a, P408i-sb, P408e-m, P204i-c, P204i-b, P816i-a and P416ie-m SR Gen10	11	3.00	Critical	cp044558.exe	update
Firmware - Storage Controller	Supplemental Update / Online ROM Flash Component for Linux (x64) - HPE	5	1.56 (C)	Recommended	firmware-smartarray-815b1ae26d-1.56-	update

	Apollo 45xx Gen10 Backplane Expander Firmware				3.1.x86_64.rpm	
Firmware - Storage Controller	HPE D6020 12Gb SAS Disk Enclosure ROM Flash Component for VMware (ESXi)	54	2.74 (G)	Recommended	CP043637.zip	update
Firmware - Storage Controller	Online ROM Flash Component for Linux (x64) - HPE Apollo 2000 System - SAS Expander	3	1.00 (C)	Recommended	firmware-smartarray-3bf7ece88e-1.00-3.1.x86_64.rpm	same
Firmware - Storage Controller	Online ROM Flash Component for Windows (x64) - Smart Array P230i, P430, P431, P731m, P830i, and P830	10	5.02	Optional	cp039412.exe	update
Firmware - Storage Controller	HPE D8000 12Gb SAS Disk Enclosure ROM Flash Component for VMware (ESXi)	16	0107	Recommended	CP043703.zip	new
Firmware - Storage Controller	Online ROM Flash Component for Windows (x64) - HPE Apollo 45xx Gen10 Backplane Expander Firmware	15	1.56 (C)	Recommended	cp037765.exe	update
Firmware - Storage Fibre Channel	HPE Firmware Flash for Emulex Fibre Channel Host Bus Adapters for Microsoft Windows Server	61	2020.09.01	Recommended	cp042254.exe	update

	2012 R2/2016/2019 x64					
Firmware - Storage Fibre Channel	HPE Firmware Flash for Emulex Mezzanine Fibre Channel Host Bus Adapters for Linux (x64)	19	2020.09. 01	Recommended	firmware-fc- mezz-emulex- 2020.09.01- 1.19.x86_64.rp m	new
Firmware - Storage Fibre Channel	HPE Firmware Flash for Emulex Mezzanine Fibre Channel Host Bus Adapters for VMware vSphere 6.5	22	2020.09. 01	Recommended	CP042260.zip	new
Firmware - Storage Fibre Channel	HPE Firmware Flash for QLogic Fibre Channel Host Bus Adapters for VMware vSphere 6.5	23	2020.09. 01	Recommended	CP042515.zip	update
Firmware - Storage Fibre Channel	HPE Firmware Online Flash for QLogic Fibre Channel Host Bus Adapters - Microsoft Windows Server 2012R2/2016/201 9 (x86_64)	18	2020.09. 01	Recommended	cp042518.exe	update
Firmware - Storage Fibre Channel	HPE Firmware Online Flash for QLogic Mezzanine Fibre Channel Host Bus Adapters - Microsoft Windows Server 2012R2/2016/201 9 (x86_64)	17	2020.09. 01	Recommended	cp042211.exe	new
Firmware - Storage	HPE Firmware Flash for Emulex	18	2020.09. 01	Recommended	CP042545.zip	new

Fibre Channel	Mezzanine Fibre Channel Host Bus Adapters for VMware vSphere 7.0					
Firmware - Storage Fibre Channel	HPE Firmware Flash for QLogic Fibre Channel Host Bus Adapters for VMware vSphere 7.0	32	2020.09.01	Recommended	CP042547.zip	new
Firmware - Storage Fibre Channel	HPE Firmware Flash for QLogic Mezzanine Fibre Channel Host Bus Adapters - Linux (x86_64)	25	2020.09.01	Recommended	firmware-fc-mezz-qlogic-2020.09.01-1.25.x86_64.rpm	new
Firmware - Storage Fibre Channel	HPE Firmware Flash for QLogic Fibre Channel Mezzanine Host Bus Adapters for VMware vSphere 7.0	11	2020.09.01	Recommended	CP042548.zip	new
Firmware - Storage Fibre Channel	HPE Firmware Flash for Emulex Fibre Channel Host Bus Adapters for VMware vSphere 6.5	32	2020.09.01	Recommended	CP042251.zip	update
Firmware - Storage Fibre Channel	HPE Firmware Flash for QLogic Mezzanine Fibre Channel Host Bus Adapters for VMware vSphere 6.7	15	2020.09.01	Recommended	CP042209.zip	new
Firmware - Storage Fibre Channel	HPE Firmware Flash for QLogic Fibre Channel Host Bus Adapters for	30	2020.09.01	Recommended	CP042516.zip	update

	VMware vSphere 6.7					
Firmware - Storage Fibre Channel	HPE Firmware Flash for Emulex Mezzanine Fibre Channel Host Bus Adapters for Microsoft Windows Server 2012R2/2016/2019 x64	37	2020.09.01	Recommended	cp042263.exe	new
Firmware - Storage Fibre Channel	HPE Firmware Flash for Emulex Fibre Channel Host Bus Adapters for VMware vSphere 7.0	25	2020.09.01	Recommended	CP042544.zip	new
Firmware - Storage Fibre Channel	HPE Firmware Flash for QLogic Mezzanine Fibre Channel Host Bus Adapters for VMware vSphere 6.5	18	2020.09.01	Recommended	CP042208.zip	new
Firmware - Storage Fibre Channel	HPE Firmware Flash for Emulex Mezzanine Fibre Channel Host Bus Adapters for VMware vSphere 6.7	27	2020.09.01	Recommended	CP042261.zip	new
Firmware - Storage Fibre Channel	HPE Firmware Flash for QLogic Fibre Channel Host Bus Adapters - Linux (x86_64)	26	2020.09.01	Recommended	firmware-fc-qlogic-2020.09.01-1.26.x86_64.rpm	update
Firmware - Storage Fibre Channel	HPE Firmware Flash for Emulex Fibre Channel Host Bus Adapters for	30	2020.09.01	Recommended	CP042252.zip	update

	VMware vSphere 6.7					
Firmware - Storage Fibre Channel	HPE Firmware Flash for Emulex Fibre Channel Host Bus Adapters for Linux (x64)	22	2020.09.01	Recommended	firmware-fc-emulex-2020.09.01-1.22.x86_64.rpm	update
Firmware - Power Management	Online ROM Flash for Linux - Power Management Controller	1	4.1 (E)	Recommended	hp-firmware-powerpic-dl580-4.1-5.i386.rpm	same
Firmware - Power Management	Online ROM Flash for VMware ESXi - Advanced Power Capping Microcontroller Firmware for HPE Gen9 Servers	1	1.0.9 (I)	Optional	CP037782.zip	same
Firmware - Power Management	Online ROM Flash for Linux - Advanced Power Capping Microcontroller Firmware for HPE Gen9 Servers	2	1.0.9 (J)	Optional	firmware-powerpic-gen9-1.0.9-10.1.i386.rpm	update
Firmware - Power Management	Online ROM Flash for Windows x64 - Advanced Power Capping Microcontroller Firmware for HPE Gen9 Servers	1	1.0.9(I)	Optional	cp037781.exe	same
Firmware - Power Management	Online ROM Flash for VMware ESXi - Power Management Controller	2	4.1 (E)	Recommended	CP026094.zip	same
Firmware - Power Management	Online ROM Flash for Windows x64 -	4	4.1 (F)	Recommended	cp037764.exe	same

	Power Management Controller for HPE ProLiant DL580 Gen9/Gen8 Servers					
Firmware - PCIe NVMe Storage Disk	Online NVMe SSD Flash Component for VMware ESXi - VO002000KWVV C, VO004000KWVU R, MO001600KWVU U, MO003200KWVU V and MO006400KWVV A Drives	6	HPK1 (B)	Recommended	CP044243.zip	new
Firmware - PCIe NVMe Storage Disk	Online NVMe SSD Flash Component for Linux (x64) - MO001600KWVN B, MO003200KWVN C and MO006400KWVN D Drives	8	HPK2 (B)	Recommended	firmware-hdd- cea219e4b1- HPK2- 2.1.x86_64.rp m	new
Firmware - PCIe NVMe Storage Disk	Online NVMe SSD Flash Component for Windows (x64) - MT001600KWST B, MT003200KWST C and MT006400KWST D Drives	2	HPK2 (B)	Recommended	cp044248.exe	new
Firmware - PCIe NVMe Storage Disk	Online NVMe SSD Flash Component for Linux (x64) - MO0400KEFHN, MO0800KEFHP, MO1600KEFHQ,	2	HPK4 (E)	Recommended	firmware-hdd- 2a5b65f157- HPK4- 5.1.x86_64.rp m	update

	MO2000KEFHR, MT0800KEXUU and MT1600KEXUV Drives					
Firmware - PCIe NVMe Storage Disk	Online NVMe SSD Flash Component for Windows (x64) - VO002000KWVV C, VO004000KWVU R, MO001600KWVU U, MO003200KWVU V and MO006400KWVV A Drives	1	HPK1 (B)	Recommended	cp044244.exe	new
Firmware - PCIe NVMe Storage Disk	Online NVMe SSD Flash Component for VMware ESXi - MT001600KWST B, MT003200KWST C and MT006400KWST D Drives	5	HPK2 (B)	Recommended	CP044246.zip	new
Firmware - PCIe NVMe Storage Disk	Online NVMe SSD Flash Component for VMware ESXi - MO001600KWVN B, MO003200KWVN C and MO006400KWVN D Drives	7	HPK2	Recommended	CP043321.zip	new
Firmware - PCIe NVMe Storage Disk	Online NVMe SSD Flash Component for Windows (x64) - VS000480KXALB drive	13	85030G0 0 (B)	Recommended	cp044288.exe	new

Firmware - PCIe NVMe Storage Disk	Online NVMe SSD Flash Component for Windows (x64) - VS000480KWDU P, VS000960KWDU Q, MS000400KWDU R and MS000800KWDU T Drives	2	HPK4 (B)	Recommended	cp043871.exe	new
Firmware - PCIe NVMe Storage Disk	Online NVMe SSD Flash Component for Windows (x64) - MT001600KWHA C, MT003200KWHA D and MT006400KWHA E Drives	4	HPS1 (B)	Recommended	cp043865.exe	new
Firmware - PCIe NVMe Storage Disk	Online NVMe SSD Flash Component for Linux (x64) - VO001000KWJS E, VO002000KWJS F, VO004000KWJS H, VT004000KWJS U, MO001600KWJS N and MO003200KWJS Q Drives	3	HPK1 (E)	Critical	firmware-hdd- 1656c1b14a- HPK1- 5.1.x86_64.rp m	new
Firmware - PCIe NVMe Storage Disk	Online NVMe SSD Flash Component for Linux (x64) - VS000480KXALB Drive	16	85030G0 0 (B)	Recommended	firmware-hdd- 805abb7e9c- 85030G00- 2.1.x86_64.rp m	new
Firmware - PCIe NVMe Storage Disk	Online NVMe SSD Flash Component for Windows (x64) -	2	HPK3 (B)	Recommended	cp043969.exe	new

	ET000750KWJTF , EO000750KWTX C and EO000375KWJU C Drives					
Firmware - PCIe NVMe Storage Disk	Online NVMe SSD Flash Component for VMware ESXi - ET000750KWJTF , EO000750KWTX C and EO000375KWJU C Drives	5	HPK3 (B)	Recommended	CP043846.zip	new
Firmware - PCIe NVMe Storage Disk	Online NVMe SSD Flash Component for Windows (x64) - MK000400KWDU K, VK000480KWDU E, MK000800KWDU L, VK000960KWDU F, MK001600KWDU N and VK001920KWDU H Drives	5	HPK4 (B)	Recommended	cp043864.exe	update
Firmware - PCIe NVMe Storage Disk	Online NVMe SSD Flash Component for Linux (x64) - MT001600KWST B, MT003200KWST C and MT006400KWST D Drives	3	HPK2 (B)	Recommended	firmware-hdd- 9ccac59e76- HPK2- 2.1.x86_64.rp m	new
Firmware - PCIe NVMe Storage Disk	Online NVMe SSD Flash Component for Windows (x64) - VO0400KEFJB, VO1200KEFJC	2	HPK4 (B)	Recommended	cp043863.exe	new

	and VO2000KEFJD Drives					
Firmware - PCIe NVMe Storage Disk	Online NVMe SSD Flash Component for Linux (x64) - MK000400KWDU K, VK000480KWDU E, MK000800KWDU L, VK000960KWDU F, MK001600KWDU N and VK001920KWDU H Drives	2	HPK4 (D)	Recommended	firmware-hdd- b45e49679c- HPK4- 4.1.x86_64.rp m	update
Firmware - PCIe NVMe Storage Disk	Online NVMe SSD Flash Component for Windows (x64) - LO0400KEFJQ, LO0800KEFJR, LO1600KEFJT, LO2000KEFJU, LT0800KEXVA, LT1600KEXVB, and LT2000KEXVC Drives	4	HPK4 (B)	Recommended	cp043870.exe	new
Firmware - PCIe NVMe Storage Disk	Online NVMe SSD Flash Component for Windows (x64) - MO001600KWVN B, MO003200KWVN C and MO006400KWVN D Drives	2	HPK2	Recommended	cp044393.exe	new
Firmware - PCIe NVMe Storage Disk	Online NVMe SSD Flash Component for Linux (x64) - ET000750KWJTF ,	2	HPK3 (B)	Recommended	firmware-hdd- c4355d15c4- HPK3- 2.1.x86_64.rp m	new

	EO000750KWTX C and EO000375KWJU C Drives					
Firmware - PCIe NVMe Storage Disk	Online NVMe SSD Flash Component for Windows (x64) - VO001000KWJS E, VO002000KWJS F, VO004000KWJS H, VT004000KWJS U, MO001600KWJS N and MO003200KWJS Q Drives	1	HPK1 (B)	Recommended	cp043872.exe	new
Firmware - PCIe NVMe Storage Disk	Online NVMe SSD Flash Component for VMware ESXi - LO0400KEFJQ, LO0800KEFJR, LO1600KEFJT, LO2000KEFJU, LT0800KEXVA, LT1600KEXVB, and LT2000KEXVC Drives	2	HPK4 (D)	Recommended	CP044498.zip	new
Firmware - PCIe NVMe Storage Disk	Online NVMe SSD Flash Component for VMware ESXi - MT001600KWHA C, MT003200KWHA D and MT006400KWHA E Drives	3	HPS1 (D)	Recommended	CP044496.zip	new
Firmware - PCIe NVMe Storage Disk	Online NVMe SSD Flash Component for Linux (x64) - VO002000KWVV	2	HPK1 (C)	Recommended	firmware-hdd- 92d876cfea- HPK1- 3.1.x86_64.rp m	new

	C, VO004000KWVU R, MO001600KWVU U, MO003200KWVU V and MO006400KWVV A Drives					
Firmware - PCIe NVMe Storage Disk	Online NVMe SSD Flash Component for VMware ESXi - VS000480KWDU P, VS000960KWDU Q, MS000400KWDU R and MS000800KWDU T Drives	6	HPK4 (C)	Recommended	CP043757.zip	new
Firmware - PCIe NVMe Storage Disk	Online NVMe SSD Flash Component for VMware ESXi - VS000480KXALB Drive	3	85030G0 0 (C)	Recommended	CP044993.zip	new
Firmware - PCIe NVMe Storage Disk	Online NVMe SSD Flash Component for Linux (x64) - LO0400KEFJQ, LO0800KEFJR, LO1600KEFJT, LO2000KEFJU, LT0800KEXVA, LT1600KEXVB and LT2000KEXVC Drives	3	HPK4 (E)	Recommended	firmware-hdd- d64642c780- HPK4- 5.1.x86_64.rp m	update
Firmware - PCIe NVMe Storage Disk	Online NVMe SSD Flash Component for Linux (x64) - MT001600KWHA C, MT003200KWHA D and	2	HPS1 (D)	Recommended	firmware-hdd- 8e8ddc5265- HPS1- 4.1.x86_64.rp m	new

	MT006400KWHAE Drives					
Firmware - PCIe NVMe Storage Disk	Online NVMe SSD Flash Component for VMware ESXi - VO001000KWJSE, VO002000KWJSF, VO004000KWJSH, VT004000KWJSU, MO001600KWJSN and MO003200KWJSQ Drives	7	HPK1 (D)	Critical	CP044495.zip	new
Firmware - PCIe NVMe Storage Disk	Online NVMe SSD Flash Component for VMware ESXi - MO0400KEFHN, MO0800KEFHP, MO1600KEFHQ, MO2000KEFHR, MT0800KEXUU and MT1600KEXUV Drives	4	HPK4 (C)	Recommended	CP043753.zip	new
Firmware - PCIe NVMe Storage Disk	Online NVMe SSD Flash Component for VMware ESXi - MK000400KWDUK, VK000480KWDU E, MK000800KWDU L, VK000960KWDU F, MK001600KWDU N and VK001920KWDU H Drives	3	HPK4 (E)	Recommended	CP044491.zip	new

Firmware - PCIe NVMe Storage Disk	Online NVMe SSD Flash Component for Linux (x64) - VO0400KEFJB, VO1200KEFJC and VO2000KEFJD Drives	2	HPK4 (E)	Recommended	firmware-hdd- 9a826ccd8a- HPK4- 5.1.x86_64.rp m	update
Firmware - PCIe NVMe Storage Disk	Online NVMe SSD Flash Component for VMware ESXi - VO0400KEFJB, VO1200KEFJC and VO2000KEFJD Drives	4	HPK4 (D)	Recommended	CP044497.zip	new
Firmware - PCIe NVMe Storage Disk	Online NVMe SSD Flash Component for Windows (x64) - MO0400KEFHN, MO0800KEFHP, MO1600KEFHQ, MO2000KEFHR, MT0800KEXUU and MT1600KEXUV Drives	3	HPK4 (B)	Recommended	cp043603.exe	new
Firmware - PCIe NVMe Storage Disk	Online NVMe SSD Flash Component for Linux (x64) - VS000480KWDU P, VS000960KWDU Q, MS000400KWDU R and MS000800KWDU T Drives	3	HPK4 (D)	Recommended	firmware-hdd- 95a2e5abcb- HPK4- 4.1.x86_64.rp m	new
Firmware - NVDIMM	Firmware package for HPE Persistent Memory featuring Intel Optane DC Persistent	3	01.02.00. 5435 (B)	Recommended	dcppmm_01.02. 00.5435.fwpkg	new

	Memory on HPE Gen10 Servers					
Firmware - NVDIMM	Online Flash Component for Linux - 16GB NVDIMM-N DDR4-2666	6	1.04 (A)	Optional	firmware-nvdim-16gb-1.04-1.1.x86_64.rpm	update
Firmware - NVDIMM	Online Flash Component for Linux - HPE Persistent Memory featuring Intel Optane DC Persistent Memory on HPE Gen10 Servers	2	1.2.0.5435 (B)	Recommended	firmware-dcpmm-1.2.0.5435-2.1.x86_64.rpm	new
Firmware - NVDIMM	Online Flash Component for Windows x64 - 16GB NVDIMM-N DDR4-2666	5	1.04 (A)	Optional	cp037531.exe	update
Firmware - NVDIMM	Firmware Package - 16GB NVDIMM-N DDR4-2666	2	1.04 (B)	Recommended	nvdim-16gb_1.04.fwpkg	update
Firmware - NVDIMM	Online Flash Component for Windows x64 - HPE Persistent Memory featuring Intel Optane DC Persistent Memory on HPE Gen10 Servers	3	1.2.0.5375	Recommended	cp039525.exe	new
Firmware - Lights-Out Management	Online ROM Flash Component for Windows x64 - HPE Integrated Lights-Out 5	66	2.30	Recommended	cp040154.exe	update
Firmware - Lights-Out Management	Online ROM Flash Component for VMware ESXi	1	2.74 (a)	Recommended	CP045029.zip	update

	- HPE Integrated Lights-Out 4					
Firmware - Lights-Out Management	Online ROM Flash Firmware Package - HPE Integrated Lights-Out 5	71	2.30	Recommended	ilo5_230.fwpkg	update
Firmware - Lights-Out Management	Online ROM Flash Component for Linux - HPE Integrated Lights-Out 4	3	2.74	Recommended	firmware-ilo4-2.74-1.1.i386.rpm	update
Firmware - Lights-Out Management	Online ROM Flash Component for Windows x64 - HPE Integrated Lights-Out 4	9	2.74	Recommended	cp043717.exe	update
Firmware - Lights-Out Management	Online ROM Flash Component for Linux - HPE Integrated Lights-Out 5	66	2.30	Recommended	firmware-ilo5-2.30-1.1.x86_64.rpm	update
Firmware (Entitlement Required) - Storage Controller	HP D2600/D2700 6Gb SAS Disk Enclosure ROM Flash Component for Windows (x64)	5	0150 (B)	Recommended	cp028806.exe	same
Firmware (Entitlement Required) - Storage Controller	HP D2600/D2700 6Gb SAS Disk Enclosure ROM Flash Component for Linux (x64)	8	0150 (B)	Recommended	hp-firmware-d2600-d2700-0150-2.1.x86_64.rpm	same
Software - Storage Fibre Channel HBA	HPE Emulex Fibre Channel Enablement Kit for Red Hat Enterprise Linux 7 Server	10	12.6.272.0	Recommended	HP-CNA-FC-Emulex-Enablement-Kit-12.6.272.0-1.rhel7.x86_64.rpm	update
Software - Storage Fibre	HPE Emulex(BRCM) Fibre Channel	2	12.0.126 4.0 (b)	Recommended	HP-CNA-FC-Broadcom-Enablement-	update

Channel HBA	Over Ethernet Enablement Kit for SUSE Linux Enterprise Server 15				Kit-12.0.1264.0-1.sles15sp1.x86_64.rpm	
Software - Storage Fibre Channel HBA	HPE Emulex Mezzanine Fibre Channel Enablement Kit for SUSE Linux Enterprise Server 15	10	12.4.256.0	Recommended	HP-CNA-FC-Emulex-Enablement-Kit-12.4.256.0-1.sles15sp1.x86_64.rpm	new
Software - Storage Fibre Channel HBA	HPE QLogic Smart SAN enablement kit for Linux	4	3.3-3 (h)	Optional	hpe-qlogic-smartsan-enablement-kit-3.3-3.x86_64.rpm	update
Software - Storage Fibre Channel HBA	HPE Emulex Fibre Channel Enablement Kit for Red Hat Enterprise Linux 8 Server	10	12.6.272.0	Recommended	HP-CNA-FC-Emulex-Enablement-Kit-12.6.272.0-1.rhel8.x86_64.rpm	new
Software - Storage Fibre Channel HBA	Fibreutils for HPE Storage Fibre Channel Host Bus Adapters for Linux -Red Hat Enterprise Linux (RHEL)	4	4.1-1 (c)	Optional	fibreutils-4.1-1_rhel.x86_64.rpm	update
Software - Storage Fibre Channel HBA	HPE QLogic Mezzanine Fibre Channel Enablement Kit for Linux	5	6.0.0.0-12	Recommended	HP-CNA-FC-hpqlgc-Enablement-Kit-6.0.0.0-12.noarch.rpm	new
Software - Storage Fibre Channel HBA	Fibreutils for HPE Storage Fibre Channel Host Bus Adapters for Linux -SuSE Linux Enterprise Server(SLES)	5	4.1-1 (c)	Optional	fibreutils-4.1-1_sles.x86_64.rpm	new

Software - Storage Fibre Channel HBA	HPE QLogic Smart SAN Enablement Kit for Microsoft Windows Server 64 bit operating systems	2	1.0.0.1 (i)	Recommended	cp039719.exe	update
Software - Storage Fibre Channel HBA	HPE Emulex(BRCM) Fibre Channel Over Ethernet Enablement Kit for Red Hat Enterprise Linux 8 Server	6	12.0.126 4.0	Recommended	HP-CNA-FC- Broadcom- Enablement- Kit- 12.0.1264.0- 1.rhel8.x86_64 .rpm	new
Software - Storage Fibre Channel HBA	HPE QLogic Fibre Channel Enablement Kit for Linux	3	6.0.0.0- 13	Recommended	HP-CNA-FC- hpqlgc- Enablement- Kit-6.0.0.0- 13.noarch.rpm	update
Software - Storage Fibre Channel HBA	HPE Emulex Fibre Channel Enablement Kit for SUSE Linux Enterprise Server 12	10	12.6.272. 0	Recommended	HP-CNA-FC- Emulex- Enablement- Kit-12.6.272.0- 1.sles12sp5.x8 6_64.rpm HP-CNA-FC- Emulex- Enablement- Kit-12.6.272.0- 1.sles12sp4.x8 6_64.rpm	update
Software - Storage Fibre Channel HBA	HPE Emulex Smart SAN Enablement Kit for Windows 64 bit operating systems	3	1.0.0.1 (j)	Recommended	cp042255.exe	update
Software - Storage Fibre Channel HBA	HPE Emulex(BRCM) Fibre Channel Over Ethernet Enablement Kit for Red Hat Enterprise Linux 7 Server	2	12.0.126 4.0 (b)	Recommended	HP-CNA-FC- Broadcom- Enablement- Kit- 12.0.1264.0- 1.rhel7.x86_64 .rpm	update

Software - Storage Fibre Channel HBA	HPE Emulex Smart SAN Enablement Kit for Linux	4	1.0.0.0-4 (f)	Optional	hpe-emulex- smartsan- enablement- kit-1.0.0.0- 4.x86_64.rpm	update
Software - Storage Fibre Channel HBA	HPE Emulex Fibre Channel Enablement Kit for SUSE Linux Enterprise Server 15	11	12.6.272. 0	Recommended	HP-CNA-FC- Emulex- Enablement- Kit-12.6.272.0- 1.sles15sp1.x8 6_64.rpm HP-CNA-FC- Emulex- Enablement- Kit-12.6.272.0- 1.sles15sp2.x8 6_64.rpm	update
Software - Storage Fibre Channel HBA	HPE Emulex Mezzanine Fibre Channel Enablement Kit for Red Hat Enterprise Linux 7 Server	9	12.4.256. 0	Recommended	HP-CNA-FC- Emulex- Enablement- Kit-12.4.256.0- 1.rhel7.x86_64 .rpm	new
Software - Storage Fibre Channel HBA	HPE Emulex(BRCM) Fibre Channel Over Ethernet Enablement Kit for SUSE Linux Enterprise Server 12	2	12.0.126 4.0 (b)	Recommended	HP-CNA-FC- Broadcom- Enablement- Kit- 12.0.1264.0- 1.sles12sp4.x8 6_64.rpm	update
Software - Storage Fibre Channel HBA	HPE Emulex Mezzanine Fibre Channel Enablement Kit for SUSE Linux Enterprise Server 12	10	12.4.256. 0	Recommended	HP-CNA-FC- Emulex- Enablement- Kit-12.4.256.0- 1.sles12sp4.x8 6_64.rpm	new
Software - System Management	NVMe Drive Eject NMI Fix for Intel Xeon Processor Scalable Family for Windows	8	1.1.0.0 (C)	Optional	cp034635.exe	update

Software - System Management	HPE System Health Application and Command Line Utilities for Red Hat Enterprise Linux 7 Server	8	10.9.2	Optional	hp-health-10.92-8.8.rhel7.x86_64.rpm	update
Software - System Management	HPE System Management Homepage Templates for Linux	3	10.8.1		hp-smh-templates-10.8.1-1487.3.noarch.rpm	update
Software - System Management	HPE ProLiant Agentless Management Service for HPE Apollo, ProLiant and Synergy Gen9 servers	2	10.97.0.0	Optional	cp041470.exe	update
Software - System Management	HPE ProLiant Agentless Management Service for Red Hat Enterprise Linux 8 Server	1	2.10.1		hp-ams-2.10.1-863.1.rhel8.x86_64.rpm	new
Software - System Management	HPE ProLiant Agentless Management Service for SUSE LINUX Enterprise Server 12	1	2.10.1		hp-ams-2.10.1-863.1.sles12.x86_64.rpm	update
Software - System Management	Agentless Management Service (iLO 5) for Red Hat Enterprise Linux 8 Server	35	2.3.0	Optional	amsd-2.3.0-1443.35.rhel8.x86_64.rpm	new
Software - System Management	HPE System Management Homepage for Windows x64	4	7.6.3.3	Recommended	cp034022.exe	update

Software - System Management	HPE System Health Application and Command Line Utilities for Red Hat Enterprise Linux 8 Server	5	10.9.2	Optional	hp-health-10.92-5.5.rhel8.x86_64.rpm	new
Software - System Management	HPE MegaRAID Storage Administrator StorCLI for Windows 64-bit	6	1.25.12.0	Optional	cp036918.exe	update
Software - System Management	HPE ProLiant Agentless Management Service for SUSE LINUX Enterprise Server 15	1	2.10.1		hp-ams-2.10.1-863.1.sles15.x86_64.rpm	update
Software - System Management	Agentless Management Service for Windows x64	2	2.30.1.0	Optional	cp044612.exe	update
Software - System Management	HPE SNMP Agents for SUSE LINUX Enterprise Server 15	4	10.9.1		hp-snmp-agents-10.91-670.4.sles15.x86_64.rpm	update
Software - System Management	HPE ProLiant Agentless Management Service for Red Hat Enterprise Linux 7 Server	1	2.10.1		hp-ams-2.10.1-863.1.rhel7.x86_64.rpm	update
Software - System Management	HPE System Health Application and Command Line Utilities for SUSE LINUX Enterprise Server 15	6	10.9.2	Optional	hp-health-10.92-6.6.sles15.x86_64.rpm	update
Software - System Management	HPE System Health Application and Command Line Utilities for	4	10.9.2	Optional	hp-health-10.92-4.4.sles12.x86_64.rpm	update

	SUSE LINUX Enterprise Server 12					
Software - System Management	HPE MegaRAID Storage Administrator (HPE MRSA) for Windows 64-bit	7	3.113.0.0	Optional	cp036916.exe	update
Software - System Management	HPE Smart Storage Administrator (HPE SSA) for Windows 64-bit	4	4.21.7.0	Optional	cp044526.exe	update
Software - System Management	HPE SNMP Agents for Red Hat Enterprise Linux 8 Server	5	10.9.1		hp-snmp-agents-10.91-670.5.rhel8.x86_64.rpm	new
Software - System Management	HPE Smart Storage Administrator (HPE SSA) CLI for Windows 64-bit	4	4.21.7.0	Optional	cp044527.exe	update
Software - System Management	HPE MegaRAID Storage Administrator (HPE MRSA) for Linux 64-bit	16	3.113.0.0	Optional	MRStorageAdministrator-003.113.000.000-00.x86_64.rpm	update
Software - System Management	NVMe Drive Eject NMI Fix for Intel Xeon v3 and Xeon v4 Processors for Windows Server 2012 R2 to Server 2019	7	1.0.5.0 (C)	Optional	cp035799.exe	same
Software - System Management	Agentless Management Service (iLO 5) for SUSE Linux Enterprise Server 15	31	2.3.0	Optional	amsd-2.3.0-1439.31.sles15.x86_64.rpm	update

Software - System Management	HPE System Management Homepage for Linux (AMD64/EM64T)	3	7.6.5-3	Recommended	hpsmh-7.6.5-3.x86_64.rpm	update
Software - System Management	HPE SNMP Agents for Red Hat Enterprise Linux 7 Server	4	10.9.1		hp-snmp-agents-10.91-670.4.rhel7.x86_64.rpm	update
Software - System Management	HPE Smart Storage Administrator Diagnostic Utility (HPE SSADU) CLI for Linux 64-bit	4	4.21.7.0	Optional	ssaduccli-4.21-7.0.x86_64.rpm	update
Software - System Management	HPE SNMP Agents for SUSE LINUX Enterprise Server 12	6	10.9.1		hp-snmp-agents-10.91-670.6.sles12.x86_64.rpm	update
Software - System Management	Agentless Management Service (iLO 5) for SUSE Linux Enterprise Server 12	30	2.3.0	Optional	amsd-2.3.0-1439.30.sles12.x86_64.rpm	update
Software - System Management	HPE Insight Management WBEM Providers for Windows Server x64 Editions	12	10.75.0.0	Optional	cp037689.exe	update
Software - System Management	HPE Insight Management Agents for Windows Server x64 Editions	7	11.0.0.0	Optional	cp037536.exe	update
Software - System Management	HPE Smart Storage Administrator Diagnostic Utility (HPE SSADU)	4	4.21.7.0	Optional	cp044528.exe	update

	CLI for Windows 64-bit					
Software - System Management	HPE MegaRAID Storage Administrator StorCLI for Linux 64-bit	11	1.25.12	Optional	storcli-1.25.12-1.noarch.rpm	update
Software - System Management	Agentless Management Service (iLO 5) for Red Hat Enterprise Linux 7 Server	49	2.3.0	Optional	amsd-2.3.0-1451.49.rhel7.x86_64.rpm	update
Software - System Management	HPE Smart Storage Administrator (HPE SSA) for Linux 64-bit	5	4.21.7.0	Optional	ssa-4.21-7.0.x86_64.rpm	update
Software - System Management	HPE Smart Storage Administrator (HPE SSA) CLI for Linux 64-bit	3	4.21.7.0	Optional	ssacli-4.21-7.0.x86_64.rpm	update
Software - Lights-Out Management	HP Lights-Out Online Configuration Utility for Linux (AMD64/EM64T)	2	5.5.0-0	Recommended	hponcfg-5.5.0-0.x86_64.rpm	update
Software - Lights-Out Management	HP Lights-Out Online Configuration Utility for Windows x64 Editions	11	5.4.0.0	Optional	cp040708.exe	update
Software - Storage Fibre Channel	HPE Storage Emulex Mezzanine Fibre Channel driver component for VMware vSphere 7.0	7	2020.09.01	Recommended	cp042275.zip	new

Software - Storage Fibre Channel	HPE QLogic Mezzanine Fibre Channel driver component for VMware vSphere 7.0	11	2020.09. 01	Recommended	cp042195.zip	new
Software - Storage Fibre Channel	HPE Storage Emulex Fibre Channel driver component for VMware vSphere 7.0	11	2020.09. 01	Recommended	cp042258.zip	new
Software - Storage Fibre Channel	HPE QLogic Mezzanine Fibre Channel driver component for VMware vSphere 6.7	14	2020.09. 01	Recommended	cp042194.zip	new
Software - Storage Fibre Channel	HPE Storage Emulex Fibre Channel driver component for VMware vSphere 6.5	8	2020.09. 01	Recommended	cp042256.zip	update
Software - Storage Fibre Channel	HPE QLogic Mezzanine Fibre Channel driver component for VMware vSphere 6.5	12	2020.09. 01	Recommended	cp042193.zip	new
Software - Storage Fibre Channel	HPE QLogic Fibre Channel driver component for VMware vSphere 6.7	9	2020.09. 01	Recommended	cp042512.zip	update
Software - Storage Fibre Channel	Emulex(BRCM) Fibre Channel over Ethernet driver for VMware vSphere 6.7	2	2019.12. 01 (b)	Recommended	cp044548.zip	update
Software - Storage	HPE QLogic Fibre Channel driver component for	7	2020.09. 01	Recommended	cp042511.zip	update

Fibre Channel	VMware vSphere 6.5					
Software - Storage Fibre Channel	HPE QLogic Fibre Channel driver component for VMware vSphere 7.0	8	2020.09.01	Recommended	cp042513.zip	new
Software - Storage Fibre Channel	HPE Storage Emulex Fibre Channel driver component for VMware vSphere 6.7	8	2020.09.01	Recommended	cp042257.zip	update
Software - Storage Fibre Channel	HPE Storage Emulex Mezzanine Fibre Channel driver component for VMware vSphere 6.5	9	2020.09.01	Recommended	cp042273.zip	new
Software - Storage Fibre Channel	Emulex(BRCM) Fibre Channel over Ethernet driver for VMware vSphere 6.5	1	2019.12.01 (b)	Recommended	cp044547.zip	update
Software - Storage Fibre Channel	HPE Storage Emulex Mezzanine Fibre Channel driver component for VMware vSphere 6.7	8	2020.09.01	Recommended	cp042274.zip	new
Software - Management	HPE Management Bundle Smart Component for ESXi 6.5	6	2020.09.01	Recommended	cp043234.zip	update
Software - Management	HPE Agentless Management Bundle Smart Component for Gen10 on ESXi 7.0	7	2020.09.01	Recommended	cp043232.zip	new

Software - Management	HPE iLO Driver Bundle Smart Component for ESXi 7.0	4	2020.09.01	Recommended	cp043231.zip	new
Software - Management	HPE Fiber Channel and Storage Enablement Bundle Smart Component for ESXi 7.0	5	2020.09.01	Recommended	cp044095.zip	new
Software - Management	HPE Agentless Management Bundle Smart Component for Gen9 on ESXi 7.0	7	2020.09.01	Recommended	cp044282.zip	new
Software - Management	HPE Management Bundle Smart Component for ESXi 6.7	5	2020.09.01	Recommended	cp043233.zip	update
Software - Management	HPE Smart Storage Administrator (HPE SSA) CLI Smart Component for ESXi 7.0	8	2020.09.01	Recommended	cp043333.zip	new
Software - Management	HPE CRU Driver Bundle Smart Component for ESXi 7.0	1	2020.04.01 (A)	Recommended	cp044598.zip	new
Software - Management	HPE SMX Provider Bundle Smart Component for ESXi 7.0	2	2020.04.01 (A)	Recommended	cp044591.zip	new
Software - Network	Broadcom Active Health System Agent for HPE ProLiant Network Adapters for Linux x86_64	4	1.0.21-1	Optional	hp-tg3sd-1.0.21-1.x86_64.rpm	same

Software - Network	Intel Active Health System Agent for HPE ProLiant Network Adapters for Linux x86_64	1	1.1.85.0-1 (B)	Optional	hp-ocsbbd-1.1.85.0-1.x86_64.rpm	update
Software - Storage Controller	HPE Smart Array SR Event Notification Service for Windows Server 64-bit Editions	2	1.2.1.64	Recommended	cp037793.exe	update
Software - Storage Controller	HPE ProLiant Smart Array SAS/SATA Event Notification Service for 64-bit Windows Server Editions	3	6.46.0.64 (E)	Optional	cp037465.exe	same
Software - Storage	HPE 3PAR HostExplorer for Windows Server 2008 2012 and 2016 x64 Operating Systems	2	3.2.1.0	Recommended	cp034831.exe	same
Utility - Tools	HPE Utilities Bundle Smart Component for ESXi 6.5	19	2020.09.14	Recommended	cp043160.zip	update
Utility - Tools	HPE Utilities Bundle Smart Component for ESXi 7.0	13	2020.09.14	Recommended	cp043159.zip	new
Utility - Tools	HPE Utilities Bundle Smart Component for ESXi 6.7	23	2020.09.14	Recommended	cp043161.zip	update